

ASS. REC. BY:

REF:

CS3 / TCS 18004728 / Gbez

Special Instruction:

'unge & any

Survivor:

TR

ASSIGNMENT (Office)

From (Person):

Janice Goh

of

TCS

Date/Time:

13032018 11am

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

She 559L

Insured:

SLA 6344X

at Workshop m/s

Sin Wee Chuan

Tel:

6748 0573

of

Blk 3021A Ubi Rd 1 #01-40

Policy No:

Claim No:

Sum Insured:

Excess:

Make of Veh:

D.O.A.

10032018

(Client's Record)

CA / REV / REP. / REV 24 HRS WPI

H.O.D. Endorsement:

Date/Time: 03032018 11:37am

Person Contacted:

Mike

Vehicle IN / OUT

Date/Time	Action/Instruction (X) Estimate
	She 559L - X
	SLA 6344X - X
	Dismantle: 14/3/2018
	" : 16/3/2018
	After repair: 20/3/2018

TAS

REF: TCS

ASSIGNMENT

From: _____ Date: 13-03-2018
 Estimated Cost: _____
 OD / TP / WS / TP RES / OD RES / EVA / INV / MV
 To Inspect Vehicle No: SLE 559L
 at Workshop m/s Sin Wai Chuan
 of Blk 3021A Ubi Rd 1 #01-40
 Insured: _____
 Policy No. _____
 Claims No. _____
 Sum Insured: _____ Excess: _____
 (Client's Record)
 Make of Veh: _____

(Policy Condition)
 Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value: _____
 IDAC Accident Rport: _____ Consistent? : Yes or No
 GIA / PR Seen: _____ Consistent? : Yes or No
 Est. Repairs: _____ days Res.: Yes or No
 Lum Sum: _____ % 3 Val.: Yes or No
 CA / REV / REP. / 24 HRS
 Date: _____ Person Contacted: _____
 Vehicle: IN / OUT

Veh No: SLE 559L Yr Regn: Aug / 13
 Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
 Truck / Trailer or _____
 Make: Volkswagen c.c. 1390
 Colour: blue A/C: Insured / Std / NI / NA
 Sp. Reading: 96563 T/Radio: Insured / Std / NI / NA
 Eng/No: _____
 C/No: www222.168 Dm 095 016
 Gen. Cond: Good / Fair / Poor / Burnt
 Steering: In order / Jammed / Leaked / Burnt or _____
 Brake: In order / Jammed / Leaked / Burnt or _____
 Modi: Nil / S/Rim / STD A/Rim or _____
 Tyre Size: F: 225/55R16
 R: 11
 BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
 TOYO / YOKO or _____
 Front _____ Rear _____
 R/Bal. 6 mm R/Bal. 6 mm
 L/Bal. 6 mm L/Bal. 6 mm
 D.O.A. _____ D.O.I. 13-03-18
 Survey held at w/s 4:20pm
 Des. of Damages Rear / O/S / N/S / UIC / Rooftop or _____
 The UIC / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

* Repair Estimate : S\$ ~~13,000~~ 7,000 - \$9,000
 * 6 days

RECEIVED 17 JUN 2018
 18/6/2018

Date/Time. File Pass to? : Preli. Report
 : Final Report

1) _____
 Date/Time. File Return to? _____

2) _____

Report Format : PRE

Lump Sum / I.B.I: (\$ _____)

Days Of Repair: 6

Resurvey No. of Trip: 3

Survey Fee: _____
 Transportation: _____

Add Fee: Site Insp (\$ _____)) \$ + RS \$ _____
 Interview (\$ _____)) Photos
 Tech. Invs (\$ _____)) Others
 Weekend (\$ _____))

TOTAL _____

Catherine Chong (LKK Auto)

From: ECICS Claims <claims@ecics.com.sg>
Sent: Tuesday, 13 March, 2018 11:00 AM
To: Cheonghoh Law; assignments@lkkauto.com
Cc: ECICS Claims; motorsurvey
Subject: RE: Our ref: LCH.ry/UB05-80214.18 Your ref: SLA 6344 X - Accident involving SLE 559 L / SLA 6344 X (ECICS) on 10/3/18 along Yishun Industrial Street 1 - Pre-repair survey ("PRS") of SLE 559 L
Attachments: 80214 (our ltr dd 13318).pdf; 80214 (our ltr dd 12318 - Notice of Accident).pdf

Without Prejudice

Dear Jennifer

Thank you for your email.
We are not agreeable with your list of surveyor.
We will arrange LKK for the PRI.
Thank you.

Aside to LKK

Please arrange PRI for TP's vehicle and refer to the attachment.

Thank you.

Regards,
Janice Goh
Claims Division
DID: +65 6303 0182
FAX: +65 6338 9267

ECICS Limited

7 Temasek Boulevard, #10-01 Suntec Tower One, Singapore 038987

WITH IMMEDIATE EFFECT FOR ALL PRE-REPAIR INSPECTION/SURVEY, please email to motorsurvey@ecics.com.sg directly.

Please bear with us should we take longer to response as we are currently experiencing a high volume of claims. Thank you for your kind patience and understanding.


From: Cheonghoh Law [mailto:mail@cheonghoh.sg]
Sent: Tuesday, 13 March, 2018 10:42 AM
To: motorsurvey
Cc: ECICS Claims
Subject: Re: Our ref: LCH.ry/UB05-80214.18 Your ref: SLA 6344 X - Accident involving SLE 559 L / SLA 6344 X (ECICS) on 10/3/18 along Yishun Industrial Street 1 - Pre-repair survey ("PRS") of SLE 559 L

URGENT

Dear Sirs

Kindly see attached our letter dated 13 March 2018 for your attention.

Thank you.



This message may contain privileged and confidential information and is only intended for use by the addressee. No representation, warranty, guarantee or undertaking expressed or implied is made by ECICS Limited; as to the fairness, accuracy or completeness of any information, projections or opinions contained in this message. Any unauthorized disclosure, use or dissemination either in whole or in part is prohibited. If you are not the addressee indicated in his message (or responsible for delivery of the message to such person), you may not copy or deliver this message to anyone. In such case, you should destroy this message and kindly notify the sender by reply email. Opinions contained herein are the personal opinions of the sender and do not necessarily represent the views of ECICS Limited.

Cheonghoh Law Corporation

(Incorporated with limited liability) Blk 53 Chin Swee Road #03-05 . Singapore 160053
Co. Reg No.201108070G Tel: 63378700 Fax: 63373700 E-mail: mail@cheonghoh.sg

In reply, please quote our Reference Number

Our Ref: LCH.ry/UB05-80214.18
Your Ref: SLA 6344 X

13 March 2018

URGENT

ECICS Limited
7 Temasek Boulevard
#10-01 Suntec Tower One
Singapore 038987
Attn: Janice Goh (Claims Division)

BY EMAIL ONLY
Fax No: 63389267

Dear Sirs

**ACCIDENT INVOLVING VEHICLES NO SLE 559 L AND SLA 6344 X ON 10 MARCH 2018 AT/ALONG
YISHUN INDUSTRIAL STREET 1 -**

We refer to the above matter and to your e-mail dated 12 March 2018.

Pursuant to the NIMA protocol of the Practice Directions Amendment No. 1 of 2016, we have our client's instructions to reject your list of appointed surveyors as stated in your aforesaid e-mail.


We are further instructed to append below our client's 10 proposed surveyors as follows:

- | | |
|---------------------------|--------------------------|
| (1) How Andrew | (6) Philip Foo |
| (2) Fong Kok Heng | (7) Ong Ah Keng, Kent |
| (3) Ang Guea Kiang | (8) Ong Poh Meng |
| (4) Lee Kok Weng | (9) Ng Soon Aik Francis |
| (5) Jayson Liaw Leong San | (10) Ng Soon Chuan Louis |

If you are not agreeable to our list of surveyors above, kindly appoint your surveyor(s) to proceed with the pre-repair survey of our client's vehicle no. SLE 559 L and is currently laying at our client's repairer workshop as follows:-

Sin Wee Chuan Spray Painting & Service Workshop
Blk 3021A Ubi Road 1 #0-40
Singapore 408715
Mr Mike Low - 6748 0573

Yours faithfully


Lee Cheong Hoh
CHEONGHOH LAW CORPORATION

cc: client - via fax only (SLE 559 L)

> Back to OneMotoring

Enquire Transfer Fee

Vehicle Details			
Vehicle No. :	SLE559L		
Vehicle Type :	P10 - Passenger Motor Car		
Vehicle Attachment 1 :	No Attachment		
Vehicle Scheme :	Normal		
Vehicle Make :	VOLKSWAGEN		
Vehicle Model :	JETTA 1.4 TSI AT 1622G5		
Chassis No. :	WVWZZZ16ZDM095016		
Propellant :	Petrol		
Engine No. :	CAXD65488		
Engine Capacity :	1390 cc		
Maximum Power Output :	90.0 kW (120 bhp)		
Maximum Laden Weight :	1870 kg		
Unladen Weight :	1417 kg		
Year Of Manufacture :	2013		
Original Registration Date :	30 Aug 2013		
Lifespan Expiry Date :	-		
COE Category :	A - Car (1600cc & below)		
Quota Premium :	\$75,556.00		
COE Expiry Date :	29 Aug 2023		
Road Tax Expiry Date :	29 Aug 2018		
PARF Eligibility Expiry Date :	29 Aug 2023		
Inspection Due Date :	29 Aug 2018		
Intended Transfer Date :	21 Jun 2018		
CO2 Emission :	138.00 (g/km)		
CEV/VES Rebate Utilised Amount :	\$10,000.00		
CO Emission :	-		
HC Emission :	-		
NOx Emission :	-		
PM Emission :	-		
The current road tax expiry is 29 Aug 2018. You may renew the road tax from 30 May 2018 with all pre-requisite(s) fulfilled. If the road tax is renewed after 29 Aug 2018, late renewal fee(s) will be imposed. Please use Enquire Road Tax Payable to check on the late fee(s) payable.			
Road tax, including Over Payment (if any), of a vehicle will follow the vehicle to the new registered owner when its ownership is being transferred.			
Amount Payable (From 30 Aug 2018 to 28 Feb 2019)			
	Amount Before GST	GST Amount	Amount After GST
	(S\$)	(S\$)	(S\$)
Transfer Fee :	25.00	-	25.00
Sub Total :			25.00
Nett Road Tax Amount (After Offsetting Over Payment) :	310.00	-	310.00
Total Amount Payable :			335.00
Amount Payable (From 30 Aug 2018 to 29 Aug 2019)			

> [Back to OneMotoring](#)

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	4033I
Vehicle Details	
Vehicle No.:	SLE559L
Vehicle to be Exported:	No
Intended De-registration Date:	21 Jun 2018
Vehicle Make:	VOLKSWAGEN
Vehicle Model:	JETTA 1.4 TSI AT 1622G5
Primary Colour:	Black
Manufacturing Year:	2013
Engine No.:	CAXD65488
Chassis No.:	WVWZZZ16ZDM095016
Maximum Power Output:	90.0 kW (120 bhp)
Open Market Value:	\$19,391.00
Original Registration Date:	30 Aug 2013
First Registration Date:	30 Aug 2013
Transfer Count:	1
Actual ARF Paid:	\$9,391.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	29 Aug 2023
PARF Rebate Amount:	\$7,043.00
Intended COE Rebate Details	
COE Expiry Date:	29 Aug 2023
COE Category:	A - Car (1600cc & below)
COE Period(Years):	10
QP Paid:	\$75,556.00
COE Rebate Amount:	\$39,199.00
Total Rebate Amount:	\$46,242.00

The information contained herein is correct as at 21 Jun 2018

OK

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	12/03/2018 14:22
Date Of Accident	10/03/2018 17:45
Exact Location Of Accident	YISHUN INDUSTRIAL STREET 1
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SLE559L
Insured/Policyholder	
Name Of Registered Owner	SARAVANAN S/O RAMAKRISHNAN
NRIC No	S8724033I
Email Address	VANCE.RAMAKRISHNAN@GMAIL.COM
Mobile Phone No	(LOCAL) +65-90469995
Alternative Phone No	OFFICE-90469995

Vehicle Particulars

Manufacturer	VOLKSWAGEN
Model	JETTA-1.4 TSI (A)
Exact Purpose for which vehicle was being used at time of accident	PRIVATE USE
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR

Insurance Company

Name of Insurance Company	NTUC INCOME INSURANCE CO-OPERATIVE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	5082656367
Cover Note Number	

Driver

Name of Driver	SARAVANAN S/O RAMAKRISHNAN
NRIC No	S8724033I
Date Of Birth	12/08/1987
Occupation	INDOOR
Date Of Driving Pass	17/12/2009
Driving Experience	8 YEARS AND 2 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-90469995
Fax Number	
Contact Number	OFFICE-90469995
Email Address	VANCE.RAMAKRISHNAN@GMAIL.COM

Address	BLK 782A WOODLANDS CRESCENT #13-307
Postcode	731782
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OWNER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	COLLISION - CHANGE/CROSS LANE
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles involved in the accident	2
Was any body injured in the Accident?	YES
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	4

Passenger 1	NAME: : NA
	GENDER: : FEMALE
Passenger 2	NAME: : NA
	GENDER: : FEMALE
Passenger 3	NAME: : NA
	GENDER: : MALE

Details of Police Action

Was the accident reported to the police?	YES
If Yes, Please state which Police Station	
Police Station Name	YISHUN NORTH NEIGHBOURHOOD POLICE CENTRE
Police Station Address	ROAD: 31 YISHUN CENTRAL , POSTCODE: 768827 , COUNTRY: SINGAPORE
Police Station Contact	TEL NO: 1800-8529999 - FAX NO: 68522299
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

AS PER POLICE REPORT NO. T/20180312/2041

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SLA6344X
Vehicle Make/Model/Colour	
Details Of Properties	

Vehicle Category PRIVATE CAR
Name of Driver ALVIS AWYONG KE WANG
NRIC/Passport Number
Contact Number
Address
Postcode
Insurance Company Name
Nature Of Damage
No. Of Passenger (Including Driver)

DETAILS OF INJURED PERSON 1

Name JANICE ANN JOSEPH
Approximate Age
Injuries Sustain
Injured person in which vehicle? SLE559L
Were seat belts worn? YES
Was this injured conveyed to hospital by ambulance? NO
Address
Postcode

DETAILS OF INJURED PERSON 2

Name SARAVANAN S/O RAMAKRISHNAN
Approximate Age
Injuries Sustain
Injured person in which vehicle? SLE559L
Were seat belts worn? YES
Was this injured conveyed to hospital by ambulance? NO
Address
Postcode

DETAILS OF INJURED PERSON 3

Name S NESAMANI
Approximate Age
Injuries Sustain
Injured person in which vehicle? SLE559L
Were seat belts worn? YES
Was this injured conveyed to hospital by ambulance? NO
Address
Postcode

Sketch Plan Pg. 1

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed.
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.

Policyholder's Signature

Date & Time:

12/3/18

1:30 pm

Driver's Signature

(if driver is not the policyholder)

Date & Time:

Reporting Centre Personnel's Signature

Name:

NRIC/FIN No.:



...CLAIM SUBFOLDER...(Pending for Survey Report)

Midnight Accident

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	28 Jun 2018 09:16 Edit Reg		13 Mar 2018 00:00 Edit Adj Rpt	S\$0.00 Edit Estimates	S\$0.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS		[Created by adjuster]							
Insured:	-, Co. Reg. No.: -, Email: EMAIL@EMAIL.COM								
Main Claimant:	-								
Vehicle Reg. No.:	SLE559L	Date of Loss:	10/03/2018 00:00 - :59 [54 Months and 10 Days From LTA Reg Date (Man Yr)]						
Claim Type:	TP	Policy/Cover Note No.:							
Vehicle Reg. No. (Insured):	SLA6344X	Policy No. (Claimant):							
		Excess:							
Repairer:	Sin Wee Chuan Spray Painting & Services (HQ) BLK 3021A UBI ROAD 1 #01-40, 408715 Ubi - Tel:								
Handling Insurer:	ECICS Limited (HQ) - Tel: 63374779 /6303 0178								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by XING GUO QIANG] ... [Final Rpt due 02/05/2018]								
ASSOCIATED MAIL RECEIVED		View All Compose Case Mail							
There are no mail for this case.									
ALL ASSOCIATED TASKS <input type="checkbox"/>		View All Search Tasks Create New Task Complete							
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*SLE559L
[SLA6344X]
TP

Mar 10 2018 12:00AM

[-]

Sin Wee Chuan Spray Painting & Services

[Upload Documents](#) | [Upload Photos](#) | [Compose New Letter](#)

View [View in Browser](#) 

No documents found.

Documents Checklist

DOCUMENTS CHECKLIST

[Reset](#) | [Save](#) | [Print](#)

There are no document checklists configured.

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)

Show Remarks To: Handling Insurer

Note: Remarks are private unless you show it to other parties.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS3/ICS18004728/GBE2

Date: 28/06/2018

REFERENCE

Handling Insurer: ECICS Limited Policy No:
Claimant Vehicle No : SLE559L **Insured Vehicle No :** SLA6344X
 Date of Loss: 10/03/2018 Nature of Claim: TP Claim No: N/A

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SLE559L**
 Make & Model: VOLKSWAGEN JETTA, 1.4 (A) Engine No: CAXD65488
 Reg. Date: 30/08/2013 (Man. Year: 2013) Chassis No: WWZZZ16ZDM095016
 Colour: Blue Odometer: 96563 km
 Engine Capacity: 1390 cc
 Market Value/New Car Price: N/A
 Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition: Yes

CONDITION OF TYRES

Front Tyre Size: 205/55 R16 Rear Tyre Size: 205/55 R16
 Front Left Side: Pirelli 6 mm Rear Left Side: Pirelli 6 mm
 Front Right Side: Pirelli 6 mm Rear Right Side: Pirelli 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Nett Amount (S\$)	0.00	0.00	0.00	

INSPECTION

Date of Assignment: 13/03/2018
 Date Inspected: 13/03/2018 Inspected At: Sin Wee Chuan Spray Painting & Services (HQ)
 BLK 3021A UBI ROAD 1 #01-40
 Singapore 408715
 Estimated Period of Repair: 6.0 days

Adjuster: XING GUO QIANG**Manager:** CATHERINE CHONG KAI LING

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

- A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
- B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE.
- C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.

THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$7,800.00 -\$9,000.00

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 28 Jun 2018)

Parts: 143 VOLKSWAGEN JETTA 1.4 (A) (Catalogue:Merimen Singapore 1.0)

Labour: Repairer's (Price-denominated Standard List)

Print Code: (Unsubmitted, no print-code for SLE559L)

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

There are no new parts selected.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.

< END OF ESTIMATES >