

UNION

INS. CASE OWNER

CC 4/AXA1800

4748, 12/63

LKK:
IDAC

Tantikh

ASSIGNMENT
w/5/18

Date / Time: 12/2/18

Surveyor:

Registered in Merimen:

Pre-assign / CCU / FTE



Insured Vehicle No.: GQ 3890E
Name of Insured: LHM LEE SAKS TRADING
Insured Tel No.: HP:
Excess Sec II :SS D.O.A.: 25/01/18
Is driver the owner? (YES / NO) Nature of Accident:
If NO, Driver Name / Age: LHM LEE SAKS 31yrs
Driver Tel No.: (V/L: YES / NO)

Claim No.: 88000000 / 34636
Policy No.: p202/25
Make / Model: Toyota
Place of Accident: 103 JUNONH EAST STN
OI GIA REPORT: YES / NO : TP GIA REPORT: YES / NO
Insured Liability: % Final ? Yes / No



INSRS:
WSP:
Tel:
Liability:
RMKS:

Regents



INSRS:
WSP:
Tel:
Liability:
RMKS:



INSRS:
WSP:
Tel:
Liability:
RMKS:



INSRS:
WSP:
Tel:
Liability:
RMKS:

Date / Time	STAGE	DATE / PIC
20/12/18	Non-Reporting Itr (1st):	
	Non-Reporting Itr (2nd):	
	Non-Reporting Itr (Final):	
	Notification Itr (if non-pickup):	
	Call OI:	
	After call Itr to OI:	
	Documentation Check List:	Handler Typist
	Notification Itr (if non-pickup)	
	After call Itr to OI:	
	Authorisation To Act:	
	Release Voucher:	
	Final Repair Bill:	
	Car Rental Invoice:	
	Towing Invoice:	
	LTA / GIA:	
	Medical Bill:	
	PIR:	
	Mandate/Reject Instruction:	
	LOD:	
	Payment Breakdown Form:	
	Post-Repair Photos:	
	Others:	
PRELIMINARY ADVICE	Date/Time: 20/12/18	Sent By: Bnu
FINALIZATION	Date/Time:	Confirm with:
Repair Cost: P/P	SS 2,915.00 (3 days)	Reduction: 34 %
FINAL SETTLEMENT	Date/Time:	Confirm with:
Final Liability:	%	(Agreed / Assessed) BOLA S/N No.:
Repair Cost:	SS -	
Loss of Rental (LOR):	SS -	(days)
Loss of Use (LOU):	SS -	(\$ x days)
Loss of Income (LOI):	SS -	(\$ x days)
LOR only ☐ LOU only ☐	LOR + LOU ☐ LOR + LOI ☐	[Tick only one]
GIA/LTA Search:	SS -	
Medical:	SS -	
Disbursement:	SS -	(e.g. Tow/Independent)
Legal Cost:	SS -	
Total:	SS	Global Sum SS:
FINAL PAYMENT	Date/Time:	Confirm with:
Payee 1:	SS -	Name 1: -
Payee 2: (Strike if N.A.)	SS -	Name 2: -
Payee 3: (Strike if N.A.)	SS -	Name 3: -

STAGE DATE / PIC

Non-Reporting Itr (1st):
Non-Reporting Itr (2nd):
Non-Reporting Itr (Final):
Notification Itr (if non-pickup):
Call OI:
After call Itr to OI:

Documentation Check List: Handler Typist

Notification Itr (if non-pickup)
After call Itr to OI:
Authorisation To Act:
Release Voucher:
Final Repair Bill:
Car Rental Invoice:
Towing Invoice:
LTA / GIA:
Medical Bill:
PIR:
Mandate/Reject Instruction:
LOD:
Payment Breakdown Form:
Post-Repair Photos:
Others:

PRELIMINARY ADVICE Date/Time: 20/12/18 Sent By: Bnu

FINALIZATION Date/Time: Confirm with: Confirm by: Email ☐ Call ☐

FINAL SETTLEMENT Date/Time: Confirm with: Email ☐ Call ☐

Final Liability: % (Agreed / Assessed) BOLA S/N No.:
Repair Cost: SS -
Loss of Rental (LOR): SS - (days)
Loss of Use (LOU): SS - (\$ x days)
Loss of Income (LOI): SS - (\$ x days)
LOR only ☐ LOU only ☐ LOR + LOU ☐ LOR + LOI ☐ [Tick only one]
GIA/LTA Search: SS -
Medical: SS -
Disbursement: SS - (e.g. Tow/Independent)
Legal Cost: SS -
Total: SS Global Sum SS:
1) Claim status: Normal/Reject/Private Settle
2) Report Format: WP REPORT
3) Survey fee: \$250.00

FINAL PAYMENT Date/Time: Confirm with: Email ☐ Call ☐

Payee 1: SS - Name 1: -
Payee 2: (Strike if N.A.) SS - Name 2: -
Payee 3: (Strike if N.A.) SS - Name 3: -



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

AXA INSURANCE PTE LTD

Ref : CC4/ASM18004748/T1hb3

8 SHENTON WAY #24-01
AXA TOWERSINGAPORE 068811

Date : 13-03-2018



Code : ASM

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	GQ 3890E	Veh. Inspected	SJZ 8128H
Policy No.		Coverage (\$)	0.00
Claim No.		Excess (\$)	0.00
Assign From		Assign Date	13/03/2018

2. Vehicle Particulars & Condition

Make & Model	c.c	0
Engine No.	HIDDEN	Year of Reg.
Chassis No.		Colour
Odometer	-	Steering
Brakes		Modification
General		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm

4. Description of Damages

--

5. General Information

Accident Date	25/01/2018	Inspection Date	16/03/2018
Survey held at	REGENT MOTORS PTE LTD 305 ALEXANDRA ROAD SINGAPORE 159942		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.
--

REGENT MOTORS

(A Division of Vantage Automotive Limited)

Business Registration No. 83055531L GST Registration No. M2-0000551-1

305 Alexandra Road

169942 Singapore

Tel : 6477 7400

Fax : 6477 7398



GST Registration No. M2-0000551-1

ESTIMATE

Estimate No. : BG 3590
Date Estimated : 12/03/2018
Prepared By : Wong Guo Xiang

Page No. : 1 of 1

- ESTIMATE REPAIR FOR -

ONG ZIHAO
BLK 547 ANG MO KIO AVENUE 10
#11-2334
SINGAPORE
SINGAPORE 560547

- ACCOUNT - 2000

CASH - Sale service

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SJZ8128H	WF0EXXGBBE9C52756	29/07/2010	MON 2.3T 5DR	0

DESCRIPTION

SUNDRIES

VALUE

30 150.00

REPLACE FRT LHS FENDER

600 900.00

RESPRAY FRT LHS FENDER, FRT LHS DOOR

600 1,500.00

WIRING CONNECTION & CHECK (NETT)

✓ 150.00

TO REMOVE & REFIX FRONT HEADLAMP INCLUDING REALIGN
HEADLIGHT BEAM LEVEL (NETT)

✓ 200.00

TUFF KOTE @ \$60 PER PANEL

60 120.00

TO CONDUCT ECU COMPUTER DIAGNOSTIC INCLUDING CLEAR
FAULT CODE (NETT)

✓ 600.00

Total Labour 1: 3,620.00

PART NUMBER	DESCRIPTION	QTY	PRICE	DISC	VALUE
P7S7116006AB	LHF FENDER - M07	1	750.00	10.00	675.00
7S71A16115AH	LHF FENDER INNER SHIELD	1	201.00	10.00	180.90

Total Parts : 855.90

LKK Auto Consultants hereby notify

the Repairer of the following:

- To survey before/after spray painting
- To display damaged part(s) during survey
- Parts prices are subject to confirmation

- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be surveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Customer Service Officer

Date:

Contact

Labour 1	:	3,620.00
Parts	:	855.90
Labour 2	:	0.00
Excess	:	0.00
Total GST @ 7%	:	313.31
Grand Total	:	4,789.21

The above estimates are base on visual inspection and it is possible that further materials and labour may be required upon dismantling. Should this occur, we will submit supplementary quotation for further approval.

4,785.90

Tan Jiah 97495749
WP 16/3/18 @ 1430
Resurvey before paint
3 days sur @ lkkand.com.

◀ Service Request Details

Claim

S8M00ALU

Reference

None 

Loss Date

January 25, 2018

Request Date

March 13, 2018

Due Date

March 20, 2018

Vendor Name

LKK AUTO CONSULTANTS PTE LTD (TP)

Type of Loss

Third Party Vehicle Damage

Services

Pending verification - Direct Settlement

13-03-2018 @ 10:55am
Guo Xing veh not in

Actions

Next Step

Agree to perform service

Decline WorkAccept Work

Vehicle Information

Incident Vehicle Registration #

SJZ8128H

Make

TPVD FORD

Service Address

...

Primary Contact/Insured

CHIAP LEE SACKS TRADING
BLK 203 JURONG EAST STREET 21, #06-121, 600203, Singapore
93872137
CHEWYIJIN@YAHOO.COM

Claim Handler

LOH Cynthia
6568804843
cynthia.loh@axa.com.sg

Additional Instructions

Messages

Invoices

History

Documents

Assessment

Metrics

Notes

New Message

**LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

AXA INSURANCE PTE LTD

Ref : CC4/ASM18004748/T1hb3q2

8 SHENTON WAY #24-01
AXA TOWERSINGAPORE 068811

Date : 19-11-2019

ATTN:VALE OH

Code : ASM

**1. Policy Particulars :- THIRD PARTY CLAIM**

Insured Veh.	GQ 3890E	Veh. Inspected	SJZ 8128H
Policy No.	P2029225	Coverage (\$)	0.00
Claim No.	S8M00ALU	Excess (\$)	0.00
Assign From		Assign Date	13/03/2018

2. Vehicle Particulars & Condition

Make & Model	FORD MONDEO	c.c	2261
Engine No.	HIDDEN	Year of Reg.	2010
Chassis No.	WF0EXXGBBE9C52756	Colour	SILVER
Odometer	97998	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	GOOD		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	235/40 R18	MICHELIN	6 mm
L/H Front Tyre	235/40 R18	MICHELIN	6 mm
R/H Rear Tyre	235/40 R18	MICHELIN	6 mm
L/H Rear Tyre	235/40 R18	MICHELIN	6 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE FRONT N/S PORTION.
DAMAGES SEE DETAILS.

5. General Information

Accident Date	25/01/2018	Inspection Date	16/03/2018
Survey held at	REGENT MOTORS PTE LTD 305 ALEXANDRA ROAD SINGAPORE 159942		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS.
B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	3 Working Days
-------------------------------------	-----------------------



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SJZ 8128H

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	SUNDRIES (SN) (CONSISTENT)	NECESSARY	150.00	30.00
1	LHF FENDER -M07 (SN) (CONSISTENT)	BENT	675.00	675.00
1	LHF FENDER INNER SHIELD (SN) (CONSISTENT)	NOT NECESSARY	180.90	-
			1,005.90	705.00
	<u>LABOUR</u>			
	REPLACE FRT LHS FENDER .		900.00	600.00
	RESPRAY FRT LHS FENDER ,FRT LHS DOOR .		1,500.00	600.00
	WIRING CONNECTION & CHECK .		150.00	150.00
	TO REMOVE & REFIX FRONT HEADLAMP INCLUDING REALIGN HEADLIGHT BEAM LEVEL.		200.00	200.00
	TUFF KOTE.		120.00	60.00
	TO CONDUCT ECU COMPUTER DIAGNOTIC INCLUDING CLEAR FAULT CODE .		600.00	600.00
			3,470.00	2,210.00
	GRAND TOTAL		4,475.90	2,915.00
	RECOMMENDED COST OF REPAIRS			2,915.00

Report Ref No. CC4/ASM18004748/T1hb3q2

MOHAMAD TAUFIKH

M.MATAI, AMSAE-A

Automotive Assessor

HO LEONG CHUAN

Automotive Assessor

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.

Service Request Details

Claim	SIMMOALLU
Reference	CCA/ASM18004748/T1H3p2
Loss Date	25 January 2018
Report Date	13 Mar 2018 9:35:19 AM
Request Date	3 June 2019
Due Date	
Vendor Name	LKK AUTO CONSULTANTS PTE LTD (TP)
Type of Loss	Third Party Vehicle Damage
Services	Pending verification - Direct Settlement

Actions

Next Step

Wait for: Approve Invoice

Add Invoice

Vehicle Information	
Incident Vehicle Registration #	SJ28128H
Make	TPVD FORD
Model	MONDEO
Service Address	

...

Primary Contact/Insured
CHIAP LEE SACKS TRADING BLK 203 JURONG EAST STREET 21, #06-121, 600203, Singapore 93872137 CHEWYIH@YAHOO.COM

Claim Handler
CHEN Xinyou chen.xinyou@axa.com.sg

Additional Instructions

Messages Invoices History Documents Assessment Metrics Notes

Document Type

Document SubType

Upload Documents

NAME	TYPE	SUB-TYPE	AUTHOR	DATE UPLOADED
INGRID GIA REPORT - Or reported no collision	Reports & Statement	GIA Report	Merimen	

NAME	TYPE	SUB-TYPE	AUTHOR	DATE UPLOADED
 LKKInvoice1 (3).pdf	Invoice	Surveyor/ Assessor expense	LKK AUTO CONSULTANTS PTE LTD (TP)	20 November 2019
 LKKInspection (1).pdf	Forms / Claim Documents	Others	LKK AUTO CONSULTANTS PTE LTD (TP)	20 November 2019
 LKKAdjustment1a (1).pdf	Forms / Claim Documents	Others	LKK AUTO CONSULTANTS PTE LTD (TP)	20 November 2019
 LKK PHOTO.pdf	Forms / Claim Documents	Others	LKK AUTO CONSULTANTS PTE LTD (TP)	20 November 2019
 Email to TP dtd 040419 .pdf	Letters and Correspondence	Third Party	LKK AUTO CONSULTANTS PTE LTD (TP)	15 November 2019
 TP ESTIMATE- MARKED.pdf	Reports & Statement	Estimate / Quotation	LKK AUTO CONSULTANTS PTE LTD (TP)	20 March 2018
 Preliminary Advice.pdf	Reports & Statement	Estimate / Quotation	LKK AUTO CONSULTANTS PTE LTD (TP)	20 March 2018
 EMAIL RECEIVED FROM WORKSHOP WITH GIA REPORT AND ESTIMATE.rmg	Forms / Claim Documents	Estimate / Quotation	DHIWAR Namrata	13 March 2018