

22/03/2002

ASS. REC. BY:

REF: CS3 / MS(18004788 / D bet Special Instruction:

Survivor: Bryan
MedimenASSIGNMENT (Office)From (Person): Jasmine Lok of MSG Date/Time: 13032018 1:17 pm

Estimated Cost: _____ Bill to: _____

OD / ~~TP~~ / WS / TP RES / OD RES / EVA / INV / MV / CSTo Inspect Vehicle No: SJF 4758X Insured: XD 9624Xat Workshop m/s Teamwork Tel: 6844 2475of 53 Ubi Ave 1 #01-24Policy No: A28810543 MKC Claim No: 552081

Sum Insured: _____ Excess: _____

Make of Veh: _____ D.O.A. 10032018
(Client's Record)CA / REV / REP. / REV 24 HRS 'wp' 14.03.2018 H.O.D. Endorsement: _____Date/Time: 13032018 3:44pm Person Contacted: Darren Vehicle IN OUT

Date/Time	Action/Instruction (X) Estimate
	<u>SJF 4758X - NA / EQL 18004619 / h4</u>
	<u>XD 9624X - x</u>


Don: 10032018

ASSIGNMENT

From: _____ Date: _____
 Estimated Cost: _____
OD / TP / WS / TP RES / OD RES / EVA / INV / MV
 To Inspect Vehicle No: _____
 at Workshop m/s _____
 of _____
 Insured: _____
 Policy No. _____
 Claims No. _____
 Sum Insured: _____ Excess: _____
 (Client's Record)
 Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
 repair at the time of inspection.



Bal. or Market Value: _____
 IDAC Accident Rpt: _____ Consistent? : Yes or No
 GIA / PR Seen: _____ Consistent? : Yes or No
 Est. Repairs: 4 days Res.: Yes or No
 Lum Sum: 20 % 3 Val: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: 85F 4758X Yr Regn: 30 May 2008
 Type: Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
 Truck / Trailer or
 Make: Toyota Corolla Altis C.C. 1598
 Colour: silver A/C: Insured / Std / NI / NA
 Sp. Reading: 198565 T/Radio: Insured / Std / NI / NA
 Eng/No: 3224769451
 C/No: MR0532EE106109712
 Gen. Cond: Good / Fair / Poor / Burnt
 Steering: Inorder / Jammed / Leaked / Burnt or
 Brake: Inorder / Jammed / Leaked / Burnt or
 Mod: Nil / S/Rim / STD A/Rim or
 Tyre Size: F: 195/65 R15
 R: 11

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
 TOYO / YOKO or Bridgestone

Front Rear
 R/Bal. S mm R/Bal. S mm
 L/Bal. S mm L/Bal. S mm
 D.O.A. 10/03/2013 D.O.I. 14/03/2018
 Survey held at Teknokrat Pagar Ubi

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or.
O/S Rear

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
	<u>MSIG XD 9624K</u>
	<u>PR8</u>
	<u>Repair Range 3K to 3.5K</u>
	<u>Repair limit 2K.</u>
	<u>Vehicle was abt 2 1/2 mths at time of loss.</u>
	<u>MV equals Part + body abt 2K.</u>
	<u>Part 8388.00</u>
	<u>Rev bumper, 2HR Fender, 2HR door,</u>
	<u>Retain RH, 2HR door chrome</u>
	<u>moulding, 2HR trunkamp</u>
	<u>2HR door trimboard.</u>

Date/Time, File Pass to?

☐

Preli. Report

1)

Date/Time, File Return to?

☐

Final Report

2)

Days Of Repair: 4

Resurvey No. of Trip: 2

Add Fee: ☐ Site Insp (\$)

☐ Interview (\$)

☐ Tech. Invs (\$)

☐ Weekend (\$)

Survey Fee:

Transportation:

S + RS. \$

Photos

Others

TOTAL

Report Format: PR8.

Lump Sum / I.B.I. (\$)

120

150

10

180

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	12 Mar 2018		13 Mar 2018 13:17 Assign				New Assignment Cancel Case

Main	Reference	Claim Details	Documents	Show All
------	-----------	---------------	-----------	----------

CLAIM SUBFOLDER DETAILS		[Created by insurer]
Insured:	CORTINA LOGISTICS PTE LTD, Co. Reg. No.: 201108508W	
Main Claimant:	ROSET LIMOUSINE SERVICES PTE LTD, Co. Reg. No.: 200406722Z	
Vehicle Reg. No.:	SJF4758X	Date of Loss: 10/03/2018 16:00 - :59
Claim Type:	TP / 552081	Policy/Cover Note No.: A28810543MKC (Comprehensive) Coverage: 27/08/2017 - 26/08/2018
Vehicle Reg. No. (Insured):	XD9624K	Policy No. (Claimant):
		Excess: S\$2,000.00
Repairer:	Teamwork Garage Pte Ltd (HQ) 53 Ubi Ave 1 #01-24, Paya Ubi Industrial Park, 408934 Ubi - Tel: 6844 2475	
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Jasmine Lok Kheng Kwei - 6594 2550]	
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Imm.Advice due 14/03/2018]	
Driver/Custodian (Insured):	HARON BIN MOHD NOOR (36 / Male), NRIC: S1383835F, Tel: +6581841837	
Adj Asg. Remarks:	Please contact MR DARREN NG @ 6844 2475 to arrange for survey	

ASSOCIATED MAIL RECEIVED	View All	Compose Case Mail
There are no mail for this case.		

ALL ASSOCIATED TASKS									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type:	Company
Owner ID:	6722Z

Vehicle Details

Vehicle No.:	SJF4758X
Vehicle to be Exported:	Yes
Intended De-registration Date:	12 Mar 2018
Vehicle Make:	TOYOTA
Vehicle Model:	COROLLA ALTIS 1.6 AUTO
Primary Colour:	Silver
Manufacturing Year:	2008
Engine No.:	3ZZ4769451
Chassis No.:	MR053ZEE106109712
Maximum Power Output:	80.0 kW (107 bhp)
Open Market Value:	\$16,777.00
Original Registration Date:	30 May 2008
First Registration Date:	30 May 2008
Transfer Count:	2
Actual ARF Paid:	\$16,777.00

Intended PARF Rebate Details

PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	29 May 2018
PARF Rebate Amount:	\$8,388.00

Intended COE Rebate Details

COE Expiry Date:	29 May 2018
COE Category:	A - Car (1600cc & below)

3/12/2018

PARF/COE Rebate Enquiry

COE Period(Years):	10
QP Paid:	\$15,701.00
COE Rebate Amount:	\$333.00
Total Rebate Amount:	\$8,721.00

The information contained herein is correct as at 12 Mar 2018

OK

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	12/03/2018 14:10
Date Of Accident	10/03/2018 16:45
Exact Location Of Accident	SIMS AVE TWDS CHANGI RD
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SJF4758X
Insured/Policyholder	
Name Of Registered Owner	ROSET LIMOUSINE SERVICES PTE LTD
Co Reg No	-
Email Address	NOEMAIL
Mobile Phone No	
Alternative Phone No	OFFICE-68445225

Vehicle Particulars

Manufacturer	TOYOTA
Model	COROLLA ALTIS
Exact Purpose for which vehicle was being used at time of accident	COMMERCIAL
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE HIRE

Insurance Company

Name of Insurance Company	EQ INSURANCE COMPANY LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	DMCFHQ17-000185
Cover Note Number	-

Driver

Name of Driver	ISMAN BIN MISTI
NRIC No	S7606997B
Date Of Birth	12/03/1976
Occupation	OUTDOOR
Date Of Driving Pass	15/04/2010
Driving Experience	7 YEARS AND 10 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-93660625
Fax Number	
Contact Number	OTHERS-92271217
EMail Address	NOEMAIL

Address	BLK 688C CHOA CHU KANG CRESCENT #08-120
Postcode	683688
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OTHER - HIRER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	COLLISION - CHANGE/CROSS LANE
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles involved in the accident	
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	5
Passenger 1	NAME: : UNKNOWN GENDER: : FEMALE
Passenger 2	NAME: : UNKNOWN GENDER: : FEMALE
Passenger 3	NAME: : UNKNOWN GENDER: : FEMALE
Passenger 4	NAME: : UNKNOWN GENDER: : MALE

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

PLEASE REFER TO ATTACHED STATEMENT.

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	XD9624K
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	COMMERCIAL VEHICLE
Name of Driver	

NRIC/Passport Number

Contact Number

Address

Postcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

Accident Sketch Plan

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes").
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.

Policyholder's Signature
Date & Time:




Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

Accident Sketch Plan

SKETCH PLAN

Sims Ave meets Changi Rd



P. SJF 1752X

B. XD9624K

[Signature]

DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

My car was stationary at the traffic light of Sims Avenue towards Changi Road due to the traffic light was red. When the traffic light was green and I was about to move (whereby my car was still in the stationary position), all of a sudden, I felt an impact from the right side portion of my car. I got off my car and found that a huge container vehicle (B) had cut into my lane and hit onto the right side portion of my car.

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder
Date & Time:



Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

...CLAIM SUBFOLDER...(Pending for Survey Report)










































CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	12 Mar 2018		13 Mar 2018 13:17 Edit Adj Rpt	S\$0.00 Edit Estimates	S\$0.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by insurer]									
Insured:	CORTINA LOGISTICS PTE LTD , Co. Reg. No.: 201108508W								
Main Claimant:	ROSET LIMOUSINE SERVICES PTE LTD , Co. Reg. No.: 200406722Z								
Vehicle Reg. No.:	SJF4758X	Date of Loss:	10/03/2018 16:00 - :59 [117 Months and 10 Days From LTA Reg Date (Man Yr)]						
Claim Type:	TP / 552081	Policy/Cover Note No.:	A28810543MKC (Comprehensive) Coverage: 27/08/2017 - 26/08/2018						
Vehicle Reg. No. (Insured):	XD9624K	Policy No. (Claimant):							
		Excess:	S\$2,000.00						
Repairer:	Teamwork Garage Pte Ltd (HQ) 53 Ubi Ave 1 #01-24, Paya Ubi Industrial Park, 408934 Ubi - Tel: 6844 2475								
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Jasmine Lok Kheng Kwei - 6594 2550]								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by BRYAN TANI] ... [Imm.Advice due 14/03/2018]								
Driver/Custodian (Insured):	HARON BIN MOHD NOOR (36 / Male), NRIC: S1383835F, Tel: +6581841837								
Adj Asg. Remarks:	Please contact MR DARREN NG @ 6844 2475 to arrange for survey								
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
There are no mail for this case.									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

***SJF4758X (552081)**
[XD9624K]
TP
ROSET LIMOUSINE SERVICES PTE LTD
Mar 10 2018 4:00PM
[CORTINA LOGISTICS PTE LTD]
Teamwork Garage Pte Ltd

Upload Documents		Upload Photos		Compose New Letter		View		View in Browser	
Assessment Reports						1 per page		<input checked="" type="checkbox"/>	
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)					Thumbnail	Print	
1	13/03/18 11:31	Accident Statement From: SC - Reg. No: XD9624K, Claimant: CORTINA LOGISTICS PTE LTD					Load HTM		
Photos/Images						3 per page		<input checked="" type="checkbox"/>	
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)					Thumbnail	Print	
1	16/07/18 17:25	Rear View Left					Load JPG	<input checked="" type="checkbox"/>	
2	16/07/18 17:25	Rear View Right					Load JPG	<input checked="" type="checkbox"/>	
3	16/07/18 17:25	General View					Load JPG	<input checked="" type="checkbox"/>	
4	16/07/18 17:25	General View					Load JPG	<input checked="" type="checkbox"/>	
5	16/07/18 17:25	General View					Load JPG	<input checked="" type="checkbox"/>	
6	16/07/18 17:25	General View					Load JPG	<input checked="" type="checkbox"/>	
7	16/07/18 17:25	General View					Load JPG	<input checked="" type="checkbox"/>	
8	16/07/18 17:25	General View					Load JPG	<input checked="" type="checkbox"/>	
9	16/07/18 17:25	General View					Load JPG	<input checked="" type="checkbox"/>	
10	16/07/18 17:25	General View					Load JPG	<input checked="" type="checkbox"/>	
11	16/07/18 17:25	General View					Load JPG	<input checked="" type="checkbox"/>	
12	16/07/18 17:25	General View					Load JPG	<input checked="" type="checkbox"/>	
13	16/07/18 17:25	General View					Load JPG	<input checked="" type="checkbox"/>	
14	16/07/18 17:25	General View					Load JPG	<input checked="" type="checkbox"/>	
15	16/07/18 17:25	General View					Load JPG	<input checked="" type="checkbox"/>	
16	16/07/18 17:25	General View					Load JPG	<input checked="" type="checkbox"/>	
17	16/07/18 17:25	General View					Load JPG	<input checked="" type="checkbox"/>	
18	16/07/18 17:25	General View					Load JPG	<input checked="" type="checkbox"/>	
19	16/07/18 17:25	General View					Load JPG	<input checked="" type="checkbox"/>	
20	16/07/18 17:25	General View					Load JPG	<input checked="" type="checkbox"/>	
21	16/07/18 17:25	General View					Load JPG	<input checked="" type="checkbox"/>	
22	16/07/18 17:25	General View					Load JPG	<input checked="" type="checkbox"/>	
23	16/07/18 17:25	General View					Load JPG	<input checked="" type="checkbox"/>	
24	16/07/18 17:25	General View					Load JPG	<input checked="" type="checkbox"/>	
25	16/07/18 17:25	General View					Load JPG	<input checked="" type="checkbox"/>	
26	16/07/18 17:25	General View					Load JPG	<input checked="" type="checkbox"/>	
27	16/07/18 17:26	General View					Load JPG	<input checked="" type="checkbox"/>	
28	16/07/18 17:26	General View					Load JPG	<input checked="" type="checkbox"/>	
29	16/07/18 17:26	General View					Load JPG	<input checked="" type="checkbox"/>	
30	16/07/18 17:26	General View					Load JPG	<input checked="" type="checkbox"/>	
31	16/07/18 17:26	General View					Load JPG	<input checked="" type="checkbox"/>	
32	16/07/18 17:26	General View					Load JPG	<input checked="" type="checkbox"/>	
33	16/07/18 17:26	Odometer Reading					Load JPG	<input checked="" type="checkbox"/>	

Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
34	16/07/18 17:26	Chassis Number	 Load JPG	<input checked="" type="checkbox"/>
35	16/07/18 17:26	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
36	16/07/18 17:26	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
37	16/07/18 17:26	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
38	16/07/18 17:26	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
39	16/07/18 17:26	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
40	16/07/18 17:26	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
41	16/07/18 17:26	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
42	16/07/18 17:26	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
43	16/07/18 17:26	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
44	16/07/18 17:26	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
45	16/07/18 17:26	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
46	16/07/18 17:26	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
47	16/07/18 17:26	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
48	16/07/18 17:26	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
49	16/07/18 17:26	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
50	16/07/18 17:26	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
51	16/07/18 17:26	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
52	16/07/18 17:26	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
53	16/07/18 17:26	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
54	16/07/18 17:26	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
55	16/07/18 17:26	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
56	16/07/18 17:26	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
57	16/07/18 17:26	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
58	16/07/18 17:26	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
59	16/07/18 17:26	Finishing Photo	 Load JPG	<input checked="" type="checkbox"/>
60	16/07/18 17:26	Finishing Photo	 Load JPG	<input checked="" type="checkbox"/>
61	16/07/18 17:26	Finishing Photo	 Load JPG	<input checked="" type="checkbox"/>
62	16/07/18 17:26	Finishing Photo	 Load JPG	<input checked="" type="checkbox"/>
63	16/07/18 17:26	Finishing Photo	 Load JPG	<input checked="" type="checkbox"/>
64	16/07/18 17:26	Finishing Photo	 Load JPG	<input checked="" type="checkbox"/>
65	16/07/18 17:26	Finishing Photo	 Load JPG	<input checked="" type="checkbox"/>
66	16/07/18 17:26	Finishing Photo	 Load JPG	<input checked="" type="checkbox"/>
67	16/07/18 17:26	Finishing Photo	 Load JPG	<input checked="" type="checkbox"/>
68	16/07/18 17:26	Finishing Photo	 Load JPG	<input checked="" type="checkbox"/>
69	16/07/18 17:26	Finishing Photo	 Load JPG	<input checked="" type="checkbox"/>
70	16/07/18 17:26	Finishing Photo	 Load JPG	<input checked="" type="checkbox"/>
71	16/07/18 17:26	Finishing Photo	 Load JPG	<input checked="" type="checkbox"/>
72	16/07/18 17:26	Finishing Photo	 Load JPG	<input checked="" type="checkbox"/>
Documentation			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
1	13/03/18 11:31	TPD SJF4758X GIA REPORT From: SC - Reg. No: XD9624K, Claimant: CORTINA LOGISTICS PTE LTD	 Load PDF	
2	13/03/18 11:37	Pre-Repair Survey	 Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)**Show Remarks To:** ☐ Handling Insurer

Note: Remarks are private unless you show it to other parties.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS3/MSG18004788/DBE2

Date: 17/07/2018

REFERENCE

Handling Insurer: MSIG Insurance (Singapore) Pte. Ltd.

Policy No: A28810543MKC

Claimant Vehicle No : SJF4758X

Insured Vehicle No : XD9624K

Date of Loss: 10/03/2018

Nature of Claim: TP

Claim No: 552081

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SJF4758X**

Make & Model: TOYOTA COROLLA ALTIS, 1.6 (A)

Engine No: 3ZZ4769451

Reg. Date: 30/05/2008 (Man. Year: 2008)

Chassis No: MR053ZEE106109712

Colour: Silver

Odometer: 198565 km

Engine Capacity: 1598 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 195/65 R15

Rear Tyre Size: 195/65 R15

Front Left Side: Bridgestone 5 mm

Rear Left Side: Bridgestone 5 mm

Front Right Side: Bridgestone 5 mm

Rear Right Side: Bridgestone 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Nett Amount (S\$)	0.00	0.00	0.00	

INSPECTION

Date of Assignment: 13/03/2018

Date Inspected: 14/03/2018 Inspected At:

Teamwork Garage Pte Ltd (HQ)
53 Ubi Ave 1 #01-24, Paya Ubi Industrial
Park
Singapore 408934

Estimated Period of Repair: 0.0 days

Adjuster: BRYAN TANI

Manager: CATHERINE CHONG KAI LING

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

- A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
- B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION.
THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE.
- C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.

THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$3,000.00 - \$3,500.00

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 17 Jul 2018)
Parts:	143	TOYOTA COROLLA ALTIS 1.6 (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SJF4758X)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

There are no new parts selected.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.

< END OF ESTIMATES >