undor:	Rachel Tion	ASSIGNMENT of	(7A1	Dat	te/Time: 1303 2018 457 pm
rom (Person); _ stimated Cost:	Kuutet luit	_ 01	ill to:		
A .	TP RES / OD RES / EV	SGQ 3338J		_ Insured:	SKF 4763T
t Workshop m/s		JEL Auto		Tel:	9231 7457
f	Blk	1 Kaki Bukit	Ave 6	# 02-11	A (.F
olicy No:		200 - 1Vr	Claim No:	CLM	M VP00 0000 645
um Insured:			Excess: _		24224
Make of Veh: _ Client's Record)		70		D.	
CA / REV /	REP. / REV 24 HRS 1 13 ()3 2()18	NP Person Contacted:	Ah Xiar		H.O.D. Endorsement:
D + T.	Action/Instruction (	V) Estimate.			NA Destru
Date/1 me	SG0 3338 J -	NA /GAII SCON	750/4		DOA: 10082018
Date/1 ime					.W.
Date/Time	9KF 4763J -	M			
Date/Time		At	-12714720	-	

# ASSIGNMENT

From: Date:	Veh No: 3603338 J. Yr Regn: 2016 / Jan.
Estimated Cost:	Type: M.Can / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
OD / TP / WS / TP RES / OD RES / EVA / INV / MV	Truck / Trailer or
To Inspect Vehicle No:	Make: Menedes Benz CLA200 cc 1595
at Workshop m/s	Colour Brawn . A/C: Insured / Std / NI / NA
of	Sp.Reading 63224. T/Radio: Insured / Std / NI / NA
Insured:	Eng/No:
Policy No.	C/No: NDD1178432×298634,
Claims No.	Gen. Cond: Good / Fair / Poor / Burnt
Sum Insured: Excess:	Steering: Inorder / Jammed / Leaked / Burnt or
(Client's Record)	Brake: Inorder / Jammed / Leaked / Burnt or
Make of Veh:	Modi: Nil / S/Rim / STD A/Rim or
	Tyre Size: F: 275/40 R18
(Policy Condition)	R: >25/40R18
Remark: The veh had commenced its N/S O/S	BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
repair at the time of inspection.	TOYO/YOKO or Contributal
Bal. or Market Value:	<u>Front</u> <u>Rear</u>
IDAC Accident Rport: Consistent? : Yes or No	R/Bal. 06 mm R/Bal. 06 mm
GIA / PR Seen: Consistent? : Yes or No	L/Bal. 06 mm L/Bal. 06 mm
Est. Repairs:days Res.: Yes or No	D.O.A. D.O.I. /3/03/18
Lum Sum: % 3 Val.: Yes or No	Survey held at
CA / REV / REP. / 24 HRS	Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or
Vehicle: IN / OUT	
Date: Person Contacted:	The U/C / Chassis frame / Body Structure affected due to collision.
Date / Time Action / Instruction  TP Great America.	
II GIRBON AIR COUNT.	
RECEIVED 2 3 WAR	2010
RECEIVED	
	Davis Of Banairy 3
Date/Time, File Pass to? : Preli. Report	Days Of Repair.
i) : Final Report	Resurvey No. of Trip: Survey Fee: Transportation:
Date/Time, File Return to?  Add Fe	
2) 33/3- typist Add Fe	: Interview (\$ ) Photos
Banari Farmat . 470	: Tech, Invs (\$ ) Others
Report Format: TP	: Weekend (\$
Lump Sum / I.B.I: (\$ >>>>>>>>>>>>>>>>>>>>>>>>>>>>>>>>>>>	OZC LATOT

Survey Department Check List (Case Handler)

Reference No.: CS GAI 1800 4793 Avb

Policy Type: OD / TP / TP RES / TL / EVA

Case Handler

**Typist** 

Customer Code Assign From Assign Date Veh No (Inspected) Veh No (Inspe	Admin (1) Offic	e Assign Form	Y-Date	N-Date	Y-Date	N-Date
Assign From Assign Date Veh No (Inspected) Veh No (Insured)  D.O.A Policy No Insurance Authorisation (CA /REV/REP) Report Type Weekend Charges Survey held at/Repairer Excess  Engine Capacity, (C.C) Colour Odometer. (Sp.Reading) Chassis No Steering Brake Modification (Modi) Tyre Bize Tyre Balance Tyre Balance Tyre Balance Date of Inspection Survey held Desof Damaged Vehicle Photographs Uploaded Torkshop Estimate /Assignment Form Att Parts condition Market Value for OD cases Estimate Repair Cost for PRI (RSI, TMI, MSIG) Days of repair Finalised Amount Realing Merity Merity Insulate Within 5 Days Insulate Insulate Insulate Within 5 Days Insulate Insulat	С	Reference No.	_ r			
Assign Date  Veh No (Inspected)  Vehicle No  Report Type  Weekend Charges  Survey held at/Repairer  Excess  Evor ( ): Case handler to make sure the surveryor completed all required inform vehicle No  Regn Month/Year  Vehicle No  Regn Month/Year  Vehicle Type  Make & Model  Engine Capacity, (C.C)  Colour  Odometer, (Sp.Reading)  Chassis No  General Condition  Steering  Brake  Modification (Modi)  Tyre Size  Tyre Make  Tyre Balance  Date of inspection  Survey held  Descof Damages  stem - (Views/Merimen)  Damaged Vehicle Photographs Uploaded  Torkshop Estimate (Assignment Form  ALL Parts condition  Market Value for OD cases  Estimate Repair Cost for PRI (RSI, TMI, MSIG)  Days of repair  Finalised Amount  Re-inspection Cases to Finalize within 5 Days  Re-inspection Cases to Finalize within 5 Days  Re-inspection Cases to Finalize within 5 Days	С	Customer Code				
Veh No (Inspected)  Veh No (Insured)  D.O.A  Policy No  Claim No  Insurance Authorisation (CA /REV/REP)  Report Type  Weekend Charges  Survey held at/Repairer  Excess  Vehicle No  Regn Month/Year  Vehicle No  Regn Month/Year  Vehicle Type  Make & Model  Engine Capacity. (C.C.)  Colour  Odometer. (Sp.Reading)  Chassis No  General Condition  Steering  Brake  In Modification (Modi)  Tyre Balance  Date of Inspection  Survey held  Desor Damages  restem - (Views/Merimen)  Damaged Vehicle Photographs Uploaded  Finalised Amount  Market Value for OD cases  Estimate Repair Cost for PRI (RSI, TMI, MSIG)  Days of repair  Finalised Amount  Finalised Amount  Regniny Classis No  Days of repair  Finalised Amount  Finalised Amount  Regniny Classis No  Arket Value for OD cases of Finalize within 5 Days  restem - (Views/Merimen)	N	Assign From				
Veh No (Insured)  D.O.A  Policy No  Claim No  Insurance Authorisation (CA /REV/REP)  Report Type  Weekend Charges  Survey held at/Repairer  Excess  eyor ( ): Case handler to make sure the surveryor completed all required inform  Vehicle No  Regn Month/Year  Vehicle Type  Make & Model  Engine Capacity, (C.C)  Colour  Odometer. (Sp.Reading)  Wentle Steering  Brake  Modification (Modi)  Tyre Size  Tyre Make  Tyre Make  Tyre Balance  Date of Inspection  Survey held  Des. of Damages  restern - (Views/Merimen)  Damaged Vehicle Photographs Uploaded  Market Value for OD cases  Estimate Repair Coses to Finalize within 5 Days  restern - (Finalised Amount)  Reinspection Cases to Finalize within 5 Days  restern - (Finalised Amount)  Reinspection Cases to Finalize within 5 Days  restern - (Finalised Amount)  Reinspection Cases to Finalize within 5 Days  restern - (Finalised Amount)  Reinspection Cases to Finalize within 5 Days  restern - (Finalised Amount)	С	Assign Date	~			
Veh No (Insured)  D.O.A  Policy No  Claim No  Insurance Authorisation (CA /REV/REP)  Report Type  Weekend Charges  Survey held at/Repairer  Excess  eyor ( ): Case handler to make sure the surveryor completed all required inform  Vehicle No  Regn Month/Year  Vehicle Type  Make & Model  Engine Capacity, (C.C)  Colour  Odometer. (Sp.Reading)  Wentle Steering  Brake  Modification (Modi)  Tyre Size  Tyre Make  Tyre Make  Tyre Balance  Date of Inspection  Survey held  Des. of Damages  restern - (Views/Merimen)  Damaged Vehicle Photographs Uploaded  Market Value for OD cases  Estimate Repair Coses to Finalize within 5 Days  restern - (Finalised Amount)  Reinspection Cases to Finalize within 5 Days  restern - (Finalised Amount)  Reinspection Cases to Finalize within 5 Days  restern - (Finalised Amount)  Reinspection Cases to Finalize within 5 Days  restern - (Finalised Amount)  Reinspection Cases to Finalize within 5 Days  restern - (Finalised Amount)	С	Veh No (Inspected)	\ \ \			
D.O.A Policy No Claim No Insurance Authorisation (CA /REV/REP) Report Type Weekend Charges Survey held at/Repairer Excess  eyor ( ): Case handler to make sure the surveryor completed all required inform signment Form Vehicle No Regn Month/Year Vehicle Type Make & Model Engine Capacity. (C.C) Colour Odometer. (Sp.Reading) Chassis No General Condition Steering Modification (Modi) Tyre Size Tyre Balance Date of inspection Survey held Dosnof Damages System - (Views/Merimen) Pays of repair Finalised Amount Finalised Amount Finalised Amount Fissignment Finalised Amount Fissignment Finalised Amount Fissignment Finalised Amount Fissignment Form Insurance Authorisation (Modi) V	c		~			
Claim No Insurance Authorisation (CA /REV/REP) Report Type Weekend Charges Survey held at/Repairer Excess  evor ( ): Case handler to make sure the surveryor completed all required inform Vehicle No Regn Month/Year Vehicle Type Make & Model Engine Capacity. (C.C) Clour Odometer. (Sp.Reading) Chassis No General Condition Steering Brake Modification (Modi) Tyre Size Tyre Balance Date of inspection Survey held Des.of Damages Surstem - (Views/Merimen) All L Parts condition Market Value for OD cases Estimate Repair Cost for PRI (RSI, TMI, MSIG) Days of repair Finalised Amount Reinspection Cases to Finalize within 5 Days Instem - (Views/Merimen) Fistems - (Views/Merimen) Fistems - (Views/Merimen) Finalised Amount Finalised Amount Finalised Amount Fistems - (Views/Merimen) Finalised Amount Fistems - (Views/Merimen) Finalised Amount Fistems - (Views/Merimen) Fistems - (Views/Merimen) Finalised Amount Fistems - (Views/Merimen) Finalised Amount Fistems - (Views/Merimen)	С	D.O.A	· ·			
Insurance Authorisation (CA /REV/REP)  Report Type Weekend Charges Survey held at/Repairer Excess  eyor ( ): Case handler to make sure the surveryor completed all required inform signment Form Vehicle No Regn Month/Year Vehicle Type Make & Model Engine Capacity. (C.C) Colour Odometer. (Sp. Reading) Chassis No General Condition Steering Brake Modification (Modi) Tyre Size Tyre Make Tyre Balance Date of Inspection Describ Damages  Firstem - (Views/Merimen) Damaged Vehicle Photographs Uploaded Corkshop Estimate/Assignment Form ALL Parts condition Alt Parts condition Days of repair Finalised Amount	С					Section Section
Report Type Weekend Charges Survey held at/Repairer Excess  Signment Form Vehicle No Regn Month/Year Vehicle Type Make & Model Engine Capacity. (C.C) Colour Odometer. (Sp.Reading) Chassis No General Condition Steering Modification (Modi) Tyre Size Tyre Balance Date of Inspection Survey held Des. of Damages System - (Views/Merimen) Market Value for OD cases Estimate Repair Cases to Finalize within 5 Days System - (Views/Merimen)  Days of repair Finalised Amount Recursive Modification Survey Modification Cases to Finalize within 5 Days System - (Views/Merimen)  Days of repair Finalised Amount Recursive Modification Survey Modification Cases to Finalize within 5 Days System - (Views/Merimen)  Days of repair Finalised Amount Recursive Market Survey Market Value for OD cases Estimate Repair Cost for PRI (RSI, TMI, MSIG)  Recircular Survey Merimen)  System - (Views/Merimen)  System - (Views/Merimen)  System - (Views/Merimen)	c	Claim No	Y			
Report Type Weekend Charges Survey held at/Repairer Excess  Signment Form Vehicle No Regn Month/Year Vehicle Type Make & Model Engine Capacity. (C.C) Colour Odometer. (Sp.Reading) Chassis No General Condition Steering Modification (Modi) Tyre Size Tyre Balance Date of Inspection Survey held Des. of Damages System - (Views/Merimen) Market Value for OD cases Estimate Repair Cases to Finalize within 5 Days System - (Views/Merimen)  Days of repair Finalised Amount Recursive Modification Survey Modification Cases to Finalize within 5 Days System - (Views/Merimen)  Days of repair Finalised Amount Recursive Modification Survey Modification Cases to Finalize within 5 Days System - (Views/Merimen)  Days of repair Finalised Amount Recursive Market Survey Market Value for OD cases Estimate Repair Cost for PRI (RSI, TMI, MSIG)  Recircular Survey Merimen)  System - (Views/Merimen)  System - (Views/Merimen)  System - (Views/Merimen)	C	Insurance Authorisation (CA /REV/REP)				
Weekend Charges    Survey held at/Repairer	C		~			
Survey held at/Repairer  Excess  Peyor ( ): Case handler to make sure the surveryor completed all required inform is ignment. Form  Vehicle No	c					
Excess  Eyor ( ): Case handler to make sure the surveryor completed all required inform signment Form  Vehicle No	N		/		8	
eyor ( ): Case handler to make sure the surveryor completed all required inform    Vehicle No	С					
Vehicle Type	910 200	nment Form				
Vehicle Type	c	Regn Month/Year				
Make & Model  Engine Capacity. (C.C)  Colour  Odometer. (Sp.Reading)  Chassis No  General Condition  Steering  Modification (Modi)  Tyre Size  Tyre Size  Tyre Balance  Date of Inspection  Survey held  Des.of Damages  Survey held  ALL Parts condition  Market Value for OD cases  Estimate Repair Cost for PRI (RSI, TMI, MSIG)  Days of repair  Market Value for Cases to Finalize within 5 Days  System - (Views/Merimen)  Re-inspection Cases to Finalize within 5 Days  System - (Views/Merimen)	N		~			
Engine Capacity. (C.C) Colour Colour Codometer. (Sp.Reading) Chassis No General Condition Steering General Condition Tyes Size Tyre Size Tyre Size Tyre Balance Date of Inspection Survey held Des. of Damages Corkshop Estimate/Assignment Form ALL Parts condition Market Value for OD cases Estimate Repair Cost for PRI (RSI, TMI, MSIG) Days of repair Finalised Amount Re-inspection Cases to Finalize within 5 Days Corkstop (Views/Merimen)	N		· ·			ete Miss
Colour Codometer. (Sp.Reading) Chassis No General Condition Steering General Condition Tyre Size Tyre Size Tyre Make Tyre Balance Date of Inspection Survey held Des. of Damages Fistem - (Views/Merimen) Corkshop Estimate/Assignment Form Market Value for OD cases Estimate Repair Cost for PRI (RSI, TMI, MSIG) Days of repair Finalised Amount Re-inspection Cases to Finalize within 5 Days Fistem - (Views/Merimen)	c					
Chassis No Chassis No General Condition Steering Steering Modification (Modi) Tyre Size Tyre Make Tyre Balance Date of Inspection Survey held Des. of Damages  Stetm - (Views/Merimen) Market Value for OD cases Estimate Repair Cost for PRI (RSI, TMI, MSIG) Days of repair Finalised Amount Re-inspection Cases to Finalize within 5 Days  Stetm - (Views/Merimen)  Finalised Amount Re-inspection Cases to Finalize within 5 Days  Stetm - (Views/Merimen)	- N				10 - 10 - 10 - 10 - 10 - 10 - 10 - 10 -	
Chassis No General Condition Steering Brake Modification (Modi) Tyre Size Tyre Size Tyre Balance Date of Inspection Survey held Des. of Damages Forkshop Estimate/Assignment Form MALL Parts condition Market Value for OD cases Estimate Repair Cost for PRI (RSI, TMI, MSIG) Market Value for OD cases Finalised Amount Re-inspection Cases to Finalize within 5 Days  Forkstone (Views/Merimen)	- <del>C</del>					
General Condition   V	c	The state of the s				
Steering	N					
Brake  Modification (Modi)  Tyre Size  Tyre Make  Date of inspection  Survey held  Des. of Damages  Stem - (Views/Merimen)  Market Value for OD cases  Estimate Repair Cost for PRI (RSI, TMI, MSIG)  Days of repair  Finalised Amount  Re-inspection Cases to Finalize within 5 Days  Stem - (Views/Merimen)	N					
Modification (Modi)  Tyre Size  Tyre Make  Tyre Balance  Date of Inspection  Survey held  Des. of Damages  Stem - (Views/Merimen)  Market Value for OD cases  Estimate Repair Cost for PRI (RSI, TMI, MSIG)  Days of repair  Finalised Amount  Re-inspection Cases to Finalize within 5 Days  Stem - (Views/Merimen)	N					
Tyre Size Tyre Make Tyre Balance Date of Inspection Survey held Des. of Damages  Stem - (Views/Merimen) Damaged Vehicle Photographs Uploaded  Sorkshop Estimate/Assignment Form ALL Parts condition Market Value for OD cases Estimate Repair Cost for PRI (RSI, TMI, MSIG) Days of repair Finalised Amount Re-inspection Cases to Finalize within 5 Days  Stem - (Views/Merimen)	N		~			
Tyre Make  Tyre Balance  Date of Inspection  Survey held  Des. of Damages  Stem - (Views/Merimen)  Damaged Vehicle Photographs Uploaded  Sorkshop Estimate/Assignment Form  ALL Parts condition  Market Value for OD cases  Estimate Repair Cost for PRI (RSI, TMI, MSIG)  Days of repair  Finalised Amount  Re-inspection Cases to Finalize within 5 Days  Stem - (Views/Merimen)	C	The state of the s				
Tyre Balance Date of Inspection  Survey held Des.of Damages  Stem - (Views/Merimen) Damaged Vehicle Photographs Uploaded  Orkshop Estimate/Assignment Form ALL Parts condition Market Value for OD cases Estimate Repair Cost for PRI (RSI, TMI, MSIG) Days of repair Finalised Amount Re-inspection Cases to Finalize within 5 Days  Stem - (Views/Merimen)	N		V			
Date of Inspection  Survey held  Des. of Damages  Stem - (Views/Merimen)  Damaged Vehicle Photographs Uploaded  Sorkshop Estimate/Assignment Form  ALL Parts condition  Market Value for OD cases  Estimate Repair Cost for PRI (RSI, TMI, MSIG)  Days of repair  Finalised Amount  Re-inspection Cases to Finalize within 5 Days  Stem - (Views/Merimen)	C	the latest and the second seco	~			
Survey held Des.of Damages  Stem - (Views/Merimen) Damaged Vehicle Photographs Uploaded  Sorkshop Estimate/Assignment Form ALL Parts condition Market Value for OD cases Estimate Repair Cost for PRI (RSI, TMI, MSIG) Days of repair Finalised Amount Re-inspection Cases to Finalize within 5 Days  Stem - (Views/Merimen)	C		~			
Des. of Damages  // Stem - (Views/Merimen)  Damaged Vehicle Photographs Uploaded  // Orkshop Estimate/Assignment Form  ALL Parts condition  Market Value for OD cases  Estimate Repair Cost for PRI (RSI, TMI, MSIG)  Days of repair  Finalised Amount  Re-inspection Cases to Finalize within 5 Days  // Stem - (Views/Merimen)	N		~			
// Stem - (Views/Merimen)  Damaged Vehicle Photographs Uploaded  // Orkshop Estimate/Assignment Form  A ALL Parts condition  Market Value for OD cases  Estimate Repair Cost for PRI (RSI, TMI, MSIG)  Days of repair  Finalised Amount  Re-inspection Cases to Finalize within 5 Days  // Stem - (Views/Merimen)	N		~			
Damaged Vehicle Photographs Uploaded  Vorkshop Estimate/Assignment Form  ALL Parts condition  Market Value for OD cases  Estimate Repair Cost for PRI (RSI, TMI, MSIG)  Days of repair  Finalised Amount  Re-inspection Cases to Finalize within 5 Days  Votem - (Views/Merimen)						
ALL Parts condition  Market Value for OD cases  Estimate Repair Cost for PRI (RSI, TMI, MSIG)  Days of repair  Finalised Amount  Re-inspection Cases to Finalize within 5 Days  vistem - (Views/Merimen)	C		T v			
ALL Parts condition  Market Value for OD cases  Estimate Repair Cost for PRI (RSI, TMI, MSIG)  Days of repair  Finalised Amount  Re-inspection Cases to Finalize within 5 Days  vstem - (Views/Merimen)					Mary Land Co.	
Market Value for OD cases  Estimate Repair Cost for PRI (RSI, TMI, MSIG)  Days of repair  Finalised Amount  Re-inspection Cases to Finalize within 5 Days  vstem - (Views/Merimen)						
Estimate Repair Cost for PRI (RSI, TMI, MSIG)  Days of repair  Finalised Amount  Re-inspection Cases to Finalize within 5 Days  vstem - (Views/Merimen)	N_			-		
Days of repair Finalised Amount Re-inspection Cases to Finalize within 5 Days rstem - (Views/Merimen)	c				-	
Finalised Amount Re-inspection Cases to Finalize within 5 Days rstem - (Views/Merimen)	С					
Re-inspection Cases to Finalize within 5 Days //stem - (Views/Merimen)	C					
ystem - (Views/Merimen)	C			-		
/stem - (Views/Merimen)	_ c_					
. Resurvey photo Opioaded	Syste C	em - (Views/Merimen) Resurvey photo Uploaded				

Check By: VERON Case Handler Date



### LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

NEW T		Affiliated to Federation Intern	ationale Des Experts En Auto	mobile
GRE	EAT AMERICAN II	NSURANCE COMPANY	Ref : CS/GAI18004	793/Avb
3 TEMASEK AVENUE #16-01 CENTENNIAL TOWER SINGAPORE 039190		Date: 13-03-2018 Code: GAI		
1.		Policy Particula	ars :- THIRD PARTY CLA	AIM
	Insured Veh.	SKF 4763T	Veh. Inspected	SGQ 3338J
	Policy No.		Coverage (\$)	0.00
	Claim No.		Excess (\$)	0.00
	Assign From	RACHEL TAN	Assign Date	13/03/2018
2.		Vehicle Pa	articulars & Condition	
	Make & Model		c.c	0
	Engine No.	HIDDEN	Year of Reg.	
Chassis No.		Colour		
Odometer -		Steering		
Brakes		Modification		
	General			
3.		Cond	ditions of Tyres	
		Size	Make	Balance
	R/H Front Tyre			mm
	L/H Front Tyre			mm
	R/H Rear Tyre			mm
	L/H Rear Tyre			mm
4.		Descri	ption of Damages	THE RESERVE
5.	rengiale No.	Gene	eral Information	
	Accident Date	10/03/2018	Inspection Date	13/03/2018
	Survey held at	JEC AUTOMOTIVE		
		1 KAKI BUKIT AVENUE 6 #02-11 AUTOBAY SINGAPORE 417883		

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

### Veron Chen (LKKAuto)

From:

Tan, Rachel <Rachel.Tan@sg.gaig.com>

Sent:

Friday, 23 March 2018 2:56 PM

To:

Veron Chen (LKKAuto)

Subject:

RE: SGQ 3338J v SKF 4763T (GA)

ORef: KSG/4613/2018/D/ct

#### CLMOMVP000000615

From: Veron Chen (LKKAuto) [mailto:veronchen@lkkauto.com]

Sent: Thursday, March 22, 2018 12:58 PM To: Tan, Rachel <Rachel.Tan@sg.gaig.com>

Cc: SUR <sur@lkkauto.com>

Subject: RE: SGQ 3338J v SKF 4763T (GA) ORef: KSG/4613/2018/D/ct

Dear Rachel,

Enclosed preliminary revised of vehicle SGQ 3338J

Date of survey: 13/3/2018 Number of days:3 days

### Please provides us the claim number.

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Veron Chen (LKKAuto)

Sent: Thursday, 15 March 2018 10:01 AM
To: 'Tan, Rachel' < Rachel. Tan@sg.gaig.com >

Cc: SUR <sur@lkkauto.com>

Subject: RE: SGQ 3338J v SKF 4763T (GA) ORef: KSG/4613/2018/D/ct

Dear Rachel,

Please be informed that we have inspected the vehicle SGQ 3338J on 13/3/2018 .

We are pending estimate from repairer.

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Catherine Chong (LKK Auto) [mailto:admin-d@lkkauto.com]

Sent: Tuesday, 13 March, 2018 7:41 PM
To: 'Tan, Rachel' <Rachel.Tan@sg.gaig.com>

Cc: 'LKK Assignments' <assignments@lkkauto.com>; 'SUR' <sur@lkkauto.com>

Subject: RE: SGQ 3338J v SKF 4763T (GA) ORef: KSG/4613/2018/D/ct

Dear Rachel,

Thank you for the assignment.

Best Regards,

Catherine Chong | Admin

LKK Auto Consultants Pte Ltd

Phone: 6741-8434 | email: <u>assignments@lkkauto.com</u> | fax: 6256-4315 Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Tan, Rachel [mailto:Rachel.Tan@sg.gaig.com]

Sent: Tuesday, 13 March, 2018 4:57 PM

To: cindy.tan@kannansg.com.sg

Cc: LKK Assignments <assignments@lkkauto.com>

Subject: FW: SGQ 3338J v SKF 4763T (GA) ORef: KSG/4613/2018/D/ct

Without Prejudice

Dear Cindy

Contents of your email noted.

Dear LKK/ Adrian Ling

Please accept assignment as SJE.

Regards

Rachel Tan

Executive, Motor Claims, Great American Insurance Company

Tel: 6804 7846

From: Cindy Tan [mailto:cindy.tan@kannansg.com.sg]

Sent: Tuesday, March 13, 2018 4:46 PM
To: Tan, Rachel < Rachel. Tan@sg.gaig.com >

Subject: RE: SGQ 3338J v SKF 4763T (GA) ORef: KSG/4613/2018/D/ct

Dear Sirs / Mdm

WITHOUT PREJUDICE

RE: PROPERTY DAMAGE CLAIM

CLAIMANT: DAIMLERFLEET MANAGEMENT SINGAPORE PTE LTD

ACCIDENT INVOLVING VEH NO. SGQ 33381 & SKF 4763T ALONG PAYA LEBAR ROAD ON 10 MARCH 2018 AT

1250 HRS

PRE-REPAIR INSPECTION NOTICE

We refer to the above matter and to your email of even date.

We are instructed to propose using Mr Adrian Ling from LKK Auto Consultants as the single joint expert as listed in your said email.

Kindly contact Ah Xian - 9232 7457 to arrange for the pre-repair inspection soonest possible.

Regards

Cindy Tan

M/S KANNAN SG Advocates & solicitors 50 Chin Swee Road #08-03 Thong Chai Building Singapore 169874

TEL: (+65) 6429 0253 FAX: (+65) 6223 1660

\*

IMPORTANT: THIS E-MAIL IS INTENDED ONLY FOR THE USE OF THE ADDRESSEE AND MAY CONTAIN CONFIDENTIAL INFORMATION AND/OR MAY BE COVERED BY PROFESSIONAL PRIVILEGE. IT MUST NOT BE READ, USED OR DISCLOSED BY ANY PERSON OTHER THAN THE ADDRESSEE(S) NAMED. IF YOU HAVE RECEIVED THIS E-MAIL IN ERROR, PLEASE NOTIFY US IMMEDIATELY BY TELEPHONE (COLLECT INTERNATIONAL CALL IF APPROPRIATE) AT (+65) 6429 0252 OR BY E-MAIL AND DELETE THE E-MAIL IMMEDIATELY. THANK YOU.

\*

From: Tan, Rachel [mailto:Rachel.Tan@sg.gaig.com]

Sent: Tuesday, 13 March, 2018 2:51 PM

To: cindy.tan@kannansg.com.sg

Subject: RE: SGQ 3338J v SKF 4763T (GA) ORef: KSG/4613/2018/D/ct

Without Prejudice

Hi Cindy

We append the following list of our panel surveyors:-

- AJAX Adjusters & Surveyors Pte Ltd
- L.B.S. Automotive Appraisal Pte Ltd
- Priority Services
- RT Appraisal Pte Ltd
- 5. LKK Auto Consultants
- JP KNIGHTS PTE LTD

Kindly let us know which SJE is selected and furnish the estimates for the survey to be carried out.

Regards

Rachel Tan

Executive, Motor Claims, Great American Insurance Company

Tel: 6804 7846

From: Cindy Tan [mailto:cindy.tan@kannansg.com.sg]

Sent: Tuesday, March 13, 2018 2:34 PM

To: General Claims < General Claims@sg.gaig.com >

Cc: Ng, Sharon < Sharon.Ng@sg.gaig.com >

Subject: RE: SKF 4763T ORef: KSG/4613/2018/D/ct

Dear Sirs / Mdm

WITHOUT PREJUDICE

RE:

PROPERTY DAMAGE CLAIM

CLAIMANT: DAIMLERFLEET MANAGEMENT SINGAPORE PTE LTD

ACCIDENT INVOLVING VEH NO. SGQ 3338J & SKF 4763T ALONG PAYA LEBAR ROAD ON 10 MARCH 2018 AT

1250 HRS

PRE-REPAIR INSPECTION NOTICE

We act for M/s Daimlerfleet Management Singapore Pte Ltd, the owners of motor vehicle No. SGQ 3338J, which was involved in the aforesaid accident.

As a result of the accident, our clients' vehicle has been damaged. Before our clients proceed to repair the damaged vehicle, please let us know within 2 working days of your receipt of this notice whether you would like to conduct a pre-repair survey of the vehicle at our clients' workshop. The details are as follows:-

Place:

M/s JEC Auto Service

1 Kaki Bukit Avenue 6

#02-11 Autobay@Kaki Bukit

Singapore 417883

Contact Person: Ah Xian - 9232 7457

If we do not receive any reply from you within the stipulated timeline, our clients shall proceed to repair the vehicle without further reference to you.

Kindly revert.

Regards

Cindy Tan

M/S KANNAN SG Advocates & solicitors 50 Chin Swee Road #08-03 Thong Chai Building Singapore 169874

TEL: (+65) 6429 0253 FAX: (+65) 6223 1660

IMPORTANT: THIS E-MAIL IS INTENDED ONLY FOR THE USE OF THE ADDRESSEE AND MAY CONTAIN CONFIDENTIAL INFORMATION AND/OR MAY BE COVERED BY PROFESSIONAL PRIVILEGE. IT MUST NOT BE READ, USED OR DISCLOSED BY ANY PERSON OTHER THAN THE ADDRESSEE(S) NAMED. IF YOU HAVE RECEIVED THIS E-MAIL IN ERROR, PLEASE NOTIFY US IMMEDIATELY BY TELEPHONE (COLLECT INTERNATIONAL CALL IF APPROPRIATE) AT (+65) 6429 0252 OR BY E-MAIL AND DELETE THE E-MAIL IMMEDIATELY. THANK YOU.

The content of this e-mail message and any attachments are confidential and may be legally privileged, intended solely for the addressee. If you are not the intended recipient, be advised that any use, dissemination, distribution, or copying of this e-mail is strictly prohibited. If you receive this message in error, please notify the sender immediately by reply email and destroy the message and its attachments.

The content of this e-mail message and any attachments are confidential and may be legally privileged, intended solely for the addressee. If you are not the intended recipient, be advised that any use, dissemination, distribution, or copying of this e-mail is strictly prohibited. If you receive this message in error, please notify the sender immediately by reply email and destroy the message and its attachments.

### Veron Chen (LKKAuto)

From:

Veron Chen (LKKAuto)

Sent:

Thursday, 22 March 2018 12:58 PM

To:

'Tan, Rachel'

Cc:

SUR

Subject:

RE: SGO 3338J v SKF 4763T (GA)

ORef: KSG/4613/2018/D/ct

Attachments:

SGQ 3338J PRELI REVISED.pdf

Dear Rachel,

Enclosed preliminary revised of vehicle SGQ 3338J

Date of survey: 13/3/2018 Number of days:3 days

### Please provides us the claim number.

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Veron Chen (LKKAuto)

Sent: Thursday, 15 March 2018 10:01 AM To: 'Tan, Rachel' <Rachel.Tan@sg.gaig.com>

Cc: SUR <sur@lkkauto.com>

Subject: RE: SGQ 3338J v SKF 4763T (GA) ORef: KSG/4613/2018/D/ct

Dear Rachel,

Please be informed that we have inspected the vehicle SGQ 3338J on 13/3/2018 .

We are pending estimate from repairer.

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Catherine Chong (LKK Auto) [mailto:admin-d@lkkauto.com]

Sent: Tuesday, 13 March, 2018 7:41 PM To: 'Tan, Rachel' < Rachel. Tan@sg.gaig.com> Cc: 'LKK Assignments' <assignments@lkkauto.com'>; 'SUR' <sur@lkkauto.com'>

Subject: RE: SGQ 3338J v SKF 4763T (GA) ORef: KSG/4613/2018/D/ct

Dear Rachel,

Thank you for the assignment.

Best Regards,

Catherine Chong | Admin

LKK Auto Consultants Pte Ltd

Phone: 6741-8434 | email: <u>assignments@lkkauto.com</u> | fax: 6256-4315 Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Tan, Rachel [mailto:Rachel.Tan@sg.gaig.com]

Sent: Tuesday, 13 March, 2018 4:57 PM

To: cindy.tan@kannansg.com.sg

Cc: LKK Assignments <assignments@lkkauto.com>

Subject: FW: SGQ 3338J v SKF 4763T (GA) ORef: KSG/4613/2018/D/ct

Without Prejudice

Dear Cindy

Contents of your email noted.

Dear LKK/ Adrian Ling

Please accept assignment as SJE.

Regards

Rachel Tan

Executive, Motor Claims, Great American Insurance Company

Tel: 6804 7846

From: Cindy Tan [mailto:cindy.tan@kannansg.com.sg]

Sent: Tuesday, March 13, 2018 4:46 PM
To: Tan, Rachel < Rachel. Tan@sg.gaig.com >

Subject: RE: SGQ 3338J v SKF 4763T (GA) ORef: KSG/4613/2018/D/ct

Dear Sirs / Mdm

WITHOUT PREJUDICE

RE: PR

PROPERTY DAMAGE CLAIM

CLAIMANT: DAIMLERFLEET MANAGEMENT SINGAPORE PTE LTD

ACCIDENT INVOLVING VEH NO. SGQ 33381 & SKF 4763T ALONG PAYA LEBAR ROAD ON 10 MARCH 2018 AT

1250 HRS

PRE-REPAIR INSPECTION NOTICE

We refer to the above matter and to your email of even date.

We are instructed to propose using Mr Adrian Ling from LKK Auto Consultants as the single joint expert as listed in your said email.

Kindly contact Ah Xian - 9232 7457 to arrange for the pre-repair inspection soonest possible.

Regards

Cindy Tan

M/S KANNAN SG Advocates & solicitors 50 Chin Swee Road #08-03 Thong Chai Building Singapore 169874

TEL: (+65) 6429 0253 FAX: (+65) 6223 1660

\*

IMPORTANT: THIS E-MAIL IS INTENDED ONLY FOR THE USE OF THE ADDRESSEE AND MAY CONTAIN CONFIDENTIAL INFORMATION AND/OR MAY BE COVERED BY PROFESSIONAL PRIVILEGE. IT MUST NOT BE READ, USED OR DISCLOSED BY ANY PERSON OTHER THAN THE ADDRESSEE(S) NAMED. IF YOU HAVE RECEIVED THIS E-MAIL IN ERROR, PLEASE NOTIFY US IMMEDIATELY BY TELEPHONE (COLLECT INTERNATIONAL CALL IF APPROPRIATE) AT (+65) 6429 0252 OR BY E-MAIL AND DELETE THE E-MAIL IMMEDIATELY, THANK YOU.

From: Tan, Rachel [mailto:Rachel.Tan@sg.gaig.com]

Sent: Tuesday, 13 March, 2018 2:51 PM

To: cindy.tan@kannansg.com.sg

Subject: RE: SGQ 3338J v SKF 4763T (GA) ORef: KSG/4613/2018/D/ct

Without Prejudice

Hi Cindy

We append the following list of our panel surveyors:-

- AJAX Adjusters & Surveyors Pte Ltd
- L.B.S. Automotive Appraisal Pte Ltd
- Priority Services
- 4. RT Appraisal Pte Ltd
- LKK Auto Consultants
- JP KNIGHTS PTE LTD

Kindly let us know which SJE is selected and furnish the estimates for the survey to be carried out.

Regards

Rachel Tan

Executive, Motor Claims, Great American Insurance Company

Tel: 6804 7846

From: Cindy Tan [mailto:cindy.tan@kannansg.com.sg]

Sent: Tuesday, March 13, 2018 2:34 PM

To: General Claims < General Claims@sg.gaig.com >

Cc: Ng, Sharon <Sharon.Ng@sg.gaig.com>

Subject: RE: SKF 4763T ORef: KSG/4613/2018/D/ct

Dear Sirs / Mdm

WITHOUT PREJUDICE

RE: PROPERTY DAMAGE CLAIM

CLAIMANT: DAIMLERFLEET MANAGEMENT SINGAPORE PTE LTD
ACCIDENT INVOLVING VEH NO. <u>SGQ 3338J</u> & SKF 4763T ALONG PAYA LEBAR ROAD ON 10 MARCH 2018 AT 1250 HRS

#### PRE-REPAIR INSPECTION NOTICE

We act for M/s Daimlerfleet Management Singapore Pte Ltd, the owners of motor vehicle No. SGQ 3338J, which was involved in the aforesaid accident.

As a result of the accident, our clients' vehicle has been damaged. Before our clients proceed to repair the damaged vehicle, please let us know within 2 working days of your receipt of this notice whether you would like to conduct a pre-repair survey of the vehicle at our clients' workshop. The details are as follows:-

Place:

M/s JEC Auto Service \_ 1 Kaki Bukit Avenue 6 #02-11 Autobay@Kaki Bukit

Singapore 417883

Contact Person: Ah Xian - 9232 7457

If we do not receive any reply from you within the stipulated timeline, our clients shall proceed to repair the vehicle without further reference to you.

Kindly revert.

Regards

Cindy Tan

M/S KANNAN SG Advocates & solicitors 50 Chin Swee Road #08-03 Thong Chai Building Singapore 169874

TEL: (+65) 6429 0253 FAX: (+65) 6223 1660

IMPORTANT: THIS E-MAIL IS INTENDED ONLY FOR THE USE OF THE ADDRESSEE AND MAY CONTAIN CONFIDENTIAL INFORMATION AND/OR MAY BE COVERED BY PROFESSIONAL PRIVILEGE. IT MUST NOT BE READ, USED OR DISCLOSED BY ANY PERSON OTHER THAN THE ADDRESSEE(S) NAMED. IF YOU HAVE RECEIVED THIS E-MAIL IN ERROR, PLEASE NOTIFY US IMMEDIATELY BY TELEPHONE (COLLECT INTERNATIONAL CALL IF APPROPRIATE) AT (+65) 6429 0252 OR BY E-MAIL AND DELETE THE E-MAIL IMMEDIATELY. THANK YOU.

\*\*\*\*\*\*\*\*\*\*\*\*

The content of this e-mail message and any attachments are confidential and may be legally privileged, intended solely for the addressee. If you are not the intended recipient, be advised that any use, dissemination, distribution, or copying of this e-mail is strictly prohibited. If you receive this message in error, please notify the sender immediately by reply email and destroy the message and its attachments.

The content of this e-mail message and any attachments are confidential and may be legally privileged, intended solely for the addressee. If you are not the intended recipient, be advised that any use, dissemination, distribution, or copying of this e-mail is strictly prohibited. If you receive this message in error, please notify the sender immediately by reply email and destroy the message and its attachments.



Company Registration No. 199607198R

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL: (065) 62563561 FAX: (065) 62564315

Your ref:

Please Advised

Our ref:

CS/GAI18004793/Avb

Date: 22/3/2018

The Motor Claims Department

Without Prejudice

M/s: GREAT AMERICAN INSURANCE COMPANY

Dear Sir/Madam,

### PRELIMINARY ADVICE OF VEHICLE NO.SGQ 3338J

We thank you for your instruction on 13/3/2018

Please be informed that we had conducted the inspection of the above mentioned vehicle on 13/3/2018 at the premises of M/s JEC AUTOMOTIVE and have the following to report:-

Workshop Estimate Amount	: S\$5,232.00		
Revised Estimate Amount	: S\$2,200.00 (LUMP SUM)		
"Check" Items Amount	: S\$		
Market Value	: S\$		
LTA Reimbursement Value	: S\$		
Nett Value	: S\$		

Description of Damage: The vehicle sustained damages at the rear portion. rear front offside

Comments/Present Status: Damages Consistent

Yours faithfully,

ADRIAN LING WAI PING
B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI
Licensed Appraiser

### Veron Chen (LKKAuto)

From:

Veron Chen (LKKAuto)

Sent:

Thursday, 15 March 2018 10:01 AM

To:

'Tan, Rachel'

Cc:

SUR

Subject:

RE: SGQ 3338J v SKF 4763T (GA)

ORef: KSG/4613/2018/D/ct

Dear Rachel,

Please be informed that we have inspected the vehicle SGQ 3338J on 13/3/2018 .

We are pending estimate from repairer.

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Catherine Chong (LKK Auto) [mailto:admin-d@lkkauto.com]

Sent: Tuesday, 13 March, 2018 7:41 PM

To: 'Tan, Rachel' < Rachel. Tan@sg.gaig.com >

Cc: 'LKK Assignments' <assignments@lkkauto.com>; 'SUR' <sur@lkkauto.com>

Subject: RE: SGQ 3338J v SKF 4763T (GA) ORef: KSG/4613/2018/D/ct

Dear Rachel,

Thank you for the assignment.

Best Regards,

Catherine Chong | Admin

LKK Auto Consultants Pte Ltd

Phone: 6741-8434 | email: <u>assignments@lkkauto.com</u> | fax: 6256-4315 Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Tan, Rachel [mailto:Rachel.Tan@sg.gaig.com]

Sent: Tuesday, 13 March, 2018 4:57 PM

To: cindy.tan@kannansg.com.sg

Cc: LKK Assignments <assignments@lkkauto.com>

Subject: FW: SGQ 3338J v SKF 4763T (GA) ORef: KSG/4613/2018/D/ct

Without Prejudice

Dear Cindy

Contents of your email noted.

Dear LKK/ Adrian Ling

Please accept assignment as SJE.

Regards

Rachel Tan

Executive, Motor Claims, Great American Insurance Company

Tel: 6804 7846

From: Cindy Tan [mailto:cindy.tan@kannansg.com.sg]

Sent: Tuesday, March 13, 2018 4:46 PM
To: Tan, Rachel < Rachel. Tan@sg.gaig.com >

Subject: RE: SGQ 3338J v SKF 4763T (GA) ORef: KSG/4613/2018/D/ct

Dear Sirs / Mdm

WITHOUT PREJUDICE

RE:

PROPERTY DAMAGE CLAIM

CLAIMANT: DAIMLERFLEET MANAGEMENT SINGAPORE PTE LTD

ACCIDENT INVOLVING VEH NO. SGQ 3338J & SKF 4763T ALONG PAYA LEBAR ROAD ON 10 MARCH 2018 AT

1250 HRS

PRE-REPAIR INSPECTION NOTICE

We refer to the above matter and to your email of even date.

We are instructed to propose using Mr Adrian Ling from LKK Auto Consultants as the single joint expert as listed in your said email.

Kindly contact Ah Xian - 9232 7457 to arrange for the pre-repair inspection soonest possible.

Regards

Cindy Tan

M/S KANNAN SG Advocates & solicitors 50 Chin Swee Road #08-03 Thong Chai Building Singapore 169874

TEL: (+65) 6429 0253 FAX: (+65) 6223 1660

IMPORTANT: THIS E-MAIL IS INTENDED ONLY FOR THE USE OF THE ADDRESSEE AND MAY CONTAIN CONFIDENTIAL INFORMATION AND/OR MAY BE COVERED BY PROFESSIONAL PRIVILEGE. IT MUST NOT BE READ, USED OR DISCLOSED BY ANY PERSON OTHER THAN THE ADDRESSEE(S) NAMED. IF YOU HAVE RECEIVED THIS E-MAIL IN ERROR, PLEASE NOTIFY US IMMEDIATELY BY TELEPHONE (COLLECT INTERNATIONAL CALL IF APPROPRIATE) AT (+65) 6429 0252 OR BY E-MAIL AND DELETE THE E-MAIL IMMEDIATELY. THANK YOU.

\*\*\*\*\*\*\*\*\*\*\*\*

From: Tan, Rachel [mailto:Pachel.Tan@sg.gaig.com]

Sent: Tuesday, 13 March, 018 2:51 PM

To: cindy.tan@kannansm.com.sg

Subject: RE: SGQ 33381 v SKF 4763T (GA) ORef: KSG/4613/2018/D/ct

Without Prejudice

#### Hi Cindy

We append the following list of our panel surveyors:-

- AJAX Adjusters & Surveyors Pte Ltd
- 2. L.B.S. Automotive Appraisal Pte Ltd
- Priority Services
- 4. RT Appraisal Pte Ltd
- LKK Auto Consultants
- JP KNIGHTS PTE LTD

Kindly let us know which SIE is selected and furnish the estimates for the survey to be carried out.

Regards

Rachel Tan

Executive, Motor Claims, Great American Insurance Company

Tel: 6804 7846

From: Cindy Tan [mailto:cindy.tan@kannansg.com.sg]

Sent: Tuesday, Marc 13, 18 2:34 PM

To: General Claims < General Claims@sg.gaig.com>

Cc: Ng, Sharon < Sharon. Ng @sg.gaig.com >

Subject: RE: SKF 4763T ORef: KSG/4613/2018/D/ct

Dear Sirs / Mdm

#### WITHOUT PREJUDICE

RE: PROPERTY DAMAGE CLAIM

CLAIMANT: 1 SLEET MANAGEMENT SINGAPORE PTE LTD

ACCIDENT IN VEH NO. SGQ 3338J & SKF 4763T ALONG PAYA LEBAR ROAD ON 10 MARCH 2018 AT

1250 HRS

PRE-REPAIR INSPECTION NOTICE

We act for M/s Daimlerfleet Management Singapore Pte Ltd, the owners of motor vehicle No. SGQ 3338J, which was involved in the aforesaid accident.

As a result of the accident, our clients' vehicle has been damaged. Before our clients proceed to repair the damaged vehicle, please let us the latest and like 2 working days of your receipt of this notice whether you would like to conduct a pre-repair survey of the latest clients' workshop. The details are as follows:-

Place:

M/ In Service

1 Kaki Bukit Avenue 6

#02-11 Autobay@Kaki Bukit

Singapore 417883

Contact Person: Ah Man - 0232 7457

If we do not receive an an advant you within the stipulated timeline, our clients shall proceed to repair the vehicle without further references you.

Kindly revert.

Regards

Cindy Tan

M/S KANNAN SG

Advocates & solicitors
50 Chin Swee Road
#08-03 Thong Chai Building
Singapore 169874

TEL: (+65) 6429 0253 FAX: (+65) 6223 1

IMPORTANT: THIS E-MAIL IS INTENDED ONLY FOR THE USE OF THE ADDRESSEE AND MAY CONTAIN CONFIDENCIAL INFORMATION AND/OR MAY BE COVERED BY PROFESSIONAL PRIVILEGE. IT MUSE IF BE READ, USED OR DISCLOSED BY ANY PERSON OTHER THAN THE ADDRESSEE(S) NAMED IF YOU HAVE RECEIVED THIS E-MAIL IN ERROR, PLEASE NOTIFY US IMMEDIATELY BY THE PHONE (COLLECT INTERNATIONAL CALL IF APPROPRIATE) AT (+65) 6429 0252 OR BY THE AND DELETE THE E-MAIL IMMEDIATELY, THANK YOU.

\*

The content of this e-mail message are authorized and may be legally privileged, intended solely for the addressee. If you are not the intended recipient, be advised that the second action of this e-mail is strictly prohibited. If you receive this message in error, please notify the sender immediately by reply email at a trace and its attachments.

The content of this e-mail mids and attachments are confidential and may be legally privileged, intended solely for the addressee. If you are not the intended recipient, be advised that any an advised that any and a substantial that are confidential and may be legally privileged, intended solely for the addressee. If you are not the intended recipient, be advised that any an advised that any advised th

### Nivitha (LKK Auto)

From:

Tan, Rachel < Rachel.Tan@sg.gaig.com>

Sent:

Tuesday, 13 March 2018 4:57 PM

To:

cindy.tan@kannansg.com.sg

Cc:

LKK Assignments

Subject:

FW: SGQ 3338J v SKF 4763T (GA)

ORef: KSG/4613/2018/D/ct

Without Prejudice

Dear Cindy

Contents of your email noted.

Dear LKK/ Adrian Ling

Please accept assignment as SJE.

Regards

Rachel Tan

Executive, Motor Claims, Great American Insurance Company

Tel: 6804 7846

From: Cindy Tan [mailto:cindy.tan@kannansg.com.sg]

Sent: Tuesday, March 13, 2018 4:46 PM To: Tan, Rachel < Rachel. Tan@sg.gaig.com>

Subject: RE: SGQ 3338J v SKF 4763T (GA) ORef: KSG/4613/2018/D/ct

Dear Sirs / Mdm

WITHOUT PREJUDICE

RE:

PROPERTY DAMAGE CLAIM

CLAIMANT: DAIMLERFLEET MANAGEMENT SINGAPORE PTE LTD

ACCIDENT INVOLVING VEH NO. SGQ 3338J & SKF 4763T ALONG PAYA LEBAR ROAD ON 10 MARCH 2018 AT

1250 HRS

PRE-REPAIR INSPECTION NOTICE

We refer to the above matter and to your email of even date.

We are instructed to propose using Mr Adrian Ling from LKK Auto Consultants as the single joint expert as listed in your said email.

Kindly contact Ah Xian - 9232 7457 to arrange for the pre-repair inspection soonest possible.

Regards

Cindy Tan

M/S KANNAN SG Advocates & solicitors 50 Chin Swee Road #08-03 Thong Chai Building Singapore 169874

TEL: (+65) 6429 0253 FAX: (+65) 6223 1660

IMPORTANT: THIS E-MAIL IS INTENDED ONLY FOR THE USE OF THE ADDRESSEE AND MAY CONTAIN CONFIDENTIAL INFORMATION AND/OR MAY BE COVERED BY PROFESSIONAL PRIVILEGE. IT MUST NOT BE READ, USED OR DISCLOSED BY ANY PERSON OTHER THAN THE ADDRESSEE(S) NAMED. IF YOU HAVE RECEIVED THIS E-MAIL IN ERROR, PLEASE NOTIFY US IMMEDIATELY BY TELEPHONE (COLLECT INTERNATIONAL CALL IF APPROPRIATE) AT (+65) 6429 0252 OR BY E-MAIL AND DELETE THE E-MAIL IMMEDIATELY. THANK YOU.

From: Tan, Rachel [mailto:Rachel.Tan@sg.gaig.com]

Sent: Tuesday, 13 March, 2018 2:51 PM

To: cindy.tan@kannansg.com.sg

Subject: RE: SGQ 3338J v SKF 4763T (GA) ORef: KSG/4613/2018/D/ct

Without Prejudice

Hi Cindy

We append the following list of our panel surveyors:-

- AJAX Adjusters & Surveyors Pte Ltd
- L.B.S. Automotive Appraisal Pte Ltd
- 3. Priority Services
- 4. RT Appraisal Pte Ltd
- 5. LKK Auto Consultants
- JP KNIGHTS PTE LTD

Kindly let us know which SJE is selected and furnish the estimates for the survey to be carried out.

Regards

Rachel Tan

Executive, Motor Claims, Great American Insurance Company

Tel: 6804 7846

From: Cindy Tan [mailto:cindy.tan@kannansg.com.sg]

Sent: Tuesday, March 13, 2018 2:34 PM

To: General Claims < General Claims@sg.gaig.com>

Cc: Ng, Sharon < Sharon.Ng@sg.gaig.com>

Subject: RE: SKF 4763T ORef: KSG/4613/2018/D/ct

Dear Sirs / Mdm

WITHOUT PREJUDICE

RE:

PROPERTY DAMAGE CLAIM

CLAIMANT: DAIMLERFLEET MANAGEMENT SINGAPORE PTE LTD

ACCIDENT INVOLVING VEH NO. SGQ 3338J & SKF 4763T ALONG PAYA LEBAR ROAD ON 10 MARCH 2018 AT

1250 HRS

PRE-REPAIR INSPECTION NOTICE

We act for M/s Daimlerfleet Management Singapore Pte Ltd, the owners of motor vehicle No. SGQ 3338J, which was involved in the aforesaid accident.

As a result of the accident, our clients' vehicle has been damaged. Before our clients proceed to repair the damaged vehicle, please let us know within 2 working days of your receipt of this notice whether you would like to conduct a pre-repair survey of the vehicle at our clients' workshop. The details are as follows:-

Place:

M/s JEC Auto Service

1 Kaki Bukit Avenue 6 #02-11 Autobay@Kaki Bukit Singapore 417883

Contact Person: Ah Xian - 9232 7457

If we do not receive any reply from you within the stipulated timeline, our clients shall proceed to repair the vehicle without further reference to you.

Kindly revert.

Regards

Cindy Tan

M/S KANNAN SG Advocates & solicitors 50 Chin Swee Road #08-03 Thong Chai Building Singapore 169874

TEL: (+65) 6429 0253 FAX: (+65) 6223 1660

IMPORTANT: THIS E-MAIL IS INTENDED ONLY FOR THE USE OF THE ADDRESSEE AND MAY CONTAIN CONFIDENTIAL INFORMATION AND/OR MAY BE COVERED BY PROFESSIONAL PRIVILEGE. IT MUST NOT BE READ, USED OR DISCLOSED BY ANY PERSON OTHER THAN THE ADDRESSEE(S) NAMED. IF YOU HAVE RECEIVED THIS E-MAIL IN ERROR, PLEASE NOTIFY US IMMEDIATELY BY TELEPHONE (COLLECT INTERNATIONAL CALL IF APPROPRIATE) AT (+65) 6429 0252 OR BY E-MAIL AND DELETE THE E-MAIL IMMEDIATELY, THANK YOU.

\*\*\*\*\*\*\*\*\*\*\*\*\*

The content of this e-mail message and any attachments are confidential and may be legally privileged, intended solely for the addressee. If you are not the intended recipient, be advised that any use, dissemination, distribution, or copying of this e-mail is strictly prohibited. If you receive this message in error, please notify the sender immediately by reply email and destroy the message and its attachments.

The content of this e-mail message and any attachments are confidential and may be legally privileged, intended solely for the addressee. If you are not the intended recipient, be advised that any use, dissemination, distribution, or copying of this e-mail is strictly prohibited. If you receive this message in error, please notify the sender immediately by reply email and destroy the message and its attachments.

MSME18034702 / SME Motor Pte Ltd - Kaki Bukit ENTRY DATE & TBME: 13/03/2018 15:46 SUBMITTED BY: Chia Pei Ying

### Your NCD will be affected due to late reporting Actual e-Filling Submission Date & Time: 13/03/2018 16:13

## SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

- 1. Please report correctly the details of the accident to speed up the claims process.
- 3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or witholding of material facts may allow insurance companies to 2. This Form must be completed by the Policyholder and/or the Authorised Driver.
- 4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
- This issue and acceptance of this country integration to the Police for investigation.
   Any false reporting may be referred to the Police for investigation.
   This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.

Any false reporting may be referred to the Police for Investiga- This report will be forwarded by the insurers of the GIA Records M rehiving and that copies of this report will, for a fee, be made available to the leaderment of this report to the insurers, you hereby consen-	lanagement Centre established by orders.  ble upon application by interested parties.  It to the archiving of this report at the centre and to copies of the report being made available to the archiving of this report at the centre and to copies of the report being made available.
By the loogement of usar operation	ACCIDENT STATEMENT
	13/03/2018 15:46
	10/03/2018 12:50
11-4	PAYA LEBAR RD
Of Accident	SINGAPORE
	ETAILS OF OWN VEHICLE
D	
Vehicle Registration Number	SGQ3338J
RELICE UPON CYPOID OF	DAMIER FLEET MANAGEMENT SINGAPORE PTE LTD
Name Of Registered Owner	
Co Reg No	199803778Z
Email Address	NOEMAIL
Mobile Phone No	22.07.0040646
Alternative Phone No	OFFICE-68498145
Vehicle Particulars	MERCEDES-BENZ
Manufacturer	
Model	C200
Exact Purpose for which vehicle was being used a time of accident	
Are you claiming under your own insurance policy	NO
for repair to your venicle?	THIRD PARTY
If No, Please state action to be taken	PRIVATE CAR
Vehicle Category	
Insurance Company	AIG ASIA PACIFIC INSURANCE PTE, LTD.
Name of Insurance Company	COMPREHENSIVE
Type Of Coverage	NO
Fleet Policy	999994843/100782243-00000
Policy Number	
Cover Note Number	
Basses	LIM XIAO CHUAN
Name of Driver	S8028723B

S8028723B NRIC No 21/09/1980 Date Of Birth INDOOR Occupation 19/05/2001 Date Of Driving Pass

16 YEARS AND 9 MONTHS

**Driving Experience** MALE

Gender (LOCAL) +65-81888770 Mobile Number

Fax Number

Contact Number NOEMAIL EMail Address

Page 1 of 14

23 COMPASSVALE ROAD #08-25 Address

Postcode

Was driver an employee of the Insured's Company YES

If No, Relationship of the Driver with the Insured

Vehicle Registration Number of Driver's Own

Vehicle

Insurance Company of Driver's Own Vehicle

ern information of the Accident COLLISION - HEAD TO REAR

Type Of Accident

CLEAR

Weather Conditions Road Surface

DRY

Other to Christian Was any foreign vehicle involved in this accident? NO

Number of vehicles involved in the accident

Was any body injured in the Accident?

YES

Was any injured conveyed to hospital by

NO

ambulance? Was any other material or property damaged?

YES

I have been approached by unknown person(s)

soliciting/offering accident claims assistance.

NO

Number of Passengers (Including Driver)

2

Passenger 1

: MAY KOH CHENG MUI NAME:

GENDER:

: FEMALE

Delike of Police Action

Was the accident reported to the police?

NO

If Yes, Please state which Police Station

Was notice of intended Prosecution given?

NO

If Yes, against whom?

ON 10/03/2018 AT AROUND 12.50PM, I WAS TRAVELLING ALONG PAYA LEBAR ROAD AND STOPPED AT THE JUNCTION OF PAYA LEBAR ROAD AND PIE BECAUSE OF RED LIGHT. AFTER A FEW SECONDS, A CAR CAME FROM BEHIND AND

HIT INTO THE BACK OF MY CAR.

Cachinett(s) Are accident photos available for attachment?

YES

Was there any video captured by Car Camera?

NO

Was there any audio recorded?

NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number

SKF4763T

Vehicle Make/Model/Colour

VEHICLE B

**Details Of Properties** Vehicle Category

PRIVATE CAR

Name of Driver

NRIC/Passport Number

87231473

Contact Number

Address

Postcode

Insurance Company Name

Nature Of Damage

Page 2 of 14

# No. Of Passenger (Including Driver)

# DETAILS OF INJURED PERSON 1

Name

LIM XIAO CHUAN

Approximate Age

Injuries Sustain

Injured person in which vehicle?

SGQ3338J

Were seat belts wom?

Was this injured conveyed to hospital by

ambulance?

Address

Postcode

### Sketch Plan Pg. 1

### SKETCH PLAN

# HAP SHANTNOTICE

- 1. PERSON CONTESTS THE details of the accident to speed up this cisims persons.
- 2. Tanis form must be completed by the Poscoplation and for the Authorised Driver S. An information provided must be as truckful and accorate as possible. Any writed presupercontaction of withholding of trialested
- feature of the insurance companies to recording notice insulate. A. The base and prospositor of this Form by insurance companies is not an actualistic of policy appear on the part of the implicance.
- 5. And the coording may be referred to the Police for investigation. 6. The report will be forwarded by the Insurers of the GIA Records histogenest Centre established by the Seneral Insurance in American Seneral Seneral Seneral Insurance by American of Seneral Senera
- T. Say the landsmoot of this reported the insurers, you haveby consent to the archaring of this report at the centre and to copies of the report being made available aforeseld.
- \$. Consequence the Personal Cala Protection Act (POPA)
- Ny brainar, my workshop and the General insurance Association of Singapor a (\* 662\*) may/are perspect to collect, one, my brainar, my workshop and the General insurance Association of Singapor a (\* 662\*) may/are perspect to collect, one, may be soon a description of Singapor a (\* 662\*) and disclose and transfer guest description of the process my becomes insurance (collectively the "personal insurance (and disclose and transfer guest description) and disclose and transfer guest description of the collection of the personal insurance and personal may be been insurance and transfer description of the social and the collection of the social personal and the personal and personal and personal and the personal and p I understand, admonission large and consent that (at) My brancer, my workshop and the General Insurance Ass
  - (8) processing, handling anti/or dealing with my deline including the customent of the cides and any nearstant investigations relating to the diskore
  - (ii) investigating the eccident and/or my claims;
  - Will carrying out another dealing with my instructions or responding to any ampointes by me
  - deductionable my claims (including the mailing of correspondence, statements, invokes, reports or notices to me, which could broke disclosure of corresponding about me to bring about disclosury states assure as and as on the experience of corresponding and/or experience or envelopes/mail packages; and/or
  - No complete with spokeshie law in administrating, processing, baseding und/or depling with my characteristics and processing and/or depling with my characteristics and processing and the depline with my characteristics and the processing and the depline with my characteristics and the processing and the depline with my characteristics and the processing and the depline with my characteristics and the processing and the depline with my characteristics and the processing and the depline with my characteristics and the processing and the depline with the processing and the processing and
  - as source(s) who have insured vehicle(s) involved in this accident and the involved lawyers/hav layer, may are personal to collect, use, disclose strat/or process my Personal information for one or more of the above Purposes, and
  - my Personal Information may/can be disclosed by any of the locurers and/or GIA to their third party service peopless or appetition under the local party service provides or appetition under lawyers/local firms), under many be sized outside of Singapore, for one or more of the above Purpose
  - (d) My Petronal information will state be collected and used to combine chiens bishors for the propose of traud desertion, interesting the management in present and all future claims.
  - (d) above may be shared / disclosed:
- @ so, all insurers and/or any other third parties that assist in eventually, issuestigation, controlling or issued fraud, regulators, law anforcement and procument agencies as ressentably required for the purposes stated, or


complying with reconstructive product any regu

og Centire Personner's Sig

Market Scientification ST

Jec

### Sketch Plan #2 Pg. 1



TP Great American Veron.

5643338J

Mercelus Benz CLA 200

WDD1179432N299634

1285 ~ Ros Brupes Defamed 50 / Pees Burges aigs New 58x2=116 X Ross Burger Side Holder XOZ Nor Peer Buyer lower Garrish out Rees Bunper Reinforcement Dented 408 4 Rear Bunger Lower Chrone Moulding . No Reverse Sensor x 04 I piece dange 280x4=1120

LKK Auto Consultants her se notifices Exhaut Chrome Pipe x 02 New the Repairer of the following:

185×2= 370 ×

. To resurvey potote after spray painting

- To display demagration (s) during resurvey
- Parts prices are \_\_\_\_\_\_\_\_restlimation
- . Third party survey is on a "V-thout Prejudice" basis
- . No illegal modification(s) is allowed
- . Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Panel Bouting.

Spony Poulting.

To remove revesse sensor

400 200

400 250

50 30

150.60

5232

Wist: 2468

Less 10%, 222120

Labour 540

total: 2761.20



### LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

10世		Affiliated to Federation Internat	ionale Des Experts En Auton	nobile
GRE	AT AMERICAN IN	SURANCE COMPANY	Ref : CS/GAI180047	93/Avbn2
¥16-	MASEK AVENUE -01 CENTENNIAL GAPORE 039190	TOWER	Date: 27-03-2018	
1.		Policy Particular	s :- THIRD PARTY CLAI	M
	Insured Veh.	SKF 4763T	Veh. Inspected	SGQ 3338J
	Policy No.		Coverage (\$)	0.00
	Claim No.	CLMOMVP000000615	Excess (\$)	0.00
	Assign From	RACHEL TAN	Assign Date	13/03/2018
2.		Vehicle Par	ticulars & Condition	
	Make & Model	MERCEDES BENZ CLA200	c.c	1595
	Engine No.	HIDDEN	Year of Reg.	2016
	Chassis No.	WDD1179432N299634	Colour	BROWN
	Odometer	63224	Steering	IN ORDER
	Brakes	IN ORDER	Modification	SPORTS RIM
	General	GOOD		
3.		Cond	itions of Tyres	
		Size	Make	Balance
	R/H Front Tyre	225/40 R18	CONTINENTAL	6 mm
	L/H Front Tyre	225/40 R18	CONTINENTAL	6 mm
	R/H Rear Tyre	225/40 R18	CONTINENTAL	6 mm
	L/H Rear Tyre	225/40 R18	CONTINENTAL	6 mm
4.		Descrip	tion of Damages	
	THE VEHICLE SU	STAINED DAMAGES AT THE R	EAR PORTION.	
	DAMAGES SEE D	ETAILS.		
5.		Gene	ral Information	
	Accident Date	10/03/2018	Inspection Date	13/03/2018
	Survey held at	JEC AUTOMOTIVE	0;	
		1 KAKI BUKIT AVENUE 6 #02-11 AUTOBAY SINGAPORE 417883		
5a.			Remarks	
	A)THE INSPECTION B)IN ACCORDANGE	ON WAS CONDUCTED ON A"W CE TO YOUR INSTRUCTIONS,	ITHOUT PREJUDICE" BAS WE HAVE NOT AUTHORIS	SIS. SED REPAIRS.
5b.		Estimat	e Days of Repair	
	ESTIMATED NOR	MAL PERIOD FOR REPAIR:	3 Working Day	ys



### LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

### ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SGQ 3338J

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
1	REAR BUMPER	DEFORMED	1,285.00	1,285.00
1	REAR BUMPER CLIPS	NECESSARY	50.00	50.00
2	REAR BUMPER SIDE HOLDER @\$58.00	NOT NECESSARY	116.00	
1	REAR BUMPER LOWER GARNISH	CUT	298.00	298.00
1	REAR BUMPER REINFORCEMENT	DENTED	585.00	585.00
1	REAR BUMPER LOWER CHROME MOULDING	NOT NECESSARY	408.00	-
4	REVERSE SENSOR	DAMAGED (1 PC ONLY)	1,120.00	250.00
2	REAR EXHAUST CHROME PIPE @\$185.00	NOT NECESSARY	370.00	-
	LESS 10% DISCOUNT		172	-246.80
			4,232.00	2,221.20
	LABOUR			
	PANEL BEATING.		400.00	200.00
	SPRAY PAINTING.		400.00	250.00
	WIRING.		50.00	30.00
	TO REMOVE REVERSE SENSOR.		150.00	60.00
			1,000.00	540.00
	GRAND TOTAL		5,232.00	2,761.20
_	DECOMMENDED COST OF LUMB SUM DEDAIDS			2 200 00

RECOMMENDED COST OF LUMP SUM REPAIRS	2,200.00
(TO ITS PRE-ACCIDENT CONDITION)	

Report Ref No. CS/GAI18004793/Avbn2

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES: This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contact or tort, is accepted to any third party who may reply on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.