

ASS. REC. BY:

REF: CS/MSG18004804/Ugdn2 Special Instruction:

SALES/OT:

ASSIGNMENT (Office)

From (Person):

Christina Wong

of

MSTN

Date/Time: 15/3/2018 8:43am

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SKA 2813Y

Insured:

SLH 367TT

at Workshop m/s

Jin Auto

Tel:

of

14 Defu Lane 10 #01-410 / 412

Policy No:

80443777 DMY

Claim No:

550084

Sum Insured:

Excess:

D.O.A.

12032018

Make of Veh:

(Client's Record)

H.O.D. Endorsement:

CA / REV / REP. / REV 24 HRS WPI

Date/Time:

Person Contacted:

Vehicle IN/OUT

| Date/Time        | Action/Instruction (✓) Estimate        |
|------------------|----------------------------------------|
|                  | SKA 2813Y - 006 / 17/11/2015 / Kwm302  |
|                  | SLH 367TT - X                          |
| 19/3/18 @ 5:05pm | revised to Christina Wong via Meinmen. |
|                  |                                        |
|                  |                                        |
|                  |                                        |
|                  |                                        |

(08/11/13) wef

ASS. REC. BY: *Marcus*

REF:

*MS14/*

## ASSIGNMENT

From: \_\_\_\_\_ Date: \_\_\_\_\_

Estimated Cost: \_\_\_\_\_

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: *SKA 28134*at Workshop m/s *J. n. Ave*

of \_\_\_\_\_

Insured: \_\_\_\_\_

Policy No. \_\_\_\_\_

Claims No. \_\_\_\_\_

Sum Insured: \_\_\_\_\_ Excess: \_\_\_\_\_

(Client's Record)

Make of Veh: \_\_\_\_\_

(Policy Condition)

Remark: The veh had commenced its  
repair at the time of inspection.

|     |     |
|-----|-----|
|     |     |
| N/S | O/S |
|     |     |

Bal. or Market Value: *74*IDAC Accident Rpt: *✓* Consistent? : Yes or NoGLA / PR Seen: *✓* Consistent? : Yes or NoEst. Repairs: *4* days Res.: Yes or NoLum Sum: *5* % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: \_\_\_\_\_ Person Contacted: \_\_\_\_\_

Vehicle: IN / OUT

Veh No: *SKA28134* Yr Regn: *2.11*Type: *M.Car* / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /Truck / Trailer or *CA*Make: *VOLVO XC90* c.c. *3192*Colour: *Grey* A/C: Insured / Std / NI / NASp. Reading: *116674* T/Radio: Insured / Std / NI / NA

Eng/No: \_\_\_\_\_

C/No: *VU1CT9556B1590726*Gen. Cond: *Good* / Fair / Poor / BurntSteering: *In order* / Jammed / Leaked / Burnt orBrake: *In order* / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: *255/50R19*

R: \_\_\_\_\_

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front *6* mm Rear *6* mmR/Bal. *6* mm R/Bal. *6* mmL/Bal. *6* mm L/Bal. *6* mmD.O.A. *12/3/18* D.O.I. *17/3/18*

Survey held at \_\_\_\_\_

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

*Rear*

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

*17952983 Dep 15k. next Mc.**huger 1912.45, huger lower 1873.78 sensor 300.38 chrom 814.05**Exhaust cost price 8980**workshop, mon p/p repair agree reduce 5% on total cost**confirmed repair sum \$ 7700 with Jones.**Note new parts replacement.**(hed 89229.11, 56%)**✓ 11/4*

Date/Time, File Pass to?

☐ : Preli. Report*11/4/18*☐ : Final Report

Date/Time, File Return to?

2)

Report Format :

*MER-7P*Lump Sum / I.B.I. (\$) *7700*Days Of Repair: *4*

Resurvey No. of Trip: \_\_\_\_\_

Add Fee:

☐ : Site Insp (\$ \_\_\_\_\_)☐ : Interview (\$ \_\_\_\_\_)☐ : Tech. Invs (\$ \_\_\_\_\_)☐ : Weekend (\$ \_\_\_\_\_)

Survey Fee:

Transportation:

Photos

Others

TOTAL

*300**10**310*

RECEIVED 12 APR 2018



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

| Affiliated to Federation Internationale Des Experts En Automobile                                                    |                                                                                 |                 |                          |                                                                                     |
|----------------------------------------------------------------------------------------------------------------------|---------------------------------------------------------------------------------|-----------------|--------------------------|-------------------------------------------------------------------------------------|
| MSIG INSURANCE (SINGAPORE) PTE LTD                                                                                   |                                                                                 |                 | Ref : CS/MSG18004804/Uqb |                                                                                     |
| 16 RAFFLES QUAY<br>#24-01 HONG LEONG BLDG SINGAPORE 048581                                                           |                                                                                 |                 | Date : 14-03-2018        |  |
|                                                                                                                      |                                                                                 |                 | Code : MSG               |                                                                                     |
| <b>1. Policy Particulars :- THIRD PARTY CLAIM</b>                                                                    |                                                                                 |                 |                          |                                                                                     |
| Insured Veh.                                                                                                         | SLH 3677T                                                                       | Veh. Inspected  | SKA 2813Y                |                                                                                     |
| Policy No.                                                                                                           | 80443777QMY                                                                     | Coverage (\$)   | 0.00                     |                                                                                     |
| Claim No.                                                                                                            | 552084                                                                          | Excess (\$)     | 0.00                     |                                                                                     |
| Assign From                                                                                                          | MERIMEN (CHRISTINA WONG)                                                        | Assign Date     | 15/03/2018               |                                                                                     |
| <b>2. Vehicle Particulars &amp; Condition</b>                                                                        |                                                                                 |                 |                          |                                                                                     |
| Make & Model                                                                                                         |                                                                                 | c.c             | 0                        |                                                                                     |
| Engine No.                                                                                                           | HIDDEN                                                                          | Year of Reg.    |                          |                                                                                     |
| Chassis No.                                                                                                          |                                                                                 | Colour          |                          |                                                                                     |
| Odometer                                                                                                             | -                                                                               | Steering        |                          |                                                                                     |
| Brakes                                                                                                               |                                                                                 | Modification    |                          |                                                                                     |
| General                                                                                                              |                                                                                 |                 |                          |                                                                                     |
| <b>3. Conditions of Tyres</b>                                                                                        |                                                                                 |                 |                          |                                                                                     |
|                                                                                                                      | Size                                                                            | Make            | Balance                  |                                                                                     |
| R/H Front Tyre                                                                                                       |                                                                                 |                 | mm                       |                                                                                     |
| L/H Front Tyre                                                                                                       |                                                                                 |                 | mm                       |                                                                                     |
| R/H Rear Tyre                                                                                                        |                                                                                 |                 | mm                       |                                                                                     |
| L/H Rear Tyre                                                                                                        |                                                                                 |                 | mm                       |                                                                                     |
| <b>4. Description of Damages</b>                                                                                     |                                                                                 |                 |                          |                                                                                     |
|                                                                                                                      |                                                                                 |                 |                          |                                                                                     |
| <b>5. General Information</b>                                                                                        |                                                                                 |                 |                          |                                                                                     |
| Accident Date                                                                                                        | 12/03/2018                                                                      | Inspection Date | 14/03/2018               |                                                                                     |
| Survey held at                                                                                                       | JIN AUTO SERVICES PTE LTD<br>BLK 14 DEFU LANE 10<br>#01-412<br>SINGAPORE 539195 |                 |                          |                                                                                     |
| <b>5a. Remarks</b>                                                                                                   |                                                                                 |                 |                          |                                                                                     |
| A) THE MARKET VALUE IS S\$----- (EST. AVERAGE)<br>B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE AUTHORISED REPAIRS. |                                                                                 |                 |                          |                                                                                     |

## ...CLAIM SUBFOLDER...(New Assignment)

| CLAIM SUBFOLDER TRACKING |             |               |                                |         |               |            |                                      |
|--------------------------|-------------|---------------|--------------------------------|---------|---------------|------------|--------------------------------------|
| Case                     | Notified    | Est Submitted | Adj Assigned                   | Adj Rpt | Adj Submitted | Ins Auth'd | Status                               |
| Main                     | 12 Mar 2018 |               | 15 Mar 2018<br>08:43<br>Assign |         |               |            | <b>New Assignment</b><br>Cancel Case |

|      |           |               |           |          |
|------|-----------|---------------|-----------|----------|
| Main | Reference | Claim Details | Documents | Show All |
|------|-----------|---------------|-----------|----------|

**CLAIM SUBFOLDER DETAILS** [Created by insurer]

|                                    |                                                                                                            |                               |                                                                  |
|------------------------------------|------------------------------------------------------------------------------------------------------------|-------------------------------|------------------------------------------------------------------|
| <b>Insured:</b>                    | ZHENG JIAXING, ID: S8377603Z                                                                               |                               |                                                                  |
| <b>Main Claimant:</b>              | SAM LAIN EQUIPMENT SERVICES, Co. Reg. No.: -                                                               |                               |                                                                  |
| <b>Vehicle Reg. No.:</b>           | SKA2813Y                                                                                                   | <b>Date of Loss:</b>          | 12/03/2018 09:00 - :59                                           |
| <b>Claim Type:</b>                 | TP / 552084                                                                                                | <b>Policy/Cover Note No.:</b> | 80443777QMY (Comprehensive)<br>Coverage: 31/10/2017 - 30/10/2018 |
| <b>Vehicle Reg. No. (Insured):</b> | SLH3677T                                                                                                   | <b>Policy No. (Claimant):</b> |                                                                  |
|                                    |                                                                                                            | <b>Excess:</b>                | S\$700.00                                                        |
| <b>Repairer:</b>                   | Jin Auto Services Pte Ltd (Defu) Blk 14 Defu Lane 10, #01-410/412, 539195 Defu Lane - Tel: 6289 8126       |                               |                                                                  |
| <b>Handling Insurer:</b>           | MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Christina Wong - 6643 1311] |                               |                                                                  |
| <b>Adjuster:</b>                   | LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Imm.Advice due 16/03/2018]                         |                               |                                                                  |
| <b>Adj Asg. Remarks:</b>           | W/s wld like Mr Marcus Chua to survey the vehicle                                                          |                               |                                                                  |

**ASSOCIATED MAIL RECEIVED** View All Compose Case Mail

There are no mail for this case.

**ALL ASSOCIATED TASKS** View All Search Tasks Create New Task Complete

| Due Date    | Priority | Type | Task Group | Subject | Handler | Assigned By | Completed On | Created On | Done? |
|-------------|----------|------|------------|---------|---------|-------------|--------------|------------|-------|
| No results. |          |      |            |         |         |             |              |            |       |

Note: This document has not been finalised.

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: MSIG Insurance (Singapore) Pte. Ltd.  
4 Shenton Way  
#21-01 SGX Centre 2  
Singapore 068807

From: LKK Auto Consultants Pte Ltd  
51 Ubi Ave 1 #01-25  
Paya Ubi Industrial Park  
Singapore 408933

Attn: Christina Wong

Date: 19 Mar 2018

**Preliminary Advice**

|                    |                                                                                            |                         |              |
|--------------------|--------------------------------------------------------------------------------------------|-------------------------|--------------|
| Insured Vehicle No | : SLH3677T                                                                                 | Accident Date           | : 12/03/2018 |
| TP Vehicle No      | : SKA2813Y                                                                                 | Assignment Date         | : 15/03/2018 |
| Make               | : VOLVO XC90                                                                               | Est. Duration of Repair | : 4.00       |
| Date of Inspection | : 14/03/2018                                                                               |                         |              |
| Inspection At      | : JIN AUTO SERVICES PTE LTD (DEFU)<br>BLK 14 DEFU LANE 10, #01-410/412<br>SINGAPORE 539195 |                         |              |

**Point of Impact / General Description of Damages**

The vehicle sustained impact / damages rear portion and parts claimed are consistent to the accident.

|                             |      |           |
|-----------------------------|------|-----------|
| Repairer's Estimate (Gross) | :S\$ | 17,429.11 |
| Revised Amount              | :S\$ | 8,420.82  |
| Check Items (Estimated)     | :S\$ | 1,631.88  |
| Total                       | :S\$ | 10,052.70 |

|                 |      |
|-----------------|------|
| Lump Sum Repair | :S\$ |
|-----------------|------|

**Total Loss Consideration**

|                    |      |
|--------------------|------|
| New for Old Value  | :S\$ |
| Pre-Accident Value | :S\$ |
| COE / PARF Rebate  | :S\$ |
| Salvage Value      | :S\$ |
| Margin for Repair  | :S\$ |

**Remarks**

- ( ) The vehicle is economical/not economical for repair.
- ( X ) The above survey was conducted on a 'without prejudice' basis.

## Enquire PARF/COE Rebate for Registered Vehicle

|                                     |                                       |
|-------------------------------------|---------------------------------------|
| <b>Vehicle Owner Particulars</b>    |                                       |
| Owner ID Type:                      | Company                               |
| Owner ID:                           | 1589R                                 |
| <b>Vehicle Details</b>              |                                       |
| Vehicle No.:                        | SKA2813Y                              |
| Vehicle to be Exported:             | No                                    |
| Intended De-registration Date:      | 19 Mar 2018                           |
| Vehicle Make:                       | VOLVO                                 |
| Vehicle Model:                      | XC90 3.2 R-DESIGN AT ABS D/AB HID AWD |
| Primary Colour:                     | Grey                                  |
| Manufacturing Year:                 | 2010                                  |
| Engine No.:                         | B6324S28111020033                     |
| Chassis No.:                        | YV1CT9556B1590726                     |
| Maximum Power Output:               | 179.0 kW (240 bhp)                    |
| Open Market Value:                  | \$58,177.00                           |
| Original Registration Date:         | 10 Feb 2011                           |
| First Registration Date:            | 10 Feb 2011                           |
| Transfer Count:                     | 1                                     |
| Actual ARF Paid:                    | \$58,177.00 <i>29088</i>              |
| <b>Intended PARF Rebate Details</b> |                                       |
| PARF Eligibility:                   | Yes                                   |
| PARF Eligibility Expiry Date:       | 09 Feb 2021                           |
| PARF Rebate Amount:                 | \$34,906.00                           |
| <b>Intended COE Rebate Details</b>  |                                       |
| COE Expiry Date:                    | 09 Feb 2021                           |
| COE Category:                       | E - Open Category                     |
| COE Period(Years):                  | 10                                    |
| QP Paid:                            | \$64,900.00                           |
| COE Rebate Amount:                  | \$18,077.00                           |
| <b>Total Rebate Amount:</b>         | <b>\$52,983.00</b>                    |

The information contained herein is correct as at 19 Mar 2018

OK

sgCARMART.COM

Login Sign up

New Cars

Used Cars

Sell My Car

Directory

Products

Insurance

Articles

Forum

Resources



VIEW CERTIFIED CARS



TOYOTA Preferred



Inchcapepreowned.com.sg

**Post an Advertisement**  
Sell it yourself! Advertise it at just  
**\$58 until it's SOLD!**

Post an Ad

Advertiser Login

Ways of Selling

2016 Golf 1.2 TSI No Repairs Needed! Up To 90% Loan



Fully Maintained By Volkswagen.  
Still Under Warranty By  
Volkswagen.  
Straits Drive StarAd



click here to view  
our **PRISTINE USED CARS**  
at **GREAT PRICES**

Browse by Category

Sort by Date Posted

20 results/page

8 vehicles

Volvo XC90

Advanced Search

Submit

|                         | Make       | Model | Price | Depreciation | Reg Date | Eng Cap | Mileage | Veh Type | Status    |
|-------------------------|------------|-------|-------|--------------|----------|---------|---------|----------|-----------|
| <b>Search Selection</b> | Volvo XC90 |       | Any   | Any          | 2011     | Any     | Any     | Any      | Available |

**Volvo XC90 3.2A R-Design****\$83,800****\$16,770 /yr****23-Jun-2011****3,192 cc****103,641 km****SUV****Available**

Elegant R Design Edition. SUV With 7 Seater Or Optional 5 Seater At Your Convenient. Only \$8,380 Down Payment. Up To 90% Flexible Loan. No Further! We Provide Lowest Interest Rate In Town. Flexible Loa...

Classic Credit Pte Ltd

Posted: 18-Mar-2018 Tags: 2011 Volvo XC90, Volvo XC90, Volvo, XC90, Used Volvo

**Volvo XC90 2.5T R-Design****\$78,800****\$15,520 /yr****12-Aug-2011****2,521 cc****90,000 km****SUV****Available**

Fully Services Records! R-Design! Interior And Exterior. Serviced And Groomed. Extremely Clean Interior And Exterior. Peace Of Mind With An Optional 1 Or 2 Years Warranty, Available In Showroom For VL...

Posted: 17-Mar-2018 Tags: 2011 Volvo XC90, Volvo XC90, Volvo, XC90, Used Volvo

**Volvo XC90 2.5T****\$87,800****\$16,690 /yr****29-Nov-2011****2,521 cc****105,000 km****SUV****Available**

Downpayment Of 20% With Low Monthly Instalment. Easy Approval With High Trade In. Contact Our Sales Team For More Info At 64721119.

Vincar Pte Ltd

Posted: 16-Mar-2018 Tags: 2011 Volvo XC90, Volvo XC90, Volvo, XC90, Used Volvo

**Volvo XC90 2.5T****\$70,800****\$15,180 /yr****28-Feb-2011****2,521 cc****89,339 km****SUV****Available**

1 Year Free Servicing! \$8K Down Payment! STA Certified Accident Free Quality Pre Owned With Low Mileage For Peace Of Mind. 100% Loan Approval With Our Flexible In House Financing Options. View Today!

Cosmo Automobiles

Posted: 16-Mar-2018 Tags: 2011 Volvo XC90, Volvo XC90, Volvo, XC90, Used Volvo

Car Buying

Car Selling

Car Ownership

Car Aftermarket

On The Move

Lifestyle

► Buy Tyres Online!  
► Latest Special Offers from Tyrepack!

**Volvo XC90 T5 R-Design****\$89,800****\$16,790 /yr****29-Nov-2011****2,521 cc****63,000 km****SUV****Available**

Volvo XC90 T5 R-Design Edition With Sunroof! One Of The Best 7 Seaters SUVs In Town! Low Mileage! High OMV Of \$55,416! Look No Further. Only \$8,980 Down Payment, Up 90% Flexible Loan. Flexible In House...

Classic Credit Pte Ltd

Posted: 16-Mar-2018 Tags: 2011 Volvo XC90, Volvo XC90, Volvo, XC90, Used Volvo

**Volvo XC90 2.5T R-Design****\$84,788****\$15,880 /yr****28-Nov-2011****2,521 cc****67,000 km****SUV****Available**

Down Payment From \$8,480 Only! From \$1,580/Month. Genuine Low Mileage, Only Use On Weekends. Full Servicing Record Available. Diligently Serviced & Maintained At Volvo Specialist Workshop. Newly Repla...

Cars 88 Pte Ltd

Posted: 13-Mar-2018 Tags: 2011 Volvo XC90, Volvo XC90, Volvo, XC90, Used Volvo

**Volvo XC90 2.5T****\$71,000****\$15,250 /yr****28-Feb-2011****2,521 cc****86,000 km****SUV****Available**

Nice 3 Digit Number. 10% Downpayment. Beautiful Unit. 1 Owner. Comes With Warranty And Free Servicing Package. View Now.

Posted: 03-Mar-2018 Tags: 2011 Volvo XC90, Volvo XC90, Volvo, XC90, Used Volvo

**Volvo XC90 2.5T****\$75,500****\$16,560 /yr****14-Mar-2011****2,521 cc****174,000 km****SUV****Available**

In-house Finance Available, Trade In Are Welcome. Call/SMS Our Sales Consultant For Viewing Appointment.

Think One Automobile &amp; Trading

Posted: 25-Feb-2018 Tags: 2011 Volvo XC90, Volvo XC90, Volvo, XC90, Used Volvo



# Jin Auto Services Pte Ltd

Blk 14 Defu Lane 10 #01-412

Singapore 539195

Tel:62898126 Fax :62870590

Company Reg No:200704370C GST Reg No ::200704370C

DATE 13/3/2018  
Our Ref : SKA2813Y

Repair sum \$ 7700

not Ackd  
H/W  
14/3/18  
The photo attached.  
P/P \$

M/S MSIG Insurance (Singapore) Pte Ltd

DEAR SIR / MADAM  
ESTIMATE REPAIR COST FOR SKA2813Y

|    |       |                             |         |
|----|-------|-----------------------------|---------|
| 1  | 1 PC  | REAR BUMPER                 |         |
| 2  | 1 PC  | REAR BUMPER CLIPS           |         |
| 3  | 1 PC  | REAR BUMPER LOWER SKIRT     |         |
| 4  | 4 PCS | REAR PARKING SENSOR         | 643.60  |
| 5  | 2 PCS | REAR BUMPER REFLECTOR       | 92.60   |
| 6  | 1 PC  | REAR BUMPER SPONGE          |         |
| 7  | 1 PC  | REAR BUMPER TO HOOK COVER   | 65.00   |
| 8  | 1 PC  | REAR END PANEL              |         |
| 9  | 1 PC  | TAILGATE LOWER              | 2101.32 |
| 10 | 1 PC  | TAIGATE LOWER XC 90 EMBLEM  | 98.50   |
| 11 | 1 PC  | TAIGATE LOWER 3.2 EMBLEM    | 90.20   |
| 12 | 1 PC  | TAIGATE LOWER XC AWD EMBLEM | 90.20   |
| 13 | 2 PCS | EXHUAIST MUFFLER            |         |
| 14 | 2 PCS | EXHUAIST MUFFLER MOUNTING   |         |
| 15 | 2 PCS | TAIL PIPE CHROME            | 211.00  |
| 16 | 1 PC  | TAILGATE TOP                |         |

## NETT ITEMS

|    |      |          |     |
|----|------|----------|-----|
| \$ | DJ   | 1,524.80 | —   |
| \$ | ren  | 45.00    | —   |
| \$ | DJ   | 1,524.80 | —   |
| \$ | shd  | 858.40   | 3PC |
| \$ | MSK  | 185.20   | 4C  |
| \$ | 11   | 431.60   | X   |
| \$ | Tur  | 85.10    | —   |
| \$ | 1    | 1,381.60 | X   |
| \$ | 3600 | 2,296.70 | —   |
| \$ | ren  | 106.20   | —   |
| \$ | ren  | 96.80    | —   |
| \$ | ren  | 96.80    | —   |
| \$ | n    | 2,451.40 | X   |
| \$ | nn   | 117.60   | X   |
| \$ | n    | 1,177.20 | —   |
| \$ | n    | 3,608.70 | X   |

LESS 10%

|    |                       |  |
|----|-----------------------|--|
| 17 | SPRAY PAINTING (REAR) |  |
| 18 | LABOUR CHARGE (REAR ) |  |
| 19 | TUFFCOAT              |  |
| 20 | WIRING CHECK          |  |
| 21 | PROGRAMMING           |  |

|    |   |            |     |
|----|---|------------|-----|
| \$ |   | 15,987.90  |     |
| \$ |   | (1,598.79) |     |
| \$ |   | 14,389.11  |     |
| \$ |   | 1,200.00   | 750 |
| \$ |   | 1,350.00   | 680 |
| \$ |   | 120.00     | 50  |
| \$ |   | 50.00      | 20  |
| \$ | n | 320.00     | X   |
| \$ |   | 17,429.11  |     |

7376.22  
6838.59

8138.59

PK Auto Consultants hence notify

the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:





UNICO MOTOR (PTE) LIMITED 友和汽車(私人)有限公司

HEAD OFFICE: Blk 9 Selegie Road, #01-23 Selegie House Singapore 180009

BRANCH OFFICE: Blk 22 Sin Ming Road, #01-242 Singapore 570022

EMAIL: sales@unicomotor.com.sg | kee@unicomotor.com.sg

WEBSITE: www.unicomotor.com.sg

GST REG NO: M2-0017235-3  
CO. REG NO: 197302096R

(HO) Tel: (65) 6336 1828 (4 lines) Fax: (65) 6337 2043  
(BR) Tel: (65) 6453 5221 (3 lines) Fax: (65) 6453 2878

## DELIVERY ORDER

↓ AUTO SERVICES (PTE LTD) (Cash)  
K 14 DEFU LANE 10 #01-412  
SINGAPORE 539195

D/O NO : 18CDO030589  
DATE : 27/03/2018  
A/C NO. : LJIN

MARKS : SKA2813Y/VOL XC90 3.2L 2012-YV1CT9556B1590726

### ITEM PART NOS. DESCRIPTION

| ITEM PART NOS. | DESCRIPTION                                            | QTY | UNIT | PRICE  | TOTAL  |
|----------------|--------------------------------------------------------|-----|------|--------|--------|
| V30733122      | BUM SECTION BRACKET,RR(07-/For R-Design Model)         | 1   | PC   | 90.00  | 90.00  |
| V30793906      | REAR EXHAUST CHROME PIPE LH/RH(Twin Pipes on One SIDE) | 2   | PCS  | 490.00 | 980.00 |

*SPR*

ISSUED BY:

RECEIVE BY:

CREDIT TERM: C.O.D

SUBTOTAL : SGD 1,070.00  
GST (7.00%) : SGD 74.90  
TOTAL : SGD 1,144.90



All enquiries are welcome.

CUSTOMER COPY

PAGE 1 OF 1

ALL CHEQUES TO BE MADE PAYABLE TO "UNICO MOTOR (PTE) LTD"

PRINTED BY WEE - AT 27/03/2018 14:16 - PRINTED COUNT: 1

## LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/MSG18004804/UQBN2

Date: 13/04/2018

## REFERENCE

|                       |                                      |                      |             |
|-----------------------|--------------------------------------|----------------------|-------------|
| Handling Insurer:     | MSIG Insurance (Singapore) Pte. Ltd. | Policy No:           | 80443777QMY |
| Claimant Vehicle No : | SKA2813Y                             | Insured Vehicle No : | SLH3677T    |
| Date of Loss:         | 12/03/2018                           | Nature of Claim:     | TP          |
|                       |                                      | Claim No:            | 552084      |

## DESCRIPTION &amp; IDENTIFICATION OF VEHICLE

|                             |                              |             |                   |
|-----------------------------|------------------------------|-------------|-------------------|
| Reg No:                     | SKA2813Y                     | Engine No:  | B6324S28111020033 |
| Make & Model:               | VOLVO XC90, 3.2 R-Design (A) | Chassis No: | YV1CT9556B1590726 |
| Reg. Date:                  | 10/02/2011 (Man. Year: 2010) | Odometer:   | 116674 km         |
| Colour:                     | Grey                         |             |                   |
| Engine Capacity:            | 3192 cc                      |             |                   |
| Market Value/New Car Price: | N/A                          |             |                   |
| Sum Insured (\$\$):         | Market Value/New Car Price   |             |                   |

## CONDITION OF VEHICLE AT THE TIME OF SURVEY

|                          |                         |                      |                          |                         |
|--------------------------|-------------------------|----------------------|--------------------------|-------------------------|
| General Condition:       | Steering (Serviceable): | Yes                  | Footbrake (Serviceable): | Yes                     |
| Handbrake (Serviceable): | Yes                     | Engine Modification: | No                       | Pre-accident Condition: |

## CONDITION OF TYRES

|                   |               |                  |               |
|-------------------|---------------|------------------|---------------|
| Front Tyre Size:  | 255/50 R19    | Rear Tyre Size:  | 255/50 R19    |
| Front Left Side:  | Michelin 6 mm | Rear Left Side:  | Michelin 6 mm |
| Front Right Side: | Michelin 6 mm | Rear Right Side: | Michelin 6 mm |

The above values represent the remaining tyre treads depth

## COST OF CLAIMS

|                                           | Repairer's       | Adjuster's      | Difference       | Diff %       |
|-------------------------------------------|------------------|-----------------|------------------|--------------|
| Parts                                     | 14,389.11        | 6,638.60        | 7,750.51         | 53.86        |
| Miscellaneous Items                       | 0.00             | 0.00            | 0.00             |              |
| Labour                                    | 3,040.00         | 1,500.00        | 1,540.00         | 50.66        |
| Paintwork Labour                          | 0.00             | 0.00            | 0.00             |              |
| Towing                                    | 0.00             | 0.00            | 0.00             |              |
| <b>Calculated Gross Total (\$\$)</b>      | <b>17,429.11</b> | <b>8,138.60</b> | <b>9,290.51</b>  | <b>53.30</b> |
| <b>Approved Total (Overridden) (\$\$)</b> |                  | <b>7,700.00</b> |                  |              |
| <b>(\$\$)</b>                             | 17,429.11        | 7,700.00        | 9,729.11         | 55.82        |
| <b>+ GST 7.00/7.00% (\$\$)</b>            | 1,220.04         | 539.00          | 681.04           | 55.82        |
| <b>Nett Amount (\$\$)</b>                 | <b>18,649.15</b> | <b>8,239.00</b> | <b>10,410.15</b> | <b>55.82</b> |

## INSPECTION

|                             |            |               |                                                                                          |
|-----------------------------|------------|---------------|------------------------------------------------------------------------------------------|
| Date of Assignment:         | 15/03/2018 |               |                                                                                          |
| Date Inspected:             | 14/03/2018 | Inspected At: | Jin Auto Services Pte Ltd (Defu)<br>Blk 14 Defu Lane 10, #01-410/412<br>Singapore 539195 |
| Estimated Period of Repair: | 4.0 days   |               |                                                                                          |

Adjuster: MARCUS CHUA

Manager: SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.



\*NOTE: NEW PARTS REPLACEMENT.

THE REPAIR COST IS REPAIR SUM \$7,700.00.

## REPAIR DETAILS

|                      |                                                                                                                                                                              |                                                               |
|----------------------|------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|---------------------------------------------------------------|
| <b>Reference</b>     |                                                                                                                                                                              |                                                               |
| <b>Part Source:</b>  | MRM-SG                                                                                                                                                                       | Version: 1.0 (Last Synchronised: 13 Apr 2018)                 |
| <b>Parts:</b>        | M1-SUV                                                                                                                                                                       | VOLVO XC90 3.2 R-Design (A) (Catalogue:Merimen Singapore 1.0) |
| <b>Labour:</b>       | Repairer's                                                                                                                                                                   | (Price-denominated Standard List)                             |
| <b>Print Code:</b>   | (Unsubmitted, no print-code for SKA2813Y)                                                                                                                                    |                                                               |
| <b>Validity:</b>     | These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page |                                                               |
| <b>Further Info:</b> | Items/values not in reference catalogue are prefixed with an asterisk *.                                                                                                     |                                                               |

## Recommended Parts

| No. | Qty | Part No. Particulars              | Condition            | Repairer's  | Amount       |
|-----|-----|-----------------------------------|----------------------|-------------|--------------|
| 1   | 1   | *REAR BUMPER                      | Distorted            | 1,524.80 FL | *1,524.80 FL |
| 2   | 1   | *REAR BUMPER CLIPS                | Necessary            | 45.00 FL    | *45.00 FL    |
| 3   | 1   | *REAR BUMPER LOWER SKIRT          | Distorted            | 1,524.80 FL | *1,524.80 FL |
| 4   | 1   | *REAR PARKING SENSOR<br>(4 Pcs)   | Shorted (3 Pcs only) | 858.40 FL   | *643.80 FL   |
| 5   | 1   | *REAR BUMPER REFLECTOR            | N/s Broken           | 185.20 FL   | *92.60 FL    |
| 6   | 1   | *REAR BUMPER SPONGE               | Not Necessary        | 431.60 FL   | *- FL        |
| 7   | 1   | *REAR BUMPER SPONGE TO HOOK COVER | Twisted              | 85.10 FL    | *65.00 FL    |
| 8   | 1   | *REAR END PANEL                   | Repair               | 1,381.60 FL | *- FL        |
| 9   | 1   | *TAILGATE LOWER                   | Badly Dented         | 2,296.70 FL | *2,101.32 FL |
| 10  | 1   | *TAILGATE LOWER XC 90 EMBLEM      | Necessary            | 106.20 FL   | *98.50 FL    |
| 11  | 1   | *TAILGATE LOWER 3.2 EMBLEM        | Necessary            | 96.80 FL    | *90.20 FL    |
| 12  | 1   | *TAILGATE LOWER XC AWD EMBLEM     | Necessary            | 96.80 FL    | *90.20 FL    |
| 13  | 2   | *EXHAUST MUFFLER                  | Repair               | 2,451.40 FL | *- FL        |
| 14  | 2   | *EXHAUST MUFFLER MOUNTING         | Not Necessary        | 117.60 FL   | *- FL        |
| 15  | 2   | *TAIL PIPE CHROME                 | Dented               | 1,177.20 FL | *1,100.00 FL |
| 16  | 1   | *TAILGATE TOP                     | Repair               | 3,608.70 FL | *- FL        |

F=Franchise part. L=ListItemDisc.

|                                                    |                  |                 |
|----------------------------------------------------|------------------|-----------------|
| <b>Sub Total (S\$)</b>                             | <b>15,987.90</b> | <b>7,376.22</b> |
| - List Item Discount on L Items 10.00/10.00% (S\$) | 1,598.79         | 737.62          |
| <b>Total Parts (S\$)</b>                           | <b>14,389.11</b> | <b>6,638.60</b> |

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

| No                       | Particulars           | Lab.Type | Repairer's | Amount   |
|--------------------------|-----------------------|----------|------------|----------|
| <b>Labour Items</b>      |                       |          |            |          |
| 1                        | SPRAY PAINTING (REAR) | New      | 1,200.00   | 750.00   |
| 2                        | LABOUR CHARGE (REAR)  | New      | 1,350.00   | 680.00   |
| 3                        | TUFFCOAT              | New      | 120.00     | 50.00    |
| 4                        | WIRING CHECK          | New      | 50.00      | 20.00    |
| 5                        | PROGRAMMING           | New      | 320.00     | -        |
| Gross Labour Cost (\$\$) |                       |          | 3,040.00   | 1,500.00 |

Report was unsubmitted during this print-out.

< END OF ESTIMATES >