

ASS. REC. BY:

REF: CS/MS(1800 4832)/R/vb

Special Instruction:

Surveyor: ASSIGNMENT (Office)

From (Person): Jenny Yung of MSU1 Date/Time: 13032018 3:57 pm

Estimated Cost: Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: SLE 6615T Insured: Public Liability

at Workshop m/s Performance Tel:

of 303 Alexandra Rd

Policy No: Claim No: B28691906PLY

Sum Insured: Excess:

Make of Veh: D.O.A. 11.03.2018

(Client's Record)

CA / REV / REP. / REV 24 HRS 'WP' 19.032018 @ 11am owner waiting H.O.D. Endorsement:

Date/Time: 14032018 9:29am Person Contacted: Kevin Vehicle IN/OUT

Date/Time	Action/Instruction (✓) Estimate
	SLE 6615T - X
	Public Liability - X
20/3/18	Email preli revised to Jenny
29/3/18	@ 1:55pm Spoken to Jenny, she said check items leave it to our surveyor.



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

MSIG INSURANCE (SINGAPORE) PTE LTD

Ref : CS/MSG18004832/R1vb

16 RAFFLES QUAY
#24-01 HONG LEONG BLDG SINGAPORE 048581

Date : 14-03-2018



Code : MSG

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	PUBLIC LIABILITY	Veh. Inspected	SLE 6615T
Policy No.		Coverage (\$)	0.00
Claim No.	B28691906PLY	Excess (\$)	0.00
Assign From	JENNY YONG	Assign Date	13/03/2018

2. Vehicle Particulars & Condition

Make & Model		c.c	0
Engine No.	HIDDEN	Year of Reg.	
Chassis No.		Colour	
Odometer	-	Steering	
Brakes		Modification	
General			

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm

4. Description of Damages

--	--

5. General Information

Accident Date	11/03/2018	Inspection Date	19/03/2018
Survey held at	PERFORMANCE MOTORS LTD 303 ALEXANDRA ROAD SINGAPORE 159941		

5a. Remarks

	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.
--	--



Auto
Consultants
Pte Ltd

Company Registration No. 199607198R

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your ref: B28691906PLY
Our ref: CS/MSG18004832/R1vb

Date: 20/3/2018

The Motor Claims Department
M/s MSIG INSURANCE (SINGAPORE) PTE LTD

Dear Sir/Madam,

PRELIMINARY ADVICE OF VEHICLE NO: SLE 6615T


We thank you for your instruction on 13/3/2018

Please be informed that we had conducted the inspection of the above mentioned vehicle on 19/3/2018 at the premises of M/s PERFORMANCE MOTORS LTD and have the following to report:-

Workshop Estimate Amount	: S\$7,908.25
Revised Estimate Amount	: S\$6,387.00
"Check" Items Amount	: S\$156.25
Market Value	: S\$
LTA Reimbursement Value	: S\$
Nett Value	: S\$

Description of Damage:

The vehicle sustained damages at the front portion and o/s body



Comments/Present Status:
Damages Consistent

Yours faithfully,

MOHAMMED RASUL
Automotive Assessor

Catherine Chong (LKK Auto)

From: Jenny Yong <jenny_yong@sg.msig-asia.com>
Sent: Tuesday, 13 March, 2018 3:57 PM
To: Catherine Chong (LKK Auto)
Subject: [New Case] Singapore Swimming Club/Policy No B 28691906 PLY : Damage to TP's vehicle on 11th March 2018
Attachments: Cust Q.pdf; MSIG Liability Form Page 2.jpg; MSIG Liability Form Page 1.jpg
Importance: High

Hi Catherine,

Public Liability

We refer to the above matter.

Attached the completed claim form and quotation from Performance Motors.

Please survey the third party vehicle on a without prejudice basis.

Regards

Jenny Yong
Senior Executive, Claims Services
D: +65 65942457 | F: +65 66431349 | jenny_yong@sg.msig-asia.com

*14/03/2018 @ 9:29am
Kavin Veh*



Insurer Claims
Team of the Year
2016

MSIG Insurance (Singapore) Pte Ltd 16 Raffles Quay, #24-01 Hong Leong Building, Singapore 048581 | T: +65 6220 9644 | F: +65 6225 6371 | Co. Reg. No. 200412212G | msig.com.sg    

A Member of **MS&AD** INSURANCE GROUP

CONFIDENTIALITY NOTICE

This e-mail (including any attachments) may contain information that is privileged or confidential. The sending of this e-mail to any person other than the intended recipient is not a waiver of the privilege or confidentiality that attaches to it. If you are not the intended recipient, please notify the sender immediately, delete the email and do not copy, distribute or disclose its contents.

Veron Chen (LKKAuto)

From: Veron Chen (LKKAuto)
Sent: Tuesday, 20 March 2018 4:03 PM
To: 'Jenny Yong'
Cc: SUR
Subject: RE: [New Case] Singapore Swimming Club/Policy No B 28691906 PLY : Damage to TP's vehicle on 11th March 2018 ,TP VEHICLE SLE 6615T
Attachments: SLE 6615T PRELI REVISED.pdf

Dear Jenny,

Enclosed preliminary revised of vehicle SLE 6615T
Date of survey: 19/3/2018
Number of days:5 days

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Admin-D (LKKAuto)
Sent: Wednesday, 14 March 2018 10:37 AM
To: 'Jenny Yong' <jenny_yong@sg.msig-asia.com>
Cc: assignments <assignments@lkkauto.com>; SUR <sur@lkkauto.com>
Subject: RE: [New Case] Singapore Swimming Club/Policy No B 28691906 PLY : Damage to TP's vehicle on 11th March 2018

Dear Jenny,

Thank you for the assignment.

Please be informed that vehicle currently not in the workshop, repairer will arrange.

Best Regards,

Catherine Chong | Admin

LKK Auto Consultants Pte Ltd

Phone: 6741-8434 | email: assignments@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Jenny Yong [mailto:jenny_yong@sg.msig-asia.com]
Sent: Tuesday, 13 March, 2018 3:57 PM
To: Catherine Chong (LKK Auto) <admin-d@lkkauto.com>
Subject: [New Case] Singapore Swimming Club/Policy No B 28691906 PLY : Damage to TP's vehicle on 11th March 2018
Importance: High

Hi Catherine,

Public Liability

We refer to the above matter.

Attached the completed claim form and quotation from Performance Motors.

Please survey the third party vehicle on a without prejudice basis.

Regards

Jenny Yong
Senior Executive, Claims Services
D: +65 65942457 | F: +65 66431349 | jenny_yong@sg.msig-asia.com



MSIG



Insurer Claims
Team of the Year
2016

MSIG Insurance (Singapore) Pte Ltd 16 Raffles Quay, #24-01 Hong Leong Building, Singapore 048581 | T: +65 6220

9644 | F: +65 6225 6371 | Co. Reg. No. 200412212G | msig.com.sg



A Member of **MS&AD** INSURANCE GROUP

CONFIDENTIALITY NOTICE

This e-mail (including any attachments) may contain information that is privileged or confidential. The sending of this e-mail to any person other than the intended recipient is not a waiver of the privilege or confidentiality that attaches to it. If you are not the intended recipient, please notify the sender immediately, delete the email and do not copy, distribute or disclose its contents.

Veron Chen (LKKAuto)

From: Veron Chen (LKKAuto)
Sent: Thursday, 29 March 2018 2:04 PM
To: 'Jenny Yong'
Cc: SUR
Subject: RE: Singapore Swimming Club/Policy No B 28691906 PLY : Damage to TP's vehicle on 11th March 2018 ,TP VEHICLE SLE 6615T - MSIG : 552258PLY

Dear Jenny,

As spoken, current is the same estimate there is no different .

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Jenny Yong [mailto:jenny_yong@sg.msig-asia.com]
Sent: Wednesday, 28 March 2018 10:33 AM
To: Veron Chen (LKKAuto) <veronchen@lkkauto.com>
Cc: SUR <sur@lkkauto.com>
Subject: Singapore Swimming Club/Policy No B 28691906 PLY : Damage to TP's vehicle on 11th March 2018 ,TP VEHICLE SLE 6615T - MSIG : 552258PLY

Hi Veron,

Attached is the quotation provided to us by Performance Motors and we note that is different from the earlier quotation.

Please review and let us have your report for our direct settlement with the workshop.

Regards

Jenny Yong
Senior Executive, Claims Services
D: +65 65942457 | F: +65 66431349 | jenny_yong@sg.msig-asia.com



Insurer Claims
Team of the Year
2016

MSIG Insurance (Singapore) Pte Ltd 16 Raffles Quay, #24-01 Hong Leong Building, Singapore 048581 | T: +65 6220 9644 | F: +65 6225 6371 | Co. Reg. No. 200412212G | msig.com.sg



A Member of **MS&AD** INSURANCE GROUP

From: Jenny Yong
Sent: Monday, 26 March, 2018 6:05 PM
To: 'Veron Chen (LKKAuto)' <veronchen@lkkauto.com>
Cc: SUR <sur@lkkauto.com>
Subject: RE: [New Case] Singapore Swimming Club/Policy No B 28691906 PLY : Damage to TP's vehicle on 11th March 2018 ,TP VEHICLE SLE 6615T

Hi Veron,

Performance Motors had written to us proposing direct settlement.

Please advise what are the check items of \$156.25.

Regards

Jenny Yong
Senior Executive, Claims Services
D: +65 65942457 | F: +65 66431349 | jenny_yong@sg.msig-asia.com



Insurer Claims
Team of the Year
2016

MSIG Insurance (Singapore) Pte Ltd 16 Raffles Quay, #24-01 Hong Leong Building, Singapore 048581 | T: +65 6220 9644 | F: +65 6225 6371 | Co. Reg. No. 200412212G | msig.com.sg



A Member of **MS&AD** INSURANCE GROUP

From: Veron Chen (LKKAuto) [<mailto:veronchen@lkkauto.com>]
Sent: Tuesday, 20 March, 2018 4:03 PM
To: Jenny Yong <jenny_yong@sg.msig-asia.com>
Cc: SUR <sur@lkkauto.com>
Subject: RE: [New Case] Singapore Swimming Club/Policy No B 28691906 PLY : Damage to TP's vehicle on 11th March 2018 ,TP VEHICLE SLE 6615T

Dear Jenny,

Enclosed preliminary revised of vehicle SLE 6615T
Date of survey: 19/3/2018
Number of days:5 days

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Admin-D (LKKAuto)
Sent: Wednesday, 14 March 2018 10:37 AM
To: 'Jenny Yong' <jenny_yong@sg.msig-asia.com>
Cc: assignments <assignments@lkkauto.com>; SUR <sur@lkkauto.com>

Subject: RE: [New Case] Singapore Swimming Club/Policy No B 28691906 PLY : Damage to TP's vehicle on 11th March 2018

Dear Jenny,

Thank you for the assignment.

Please be informed that vehicle currently not in the workshop, repairer will arrange.

Best Regards,

Catherine Chong | Admin

LKK Auto Consultants Pte Ltd

Phone: 6741-8434 | email: assignments@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Jenny Yong [mailto:jenny_yong@sg.msig-asia.com]

Sent: Tuesday, 13 March, 2018 3:57 PM

To: Catherine Chong (LKK Auto) <admin-d@lkkauto.com>

Subject: [New Case] Singapore Swimming Club/Policy No B 28691906 PLY : Damage to TP's vehicle on 11th March 2018

Importance: High

Hi Catherine,

Public Liability

We refer to the above matter.

Attached the completed claim form and quotation from Performance Motors.

Please survey the third party vehicle on a without prejudice basis.

Regards

Jenny Yong

Senior Executive, Claims Services

D: +65 65942457 | F: +65 66431349 | jenny_yong@sg.msig-asia.com



Insurer Claims
Team of the Year
2016

MSIG Insurance (Singapore) Pte Ltd 16 Raffles Quay, #24-01 Hong Leong Building, Singapore 048581 | T: +65 6220 9644 | F: +65 6225 6371 | Co. Reg. No. 200412212G | msig.com.sg



A Member of **MS&AD** INSURANCE GROUP

CONFIDENTIALITY NOTICE

This e-mail (including any attachments) may contain information that is privileged or confidential. The sending of this e-mail to any person other than the intended recipient is not a waiver of the privilege or confidentiality that attaches to it. If you are not the intended recipient, please notify the sender immediately, delete the email and do not copy, distribute or disclose its contents.

Janice Lee (LKKAuto)

From: Jenny Yong <jenny_yong@sg.msig-asia.com>
Sent: Wednesday, March 28, 2018 10:33 AM
To: Veron Chen (LKKAuto)
Cc: SUR
Subject: Singapore Swimming Club/Policy No B 28691906 PLY : Damage to TP's vehicle on 11th March 2018 ,TP VEHICLE SLE 6615T - MSIG : 552258PLY
Attachments: 28032018100240-0001.pdf

Hi Veron,

Attached is the quotation provided to us by Performance Motors and we note that is different from the earlier quotation.

Please review and let us have your report for our direct settlement with the workshop.

Regards

Jenny Yong
Senior Executive, Claims Services
D: +65 65942457 | F: +65 66431349 | jenny_yong@sg.msig-asia.com



Insurer Claims
Team of the Year
2016

MSIG Insurance (Singapore) Pte Ltd 16 Raffles Quay, #24-01 Hong Leong Building, Singapore 048581 | T: +65 6220 9644 | F: +65 6225 6371 | Co. Reg. No. 200412212G | msig.com.sg



A Member of **MS&AD** INSURANCE GROUP

From: Jenny Yong
Sent: Monday, 26 March, 2018 6:05 PM
To: 'Veron Chen (LKKAuto)' <veronchen@lkkauto.com>
Cc: SUR <sur@lkkauto.com>
Subject: RE: [New Case] Singapore Swimming Club/Policy No B 28691906 PLY : Damage to TP's vehicle on 11th March 2018 ,TP VEHICLE SLE 6615T

Hi Veron,

Performance Motors had written to us proposing direct settlement.

Please advise what are the check items of \$156.25.

Regards

Jenny Yong
Senior Executive, Claims Services
D: +65 65942457 | F: +65 66431349 | jenny_yong@sg.msig-asia.com



Insurer Claims
Team of the Year
2016

MSIG Insurance (Singapore) Pte Ltd 16 Raffles Quay, #24-01 Hong Leong Building, Singapore 048581 | T: +65 6220 9644 | F: +65 6225 6371 | Co. Reg. No. 200412212G | msig.com.sg



A Member of **MS&AD** INSURANCE GROUP

From: Veron Chen (LKKAuto) [<mailto:veronchen@lkkauto.com>]
Sent: Tuesday, 20 March, 2018 4:03 PM
To: Jenny Yong <jenny_yong@sg.msig-asia.com>
Cc: SUR <sur@lkkauto.com>
Subject: RE: [New Case] Singapore Swimming Club/Policy No B 28691906 PLY : Damage to TP's vehicle on 11th March 2018 ,TP VEHICLE SLE 6615T

Dear Jenny,

Enclosed preliminary revised of vehicle SLE 6615T
Date of survey: 19/3/2018
Number of days:5 days

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Admin-D (LKKAuto)
Sent: Wednesday, 14 March 2018 10:37 AM
To: 'Jenny Yong' <jenny_yong@sg.msig-asia.com>
Cc: assignments <assignments@lkkauto.com>; SUR <sur@lkkauto.com>
Subject: RE: [New Case] Singapore Swimming Club/Policy No B 28691906 PLY : Damage to TP's vehicle on 11th March 2018

Dear Jenny,

Thank you for the assignment.

Please be informed that vehicle currently not in the workshop, repairer will arrange.

Best Regards,

Catherine Chong | Admin

LKK Auto Consultants Pte Ltd

Phone: 6741-8434 | email: assignments@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Jenny Yong [mailto:jenny_yong@sg.msig-asia.com]

Sent: Tuesday, 13 March, 2018 3:57 PM

To: Catherine Chong (LKK Auto) <admin-d@lkkauto.com>

Subject: [New Case] Singapore Swimming Club/Policy No B 28691906 PLY : Damage to TP's vehicle on 11th March 2018

Importance: High

Hi Catherine,

Public Liability

We refer to the above matter.

Attached the completed claim form and quotation from Performance Motors.

Please survey the third party vehicle on a without prejudice basis.

Regards

Jenny Yong

Senior Executive, Claims Services

D: +65 65942457 | F: +65 66431349 | jenny_yong@sg.msig-asia.com



MSIG



Insurer Claims
Team of the Year
2016

MSIG Insurance (Singapore) Pte Ltd 16 Raffles Quay, #24-01 Hong Leong Building, Singapore 048581 | T: +65 6220

9644 | F: +65 6225 6371 | Co. Reg. No. 200412212G | msig.com.sg



A Member of **MS&AD** INSURANCE GROUP

CONFIDENTIALITY NOTICE

This e-mail (including any attachments) may contain information that is privileged or confidential. The sending of this e-mail to any person other than the intended recipient is not a waiver of the privilege or confidentiality that attaches to it. If you are not the intended recipient, please notify the sender immediately, delete the email and do not copy, distribute or disclose its contents.

GMR Dealer

Performance Motors Limited

A member of the Sime Darby Group
Co. Reg. No. 197401559W GST Reg. No M2-0020081-X



303, Alexandra Road
Sime Darby Performance Centre
Singapore 159941
Tel. 63190100 (Sales & Admin)
63190111 (AfterSales)
Fax. 64747770

380, Kampong Arang Road
East Coast Centre
Singapore 438180
Tel. 63190688 (AfterSales)
Fax. 63449773

315, Alexandra Road
Sime Darby Business Centre
Singapore 159944
Tel. 63190528 (AfterSales)
63190933/530 (Motorrad)
Fax. 64796401 (AfterSales)
64796424 (Motorrad)

GST REG. NO : M2 - 0020081 - X

ESTIMATE

2.6 MAR 2018

Page No. : 1 of 2

Estimate No. : b1 46201
Date Estimated : 12/03/2018
Prepared By : Kevin Leong Wai Kit

- ESTIMATE REPAIR FOR -
Gui Wee Fong Quiner
6 Kew Avenue

Singapore 466340

- ACCOUNT - 40000
Cash Sales - Service
Singapore

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SLE6615T	5F01686	28/07/2016	X1 sDrive18i	0

DESCRIPTION

To replace front right door moulding, door chrome, rear right door moulding, door chrome, right roof moulding and all attachments cause by accident.

VALUE
3,400.00

Painting on right roof frame & rear lid spoiler

896.00

To replace front windscreen glass include conduct water leak test.

649.00

To supply and install front windscreen solar film.

531.00

To supply and install IU unit bracket.

31.00

Sundries.

80.00

Total Labour 1: 5,587.00

DESCRIPTION

HEX NUT
RH ROOF RAILS ALUMINIUM SATINATED
BUMP STOP
COVER WINDSHIELD TOP
FRT WINDSCREEN RAIN SENSOR (RLSBS)
LH DRIP MOULDING
RH DRIP MOULDING
FRT RH DOOR COLUMN B COVER
FRT RH DOOR WINDOW FRAME COVER (ALU)
REAR RH DOOR COLUMN B COVER
RR RH DOOR WINDOW FRAME COVER (ALU)
REAR RH SIDE WINDOW FIXED (ALU)
(S/L) SOUND INSULATION APRON L1387M
(DG) CLEANER R1 (100ML)
(DG/SL) W/SCREEN SEALANT (COLD 1 HOUR)
(DG/SL) GLASS PRIMER 30ML (VP208)

QTY	PRIC	VALUE
6	2.75	16.50
1	465.60	465.60
10	3.25	32.50
1	34.10	34.10
1	686.40	686.40
1	66.15	66.15
1	66.15	66.15
1	74.05	74.05
1	74.90	74.90
1	38.00	38.00
1	59.75	59.75
1	310.05	310.05
1	82.30	82.30
1	23.85	23.85
2	131.55	263.10
1	27.85	27.85

BMW Dealer

Performance Motors Limited

A member of the Sime Darby Group
Co. Reg. No. 197401555N GST Reg. No M2-0020081-X



303, Alexandra Road
Sime Darby Performance Centre
Singapore 159941
Tel. 63190100 (Sales & Admin)
63190111 (AfterSales)
Fax. 64747770

280, Karpool Achang Road
East Coast Centre
Singapore 438120
Tel. 63190888 (AfterSales)
Fax. 63449773

315, Alexandra Road
Sime Darby Business Centre
Singapore 159944
Tel. 63190528 (AfterSales)
63190533/530 (Motorrad)
64796501 (AfterSales)
64796524 (Motorrad)

GST REG. NO : M2 - 0020081 - X

E S T I M A T E

Estimate No.	: b1 46201	Page No. : 2 of 2
Date Estimated	: 12/03/2018	
Prepared By	: Kevin Leong Wai Kit	

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SLE6615T	5F01686	28/07/2016	X1 sDrive18i	0

Total Parts :			2,321.25
---------------	--	--	----------

Labour 1	:	5,587.00
Parts	:	2,321.25
Labour 2	:	0.00
Excess	:	0.00
Total GST @ 7%	:	553.58
Grand Total	:	8,461.83

** THIS ESTIMATE IS VALID FOR A PERIOD OF 30 DAYS ONLY**
** PRICE FOR PARTS ARE SUBJECTED TO CHANGE WITHOUT PRIOR NOTICE **

Veron Chen (LKKAuto)

From: Veron Chen (LKKAuto)
Sent: Friday, 1 June 2018 9:20 AM
To: 'PBSP'; Rasul (LKKAuto); SUR
Subject: RE: FINAL REPORT / SLE6615T

Dear Caroline,

WITHOUT PREJUDUCE

Confirmed amount \$7,167.66 before GST

Repair days: 5 days

Final invoice and all supporting documents sent over to MSIG INSURANCE

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: PBSP [mailto:pml-pbsp@simedarby.com.sg]
Sent: Thursday, 31 May 2018 3:05 PM
To: Rasul (LKKAuto) <Rasul@lkkauto.com>; SUR <sur@lkkauto.com>
Subject: FINAL REPORT / SLE6615T

Dear Rasul

We refer to the above and attached Final Report.

Please confirm COR as follows:

Total Labour : 3,691.00

Total Parts : 3,476.66

Total Labour & Parts : 7,167.66

Repair days: 5

Thank you.

Regards,
Caroline
C/o Performance Motors Limited - Body and Paint
303 Alexandra Road Singapore 159941
DID: 6319 0174 Fax: 6479 4601

"This electronic mail content and any accompanying attachments ("the Message") is intended only for the named addressee ("the Recipient") and may contain information that is confidential, privileged and/or proprietary to the Sime Darby group of companies ("Sime Darby") and/or protected under applicable laws. If you are not the intended Recipient, you are strictly prohibited from using, disseminating, forwarding and/or printing the Message. Please notify the sender immediately by return e-mail and permanently delete all copies of the Message. Sime Darby disclaims all liability for any error, loss or damage arising from the Message being infected by computer virus or other malicious software. Any views and/or opinions expressed in the Message are solely those of the author's and do not necessarily represent those of Sime Darby's."

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any willful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	12/03/2018 16:56
Date Of Accident	11/03/2018 18:40
Exact Location Of Accident	SINGAPORE SWIMMING CLUB(SSC) 45 TANJONG RHU RD SG
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SLE6615T
Insured/Policyholder	
Name Of Registered Owner	GUI WEE FONG QUINER
NRIC No	S7212643B
Email Address	QUINERQUI@YAHOO.COM
Mobile Phone No	(LOCAL) +65-90884375
Alternative Phone No	OFFICE-90884375

Vehicle Particulars

Manufacturer	BMW
Model	X1
Exact Purpose for which vehicle was being used at time of accident	NORMAL USAGE
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR

Insurance Company

Name of Insurance Company	AXA INSURANCE PTE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	CN781366
Cover Note Number	

Driver

Name of Driver	GUI WEE FONG QUINER
NRIC No	S7212643B
Date Of Birth	20/04/1972
Occupation	INDOOR
Date Of Driving Pass	31/12/1993
Driving Experience	24 YEARS AND 2 MONTHS
Gender	FEMALE
Mobile Number	(LOCAL) +65-90884375
Fax Number	
Contact Number	OFFICE-90884375
Email Address	QUINERQUI@YAHOO.COM

Address	56 KEW AVENUE
Postcode	466340
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OWNER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	COLLIDED INTO PROPERTY
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles involved in the accident	
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	
Was any other material or property damaged?	NO
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	2

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of Intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

REFER TO ATTACH.

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	YES
Remarks/ Reasons:	FILE TOO BIG, NEED TO BURN CD
Was there any audio recorded?	NO

Details of Witness 1

Name	MATTHIAS MITRA
Phone Number	
Email Address	

Sketch Plan Pg. 1

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the Centre and to copies of the report being made available aforesaid.
8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:


- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.


 Policyholder's Signature
 Date & Time:
 12/3/2018
 1.30pm


 Driver's Signature
 (if driver is not the policyholder)
 Date & Time:


 Reporting Centre Personnel's Signature
 Name:
 NRIC/FIN No.:

Sketch Plan Pg. 2



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

around 6:40pm

Driving up the car park ramp and fallen Metal signage drop down and hit my car windshield and as well as scratched and dented the car on the side of the driver.

Scratches and cracks are visible on the side windows and top metal framing, as well as glass windshield.

Hanging signage drop on the car front windshield & dent scratched the car top driver side body & windows

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:
NRIC/PIR No.:

Addendum Sheet



GENERAL INSURANCE ASSOCIATION OF SINGAPORE RECORDS MANAGEMENT CENTRE
8 Raffles Quay #12-00 Singapore 048580
Tel: (65) 4224 0010 Fax: (65) 4224 0030
Operating Hours: Monday to Friday: 09:00 - 17:00
UEN: S66989959 / GST Reg. No.: M400017731

IMPORTANT NOTE: Please submit the completed Addendum form to the same Authorised Reporting Centre with whom you submitted the Original Report.

ADDENDUM

(A) PARTICULARS OF PERSON MAKING THE AMENDMENTS:

Original Report No. : MPML 18034273 Vehicle Registration No. : SLE 6615T
Name (as shown in NRIC) : Gai Wee Fong Quiner NRIC/FIN/Passport No. : S7212643B
(*Vehicle Driver / Vehicle Owner) (*) Please delete as appropriate
Address : 56 Kew Avenue Singapore 466004
Contact (Tel) : _____ Mobile No. : 90884575
Email Address : _____
Date of Accident : 11/3/18 Time of Accident : 1840 hrs
Place of Accident : Singapore swimming club (SSC) 45 Tanjong Pagar Rd. SG
Insurance Company : AXA

(B) ADDITIONAL INFORMATION / AMENDMENTS:

I have made a report on the above mentioned accident and would like to include additional information or make the following amendments:

changing from own damage claim to 3rd party claim

Policyholder / Driver's Signature
Date:


Reporting Centre Personnel's Signature
Name: Kevin Loong
NRIC/FIN No.:
Date:

Performance Motors Limited

A member of the Sime Darby Group
Co. Reg. No. 197401559W GST Reg. No. M2-0020081-x



303, Alexandra Road
Sime Darby Performance Centre
Singapore 159941
Tel. 63190100 (Sales & Admin)
63190111 (AfterSales)
Fax. 64747770

280, Kampong Arang Road
East Coast Centre
Singapore 438180
Tel. 63190888 (AfterSales)
Fax. 63449773

315, Alexandra Road
Sime Darby Business Centre
Singapore 159944
Tel. 63190528 (AfterSales)
63190533/530 (Motorrad)
Fax. 64796601 (AfterSales)
64796624 (Motorrad)

GST REG. NO : M2 - 0020081 - X

ESTIMATE

Estimate No. : b1 46201	Page No. : 1 of 2
Date Estimated : 12/03/2018	
Prepared By : Kevin Leong Wai Kit	

- ESTIMATE REPAIR FOR - Gui Wee Fong Quiner 56 Kew Avenue Singapore 466340	- ACCOUNT - 40000 Cash Sales - Service Singapore
--	---

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SLE6615T	5F01686	28/07/2016	X1 sDrive18i	0

DESCRIPTION	VALUE
To replace front right door moulding, door chrome, rear right door moulding, door chrome, right roof moulding and all attachments cause by accident.	✓ 2125 3,400.00
Painting on right roof frame & rear lid spoiler	✓ 806 898.00
To replace front windscreen glass include conduct water leak test.	✓ 649.00
To supply and install front windscreen solar film.	MX 531.00
To supply and install IU unit bracket.	✓ 31.00
Sundries.	✓ ? 80.00 <i>rec</i>
Total Labour 1:	5,587.00

DESCRIPTION	QTY	PRIC	VALUE
HEX NUT	6	2.75	AN ? 16.50
RH ROOF RAILS ALUMINIUM SATINATED	1	465.60	Scr 465.60
BUMP STOP	10	3.25	na 32.50
COVER WINDSHIELD TOP	1	34.10	na 34.10
FRT WINDSCREEN RAIN SENSOR (RLSBS)	1	686.40	Chopped 686.40
LH DRIP MOULDING	1	66.15	na 66.15
RH DRIP MOULDING	1	66.15	na 66.15
FRT RH DOOR COLUMN B COVER	1	74.05	scr 74.05
FRT RH DOOR WINDOW FRAME COVER (ALU)	1	74.90	scr 74.90
REAR RH DOOR COLUMN B COVER	1	38.00	scr 38.00
RR RH DOOR WINDOW FRAME COVER (ALU)	1	59.75	scr ? 59.75
REAR RH SIDE WINDOW FIXED (ALU)	1	310.05	cut 310.05
(S/L) SOUND INSULATION APRON L1367M	1	82.30	na 82.30
(DG) CLEANER R1 (100ML)	1	23.85	na 23.85
(DG/SL) W/SCREEN SEALANT (COLD 1 HOUR)	2	131.55	na 263.10
(DG/SL) GLASS PRIMER 30ML (VP206)	1	27.85	na 27.85

Performance Motors Limited

A member of the Sime Darby Group
Co. Reg. No. 197401559W GST Reg. No M2-0020081-X



303, Alexandra Road
Sime Darby Performance Centre
Singapore 159941
Tel. 63190100 (Sales & Admin)
63190111 (AfterSales)
Fax. 64747770

280, Kampong Arang Road
East Coast Centre
Singapore 438180
Tel. 63190888 (AfterSales)
Fax. 63449773

315, Alexandra Road
Sime Darby Business Centre
Singapore 159944
Tel. 63190528 (AfterSales)
63190533/530 (Motorrad)
64796801 (AfterSales)
64796624 (Motorrad)

GST REG. NO : M2 - 0020081 - X

ESTIMATE

Estimate No. : b1 46201
Date Estimated : 12/03/2018
Prepared By : Kevin Leong Wai Kit

Page No. : 2 of 2

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SLE6615T	5F01686	28/07/2016	X1 sDrive18i	0

Total Parts : 2,321.25

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Claims: OD / 3rd Party / Uninsured losses / Direct Settlement

Regn No. _____ Claim No. _____

Date & Time 19/03/18 @ 1130 Excess S\$ _____Surveyor's Name RRAU Sign _____Surveyor's Tel 90010068 Authorized Yes / No _____

Authorized Date _____ Time _____

RESURVEY PARTS PHOTO BY SURVEYOR Yes / No _____ PML Yes / No _____

Surveyor's Email _____

No. of Working Days Recommended 5 days

8920.20

[Signature]
21/3/18

Labour 1	:	5,587.00
Parts	:	2,321.25
Labour 2	:	0.00
Excess	:	0.00
Total GST @ 7%	:	553.58
Grand Total	:	8,461.83

** THIS ESTIMATE IS VALID FOR A PERIOD OF 30 DAYS ONLY**

** PRICE FOR PARTS ARE SUBJECTED TO CHANGE WITHOUT PRIOR NOTICE **

Performance Motors Limited

A member of the Sime Darby Group
Co Reg No. 197401509W. GST Reg No. M2-0020081-X



FINAL REPORT

Estimate No. : b1 46201
Date Estimated : 12/03/2018
Prepared By : Kevin Leong Wai Kit

Page No. :

REPAIR FOR -
Gui Wee Fong Quiner
56 Kew Avenue

- ACCOUNT - 66
MSIG Insurance (S) Pte Ltd
4 Shenton Way
#21-01 SGX Centre 2
Singapore 068807

Singapore 466340

REGN NO	CHASSIS NO	REGN DATE	MODEL	M LEASE
SLE6615T	5F01686	28/07/2016	X1 sDrive18i	0
DESCRIPTION	ORIGINAL PRICE	DISC. %	NETT	
To make good the RH roof frame, rear spoiler for boot lid include replacement of damaged parts and knocking out dents caused by the accident.	2125.00		2,125.00	
To spray paint RH roof frame and rear spoiler for boot lid	806.00		806.00	
To replace front windscreen glass include conduct water leak test.	649.00		649.00	
To supply and install IU unit bracket.	31.00		31.00	
Sundries.	80.00		80.00	

DESCRIPTION	INIT PRICE	QTY	DISC. %	NETT
3M S/F PLATINUM FFRONT WINDSCREEN	308.41	1.00		308.41 (A) SCR ✓
RH ROOF RAILS ALUMINIUM SATINATED	465.60	1.00		465.60
BUMP STOP	3.25	10.00		32.50
COVER WINDSHIELD TOP	34.10	1.00		34.10
FRT WINDSCREEN RAIN SENSOR (RLSBS)	686.40	1.00		686.40
RH DRIP MOULDING	66.15	1.00		66.15
# FRT RH DOOR SIDE GLASS WINDOW *	247.20	1.00		247.20 (A) SCR
FRT RH DOOR COLUMN B COVER	74.05	1.00		74.05
FRT RH DOOR WINDOW FRAME COVER (ALU)	74.90	1.00		74.90
# FRT RH DOOR WINDOW GUIDE *	108.15	1.00		108.15 } (A) SCR
# REAR RH DOOR WINDOW GUIDE *	127.85	1.00		127.85
REAR RH DOOR COLUMN B COVER	48.15	1.00		48.15
RR RH DOOR WINDOW FRAME COVER (ALU)	59.75	1.00		59.75
REAR RH SIDE WINDOW FIXED (ALU)	310.05	1.00		310.05
# RR RH SIDE DOOR WINDOW FIXED *	146.05	1.00		146.05 } (A) SCR
# SENSOR RAIN/LIGHT/SOLAR/CONDENSATIO * (DG) CLEANER R1 (100ML)	372.55	1.00		372.55 } (A) SCR
(DG/SL) W/SCREEN SEALANT (COLD 1 HOUR)	23.85	1.00		23.85
(DG/SL) GLASS PRIMER 30ML (VP206)	131.55	2.00		263.10
	27.85	1.00		27.85

SUPPLEMENTARY ITEMS

Total Labour :	3,691.00
Total Parts :	3,476.66
Total Labour & Parts :	7,167.66
Deduction for Excess :	
Total Repair Costs less Excess:	7,167.66
GST @7%:	501.74
Grand Total :	7,669.40

Performance Motors Limited

A member of the Sims Darby Group
Co. Reg. No. 197401559W. GST Reg. No. M2-0020081-X



SUPPLEMENTARY

Estimate No. : b1 46201
Date Estimated : 12/03/2018
Prepared By : Kevin Leong Wai Kit

Page No. :

REPAIR FOR -
Gui Wee Fong Quiner
56 Kew Avenue

- ACCOUNT - 66
MSIG Insurance (S) Pte Ltd
4 Shenton Way
#21-01 SGX Centre 2
Singapore 068807

Singapore 466340

REGN NO	CHASSIS NO	REGN DATE	MODEL	M LEASE	
SLE6615T	5F01686	28/07/2016	X1 sDrive18i	0	
DESCRIPTION			ORIGINAL PRICE	DISC. %	NETT

DESCRIPTION	INIT PRICE	QTY	DISC. %	NETT
# FRT RH DOOR SIDE GLASS WINDOW *	247.20	1.00		247.20 <i>su</i>
# FRT RH DOOR WINDOW GUIDE *	108.15	1.00		108.15 <i>su</i>
# REAR RH DOOR WINDOW GUIDE *	127.85	1.00		127.85 <i>su</i>
# RR RH SIDE DOOR WINDOW FIXED *	146.05	1.00		146.05 <i>su</i>
# SENSOR RAIN/LIGHT/SOLAR/CONDENSATIO *	372.55	1.00		372.55 <i>su</i>

Total Labour :	
Total Parts :	1,001.80
Total Labour & Parts :	1,001.80



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
MSIG INSURANCE (SINGAPORE) PTE LTD		Ref : CS/MSG18004832/R1vbn2	
16 RAFFLES QUAY #24-01 HONG LEONG BLDG SINGAPORE 048581		Date : 01-06-2018	
		Code : MSG	
1. Policy Particulars :- THIRD PARTY CLAIM			
Insured Veh.	PUBLIC LIABILITY	Veh. Inspected	SLE 6615T
Policy No.		Coverage (\$)	0.00
Claim No.	B28691906PLY	Excess (\$)	0.00
Assign From	JENNY YONG	Assign Date	13/03/2018
2. Vehicle Particulars & Condition			
Make & Model	B.M.W X1 SD 18I AT	c.c	1499
Engine No.	HIDDEN	Year of Reg.	2016
Chassis No.	WBAHS120605F01686	Colour	WHITE
Odometer	42069	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	FAIR		
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre	225/50 R18	BRIDGESTONE	6 mm
L/H Front Tyre	225/50 R18	BRIDGESTONE	6 mm
R/H Rear Tyre	225/50 R18	BRIDGESTONE	6 mm
L/H Rear Tyre	225/50 R18	BRIDGESTONE	6 mm
4. Description of Damages			
THE VEHICLE SUSTAINED DAMAGES AT THE FRONT PORTION AND O/S BODY. DAMAGES SEE DETAILS.			
5. General Information			
Accident Date	11/03/2018	Inspection Date	19/03/2018
Survey held at	PERFORMANCE MOTORS LTD 303 ALEXANDRA ROAD SINGAPORE 159941		
5a. Remarks			
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair			
ESTIMATED NORMAL PERIOD FOR REPAIR:		5 Working Days	



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLE 6615T

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	SUNDRIES (SN)	NECESSARY	80.00	80.00
6	HEX NUT (SN)	NOT NECESSARY	16.50	-
1	RH ROOF RAILS ALUMINIUM SATINATED (SN)	SCRATCHED	465.60	465.60
10	BUMP STOP (SN)	NECESSARY	32.50	32.50
1	COVER WINDSHIELD TOP (SN)	NECESSARY	34.10	34.10
1	FRT WINDSCREEN RAIN SENSOR (RLSBS)(SN)	CHIPPED	686.40	686.40
1	LH DRIP MOULDING (SN)	NOT NECESSARY	66.15	-
1	RH DRIP MOULDING (SN)	NECESSARY	66.15	66.15
1	FRT RH DOOR COULUM B COVER (SN)	SCRATCHED	74.05	74.05
1	FRT RH DOOR WINDOW FRAME COVER (ALU)(SN)	SCRATCHED	74.90	74.90
1	REAR RH DOOR COULUM B COVER (SN)	SCRATCHED	48.15	48.15
1	RR RH DOOR WINDOW FRAME COVER (ALU)(SN)	SCRATCHED	59.75	59.75
1	REAR RH SIDE WINDOW FIXED (ALU)(SN)	CUT	310.05	310.05
1	(S/L) SOUND INSULATOR APRON L1367M (SN)	NOT NECESSARY	82.30	-
1	(D/G) CLEANER R1 (100ML)(SN)	NECESSARY	23.85	23.85
2	(DG/SL) W/SCREEN SEALANT (COLD 1 HOUR)(SN)	NECESSARY	263.10	263.10
1	(DG/SL) GLASS PRIMER 30ML (VP206)(SN)	NECESSARY	27.85	27.85
1	FRONT WINDSCREEN SOLAR FILM (SN)	NOT NECESSARY	531.00	-
1	FRT RH DOOR SIDE GLASS WINDOW (ADDITIONAL)(SN)	SCRATCHED	247.20	247.20
1	FRT RH DOOR WINDOW GUIDE (ADDITIONAL)(SN)	SCRATCHED	108.15	108.15
1	REAR RH DOOR WINDOW GUIDE (ADDITIONAL)(SN)	SCRATCHED	127.85	127.85
1	RR RH SIDE DOOR WINDOW FIXED (ADDITIONAL)(SN)	SCRATCHED	146.05	146.05
1	SENSOR RAIN/LIGHT/SOLAR/CONDENSATIO (ADDITIONAL)(SN)	NECESSARY	372.55	372.55
1	3M S/F PLATINUM FFRONT WINDSCREEN (ADDITIONAL) (SN)	SCRATCHED	308.41	308.41
			4,252.61	3,556.66
LABOUR				
	TO REPLACE FRONT RIGHT DOOR MOULDING, DOOR CHROME, REAR RIGHT DOOR MOULDING, DOOR CHROME, RIGHT ROOF MOULDING AND ALL ATTACHMENTS CAUSED BY ACCIDENT.		3,400.00	2,125.00

Report Ref No. CS/MSG18004832/R1vbn2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.: 2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	PAINING ON RIGHT DOOR FRAME & REAR LID SPOILER.		896.00	806.00
	TO REPLACE FRONT WINDSCREEN GLASS INCLUDE CONDUCT WATER LEAK TEST.		649.00	649.00
	TO SUPPLY AND INSTALL IU UNIT BRACKET.		31.00	31.00
			4,976.00	3,611.00
	GRAND TOTAL		9,228.61	7,167.66
	RECOMMENDED COST OF REPAIRS			7,167.66

Report Ref No. CS/MSG18004832/R1vbn2

MOHAMMED RASUL BIN MOHD YUNUS

Automotive Assessor

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.