

22/03/2002

ASS. REC. BY:

REF: CS/CT18004835 / Gvbm2 Special Instruction:

## ASSIGNMENT (Office)

Surveyor:

merimen

From (Person):

Juwyn Tay

of

CTE

Date/Time: 14/3/2018 10:28am

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

GBD 1715U

Insured:

at Workshop m/s

Jim Auto

Tel:

6289 8126

of

14 Dehu Lane 10 #01-410

Policy No:

DMCVSN1425791703

Claim No:

SNM18DD1292C01

Excess:

\$ 500.00

Sum Insured:

D.O.A.

19/3/2018

Make of Veh:

(Client's Record)

CA / REV / REP. / REV 24 HRS

15.03.2018

H.O.D. Endorsement:

Date/Time:

14/3/2018 1:50pm

Person Contacted:

Jouis

Vehicle IN / OUT

| Date/Time | Action/Instruction (✓) Estimate                          |
|-----------|----------------------------------------------------------|
|           | GBD 1715U - CTE / EQ2 14018736 / 11pm 3/12 DUT: 18.10.14 |
| 16/3/18   | Revert by merimen                                        |
| 19/3/18   | Rece approved from Alfred by merimen                     |
| 17/3/18   | Informed Jouis c/A ex \$500 by email                     |
| 13/7/18   | Final fig \$5945 confirmed by email (Reel 1200, 1770)    |

REF: CT

Merimen

## ASSIGNMENT

From:

Date:

15/3/2018

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No:

GBD 1715U

at Workshop m/s

Jin Auto

of

14 Defu Lane 10 # 01-40

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

\$ 500.00

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value:

\$50K

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

7

days

Res.: Yes or No

Lum Sum:

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No:

GBD 1715U

Yr Regn:

19 Jul 2014

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Nissan cabstar c.c. 2953

Colour:

Silver

A/C:

Insured / Std / NI / NA

Sp. Reading

13/197

T/Radio:

Insured / Std / NI / NA

Eng/No:

C/No:

TN1SC2F248 0856018

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F: 195 R15

R: 165 R13

EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal.

mm

R/Bal.

mm

L/Bal.

mm

L/Bal.

mm

D.O.A.

D.O.I.

15-03-18

Survey held at

W/S

3pm

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

N/S

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

RECEIVED 17 JUL 2018

16/7/2018

Date/Time. File Pass to?

☐

Preli. Report

1)

☐

Final Report

Date/Time. File Return to?

2)

16/7 - typist

Report Format :

merimen

Lump Sum / I.B.I: (\$ 5945 / 2)

Days Of Repair:

7

Resurvey No. of Trip:

1

Add Fee:

☐

Site Insp (\$

☐

Interview (\$

☐

Tech. Invs (\$

☐

Weekend (\$

Survey Fee:

Transportation:

) \$ + RS. \$ SI

) Photos

) Others

TOTAL

120



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

| Affiliated to Federation Internationale Des Experts En Automobile                                                  |                     |                                                                                 |                          |           |
|--------------------------------------------------------------------------------------------------------------------|---------------------|---------------------------------------------------------------------------------|--------------------------|-----------|
| CHINA TAIPING INSURANCE (S) PTE LTD                                                                                |                     |                                                                                 | Ref : CS/CTI18004835/Gvb |           |
| 3 ANSON ROAD #16-00<br>SPRINGLEAF TOWERSINGAPORE 079909                                                            |                     |                                                                                 | Date : 14-03-2018        |           |
|                                                                                                                    |                     |                                                                                 | Code : CTI               |           |
| <b>1. Policy Particulars :- OWN DAMAGE</b>                                                                         |                     |                                                                                 |                          |           |
| Insured Veh.                                                                                                       |                     | Veh. Inspected                                                                  |                          | GBD 1715U |
| Policy No.                                                                                                         | DMCVSN1425791703    | Coverage (\$)                                                                   | 0.00                     |           |
| Claim No.                                                                                                          | SNM18D01292C01      | Excess (\$)                                                                     | 500.00                   |           |
| Assign From                                                                                                        | MERIMEN (JOWYN TAY) | Assign Date                                                                     | 14/03/2018               |           |
| <b>2. Vehicle Particulars &amp; Condition</b>                                                                      |                     |                                                                                 |                          |           |
| Make & Model                                                                                                       |                     | c.c                                                                             |                          | 0         |
| Engine No.                                                                                                         | HIDDEN              | Year of Reg.                                                                    |                          |           |
| Chassis No.                                                                                                        |                     | Colour                                                                          |                          |           |
| Odometer                                                                                                           | -                   | Steering                                                                        |                          |           |
| Brakes                                                                                                             |                     | Modification                                                                    |                          |           |
| General                                                                                                            |                     |                                                                                 |                          |           |
| <b>3. Conditions of Tyres</b>                                                                                      |                     |                                                                                 |                          |           |
|                                                                                                                    | Size                | Make                                                                            | Balance                  |           |
| R/H Front Tyre                                                                                                     |                     |                                                                                 | mm                       |           |
| L/H Front Tyre                                                                                                     |                     |                                                                                 | mm                       |           |
| R/H Rear Tyre                                                                                                      |                     |                                                                                 | mm                       |           |
| L/H Rear Tyre                                                                                                      |                     |                                                                                 | mm                       |           |
| <b>4. Description of Damages</b>                                                                                   |                     |                                                                                 |                          |           |
|                                                                                                                    |                     |                                                                                 |                          |           |
| <b>5. General Information</b>                                                                                      |                     |                                                                                 |                          |           |
| Accident Date                                                                                                      |                     | 09/03/2018                                                                      | Inspection Date          |           |
|                                                                                                                    |                     |                                                                                 | 14/03/2018               |           |
| Survey held at                                                                                                     |                     | JIN AUTO SERVICES PTE LTD<br>BLK 14 DEFU LANE 10<br>#01-412<br>SINGAPORE 539195 |                          |           |
| <b>5a. Remarks</b>                                                                                                 |                     |                                                                                 |                          |           |
| A)THE MARKET VALUE IS S\$------(EST. AVERAGE)<br>B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE AUTHORISED REPAIRS. |                     |                                                                                 |                          |           |

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

|       |                                                                                                              |       |                                                                                                     |
|-------|--------------------------------------------------------------------------------------------------------------|-------|-----------------------------------------------------------------------------------------------------|
| To:   | China Taiping Insurance (Singapore) Pte. Ltd.<br>3 Anson Road<br>#16-00 Springleaf Tower<br>Singapore 079909 | From: | LKK Auto Consultants Pte Ltd<br>51 Ubi Ave 1 #01-25<br>Paya Ubi Industrial Park<br>Singapore 408933 |
| Attn: | Jowyn Tay                                                                                                    | Date: | 16 Mar 2018                                                                                         |

**Preliminary Advice**

|                    |                                                                                            |                         |                    |
|--------------------|--------------------------------------------------------------------------------------------|-------------------------|--------------------|
| Vehicle No         | : GBD1715U                                                                                 | Accident Date           | : 09/03/2018       |
| Make               | : NISSAN CABSTAR                                                                           | Policy No.              | : DMCVSN1425791703 |
| Assignment Date    | : 14/03/2018                                                                               | Excess                  | : S\$500.00        |
| Date of Inspection | : 15/03/2018                                                                               | Est. Duration of Repair | : 7.00             |
| Inspection At      | : JIN AUTO SERVICES PTE LTD (DEFU)<br>BLK 14 DEFU LANE 10, #01-410/412<br>SINGAPORE 539195 |                         |                    |

**Point of Impact / General Description of Damages**

The vehicle sustained impact / damages front n/s portion and parts claimed are consistent to the accident.

|                             |      |          |
|-----------------------------|------|----------|
| Repairer's Estimate (Gross) | :S\$ | 6,345.00 |
| Revised Amount              | :S\$ | 5,635.00 |
| Check Items (Estimated)     | :S\$ | 445.00   |
| Total                       | :S\$ | 6,080.00 |

Lump Sum Repair :S\$

**Total Loss Consideration**

|                    |      |           |
|--------------------|------|-----------|
| New for Old Value  | :S\$ |           |
| Pre-Accident Value | :S\$ | 50,000.00 |
| COE / PARF Rebate  | :S\$ | 3,939.00  |
| Salvage Value      | :S\$ |           |
| Margin for Repair  | :S\$ | 46,061.00 |

|                        |            |
|------------------------|------------|
| Brake System           | : In Order |
| Steering System        | : In Order |
| Tyre Condition (Front) | : 6/6 mm   |
| Tyre Condition (Rear)  | : 6/6mm    |

**Remarks**

( X ) The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.

( ) The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.

( X ) Other comments : Vehicle repair on part by part.

## ...CLAIM SUBFOLDER...(New Assignment)

## CLAIM SUBFOLDER TRACKING

| Case | Notified                    | Est Submitted                       | Adj Assigned                   | Adj Rpt | Adj Submitted | Ins Auth'd | Status                               |
|------|-----------------------------|-------------------------------------|--------------------------------|---------|---------------|------------|--------------------------------------|
| Main | 13 Mar 2018<br>Sendback Est | 13 Mar 2018<br>12:22<br>S\$6,345.00 | 14 Mar 2018<br>10:28<br>Assign |         |               |            | <b>New Assignment</b><br>Cancel Case |

Main

Reference

Claim Details

Documents

Show All

## CLAIM SUBFOLDER DETAILS

|                          |                                                                                                            |                               |                                  |
|--------------------------|------------------------------------------------------------------------------------------------------------|-------------------------------|----------------------------------|
| <b>Insured:</b>          | TREDI CONSTRUCTION PTE LTD, Co. Reg. No.: 199302238C                                                       |                               |                                  |
| <b>Vehicle Reg. No.:</b> | GBD1715U                                                                                                   | <b>Date of Loss:</b>          | 09/03/2018 00:00 - :59           |
| <b>Claim Type:</b>       | OD / SNM18D01292C01                                                                                        | <b>Policy/Cover Note No.:</b> | DMCVSN1425791703 (Comprehensive) |
|                          |                                                                                                            | <b>Excess:</b>                | S\$500.00                        |
| <b>Repairer:</b>         | Jin Auto Services Pte Ltd (Defu) Blk 14 Defu Lane 10, #01-410/412, 539195 Defu Lane - Tel: 6289 8126       |                               |                                  |
| <b>Handling Insurer:</b> | China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Jowyn Tay - 6389 6174] |                               |                                  |
| <b>Adjuster:</b>         | LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Final Rpt due 23/03/2018]                          |                               |                                  |
| <b>Driver/Custodian:</b> | AIW TIAN FONG ( / Male)                                                                                    |                               |                                  |
| <b>Adj Asg. Remarks:</b> | PLEASE PROCEED TO SURVEY & REVERT, EXCESS OF \$500.00 APPLIES.                                             |                               |                                  |

## ASSOCIATED MAIL RECEIVED

View All

Compose Case Mail

There are no mail for this case.

## ALL ASSOCIATED TASKS

View All

Search Tasks

Create New Task

Complete

| Due Date    | Priority | Type | Task Group | Subject | Handler | Assigned By | Completed On | Created On | Done? |
|-------------|----------|------|------------|---------|---------|-------------|--------------|------------|-------|
| No results. |          |      |            |         |         |             |              |            |       |

## Veron Chen (LKKAUTO)

---

**From:** jouis <jouis@jinauto.com.sg>  
**Sent:** Friday, 13 July 2018 10:34 AM  
**To:** Veron Chen (LKKAUTO)  
**Subject:** RE: GBD1715 OD CLAIM

Dear Veron

Ok . confirm please offer in merimen

Thank you & Best Regards,  
Jouis Seow  
Jin Auto Services Pte Ltd  
Blk 14 #01-412 Defu Lane 10  
Singapore 539195.

Tel : (65) 62898126  
Fax : (65) 62870590  
Email : [jouis@jinauto.com.sg](mailto:jouis@jinauto.com.sg)

---

**From:** Veron Chen (LKKAUTO) [mailto:veronchen@lkkauto.com]  
**Sent:** Wednesday, 11 July 2018 5:30 PM  
**To:** jouis <jouis@jinauto.com.sg>; guoqiang@lkkauto.com.sg  
**Cc:** SUR <sur@lkkauto.com>  
**Subject:** RE: GBD1715 OD CLAIM

Dear Jouis,

Finalize amount \$5945 before excess \$500

No of days: 7 days

Kindly confirmed.

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

---

**From:** jouis [mailto:jouis@jinauto.com.sg]  
**Sent:** Wednesday, 11 July 2018 11:57 AM  
**To:** [guoqiang@lkkauto.com.sg](mailto:guoqiang@lkkauto.com.sg)  
**Cc:** Admin-D (LKKAUTO) <[admin-d@lkkauto.com](mailto:admin-d@lkkauto.com)>  
**Subject:** FW: GBD1715 OD CLAIM

Dear 国强,

请尽快 FINALISED

Thank you & Best Regards,  
Jouis Seow  
Jin Auto Services Pte Ltd  
Blk 14 #01-412 Defu Lane 10  
Singapore 539195.

Tel : (65) 62898126  
Fax : (65) 62870590  
Email : [jouis@jinauto.com.sg](mailto:jouis@jinauto.com.sg)

---

**From:** jouis [<mailto:jouis@jinauto.com.sg>]  
**Sent:** Wednesday, 6 June 2018 10:11 AM  
**To:** 'Catherine Chong (LKK Auto)' <[admin-d@lkkauto.com](mailto:admin-d@lkkauto.com)>  
**Subject:** FW: GBD1715 OD CLAIM for guo qiang

Thank you & Best Regards,  
Jouis Seow  
Jin Auto Services Pte Ltd  
Blk 14 #01-412 Defu Lane 10  
Singapore 539195.

Tel : (65) 62898126  
Fax : (65) 62870590  
Email : [jouis@jinauto.com.sg](mailto:jouis@jinauto.com.sg)

---

**From:** jouis [<mailto:jouis@jinauto.com.sg>]  
**Sent:** Thursday, 17 May 2018 1:48 PM  
**To:** 'Catherine Chong (LKK Auto)' <[admin-d@lkkauto.com](mailto:admin-d@lkkauto.com)>  
**Subject:** FW: GBD1715 OD CLAIM for guo qiang

Thank you & Best Regards,  
Jouis Seow  
Jin Auto Services Pte Ltd  
Blk 14 #01-412 Defu Lane 10  
Singapore 539195.

Tel : (65) 62898126  
Fax : (65) 62870590  
Email : [jouis@jinauto.com.sg](mailto:jouis@jinauto.com.sg)

---

**From:** jouis [<mailto:jouis@jinauto.com.sg>]  
**Sent:** Thursday, 17 May 2018 10:47 AM  
**To:** [guoqiang@lkkauto.com.sg](mailto:guoqiang@lkkauto.com.sg)  
**Subject:** RE: GBD1715 OD CLAIM



• Thank you & Best Regards,  
Jouis Seow  
Jin Auto Services Pte Ltd  
Blk 14 #01-412 Defu Lane 10  
Singapore 539195.

Tel : (65) 62898126  
Fax : (65) 62870590  
Email : [jouis@jinauto.com.sg](mailto:jouis@jinauto.com.sg)

---

**From:** jouis [<mailto:jouis@jinauto.com.sg>]  
**Sent:** Wednesday, 4 April 2018 3:53 PM  
**To:** 'Admin A' <[admin-a@lkkauto.com](mailto:admin-a@lkkauto.com)>  
**Subject:** GBD1715 OD CLAIM

Surveyed by Guo Qiang

Thank you & Best Regards,  
Jouis Seow  
Jin Auto Services Pte Ltd  
Blk 14 #01-412 Defu Lane 10  
Singapore 539195.

Tel : (65) 62898126  
Fax : (65) 62870590  
Email : [jouis@jinauto.com.sg](mailto:jouis@jinauto.com.sg)

**Veron Chen (LKKAuto)**

---

**From:** Veron Chen (LKKAuto)  
**Sent:** Monday, 19 March 2018 10:36 AM  
**To:** 'Jouis'; SUR  
**Subject:** RE: MRM34128061.PDF GBD1715U estimate

Dear Jouis,

As instructed by our client, please proceed to repair the insured vehicle **GBD 1715U (Excess \$500/-)**.

If there are any check items or supplementary items please inform our office's Assignment Team at Tel: 6741 8434 to arrange our surveyor for inspection.

All supplementary items and unconfirm items are subjected to further approval from insurance company before completion of the repair.

\*Our client reserve their right **not to pay** if there is no valid approval obtained before repair.

Best Regards,

**Veron Chen** | Case Handler

**LKK Auto Consultants Pte Ltd**

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

---

**From:** Jouis [mailto:jouis@jinauto.com.sg]  
**Sent:** Friday, 16 March 2018 11:20 AM  
**To:** Admin-D (LKKAuto) <admin-d@lkkauto.com>  
**Subject:** RE: MRM34128061.PDF GBD1715U estimate

Thank you & Best Regards,  
Jouis Seow  
Jin Auto Services Pte Ltd  
Blk 14 #01-412 Defu Lane 10  
Singapore 539195.

Tel : (65) 62898126  
Fax : (65) 62870590  
Email : [jouis@jinauto.com.sg](mailto:jouis@jinauto.com.sg)

---

**From:** Catherine Chong (LKK Auto) [mailto:admin-d@lkkauto.com]  
**Sent:** Friday, 16 March 2018 10:54 AM  
**To:** 'Jouis'  
**Subject:** RE: MRM34128061.PDF GBD1715U estimate

Dear Jouis,

No surveyor marking?

Best Regards,

**Catherine Chong** | Admin

**LKK Auto Consultants Pte Ltd**

Phone: 6741-8434 | email: [assignments@lkkauto.com](mailto:assignments@lkkauto.com) | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

---

**From:** jous [mailto:[jous@jinauto.com.sg](mailto:jous@jinauto.com.sg)]

**Sent:** Friday, 16 March, 2018 10:43 AM

**To:** [assignments@lkkauto.com](mailto:assignments@lkkauto.com)

**Subject:** MRM34128061.PDF GBD1715U estimate

Hi Catherine ,

As requested .

Thank you & Best Regards,

Jouis Seow

Jin Auto Services Pte Ltd

Blk 14 #01-412 Defu Lane 10

Singapore 539195.

Tel : (65) 62898126

Fax : (65) 62870590

Email : [jous@jinauto.com.sg](mailto:jous@jinauto.com.sg)

## View Received Message

This mail is associated with :

**GBD1715U (SNM18D01292C01)**

OD

Mar 9 2018 12:00AM

[TRED] CONSTRUCTION PTE LTD]

Jin Auto Services Pte Ltd

[Reply](#) [Reply All](#) [Mark as Unread](#) [Print Message](#) [Delete Message](#) [Forward](#)

**From** China Taiping Insurance (Singapore) Pte. Ltd. (HQ) (CHINA\_TAIPING), sent on **19/03/2018 10:17 AM**.  
**To** LKK\_HQ  
**Subject** Alert - Adj Mandate Approved (S\$6080.00) - GBD1715U - Claim Handler: Jowyn Tay

Approved:6080.00:PLEASE PROCEED TO AUTHORIZE REPAIRS UP TO \$6,080.00 BEFORE EXCESS OF \$500.00. RE-INSPECTION OF VEHICLE REQUIRED.

### DOCUMENTS SUMMARY

There are no documents.

## Enquire PARF/COE Rebate for Registered Vehicle

| Vehicle Owner Particulars      |                                     |
|--------------------------------|-------------------------------------|
| Owner ID Type:                 | Company                             |
| Owner ID:                      | 2238C                               |
| Vehicle Details                |                                     |
| Vehicle No.:                   | GBD1715U                            |
| Vehicle to be Exported:        | No                                  |
| Intended De-registration Date: | 16 Mar 2018                         |
| Vehicle Make:                  | NISSAN                              |
| Vehicle Model:                 | CABSTAR 3.0 5M/T ABS 2DR 2WD EURO 5 |
| Primary Colour:                | Silver                              |
| Manufacturing Year:            | 2014                                |
| Engine No.:                    | ZD30340117K                         |
| Chassis No.:                   | JN1SC2F24Z0856018                   |
| Maximum Power Output:          | -                                   |
| Open Market Value:             | \$25,081.00                         |
| Original Registration Date:    | 19 Jul 2014                         |
| First Registration Date:       | 19 Jul 2014                         |
| Transfer Count:                | 0                                   |
| Actual ARF Paid:               | \$1,255.00                          |
| Intended PARF Rebate Details   |                                     |
| PARF Eligibility:              | No                                  |
| PARF Eligibility Expiry Date:  | -                                   |
| PARF Rebate Amount:            | \$0.00                              |
| Intended COE Rebate Details    |                                     |
| COE Expiry Date:               | 18 Jul 2024                         |
| COE Category:                  | C - Goods Vehicle & Bus             |
| COE Period(Years):             | 10                                  |
| PQP Paid:                      | \$6,215.00                          |
| COE Rebate Amount:             | \$3,939.00                          |
| <b>Total Rebate Amount:</b>    | <b>\$3,939.00</b>                   |

The information contained herein is correct as at 16 Mar 2018

OK

# *Jin Auto Services Pte Ltd*

Blk 14 Defu Lane 10 #01-410/412

Singapore 539195

Tel: 6289 8126 Fax: 6287 0590

Email: Jin@jinauto.com.sg

Company Reg. No: 200704370C GST Reg.No: 200704370C

INSURER: China Taiping Insurance (Singapore) Pte. Ltd. (HQ)

LKK.

## PARTICULARS OF CLAIM

|                   |                               |                    |                   |
|-------------------|-------------------------------|--------------------|-------------------|
| Claim Type:       | OD (OWN DAMAGE)               | Ref. No:           | GBD1715U          |
| Policy No:        | DMCVSN1425791703              | Date of Loss:      | 09/03/2018        |
| Vehicle Reg. No.: | GBD1715U                      | Driveable?         |                   |
| Driver Age/Info:  | / MALE                        | Party At Fault:    | UNKNOWN           |
| TP Injury         | NO                            | Third Party        | NO                |
| Involved?         |                               | Involved?          |                   |
| Insured/Claimant: | TREDI CONSTRUCTION PTE LTD    |                    |                   |
| Driver:           | AIW TIAN FONG                 |                    |                   |
| Make/Model:       | NISSAN CABSTAR, 3.0 D F24 (M) | Vehicle Reg. Date: | 19/07/2014        |
| Vehicle Colour:   | METALLIC SILVER               |                    |                   |
| Engine No:        | ZD30340117K                   | Chassis No:        | JN1SC2F24Z0856018 |
| Odometer:         | 131195 KM                     |                    |                   |

Paint Type:

Total Loss? NO

Est. Duration of  
Repair (day) 9

Description of Accident/Loss I HIT ONTO A STONE WHEN I TRAVELLED ALONG THOMSON ROAD, AS A RESULT, MY VEHICLE SKIDED AND HIT ONTO THE WALL OF ONE OF THE HOUSE AT THE RESIDENCE AREA NEARBY.

Remarks: FRONT LH DOOR NO STOCK ( NEED ORDER FROM AGENT )

Present Location: JIN AUTO SERVICES PTE LTD (DEFU)

| COST OF CLAIMS               | Amount      |
|------------------------------|-------------|
| Parts                        | 4,160.00    |
| Miscellaneous Items          | 0.00        |
| Labour                       | 2,185.00    |
| Paintwork Labour             | 0.00        |
| Towing                       | 0.00        |
|                              | <b>7145</b> |
| Calculated Gross Total (S\$) | 6,345.00    |
| - Excess (S\$)               | 500.00      |
| (S\$)                        | 5,845.00    |
| + GST 7.00% (S\$)            | 409.15      |
| Nett Amount (S\$)            | 6,254.15    |

This claim is handled by: JOUIS SEOW

Generated using Merimen e-Claims Internet Estimation & Adjusting System

**REPAIR DETAILS****Reference**

Part Source: (Last Synchronised: 13 Mar 2018)  
 Parts: N/A NISSAN CABSTAR 3.0 D F24 (M) (Model not available in database)  
 Labour: Repairer's (Price-denominated Standard List)  
 Print Code: Jin Auto Services Pte Ltd/GBD1715U/13/03/2018 12:22  
 Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page  
 Further Info: Items/values not in reference catalogue are prefixed with an asterisk \*.

**Estimates on Parts**

| No.               | Qty | Part No. | Particulars                                          | %Disc | %Depr | Amount           |
|-------------------|-----|----------|------------------------------------------------------|-------|-------|------------------|
| 1                 | 1   |          | *FRONT BUMPER / CRA                                  | 0.00  | 0.00  | *550.00 F ✓      |
| 2                 | 1   |          | *FRONT BUMPER LH SIDE RETAINER X NN                  | 0.00  | 0.00  | *20.00 F         |
| 3                 | 10  |          | *FRONT BUMPER CLIPS X NN                             | 0.00  | 0.00  | *30.00 F         |
| 4                 | 1   |          | *LH HEADLAMP / Int                                   | 0.00  | 0.00  | *380.00 F ✓      |
| 5                 | 1   |          | *FRONT LH CORNER PANEL / TV                          | 0.00  | 0.00  | *230.00 F ✓      |
| 6                 | 1   |          | *FRONT LH SIDE MIRROR X <del>AS</del> NN / O'S       | 0.00  | 0.00  | *70.00 F 50      |
| 7                 | 1   |          | *FRONT LH SIDE MIRROR STAND / BT                     | 0.00  | 0.00  | *150.00 F ✓      |
| 8                 | 1   |          | *FRONT LH SIDE MIRROR ROUND X NN                     | 0.00  | 0.00  | *60.00 F         |
| 9                 | 1   | AGENT    | *FRONT LH DOOR / Bul                                 | 0.00  | 0.00  | *1,400.00 F 1300 |
| 10                | 2   |          | *FRONT LH DOOR HINGE X BT                            | 0.00  | 0.00  | *100.00 F        |
| 11                | 1   |          | *FRONT LH DOOR HINGE CHECKER X BT / repair           | 0.00  | 0.00  | *35.00 F         |
| 12                | 1   |          | *FRONT WINDSCREEN / CRA                              | 0.00  | 0.00  | *650.00 F ✓      |
| 13                | 2   |          | *FRONT WINDSCREEN MOULDING / MC                      | 0.00  | 0.00  | *100.00 F ✓      |
| 14                | 1   |          | *FRONT LH STEP GARNISH / Cat                         | 0.00  | 0.00  | *125.00 F ✓      |
| 15                | 1   |          | *FRONT LH DOOR SIGNAL LAMP X <del>Cat</del> NN       | 0.00  | 0.00  | *35.00 F         |
| 16                | 1   |          | *FRONT LH SIDE MIRROR STAND COVER X NN               | 0.00  | 0.00  | *75.00 F         |
| 17                | 1   |          | *FRONT LH SIDE MIRROR STAND TOP CAP / <del>mis</del> | 0.00  | 0.00  | *20.00 F ✓       |
| 18                | 1   |          | *FRONT LH FENDER SHIELD X NN                         | 0.00  | 0.00  | *95.00 F         |
| 19                | 1   |          | *SEALANT X                                           | 0.00  | 0.00  | *25.00 F         |
| 20                | 1   |          | *DOOR STICKER X <del>MC</del> NN                     | 0.00  | 0.00  | *10.00 F         |
| Total Parts (S\$) |     |          |                                                      |       |       | 4,160.00         |

F=Franchise part.

Jin Auto Services Pte Ltd/GBD1715U/13/03/2018 12:22. Not valid without Reference section.  
 Generated using Merimen e-Claims IEAS

(C)



## Estimates on Miscellaneous Items

There are no new miscellaneous items selected.

## Estimates on Labour

| No                      | Particulars                          | Lab.Type | Amount                 |
|-------------------------|--------------------------------------|----------|------------------------|
| <u>Labour Items</u>     |                                      |          |                        |
| 1                       | LABOUR CHARGE                        | New      | 900.00 720             |
| 2                       | SPRAY PAINTING                       | New      | 780.00 720             |
| 3                       | TO REMOVE AND RENEW FRONT WINDSCREEN | New      | 120.00 <del>10</del> ✓ |
| 4                       | WIRING CHECK                         | New      | 35.00 30               |
| 5                       | REMOVE AND REFIX FRONT DASHOARD      | New      | 350.00 X NN            |
| Gross Labour Cost (S\$) |                                      |          | 2,185.00               |

Jin Auto Services Pte Ltd/GBD1715U/13/03/2018 12:22. Not valid without Reference section.  
Generated using Merimen e-Claims IEAS

&lt; END OF ESTIMATES &gt;

7 Days.

part by part.

before paint photos.

Not Authorised.

Excess \$500.

Gao Qiang - 6880282

15/3/18.

*[Signature]*  
16/3/18

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

# Jin Auto Services Pte Ltd

Blk 14 Defu Lane 10 #01-410/412

Singapore 539195

Tel: 6289 8126 Fax: 6287 0590

Email: Jin@jinauto.com.sg

Company Reg. No: 200704370C GST Reg.No: 200704370C

## (SUPPLEMENTARY)

INSURER: China Taiping Insurance (Singapore) Pte. Ltd. (HQ)

### PARTICULARS OF CLAIM

|                               |                                                                                                                                                                |                       |                   |
|-------------------------------|----------------------------------------------------------------------------------------------------------------------------------------------------------------|-----------------------|-------------------|
| Claim Type:                   | OD (OWN DAMAGE)                                                                                                                                                | Ref. No:              | GBD1715U          |
| Policy No:                    | DMCVSN1425791703                                                                                                                                               | Date of Loss:         | 09/03/2018        |
| Vehicle Reg. No.:             | <b>GBD1715U</b>                                                                                                                                                | Driveable?            |                   |
| Driver Age/Info:              | / MALE                                                                                                                                                         | Party At Fault:       | UNKNOWN           |
| TP Injury Involved?           | NO                                                                                                                                                             | Third Party Involved? | NO                |
| Insured/Claimant:             | TREDI CONSTRUCTION PTE LTD                                                                                                                                     |                       |                   |
| Driver:                       | AIW TIAN FONG                                                                                                                                                  |                       |                   |
| Make/Model:                   | NISSAN CABSTAR, 3.0 D F24 (M)                                                                                                                                  | Vehicle Reg. Date:    | 19/07/2014        |
| Vehicle Colour:               | METALLIC SILVER                                                                                                                                                | Chassis No:           | JN1SC2F24Z0856018 |
| Engine No:                    | ZD30340117K                                                                                                                                                    |                       |                   |
| Odometer:                     | 131195 KM                                                                                                                                                      |                       |                   |
| Paint Type:                   |                                                                                                                                                                |                       |                   |
| Total Loss?                   | <b>NO</b>                                                                                                                                                      |                       |                   |
| Est. Duration of Repair (day) | 9                                                                                                                                                              |                       |                   |
| Description of Accident/Loss  | I HIT ONTO A STONE WHEN I TRAVELLED ALONG THOMSON ROAD, AS A RESULT, MY VEHICLE SKIDED AND HIT ONTO THE WALL OF ONE OF THE HOUSE AT THE RESIDENCE AREA NEARBY. |                       |                   |
| Present Location:             | JIN AUTO SERVICES PTE LTD (DEFU)                                                                                                                               |                       |                   |

| <b>COST OF CLAIMS</b>             | <b>Amount</b>   |
|-----------------------------------|-----------------|
| Parts                             | 800.00          |
| Miscellaneous Items               | 0.00            |
| Labour                            | 0.00            |
| Paintwork Labour                  | 0.00            |
| Towing                            | 0.00            |
| <b>Gross Total (S\$)</b>          | <b>800.00</b>   |
| <b>+ GST 7.00% (S\$)</b>          | <b>56.00</b>    |
| <b>Nett Amount (S\$)</b>          | <b>856.00</b>   |
| <b>+ Previous Estimates (S\$)</b> | <b>6,254.15</b> |
| <b>Claim Total (S\$)</b>          | <b>7,110.15</b> |

Generated using Merimen e-Claims Internet Estimation &amp; Adjusting System

**REPAIR DETAILS****Reference****Part Source:** (Last Synchronised: 16 Apr 2018)**Parts:** N/A NISSAN CABSTAR 3.0 D F24 (M) (Model not available in database)**Labour:** Repairer's (Price-denominated Standard List)**Print Code:** Jin Auto Services Pte Ltd/GBD1715U/16/04/2018 13:29**Validity:** These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page**Further Info:** Items/values not in reference catalogue are prefixed with an asterisk \*.**Estimates on Parts**

| No.               | Qty | Part No.      | Particulars                      | %Disc | %Depr | Amount      |
|-------------------|-----|---------------|----------------------------------|-------|-------|-------------|
| 1                 | 1   | N61877-MA01B  | *SLIT COVER / <i>re.</i>         | 0.00  | 0.00  | *20.00 F ✓  |
| 2                 | 1   | N61877-MA160  | *SIDE GARNISH / <i>re.</i>       | 0.00  | 0.00  | *75.00 F ✓  |
| 3                 | 1   | N96303-MA000Y | *MIRROR / <i>cut</i>             | 0.00  | 0.00  | *20.00 F ✓  |
| 4                 | 1   |               | *F/DR INNER LOCK LH / <i>BT</i>  | 0.00  | 0.00  | *90.00 F ✓  |
| 5                 | 1   |               | *AC FAN ASSY / <i>URA.</i>       | 0.00  | 0.00  | *560.00 F ✓ |
| 6                 | 1   | N261609Y000   | *FENDER SIGNAL LAMP / <i>cut</i> | 0.00  | 0.00  | *35.00 F ✓  |
| Total Parts (S\$) |     |               |                                  |       |       | 800.00      |

Franchise part.

Jin Auto Services Pte Ltd/GBD1715U/16/04/2018 13:29. Not valid without Reference section.  
Generated using Merimen e-Claims IEAS

6

## Estimates on Miscellaneous Items

There are no new miscellaneous items selected.

## Estimates on Labour

There are no labour items selected.

Jin Auto Services Pte Ltd/GBD1715U/16/04/2018 13:29. Not valid without Reference section.  
Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >

05:05p


Received by: JIN AUTO SERVICES PTE LTD

page.2  
0002.

FAX 67492098

Fong Tat Motor

# 767- -A 02 BODY SIDE FITTING



GBD 7154



# 合興汽車玻璃私人有限公司

## HE XING AUTO GLASS PTE LTD

MAIN OFFICE: No. 76 DUNLOP STREET, SINGAPORE 209403  
CAR WINDSCREEN DIV. No 26 CUFF RD. S 209736  
TEL : 6298 3113 FAX : 6298 3002  
A/C : 6291 1886 FAX : 6291 7717  
Co. Reg. No: 200310936C GST Reg. No: 20-0310936-C

### TAX INVOICE

NO: GLI8131301  
DATE: 21/03/2018  
A/C CODE: LDJ1219  
TERMS: CR  
P/O NO: GBD 1715U

M/S: JIN AUTO SERVICES PTE LTD

BLK 14 #01-412  
DEFULANE 10  
SINGAPORE 539195  
NISSAN CABSTAR (GBD 1715U)

|         |                       |          |     |              | PAGE:1     |
|---------|-----------------------|----------|-----|--------------|------------|
| Part No | Description           | Location | Qty | Unit Price   | Amount     |
|         |                       |          |     | SIN          | SIN        |
| 1       | WN72712-MA000         | CC1A     | 1   | 650.00       | 650.00     |
|         | W/S GLASS FRT         | CC1A     | 2   | 50.00        | 100.00     |
|         | W/S SIDE MLDG FRT R/L |          |     |              |            |
|         | WN72752-MA00A         |          | 3   | TOTAL        | SIN 750.00 |
|         |                       |          |     | ADD GST @ 7% | 52.50      |
|         |                       |          |     | GRAND TOTAL  | SIN 802.50 |

TOTAL QUANTITY:

汽车挡风镜

Reprint:1 / SENG / 04/04/2018 2:45:31 PM  
SALESMAN: SENG  
This document is computer generated. No signature required.

GOODS SOLD ARE NOT RETURNABLE



Door Glass



Back Glass

E. & O. E.

GOODS RECEIVED BY

Side Glass



# 力善汽車零件私人有限公司 LESUN AUTO PARTS PTE LTD

BLK 3018 UBI ROAD 1 #02-117 SINGAPORE 408710

TEL: 6846 8655 FAX: 6748 3092

A/C TEL: 6291 1886 FAX: 6291 7717

EMAIL: lesun@singnet.com.sg

Co. Reg. No.: 200516381H GST Reg. No.: 20-0516381-H

## TAX INVOICE

M/S: JIN AUTO SERVICES PTE LTD

BLK 14 #01-412

DEFU LANE 10

SINGAPORE 539195

GBA 1715 U

(T)

NO: LLI0207033

DATE: 21/03/2018

A/C CODE: LLDJA43

TERMS: CR

|                 |                                                  |          |     |            |            | PAGE:1 |
|-----------------|--------------------------------------------------|----------|-----|------------|------------|--------|
| Part No         | Description                                      | Location | Qty | Unit Price | Amount     |        |
|                 |                                                  |          |     | SIN        | SIN        |        |
| 1               | N96303-MA000Y (CA) MIRROR                        | NSC-5D   | 1   | 20.00      | 20.00      |        |
| 2               | N80503-AA210 (CA) F/DR INNER LOCK LH (AA200)     | NSB-2A2  | 1   | 90.00      | 90.00      |        |
| 3               | N92123-MA00A (CA) AC FAN ASSY ###                | NSD-3    | 1   | 560.00     | 560.00     |        |
| 4               | N26160-9Y000 (CA) FENDER SIGNAL LAMP R/L (2YA00) | NOF-30A  | 1   | 35.00      | 35.00      |        |
| TOTAL QUANTITY: |                                                  |          | 4   | TOTAL      | SIN 705.00 |        |
| ADD GST @ 7%    |                                                  |          |     |            | 49.35      |        |
| GRAND TOTAL     |                                                  |          |     |            | SIN 754.35 |        |

(4)

Reprint:1 / MENG / 04/04/2018 3:26:39 PM

SALESMAN: MENG

This document is computer generated. No signature required.

GOODS SOLD ARE NOT RETURNABLE

E. & O. E.

GOODS RECEIVED BY







# 力善汽車零件私人有限公司 LESUN AUTO PARTS PTE LTD

BLK 3018 UBI ROAD 1 #02-117 SINGAPORE 408710

TEL: 6846 8655 FAX: 6748 3092

A/C TEL: 6291 1886 FAX: 6291 7717

EMAIL: lesun@singnet.com.sg

Co. Reg. No.: 200516381H GST Reg. No.: 20-0516381-H

## TAX INVOICE

M/S: JIN AUTO SERVICES PTE LTD

BLK 14 #01-412  
DEFU LANE 10  
SINGAPORE 539195  
GBD1715U



NO: LLI0206903  
DATE: 19/03/2018  
A/C CODE: LLDJA43  
TERMS: CR

PAGE:1

| Part No         | Description  | Location                      | Qty | Unit Price   | Amount              |
|-----------------|--------------|-------------------------------|-----|--------------|---------------------|
|                 |              |                               |     | SIN          | SIN                 |
| 1               | N62010-MD80A | FRT BUMPER ***                | 1   | 550.00       | 550.00              |
| 2               | N26075-MA000 | H.LAMP UNIT LH ###            | 1   | 380.00       | 380.00              |
| 3               | NF1263-MA0AA | FRT SIDE PANEL LH ##          | 1   | 230.00       | 230.00              |
| 4               | N96311-MA000 | MIRROR ARM LH ##              | 1   | 150.00       | 150.00              |
| 5               | N61877-MA01B | (A) SLIT COVER LH (MA010) *** | 1   | 20.00        | 20.00               |
| 6               | N61877-MA160 | (A) SIDE GARNISH LH ##        | 1   | 75.00        | 75.00               |
| 7               | N96331-5T002 | UNDER VIEW MIRROR ***         | 1   | 50.00        | 50.00               |
| 8               | N96113-MA00A | STEP GARNISH LH ***           | 1   | 125.00       | 125.00              |
| 9               | N96374-MA00A | COVER MIRROR ARM ##           | 1   | 20.00        | 20.00               |
| 10              | NH0101-MA0MM | FRT DOOR LH ##                | 1   | 1,300.00     | 1,300.00            |
| TOTAL QUANTITY: |              |                               | 10  | TOTAL        | SIN 2,900.00        |
|                 |              |                               |     | ADD GST @ 7% | 203.00              |
|                 |              |                               |     | GRAND TOTAL  | <u>SIN 3,103.00</u> |

10

Reprint:1 / MENG / 03/04/2018 3:58:12 PM

SALESMAN: MENG

This document is computer generated. No signature required.

GOODS SOLD ARE NOT RETURNABLE

E. & O. E.

GOODS RECEIVED BY





# LKK Auto Consultants Pte Ltd (Co Reg No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

China Taiping Insurance (Singapore) Pte. Ltd.  
3 Anson Road, #16-00 Springleaf Tower  
Singapore 079909

Our File No: CS/CTI18004835/GVBN2

Date: 18/07/2018

### REFERENCE

Insured/Claimant: TREDI CONSTRUCTION PTE LTD Policy No: DMCVSN1425791703  
Date of Loss: 09/03/2018 Nature of Claim: OD Claim No: SNM18D01292C01

### DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: GBD1715U Engine No: ZD30340117K  
Make & Model: NISSAN CABSTAR, 3.0 D F24 (M) Chassis No: JN1SC2F24Z0856018  
Reg. Date: 19/07/2014 (Man. Year: 2014) Odometer: 131197 km  
Colour: Silver  
Engine Capacity: 2953 cc  
Market Value/New Car Price: S\$50,000.00  
Sum Insured (S\$): Market Value/New Car Price

### CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes  
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

### CONDITION OF TYRES

Front Tyre Size: 195 R15 Rear Tyre Size: 165 R13  
Front Left Side: Dunlop 6 mm Rear Left Side: Dunlop 6 mm  
Front Right Side: Dunlop 6 mm Rear Right Side: Dunlop 6 mm

The above values represent the remaining tyre treads depth

| COST OF CLAIMS                      | Repairer's      | Adjuster's      | Difference      | Diff %       |
|-------------------------------------|-----------------|-----------------|-----------------|--------------|
| Parts                               | 4,960.00        | 4,355.00        | 605.00          | 12.20        |
| Miscellaneous Items                 | 0.00            | 0.00            | 0.00            |              |
| Labour                              | 2,185.00        | 1,590.00        | 595.00          | 27.23        |
| Paintwork Labour                    | 0.00            | 0.00            | 0.00            |              |
| Towing                              | 0.00            | 0.00            | 0.00            |              |
| <b>Calculated Gross Total (S\$)</b> | <b>7,145.00</b> | <b>5,945.00</b> | <b>1,200.00</b> | <b>16.79</b> |
| <b>- Excess (S\$)</b>               | <b>500.00</b>   | <b>500.00</b>   | <b>0.00</b>     | <b>0.00</b>  |
| <b>(S\$)</b>                        | <b>6,645.00</b> | <b>5,445.00</b> | <b>1,200.00</b> | <b>18.06</b> |
| <b>+ GST 7.00/7.00% (S\$)</b>       | <b>465.15</b>   | <b>381.15</b>   | <b>84.00</b>    | <b>18.06</b> |
| <b>Nett Amount (S\$)</b>            | <b>7,110.15</b> | <b>5,826.15</b> | <b>1,284.00</b> | <b>18.06</b> |

### INSPECTION

Date of Assignment: 14/03/2018 Present Location: Jin Auto Services Pte Ltd (Defu)  
Date Inspected: 15/03/2018 Inspected At: Jin Auto Services Pte Ltd (Defu)  
Blk 14 Defu Lane 10, #01-410/412  
Singapore 539195

Estimated Period of Repair: 7.0 days

Adjuster: XING GUO QIANG

Manager: VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

## REPAIR DETAILS

### Reference

|                      |                                                                                                                                                                              |                                                                |
|----------------------|------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|----------------------------------------------------------------|
| <b>Part Source:</b>  | (Last Synchronised: 18 Jul 2018)                                                                                                                                             |                                                                |
| <b>Parts:</b>        | N/A                                                                                                                                                                          | NISSAN CABSTAR 3.0 D F24 (M) (Model not available in database) |
| <b>Labour:</b>       | Repairer's                                                                                                                                                                   | (Price-denominated Standard List)                              |
| <b>Print Code:</b>   | (Unsubmitted, no print-code for GBD1715U)                                                                                                                                    |                                                                |
| <b>Validity:</b>     | These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page |                                                                |
| <b>Further Info:</b> | Items/values not in reference catalogue are prefixed with an asterisk *.                                                                                                     |                                                                |

### Recommended Parts

| No.                     | Qty | Part No.      | Particulars                         | Condition     | Repairer's | Amount      |
|-------------------------|-----|---------------|-------------------------------------|---------------|------------|-------------|
| 1                       | 1   |               | *FRONT BUMPER                       | Cracked       | 550.00 F   | *550.00 F   |
| 2                       | 1   |               | *FRONT BUMPER LH SIDE RETAINER      | Not Necessary | 20.00 F    | *- F        |
| 3                       | 10  |               | *FRONT BUMPER CLIPS                 | Not Necessary | 30.00 F    | *- F        |
| 4                       | 1   |               | *LH HEADLAMP                        | Cut           | 380.00 F   | *380.00 F   |
| 5                       | 1   |               | *FRONT LH CORNER PANEL              | Torn          | 230.00 F   | *230.00 F   |
| 6                       | 1   |               | *FRONT LH SIDE MIRROR               | Distorted     | 70.00 F    | *50.00 F    |
| 7                       | 1   |               | *FRONT LH SIDE MIRROR STAND         | Bent          | 150.00 F   | *150.00 F   |
| 8                       | 1   |               | *FRONT LH SIDE MIRROR ROUND         | Not Necessary | 60.00 F    | *- F        |
| 9                       | 1   | AGENT         | *FRONT LH DOOR                      | Buckled       | 1,400.00 F | *1,300.00 F |
| 10                      | 2   |               | *FRONT LH DOOR HINGE                | Repair        | 100.00 F   | *- F        |
| 11                      | 1   |               | *FRONT LH DOOR HINGE CHECKER        | Repair        | 35.00 F    | *- F        |
| 12                      | 1   |               | *FRONT WINDSCREEN                   | Cracked       | 650.00 F   | *650.00 F   |
| 13                      | 2   |               | *FRONT WINDSCREEN MOULDING          | Necessary     | 100.00 F   | *100.00 F   |
| 14                      | 1   |               | *FRONT LH STEP GARNISH              | Cut           | 125.00 F   | *125.00 F   |
| 15                      | 1   |               | *FRONT LH DOOR SIGNAL LAMP          | Not Necessary | 35.00 F    | *- F        |
| 16                      | 1   |               | *FRONT LH SIDE MIRROR STAND COVER   | Not Necessary | 75.00 F    | *- F        |
| 17                      | 1   |               | *FRONT LH SIDE MIRROR STAND TOP CAP | Missing       | 20.00 F    | *20.00 F    |
| 18                      | 1   |               | *FRONT LH FENDER SHIELD             | Not Necessary | 95.00 F    | *- F        |
| 19                      | 1   |               | *SEALANT                            | Not Necessary | 25.00 F    | *- F        |
| 20                      | 1   |               | *DOOR STICKER                       | Not Necessary | 10.00 F    | *- F        |
| <b>Supplementary #1</b> |     |               |                                     |               |            |             |
| 21                      | 1   | N61877-MA01B  | *SLIT COVER                         | Deformed      | 20.00 F    | *20.00 F    |
| 22                      | 1   | N61877-MA160  | *SIDE GARNISH                       | Deformed      | 75.00 F    | *75.00 F    |
| 23                      | 1   | N96303-MA000Y | *MIRROR                             | Cut           | 20.00 F    | *20.00 F    |
| 24                      | 1   |               | *F/DR INNER LOCK LH                 | Bent          | 90.00 F    | *90.00 F    |
| 25                      | 1   |               | *AC FAN ASSY                        | Cracked       | 560.00 F   | *560.00 F   |
| 26                      | 1   | N261609Y000   | *FENDER SIGNAL LAMP                 | Cut           | 35.00 F    | *35.00 F    |

F=Franchise part.

**Total Parts (\$\$)**    **4,960.00**    **4,355.00**

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

| No                       | Particulars                          | Lab.Type | Repairer's | Amount   |
|--------------------------|--------------------------------------|----------|------------|----------|
| <b>Labour Items</b>      |                                      |          |            |          |
| 1                        | LABOUR CHARGE                        | New      | 900.00     | 720.00   |
| 2                        | SPRAY PAINTING                       | New      | 780.00     | 720.00   |
| 3                        | TO REMOVE AND RENEW FRONT WINDSCREEN | New      | 120.00     | 120.00   |
| 4                        | WIRING CHECK                         | New      | 35.00      | 30.00    |
| 5                        | REMOVE AND REFIX FRONT DASHOARD      | New      | 350.00     | -        |
| Gross Labour Cost (\$\$) |                                      |          | 2,185.00   | 1,590.00 |

Report was unsubmitted during this print-out.

< END OF ESTIMATES >