

ASS. REC. BY:

REF: C83 / ALH 18004842 / Gbez

Special Instruction:

Surveyor:

Gib

ASSIGNMENT (Office)

From (Person):

Chin Lee Ying

of

ALH

Date/Time: 14/03/2018 8:57am

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SLJ 3109G

Insured:

SLR 2966M

at Workshop m/s

Soon Seng

Tel:

of

160 Sin Ming Drive #04-05

Policy No:

0999994795

Claim No:

9409821948SG

Sum Insured:

Excess:

Make of Veh:

D.O.A.

09032018

(Client's Record)

CA / REV / REP. / REV 24 HRS WP

H.O.D. Endorsement:

Date/Time:

14/03/2018 12pm

Person Contacted:

Amos

Vehicle IN / OUT

Date/Time

Action/Instruction (X) Estimate

SLJ 3109G - X

SLR 2966M - X

Dicmanth: 15/3/2018

DAR

PPS
Khal

REF:

ASSIGNMENT

From: Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Bal. or Market Value:

IDAC Accident Rpt.: Consistent? : Yes or No

GIA / PR Seen: Consistent? : Yes or No

Est. Repairs: days Res.: Yes or No

Lum Sum: % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No:

Type: M/C / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Colour:

Sp. Reading

Eng/No:

C/No:

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD / A/Rim or

Tyre Size:

F:

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI / TOYO / YOKO or

Front

R/Bal.

L/Bal.

D.O.A.

Rear

R/Bal.

L/Bal.

D.O.A.

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

RECEIVED 30 MAY 2010

Date/Time, File Pass to?

☐ : Preli. Report
☐ : Final Report

Date/Time, File Return to?

1)

Report Format :

Lump Sum / I.B.I: (\$

Days Of Repair:

Resurvey No. of Trip:

Add Fee:

☐ : Site Insp (\$)
☐ : Interview (\$)
☐ : Tech. Invs (\$)
☐ : Weekend (\$)

Survey Fee:

Transportation:

S + RS, SI

Photos

Others

TOTAL

| |
|-----|
| 180 |
| 20 |
| 200 |

Catherine Chong (LKK Auto)

From: Chin, Lee-Ying <Lee-Ying.Chin@aig.com>
Sent: Wednesday, 14 March, 2018 8:57 AM
To: 'assignments'; Admin A
Cc: Fong, Andy-SY
Subject: FW: PRE-REPAIR INSPECTION - ACCIDENT INVOLVING OUR INSURED VEHICLE SLR2966M AND SLJ3109G ON 9/3/2018
Attachments: RE: PRE-REPAIR INSPECTION - ACCIDENT INVOLVING OUR INSURED VEHICLE SLR65... (58.8 KB)

Hi LKK,

Kindly contact Amos to arrange for survey.

Thanks.

Best Regards

Lee Ying, Chin

AIG

Claims | AIG Asia Pacific Insurance Pte. Ltd.

78 Shenton Way #08-16 Singapore 079120

Tel +(65) 6419 1947 | Fax +(65) 6835 7416

Lee-Ying.Chin@aig.com | www.aig.com.sg

From: Ruby Ong [mailto:ruby@htapartners.com.sg]
Sent: Tuesday, March 13, 2018 3:14 PM
To: Abu Kassim, Noor Mariesa
Cc: Tan, Lily (AIG); Fong, Andy-SY; Kaur, Baljit; Lim, Sheng Yang; Md Ishak, Mohd Imran; Chan, Yoke Shi; Supramaniam, Darshene; Chin, Lee-Ying
Subject: RE: PRE-REPAIR INSPECTION - ACCIDENT INVOLVING OUR INSURED VEHICLE SLR2966M AND SLJ3109G ON 9/3/2018

WITHOUT PREJUDICE

Dear Sir / Madam

We replied yesterday, however, there was a typo error in the subject heading. Our apologies.

Best regards,

Ruby Ong

Secretary

M/s Hin Tat Augustine & Partners

20 Upper Circular Road

#02-10/12 The Riverwalk

Singapore 058416

Tel : 6533 0212 ext 257

Fax : 6533 0313 / 6338 3536

www.htapartners.com.sg

Privileged/Confidential information is contained in this message. If you are not the addressee indicated in this message (or responsible for delivery of the message to such person), you may not copy or deliver this message to anyone. In such case, you should destroy this message and kindly notify the sender by reply email.

From: Abu Kassim, Noor Mariesa <NoorMariesa.AbuKassim@aig.com>

Sent: Tuesday, March 13, 2018 2:58 PM

To: Ruby Ong <ruby@htapartners.com.sg>

Cc: Tan, Lily (AIG) <Lily.Tan@aig.com>; Fong, Andy-SY <Andy-SY.Fong@aig.com>; Kaur, Baljit <Baljit.Kaur@aig.com>; Lim, Sheng Yang <ShengYang.Lim@aig.com>; Md Ishak, Mohd Imran <Imran.Ishak@aig.com>; Chan, Yoke Shi <yokeshi.chan@aig.com>; Supramaniam, Darshene <Darshene.Supramaniam@aig.com>; Chin, Lee-Ying <Lee-Ying.Chin@aig.com>

Subject: RE: PRE-REPAIR INSPECTION - ACCIDENT INVOLVING OUR INSURED VEHICLE SLR2966M AND SLJ3109G ON 9/3/2018

Dear Sir/Madam,

Reminder for pre-repair survey.

Kindly respond to the email below whether you agree to the appointment of any of these motor surveyors below as a single joint expert.

Thank you.

Regards,

Mariesa Abu Kassim (Mariesa)

AIG

Claim Adjuster II, Singapore FNOL, Claims Operations – Auto

Shared Services – Malaysia | Global Business Services

AIG Shared Services (M) Sdn Bhd (887191-D)

Menara Worldwide, Level 12, 198 Jalan Bukit Bintang, 55100 Kuala Lumpur, Malaysia

Tel +6 03 2719 6000 | Ext 1012202 | Fax +6 03 2685 5898

NoorMariesa.AbuKassim@aig.com | www.aig.com

From: Abu Kassim, Noor Mariesa

Sent: Monday, March 12, 2018 12:45 PM

To: 'Ruby Ong'

Cc: Tan, Lily (AIG); Fong, Andy-SY; Kaur, Baljit; Lim, Sheng Yang; Md Ishak, Mohd Imran; Chan, Yoke Shi; Supramaniam, Darshene; Chin, Lee-Ying

Subject: PRE-REPAIR INSPECTION - ACCIDENT INVOLVING OUR INSURED VEHICLE SLR2966M AND SLJ3109G ON 9/3/2018

Your Reference : TCL.MH.RO.50078.18.EDE

Our Reference : SLR2966M

Dear Ruby,

We refer to your Notice of Accident of even date.

We intend to conduct a pre-repair survey of the damage to your client's/your customer's vehicle jointly with your client/your motor workshop. We propose to use one of the motor surveyors named in the attached list to conduct the joint pre-repair survey as a single joint expert:

| Name of Surveyor | Company Name |
|----------------------|------------------------------------|
| Lim Kok Chong | AIG Asia Pacific Insurance Pte Ltd |
| Kumar Uthaya | AIG Asia Pacific Insurance Pte Ltd |
| Ken Wong | AIG Asia Pacific Insurance Pte Ltd |
| Lawrence Ng Chun Kee | Priority Services |

| | |
|--------------------------|--|
| Jeffrey Ong Leng Kiat | Priority Services |
| Jimmy Lee | Priority Services |
| EC Looi | Automobile Inspection Services Pte Ltd |
| Ricky Teng | RT Appraisal Pte Ltd |
| Elson Teng | RT Appraisal Pte Ltd |
| Michael Cheong | RT Appraisal Pte Ltd |
| Pang Kiah Keen (Frankie) | Formteam Adjusters Pte Ltd |
| Ng You Han | Formteam Adjusters Pte Ltd |
| Soon HanXin (Gary) | Formteam Adjusters Pte Ltd |
| Chow Bo Xiong | Formteam Adjusters Pte Ltd |
| Chua Soo Teck (Benjamin) | Formteam Adjusters Pte Ltd |
| Kalvin Ang | LKK Auto Consultants Pte Ltd |
| Xing Guo Qiang | LKK Auto Consultants Pte Ltd |
| Marcus Chua | LKK Auto Consultants Pte Ltd |
| Mohamad Taufikh | LKK Auto Consultants Pte Ltd |
| Adrian Ling | LKK Auto Consultants Pte Ltd |
| Henry Ng | LKK Auto Consultants Pte Ltd |
| Mohammed Rasul | LKK Auto Consultants Pte Ltd |
| Steven Foong | LKK Auto Consultants Pte Ltd |
| Wei Jie | LKK Auto Consultants Pte Ltd |
| Ma Chin Fook | LKK Auto Consultants Pte Ltd |
| Kenneth Kong | LKK Auto Consultants Pte Ltd |

Please let us know within two (2) working days whether you agree to the appointment of any of these motor surveyors as a single joint expert. You may select one or more of the listed motor surveyors. We will bear the cost of the pre-repair survey carried out by the single joint expert.

Thank you.

Best Regards,

Mariesa Abu Kassim (Mariesa)

AIG

Claim Adjuster II, Singapore FNOL, Claims Operations – Auto

Shared Services – Malaysia | Global Business Services

AIG Shared Services (M) Sdn Bhd (887191-D)

Menara Worldwide, Level 12, 198 Jalan Bukit Bintang, 55100 Kuala Lumpur, Malaysia

Tel +6 03 2719 6000 | Ext 1012202 | Fax +6 03 2685 5898

NoorMariesa.AbuKassim@aig.com | www.aig.com

From: Ruby Ong [<mailto:ruby@htapartners.com.sg>]

Sent: Monday, March 12, 2018 12:09 PM

To: Abu Kassim, Noor Mariesa; Chan, Yoke Shi; Lim, Sheng Yang

Subject: REQUEST FOR PRE-SURVEY PROTOCOL FOR SLJ3109G [OUR REF. TCL.MH.RO.50078.18.EDE]

Importance: High

Your ref: SLR 2966M

Our ref : TCL.MH.ro.50078.18.ede

WITHOUT PREJUDICE

12 March 2018

AIG Asia Pacific Insurance Pte Ltd

Motor Claims Department
8 Shenton Way
#08-16 AIG Building
Singapore 068811

By Email Only

VERY URGENT

Dear Sir,

CLAIMANT: AMV PTE LTD

ACCIDENT INVOLVING SLJ 3109G, SLR 2966M & SKH 844J ALONG ECP TOWARDS CITY ON 9 MARCH 2018 @ 0740HRS

We are instructed by AMV Pte Ltd to notify you of a road traffic accident on 9 March 2018 at about 0740 hrs along ECP towards City involving our client's vehicle registration number SLJ 3109G and vehicle registration number SLR 2966M driven by your insured's driver at the material time.

As a result of the accident, our client's vehicle has been damaged. Before our client proceed to repair the damaged vehicle, please let us know within 2 working days of your receipt of this notice whether you or your insurers would like to conduct a pre-repair survey of the vehicle. If we do not receive any reply from you within the stipulated timeline, our client shall proceed to repair the vehicle without reference to you.

Best regards,

Ruby Ong

Secretary

M/s Hin Tat Augustine & Partners

20 Upper Circular Road

#02-10/12 The Riverwalk

Singapore 058416

Tel : 6533 0212 ext 257

Fax : 6533 0313 / 6338 3536

www.htapartners.com.sg

Privileged/Confidential information is contained in this message. If you are not the addressee indicated in this message (or responsible for delivery of the message to such person), you may not copy or deliver this message to anyone. In such case, you should destroy this message and kindly notify the sender by reply email.

IMPORTANT NOTICE:

The information in this email (and any attachments) is confidential. If you are not the intended recipient, you must not use or disseminate the information. If you have received this email in error, please immediately notify me by "Reply" command and permanently delete the original and any copies or printouts thereof. Although this email and any attachments are believed to be free of any virus or other defect that might affect any computer system into which it is received and opened, it is the responsibility of the recipient to ensure that it is virus free and no responsibility is accepted by American International Group, Inc. or its subsidiaries or affiliates either jointly or severally, for any loss or damage arising in any way from its use.

IMPORTANT NOTICE:

The information in this email (and any attachments) is confidential. If you are not the intended recipient, you must not use or disseminate the information. If you have received this email in error, please immediately notify me by "Reply" command and permanently delete the original and any copies or printouts thereof. Although this email and any attachments are believed to be free of any virus or other defect that might affect any computer system into which it is received and opened, it is the responsibility of the recipient to ensure that it is virus free and no responsibility is accepted by American International Group, Inc. or its subsidiaries or affiliates either jointly or severally, for any loss or damage arising in any way from its use.

Catherine Chong (LKK Auto)

From: Ruby Ong <ruby@htapartners.com.sg>
Sent: Monday, 12 March, 2018 3:43 PM
To: 'Abu Kassim, Noor Mariesa'
Cc: 'Tan, Lily (AIG)'; 'Fong, Andy-SY'; 'Kaur, Baljit'; 'Lim, Sheng Yang'; 'Md Ishak, Mohd Imran'; 'Chan, Yoke Shi'; 'Supramaniam, Darshene'; 'Chin, Lee-Ying'; 'EVERDRIVE ENTERPRISE'
Subject: RE: PRE-REPAIR INSPECTION - ACCIDENT INVOLVING OUR INSURED VEHICLE SLR6570U AND PA8018C ON 11/03/2018
Importance: High

WITHOUT PREJUDICE

Dear Sirs

We refer to your email of even date.

TAKE NOTICE that we object to all your surveyors stated in your said List, for appointment as the Single Joint Expert. Pursuant to Pre-Action Protocol for NIMA cases, we now propose **Mr Louis Ng of Prestige Appraiser Services** for appointment as Single Joint Expert.

Please make the necessary arrangements with Mr Amos (HP : 9643 1861) / Mr Alan (HP : 9144 5117).

In the event that the pre-repair survey was not conducted during the prescribed time or already conducted at your end previously, we reserve our client's right to claim for compensation for loss of use for your current request for re-survey.

Best regards,
Ruby Ong
Secretary
M/s Hin Tat Augustine & Partners
20 Upper Circular Road
#02-10/12 The Riverwalk
Singapore 058416
Tel : 6533 0212 ext 257
Fax : 6533 0313 / 6338 3536
www.htapartners.com.sg

Privileged/Confidential information is contained in this message. If you are not the addressee indicated in this message (or responsible for delivery of the message to such person), you may not copy or deliver this message to anyone. In such case, you should destroy this message and kindly notify the sender by reply email.

From: Abu Kassim, Noor Mariesa <NoorMariesa.AbuKassim@aig.com>
Sent: Monday, March 12, 2018 3:10 PM
To: Ruby Ong <ruby@htapartners.com.sg>
Cc: Tan, Lily (AIG) <Lily.Tan@aig.com>; Fong, Andy-SY <Andy-SY.Fong@aig.com>; Kaur, Baljit <Baljit.Kaur@aig.com>; Lim, Sheng Yang <ShengYang.Lim@aig.com>; Md Ishak, Mohd Imran <Imran.Ishak@aig.com>; Chan, Yoke Shi <yokeshi.chan@aig.com>; Supramaniam, Darshene <Darshene.Supramaniam@aig.com>; Chin, Lee-Ying <Lee-Ying.Chin@aig.com>
Subject: PRE-REPAIR INSPECTION - ACCIDENT INVOLVING OUR INSURED VEHICLE SLR6570U AND PA8018C ON 11/03/2018

Your Reference : TCL.MH.ro.50079.18.jdm
Our Reference : SLR6570U

Dear Sir/Madam,

We refer to your Notice of Accident of even date.

We intend to conduct a pre-repair survey of the damage to your client's/your customer's vehicle jointly with your client/your motor workshop. We propose to use one of the motor surveyors named in the attached list to conduct the joint pre-repair survey as a single joint expert:

| Name of Surveyor | Company Name |
|--------------------------|--|
| Lim Kok Chong | AIG Asia Pacific Insurance Pte Ltd |
| Kumar Uthaya | AIG Asia Pacific Insurance Pte Ltd |
| Ken Wong | AIG Asia Pacific Insurance Pte Ltd |
| Lawrence Ng Chun Kee | Priority Services |
| Jeffrey Ong Leng Kiat | Priority Services |
| Jimmy Lee | Priority Services |
| EC Looi | Automobile Inspection Services Pte Ltd |
| Ricky Teng | RT Appraisal Pte Ltd |
| Elson Teng | RT Appraisal Pte Ltd |
| Michael Cheong | RT Appraisal Pte Ltd |
| Pang Kiah Keen (Frankie) | Formteam Adjusters Pte Ltd |
| Ng You Han | Formteam Adjusters Pte Ltd |
| Soon HanXin (Gary) | Formteam Adjusters Pte Ltd |
| Chow Bo Xiong | Formteam Adjusters Pte Ltd |
| Chua Soo Teck (Benjamin) | Formteam Adjusters Pte Ltd |
| Kalvin Ang | LKK Auto Consultants Pte Ltd |
| Xing Guo Qiang | LKK Auto Consultants Pte Ltd |
| Marcus Chua | LKK Auto Consultants Pte Ltd |
| Mohamad Taufikh | LKK Auto Consultants Pte Ltd |
| Adrian Ling | LKK Auto Consultants Pte Ltd |
| Henry Ng | LKK Auto Consultants Pte Ltd |
| Mohammed Rasul | LKK Auto Consultants Pte Ltd |
| Steven Foong | LKK Auto Consultants Pte Ltd |
| Wei Jie | LKK Auto Consultants Pte Ltd |
| Ma Chin Fook | LKK Auto Consultants Pte Ltd |
| Kenneth Kong | LKK Auto Consultants Pte Ltd |

Please let us know within two (2) working days whether you agree to the appointment of any of these motor surveyors as a single joint expert. You may select one or more of the listed motor surveyors. We will bear the cost of the pre-repair survey carried out by the single joint expert.

Thank you.

Best Regards,

Mariesa Abu Kassim (Mariesa)

AIG

Claim Adjuster II, Singapore FNOL, Claims Operations – Auto
Shared Services – Malaysia | Global Business Services

AIG Shared Services (M) Sdn Bhd (887191-D)
Menara Worldwide, Level 12, 198 Jalan Bukit Bintang, 55100 Kuala Lumpur, Malaysia
Tel +6 03 2719 6000 | Ext 1012202 | Fax +6 03 2685 5898

NoorMariesa.AbuKassim@aig.com | www.aig.com

From: Ruby Ong [<mailto:ruby@htapartners.com.sg>]

Sent: Monday, March 12, 2018 2:46 PM

To: Abu Kassim, Noor Mariesa; Chan, Yoke Shi; Lim, Sheng Yang

Cc: anil@htapartners.com.sg

Subject: REQUEST FOR PRE-REPAIR PROTOCOL FOR PA8018C [OUR REF. TCL.GCN.AN.50079.18.JDM]

Importance: High

Your ref: SLR 6570U

WITHOUT PREJUDICE

Our ref: TCL.MH.ro.50079.18.jdm

12 March 2018

AIG Asia Pacific Insurance Pte Ltd

By Email Only

Motor Claims Department

8 Shenton Way

#08-16 AIG Building

Singapore 068811

VERY URGENT

Dear Sir,

CLAIMANT: SOH KHENG CHUAN

ACCIDENT INVOLVING PA 8018C & SLR 6570U ALONG BRADDELL ROAD TOWARDS CTE ON 11 MARCH 2018 @ 1445HRS

We are instructed by Soh Kheng Chuan to notify you of a road traffic accident on 11 March 2018 at about 1445 hrs along Braddell Road towards CTE involving our client's vehicle registration number PA 8018C and vehicle registration number SLR 6570U driven by your insured's driver at the material time.

As a result of the accident, our client's vehicle has been damaged. Before our client proceed to repair the damaged vehicle, please let us know within 2 working days of your receipt of this notice whether you or your insurers would like to conduct a pre-repair survey of the vehicle. If we do not receive any reply from you within the stipulated timeline, our client shall proceed to repair the vehicle without reference to you.

Best regards,

Ruby Ong

Secretary

M/s Hin Tat Augustine & Partners

20 Upper Circular Road

#02-10/12 The Riverwalk

Singapore 058416

Tel : 6533 0212 ext 257

Fax : 6533 0313 / 6338 3536

www.htapartners.com.sg

Privileged/Confidential information is contained in this message. If you are not the addressee indicated in this message (or responsible for delivery of the message to such person), you may not copy or deliver this message to anyone. In such case, you should destroy this message and kindly notify the sender by reply email.

IMPORTANT NOTICE:

The information in this email (and any attachments) is confidential. If you are not the intended recipient, you must not use or disseminate the information. If you have received this email in error, please immediately notify me by "Reply" command and permanently delete the original and any copies or printouts thereof. Although this email and any attachments are believed to be free of any virus or other defect that might affect any computer system into which it is received and opened, it is the responsibility of the recipient to ensure that it is virus free and no responsibility is accepted by American International Group, Inc. or its subsidiaries or affiliates either jointly or severally, for any loss or damage arising in any way from its use.

> Back to OneMotoring

Enquire Transfer Fee

Vehicle Details

| | |
|---------------------------------|--|
| Vehicle No.: | SLJ3109G |
| Vehicle Type: | Z11 - Private Hire (Chauffeur) Station Wagon/Jeep/Land Rover |
| Vehicle Attachment 1: | No Attachment |
| Vehicle Scheme: | Normal |
| Vehicle Make: | HONDA |
| Vehicle Model: | VEZEL 1.5X CVT |
| Chassis No.: | RU11114612 |
| Propellant: | Petrol |
| Engine No.: | L15B4034614 |
| Engine Capacity: | 1496 cc |
| Maximum Power Output: | 96.0 kW (128 bhp) |
| Maximum Laden Weight: | 1465 kg |
| Unladen Weight: | 1190 kg |
| Year Of Manufacture: | 2016 |
| Original Registration Date: | 05 Dec 2016 |
| Lifespan Expiry Date: | - |
| COE Category: | A - Car up to 1600cc & 97kW (130bhp) |
| Quota Premium: | \$50,951.00 |
| COE Expiry Date: | 04 Dec 2026 |
| Road Tax Expiry Date: | 04 Dec 2018 |
| PARF Eligibility Expiry Date: | 04 Dec 2026 |
| Inspection Due Date: | 04 Dec 2019 |
| Intended Transfer Date: | 25 May 2018 |
| CO2 Emission: | 117.00 (g/km) |
| CEV/VES Rebate Utilised Amount: | \$10,000.00 |
| CO Emission: | - |
| HC Emission: | - |
| NOx Emission: | - |
| PM Emission: | - |

Late renewal fee(s) will be imposed if road tax / lay up has expired. Please use Enquire Road Tax Payable for fee(s) payable.

Road tax, including Over Payment (if any), of a vehicle will follow the vehicle to the new registered owner when its ownership is being transferred.

Amount Payable

| | Amount Before GST (S\$) | GST Amount (S\$) | Amount After GST (S\$) |
|---------------|----------------------------|---------------------|---------------------------|
| Transfer Fee: | 25.00 | - | 25.00 |

Total Amount Payable:

25.00

You may print this page for reference.

OK

Print

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

| | |
|-------------------------------------|--------------------------------------|
| Vehicle Owner Particulars | |
| Owner ID Type: | Company |
| Owner ID: | 5825Z |
| Vehicle Details | |
| Vehicle No.: | SLJ3109G |
| Vehicle to be Exported: | No |
| Intended De-registration Date: | 25 May 2018 |
| Vehicle Make: | HONDA |
| Vehicle Model: | VEZEL 1.5X CVT |
| Primary Colour: | White |
| Manufacturing Year: | 2016 |
| Engine No.: | L15B4034614 |
| Chassis No.: | RU11114612 |
| Maximum Power Output: | 96.0 kW (128 bhp) |
| Open Market Value: | \$22,027.00 |
| Original Registration Date: | 05 Dec 2016 |
| First Registration Date: | 05 Dec 2016 |
| Transfer Count: | 0 |
| Actual ARF Paid: | \$12,838.00 |
| Intended PARF Rebate Details | |
| PARF Eligibility: | Yes |
| PARF Eligibility Expiry Date: | 04 Dec 2026 |
| PARF Rebate Amount: | \$9,628.00 |
| Intended COE Rebate Details | |
| COE Expiry Date: | 04 Dec 2026 |
| COE Category: | A - Car up to 1600cc & 97kW (130bhp) |
| COE Period(Years): | 10 |
| QP Paid: | \$50,951.00 |
| COE Rebate Amount: | \$43,433.00 |
| Total Rebate Amount: | \$53,061.00 |

The information contained herein is correct as at 25 May 2018

OK

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report 09/03/2018 12:26
 Date Of Accident 09/03/2018 07:40
 Exact Location Of Accident ECP TOWARDS CITY
 Country/State of Loss SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number SLJ3109G
Insured/Policyholder
 Name Of Registered Owner AMV PTE. LTD.
 Co Reg No 201505825Z
 Email Address NOEMAIL
 Mobile Phone No
 Alternative Phone No OFFICE-91545505

Vehicle Particulars

Manufacturer HONDA
 Model VEZEL 1.5X CVT
 Exact Purpose for which vehicle was being used at time of accident
 Are you claiming under your own insurance policy for repair to your vehicle? NO
 If No, Please state action to be taken THIRD PARTY
 Vehicle Category PRIVATE HIRE

Insurance Company

Name of Insurance Company NTUC INCOME INSURANCE CO-OPERATIVE LTD
 Type Of Coverage COMPREHENSIVE
 Fleet Policy NO
 Policy Number 5086660036-01 CLASSIC
 Cover Note Number

Driver

Name of Driver RANDEEP SINGH KALRA S/O CHARANPAL SINGH
 NRIC No S8070121G
 Date Of Birth 28/02/1980
 Occupation OUTDOOR
 Date Of Driving Pass 17/01/2007
 Driving Experience 11 YEARS AND 1 MONTH
 Gender MALE
 Mobile Number (LOCAL) +65-91545505
 Fax Number
 Contact Number
 Email Address NOEMAIL

Address BLK 11 JALAN BATU #04-136
 Postcode 431011
 Was driver an employee of the Insured's Company YES
 If No, Relationship of the Driver with the Insured
 Vehicle Registration Number of Driver's Own Vehicle -
 Vehicle -
 Insurance Company of Driver's Own Vehicle -
 -

General Information of the Accident

Type Of Accident CHAIN COLLISION
 Weather Conditions CLEAR
 Road Surface DRY

Other Information

Was any foreign vehicle involved in this accident? NO
 Number of vehicles involved in the accident 3
 Was any body injured in the Accident? NO
 Was any injured conveyed to hospital by ambulance? NO
 Was any other material or property damaged? YES
 I have been approached by unknown person(s) soliciting/offering accident claims assistance. NO
 Number of Passengers (Including Driver) 2
 Passenger 1 NAME: : UNKNOWN
 GENDER: : MALE

Details of Police Action

Was the accident reported to the police? NO
 If Yes, Please state which Police Station
 Was notice of intended Prosecution given? NO
 If Yes, against whom?

Circumstances of Accident

REFER TO SKETCH PLAN ATTACHED

Attachment(s)

Are accident photos available for attachment? YES
 Was there any video captured by Car Camera? YES
 Remarks/ Reasons: WITH DRIVER
 Was there any audio recorded? NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number SLR2966M
 Vehicle Make/Model/Colour MITSUBISHI LANCER EX 1.6 AT
 Details Of Properties
 Vehicle Category PRIVATE CAR
 Name of Driver SAUFI BIN MUSTAFAH
 NRIC/Passport Number S9209484G
 Contact Number 92471453
 Address
 Postcode
 Insurance Company Name
 Nature Of Damage

No. Of Passenger (Including Driver)

DETAILS OF OTHER VEHICLE PROPERTY 2

| | |
|-------------------------------------|------------------|
| Vehicle Registration Number | SKH844J |
| Vehicle Make/Model/Colour | BMW 520I 2.0L AT |
| Details Of Properties | |
| Vehicle Category | PRIVATE CAR |
| Name of Driver | KHOO KEAN TIONG |
| NRIC/Passport Number | S7140810H |
| Contact Number | 97438328 |
| Address | |
| Postcode | |
| Insurance Company Name | |
| Nature Of Damage | |
| No. Of Passenger (Including Driver) | |

Sketch Plan

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this form and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all Insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.



Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time: 9 MAR 2018



IDAC KAKI BUKIT (VAC)
23 Kaki Bukit Ave 4
Singapore 415933
Tel: 67416697 Fax: 67492305
Email: vackb@singnet.com.sg

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

SKETCH PLAN

Vehicle No
A - JS 3109 G
B - SR 2966 M
C - SKH 8445

ECP Towards City

Legend
 Vehicle
 Bike

DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

On 7/3/2018, I was driving along ECP towards city at around 0740hrs on overtaking lane. Car in front of me braked and I had to brake hard to avoid collision. Suddenly I felt my car jerk and rolled forward due to a from the car behind me.

DECLARATION

I/We declare the foregoing particulars are true in every respect. Please be advised that your insurer may have a 14 day clause whereby the claim against own vehicle must be made within the stipulated timeframe from the date of occurrence. Kindly check your policy for more details.



Policy No. _____
Date & Time: _____

SPF/PC Sketch Plan Form V3

Driver's Signature
(if driver is not the policyholder)
Date & Time: - 9 MAR 2018

IDAC KAKI BUKIT (VAC)

23 Kaki Bukit Ave 4
Singapore 415933
Tel: 67416697 Fax: 67492305
Email: vackb@singnet.com.sg

Name: _____
NRIC/FIN No.: _____

1/eh SLJ 3109G

DoI 14/3/18

- | | |
|-------------------------------------|-----|
| 1. Rear tailgate | di |
| 2. Rear bumper | di |
| 3. Rear bumper chip set | rec |
| 4. Rear tailgate weather strip | dm |
| 5. Rear tailgate logo emblem | nec |
| 6. Rear tailgate VEZEL emblem | nec |
| 7. Rear tail lamps x 2 | cr |
| 8. Reverse sensor x 1 - | dm |
| 9. Tailgate windscreen sealant - | nec |
| 10. Rear panel garnish - | dm |
| 11. Rear tailgate inner trimboard - | dm |
| 12. Rear bumper retainer x 2 - | dm |
| 13. Spare tyre panel tools tray - | dm |

Painting 2 panels

Labour 3 days

him 23/5/18

...CLAIM SUBFOLDER...(Pending for Survey Report)

PRI

CLAIM SUBFOLDER TRACKING



















































| Case | Notified | Est Submitted | Adj Assigned | Adj Rpt | Adj Submitted | Ins Auth'd | Status |
|------|---|---------------|--|--|--|------------|---|
| Main | 04 Apr 2018 Edit Reg | | 14 Mar 2018 00:00 Edit Adj Rpt | S\$0.00 Edit Estimates | S\$0.00 View Rpt | | Pending for Survey Report Cancel Case |



















































| Main | Reference | Claim Details | Documents | Show All | | | | | |
|---|---|------------------------|---|----------|---------|-------------|--------------|------------|-------|
| CLAIM SUBFOLDER DETAILS [Created by adjuster] | | | | | | | | | |
| Insured: | LCRF PTE LTD, Co. Reg. No.: - | | | | | | | | |
| Main Claimant: | AMV Pte Ltd | | | | | | | | |
| Vehicle Reg. No.: | SLJ3109G | Date of Loss: | 09/03/2018 07:00 - :59 [15 Months and 4 Days From LTA Reg Date (Man Yr)] | | | | | | |
| Claim Type: | TP / 9409821948SG | Policy/Cover Note No.: | 0999994795 (Comprehensive) | | | | | | |
| Vehicle Reg. No. (Insured): | SLR2966M | Policy No. (Claimant): | | | | | | | |
| | | Excess: | | | | | | | |
| Repairer: | Soon Seng Company (HQ) Blk 18 Sin Ming Industrial Estate Sector A, #01-33, 575676 Sin Ming - Tel: | | | | | | | | |
| Handling Insurer: | AIG Asia Pacific Insurance Pte. Ltd. (Express) - Tel: 65-6419-3000 ... [Handled by Tan, Wilson-KL] | | | | | | | | |
| Adjuster: | LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by XING GUO QIANG] ... [Final Rpt due 13/04/2018] | | | | | | | | |
| Claimant's Solicitor: | HIN TAT AUGUSTINE & PARTNERS - Tel: 65330212 | | | | | | | | |
| ASSOCIATED MAIL RECEIVED View All Compose Case Mail | | | | | | | | | |
| <ul style="list-style-type: none"> AIG_SG (06/04/2018): TP GIA REPORT | | | | | | | | | |
| ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete | | | | | | | | | |
| Due Date | Priority | Type | Task Group | Subject | Handler | Assigned By | Completed On | Created On | Done? |
| No results. | | | | | | | | | |

Claim Documents

*SLJ3109G (9409821948SG)
 [SLR2966M]
 TP
 AMV Pte Ltd
 Mar 9 2018 7:00AM
 [LCRF PTE LTD]
 Soon Seng Company

| | | | | | | | |
|----------------------------------|-----------------|---|------------------------------------|------------------------------|------------------------------|---|--|
| Upload Documents | | Upload Photos | Compose New Letter | Upload Video | Upload Audio | View View in Browser <input type="button" value="v"/> | |
| Assessment Reports | | | | | | 1 per page <input type="button" value="v"/> <input checked="" type="checkbox"/> | |
| No | Finalized On | AIG Asia Pacific Insurance Pte. Ltd. (SG) | | | Thumbnail | Print | |
| 1 | 06/04/18 15:46 | Accident Statement From: SC - Reg. No: SLR2966M, Claimant: LCRF PTE LTD | | | Load HTM | <input type="checkbox"/> | |
| Photos/Images | | | | | | 3 per page <input type="button" value="v"/> <input checked="" type="checkbox"/> | |
| No | Relabel/Reorder | LKK Auto Consultants Pte Ltd (HQ) | | | Thumbnail | Print | |
| 1 | 04/04/18 09:58 | General View | | | Load JPG | <input checked="" type="checkbox"/> | |
| 2 | 04/04/18 09:58 | General View | | | Load JPG | <input checked="" type="checkbox"/> | |
| 3 | 04/04/18 09:58 | General View | | | Load JPG | <input checked="" type="checkbox"/> | |
| 4 | 04/04/18 09:58 | General View | | | Load JPG | <input checked="" type="checkbox"/> | |
| 5 | 04/04/18 09:58 | General View | | | Load JPG | <input checked="" type="checkbox"/> | |
| 6 | 04/04/18 09:58 | General View | | | Load JPG | <input checked="" type="checkbox"/> | |
| 7 | 04/04/18 09:58 | General View | | | Load JPG | <input checked="" type="checkbox"/> | |
| 8 | 04/04/18 09:58 | General View | | | Load JPG | <input checked="" type="checkbox"/> | |
| 9 | 04/04/18 09:58 | General View | | | Load JPG | <input checked="" type="checkbox"/> | |
| 10 | 04/04/18 09:58 | General View | | | Load JPG | <input checked="" type="checkbox"/> | |
| 11 | 04/04/18 09:58 | General View | | | Load JPG | <input checked="" type="checkbox"/> | |
| 12 | 04/04/18 09:58 | General View | | | Load JPG | <input checked="" type="checkbox"/> | |
| 13 | 04/04/18 09:58 | General View | | | Load JPG | <input checked="" type="checkbox"/> | |
| 14 | 04/04/18 09:58 | General View | | | Load JPG | <input checked="" type="checkbox"/> | |
| 15 | 04/04/18 09:58 | General View | | | Load JPG | <input checked="" type="checkbox"/> | |
| 16 | 04/04/18 09:58 | General View | | | Load JPG | <input checked="" type="checkbox"/> | |
| 17 | 04/04/18 09:58 | General View | | | Load JPG | <input checked="" type="checkbox"/> | |
| 18 | 04/04/18 09:58 | General View | | | Load JPG | <input checked="" type="checkbox"/> | |
| 19 | 04/04/18 09:58 | General View | | | Load JPG | <input checked="" type="checkbox"/> | |
| 20 | 04/04/18 09:58 | General View | | | Load JPG | <input checked="" type="checkbox"/> | |
| 21 | 04/04/18 09:58 | General View | | | Load JPG | <input checked="" type="checkbox"/> | |
| 22 | 04/04/18 09:58 | General View | | | Load JPG | <input checked="" type="checkbox"/> | |
| 23 | 04/04/18 09:58 | General View | | | Load JPG | <input checked="" type="checkbox"/> | |
| 24 | 04/04/18 09:58 | General View | | | Load JPG | <input checked="" type="checkbox"/> | |
| 25 | 04/04/18 09:58 | General View | | | Load JPG | <input checked="" type="checkbox"/> | |
| 26 | 04/04/18 09:58 | General View | | | Load JPG | <input checked="" type="checkbox"/> | |
| 27 | 04/04/18 09:58 | General View | | | Load JPG | <input checked="" type="checkbox"/> | |
| 28 | 04/04/18 09:58 | General View | | | Load JPG | <input checked="" type="checkbox"/> | |
| 29 | 04/04/18 09:58 | General View | | | Load JPG | <input checked="" type="checkbox"/> | |
| 30 | 04/04/18 09:58 | General View | | | Load JPG | <input checked="" type="checkbox"/> | |
| 31 | 04/04/18 09:58 | General View | | | Load JPG | <input checked="" type="checkbox"/> | |
| 32 | 04/04/18 09:58 | General View | | | Load JPG | <input checked="" type="checkbox"/> | |
| 33 | 04/04/18 09:58 | Chassis Number | | | Load JPG | <input checked="" type="checkbox"/> | |

| Assessment Reports | | | 1 per page | <input checked="" type="checkbox"/> |
|--------------------|----------------|---|--|-------------------------------------|
| No | Finalized On | AIG Asia Pacific Insurance Pte. Ltd. (SG) | Thumbnail | Print |
| 34 | 04/04/18 09:58 | Odometer Reading |  Load JPG | <input checked="" type="checkbox"/> |
| 35 | 04/04/18 09:58 | General View |  Load JPG | <input checked="" type="checkbox"/> |
| 36 | 04/04/18 09:58 | General View |  Load JPG | <input checked="" type="checkbox"/> |
| 37 | 04/04/18 09:59 | Reinspection Photo |  Load JPG | <input checked="" type="checkbox"/> |
| 38 | 04/04/18 09:59 | Reinspection Photo |  Load JPG | <input checked="" type="checkbox"/> |
| 39 | 04/04/18 09:59 | Reinspection Photo |  Load JPG | <input checked="" type="checkbox"/> |
| 40 | 04/04/18 09:59 | Reinspection Photo |  Load JPG | <input checked="" type="checkbox"/> |
| 41 | 04/04/18 09:59 | Reinspection Photo |  Load JPG | <input checked="" type="checkbox"/> |
| 42 | 04/04/18 09:59 | Reinspection Photo |  Load JPG | <input checked="" type="checkbox"/> |
| 43 | 04/04/18 09:59 | Reinspection Photo |  Load JPG | <input checked="" type="checkbox"/> |
| 44 | 04/04/18 09:59 | Reinspection Photo |  Load JPG | <input checked="" type="checkbox"/> |
| 45 | 04/04/18 09:59 | Reinspection Photo |  Load JPG | <input checked="" type="checkbox"/> |
| 46 | 04/04/18 09:59 | Reinspection Photo |  Load JPG | <input checked="" type="checkbox"/> |
| 47 | 04/04/18 09:59 | Reinspection Photo |  Load JPG | <input checked="" type="checkbox"/> |
| 48 | 04/04/18 09:59 | Reinspection Photo |  Load JPG | <input checked="" type="checkbox"/> |
| 49 | 04/04/18 09:59 | Reinspection Photo |  Load JPG | <input checked="" type="checkbox"/> |
| 50 | 04/04/18 09:59 | Reinspection Photo |  Load JPG | <input checked="" type="checkbox"/> |
| 51 | 04/04/18 09:59 | Reinspection Photo |  Load JPG | <input checked="" type="checkbox"/> |
| 52 | 04/04/18 09:59 | Reinspection Photo |  Load JPG | <input checked="" type="checkbox"/> |
| 53 | 04/04/18 09:59 | Reinspection Photo |  Load JPG | <input checked="" type="checkbox"/> |
| 54 | 04/04/18 09:59 | Reinspection Photo |  Load JPG | <input checked="" type="checkbox"/> |
| 55 | 04/04/18 09:59 | Reinspection Photo |  Load JPG | <input checked="" type="checkbox"/> |
| 56 | 04/04/18 09:59 | Reinspection Photo |  Load JPG | <input checked="" type="checkbox"/> |
| 57 | 04/04/18 09:59 | Reinspection Photo |  Load JPG | <input checked="" type="checkbox"/> |
| 58 | 04/04/18 09:59 | Reinspection Photo |  Load JPG | <input checked="" type="checkbox"/> |
| 59 | 04/04/18 09:59 | Reinspection Photo |  Load JPG | <input checked="" type="checkbox"/> |
| 60 | 04/04/18 09:59 | Reinspection Photo |  Load JPG | <input checked="" type="checkbox"/> |
| 61 | 04/04/18 09:59 | Reinspection Photo |  Load JPG | <input checked="" type="checkbox"/> |
| 62 | 04/04/18 09:59 | Reinspection Photo |  Load JPG | <input checked="" type="checkbox"/> |
| 63 | 04/04/18 09:59 | Reinspection Photo |  Load JPG | <input checked="" type="checkbox"/> |
| 64 | 04/04/18 09:59 | Reinspection Photo |  Load JPG | <input checked="" type="checkbox"/> |
| 65 | 04/04/18 09:59 | Reinspection Photo |  Load JPG | <input checked="" type="checkbox"/> |
| 66 | 04/04/18 09:59 | Reinspection Photo |  Load JPG | <input checked="" type="checkbox"/> |
| 67 | 04/04/18 09:59 | Reinspection Photo |  Load JPG | <input checked="" type="checkbox"/> |
| 68 | 04/04/18 09:59 | Reinspection Photo |  Load JPG | <input checked="" type="checkbox"/> |
| 69 | 04/04/18 09:59 | Reinspection Photo |  Load JPG | <input checked="" type="checkbox"/> |
| 70 | 04/04/18 09:59 | Reinspection Photo |  Load JPG | <input checked="" type="checkbox"/> |
| 71 | 04/04/18 09:59 | Reinspection Photo |  Load JPG | <input checked="" type="checkbox"/> |
| 72 | 04/04/18 09:59 | Reinspection Photo |  Load JPG | <input checked="" type="checkbox"/> |
| 73 | 04/04/18 09:59 | Reinspection Photo |  Load JPG | <input checked="" type="checkbox"/> |
| 74 | 04/04/18 09:59 | Reinspection Photo |  Load JPG | <input checked="" type="checkbox"/> |
| 75 | 04/04/18 09:59 | Reinspection Photo |  Load JPG | <input checked="" type="checkbox"/> |
| 76 | 04/04/18 09:59 | Reinspection Photo |  Load JPG | <input checked="" type="checkbox"/> |
| 77 | 04/04/18 09:59 | Reinspection Photo |  Load JPG | <input checked="" type="checkbox"/> |
| 78 | 04/04/18 09:59 | Reinspection Photo |  Load JPG | <input checked="" type="checkbox"/> |
| 79 | 04/04/18 09:59 | Reinspection Photo |  Load JPG | <input checked="" type="checkbox"/> |
| 80 | 04/04/18 09:59 | Reinspection Photo |  Load JPG | <input checked="" type="checkbox"/> |
| 81 | 04/04/18 09:59 | Reinspection Photo |  Load JPG | <input checked="" type="checkbox"/> |
| 82 | 04/04/18 09:59 | Reinspection Photo |  Load JPG | <input checked="" type="checkbox"/> |
| 83 | 04/04/18 09:59 | Reinspection Photo |  Load JPG | <input checked="" type="checkbox"/> |

| Assessment Reports | | | 1 per page | <input checked="" type="checkbox"/> |
|--------------------|----------------|---|--|-------------------------------------|
| No | Finalized On | AIG Asia Pacific Insurance Pte. Ltd. (SG) | Thumbnail | Print |
| 84 | 04/04/18 09:59 | Reinspection Photo |  Load JPG | <input checked="" type="checkbox"/> |
| 85 | 04/04/18 09:59 | Reinspection Photo |  Load JPG | <input checked="" type="checkbox"/> |
| 86 | 04/04/18 09:59 | Reinspection Photo |  Load JPG | <input checked="" type="checkbox"/> |
| 87 | 04/04/18 09:59 | Reinspection Photo |  Load JPG | <input checked="" type="checkbox"/> |
| 88 | 04/04/18 09:59 | Reinspection Photo |  Load JPG | <input checked="" type="checkbox"/> |
| 89 | 04/04/18 09:59 | Reinspection Photo |  Load JPG | <input checked="" type="checkbox"/> |
| 90 | 04/04/18 09:59 | Reinspection Photo |  Load JPG | <input checked="" type="checkbox"/> |
| 91 | 04/04/18 09:59 | Reinspection Photo |  Load JPG | <input checked="" type="checkbox"/> |
| 92 | 04/04/18 09:59 | Reinspection Photo |  Load JPG | <input checked="" type="checkbox"/> |
| 93 | 04/04/18 09:59 | Reinspection Photo |  Load JPG | <input checked="" type="checkbox"/> |
| 94 | 04/04/18 09:59 | Reinspection Photo |  Load JPG | <input checked="" type="checkbox"/> |
| 95 | 04/04/18 09:59 | Reinspection Photo |  Load JPG | <input checked="" type="checkbox"/> |
| 96 | 04/04/18 09:59 | Reinspection Photo |  Load JPG | <input checked="" type="checkbox"/> |
| 97 | 04/04/18 09:59 | Reinspection Photo |  Load JPG | <input checked="" type="checkbox"/> |
| 98 | 04/04/18 09:59 | Reinspection Photo |  Load JPG | <input checked="" type="checkbox"/> |
| 99 | 04/04/18 09:59 | Reinspection Photo |  Load JPG | <input checked="" type="checkbox"/> |
| 100 | 04/04/18 09:59 | Reinspection Photo |  Load JPG | <input checked="" type="checkbox"/> |
| 101 | 04/04/18 09:59 | Reinspection Photo |  Load JPG | <input checked="" type="checkbox"/> |
| 102 | 04/04/18 09:59 | Reinspection Photo |  Load JPG | <input checked="" type="checkbox"/> |
| 103 | 04/04/18 09:59 | Reinspection Photo |  Load JPG | <input checked="" type="checkbox"/> |
| 104 | 04/04/18 09:59 | Reinspection Photo |  Load JPG | <input checked="" type="checkbox"/> |
| 105 | 04/04/18 09:59 | Reinspection Photo |  Load JPG | <input checked="" type="checkbox"/> |
| 106 | 04/04/18 09:59 | Reinspection Photo |  Load JPG | <input checked="" type="checkbox"/> |
| 107 | 04/04/18 09:59 | Reinspection Photo |  Load JPG | <input checked="" type="checkbox"/> |
| 108 | 04/04/18 09:59 | Reinspection Photo |  Load JPG | <input checked="" type="checkbox"/> |
| 109 | 04/04/18 09:59 | Reinspection Photo |  Load JPG | <input checked="" type="checkbox"/> |
| 110 | 04/04/18 09:59 | Reinspection Photo |  Load JPG | <input checked="" type="checkbox"/> |
| 111 | 04/04/18 09:59 | Reinspection Photo |  Load JPG | <input checked="" type="checkbox"/> |
| 112 | 04/04/18 09:59 | Reinspection Photo |  Load JPG | <input checked="" type="checkbox"/> |
| 113 | 04/04/18 09:59 | Reinspection Photo |  Load JPG | <input checked="" type="checkbox"/> |
| 114 | 04/04/18 09:59 | Reinspection Photo |  Load JPG | <input checked="" type="checkbox"/> |
| 115 | 04/04/18 09:59 | Reinspection Photo |  Load JPG | <input checked="" type="checkbox"/> |
| 116 | 04/04/18 09:59 | Reinspection Photo |  Load JPG | <input checked="" type="checkbox"/> |
| 117 | 04/04/18 09:59 | Reinspection Photo |  Load JPG | <input checked="" type="checkbox"/> |
| 118 | 04/04/18 09:59 | Reinspection Photo |  Load JPG | <input checked="" type="checkbox"/> |
| 119 | 04/04/18 09:59 | Reinspection Photo |  Load JPG | <input checked="" type="checkbox"/> |
| 120 | 04/04/18 09:59 | Reinspection Photo |  Load JPG | <input checked="" type="checkbox"/> |
| 121 | 04/04/18 09:59 | Reinspection Photo |  Load JPG | <input checked="" type="checkbox"/> |
| 122 | 04/04/18 09:59 | Reinspection Photo |  Load JPG | <input checked="" type="checkbox"/> |
| 123 | 04/04/18 09:59 | Reinspection Photo |  Load JPG | <input checked="" type="checkbox"/> |
| 124 | 04/04/18 09:59 | Reinspection Photo |  Load JPG | <input checked="" type="checkbox"/> |
| 125 | 04/04/18 09:59 | Reinspection Photo |  Load JPG | <input checked="" type="checkbox"/> |
| 126 | 04/04/18 09:59 | Reinspection Photo |  Load JPG | <input checked="" type="checkbox"/> |
| 127 | 04/04/18 09:59 | Reinspection Photo |  Load JPG | <input checked="" type="checkbox"/> |
| 128 | 04/04/18 09:59 | Reinspection Photo |  Load JPG | <input checked="" type="checkbox"/> |
| 129 | 04/04/18 09:59 | Reinspection Photo |  Load JPG | <input checked="" type="checkbox"/> |
| 130 | 04/04/18 09:59 | Reinspection Photo |  Load JPG | <input checked="" type="checkbox"/> |
| 131 | 04/04/18 09:59 | Reinspection Photo |  Load JPG | <input checked="" type="checkbox"/> |
| 132 | 04/04/18 09:59 | Reinspection Photo |  Load JPG | <input checked="" type="checkbox"/> |
| 133 | 04/04/18 09:59 | Reinspection Photo |  Load JPG | <input checked="" type="checkbox"/> |

| Assessment Reports | | | 1 per page | <input checked="" type="checkbox"/> |
|--------------------|----------------|---|--|-------------------------------------|
| No | Finalized On | AIG Asia Pacific Insurance Pte. Ltd. (SG) | Thumbnail | Print |
| 134 | 04/04/18 09:59 | Reinspection Photo |  Load JPG | <input checked="" type="checkbox"/> |
| 135 | 04/04/18 09:59 | Reinspection Photo |  Load JPG | <input checked="" type="checkbox"/> |
| 136 | 04/04/18 09:59 | Reinspection Photo |  Load JPG | <input checked="" type="checkbox"/> |
| 137 | 04/04/18 09:59 | Reinspection Photo |  Load JPG | <input checked="" type="checkbox"/> |
| 138 | 04/04/18 09:59 | Reinspection Photo |  Load JPG | <input checked="" type="checkbox"/> |
| 139 | 04/04/18 09:59 | Reinspection Photo |  Load JPG | <input checked="" type="checkbox"/> |
| 140 | 04/04/18 09:59 | Reinspection Photo |  Load JPG | <input checked="" type="checkbox"/> |
| 141 | 04/04/18 09:59 | Reinspection Photo |  Load JPG | <input checked="" type="checkbox"/> |
| 142 | 04/04/18 09:59 | Reinspection Photo |  Load JPG | <input checked="" type="checkbox"/> |
| 143 | 04/04/18 09:59 | Reinspection Photo |  Load JPG | <input checked="" type="checkbox"/> |
| 144 | 04/04/18 09:59 | Reinspection Photo |  Load JPG | <input checked="" type="checkbox"/> |

Documents Checklist

| | | | |
|--|-------|------|-------|
| DOCUMENTS CHECKLIST | Reset | Save | Print |
| There are no document checklists configured. | | | |
| Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ) <div style="border: 1px solid black; height: 40px; margin-top: 5px;"></div> | | | |
| Show Remarks To: <input type="checkbox"/> Handling Insurer <small>Note: Remarks are private unless you show it to other parties.</small> | | | |

LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS3/AIG18004842/GBE2

Date: 31/05/2018

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 0999994795
 Claimant Vehicle No: SLJ3109G Insured Vehicle No: SLR2966M
 Date of Loss: 09/03/2018 Nature of Claim: TP Claim No: 9409821948SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SLJ3109G**
 Make & Model: HONDA VEZEL, 1.5 1.5X CVT (A) Engine No: L15B4034614
 Reg. Date: 05/12/2016 (Man. Year: 2016) Chassis No: RU11114612
 Colour: White Odometer: 77217 km
 Engine Capacity: 1496 cc
 Market Value/New Car Price: N/A
 Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 215/60 R16 Rear Tyre Size: 215/60 R16
 Front Left Side: Dunlop 6 mm Rear Left Side: Dunlop 6 mm
 Front Right Side: Dunlop 6 mm Rear Right Side: Dunlop 6 mm

The above values represent the remaining tyre treads depth

| COST OF CLAIMS | Repairer's | Adjuster's | Difference | Diff % |
|--------------------------|-------------|-------------|-------------|--------|
| Parts | 0.00 | 0.00 | 0.00 | |
| Miscellaneous Items | 0.00 | 0.00 | 0.00 | |
| Labour | 0.00 | 0.00 | 0.00 | |
| Paintwork Labour | 0.00 | 0.00 | 0.00 | |
| Towing | 0.00 | 0.00 | 0.00 | |
| Nett Amount (S\$) | 0.00 | 0.00 | 0.00 | |

INSPECTION

Date of Assignment: 14/03/2018
 Date Inspected: 14/03/2018 Inspected At: 160 SIN MING DRIVE #04-05
 Estimated Period of Repair: 3.0 days Repairer : Soon Seng Company (HQ)

Adjuster: XING GUO QIANG

Manager: CATHERINE CHONG KAI LING

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

| No. | Qty | Part No. | Particulars | Condition | Repairer's | Amount |
|-------------------|-----|----------|--------------------------------|-----------|------------|--------|
| 1 | 1 | | *REAR TAILGATE | Distorted | 0.00 F | *- F |
| 2 | 1 | | *REAR BUMPER | Distorted | 0.00 F | *- F |
| 3 | 1 | | *SET REAR BUMPER CLIP | Necessary | 0.00 F | *- F |
| 4 | 1 | | *REAR TAILGATE WEATHER STRIP | Damaged | 0.00 F | *- F |
| 5 | 1 | | *REAR TAILGATE LOGO EMBLEM | Necessary | 0.00 F | *- F |
| 6 | 1 | | *REAR TAILGATE VEZEL EMBLEM | Necessary | 0.00 F | *- F |
| 7 | 2 | | *REAR TAILLAMPS | Cracked | 0.00 F | *- F |
| 8 | 1 | | *REVERSE SENSOR | Damaged | 0.00 F | *- F |
| 9 | 1 | | *TAILGATE WINDSCREEN SEALANT | Necessary | 0.00 F | *- F |
| 10 | 1 | | *REAR PANEL GARNISH | Damaged | 0.00 F | *- F |
| 11 | 1 | | *REAR TAILGATE INNER TRIMBOARD | Damaged | 0.00 F | *- F |
| 12 | 2 | | *REAR BUMPER RETAINER | Damaged | 0.00 F | *- F |
| 13 | 1 | | *SPARE TYRE PANEL TOOLS TRAYS | Damaged | 0.00 F | *- F |
| Total Parts (S\$) | | | | | 0.00 | 0.00 |

F=Franchise part.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.

< END OF ESTIMATES >