

ASS. REC. BY:

REF:

CS3/CTI18004844/R103/2

Special Instruction:

range 2 days

Surveyor:

Rasul

ASSIGNMENT (Office)

From (Person):

Irene Tay

of

CTI

Date/Time:

13/3/18 @ 4.28pm

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SKB 8577J

Insured:

SLL 7758X

at Workshop m/s

Pro Plus Automobile

Tel:

G2640138

of

221 Bulohier Rd #10-01

Policy No:

DMHCSN1719391700

Claim No:

8NM18D0129402

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A. 8/3/18

Insp: Rayspeed @ 15/3/18 @ after 10am

CA / REV / REP. / REV 24 HRS

w/p

H.O.D. Endorsement:

Date/Time:

10.22am @ 14/3/18

Person Contacted:

May Pheng

Vehicle IN/OUT

Date/Time	Action/Instruction (X) Estimate
	SKB 8577J - X
	SLL 7758X - X
	After repair: 8/5/2018

Surgeon *Sam*

REF:

49826

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: SKB 85773

at Workshop m/s PRO PLUS

of BLK 5, PIONEER RD NORTH #01-35

Insured: CTI / TP

Policy No. _____

Claims No. _____


Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Bal. or Market Value: _____

IDAC Accident Report: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: _____ days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: SKB 85773 Yr Regn: 2011 / July

Type: M.Gar / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: MERCEDES BENZ E250 C.C. 1796

Colour: GRY A/C: Insured / Std / NI / NA

Sp. Reading: 132405 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: W00 21204 72A 416322

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 245/45R17

R: _____

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or CONTINENTAL

Front

R/Bal. 6 mm R/Bal. 6 mm

L/Bal. 6 mm L/Bal. 6 mm

D.O.A. 08/03/18 D.O.I. 15/03/18

Survey held at PRO PLUS

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

O/S Rear

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

* Repair Estimate : S\$3,000 - 4,000

* 3 days

RECEIVED 21 MAY 2018

Date/Time, File Pass to?

☐ : Preli. Report

1)

☐ : Final Report

Date/Time, File Return to?

2)

Days Of Repair: 3

Resurvey No. of Trip: 1

Survey Fee: 150

Transportation: _____

Add Fee: ☐ : Site Insp (\$ _____) \$ + RS \$ _____

☐ : Interview (\$ _____) Photos _____

☐ : Tech. Invs (\$ _____) Others _____

☐ : Weekend (\$ _____)

Report Format : PRG

Lump Sum / I.B.I: (\$ _____)

TOTAL

150

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	13 Mar 2018		13 Mar 2018 16:28 Assign				New Assignment Cancel Case

Main

Reference

Claim Details

Documents

[Show All](#)

CLAIM SUBFOLDER DETAILS

[Created by insurer]

Insured:	BLUE STAR CONCIERGE PTE LTD, Co. Reg. No.: 201506692D		
Main Claimant:	TEE HENG SUNG, ID: S2654982E		
Vehicle Reg. No.:	SKB8577J	Date of Loss:	08/03/2018 18:00 - :59
Claim Type:	TP / SNM18D01294C02	Policy/Cover Note No.:	DMHCSN1719391700 (Comprehensive)
Vehicle Reg. No. (Insured):	SLL7758X	Policy No. (Claimant):	D17MTPV01009003
		Excess:	S\$0.00
Repairer:	Pro Plus Automobile Engineers (HQ) 221 BALESTIER ROAD #10-01 ROCCA BALESTIER, 329928 Balestier - Tel:		
Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Irene Tay Hui Ping - 638986192]		
Claimant's Insurer:	Sompo Insurance Singapore Pte. Ltd. (HQ) - Tel: 6461 6555		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Final Rpt due 22/03/2018]		
Driver/Custodian (Insured):	LING THIAN CHYE (55 / Male), NRIC: S1525952C, Tel: +6596655604		
Adj Asg. Remarks:	NO EST, CASE W/O SJE.		

ASSOCIATED MAIL RECEIVED

[View All](#)[Compose Case Mail](#)

There are no mail for this case.

ALL ASSOCIATED TASKS

[View All](#)[Search Tasks](#)[Create New Task](#)[Complete](#)

Due Date Priority Type Task Group Subject Handler Assigned By Completed On Created On Done?

No results.

Lucas Lee

From: Sow-ye Wong <wongsylaw@gmail.com>
Sent: Tuesday, 13 March, 2018 4:06 PM
To: Lucas Lee; Raymond Cheong; Errol Tan
Cc: Irene Tay
Subject: Re: PRS FOR SKB8577J (CTI REF: SNM18D01294C02)

Dear Sirs

We thank you for your list of proposed Surveyors for the PRS *below*

We regret to inform you that our Client is unable to agree to your list of nominated Surveyors

Our Client proposes

MR ERROL TAN
M/s Pro Plus Automobile Engineers
Mobile : 9673 0595 / 9788 9809

Please contact our **Ms May Pang - 9799 5138 / 6264 0138**

Appreciate your kind understanding & help

Yours Sincerely

Sow yee
M/s Fong & Fong LLC

On Tue, Mar 13, 2018 at 4:00 PM, Lucas Lee <lucas.lee@sg.cntaiping.com> wrote:

Without Prejudice

Dear Sirs

We intend to conduct a pre-repair survey of the damage to your client's vehicle jointly with your client/your motor workshop. We propose to use one of the following motor surveyors to conduct the joint pre-repair survey as a single joint expert.

TAY BENG HEE
DERECK OH SIONG WEE
SEE CHEW SENG
MOHD FADHILAH BIN OSMAN
XING QUO QIANG
KENNETH KONG
SIMON HO
CHUA WEIJIE
MARCUS CHUA
HENRY NG

Please let us know within two(2) working days whether you agree to the appointment of any of these motor surveyors as a single joint expert.

You may select one of the listed motor surveyors and we will bear the cost of the pre-repair survey carried out by the single joint expert.

Case Handler: Irene Tay

Regards,

Lucas Lee

Claims Department (Motor)

China Taiping Insurance (Singapore) Pte. Ltd.

3, Anson Road, #16-00

Springleaf Tower,

Singapore 079909

Co. Reg. No. 200208384E

DID: 6389 6181

Fax: 6224 7175

Email: claimsdept@sg.cntaiping.com

Email: lucas.lee@sg.cntaiping.com

Website: www.sg.cntaiping.com

This email has been scanned by the Symantec Email Security.cloud service.
For more information please visit <http://www.symanteccloud.com>

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	4982E
Vehicle Details	
Vehicle No.:	SKB8577J
Vehicle to be Exported:	No
Intended De-registration Date:	21 May 2018
Vehicle Make:	MERCEDES BENZ
Vehicle Model:	E 250CGI
Primary Colour:	Silver
Manufacturing Year:	2011
Engine No.:	27186030216502
Chassis No.:	WDD2120472A416322
Maximum Power Output:	150.0 kW (201 bhp)
Open Market Value:	\$53,854.00
Original Registration Date:	01 Jul 2011
First Registration Date:	01 Jul 2011
Transfer Count:	0
Actual ARF Paid:	\$53,854.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	30 Jun 2021
PARF Rebate Amount:	\$35,005.00
Intended COE Rebate Details	
COE Expiry Date:	30 Jun 2021
COE Category:	B - Car (1601cc & above)
COE Period(Years):	10
QP Paid:	\$67,700.00
COE Rebate Amount:	\$21,043.00
Total Rebate Amount:	\$56,048.00

The information contained herein is correct as at 21 May 2018

OK

Sketch Plan Pg. 7

REPUBLIC OF SINGAPORE
IDENTITY CARD NO. S8671917G



Name

TEE MEI KEE

郑美琪

Race
CHINESE

Date of birth
16-07-1986

Sex
F

Country/Place of birth
MALAYSIA



5726235



NRIC No. S8671917G



Date of issue
07-04-2017

Address

APT BLK 113 TECK WHYE LANE
#09-650
SINGAPORE 680113

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	09/03/2018 15:09
Date Of Accident	08/03/2018 18:10
Exact Location Of Accident	ALONG STRAITS VIEW RD IN FRT OF MARINA 1 WEST TWR
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SKB8577J
Insured/Policyholder	
Name Of Registered Owner	TEE HENG SUNG
NRIC No	S2654982E
Email Address	VICKSONFURNISHING@GMAIL.COM
Mobile Phone No	(LOCAL) +65-97809098
Alternative Phone No	OFFICE-97809098

Vehicle Particulars

Manufacturer	MERCEDES-BENZ
Model	E250-1.8 CGI (A)
Exact Purpose for which vehicle was being used at time of accident	
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR

Insurance Company

Name of Insurance Company	SOMPO INSURANCE SINGAPORE PTE. LTD.
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	D17MTPV01009003
Cover Note Number	

Driver

Name of Driver	TEE MEI KEE
NRIC No	S8671917G
Date Of Birth	16/07/1986
Occupation	INDOOR
Date Of Driving Pass	01/07/2008
Driving Experience	9 YEARS AND 8 MONTHS
Gender	FEMALE
Mobile Number	(LOCAL) +65-85713423
Fax Number	
Contact Number	
Email Address	NOEMAIL

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the Insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the Insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:


- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the Information so collected under (d) above may be shared / disclosed:
 - (i) to all Insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.

Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:

9 March 2018

Reporting Centre Personnel's Signature
Name: Toh Khar Kian
NRIC/FIN No.:



Sompo Insurance Singapore Pte. Ltd.
 50 Raffles Place, #05-01/02 Singapore Land Tower, Singapore 049623
 Tel: 6461 6555 | Fax: 6221 3302 | Website: www.sompo.com.sg
 Co. Reg. No.: 195005490E | GST Reg. No.: M200903190

Certificate of Insurance

MOTOR VEHICLES (THIRD-PARTY RISKS AND COMPENSATION) ACT (CHAPTER 189)
 MOTOR VEHICLES (THIRD-PARTY RISKS AND COMPENSATION) RULES, 1960
 ROAD TRANSPORT ACT, 1987 (MALAYSIA)
 MOTOR VEHICLES (THIRD-PARTY RISKS) RULES, 1959 (MALAYSIA)

Cert No./Policy No. : D17MTPV01009003
 Insured : TEE HENG SUNG
 Motor Car (Registration No.) : SKB8577J
 Cover : Comprehensive - ExcelDrive Gold Plan
 Policy Commencement Date : 01 JULY 2017 00:00
 Policy Expiry Date : 30 JUNE 2018 23:59
 Maximum Liability (Section I) : Market value at time of loss
 Excess* : \$600 - Section I
 (Waived up to S\$1,000 if accident repair is done at ExcelDrive Workshops for the first claim per policy year)
 Voluntary Excess* : N/A
 Windscreen Excess* : S\$100.00 - Waived if Repair at ExcelDrive Workshop
 Loss of Use : Per Policy Schedule
 * Subject to GST wherever applicable

Persons or Classes of Persons entitled to drive*

1. The Insured.
2. Any other person who is driving on the Insured's order or with his permission.
3. In the event of the death of the Insured,
 - a. any member of the Insured's family, or a paid driver who has been driving the Motor Car during the life of the Insured and permission to drive had not been withdrawn prior to the death of the Insured; and
 - b. any other person who has been given permission to drive the Motor Car prior to the death and such permission had not been withdrawn by the Insured.

Provided that the person driving is permitted in accordance with the licensing or other laws or regulations to drive the Motor Car or has been so permitted and is not disqualified by order of a Court of Law or by reason of any enactment or regulation in that behalf from driving the Motor Car. And provided further that the Motor Car is registered under the Road Traffic Act (Chapter 276) and its registration under the Road Traffic Act (Chapter 276) has not been cancelled at the time of the accident, loss or damage.

Limitations As To Use

Use only for social, domestic and pleasure purpose and for the Insured's business. The Policy does not cover use for hire or reward, racing, pace-making, speed testing, reliability trial, the carriage of goods other than samples in connection with any trade or business or use for any purposes in connection with the Motor Trade.

ExcelDrive Workshops and Accident Reporting

It is a condition precedent to liability that the Insured shall call at the Company's Accident Reporting Center with the Motor Car within 24 hours of the accident or by the next working day thereof.

All accident repairs to the Motor Car must be carried out at ExcelDrive Workshops, otherwise the claim is not payable under the Policy. For ExcelDrive Prestige Plan, accident repairs to the Motor Car can be carried out at any workshop other than ExcelDrive Workshops.

For the list of Accident Reporting Centres and ExcelDrive Workshops, please visit our website at www.sompo.com.sg or call our Emergency Hotline: (65) 6226 3323.

I/We HEREBY CERTIFY that the policy to which this Certificate relates is issued in accordance with (1) the provisions of the Motor Vehicles (Third-Party Risks and Compensation) Act (Chapter 189) and Part IV of the Road Transport Act, 1987 (Malaysia); and (2) the Policy terms, conditions and exceptions of the Private Car Policy ref MTP.27

Sompo Insurance Singapore Pte. Ltd.

Authorised Signatory

Date/Time of Issue : 08 JUNE 2017 14:45

IMPORTANT NOTICE

- o Keep the Certificate in your Motor Car.
- o Under the Motor Vehicles (Third-Party Risks and Compensation) Act (Chapter 189), it shall be unlawful for any person to use or cause to permit any other person to use a motor vehicle without a valid policy of insurance under the Act.
- o On the sale of the Motor Car or if for any reason the insurance is terminated during its currency, the Insured must surrender the Certificate of Insurance and the Policy to the insurance company. If the Certificate of Insurance has been lost or destroyed, a statutory declaration to that effect must be made. Failure to comply with this obligation is an offence under the Motor Vehicles (Third-Party Risks and Compensation) Act (Chapter 189).
- o This Policy will cease to be valid once the Motor Car has been sold to another person. The Policy is not transferable to the new owner of the Motor Car.

Intermediary Code & Name : 11T10205 & TAY KIM SAN CI Code: 22A 4RTDHPM44LKM8DEA



**NANYANG
TECHNOLOGICAL
UNIVERSITY**

Sketch Plan B

- On 8 March 2018, at about 6.10 pm, I arrived at Straits View road in front of Marina One West Tower.
- Upon arriving, I noticed from my rear view mirror that an LTA officer was also arriving.
- There was a row of cars (at least 6/7, mostly private hires) illegally parked and waiting to pick up passengers on the right side kerb when I arrived. Please refer to image 1, 2 and 3.
- My vehicle was on the right lane and was moving in front of the other party's vehicle, SLL 7758X, which was parked and stationary on the right side kerb.
- When my vehicle was almost fully (80%) in front of SLL 7758X, I suddenly heard some noise and felt an impact on the back of my car. Please refer to diagram attached!
- During my conversation with the driver of SLL 7758X, the LTA officer came over to see if we needed assistance, at that time I realised most cars that were illegally parked along the kerb had left hurriedly due to his arrival.
- In his hurry to run away and avoid a booking from the LTA officer for illegally parking on double yellow line, the driver of SLL 7758X failed to observe safety before moving off and failed to give way to my vehicle. In his panic, he collided into the back of my vehicle.
- In view of the above, I would like to claim against third party's insurance for damages caused to my vehicle due to his negligence and failure to observe safety and give way.

Lin K



























...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	13 Mar 2018		13 Mar 2018 16:28 Edit Adj Rpt	\$0.00 Edit Estimates	\$0.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by insurer]									
Insured:	BLUE STAR CONCIERGE PTE LTD , Co. Reg. No.: 201506692D								
Main Claimant:	TEE HENG SUNG , ID: S2654982E								
Vehicle Reg. No.:	SKB8577J	Date of Loss:	08/03/2018 18:00 - :59 [80 Months and 7 Days From LTA Reg Date (Man Yr)]						
Claim Type:	TP / SNM18D01294C02	Policy/Cover Note No.:	DMHCSN1719391700 (Comprehensive)						
Vehicle Reg. No. (Insured):	SLL7758X	Policy No. (Claimant):	D17MTPV01009003						
		Excess:	\$0.00						
Repairer:	Pro Plus Automobile Engineers (HQ) 221 BALESTIER ROAD #10-01 ROCCA BALESTIER, 329928 Balestier - Tel:								
Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Irene Tay Hui Ping - 638986192]								
Claimant's Insurer:	Sompo Insurance Singapore Pte. Ltd. (HQ) - Tel: 6461 6555								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by MOHD RASUL] ... [Final Rpt due 22/03/2018]								
Driver/Custodian (Insured):	LING THIAN CHYE (55 / Male), NRIC: S1525952C, Tel: +6596655604								
Adj Asg. Remarks:	NO EST, CASE W/O SJE.								
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
There are no mail for this case.									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

***SKB8577J (SNM18D01294C02)**
[SLL7758X]
TP
TEE HENG SUNG
Mar 8 2018 6:00PM
[BLUE STAR CONCIERGE PTE LTD]
Pro Plus Automobile Engineers

Upload Documents Upload Photos Compose New Letter			View View in Browser	
Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	ETHOZ Protect Pte Ltd (Bukit Batok)	Thumbnail	Print
1	09/03/18 15:41	Accident Statement	 Load HTM	
Photos/Images			3 per page	<input checked="" type="checkbox"/>
No	Finalized On	ETHOZ Protect Pte Ltd (Bukit Batok)	Thumbnail	Print
1	09/03/18 15:33	Accident Photo [Linked Accident Report Documents]	 Load JPG	<input checked="" type="checkbox"/>
2	09/03/18 15:33	Accident Photo [Linked Accident Report Documents]	 Load JPG	<input checked="" type="checkbox"/>
3	09/03/18 15:33	Accident Photo [Linked Accident Report Documents]	 Load JPG	<input checked="" type="checkbox"/>
4	09/03/18 15:33	Accident Photo [Linked Accident Report Documents]	 Load JPG	<input checked="" type="checkbox"/>
5	09/03/18 15:33	Accident Photo [Linked Accident Report Documents]	 Load JPG	<input checked="" type="checkbox"/>
6	09/03/18 15:33	Accident Photo [Linked Accident Report Documents]	 Load JPG	<input checked="" type="checkbox"/>
7	09/03/18 15:33	Accident Photo [Linked Accident Report Documents]	 Load JPG	<input checked="" type="checkbox"/>
8	09/03/18 15:33	Accident Photo [Linked Accident Report Documents]	 Load JPG	<input checked="" type="checkbox"/>
9	09/03/18 15:33	Accident Photo [Linked Accident Report Documents]	 Load JPG	<input checked="" type="checkbox"/>
10	09/03/18 15:33	Accident Photo [Linked Accident Report Documents]	 Load JPG	<input checked="" type="checkbox"/>
11	09/03/18 15:33	Accident Photo [Linked Accident Report Documents]	 Load JPG	<input checked="" type="checkbox"/>
12	09/03/18 15:33	Accident Photo [Linked Accident Report Documents]	 Load JPG	<input checked="" type="checkbox"/>
13	09/03/18 15:33	Accident Photo [Linked Accident Report Documents]	 Load JPG	<input checked="" type="checkbox"/>
14	09/03/18 15:33	Accident Photo [Linked Accident Report Documents]	 Load JPG	<input checked="" type="checkbox"/>
15	09/03/18 15:33	Accident Photo [Linked Accident Report Documents]	 Load JPG	<input checked="" type="checkbox"/>
16	09/03/18 15:33	Accident Photo [Linked Accident Report Documents]	 Load JPG	<input checked="" type="checkbox"/>
17	09/03/18 15:33	Accident Photo [Linked Accident Report Documents]	 Load JPG	<input checked="" type="checkbox"/>
18	09/03/18 15:33	Accident Photo [Linked Accident Report Documents]	 Load JPG	<input checked="" type="checkbox"/>
19	09/03/18 15:33	Accident Photo [Linked Accident Report Documents]	 Load JPG	<input checked="" type="checkbox"/>
20	09/03/18 15:33	Accident Photo [Linked Accident Report Documents]	 Load JPG	<input checked="" type="checkbox"/>
21	09/03/18 15:33	Accident Photo [Linked Accident Report Documents]	 Load JPG	<input checked="" type="checkbox"/>
22	09/03/18 15:33	Accident Photo [Linked Accident Report Documents]	 Load JPG	<input checked="" type="checkbox"/>
23	09/03/18 15:33	Accident Photo [Linked Accident Report Documents]	 Load JPG	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	21/05/18 10:58	General View	 Load PDF	
2	21/05/18 10:58	Photo After Spray	 Load PDF	

Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	ETHOZ Protect Pte Ltd (Bukit Batok)	Thumbnail	Print
Documentation			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	ETHOZ Protect Pte Ltd (Bukit Batok)	Thumbnail	Print
1	09/03/18 15:39	Sketch Plan [Linked Accident Report Documents]	Load TIF	
No	Finalized On	China Taiping Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
1	13/03/18 16:28	PRS	Load PDF	
2	13/03/18 16:28	OI GIA REPORT	Load PDF	

Linked Accident Report Documents

			View	View in Browser
			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	ETHOZ Protect Pte Ltd (Bukit Batok)	Thumbnail	Print
1	09/03/18 15:41	Accident Statement	Load HTM	
Photos/Images			3 per page	<input checked="" type="checkbox"/>
No	Finalized On	ETHOZ Protect Pte Ltd (Bukit Batok)	Thumbnail	Print
1	09/03/18 15:33	Accident Photo	Load JPG	<input checked="" type="checkbox"/>
2	09/03/18 15:33	Accident Photo	Load JPG	<input checked="" type="checkbox"/>
3	09/03/18 15:33	Accident Photo	Load JPG	<input checked="" type="checkbox"/>
4	09/03/18 15:33	Accident Photo	Load JPG	<input checked="" type="checkbox"/>
5	09/03/18 15:33	Accident Photo	Load JPG	<input checked="" type="checkbox"/>
6	09/03/18 15:33	Accident Photo	Load JPG	<input checked="" type="checkbox"/>
7	09/03/18 15:33	Accident Photo	Load JPG	<input checked="" type="checkbox"/>
8	09/03/18 15:33	Accident Photo	Load JPG	<input checked="" type="checkbox"/>
9	09/03/18 15:33	Accident Photo	Load JPG	<input checked="" type="checkbox"/>
10	09/03/18 15:33	Accident Photo	Load JPG	<input checked="" type="checkbox"/>
11	09/03/18 15:33	Accident Photo	Load JPG	<input checked="" type="checkbox"/>
12	09/03/18 15:33	Accident Photo	Load JPG	<input checked="" type="checkbox"/>
13	09/03/18 15:33	Accident Photo	Load JPG	<input checked="" type="checkbox"/>
14	09/03/18 15:33	Accident Photo	Load JPG	<input checked="" type="checkbox"/>
15	09/03/18 15:33	Accident Photo	Load JPG	<input checked="" type="checkbox"/>
16	09/03/18 15:33	Accident Photo	Load JPG	<input checked="" type="checkbox"/>
17	09/03/18 15:33	Accident Photo	Load JPG	<input checked="" type="checkbox"/>
18	09/03/18 15:33	Accident Photo	Load JPG	<input checked="" type="checkbox"/>
19	09/03/18 15:33	Accident Photo	Load JPG	<input checked="" type="checkbox"/>
20	09/03/18 15:33	Accident Photo	Load JPG	<input checked="" type="checkbox"/>
21	09/03/18 15:33	Accident Photo	Load JPG	<input checked="" type="checkbox"/>
22	09/03/18 15:33	Accident Photo	Load JPG	<input checked="" type="checkbox"/>
23	09/03/18 15:33	Accident Photo	Load JPG	<input checked="" type="checkbox"/>
Documentation			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	ETHOZ Protect Pte Ltd (Bukit Batok)	Thumbnail	Print
1	09/03/18 15:39	Sketch Plan	Load TIF	

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)

Show Remarks To: ☐ Handling Insurer

Note: Remarks are private unless you show it to other parties.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS3/CTI18004844/R1D3E2

Date: 22/05/2018

REFERENCE

Handling Insurer: China Taiping Insurance
(Singapore) Pte. Ltd.

Policy No: DMHCSN1719391700

Claimant Vehicle
No: SKB8577JInsured Vehicle
No: SLL7758X

Date of Loss: 08/03/2018

Nature of Claim: TP

Claim
No: SNM18D01294C02

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SKB8577J

Make & Model: MERCEDES-BENZ E250, 1.8 CGI (A)

Engine No: 27186030216502

Reg. Date: 01/07/2011 (Man. Year: 2011)

Chassis No: WDD2120472A416322

Colour: Grey

Odometer: 132405 km

Engine Capacity: 1796 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable):

Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification:

No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 245/45 R17

Rear Tyre Size: 245/45 R17

Front Left Side: Continental 6 mm

Rear Left Side: Continental 6 mm

Front Right Side: Continental 6 mm

Rear Right Side: Continental 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Nett Amount (S\$)	0.00	0.00	0.00	

INSPECTION

Date of Assignment: 13/03/2018

Date Inspected: 15/03/2018 Inspected At:

Pro Plus Automobile Engineers (HQ)
221 BALESTIER ROAD #10-01 ROCCA
BALESTIER
Singapore 329928

Estimated Period of Repair: 3.0 days

Adjuster: MOHD RASUL

Manager: Nivitha Govindasamy

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

- A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
- B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION.
THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE.
- C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.

THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$3,000.00 - \$4,000.00

REPAIR DETAILS

Reference

Part Source: MRM-SG **Version:** 1.0 (Last Synchronised: 22 May 2018)

Parts: 143 MERCEDES-BENZ E250 1.8 CGI (A) (Catalogue:Merimen Singapore 1.0)

Labour: Repairer's (Price-denominated Standard List)

Print Code: (Unsubmitted, no print-code for SKB8577J)

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

There are no new parts selected.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.

< END OF ESTIMATES >