

ASS. REC. BY:

REF:

CS3/CT1/8004854/7163

Special Instructions:

Surveyor:
Mennen

Taufik

ASSIGNMENT (Office)

From (Person):

Jowyn Tay

of

CTI

Date/Time: 13/3/18

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

CB 7573X

Insured:

PC 6842S

at Workshop m/s

Dynacle Transportation

Tel:

6635 7070/87220417

of 21 woodlands close # 07-42

Policy No:

DMB ISN 1803221800

Claim No:

SNM 18D01331C02

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A. 10/2/2018

Insp: 27A Juvang Pot Rd

CA / REV / REP. / REV 24 HRS WP

H.O.D. Endorsement:

Date/Time:

10:15am 01/3/18

Person Contacted:

Ms. Tan

Vehicle IN/OUT

Date/Time Action/Instruction (x) Estimate

CB 7573X -X

PC 6842S -X

Dismantle: 16/3/2018

After repair: 20/3/2018

Surveyor

Tan Jiah

REF: CTI

ASSIGNMENT

From: Date: 16/3/18


Estimated Cost:

OD ☒ TP ☐ WS ☐ TP RES ☐ OD RES ☐ EVA ☐ INV ☐ MV

To inspect Vehicle No: CB7573X
at Workshop m/s Dynacle Transportation
of 27A Jurong Port Rd, 619101
Insured: Willy Mufaz
Policy No:
Claims No:
Sum Insured: Excess:
(Client's Record)
Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Bal. or Market Value:

IDAC Accident Rpt: Consistent? : Yes or No

GIA / PR Seen: Consistent? : Yes or No

Est. Repairs: 3 days Res.: Yes or No

Lum Sum: % 3 Val: Yes or No

CA / REV / REP. / 24 HRS ^{up}

Date: Person Contacted: Ms Lim

Vehicle: IN / OUT
Ms Lim

Veh No: CB 7573X Yr Regn: 15

Type: M.Car / M.Cycle / ☒ Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Nissan N350 C.C. 2488

Colour: Silver A/C: Insured / Std / NI / NA

Sp. Reading: 415 7832 T/Radio: Insured / Std / NI / NA

Eng/No:

C/No: JN1TC2E26Z0001643

Gen. Cond: ☒ Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 145/115

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

R/Bal. C mm

L/Bal. L mm

D.O.A.

Rear

R/Bal. C mm

L/Bal. L mm

D.O.I. 16/3/18 04pm

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

Rear N/S

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

Est: \$2000 - \$3000, 3 days.

RECEIVED 20 APR 2018

Date/Time, File Pass to?

☐ : Preli. Report

☐ : Final Report

1)

Date/Time, File Return to?

2)

Days Of Repair: 3

Resurvey No. of Trip: 2

Survey Fee:

Transportation

1) S + RS \$

2) Photos

3) Others

TOTAL

Report Format: PRS

Lump Sum / I.B.I: (\$

Add Fee: ☐ : Site Insp (\$

☐ : Interview (\$

☐ : Tech. Invs (\$

☐ : Weekend (\$




LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
CHINA TAIPING INSURANCE (S) PTE LTD		Ref : CS3/CTI18004854/T1d3		
3 ANSON ROAD #16-00 SPRINGLEAF TOWERS SINGAPORE 079909		Date : 14-03-2018		
		Code : CTI		
1. Policy Particulars :- (THIRD PARTY CLAIM)				
Insured Veh.	PC 6842S	Veh. Inspected	CB 7573X	
Policy No.	DMB1SN1803221800	Coverage (\$)	0.00	
Claim No.	SNM18D01339C02	Excess (\$)	0.00	
Assign From	MERIMEN (JOWYN TAY)	Assign Date	14/03/2018	
2. Vehicle Particulars & Condition				
Make & Model		c.c	0	
Engine No.	HIDDEN	Year of Reg.		
Chassis No.		Colour		
Odometer	-	Steering		
Brakes		Modification		
General				
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre			mm	
L/H Front Tyre			mm	
R/H Rear Tyre			mm	
L/H Rear Tyre			mm	
4. Description of Damages				
5. General Information				
Accident Date	10/02/2018	Inspection Date	14/03/2018	
Survey held at	-			
5a. Remarks				
A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.				

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	13 Mar 2018		13 Mar 2018 17:43 Assign				New Assignment Cancel Case

Main

Reference

Claim Details

Documents

[Show All](#)

CLAIM SUBFOLDER DETAILS

[Created by insurer]

Insured:	NAM HO DMC PTE LTD		
Main Claimant:	TIN LING TIEN, ID: S1370239Z		
Vehicle Reg. No.:	CB7573X	Date of Loss:	10/02/2018 15:00 - :59
Claim Type:	TP / SNM18D01339C02	Policy/Cover Note No.:	DMB1SN1803221800
Vehicle Reg. No. (Insured):	PC6842S	Policy No. (Claimant):	
		Excess:	S\$0.00
Repairer:	Dynacle Transportation And Workshop Pte Ltd (woodlands) (HQ) 21 WOODLANDS CLOSE, #07-42 PRIMZ BIZHUB, 737854 Woodlands - Tel: 87220417/66357070		
Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Jowyn Tay - 6389 6174]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Final Rpt due 22/03/2018]		
Adj Asg. Remarks:	PLEASE SURVEY THIRD PARTY, CHECK CONSISTENCY OF THE DAMAGES ON WITHOUT PREJUDICE BASIS. KINDLY LET US HAVE YOUR RECOMMENDED REPAIR AMOUNT IF THERE IS NO ESTIMATE PROVIDED DURING PRE REPAIR.		

ASSOCIATED MAIL RECEIVED

[View All](#)[Compose Case Mail](#)

There are no mail for this case.

ALL ASSOCIATED TASKS

[View All](#)[Search Tasks](#)[Create New Task](#)[Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	12/02/2018 14:02
Date Of Accident	10/02/2018 15:00
Exact Location Of Accident	CHANDER RD
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	CB7573X
Insured/Policyholder	
Name Of Registered Owner	TIN LING TIEN
NRIC No	S1370239Z
Email Address	NOEMAIL
Mobile Phone No	(LOCAL) +65-98079555
Alternative Phone No	OFFICE-98079555

Vehicle Particulars

Manufacturer	NISSAN
Model	NV350
Exact Purpose for which vehicle was being used at time of accident	
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	BUS

Insurance Company

Name of Insurance Company	NTUC INCOME INSURANCE CO-OPERATIVE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	5072379693-03
Cover Note Number	

Driver

Name of Driver	TIN LING TIEN
NRIC No	S1370239Z
Date Of Birth	18/07/1959
Occupation	OUTDOOR
Date Of Driving Pass	15/08/1984
Driving Experience	33 YEARS AND 5 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-98079555
Fax Number	
Contact Number	OFFICE-98079555
Email Address	NOEMAIL

Address BLK 714 CLEMENTI WEST ST 2 #04-139
 Postcode
 Was driver an employee of the Insured's Company NO
 If No, Relationship of the Driver with the Insured OWNER
 Vehicle Registration Number of Driver's Own Vehicle -
 -
 -
 Insurance Company of Driver's Own Vehicle -
 -
 -

General Information of the Accident

Type Of Accident HIT AND RUN / VANDALISM / DAMAGED WHILST PARKED
 Weather Conditions CLEAR
 Road Surface DRY

Other Information

Was any foreign vehicle involved in this accident? NO
 Number of vehicles involved in the accident
 Was any body injured in the Accident? NO
 Was any injured conveyed to hospital by ambulance?
 Was any other material or property damaged? YES
 I have been approached by unknown person(s) soliciting/offering accident claims assistance. NO
 Number of Passengers (Including Driver) 1

Details of Police Action

Was the accident reported to the police? NO
 If Yes, Please state which Police Station
 Was notice of intended Prosecution given? NO
 If Yes, against whom?

Circumstances of Accident

WHEN MY VEHICLE WAS STATIONARY WAITING FOR PASSENGERS. SUDDENLY A VEHICLE WHICH WAS PARKING BEHIND MY REAR MOVED OUT AND HIT ONTO THE REAR LEFT PORTION OF MY VEHICLE.

Attachment(s)

Are accident photos available for attachment? YES
 Was there any video captured by Car Camera? NO
 Was there any audio recorded? NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number PC6842S
 Vehicle Make/Model/Colour
 Details Of Properties
 Vehicle Category BUS
 Name of Driver
 NRIC/Passport Number
 Contact Number
 Address
 Postcode
 Insurance Company Name
 Nature Of Damage
 No. Of Passenger (Including Driver)

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all Insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.

Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

Sketch Plan #2 Pg. 1

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

This image shows a single sheet of white paper with horizontal blue or grey ruling lines. The lines are evenly spaced and run across the width of the page. There is no handwriting or other markings on the paper.

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

Enquire Transfer Fee

Vehicle Details			
Vehicle No. :	CB7573X		
Vehicle Type :	S20 - School Transport Bus/Coach/Minibus		
Vehicle Attachment 1 :	Air-Conditioned		
Vehicle Scheme :	School Bus with AWC		
Vehicle Make :	NISSAN		
Vehicle Model :	NV350 MICROBUS 2.5 4DR 5MT ABS		
Chassis No. :	JN1TC2E26Z0001643		
Propellant :	Diesel		
Engine No. :	YD25353053A		
Engine Capacity :	2488 cc		
Maximum Power Output :	-		
Maximum Laden Weight :	3200 kg		
Unladen Weight :	1960 kg		
Year Of Manufacture :	2014		
Original Registration Date :	23 Jun 2015		
Lifespan Expiry Date :	22 Jun 2035		
Road Tax Expiry Date :	22 Jun 2018		
Inspection Due Date :	22 Jun 2018		
Intended Transfer Date :	25 Apr 2018		
CO2 Emission :	-		
CO Emission :	-		
HC Emission :	-		
NOx Emission :	-		
PM Emission :	-		
The current road tax expiry is 22 Jun 2018. You may renew the road tax from 23 Mar 2018 with all pre-requisite(s) fulfilled. If the road tax is renewed after 22 Jun 2018, late renewal fee(s) will be imposed. Please use Enquire Road Tax Payable to check on the late fee(s) payable.			
Road tax, including Over Payment (if any), of a vehicle will follow the vehicle to the new registered owner when its ownership is being transferred.			
Amount Payable (From 23 Jun 2018 to 22 Dec 2018)			
	Amount Before GST (S\$)	GST Amount (S\$)	Amount After GST (S\$)
Transfer Fee :	25.00	-	25.00
Sub Total :			25.00
Nett Road Tax Amount (After Offsetting Over Payment) :	0.00	-	0.00
Total Amount Payable :			25.00
Amount Payable (From 23 Jun 2018 to 22 Jun 2019)			
	Amount Before GST (S\$)	GST Amount (S\$)	Amount After GST (S\$)
Transfer Fee :	25.00	-	25.00
Sub Total :			25.00
Nett Road Tax Amount (After Offsetting Over Payment) :	0.00	-	0.00

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	13 Mar 2018		13 Mar 2018 17:43 Edit Adj Rpt	\$0.00 Edit Estimates	\$0.00 View Rpt		Pending for Survey Report Cancel Case

Main

Reference

Claim Details

Documents

[Show All](#)

CLAIM SUBFOLDER DETAILS

[Created by insurer]

Insured:	NAM HO DMC PTE LTD, Co. Reg. No.: -		
Main Claimant:	TIN LING TIEN, ID: S1370239Z		
Vehicle Reg. No.:	CB7573X	Date of Loss:	10/02/2018 15:00 - :59 [31 Months and 18 Days From LTA Reg Date (Man Yr)]
Claim Type:	TP / SNM18D01339C02	Policy/Cover Note No.:	DMB1SN1803221800
Vehicle Reg. No. (Insured):	PC6842S	Policy No. (Claimant):	
		Excess:	\$0.00
Repairer:	Dynacle Transportation And Workshop Pte Ltd (woodlands) (HQ) 21 WOODLANDS CLOSE, #07-42 PRIMZ BIZHUB, 737854 Woodlands - Tel: 87220417/66357070		
Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Jowyn Tay - 6389 6174]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by Sebastian Yeang Wai Keen] ... [Final Rpt due 22/03/2018]		
Adj Asg. Remarks:	PLEASE SURVEY THIRD PARTY, CHECK CONSISTENCY OF THE DAMAGES ON WITHOUT PREJUDICE BASIS. KINDLY LET US HAVE YOUR RECOMMENDED REPAIR AMOUNT IF THERE IS NO ESTIMATE PROVIDED DURING PRE REPAIR.		

ASSOCIATED MAIL RECEIVED

[View All](#)[Compose Case Mail](#)

There are no mail for this case.

ALL ASSOCIATED TASKS

[View All](#)[Search Tasks](#)[Create New Task](#)[Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

***CB7573X (SNM18D01339C02)**
[PC6842S]

TP

TIN LING TIEN

Feb 10 2018 3:00PM

[NAM HO DMC PTE LTD]

Dynacle Transportation And Workshop Pte Ltd (woodlands)

Upload Documents Upload Photos Compose New Letter

View View in Browser ▼

Photos/Images

3 per page ▼



No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
1	25/04/18 16:51	General View		Load PDF	
2	25/04/18 16:53	Photographs of Damaged Parts		Load PDF	
3	25/04/18 16:54	Photo After Spray		Load PDF	

Documentation

1 per page ▼



No	Finalized On	China Taiping Insurance (Singapore) Pte. Ltd. (HQ)		Thumbnail	Print
1	13/03/18 17:45	THIRD PARTY CB7573X -PRS EMAIL BTW CIC AND KSCGP		Load PDF	
2	13/03/18 17:45	THIRD PARTY CB7573X -FR KSCGP -PRS LTR		Load PDF	
3	13/03/18 17:45	THIRD PARTY SAS REPORT CB7573X		Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST

Reset

Save

Print

There are no document checklists configured.

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)

Show Remarks To: ☐ Handling Insurer

Note: Remarks are private unless you show it to other parties.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS3/CT118004854/T1D3S2
Date: 27/04/2018

REFERENCE

Handling Insurer: China Taiping Insurance (Singapore) Pte. Ltd. Policy No: DMB1SN1803221800
Claimant Vehicle No: CB7573X Insured Vehicle No: PC6842S
Date of Loss: 10/02/2018 Nature of Claim: TP Claim No: SNM18D01339C02

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: CB7573X
Make & Model: NISSAN NV350, 2.5 D HR MICROBUS (A) Engine No: YD25353053A
Reg. Date: 23/06/2015 (Man. Year: 2014) Chassis No: JN1TC2E26Z0001643
Colour: Silver Odometer: 157832 km
Engine Capacity: 2488 cc
Market Value/New Car Price: N/A
Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Good Steering (Serviceable): Yes Footbrake (Serviceable): Yes
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 195 R15 Rear Tyre Size: 195 R15
Front Left Side: Michelin 6 mm Rear Left Side: Michelin 6 mm
Front Right Side: Michelin 6 mm Rear Right Side: Michelin 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Nett Amount (S\$)	0.00	0.00	0.00	

INSPECTION

Date of Assignment: 13/03/2018
Date Inspected: 16/03/2018 Inspected At: 27A JURONG PORT ROAD SINGAPORE 619101
Repairer: Dynacle Transportation And Workshop Pte Ltd (woodlands) (HQ)
21 WOODLANDS CLOSE, #07-42 PRIMZ BIZHUB
Singapore 737854
Estimated Period of Repair: 3.0 days

Adjuster: Sebastian Yeang Wai Keen

Manager: Nivitha Govindasamy

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

4/27/2018

Adjuster Report

- A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
- B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION.
THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE.
- C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.

THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$2,000.00 - \$3,000.00

REPAIR DETAILS

Reference

Part Source: (Last Synchronised: 27 Apr 2018)

Parts: N/A NISSAN NV350 2.5 D HR MICROBUS (A) (Model not available in database)

Labour: Repairer's (Price-denominated Standard List)

Print Code: (Unsubmitted, no print-code for CB7573X)

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

There are no new parts selected.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.

< END OF ESTIMATES >