

ASS. REC. BY:

REF: CS/FCI 18 004869/TIRD3

Special Instruction: <sup>n2</sup>

Surveyor: Taukikh

ASSIGNMENT (Office)

From (Person): Karen Tan

of FCI

Date/Time: 14/3/18 10am

Estimated Cost:

Bill to:

OD/TP/WS/TP RES / OD RES / EVA / INV / MV? CS

To Inspect Vehicle No: SIF 2184R

Insured: SHB 1346X

at Workshop m/s Cycle & Carriage Automotive  
of 209 Penden Gardens

Tel: 6568 4555

Policy No: \_\_\_\_\_ Claim No: D18 001999 MFSH

Sum Insured: \_\_\_\_\_ Excess: \_\_\_\_\_

Make of Veh: \_\_\_\_\_ D.O.A. 08/03/2018  
(Client's Record)

CA / REV / REP. / REV 24 HRS <sup>wp</sup>

H.O.D. Endorsement: \_\_\_\_\_

Date/Time: 12:10pm @ 14/3/18 Person Contacted: COCO

Vehicle IN / OUT


Date/Time	Action/Instruction	Estimate
	SIF 2184R - CC3 / LCR 1800 1625 / K/wb3	D.O.A: 08/03/2018
	SHB 1346X - CC3 / LCR 1800 1625 / K/wb3	D.O.A: 08/03/2018
	Confirm \$3130.00 @ 5 days	
	Red: \$1953.00, 38/	

Shirazulie Taught

REF: ~~2018~~ FC1

**ASSIGNMENT**

From: \_\_\_\_\_ Date: 14/03/2018  
 Estimated Cost: \_\_\_\_\_  
 OD / TP / WS / TP RES / OD RES / EVA / INV / MV  
 To Inspect Vehicle No: SMA 3188  
 at Workshop m/s: Perth  
 of: 3D3 Accidental Rd  
 Insured: \_\_\_\_\_  
 Policy No. \_\_\_\_\_  
 Claims No. \_\_\_\_\_  
 Sum Insured: \_\_\_\_\_ Excess: \_\_\_\_\_  
 (Client's Record)  
 Make of Veh: Subaru

	
N/S	O/S

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value: \_\_\_\_\_  
 IDAC Accident Rpt: \_\_\_\_\_ Consistent?: Yes or No  
 GIA / PR Seen: \_\_\_\_\_ Consistent?: Yes or No  
 Est. Repairs: \_\_\_\_\_ days Res.: Yes or No  
 Lum Sum: \_\_\_\_\_ % 3 Val.: Yes or No  
 CA / REV / REP. / 24 HRS  
 WP

Vehicle: IN / OUT  
 C/C

Veh No: SLF 2184R Yr Regn: 2016 / Aug  
 Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /  
 Truck / Trailer or \_\_\_\_\_  
 Make: Mitsubishi Attrage c.c. 1193  
 Colour: white A/C: Insured / Std / NI / NA  
 Sp. Reading: \_\_\_\_\_ T/Radio: Insured / Std / NI / NA  
 Eng/No: \_\_\_\_\_  
 C/No: MMBSTA13A H4 001784  
 Gen. Cond: Good / Fair / Poor / Burnt  
 Steering: Inorder / Jammed / Leaked / Burnt or \_\_\_\_\_  
 Brake: Inorder / Jammed / Leaked / Burnt or \_\_\_\_\_  
 Modi: Nil / S/Rim / STD A/Rim or \_\_\_\_\_  
 Tyre Size: F: 185/55R15  
 R: \_\_\_\_\_  
 BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /  
 TOYO / YOKO or Achilles  
 Front \_\_\_\_\_ Rear \_\_\_\_\_  
 R/Bal. 6 mm R/Bal. 6 mm  
 L/Bal. 6 mm L/Bal. 6 mm  
 D.O.A. \_\_\_\_\_ D.O.I. 14/3/18 @ 17W  
 Survey held at C&C Rander Gdn  
 Des. of Damages: Frt / Rear / O/S / N/S / UIC / Rooftop or \_\_\_\_\_

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

RECEIVED 16 SEP 2018

Date/Time File Pass to?  : Preli. Report  
 1) fyas1  : Final Report  
 Date/Time File Return to?

Days Of Repair: 5  
 Resurvey No. of Trip: -

Report Format: TP  
 Lump Sum / I.B.I: (\$ 3130.00)

Add Fee:  Site Insp (\$ \_\_\_\_\_) ) S + RS \$  
 Interview (\$ \_\_\_\_\_) ) Photos  
 Tech. Invs (\$ \_\_\_\_\_) ) Others  
 Weekend (\$ \_\_\_\_\_) )

Survey Fee:	<u>140</u>
Transportation:	<u>50</u>
	<u>27</u>
<b>TOTAL</b>	<b><u>217</u></b>



# LKK Auto Consultants Pte Ltd

51 Ubi Ave. 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
FIRST CAPITAL INSURANCE LTD		Ref : CS/FC118004869/T1rd3	
36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877		Date : 14-03-2018	
		Code : FCI2	
1. Policy Particulars :- THIRD PARTY CLAIM			
Insured Veh.	SHB 4346X	Veh. Inspected	SLF 2184R
Policy No.		Coverage (\$)	0.00
Claim No.	D18001999MFSH	Excess (\$)	0.00
Assign From	CWS (KAREN TAN)	Assign Date	14/03/2018
2. Vehicle Particulars & Condition			
Make & Model		c.c	0
Engine No.	HIDDEN	Year of Reg.	
Chassis No.		Colour	
Odometer	-	Steering	
Brakes		Modification	
General			
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm
4. Description of Damages			
5. General Information			
Accident Date	08/03/2018	Inspection Date	14/03/2018
Survey held at	CYCLE & CARRIAGE AUTOMOTIVE PTE LTD 209 PANDAN GARDENS SINGAPORE 609339		
5a. Remarks			
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			

**MOTOR SURVEY ASSIGNMENT**

<b>Date</b>	09-03-2018	<b>Our Ref No.</b> D18001999MFSH
<b>Accident Date</b>	08-03-2018	<b>Claim Type.</b> Third Party
<b>Insured Vehicle</b>	SHB4346X	<b>Third Party Vehicle.</b> SLF2184R
<b>Survey Location</b>	209 PANDAN GARDENS	
<b>Contact Person.</b>	COCO LU TING	
<b>Contact No.</b>	65684555/ 0	<b>Fax No.</b> 65691056
<b>Survey Type</b>	WITHOUT PREJUDICE: LIABILITY UNCLEAR:	
<b>Appointed Surveyor</b>	LKK AUTO CONSULTANTS PTE LTD	
<b>Contact Person</b>	NA	<b>Fax No.</b> 68416315
<b>Contact Number.</b>	NA	

**FOR DIRECT SETTLEMENT**

Please submit to us the Tax Invoice together with letter of claim for Rental OR Loss of use (based on NIMA Benchmark rates) together with your survey report.

## THIRD PARTY SURVEY REQUEST

<b>Cc : Workshop</b>	CYCLE & CARRIAGE AUTOMOTIVE PTE LTD	<b>Attention.</b> NIL
<b>Cc : TP Solicitor</b>	NA	<b>TP Solicitor Fax No.</b> NA
<b>Officer Incharge</b>	KARENT	

**IMPORTANT NOTE**

Kindly submit the survey report via CWS within 14 days for survey assignment and 7 days for re-inspection.  
This is a computer generated letter, no signature required.

Job Sheet (/ClaimWS/Surveyor/JobSheet/235799)



PRI Documents



Close



## PRI Header Details

<b>Claim No</b>	D18001999MFSH	<b>Policy No</b>	D-18088936MFSH	<b>Claimant S.No &amp; Name</b>	1 & CYCLE & ( LTD
<b>Workshop Name</b>	CYCLE & CARRIAGE AUTOMOTIVE PTE LTD (Contact Person : COCO LU TING)	<b>Survey Location &amp; Contact Details</b>	209 PANDAN GARDENS <b>Mobile:</b> 0 , <b>Phone:</b> 65684555 , <b>Fax:</b> 65691056 <b>EmailId:</b> COCO.LU@CYCLECARRIAGE.COM.SG		
<b>Our Surveyor</b>	LKK AUTO CONSULTANTS PTE LTD	<b>Instructions To Surveyor</b>	WITHOUT PREJUDICE: LIABILITY UNCLEAR:		
<b>Insured Name</b>	COMFORT TRANSPORTATION PTE LTD	<b>Insured Vehicle No</b>	SHB4346X	<b>TP Vehicle No</b>	SLF2184R
<b>PRI Recieved Date</b>	13-03-2018 04:26:53 PM	<b>Surveyor Appointed Date</b>	14-03-2018 09:59:25 AM	<b>Surveyor Accept Date</b>	14-03-2018 0

## Survey Report Upload

<b>Surveyor Inspection Date *:</b>	<input type="text"/>	<b>Surveyor Report Date</b>	14-03-2018	<b>Upload Survey Report *:</b>	<input type="button" value="Choose File"/>
------------------------------------	----------------------	-----------------------------	------------	--------------------------------	--

## Vehicle Particulars

<b>Make</b>	<input type="text" value="Please Select Make"/>	<b>Model</b>	<input type="text" value="Please Select Model"/>	<b>Year</b>	<input type="text" value="Select Year"/>
<b>Chasis No</b>	<input type="text"/>	<b>Engine No</b>	<input type="text"/>	<b>Mileage</b>	<input type="text"/>
<b>Color</b>	<input type="text"/>	<b>Cubic Capacity</b>	<input type="text"/>		

## Multiple Documents Upload

<input type="button" value="Upload Multiple Documents"/>	
<b>File Name</b>	<b>Action</b>

## Surveyor Job Remarks

<b>Remarks</b>	<input type="text"/>	<input type="button" value="Save"/>
----------------	----------------------	-------------------------------------

## Janice Lee (LKKAuto)

---

**From:** Cheng Jo Jo <jojo.cheng@cyclecarriage.com.sg>  
**Sent:** Wednesday, July 11, 2018 4:28 PM  
**To:** Taufikh (LKKAuto); Mei Kwan (LKKAuto); Admin-D (LKKAuto); Admin A  
**Cc:** Loi Ai Ting; Lauro Araos Songcuan Jr; Andre Chow En De  
**Subject:** FINALISE - SLF2184R (MIT) - TP 1ST CAPITAL  
**Attachments:** scan.pdf


Hi Taufikh,

Attached here with the file and photo for your kind perusal.

Kindly confirm finalised amount at \$ 3,349.10 after GST.

Best Regards,

**JoJo Cheng**  
Customer Service



**CYCLE & CARRIAGE**

Exceptional Journeys

Cycle & Carriage Singapore • 209 Pandan Gardens, Singapore 609339  
T: +65 6568 4554 • F: +65 6565 1240 • [www.cyclecarriage.com.sg](http://www.cyclecarriage.com.sg)

 A member of the Jardine Cycle & Carriage Group

**DISCLAIMER:-** This email and any attachment to it is confidential and intended only for the use of the individual or entity named above and may contain information that is privileged. If you are not the intended recipient, you are notified that any dissemination, distribution or copying of this email or any attachment is strictly prohibited. If you have received this email in error, please notify us immediately by return email and destroy the original message. Any views expressed are those of the individual sender, and not necessarily the views of Cycle Carriage Industries Pte Ltd and/or any of its related corporations.

REPUBLIC OF SINGAPORE DRIVING LICENCE

License Number: **S1268467C**

Name: **LIM HUNG**

Birth Date: **13 Jul 1957**

Issue Date: **04 Jul 2003**

1000625883B



REPUBLIC OF SINGAPORE

IDENTITY CARD NO. **S1268467C**

Name: **LIM HUNG**

林 泓

Race: **CHINESE**

Date of Birth: **13-07-1957**

Sex: **M**

Country of Birth: **SINGAPORE**




FOR C&C USE ONLY

YOU ARE LICENSED TO DRIVE VEHICLES IN THE FOLLOWING CLASS(ES)

CLASS DATE

Class 3 Motor Cars and Motor Tractors the weight of which unladen does not exceed 2500 kilograms 09 Jun 1978

NP 428A

Licence No: **S1268467C**

0933397

S1268467C



Blood Group: **B+** Date of issue: **04-05-1993**

Address: **APT BLK 721 TAMPINES STREET 71 #15-226 SINGAPORE 520721**

NRIC No: **S1268467C** Date: **22-05-2001** No: **3999376**

FOR C&C USE ONLY



CYCLE & CARRIAGE

CYCLE & CARRIAGE AUTOMOTIVE PTE LIMITED  
PANDAN GARDENS CUSTOMER SERVICE CENTRE

209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65691056



ESTIMATE

GST Reg No : MR-8500111-X

Co Reg No : 197701469G

Invoice Name & Address	Owner Name & Vehicle Info	
Lion City Rentals Pte Ltd  60 Anson Road #11-01 Mapletree Anson Singapore 079914  Contact No Mobile: 67420984	Cust No/Name	/Lion City Rentals Pte Ltd
	Reg No/Reg Date	SLF2184R / 18/08/201
	Date In/Mileage	/ 0
	Chassis No	MMBSTA13AHH001784
	Engine No	3A92UDH3733
	Make/Model	MIT/17MY ATTRAGE 1.2 CVT
	Colour/Trim	W05 WHITE PEARL / BK BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No
CSM00041	Cash	13/03/2018/ 11:18	tlc	442 / CocoLu	22731

Description of Goods / Services	Qty	Unit Price	Disc%	Amount
E PNT88000 TO REPAIR FRT DOOR RH, REAR DOOR RH, SIDE SILL RH, REAR FENDER RH REAR BUMPER				1100 1650.00
E PNT98000 TO SPRAY PAINT FOR REAR BUMPER, REAR FENDER RH, REAR DOOR RH FRT DOOR RH, SIDE SILL RH,				1890 2520.00
B WHEELALIGNMENT To Conduct Computerize Full Wheel Alignment				✓ 120.00
M SUNDRY TO TRANSFER RIM TO TYRE				X ✓ 30.00
M SUNDRY Sundry				✓ nec 20.00
M WHEEL,DISC	1.00	743.00	00.00	Rx 743.00

Estimate

SURVEYOR NAME: Tan Jiah 97495749

SURVEYOR SIGNATURE: [Signature]

DATE: 14/3/18 @ 1726

REMARKS: Resurvey after repair. WP  
4-5 days sur @ lkk auto.

**LKK Auto Consultants hence notify the Repairer of the following:**

- To resurvey before/after spray painting

- Confirm & accepted by
- To display damaged part(s) during resurvey
  - Parts prices are subject to confirmation
  - Third party survey is on a "Without Prejudice" basis
  - No illegal modification(s) is allowed
  - Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

	Nett	5,083.00
7% GST on	5083.00	355.81
<b>Total Payable</b>		<b>5,438.81</b>

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.



Exceptional Journeys

Surveyor : Taufikh  
Company : LKK

VEHICLE NO : SLF2184R  
MODEL : MIT/17MY ATTRAGE 1.2 CVT  
WIP : 22731

Material	:	\$	-
Labour	:	\$	3,130.00
Sub-Total	:	\$	3,130.00
	:		
Less Excess	:	\$	-
Total	:	\$	3,130.00
GST 7%	:	\$	219.10
Grand Total	:	\$	3,349.10
Finalise By/Date	:		<u>JoJo dtd 11/07/2018</u>

Email :

REVERT BACK WITHIN 7 DAYS,  
OTHERWISE WILL PROCEED WITH INVOICING

SURVEYOR'S REPORT REQUIRED

REPAIR TOOK 5 WORKING DAYS + 2 Days ( 1 ) Weekends  
+        Days (        ) Public Holiday  
TOTAL DAYS REPAIR TOOK = 7


TP Claim 1ST CAPITAL - SLF2184R

Claim GIA / LTA fee       

Claim Loss  Use  Rental

Claim Medical Fee / Others       

Third Party Report



CYCLE &amp; CARRIAGE

**CYCLE & CARRIAGE AUTOMOTIVE PTE LIMITED  
PANDAN GARDENS CUSTOMER SERVICE CENTRE**

209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65691056

**PRO-FORMA INVOICE**

Co Reg No : 197701469G

**THIS IS NOT AN OFFICIAL TAX INVOICE**

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info
Lion City Rentals Pte Ltd	Cust No/Name /Lion City Rentals Pte Ltd
60 Anson Road	Reg No/Reg Date SLF2184R / 18/08/2016
#11-01 Mapletree Anson	Date In/Mileage 24/03/2018/ 79981
Singapore 079914	Chassis/Package MMBSTA13AHH001784
Contact No Mobile: 67420984	Engine No 3A92UDH3733
26/03/	Make/Model MIT/17MY ATTRAGE 1.2 CVT
	Colour/Trim W05 WHITE PEARL / BK BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No
CSM00041	Cash	11/07/2018/ 16:03	TLC	881 / Jojo Cheng	22731

Description of Goods / Services	Qty	Unit Price	Disc%	Amount
E PNT88000 REPAIR FRONT DOOR RH, REAR DOOR RH, SIDE SILL RH, REAR FENDER RH REAR BUMPER				✓1100.00
E PNT98000 RESPRAY FOR REAR BUMPER, REAR FENDER RH, REAR DOOR RH FRT DOOR RH, SIDE SILL RH				✓1890.00
B WHEELALIGNMENT To Conduct Computerize Full Wheel Alignment				✓120.00
M SUNDRY SUNDRY				✓20.00
Z TEXT FIRST CAPITAL TP CLAIM SHB4346X DOA: 08/03/18 SURVEYOR: TAUFIKH DTD 14/03/18				
<i>"Guarantee your warranty, maintain with Cycle &amp; Carriage."</i>				

Parts	0.00		Nett	3,130.00
Labour	3,110.00	7% GST on	3130.00	219.10
Standard Menu	0.00			
Specialist Job	0.00		<b>Total Payable</b>	<b>3,349.10</b>
Diagnostics Job	0.00			
Sundry/Others	20.00			
Total(w/o GST)	3,130.00			

This is not an official tax invoice.  
This is a computer generated document, no signature is required.

Work Order: R000168  
 License: SLF2184R  
 Technician: 108  
 Mileage: 84842  
 Date: 27.3.18 13:56

Mitsubishi : Mirage/Attrage : 2012- (Including G4)

Front : Left

Actual	Before	Specified Range
-0°48**	-0°48**	-0°40' 0°50'
3°45'	3°47'	3°15' 4°45'
0°02'	0°03'	-0°07' 0°07'
12°20'	12°22'	10°05' 13°05'
11°32'	11°34'	9°25' 13°55'

Camber  
 Caster  
 Toe  
 SAI  
 Included Angle  
 Turning Angle Diff.

Front : Right

Actual	Before	Specified Range
-0°33'	-0°32'	-0°40' 0°50'
4°24'	4°25'	3°15' 4°45'
0°02'	0°00'	-0°07' 0°07'
14°29**	14°05**	10°05' 13°05'
13°56**	13°32'	9°25' 13°55'

Front

Cross Camber  
 Cross Caster  
 Cross SAI  
 Total Toe  
 Cross Turn Diff.

Actual	Before	Specified Range
-0°15'	-0°16'	-0°30' 0°30'
-0°40**	-0°39**	-0°30' 0°30'
-2°08'	-1°42'	
0°04'	0°04'	-0°14' 0°14'

Rear : Left

Actual	Before	Specified Range
-0°50'	-0°51'	-1°45' -0°15'
0°06'	0°06'	-0°01' 0°13'

Camber  
 Toe

Rear : Right

Actual	Before	Specified Range
-1°00'	-1°00'	-1°45' -0°15'
0°14**	0°14**	-0°01' 0°13'

Rear

Cross Camber  
 Total Toe  
 Thrust Angle

Actual	Before	Specified Range
0°10'	0°09'	-0°30' 0°30'
0°20'	0°20'	-0°02' 0°26'
-0°04'	-0°04'	

\* This value is not within specification. Tire wear, handling and safety problems may result.



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
FIRST CAPITAL INSURANCE LTD		Ref : CS/FCI18004869/T1rd3n2	
36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877		Date : 19-09-2018	
		Code : FCI2	
1. Policy Particulars :- THIRD PARTY CLAIM			
Insured Veh.	SHB 4346X	Veh. Inspected	SLF 2184R
Policy No.	D-18088936MFSH	Coverage (\$)	0.00
Claim No.	D18001999MFSH	Excess (\$)	0.00
Assign From	KARENT	Assign Date	14/03/2018
2. Vehicle Particulars & Condition			
Make & Model	MITSUBISHI ATTRAGE	c.c	1193
Engine No.	HIDDEN	Year of Reg.	2016
Chassis No.	MMBSTA13AHH001784	Colour	WHITE
Odometer	-	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	GOOD		
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre	185/55 R15	ACHILLES	6 mm
L/H Front Tyre	185/55 R15	ACHILLES	6 mm
R/H Rear Tyre	185/55 R15	ACHILLES	6 mm
L/H Rear Tyre	185/55 R15	ACHILLES	6 mm
4. Description of Damages			
THE VEHICLE SUSTAINED DAMAGES AT THE O/S BODY. DAMAGES SEE DETAILS.			
5. General Information			
Accident Date	08/03/2018	Inspection Date	14/03/2018
Survey held at	CYCLE & CARRIAGE AUTOMOTIVE PTE LTD 209 PANDAN GARDENS SINGAPORE 609339		
5a. Remarks			
A)DAMAGES CONSISTENT TO ACCIDENT REPORT. B)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. C)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair			
ESTIMATED NORMAL PERIOD FOR REPAIR:		<b>5 Working Days</b>	



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

### ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLF 2184R

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<b>REPLACEMENT OF PARTS</b>			
1	WHEEL,DISC (SN)	TO REPAIR SEE LABOUR	743.00	-
1	SUNDRY (SN)	NECESSARY	20.00	20.00
			763.00	20.00
	<b>LABOUR</b>			
	TO REPAIR FRT DOOR RH,REAR DOOR RH,SIDE SILL RH,REAR FENDER RH,REAR BUMPER.INCLUSIVE OF THE REPAIR OF WHEEL,DISC.		1,650.00	1,100.00
	TO SPRAY PAINT FOR REAR BUMPER,REAR FENDER RH,REAR DOOR RH,FRT DOOR RH,SIDE SILL RH.		2,520.00	1,890.00
	TO CONDUCT COMPUTERIZE FULL WHEEL ALIGNMENT.		120.00	120.00
	TO TRANSFER RIM TO TYRE.	NOT NECESSARY	30.00	-
			4,320.00	3,110.00
	<b>GRAND TOTAL</b>		<b>5,083.00</b>	<b>3,130.00</b>
<b>RECOMMENDED COST OF REPAIRS</b>				<b>3,130.00</b>

Report Ref No. CS/FCI18004869/T1rd3n2

MOHAMAD TAUFIKH

M.MATAI, AMSAE-A

Automotive Assessor

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.