

ASS. REC. BY:

REF: CS/FCL18004887 / Uqbn2 Special Instruction:

Surveyor:

Marius

ASSIGNMENT (Office)

From Person:

CWS Sithara

of

FCL

Date/Time:

11/03/2018 5:24pm

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SJH 9353L

Insured:

SHC 772U

at Workshop m/s

Fastech Auto

Tel:

6744 5405

of

Blk 1 Kaki Bukit Ave 6 #01-46

Policy No:

Claim No:

D18002117MFSH

Sum Insured:

Excess:

Make of Veh:

D.O.A.

12/03/2018

(Client's Record)

CA / REV / REP. / REV 24 HRS 'Wp'

H.O.D. Endorsement:

Date/Time:

11/03/2018 5:40pm

Person Contacted:

Nancy

Vehicle IN/OUT

Date/Time

Action/Instruction (✓) Estimate

SJH 9353L - PCH / AXA 12003381 / AHCFI

DOA: 21/02/2012

SHC 772U - NA / TNC 16003192 / 14

DOA: 01/05/2016

19/13/18@5:44pm performed Sithara, we are pending estimate from repairer.

21/3/18@1:56pm revised to Sithara by email.

(08/11/13) wef

ASS. REC. BY: *Marius*

REF:

Hel

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: *SYH 9353C*

at Workshop m/s *PL*

of _____

Insured: *SHC 772U*

Policy No. _____

Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Bal. or Market Value: _____

IOAC Accident Report: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: *3* days Res.: Yes or No

Lum Sum: *191* % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____ Vehicle: IN / OUT

Veh No: *SYH 9353C* Yr Regn: *8, 08*

Type: *M. Car* / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or *4P*

Make: *Honda air wave* c.c. *1496*

Colour: *black* A/C: Insured / Std / NI / NA

Sp. Reading: *231706* T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: *61 / 1210056*

Gen. Cond: *Good* / Fair / Poor / Burnt

Steering: *In order* / Jammed / Leaked / Burnt or

Brake: *In order* / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: *195/65R15*

R: _____

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front: *6* mm Rear: *6* mm

R/Bal. *6* mm

L/Bal. *6* mm

D.O.A. *12/3/18* D.O.I. *14/3/18*

Survey held at _____

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

O/S Rear

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

4/02/18 *Under, rear door rear by* *hmc 6.07*

20/3/18 *confirm* *Final by 8900 with Alis.*

(red to 2280.30, 21/3/18)

no lump sum.

21/3/2018

RECEIVED 22 MAR 2018

Date/Time, File Pass to?

1) *21/3/18* *hmc*

Date/Time, File Return to?

2) _____

☐ : Preli. Report

☐ : Final Report

Days Of Repair: *3*

Resurvey No. of Trip: *1*

Add Fee: ☐ : Site Insp (\$ _____)

☐ : Interview (\$ _____)

☐ : Tech. Invs (\$ _____)

☐ : Weekend (\$ _____)

Survey Fee:

Transportation:

\$ + RS. \$

Photos

Others

TOTAL

Report Format :

Lump Sum / I.B.I. (\$) *900*

130

50

50

27

257



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
FIRST CAPITAL INSURANCE LTD		Ref : CS/FCI18004887/Uqb	
36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877		Date : 14-03-2018	
		Code : FCI2	
1. Policy Particulars :- THIRD PARTY CLAIM			
Insured Veh.	SHC 772U	Veh. Inspected	SJH 9353L
Policy No.		Coverage (\$)	0.00
Claim No.	D18002117MFSH	Excess (\$)	0.00
Assign From	CWS (SITHARA)	Assign Date	14/03/2018
2. Vehicle Particulars & Condition			
Make & Model		c.c	0
Engine No.	HIDDEN	Year of Reg.	
Chassis No.		Colour	
Odometer	-	Steering	
Brakes		Modification	
General			
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm
4. Description of Damages			
5. General Information			
Accident Date	12/03/2018	Inspection Date	14/03/2018
Survey held at	FASTECH AUTO PTE LTD 1 KAKI BUKIT AVENUE 6 #01-46/48/50 AUTOBAY SINGAPORE 417883		
5a. Remarks			
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			

MOTOR SURVEY ASSIGNMENT

Date	14-03-2018	Our Ref No. D18002117MFSH
Accident Date	12-03-2018	Claim Type. Third Party
Insured Vehicle	SHC0772U	Third Party Vehicle. SJH9353L
Survey Location	1 KAKI BUKIT AVENUE 6 #01-46/48/50AUTOBAY	
Contact Person.	NANCY LAM	
Contact No.	67465405/ 0	Fax No. 67458520
Survey Type	WITHOUT PREJUDICE: LIABILITY UNCLEAR:	
Appointed Surveyor	LKK AUTO CONSULTANTS PTE LTD	
Contact Person	NA	Fax No. 68416315
Contact Number.	NA	

FOR DIRECT SETTLEMENT

Please submit to us the Tax Invoice together with letter of claim for Rental OR Loss of use (based on NIMA Benchmark rates) together with your survey report.

THIRD PARTY SURVEY REQUEST

Cc : Workshop	FASTECH AUTO PTE LTD	Attention. NIL
Cc : TP Solicitor	NA	TP Solicitor Fax No. NA
Officer Incharge	SITHARA	

IMPORTANT NOTE

Kindly submit the survey report via CWS within 14 days for survey assignment and 7 days for re-inspection.
This is a computer generated letter, no signature required.

Shiau Chan (LKKAUTO)

From: Shiau Chan (LKKAUTO)
Sent: Wednesday, 21 March 2018 1:56 PM
To: 'Claim Workflow System'; assignments
Cc: SITHARA@MSFIRSTCAPITAL.COM.SG; SUR
Subject: RE: SURVEY ASSESSMENT - D18002117MFSH/1
Attachments: CSFCI18004887Uqb.pdf

Dear Sithara,

Enclosed herewith preliminary advice of SJH 9353L.

Best Regards,

Shiau Chan (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: siewsc@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Shiau Chan (LKKAUTO)
Sent: Monday, 19 March 2018 5:11 PM
To: 'Claim Workflow System' <cwsmotorclaims@msfirstcapital.com.sg>; assignments <assignments@lkkauto.com>
Cc: SITHARA@MSFIRSTCAPITAL.COM.SG; SUR <sur@lkkauto.com>
Subject: RE: SURVEY ASSESSMENT - D18002117MFSH/1

Dear Sithara,

Please be informed that we have inspected the vehicle SJH 9353L on 14/03/2018.

We are pending for estimate from repairer.

Best Regards,

Shiau Chan (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: siewsc@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Admin-D (LKKAUTO)
Sent: Wednesday, 14 March 2018 5:39 PM
To: 'Claim Workflow System' <cwsmotorclaims@msfirstcapital.com.sg>; assignments <assignments@lkkauto.com>
Cc: SITHARA@MSFIRSTCAPITAL.COM.SG; SUR <sur@lkkauto.com>
Subject: RE: SURVEY ASSESSMENT - D18002117MFSH/1

Dear Sir / Madam,

Thank you for the assignment.

Best Regards,

Catherine Chong | Admin

LKK Auto Consultants Pte Ltd

Phone: 6741-8434 | email: assignments@lkkauto.com | fax: 6256-4315



Auto
Consultants
Pte Ltd

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your Ref: D18002117MFSH

Date: 21 March 2018

Our Ref: CS/FCI18004887/Uqb

The Motor Claims Department
First Capital Insurance Ltd

Dear Sir/Madam,


INITIAL INSPECTION REPORT OF VEHICLE NO. SJH 9353L

Please be informed that we had conducted the inspection of the abovementioned vehicle on 14/03/2018 at the premises of M/s FASTECH AUTO, and have the following to report:-

Workshop Estimate Amount	: S\$ <u>3,180.30</u>
Revised Estimate Amount	: S\$ <u>900.00</u>
"Check" Items Amount	: S\$ <u>-</u>
Market Value	: S\$ <u>-</u>
LTA Reimbursement Value	: S\$ <u>-</u>
Nett Value	: S\$ <u>-</u>

Description of Damage:

The vehicle sustained damages at the o/s rear portion.



Yours faithfully

CHUA KANG SENG
Licensed Appraiser

Shiau Chan (LKKAUTO)

From: Shiau Chan (LKKAUTO)
Sent: Monday, 19 March 2018 5:11 PM
To: 'Claim Workflow System'; assignments
Cc: SITHARA@MSFIRSTCAPITAL.COM.SG; SUR
Subject: RE: SURVEY ASSESSMENT - D18002117MFSH/1

Dear Sithara,

Please be informed that we have inspected the vehicle SJH 9353L on 14/03/2018.

We are pending for estimate from repairer.

Best Regards,

Shiau Chan (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: siewsc@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Admin-D (LKKAUTO)
Sent: Wednesday, 14 March 2018 5:39 PM
To: 'Claim Workflow System' <cwsmotorclaims@msfirstcapital.com.sg>; assignments <assignments@lkkauto.com>
Cc: SITHARA@MSFIRSTCAPITAL.COM.SG; SUR <sur@lkkauto.com>
Subject: RE: SURVEY ASSESSMENT - D18002117MFSH/1

Dear Sir / Madam,

Thank you for the assignment.

Best Regards,

Catherine Chong | Admin

LKK Auto Consultants Pte Ltd

Phone: 6741-8434 | email: assignments@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Claim Workflow System [<mailto:cwsmotorclaims@msfirstcapital.com.sg>]
Sent: Wednesday, 14 March, 2018 5:24 PM
To: ASSIGNMENTS@LKKAUTO.COM
Cc: CWSMOTORCLAIMS@MSFIRSTCAPITAL.COM.SG; SITHARA@MSFIRSTCAPITAL.COM.SG
Subject: PRI: SURVEY ASSESSMENT - D18002117MFSH/1

Dear Sir/Mdm,

We refer to the above reference.

Please find attached the necessary documents for survey.

Kindly submit your report via CWS within the next 14 days.

Best Regards,

Admin Team

Claim Workflow System

Motor Claims Department

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Business
Owner ID:	4608L
Vehicle Details	
Vehicle No.:	SJH9353L
Vehicle to be Exported:	No
Intended De-registration Date:	14 Mar 2018
Vehicle Make:	HONDA
Vehicle Model:	AIRWAVE 1.5M A
Primary Colour:	Black
Manufacturing Year:	2008
Engine No.:	L15A5161914
Chassis No.:	GJ11210056
Maximum Power Output:	81.0 kW (108 bhp)
Open Market Value:	\$15,199.00
Original Registration Date:	28 Aug 2008
First Registration Date:	28 Aug 2008
Transfer Count:	2
Actual ARF Paid:	\$7,937.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	27 Aug 2018
PARF Rebate Amount:	\$3,968.00
Intended COE Rebate Details	
COE Expiry Date:	27 Aug 2018
COE Category:	A - Car (1600cc & below)
COE Period(Years):	10
QP Paid:	\$3,276.00
COE Rebate Amount:	\$663.00
Total Rebate Amount:	\$4,631.00

The information contained herein is correct as at 14 Mar 2018

OK

FASTECH AUTO PTE LTD

1 Kaki Bukit Ave 6 #01-48 Autobay

Singapore 417883

Tel No:67452063/67467158 Fax No:67458520

Not Authorized
date
14/3/18
P/P 900
3 day

VEH: SJH 9353L

QTY	PARTICULAR	AMOUNT
1PCS	REAR FENDER O/S	R \$1,120.30 X

TO CHECK WIRING	11 \$50.00
TO DISMENTLE & REFIX REVERSE SENSOR	11 \$50.00
TO CONDUCT WHEEL ALIGNMENT	11 \$80.00
LABOUR FOR PANEL BEATING REAR FENDER, REAR DOOR & REAR BUMPER ECTS	\$800.00 300
TO PUTTY & SPRAY PAINTING	\$1,080.00 600
TOTAL	\$3,180.30

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
FIRST CAPITAL INSURANCE LTD			Ref : CS/FCI18004887/Uqbn2	
36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877			Date : 26-03-2018	
			Code : FCI2	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SHC 772U	Veh. Inspected	SJH 9353L	
Policy No.		Coverage (\$)	0.00	
Claim No.	D18002117MFSH	Excess (\$)	0.00	
Assign From	SITHARA	Assign Date	14/03/2018	
2. Vehicle Particulars & Condition				
Make & Model	HONDA AIRWAVE (A)	c.c	1496	
Engine No.	HIDDEN	Year of Reg.	2008	
Chassis No.	GJ11210056	Colour	BLACK	
Odometer	231706	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	195/65 R15	YOKOHAMA	6 mm	
L/H Front Tyre	195/65 R15	YOKOHAMA	6 mm	
R/H Rear Tyre	195/65 R15	YOKOHAMA	6 mm	
L/H Rear Tyre	195/65 R15	YOKOHAMA	6 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE O/S REAR PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	12/03/2018	Inspection Date	14/03/2018	
Survey held at	FASTECH AUTO PTE LTD 1 KAKI BUKIT AVENUE 6 #01-46/48/50 AUTOBAY SINGAPORE 417883			
5a. Remarks				
A) DAMAGES CONSISTENT TO ACCIDENT REPORT. B) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. C) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		3 Working Days		

**LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SJH 9353L

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	REPLACEMENT OF PARTS			
	REAR FENDER O/S	TO REPAIR SEE LABOUR	1,120.30	-
			1,120.30	-
	LABOUR			
	TO CHECK WIIRNG.	NOT NECESSARY	50.00	-
	TO DISMENTLE & REFIX REVERSE SENSOR.	NOT NECESSARY	50.00	-
	TO CONDUCT WHEEL ALIGNMENT.	NOT NECESSARY	80.00	-
	LABOUR FOR PANEL BEATING REAR FENDER,REAR DOOR & REAR BUMPER CLIPS.		800.00	300.00
	TO PUTTY & SPRAY PAINTING.		1,080.00	600.00
			2,060.00	900.00
GRAND TOTAL			3,180.30	900.00
RECOMMENDED COST OF REPAIRS				900.00

Report Ref No. CS/FCI18004887/Uqbn2

CHUA KANG SENG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.