ISSEMP INS. CASE OWNER	51 76 4M cc 4 AXA 1800 489 K,	Kata 3 9- LKK IDAC:
Surveyor.	Cennelly DG!: ASSIGNMENT	Date/Time: LU13/18
Pre-assign / CCU Insured Vehicle No Name of Insured Insured Tel No. Excess Sec II :SS Is driver the owner	TRANSCAS SERVICES P(L) TRANSCAS SERVICES P(L) Policy No. HP: Make / Mode Place of Ace	FALL TOWNER WAS NO ALL
If NO, Driver Nat Driver Tel		ORT: VS / NO ; TP GIA REPORT: YBS / NO ility: % Final? Yes / No
5/8 400	<u>IM</u> → →	
INSRS: WSP: Tel: Liability: Bc(RMKS:	INSRS: WSP: Tel: Liability: RMKS: INSRS: WSP: Tel: Liability: RMKS:	INSRS: WSP: Tel: Liability: RMKS:
Date/Time	PROVING INC. X	STAGE DATE/PIC
789	40/-	Non-Reporting ltr (Lst):
748	2461114 F- (13 (1301130116231 (1643) P=4134)34	Non-Reporting ltr (2nd): Non-Reporting ltr (Final):
		Notification ltr (if non-pickup):
		Call Ot: 24 12-2-19
		After call itr to Ol. Documentation Check List: Hundler Typist
		Notification ltr (if non-pickup)
		After call litr to Oi
		Authorisation To Act
		Release Voucher:
		Final Repair Bill:
		Car Rental Invoice:
	Market 11/1 has a second	Towing Invoice
(2-2-19	SPOKEN W/ BEL. FOR THEIR LUD.	LTA/QIA: SK
- "		Medical Bill:
		PIR:
		Mandate/Reject Instruction:
		LOD
PRELIMINARY ADVICE	Date/Plant 2 In	Payment Breakdown Form:
RELEMENTE ADVICE	Date/Time: Sent By:	Post-Repair Photos:
FINALIZATION	Date/Time: Confirm with:	Others:
Repair Cost:	0.6	Confirm by:
FINAL SETTLEMENT	Date/Time: 23 - 3 - (4 Confirm with MAR(0	Email Call
Final Liability:	10-	Email Cutl
Repair Cost: GST	S\$ 2, 835.50 (Agree) / Assessed) BOLA S/N No. : 26	If NO or B 28, Ass. Lia:
Loss of Rental (LOR)	SS - I desail	OPENING DOOR
Loss of Use (LOU):	S5 S DO (S OO x 5 days)	
Loss of Income (LOI):	SS _ (S x days)	C 10 11 7 11 13 11
LOR only LOU only		1/11/2019
GIA/LTA Search	SS -	3141
Medical:	SS -	1) Claim status: Normal/Reject/Private Settle
Disbursement:	SS 3 33C (e.g. Tow/ Independent)	2) Report Format:
Legal Cost	SS 97775.30	3) Survey fee:
Total:	SS 2 , 335 - 50 Global Sum SS:	
FINAL PAYMENT	Date/Time: Confirm with:	Email Cail
0 mos 1	Ul-Sand Protocological Control of the Control of th	JOUR PLE LID
Pose 2 (Schelf NA)	S5	
Payes 3: Garles (FNA.)	15 Nemo 3: X	

ASSIGNMENT From: Date: Date: Structure Accounts Continued Cost: Date: Structure Accounts Cost:		
OD/TP/WS/TP/RES/OD RES/EVA/INV/INV To lasped Vehicle No: at Workshop m/s It workshop m/s	ennerh	ASSIGNMENT
OD/TP/WS/TP/RES/OD RES/EVA/INV/INV To lasped Vehicle No: at Workshop m/s It workshop m/s	From: Date:	Vah No. STO GOOLS 01
To inspect Vehicle No: at Workshop mis Insured:		Type: MCAV M Corle / Proc / Ven 14
To inspect Vehicle No: at Workshop m/s of Insured: Policy No. Ctaims No. Choicy No. (Close's Record) Make Tuy Priss Call Insured Istal INIII Somework I Proof I Burnt Seering: Insured! Jammed / Leaked / Burnt or Seering: Insured! Jammed / Leaked / Burnt or Seering: Insured! Jammed / Leaked / Burnt or Mod: NS of I Park In You All I Park I Poor I Burnt Seering: Insured! Jammed / Leaked / Burnt or Mod: NS of I Park In You All I Park I Poor I Burnt Seering: Insured! Jammed / Leaked / Burnt or Nod: NS of I park I Jammed / Leaked / Burnt or Nod: NS of I park I Jammed / Leaked / Burnt or Nod: NS of I park I Jammed / Leaked / Burnt or Nod: NS of I park I Jammed / Leaked / Burnt or Nod: NS of I park I Jammed / Leaked / Burnt or Nod: NS of I park I Jammed / Leaked / Burnt or Nod: NS of I park I Jammed / Leaked / Burnt or Nod: NS of I park I Jammed / Leaked / Burnt or Nod: NS of I park I Jammed / Leaked / Burnt or Nod: NS of I park I Jammed / Leaked / Burnt or Nod: NS of I park I Jammed / Leaked / Burnt or Nod: NS of I park I Jammed / Leaked / Burnt or Nod: NS of I park I Jammed / Leaked / Burnt or Nod: NS of I park I Jammed / Leaked / Burnt or Nod: NS of I park I Jammed / Leaked / Burnt or Nod: NS of I park I Jammed / Leaked / Burnt or Nod: NS of I park I Jammed / Leaked / Burnt or Nod: NS of I park I Jammed / Leaked / Burnt or Nod: NS of I park I Jammed / Leaked / Burnt or Nod: NS of I park I Jammed / Leaked / Burnt or NS of I park I Jammed / Leaked / Burnt or NS of I park I Jammed / Leaked / Burnt or NS of I park I Jammed / Leaked / Burnt or NS of I park I Jammed / Leaked / Burnt or NS of I park I Jammed / Leaked / Burnt or NS of I park I Jammed / Leaked / Burnt or NS of I park I Jammed / Leaked / Burnt or NS of I park I Jammed / Leaked / Burnt or NS of I park I Jammed / Leaked / Burnt or NS of I park I Jammed / Leaked / Burnt or NS of I park I Jammed / Leak	OD TTP IWS I TP RES I OD RES I EVA / INV I MV	Inick / Testing
col insured: Policy No. Chairs Record) Chairs Record Chairs Record) Chairs Record Chairs Record) Chairs Record Chairs		7 7
Insured: Insured: Insured: Insured: Insured: Policy No. Ctaims No.	at Workshop m/s	
EngNo: Claims No. Claims No. Sum insured: (Clion's Record) Make of Veh:	(41)	On Da Insured / Std / NI /
Claims No. Claims No. Claims No. Sum insured: (Client's Record) Make of Vets: Make of	Insured:	
Sum instured: Excess: (Client's Record) Make of Veh: (Client's Record) Make of Veh: (Pokey Condition) Remark: The veh had commenced its repair at the time of inspection. Bal. or Market Value: (DAC Accident Root: Consistent?: Yea or No GIA / PR Son: Consistent?: Yea or No Est. Repairs: Of days Res.: Yea or No CA / REV / REP. / 24 HRS Date: Person Contacted: Vehicle: IN / OUT Date / Time Action / Instruction J. J	Policy No.	
Sum insured: Excess: Seeing: InopeRF1 Jammed / Leaked / Burnt or Seeing: InopeRF1 Jammed / Leaked / Burnt or Modis of Veh: College Condition Condition Consistent? : Yes or No Set Consistent : Yes or	Claims No.	CNO: JTDKN3648011498
(Client's Record) Make of Veh: (Pokey Condition) Remark: The veh had commenced its repair at the time of inspection. Bal or Market Value: IDAC Accident Rport: Consistent?: Yes or No Est. Repairs: IO 4 days Res.: Yes or No CA I REV / REP. / 24 HRS Date: Person Contacted: Person No. of Trip: Survey Fee: Transportation: Transporta	Characteristics	Gen. Cond: Good'/ Fair / Poor / Burnt
Brake: Inoder / Jammed / Leaked / Burnt or Mod: NII British / STD ARIM or Tyre Size: F: / Jamkeek 205 60R / 5	LACESS.	Steering: Inopdef / Jammed / Leaked / Burnt or
Modi: NII SRTim STD ARRIM or Tyre Size: F. Clanked: 205 60R 5 R. Applio Bs DUN EXNOVA GY FS LIZA MIC OHTSU PIR SUM! TOYO YOKO or TOYO YOKO TOYO YOKO or TOYO YOKO TOYO YOKO or TOYO YOKO YO	THE SECTION OF THE SE	Brake: Inorder / Jammed / Leaked / Burnt or
Particular Par	1 130	Modi: NII / S/RIm / STD A/RIm or
Remark: The veh had commenced its repair at the time of inspection. Ball or Market Value: IDAC Accident Rport: Consistent?: Yes or No GIA / PR Seen: Consistent?: Yes or No Est. Repairs: Consistent?: Yes or No Lum Sum: 20 % 3 Val.: Yes or No CA / REV / REP. / 24 HRS Date: Person Contincted: Vehicle: IN / OUT Date / Time Action / Instruction John Summary Results of Survey heid et and Survey heid		Tyre Size: F: Hankest 205/1-2-
repair at the time of inspection. Ball or Market Value: IDAC Accident Rport: Consistent?: Yes or No GIA / PR Seen: Consistent?: Yes or No Lum Sum: Dots CA / REV / REP, / 24 HRS Date: Person Contacted: Vehicle: IN / OUT Date / Time Action / Instruction // S / S / S / S / S / S / S / S / S /		R. Apalla
Bal or Market Value: IDAC Accident Roort: Consistent?: Yes or No GIA / PR Seen: Consistent?: Yes or No Est. Repairs: J days Res.: Yes or No Lum Sum: J O		
Bat or Market Value: IDAC Accident Roort: Consistent?: Yes or No GIA / PR Seen: Consistent?: Yes or No Est. Repairs: Of days Res.: Yes or No Lum Sum: 20 % 3 Val.: Yes or No CA / REV / REP. / 24 HRS Date: Person Conlocted: Vehicle: IN / OUT Date / Time Action / Instruction / S / S / S / S / S / S / S / S / S /	W 25004	TOYO / YOKO or
IDAC Accident Roort: Consistent?: Yes or No GIA / PR Seen: Consistent?: Yes or No Est. Repairs:	Bal. or Market Value:	
GIA / PR Seen: Consistent?: Yes or No Est. Repairs: O days Res.: Yes or No Lum Sum: 20 % 3 Val.: Yes or No CA / REV / REP. / 24 HRS Date: Person Contacted: Vehicle: IN / OUT Date / Time Action / Instruction // S / S / S / S / S / S / S / S / S /	IDAC Accident Rport: Consistent? : Yes or No	
Est. Repairs:	GIA / PR Seen: Consistent?: Yes or No	mm R/8al. 5 mm
Lum Sum: 20 % 3 Val.: Yes or No CA / REV / REP. / 24 HRS Date: Person Contacted: Vehicle: IN / OUT Date / Time Action / Instruction IS / 3 File Pass 76 Catherine O'Ly 8 2 (5 or) Prell. Report Days Of Repair: Resurvey No. of Trip: Survey held at Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or ALS / A Body The U/C / Chassis frame / Body Structure affected due to collision. S / 3 File Pass 76 Catherine O'Ly 8 2 (5 or) Prell. Report Days Of Repair:	Est. Repairs: 0 9 days Res.: Yes or No.	mm USal Z
Date: Person Contacted: Vehicle: IN / OUT Date / Time Action / Instruction Action / Instruction The U/C / Chassis frame / Body Structure affected due to collision. 15 / 3 File Past to Catherine		
Date: Person Contacted: Vehicle: IN / OUT Date / Time Action / Instruction The U/C / Chassis frame / Body Structure affected due to collision. 15 / 3 File Pass / 7 Catherine	CA / REV / REP. / 24 HRS	
Date / Time Action / Instruction The U/C / Chassis frame / Body Structure affected due to collision. 15 3 File Pass 76 Carthorice	Vohleler 111 (or	UT A/S THE REST TOIS I NIS I UIC I Rooftop or
#Trno, File Pass to? Prell. Report Days Of Repair:		The U/C / Chassis frame / Body Structure of
#Time, File Pass to? Prell. Report Days Of Repair: Final Report Resurvey No. of Trip: Survey Fee: Transportation: Transportation: Interview (\$) Photos Photos Tech Invs (\$) Others	nesott/ Hisbuction	anected due to collision.
Days Of Repair: Final Report Days Of Repair: Survey Fee: Transportation.	118 Pass to Cotherine	
Prell. Report Days Of Repair:	212 866301	
Prell. Report Days Of Repair:		
Prell. Report Days Of Repair:		
Prell. Report Days Of Repair:		
Prell. Report Days Of Repair:		
Prell. Report Days Of Repair:		PCX (A)
Prell. Report Days Of Repair:		~ (\$ 1,135.34 30° i)
: Final Report Resurvey No. of Trip: Survey Fee: Transportation: Add Fee: Interview (\$) Photos Transportation: Transp	: Prell. Report	Days Of Repair
Add Fee: : Site Insp (\$)S - RSSI Dort Format : Interview (\$) Photos Transportation: Interview (\$) Photos Tech Invs (\$) Others	: Final Report	Danuary M. American I.
Add Fee: :Site Insp (\$)S - RSSI Dort Format: :Interview (\$) Photos Tech Invs (\$) Others	Time, File Return to?	
port Format : Interview (\$) Photos Tech Invs (\$) Others	Add Fee	1 Charles /c
np Sum / I.B.I: (S) Others		
np sum / I.B.I: /S	ort Format :	// 1003
Weekend (\$	4	Tech Invs (\$) Ober
	p Sum / I.B.I: (S	The state of the s

辉陽汽車有限公司

HUI YANG MOTOR PTE. LTD.

Contact Add: SIN MING AUTOCARE Blk 176 Sin Ming Drive #04-02 Singapore 575721

Tel: 64515752 (2 Lines) . Fax: 64514658 Reg No. 201629438M

13/03/2018

Owner:

HYMS CAR LEASING PTE LTD

Not Norhanke CIRM 826501 Renny After Paint 4 days

ESTIMATE TO REPAIR TOYOTA PRIUS HYBRID 1.8A - SJQ4001M

lpe	front LH fender	By S	591.60
1pc	front LH fender "HYBRID" emblem	nu s	61.75
1pc	front LH door	B1 8	972.45
1pc	front LH door moulding	Adlson S	181.75
lpc	front LH door glass	ars	381.75 —
1pc	front LH side mirror	Bro S	581.85 —
1pc	front LH side mirror cover	1118	182.85

	\$ 2,954.00
less 25%	\$ 738.50
	\$ 2,215.50

remove & refit front LH door glass	\$ 60.00
wiring	\$ 50.00 201
tuffkote	\$ 60.00
spray painting	\$ 700.00 5001
labour charges	\$ 700.00 8801
Total	\$ 3,785.50



LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey beforefather spray pointing:
- To display damages points) during resurvey.
- Parts prices any subject to continuation.
- . Third party survey of one in Victoria Projection Bends
- No librari modificazioni pro presenti
- Supplementary through more the insurveyed and
 is subject to foul approve that insurveyed Company

Addition religious by Reporter

Signature

Date

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933
Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To:

AXA Insurance Pte Ltd 8 Shenton Way #24-01

AXA Tower Singapore 068811

From: LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park Singapore 408933

Attn:

Ernest Tay

Date:

16 Mar 2018

Preliminary Advice

Insured Vehicle No : SHD124K

TP Vehicle No

: SJQ4001M

Accident Date

13/03/2018

Make

: TOYOTA PRIUS

Assignment Date

: 14/03/2018

Date of Inspection : 14/03/2018

Est. Duration of Repair

4 days

Inspection At

: Hui Yang Motor Pte Ltd (HQ)

176 Sin Ming Drive #04-02, Sin Ming AutoCare

Singapore 575721

Point of Impact / General Description of Damages

The vehicle sustained impact / damages ... N/S front and body.... portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	3,785.50
Revised Amount	:S\$	2,650.00
Check Items (Estimated)	:S\$	0.00
Total	:S\$	2,650.00
Lump Sum Repair	:8\$	2,650.00

Total Loss Consideration

New for Old Value	S\$
Pre-Accident Value	:S\$
COE / PARF Rebate	:S\$
Salvage Value	:S\$
Margin for Repair	S\$

Remarks

()	The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage.
17.		Kindly let us have your authorisation.

The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.

(X) Other comments: We have not authorized repairs.

Print Received Message

This mail is associated with:

*SJQ4001M (C0472387) [SHD124K]

TP

HYMS CAR LEASING PTE LTD Mar 13 2018 9:00AM [TRANS-CAB SERVICES PTE LTD] Hui Yang Motor Pte Ltd

From

AXA Insurance Pte Ltd (HQ) (AXA_SG), sent on 16/03/2019 16:09 PM.

To Subject

LKK_HQ

Alert - Adj Mandate Approved (S\$3335.00) - SJQ4001M - Claim Handler: Khor Saw Theng

Approved:3335.00.		



51 UBI AVE 1, 902-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408935 TEL.; (065) 62563561 FAX; (065) 62564515

Immediate Advice

To: AXA Insurance Pte Ltd

Date: 15/3/2019

Survey Details:

Date of loss	13-Mar-18	
Date of appointment	14-Mar-18	
Date of survey	14-Mar-18	
Location of survey	HUI YANG	

Vehicle Details:

Claim Type:	THIRD PARTY CLAIM	
Vehicle number	SJQ 4001M	
Make and Model	TOYOTA PRIUS 1798CC	
Date of registration	1-Jan-11	
Excess		
Market Value	\$	- 4
Parf Rebate	\$	
Nett Loss	\$ -	

Repair details:

Initial Estimate	3.785.50

Proposed/Revised repair cost:

Parts	\$	2,215.50
Check items (estimate)	\$	-
Labour	\$	1,120.00
Total	5	3,335.50
Lump Sum(if applicable)	\$	2,650.00

Number of days for repair	4 days	
---------------------------	--------	--



51 UHLAVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 469933 TEL.; (965) 62563561 FAX; (965) 62564315

Remarks:

OPENING DOOR	

Mandate:

Liability(TP)	100%]	
Proposed repair cost	\$ 2,835.00		
Loss of Use	\$ 500.00	\$100 x Sdays	
Proposed Total	\$ 3,335.00		

View Received Message

This mail is associated with:

*53Q4001M (C0472387) [SHD124K]

HYMS CAR LEASING PTE LTD
Mar 13 2018 9:00AM
[TRANS-CAB SERVICES PTE LTD]
Hui Yang Motor Pte Ltd

Reply Reply All Mark as Unread Print Message Delete Message Forward

From AXA Insurance Pte Ltd (HQ) (AXA_SG), sent on 16/05/2019 22:41 PM.

To LXK_HQ
Subject Alert - Adj Mandate Approved (S\$3335.50) - SJQ4001M - Claim Handler: Khor Saw Theng

Approved: 3335.50:You may proceed with your proposed mandate if it is confirm the COR is within net loss repair limit.

DOCUMENTS SUMMARY

There are no documents.

辉陽汽車有限公司 HUI YANG MOTOR PTE. LTD.

Contact Add: SIN MING AUTOCARE Blk 176 Sin Ming Drive #04-02 Singapore 575721 Tel: 64515752 (2 Lines) - Fax: 64514658 Reg No. 201629438M

Date: 02/04/2018

AXA Insurance Singapore Pte Ltd Motor Claims Department 8 Shenton Way #27-01 AXA Tower Singapore 068811

RE: ACCIDENT INVOLVING SJQ4001M & SHD124K ON 13/03/2018 ALONG MARINA ONE EAST TOWER DROP OFF POINT

SETTLEMENT OF OUR CLAIM FOR SJQ4001M

Lump sum repair cost as recommended by surveyor (TP0325)	S	2,835.50
05 days Loss of Use @ \$100.00 per day	S	500.00
(4 repair days + 1 Sunday)		
Total	8	3,335.50

*The above claim applies only to vehicle damage and expressly exclude all personal injuries and other consequential loss.

Please let us have your reply soonest possible, thank you.

Best Regards, Marco Neo HUI YANG MOTOR PTE LTD DID: 64515752

Fax: 64514658

email: hui_yang_motor@hotmail.com

Joy Irene (LKKAuto)

From:

Joy Irene (LKKAuto)

Sent:

Tuesday, 12 February 2019 1:34 PM

To:

'claims@transcab.com.sg'

Cc:

'carrisalee@ava-ins.com'; 'icewong@ava-ins.com'; 'ireneng@ava-ins.com';

'foonghon@ava-ins.com'; Admin A

Subject:

ACCIDENT INVOLVING SHD 124K & SJQ 4001M ALONG MARINA ONE EAST

TOWER ON 13/03/2018

Transcab Taxi

Singapore

Dear Sir/Madam,

OUR REF : CC4/AXA18004895/Kja3 YOUR REF : P1680520 (SHD 124K)

ACCIDENT INVOLVING SHD 124K & SJQ 4001M ALONG MARINA ONE EAST TOWER ON 13/03/2018

We refer to the above subject matter. We write to inform you that we are the loss adjuster appointed by your motor insurer, AXA Insurance Pte Ltd to deal with the third party claim against your policy.

We have received a claim from M/s HUI YANG MOTOR PTE LTD acting on behalf of the owner of SJQ 4001M against your motor insurance policy.

Based on the accident reports, your taxi had hit Third Party whilst opening your taxi's door. We will therefore proceed to negotiate for an amicable settlement with the Third Party.

We also wish to advise that there is an excess of <u>\$\$5,000.00</u> attached with Third Party Claims. Please be informed that you shall be liable for the excess following any settlement of the third party claim.

AXA shall keep you informed of the third party claim settlement and thereafter kindly let AXA have the excess payment in your cheque payable to "AXA Insurance Pte Ltd". Please indicate your vehicle registration number and the date of accident on the back of the cheque.

Notwithstanding the excess being applied and/or received by AXA for the above subject matter, AXA expressly reserves all their rights under the policy to refund the excess payment in the event that there arises any known policy breach and or exclusion material to coverage.

We shall proceed to deal with the claim(s) subject to the merits of the case and according to the rights afforded under the policy. Should you not be seeking the protection of your policy and seek to take conduct of third party claim(s) arising from this incident, at your own cost and defence, please reply to us within 10 days from the date of this letter. Your intent must be formally expressed to us and acknowledged by AXA.

Your full co-operation in the handling of the claim is required and kindly submit the following if not provided at our reporting centre. The list below is not all inclusive and further document may be required:

- Police report, Police Investigation result, appeal against the Traffic Police offence and status (if any)
- · Driver's driving license or foreign driving license (if any)
- · Coloured photographs of accident scene (if any)
- Coloured photographs of damage to all vehicles involved (If any)
- · Video footage of accident (if any)
- Statement and/or police report from independent witness(es) (if any)
- If you or your passenger(s) are filing a claim against any of the involved Third Party(s), you are to keep us informed of your legal representative(s) and the status of the claim.

To protect your interest(s) in the handling of this claim, please do not discuss liability with any of the Third Party(s) and/or their legal representatives, or make any compromise or settlement without our prior knowledge and consent. If you receive any correspondence or legal document such as a Writ of Summons in connection with this accident, please forward it to us immediately. You may email it to cst@axa.com.sg/joyirene@lkkauto.com or deliver it by hand to our Customer Care Centre.

This letter should **not** be regarded as a waiver by AXA of their rights to repudiate any claim because of any breach of policy terms and conditions you and/or your authorized driver may have committed.

In the event of receiving and handling of any third party injury claim(s), we shall keep you informed of the final indemnity upon conclusion of the matter(s).

If you need any clarification, please do not hesitate to contact our Claims Service Team at 1800-880 4888 at our operating hours 9:00am to 5:30pm (press 1 for GI and option 3 for claims) or cst@axa.com.sg / joyirene@lkkauto.com. Please quote our claim reference when you contact us that we can assist you more effectively.

Thank you.

Best Regards,
Joy Irene | Case Handler
LKK Auto Consultants Pte Ltd
DID: 6841-2409 | email: joyirene@lkkauto.com| Fax: 6741-4108
Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

All contents of this email is intended strictly for the addressee(s) only. It may contain confidential and/or privileged information. If you are not the intended recipient (or have received this email in error) please notify the sender immediately and destroy this email. Any unauthorized copying, disclosure or distribution of the material in this email is strictly forbidden.


AUTHORIZATION LETTER

TO WHOM IT MAY CONCERN

I/We, HYMS Car Leasing 94e Hd hereby d	eclare and agree to use the
address of Hui Yang Motor Pte Ltd, that is at Blk 176 Sin M	ing Drive, #04-02 Sin Ming
Autocare Singapore 575721 in all my/our correspondences with	any party in connection with
my/our claim arising from an accident involving my/our motor SJQ+00 \ M and other vehicles registration number	
Marina One Bast Tower prop off point	on 13-03-2018

I/We, further grant authority to Messrs Hui Yang Motor Pte Ltd or any of their representatives to open all my/our letters and to negotiate my/our claim on my/our behalf.

I/We wish to inform you that you could issue the cheque payment in favour of my/our repairer Messrs Hui Yang Motor Pte Ltd.



Signature of registered owner and/or Company's stamp



AXA THIRD PARTY DIRECT SETTLEMENT

ehicle No:	SHD 124K (In	sd veh)	Model: TOYOTA PR	ius
	SJQ 4001M (TI	veh)	1	
Pate of Accident/ Time:	13/03/18 09:45		1	
tepair Estimate		: 5	3,785.50	
inal Repair Cost		: \$	2,835.50	1
oss of Use		:5	500.00	5 days at \$ 100 per day
ental (if any)		:5	25.18777	days at \$ per day
TA / GIA Search Fee		:5		
Others:		:5		7
inal Settlement Sum		:5	3,335.50	
ayee Name: HUI YANG	MOTOR PTE LTD	-		
Third Party Workshop GIA	Registered? [] YES	IVI I	NO (Kindly indicate be	low)
For Non Gi	A Registered Workshop:		Agreed Liability 190	(%)
) For GIA Reg	istered Workshop:	-	BOLA Applicable: Yes/ No	BOLA Scenario No:
BOLA Liabil	ty:(%)		Assessed Liability (*):	(%)
* Assessed	Liability to be filled only for chai	n collision:	s and for cases where BO	LA does not apply.
emarks:				
OTE:				
1. PLEASE EXPRESSLY	RESERVE YOUR CLIENT'S RIGHT	IE SO PE	OLIDED IN THIS SETTIEN	ENT DOCUMENT
at the second contraction				AS AN ADMISSION OF LIABILIT

AXA RESERVES THEIR RIGHTS UNDER THE POLICY TERMS & CONDITIONS AS WELL AS THEIR RIGHTS IN LAW.

Only applicable to rental claim - All document are to be submitted with this settlement confirmation. In the event, rental agreement / Involces are not received within 7 days of this signed confirmation, we will automatically revert to loss of use claim per the NIMA rates.

We/I confirmed that this is a full and final settlement that we and or our client have/had/has against you (AXA and their policyholder/authorised driver/tortfeasor) for any and all losses (past/present/future) arising from this accident.

We confirmed that we have the authority of our client to act for and on their behalf in this accident. 1200 3 Signature of workshop representative / Workshop stamp
Name of Representative: Signature of Witness / Workshop stamp (if applicable) Name of Witness: &/
Date: 08 /05/19 00/05/19 Date:

Signature of AXA's surveyor/representative: Name of AXA's surveyor /Representative:

Date: 08/05/19

HUI YANG MOTOR PTE LTD

Bill To:

TAX INVOICE

TP Claim Invoice No:

TP0325

Bill Date: 02/04/2018

Motor Claims Department

AXA Insurance Singapore Pte Ltd

8 Shenton Way #27-01 AXA Tower Singapore 068811

Description	An	nount
Date of Accident: 13/03/2018 Owner: HYMS CAR LEASING PTE LTD Vehicle No: SJQ4001M Make & Model: TOYOTA PRIUS 1.8A Lump Sum repair cost as recommended by surveyor	s	2,650.00
Sub-Total : Add 7% GST : Total Amount SGD :	\$ \$ \$	2,650.00 185.50 2,835.50

Reg No.:201629438M GST No:201629438M

HUI YANG MOTOR PTE LTD

Authorised Signature

Hui Yang Motor Pte Ltd

Sin Ming Autocare Blk 176 Sin Ming Drive

#04-02 Singapore 575721

Email: hui_yang_motor@hotmail.com

H/P: 98625891 Office: 64515752 Fax: 64514658

...CLAIM SUBFOLDER...(Pending for Survey Report)

	OLDER TRA	The state of the s	Parama moreomia	Experience	Terret	ett de contae in d	Proper and addressed	Canada
	Notified 13 Mar 2018	Est Submitted	Adj Assigned 14 Mar 2018 09:25 Edit Adj Rpt	S\$2,650.00 Edit Estima	5\$2	Submitted 2,650.00 lew Rpt	Ins Auth'ed	Pending for Surve Report Cancel Case
	tain	R	eference	Clair	n Details		Documents	Show /
CLAIM SUE	FOLDER DE	TAILS		***************************************		[Created	by insurer]	
Insured:	TRANS-C	AB SERVICES PT	ELTD, Co. Reg. N	o.: 200303878	K			
Main Claimant:	HYMS CA	R LEASING PTE	LTD, Co. Reg. No.	: 201320561K				
Vehicle Reg. No.:	SJQ400	1M		De	ite of Loss:		3 09:00 - :59 and 16 Days From L	TA Reg Date (Man Y
Claim Type:	TP / C04	72387		100	licy/Cover ite No.:	P1680520 ((Third Party Only)	
Vehicle Reg. No. (Insured):	SHD124K				licy No. laimant):	508257800	0-01	
Torrison and American				Ex	cess:	5\$5,000.00		
Repairer:	Hui Yang	Motor Pte Ltd (F	1Q) 176 Sin Ming D	rive #04-02, S	in Ming Aut	oCare, 57572	1 Sin Ming - Tel: 645	15752
Handling Insurer:	AXA Insu	rance Pte Ltd (H	Q) - Tel: 6338 728	[Handled I	y Khor Sa	w Theng - 5	880 4754)	
Claimant's Insurer:	NTUC Inc	ome Insurance	Co-operative Ltd (HQ) - Tel:				
Adjuster:	LKK Auto	Consultants Pte	Ltd (HQ) - Tel: 62	56-3561 [H	andled by P	CENNETH KO	NG] [Final Rpt	due 23/03/2018
ASSOCIAT	ED MAIL RE	CEIVED					View A	Compose Case
AXA_SG AXA_SG AXA_SG	(16/03/2019) (20/12/2018) (14/03/2018)	: Alert - Adj Mar : C0472387 STA : WP / New TP /	date Approved (S	\$3335.00) - : 2387/P1680	53Q4001M 520	- Claim Han	dier: Khor Saw Th. dier: Khor Saw Th. search Tasks Creat	

Claim Documents

*SJQ4001M (C0472387)
[SHD124K]
TP
HYMS CAR LEASING PTE LTD
Mar 13 2018 9:00AM
[TRANS-CAB SERVICES PTE LTD]
Hul Yang Motor Pte Ltd

Up	oload Documents U	pload Photos Compose New Letter Upload Video Upload Audio	View	View in Brow	ser v
Let	ters/Corresponder	nces	1 per	page 💟	V
Nσ	Finalized On	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Prin
1	(Draft)	Third Party Express Settlement - Payment Breakdown	0	Edit	
Ass	essment Reports		1 per i	page V	V
No	Finalized On	AXA Insurance Pte Ltd (HQ)		Thumbnail	Print
1	14/03/18 09:26	Accident Statement From:SC - Reg. No: SHD124K, Claimant: TRANS-CAB SERVICES FTE LTD	0	Load HTM	
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Prin
1	16/03/18 11:41	Adjuster Immediate Advice	0	Load HTM	
nh.					
	otos/Images		3 per s		~
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	
1	12/02/19 13:28	General View	0	Load JPG	V
2	12/02/19 13:28	General View	0	Load JPG	V
3	12/02/19 13:28	General View	0	Load JPG	W
4	12/02/19 13:28	General View	0	Load JPG	V
5	12/02/19 13:28	General View	0	Load JPG	V
6	12/02/19 13:28	General View	0	Load JPG	S
7	12/02/19 13:28	General View	0	Load JPG	V
8	12/02/19 13:28	General View	0	Load JPG	V
9	12/02/19 13:28	General View	0	Load JPG	V
10	12/02/19 13:28	General View	0	Load JPG	V
11	12/02/19 13:28	General View	0	Load JPG	V
12	12/02/19 13:28	General View	0	Load JPG	V
13	12/02/19 13:28	General View	0	Load JPG	[2]
14	12/02/19 13:28	General View	0	Load 3PG	V
		<u></u>			
Doc	umentation	The first and the state of the	1 per p	age 🗸	<u>S</u>
No	Finalized On	AXA Insurance Pte Ltd (HQ)		Thumbnail	Print
1	13/03/18 14:09	EMAIL	0	Load PDF	
2	13/03/18 14:09	53Q4001M TP GIA REPORT	0	Load PDF	40.1.4
No 1	Relabel/Reorder 19/03/18 11:01	LKK Auto Consultants Pte Ltd (HQ) TP ESTIMATE - MARKED	0	Load PDF	Print
2	26/09/18 14:30	OI GIA REPORT	ŏ	Load PDF	
3	16/03/19 13:41	MANDATE IA	ő	Load PDF	
4	03/04/19 09:25	MANDATE IA - AMENDED	ŏ	Load PDF	
5	23/05/19 10:26	WORKSHOP INVOICE	ő	Load PDF	
5	23/05/19 10:26	AUTHORISATION TO ACT FORM	ŏ	Load PDF	
7	23/05/19 10:26	DS FORM	ŏ	Load PDF	
В	23/05/19 10:26	LETTER TO 01	0	Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST	Reset Save Print
There are no document checklists configured.	
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)	
	^
	Ų.
Show Remarks To: Handling Insurer Note: Remarks are private unless you show it to other parties.	

NOTE: TO BE COMPLETED BY SURVEYOR

TEAM		
IHAM		

THIRD PARTY EXPRESS SETTLEMENT (PAYMENT BREAKDOWN)

Vehicle No:	SHD124K (Insd veh)				Model:			TOYOTA PRIUS 1.8 (A)	
	SJQ4001M (TP veh)								
Date of Accident:	of Accident: 13/03/2018								
Global Sum Settler	ent [] Yes		[X] No				
Repair Estimate			: \$		4,05	60.49			
Final Repair Cost			: \$		2,8	835.50			
Loss of Use			: \$	500.00			5.00 days at \$100.00 per day		
Rental (if any)			: \$	0.00			days		
LTA / GIA Search F	ee		: \$			0.00			
Others:			: \$			0.00			
			: \$						
Final Settlement Su	m		: \$		3,3	335.50			
Is Third Party World below)	kshop GIA	Registered	?	[]	YE	s [X]	NO	(Kindly indicate
A) For Non GIA R	egistered V	Vorkshop:		Α	greed L	iability		100	(%)
8 /	BOLA Liability: (%)				_				BOLA Scenario No:
* Assessed Lia	bility to be fi	lled only for	chain						OLA does not apply.
Remarks									
Payment Instruction	n: Payee's	Breakdown	1						
1) Hui Yang Moto	r Pte Ltd					\$			3,335.50
2)					:	s			
JOANNE I	EE KHANG	MIN		1	23 May 2019				
LKK Auto C	onsultants F	Pte Ltd		-	Date				

Please attach all the supporting documents to the form. (Final Repair Bill; Rental Invoice; Release Voucher; Authorisation to Act; Survey Report; Medical Report/ Bill (if any)

LKK Auto Consultants Pte Ltd (Co. Reg. No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No:

CC4/AXA18004895/KJA3Q2

Date:

23/05/2019

REFERENCE

Handling Insurer: AXA Insurance Pte Ltd

Policy No:

P1680520

Claimant Vehicle No :

SJQ4001M

Insured Vehicle No:

SHD124K

Date of Loss:

13/03/2018

Nature of Claim:

TP

Claim No:

C0472387

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:

SJQ4001M

Make & Model:

TOYOTA PRIUS, 1.8 (A)

Engine No:

2ZRR097882

Reg. Date: Colour: 25/01/2011 (Man. Year: 2010) Metallic Red Chassis No: Odometer: JTDKN36U801149823 228706 km

Engine Capacity:

Metallic Red

1798 cc

Market Value/New Car Price: N/A Sum Insured (S\$): Mar

Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:

Steering (Serviceable):

Yes Footbrake (Serviceable):

Yes

Handbrake (Serviceable):

Yes Engine Modification:

No Pre-accident Condition:

10

CONDITION OF TYRES

Front Tyre Size:

205/60 R15

Rear Tyre Size:

205/60 R15

Front Left Side: Front Right Side: Hankook 3 mm Hankook 3 mm Rear Left Side: Rear Right Side: APOLLO 4 mm APOLLO 4 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS		Repairer's	Adjuster's	Difference	Diff %
Parts		2,215.50	2,215.50	0.00	0.00
Miscellaneous Items		0.00	0.00	0.00	
Labour		1,570.00	1,120.00	450.00	28.66
Paintwork Labour		0.00	0.00	0.00	
Towing		0.00 0.00 0.00 s Total (S\$) 3,785.50 3,335.50 450.00			
	Calculated Gross Total (S\$)	3,785.50	3,335.50	450.00	11.89
A	approved Total (Overridden) (S\$)		2,650.00		
	(S\$)	3,785.50	2,650.00	1,135.50	30.00
	+ GST 7.00/7.00% (S\$)	264.99	185.50	79.49	30.00
	Nett Amount (S\$)	4,050.49	2,835.50	1,214.99	30.00
	+ Loss of Use (5.0 x S\$1	00.00/day) (S\$)	500.00		

Nett Liability (S\$)

INSPECTION

Date of Assignment:

14/03/2018

Date Inspected:

14/03/2018 Inspected At:

Hui Yang Motor Pte Ltd (HQ)

176 Sin Ming Drive #04-02, Sin Ming

AutoCare

Singapore 575721

3,335.50

Adjuster Report Page 2 of 4

Estimated Period of Repair: 4.0 days

Adjuster: KENNETH KONG Manager: Joy Irene Bascao

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

Adjuster Report Page 3 of 4

REPAIR DETAILS

Referen	ce	
Part Source	: MRM-SG	Version: 1.0 (Last Synchronised: 21 May 2019)
Parts:	144	TOYOTA PRIUS 1.8 (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted,	no print-code for SJQ4001M)
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info	Items/values n	ot in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No. Particulars	Condition	Repairer's	Amount
1	1	*FRONT LH FENDER (CONSISTENT)	Bent	591,60 FL	*591.60 FL
2	1	*FRONT LH FENDER HYBRID EMBLEM (CONSISTENT)	Dented	61.75FL	*61.75 FL
3	1	*FRONT LH DOOR (CONSISTENT)	Bent	972.45 FL	*972.45FL
4	1	*FRONT LH DOOR MOULDING (CONSISTENT)	Dented / Scratched	181.75 FL	*181.75FL
5	1	*FRONT LH DOOR GLASS (CONSISTENT)	Cut	381.75 FL	*381.75 FL
6	1	*FRONT LH SIDE MIRROR (CONSISTENT)	Broken	581.85 FL	*581.85 FL
7	1	*FRONT LH SIDE MIRROR COVER (CONSISTENT)	Missing	182.85 FL	*182.85 FL
F=Fre	nchise	part. L=ListflemDisc.			CANCELL PROTECTION
			Sub Total (S\$)	2,954.00	2,954.00
		- List Item Discount on L Items	25.00/25.00% (S\$)	738.50	738.50
			Total Parts (S\$)	2,215.50	2,215.50

Total Parts (S\$) 2,215.50 2,215.50

Report was unsubmitted during this print-out.

Adjuster Report Page 4 of 4

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Lab	our Items			
1	REMOVE & REFIT FRONT LH DOOR GLASS	New	60.00	60.00
2	WIRING	New	50.00	20.00
3	TUFFKOTE	New	60.00	60.00
4	SPRAY PAINTING	New	700.00	500.00
5	LABOUR CHARGES	New	700.00	480.00
		Gross Labour Cost (S\$)	1,570.00	1,120.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >