

22/02/2018

ASS. REC BY:

REF: CS/C7U8004900/Arb

Special Instruction:

Supervisor:

ASSIGNMENT (Office)

From (Person):

Irene Tay

of

STI

Date/Time:

14/3/2018 2:21pm

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

GBD 4484R

Insured:

GY 2878G

at Workshop m/s

Joo Hak Kee

Tel:

6743 1913

of

Blk 3067 Ubi Rd 1 # 01-406

Policy No:

DMCVSN3013321800

Claim No:

GNM18D01363C02

Sum Insured:

Excess:

Make of Veh:

D.O.A.

12032018

(Client's Record)

CA / REV / REP. / REV 24 HRS wpi

H.O.D. Endorsement:

Date/Time:

14/3/2018 3:16pm

Person Contacted:

Nabilah

Vehicle IN/OUT

Date/Time

Action/Instruction (✓) Estimate

GBD 4484R - X

GY 2878G - N/A / TGN18011154 / Y1

D.O.A. - 17042008

Confirm L1S \$3350, 5 days

Red: \$7959.36, 70%

ASS. SEC. BY: Adrian Ling

REF:

**ASSIGNMENT**

From: \_\_\_\_\_ Date: \_\_\_\_\_

Estimated Cost: \_\_\_\_\_

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: \_\_\_\_\_

at Workshop m/s \_\_\_\_\_

of \_\_\_\_\_

Insured: \_\_\_\_\_

Policy No. \_\_\_\_\_

Claims No. \_\_\_\_\_

Sum Insured: \_\_\_\_\_ Excess: \_\_\_\_\_

(Client's Record)

Make of Veh: \_\_\_\_\_

(Policy Condition)

Remark: The veh had commenced its  
repair at the time of inspection.

N/S	O/S

Bal. or Market Value: \_\_\_\_\_

IDAC Accident Report: \_\_\_\_\_ Consistent? : Yes or No

GIA / PR Seen: \_\_\_\_\_ Consistent? : Yes or No

Est. Repairs: \_\_\_\_\_ days Res.: Yes or No

Lum Sum: \_\_\_\_\_ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: \_\_\_\_\_ Person Contacted: \_\_\_\_\_

Veh No: G8D4484R Yr Regn: 2014 OctType: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Nissan Cabster cc 2953Colour: Grey A/C: Insured / Std / NI / NASp. Reading: 72345 T/Radio: Insured / Std / NI / NA

Eng/No: \_\_\_\_\_

C/No: JNISC2F24Z0856645Gen. Cond: Good / Fair / Poor / BurntSteering: Inorder / Jammed / Leaked / Burnt orBrake: Inorder / Jammed / Leaked / Burnt orModi: Nil / S/Rim / STD A/Rim orTyre Size: F: 195/20 R15 610R: 165 R13 Dunlop

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal. 06 mmR/Bal. 06 mmL/Bal. 06 mmL/Bal. 06 mm

D.O.A. \_\_\_\_\_

D.O.L. 14/03/18Survey held at JHKDes. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

TP China

RECEIVED 13 APR 2018

Date/Time, File Pass to?

1) typist

Date/Time, File Return to?

2) \_\_\_\_\_

☐ : Prel. Report☒ : Final ReportDays Of Repair: 5Resurvey No. of Trip: -Add Fee: ☐ : Site Insp (\$)☐ : Interview (\$)☐ : Tech. Invs (\$)☐ : Weekend (\$)Survey Fee: 120

Transportation: \_\_\_\_\_

S + RS \$ \_\_\_\_\_

Photos \_\_\_\_\_

Others \_\_\_\_\_

TOTAL

Report Format: TPLump Sum / T.B.I. (\$) 3350



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
CHINA TAIPING INSURANCE (S) PTE LTD		Ref : CS/CTI18004900/Arb		
3 ANSON ROAD #16-00 SPRINGLEAF TOWERS SINGAPORE 079909		Date : 14-03-2018		
		Code : CTI		
<b>1. Policy Particulars :- THIRD PARTY CLAIM</b>				
Insured Veh.	GY 2878G	Veh. Inspected	GBD 4484R	
Policy No.	DMCVSN3013321800	Coverage (\$)	0.00	
Claim No.	SNM18D01363C02	Excess (\$)	0.00	
Assign From	MERIMEN (IRENE TAY)	Assign Date	14/03/2018	
<b>2. Vehicle Particulars &amp; Condition</b>				
Make & Model		c.c	0	
Engine No.	HIDDEN	Year of Reg.		
Chassis No.		Colour		
Odometer	-	Steering		
Brakes		Modification		
General				
<b>3. Conditions of Tyres</b>				
	Size	Make	Balance	
R/H Front Tyre			mm	
L/H Front Tyre			mm	
R/H Rear Tyre			mm	
L/H Rear Tyre			mm	
<b>4. Description of Damages</b>				
<b>5. General Information</b>				
Accident Date	12/03/2018	Inspection Date	14/03/2018	
Survey held at	JOO HAK KEE AUTO PTE LTD 3007 UBI ROAD 1 #01-406 KAMPONG UBI INDUSTRIAL ESTATE SINGAPORE 408701			
<b>5a. Remarks</b>				
A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				

## ...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	14 Mar 2018		14 Mar 2018 14:21 <a href="#">Assign</a>				<b>New Assignment</b> <a href="#">Cancel Case</a>

  

Main	Reference	Claim Details	Documents	Show All					
<b>CLAIM SUBFOLDER DETAILS</b> <span style="float: right;">[Created by insurer]</span>									
<b>Insured:</b>									
Main Claimant: <b>DISTINCTIDENTITY PTE. LTD.</b>									
Vehicle Reg. No.: <b>GBD4484R</b>		Date of Loss: 12/03/2018 00:00 - :59							
Claim Type: <b>TP / SNM18D01363C02</b>		Policy/Cover Note No.: <b>DMCVSN3013321800</b>							
Vehicle Reg. No. (Insured): <b>GY2878G</b>		Policy No. (Claimant):							
		Excess: <b>\$40.00</b>							
Repairer: <b>Joo Hak Kee Auto Pte Ltd (HQ) Blk 3007 Ubi Road 1, #01-406, 408701 Ubi - Tel: 67431913</b>									
Handling Insurer: <b>China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Irene Tay Hui Ping - 638986192]</b>									
Adjuster: <b>LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Final Rpt due 23/03/2018]</b>									
Adj Asg. Remarks: <b>NO EST, CASE WITH SJE.</b>									
<b>ASSOCIATED MAIL RECEIVED</b> <span style="float: right;"><a href="#">View All</a> <a href="#">Compose Case Mail</a></span>									
There are no mail for this case.									
<b>ALL ASSOCIATED TASKS</b> <span style="float: right;"><a href="#">View All</a> <a href="#">Search Tasks</a> <a href="#">Create New Task</a> <a href="#">Complete</a></span>									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

## SINGAPORE ACCIDENT STATEMENT

### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

### ACCIDENT STATEMENT

Date Of Report	13/03/2018 10:50
Date Of Accident	12/03/2018 12:30
Exact Location Of Accident	SLIP ROAD CTE AYE TO ANG MO KIO AVE 5
Country/State of Loss	SINGAPORE

### DETAILS OF OWN VEHICLE

Vehicle Registration Number	GBD4484R
<b>Insured/Policyholder</b>	
Name Of Registered Owner	DISTINCTIDENTITY PTE. LTD.
Co Reg No	201007784E
Email Address	NOEMAIL
Mobile Phone No	
Alternative Phone No	OFFICE-91279904

### Vehicle Particulars

Manufacturer	NISSAN
Model	CABSTAR
Exact Purpose for which vehicle was being used at time of accident	WORK
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	COMMERCIAL VEHICLE

### Insurance Company

Name of Insurance Company	NTUC INCOME INSURANCE CO-OPERATIVE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	5092726821
Cover Note Number	

### Driver

Name of Driver	SABAPATHY S/O MOTTAYAN
NRIC No	S2560487C
Date Of Birth	19/12/1950
Occupation	OUTDOOR
Date Of Driving Pass	17/10/1984
Driving Experience	33 YEARS AND 4 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-81625880
Fax Number	
Contact Number	
Email Address	NOEMAIL

## Sketch Plan Pg. 1

INCOME MOTOR SERVICE CENTRE

Report Date & Start Time: 13-03-2018 / 10:45

Report No: MT/

D.O.A: 12-03-2018

Time: 12:30 hrs

Vehicle No: GBD4484R

Reporting Type: TP

### SKETCH PLAN

#### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
  - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
  - (ii) investigating the accident and/or my claims;
  - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
  - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
  - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
  - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
  - (ii) for complying with requirements under any regulations, laws or court orders.



Policyholder's Signature / Date & Time

SABAPATHY

Driver's Signature (If driver is not the policyholder) / Date & Time

13-03-18 / 10:45

Alan Tang (S098825)  
Customer Care Executive  
Motor Service Centre

Witnessed by Reporting Centre Personnel

## Enquire Transfer Fee

### Vehicle Details

Vehicle No. :	GBD4484R
Vehicle Type :	B31 - Goods (Open) Lorry (Metal Body)/Pickup
Vehicle Attachment 1 :	With Hood
Vehicle Scheme :	Normal
Vehicle Make :	NISSAN
Vehicle Model :	CABSTAR 3.0 5M/T ABS 2DR 2WD EURO 5
Chassis No. :	JN15C2F24Z0856645
Propellant :	Diesel
Engine No. :	ZD30342790K
Engine Capacity :	2953 cc
Maximum Power Output :	-
Maximum Laden Weight :	3500 kg
Unladen Weight :	1800 kg
Year Of Manufacture :	2014
Original Registration Date :	27 Oct 2014
Lifespan Expiry Date :	26 Oct 2034
COE Category :	C - Goods Vehicle & Bus
PQP Paid :	\$31,951.00
COE Expiry Date :	26 Oct 2024

ATTN: MOTOR CLAIMS DEPARTMENT  
 OWNER: DISTINCTIDENTITY PTE LTD  
 INSURER: NTUC INCOME INSURANCE CO-OPERATIVE LTD  
 POLICY NO.: 5092726821  
 REFERENCE: CHINA TAIPING DIRECT SETTLE  
 DATE OF ACCIDENT: 12/03/2018

TPC/Chen  
 Janice

## REPAIR ESTIMATE

Est. No. : E18030006  
 Date : 14/03/2018  
 Vehicle Num. : GBD4484R  
 Make/Model : Nissan, Cabstar 3.0 5M/T  
 Chassis/Eng# : JN1SC2F24Z0856645  
 Yr. of Manu : 2014

No	Description	Qty	U/P	Amt
<b>Section: LIST ITEMS</b>				
1	REAR ALUMINIUM BUMPER <i>Best</i>	1.00	786.90	786.90 ✓
2	REAR BUMPER BRACKET LH <i>Best</i>	1.00	365.40	365.40 ✓ 180/50
3	REAR BUMPER BRACKET RH <i>Best</i>	1.00	365.40	365.40 ✓ 180/50
4	SPARE TYRE HOLDER <i>new</i>	1.00	289.60	289.60 +
5	REAR NUMBER PLATE HOLDER <i>new</i>	1.00	128.90	128.90 +
6	TAIL LAMP LH <i>Coated</i>	1.00	486.80	486.80 ✓ 245-10
7	TAIL LAMP RH <i>Coated</i>	1.00	486.80	486.80 ✓ 245-10
8	TAIL GATE INNER ALUMINIUM PANEL <i>new</i>	1.00	1,864.90	1,864.90 +
9	TAIL GATE FLOOR PANEL <i>new</i>	1.00	3,500.60	3,500.60 +
10	TAIL GATE LOCK (UPPER) LH <i>new</i>	1.00	221.85	221.85 +
11	TAIL GATE LOCK (UPPER) LH <i>new</i>	1.00	221.85	221.85 +
12	TAIL GATE LOCK (UPPER) RH <i>new</i>	1.00	221.85	221.85 +
13	TAIL GATE LOCK (UPPER) RH <i>Best</i>	1.00	221.85	221.85 ✓ 172-8
14	TAIL GATE RUBBER <i>new</i>	4.00	68.00	272.00 +
15	TAIL GATE <i>Best</i>	1.00	2,150.10	2,150.10 ✓ 1688-40
				<b>Amt</b> S\$ 11,584.80
				<b>Discount (30.00%)</b> S\$ 999.99
				<b>Subtotal</b> S\$ 8,109.36

## Section: SPECIAL NETT ITEMS

16	REAR NUMBER PLATE <i>Best</i>	1.00	50.00	50.00 ✓ 30
17	REVERSE SENSOR <i>Best</i>	1.00	300.00	300.00 ✓ 200
18	'70KM/H' STICKER <i>new</i>	1.00	50.00	50.00 ✓ 15

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey below after spray painting
- To repair damaged parts during resurvey
- Parts prices are subject to confirmation
- Third party survey is done on "Without Prejudice" basis
- No illegal modifications is allowed
- Supplementary items must be resurveyed and is subject to final approval from Insurance Company

Continue on next page...



612SAFE



ATTN: MOTOR CLAIMS DEPARTMENT  
 OWNER: DISTINCTIDENTITY PTE LTD  
 INSURER: NTUC INCOME INSURANCE CO-OPERATIVE LTD  
 POLICY NO.: 5092726821  
 REFERENCE: CHINA TAIPING DIRECT SETTLE  
 DATE OF ACCIDENT: 12/03/2018

**REPAIR ESTIMATE**

Est. No. : E18030006  
 Date : 14/03/2018  
 Vehicle Num. : GBD4484R  
 Make/Model : Nissan, Cabstar 3.0 5M/T  
 Chassis/Eng# : JN1SC2F24Z0856645  
 Yr. of Manu : 2014

No	Description	Qty	U/P	Amt
19	8 PAX STICKER <i>plan</i>	1.00	50.00	50.00 <i>15</i>
20	COMPANY STICKER <i>xen</i>	1.00	300.00	300.00 <i>780</i>
				<b>Amt</b> S\$ 750.00
				<b>Discount (0.00%)</b> S\$ 0.00
				<b>Subtotal</b> S\$ 750.00

**Section: LABOUR**

21	TO PANEL BEAT AND RENEWAL OF ALL DAMAGED PARTS	1.00	1,150.00	1,150.00 <i>600</i>
22	TO PUTTY & SPRAY PAINTING ON ACCIDENT DAMAGED PORTION	1.00	850.00	850.00 <i>500</i>
23	TO DISMANTLE AND REFIT TAILGATE COMPONENTS	1.00	250.00	250.00 <i>+</i>
24	TO CHECK WIRING FUNCTION AND REFIT WIRING	1.00	100.00	100.00 <i>70</i>
25	TO ANTI-RUST	1.00	100.00	100.00 <i>40</i>
				<b>Amt</b> S\$ 2,450.00
				<b>Discount (0.00%)</b> S\$ 0.00
				<b>Subtotal</b> S\$ 2,450.00

*Adrian Ling*  
*14/03/18-*  
*05 days*  
*Label: 4206.55*  
*1/5 3350*



Joo Hak Kee Auto Pte. Ltd.

**LIST ITEMS Subtotal** S\$ 8,109.36  
**SPECIAL NETT ITEMS Subtotal** S\$ 750.00  
**LABOUR Subtotal** S\$ 2,450.00  
**Total** S\$ 11,309.36

## ...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	14 Mar 2018		14 Mar 2018 14:21 <a href="#">Edit Adj Rpt</a>	<b>S\$3,350.00</b> <a href="#">Edit Estimates</a>	<b>S\$3,350.00</b> <a href="#">View Rpt</a>		<b>Pending for Survey Report</b> <a href="#">Cancel Case</a>

<b>Main</b>	<b>Reference</b>	<b>Claim Details</b>	<b>Documents</b>	<a href="#">Show All</a>
-------------	------------------	----------------------	------------------	--------------------------

**CLAIM SUBFOLDER DETAILS** [Created by Insurer]

Insured:	- ID: -		
Main Claimant:	DISTINCTIDENTITY PTE. LTD.		
Vehicle Reg. No.:	GBD4484R	Date of Loss:	12/03/2018 00:00 - :59 [40 Months and 13 Days From LTA Reg Date (Man Yr)]
Claim Type:	TP / SNM18D01363C02	Policy/Cover Note No.:	DMCVSN3013321800
Vehicle Reg. No. (Insured):	GY2878G	Policy No. (Claimant):	
		Excess:	S\$0.00
Repairer:	Joo Hak Kee Auto Pte Ltd (HQ) Blk 3007 Ubi Road 1, #01-406, 406701 Ubi - Tel: 67431913		
Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Irene Tay Hui Ping - 638986192]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by ADRIAN LING] ... [Final Rpt due 23/03/2018]		
Adj Asg. Remarks:	NO EST, CASE WITH SJE.		

**ASSOCIATED MAIL RECEIVED** [View All](#) [Compose Case Mail](#)

There are no mail for this case.

**ALL ASSOCIATED TASKS** [View All](#) [Search Tasks](#) [Create New Task](#) [Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

## Claim Documents

\*GBD4484R (SNM18D01363C02)  
[GY2878G]  
TP  
DISTINCTIDENTITY PTE. LTD.  
Mar 12 2018 12:00AM  
[-]  
Joo Hak Kee Auto Pte Ltd

Upload Documents   Upload Photos   Compose New Letter			View <span>View in Browser</span>	
<b>Photos/Images</b>			3 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	12/04/18 16:54	General View	Load JPG	<input checked="" type="checkbox"/>
2	12/04/18 16:54	General View	Load JPG	<input checked="" type="checkbox"/>
3	12/04/18 16:54	General View	Load JPG	<input checked="" type="checkbox"/>
4	12/04/18 16:54	General View	Load JPG	<input checked="" type="checkbox"/>
5	12/04/18 16:54	General View	Load JPG	<input checked="" type="checkbox"/>
6	12/04/18 16:54	General View	Load JPG	<input checked="" type="checkbox"/>
7	12/04/18 16:54	General View	Load JPG	<input checked="" type="checkbox"/>
8	12/04/18 16:54	General View	Load JPG	<input checked="" type="checkbox"/>
9	12/04/18 16:54	General View	Load JPG	<input checked="" type="checkbox"/>
10	12/04/18 16:54	General View	Load JPG	<input checked="" type="checkbox"/>
11	12/04/18 16:54	General View	Load JPG	<input checked="" type="checkbox"/>
12	12/04/18 16:54	General View	Load JPG	<input checked="" type="checkbox"/>
13	12/04/18 16:54	General View	Load JPG	<input checked="" type="checkbox"/>
14	12/04/18 16:54	General View	Load JPG	<input checked="" type="checkbox"/>
15	12/04/18 16:55	General View	Load JPG	<input checked="" type="checkbox"/>
16	12/04/18 16:55	General View	Load JPG	<input checked="" type="checkbox"/>
17	12/04/18 16:55	General View	Load JPG	<input checked="" type="checkbox"/>
18	12/04/18 16:55	General View	Load JPG	<input checked="" type="checkbox"/>
19	12/04/18 16:55	General View	Load JPG	<input checked="" type="checkbox"/>
20	12/04/18 16:55	General View	Load JPG	<input checked="" type="checkbox"/>
21	12/04/18 16:55	General View	Load JPG	<input checked="" type="checkbox"/>
22	12/04/18 16:55	General View	Load JPG	<input checked="" type="checkbox"/>
23	12/04/18 16:55	General View	Load JPG	<input checked="" type="checkbox"/>
24	12/04/18 16:55	General View	Load JPG	<input checked="" type="checkbox"/>
25	12/04/18 16:55	General View	Load JPG	<input checked="" type="checkbox"/>
<b>Documentation</b>			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	China Taiping Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
1	14/03/18 14:20	PRS	Load PDF	
2	14/03/18 14:20	TP GIA REPORT	Load PDF	

## Documents Checklist

<b>DOCUMENTS CHECKLIST</b>	Reset   Save   Print
There are no document checklists configured.	

**Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)****Show Remarks To:** ☐ Handling InsurerNote: Remarks are private unless you show it to other parties.

# LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607196R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/CT118004900/ARBQ2

Date: 13/04/2018

### REFERENCE

Handling Insurer: China Taiping Insurance  
(Singapore) Pte. Ltd.

Policy No: DMCVSN3013321800

Claimant Vehicle  
No: GBD4484RInsured Vehicle  
No: GY2878G

Date of Loss: 12/03/2018

Nature of Claim: TP

Claim  
No: SNM18D01363C02

### DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: GBD4484R

Make &amp; Model: NISSAN CABSTAR, 3.0 (M)

Engine No: ZD30342790K

Reg. Date: 27/10/2014 (Man. Year: 2014)

Chassis No: JN1SC2F24Z0856645

Colour: Grey

Odometer: 72345 km

Engine Capacity: 2953 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): Market Value/New Car Price

### CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

### CONDITION OF TYRES

Front Tyre Size:	195/70 R15C	Rear Tyre Size:	165 R13
Front Left Side:	Yokohama 6 mm	Rear Left Side:	Dunlop 6 mm
Front Right Side:	Yokohama 6 mm	Rear Right Side:	Dunlop 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	8,859.36	2,996.95	5,862.41	66.17
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,450.00	1,210.00	1,240.00	50.61
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (S\$)</b>	<b>11,309.36</b>	<b>4,206.95</b>	<b>7,102.41</b>	<b>62.80</b>
<b>Approved Total (Overridden) (S\$)</b>		<b>3,350.00</b>		
<b>(S\$)</b>	11,309.36	3,350.00	7,959.36	70.38
<b>+ GST 7.00/7.00% (S\$)</b>	791.66	234.50	557.16	70.38
<b>Nett Amount (S\$)</b>	<b>12,101.02</b>	<b>3,584.50</b>	<b>8,516.52</b>	<b>70.38</b>

### INSPECTION

Date of Assignment: 14/03/2018

Date Inspected: 14/03/2018 Inspected At:

Joo Hak Kee Auto Pte Ltd (HQ)  
Blk 3007 Ubi Road 1, #01-406  
Singapore 408701

Estimated Period of Repair: 5.0 days

---

**Adjuster:** ADRIAN LING**Manager:** Janice Lee Si Hua

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

## Reference

<b>Part Source:</b>	(Last Synchronised: 13 Apr 2018)	
<b>Parts:</b>	N/A	NISSAN CABSTAR 3.0 (M) (Model not available in database)
<b>Labour:</b>	Repairer's	(Price-denominated Standard List)
<b>Print Code:</b>	(Unsubmitted, no print-code for GBD4484R)	
<b>Validity:</b>	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
<b>Further Info:</b>	Items/values not in reference catalogue are prefixed with an asterisk *.	

## Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR ALUMINIUM BUMPER	Bent	786.90 FL	*786.90 FL
2	1		*REAR BUMPER BRACKET LH	Bent	255.78 FS	*180.00 FS
3	1		*REAR BUMPER BRACKET RH	Bent	255.78 FS	*180.00 FS
4	1		*SPARE TYRE HOLDER	Not Necessary	289.60 FL	*- FL
5	1		*REAR NUMBER PLATE HOLDER	Not Necessary	128.90 FL	*- FL
6	1		*TAIL LAMP LH	Cracked	486.80 FL	*245.20 FL
7	1		*TAIL LAMP RH	Cracked	486.80 FL	*245.20 FL
8	1		*TAIL GATE INNER ALUMINIUM PANEL	Not Necessary	1,864.90 FL	*- FL
9	1		*TAIL GATE FLOOR PANEL	Not Necessary	3,500.60 FL	*- FL
10	1		*TAIL GATE LOCK (UPPER) LH	Not Necessary	221.85 FL	*- FL
11	1		*TAIL GATE LOCK (LOWER) LH	Not Necessary	221.85 FL	*- FL
12	1		*TAIL GATE LOCK (UPPER) RH	Not Necessary	221.85 FL	*- FL
13	1		*TAIL GATE LOCK (LOWER) RH	Not Necessary	221.85 FL	*172.80 FL
14	4		*TAIL GATE RUBBER	Not Necessary	272.00 FL	*- FL
15	1		*TAIL GATE	Dented	2,150.10 FL	*1,688.40 FL
16	1		*REAR NUMBER PLATE	Bent	50.00 FS	*30.00 FS
17	1		*REVERSE SENSOR	Damaged	300.00 FS	*200.00 FS
18	1		*70KM/H STICKER	Necessary	50.00 FS	*15.00 FS
19	1		*8 PAX STICKER	Necessary	50.00 FS	*15.00 FS
20	1		*COMPANY STICKER	Necessary	300.00 FS	*180.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

<b>Sub Total (\$\$)</b>	<b>12,115.56</b>	<b>3,938.50</b>
<b>- List Item Discount on L Items 30.00/30.00% (\$\$)</b>	<b>3,256.20</b>	<b>941.55</b>
<b>Total Parts (\$\$)</b>	<b>8,859.36</b>	<b>2,996.95</b>

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	TO PANEL BEAT AND RENEWAL OF ALL DAMAGED PARTS	New	1,150.00	600.00
2	TO PUTTY & SPRAY PAINTING ON ACCIDENT DAMAGED PORTION	New	850.00	500.00
3	TO DISMANTLE & REFIT TAILGATE COMPONENTS	New	250.00	0.00
4	TO CHECK WIRING FUNCTION AND REFIT WIRING	New	100.00	70.00
5	TO ANTI-RUST	New	100.00	40.00
<b>Gross Labour Cost (\$\$)</b>			<b>2,450.00</b>	<b>1,210.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >