

ASS. REC. BY: Adrian Ling

REF: CC3 / MSG18004901 / Avbnz

ASSIGNMENT

22/05/08

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured: SKP 2473R

Policy No. 80411540 ARW

Claims No. 552093

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

Bal. or Market Value: _____

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: _____ days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: _____ Person Contacted: _____

Veh No: SJQ 788C - Yr Regn: 2008 / May

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Honda Civic c.c. 1799.

Colour: Silver A/C: Insured / Std / NI / NA

Sp. Reading: 302818 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: JHMPD163085215704.

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 205/55 R16

R: 205/55 R16

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or Falken

Front

Rear

R/Bal. 06 mm R/Bal. 06 mm

L/Bal. 06 mm L/Bal. 06 mm

D.O.A. 11/3/18 D.O.I. 14/03/18

Survey held at Hua Meng

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

TP MSG.

15/3/18 Email GIA to Katherine Wong / Nabikh

12/6/18 Adrian confirmed LS \$2400 (Red 4646.16, 6690)

MV: 14K.

PV: 11.1K

Nett: 2.9K

RECEIVED 12 JUN 2018

SJQ 788C - X

SKP 2473R - X

12/6/18 Send Preli revised by merimen

Date/Time, File Pass to?

☐ : Preli. Report☐ : Final Report

1)

Date/Time, File Return to?

2) 12/6 - typist

Report Format: merimen

Lump Sum / I.B.I: (\$ 2400)

Days Of Repair: 4

Resurvey No. of Trip: 1

Add Fee: ☐ : Site Insp (\$)☐ : Interview (\$)☐ : Tech. Invs (\$)☐ : Weekend (\$)

Survey Fee:

Transportation:

S + RS: \$

Photos

Others

TOTAL

17858

200

10

210

Survey Department Check List (Case Handler)

Reference No. :

CC3 | MSG | 8004901 | AVB

Policy Type: OD / TP / TP RES / TL / EVA

Case Handler

Typist

Admin (): Case handler to make sure all Information created by the assignment team are **ACCURATE**.

(1) Office Assign Form		Y-Date	N-Date	Y-Date	N-Date
C	Reference No.	✓			
C	Customer Code				
N	Assign From				
C	Assign Date	✓			
C	Veh No (Inspected)	✓			
C	Veh No (Insured)	✓			
C	D.O.A	✓			
C	Policy No	✓			
C	Claim No	✓			
C	Insurance Authorisation (CA /REV/REP)				
C	Report Type	✓			
C	Weekend Charges				
N	Survey held at/Repairer	✓			
C	Excess				

Surveyor (): Case handler to make sure the surveyor completed all required information.

(1) Assignment Form					
C	Vehicle No	✓			
C	Regn Month/Year	✓			
N	Vehicle Type	✓			
N	Make & Model	✓			
C	Engine Capacity. (C.C)	✓			
N	Colour	✓			
C	Odometer. (Sp.Reading)	✓			
C	Chassis No	✓			
N	General Condition	✓			
N	Steering	✓			
N	Brake	✓			
N	Modification (Modi)	✓			
C	Tyre Size	✓			
N	Tyre Make	✓			
C	Tyre Balance	✓			
C	Date of Inspection	✓			
N	Survey held	✓			
N	Des.of Damages	✓			

(2) System - (Views/Merimen)

C	Damaged Vehicle Photographs Uploaded	✓			
---	--------------------------------------	---	--	--	--

(3) Workshop Estimate/Assignment Form

N	ALL Parts condition	✓			
C	Market Value for OD cases				
C	Estimate Repair Cost for PRI (RSI, TMI, MSIG)				
C	Days of repair	✓			
C	Finalised Amount	✓			
C	Re-inspection Cases to Finalize within 5 Days				

(4) System - (Views/Merimen)

C	Resurvey photo Uploaded	✓			
---	-------------------------	---	--	--	--

Check By: **VERON** | 12/6/18
Case Handler Date

*C: Critical *N: Non-Critical

21/05/201



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
MSIG INSURANCE (SINGAPORE) PTE LTD		Ref : CC3/MSG18004901/Avb		
16 RAFFLES QUAY #24-01 HONG LEONG BLDG SINGAPORE 048581		Date : 14-03-2018		
		Code : MSG		
1.	Policy Particulars :- THIRD PARTY CLAIM			
	Insured Veh.	SKP 2473R	Veh. Inspected	SJQ 788C
	Policy No.		Coverage (\$)	0.00
	Claim No.		Excess (\$)	0.00
	Assign From		Assign Date	14/03/2018
2.	Vehicle Particulars & Condition			
	Make & Model		c.c	0
	Engine No.	HIDDEN	Year of Reg.	
	Chassis No.		Colour	
	Odometer	-	Steering	
	Brakes		Modification	
	General			
3.	Conditions of Tyres			
		Size	Make	Balance
	R/H Front Tyre			mm
	L/H Front Tyre			mm
	R/H Rear Tyre			mm
	L/H Rear Tyre			mm
4.	Description of Damages			
5.	General Information			
	Accident Date	11/03/2018	Inspection Date	14/03/2018
	Survey held at	HUA MENG SPRAY PAINTING WKSP 1 KAKI BUKIT AVE 6 #01-61 AUTOBAY SINGAPORE 417883		
5a.	Remarks			
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: MSIG Insurance (Singapore) Pte. Ltd.
4 Shenton Way
#21-01 SGX Centre 2
Singapore 068807

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Katherine Wong Chew Shong

Date: 12 Jun 2018

Preliminary Advice

Insured Vehicle No : SKP2473R

TP Vehicle No : SJQ788C

Make : HONDA CIVIC

Date of Inspection : 14/03/2018

Inspection At : HUA MENG SPRAY PAINTING WORKSHOP (HQ)
NO 1 KAKI BUKIT AVENUE 6, #01-61 AUTOBAY@KAKI BUKIT
SINGAPORE 417883

Accident Date : 11/03/2018

Assignment Date : 21/03/2018

Est. Duration of Repair : 4.00

Point of Impact / General Description of Damages

The vehicle sustained impact / damages n/s body and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	7,046.16
Revised Amount (EST)	:S\$	2,400.00 (LUMP SUM)
Check Items (Estimated)	:S\$	0.00
Total	:S\$	0.00

Lump Sum Repair :S\$

Total Loss Consideration

New for Old Value	:S\$
Pre-Accident Value	:S\$
COE / PARF Rebate	:S\$
Salvage Value	:S\$
Margin for Repair	:S\$

Remarks

() The vehicle is economical/not economical for repair.

(x) The above survey was conducted on a 'without prejudice' basis.

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	12 Mar 2018		21 Mar 2018 14:54 Edit Adj Rpt				Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All
------	-----------	---------------	-----------	--------------------------

CLAIM SUBFOLDER DETAILS [Created by insurer]

Insured:	TAN POH CHYE ALBIN, ID: S1246187I, Tel: +6598182562			
Main Claimant:	Lim Meng Jeow, ID: S3041785B			
Vehicle Reg. No.:	SJQ788C	Date of Loss:	11/03/2018 12:00 - :59 [117 Months and 17 Days From LTA Reg Date (Man Yr)]	
Claim Type:	TP / 552093	Policy/Cover Note No.:	80411840AVW (Comprehensive) Coverage: 26/08/2017 - 25/08/2018	
Vehicle Reg. No. (Insured):	SKP2473R	Policy No. (Claimant):		
		Excess:	S\$2,000.00	
Repairer:	Hua Meng Spray Painting Workshop (HQ) No 1 Kaki Bukit Avenue 6, #01-61 Autobay@Kaki Bukit, 417883 Kaki Bukit - Tel: 67478064, 67465519			
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Katherine Wong Chew Shong - 6594 2544]			
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by ADRIAN LING] ... [Imm.Advice due 22/03/2018]			
Driver/Custodian (Insured):	TAN WEI LONG (), NRIC: S9127877D, Tel: +6592961766			
Adj Asg. Remarks:	direct survey done.			

[View All](#) [Compose Case Mail](#)

ASSOCIATED MAIL RECEIVED

There are no mail for this case.

[View All](#) [Search Tasks](#) [Create New Task](#) [Complete](#)

ALL ASSOCIATED TASKS []

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Veron Chen (LKKAuto)

From: Veron Chen (LKKAuto)
Sent: Thursday, 15 March 2018 8:28 AM
To: 'Katherine Wong'; 'Nabilah Rasol'
Cc: KKLau; Accounts (LKKAuto); 'Christopher Chionh'; SUR
Subject: DIRECT SURVEY INSPECTION ON WORKSHOP - HUA MENG SPRAY PAINTING WORKSHOP, DOA: 11/3/2018, SJQ 788C (TP VEHICLE), SKP 2473R (OI VEHICLE)
Attachments: SJQ 788C (GIA).pdf

Dear Katherine/Nabilah,

Please be informed that we had inspected the vehicle SJQ 788C at M/s: HUA MENG SPRAY PAINTING WORKSHOP, 1 KAKI BUKIT AVE 6 #01-61 AUTOBAY SINGAPORE 417883

Enclosed herewith a copy of TP's GIA report. The estimated cost of repair will forward to you shortly.

Meanwhile, kindly provide us the claim reference number for our necessary action.

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	1785B
Vehicle Details	
Vehicle No.:	SJQ788C
Vehicle to be Exported:	Yes
Intended De-registration Date:	14 Mar 2018
Vehicle Make:	HONDA
Vehicle Model:	CIVIC 1.8L A
Primary Colour:	Silver
Manufacturing Year:	2008
Engine No.:	R18A13034299
Chassis No.:	JHMFD163085215704
Maximum Power Output:	103.0 kW (138 bhp)
Open Market Value:	\$21,609.00
Original Registration Date:	22 May 2008
First Registration Date:	22 May 2008
Transfer Count:	1
Actual ARF Paid:	\$21,609.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	21 May 2018
PARF Rebate Amount:	\$10,804.00
Intended COE Rebate Details	
COE Expiry Date:	21 May 2018
COE Category:	B - Car (1601cc & above)
COE Period(Years):	10
QP Paid:	\$17,510.00
COE Rebate Amount:	\$324.00
Total Rebate Amount:	\$11,128.00

The information contained herein is correct as at 14 Mar 2018

OK

Cheap Car Insurance Renewal

Is your car insurance expiring soon?

Receive best quotations from multiple insurers in as little as 2 hours.

Civic Price Range Depreciation 2008 Vehicle Type

Advanced Search

Used Car Comparison

--- Comparing 3 Vehicles ---

Honda Civic 2.0A

Honda Civic 1.8M VTI-S

Honda Civic 1.8A VTI-S



Use search bar above to search to compare.

Clear All

Add all to Shortlist

Add to Shortlist

Add to Shortlist

Add to Shortlist

Back to search result

CAR DETAILS

Price	\$15,800	\$14,900	\$15,800
Instalment	\$11,087	\$10,456	\$2,792
Registration Date	30-Apr-2008	03-May-2008	18-Jul-2008
Manufactured	2008	2008	2008
Mileage	-	-	148,305 km
Transmission	Auto	Manual	Auto
Engine Cap	1,998 cc	1,799 cc	1,799 cc
Road Tax	\$1,210 /yr	\$978 /yr	\$978 /yr
Power	114.0 kW (152 bhp)	103.0 kW (138 bhp)	103.0 kW (138 bhp)
Curb Weight	1,312 kg	1,190 kg	1,219 kg
Features	2.0L DOHC I-VTEC Engine, 5 Speed Auto Transmission, SRS Airbags, Multi Function Steering Control, Paddle Shifter, Reverse Sensors, Cruise Control, VSA	1.8L DOHC I-VTEC Inline 4 Engine, 138 Bhp, 5 Speed Manual Transmission, SRS Airbags, ABS, Knockdown Rear Seats, HID Headlights, Rain Sensors.	1.8L I-VTEC Engine, 5 Speed Auto Transmission, SRS Airbags, Multi Function Steering Wheel, Paddle Shifters, Reverse Sensors, Auto Climatic Air-con.
Accessories	Sport Rims, Factory Fitted Audio System, Electrical Retractable Side Mirrors With Indicator, Upholstery Leather Seats.	Leather Interior, Factory Fitted Audio System With Steering Controls, Reverse Sensors, Tinted, Retractable Side Mirrors.	Sport Rims, Factory Fitted Audio System, Solar Film, Electrical Retractable Side Mirrors With Indicator, Upholstery Leather Seats.
Description	3 Digit Number Plate! \$0 Down-payment! Ideal For Short Term Usage! High Trade-in! Well Maintained, Powerful Sedan Designed To Give You Excellent Performance And Handling. Awaits You To View And Test Drive It! Buy It From Us With A Peace Of Mind, A Company Accredited With Outstanding Awards, Professional After Sales Service Assured. Be Here To Appreciate It In Pristine Condition Today!	Good For Short Term Drive, Too Good To Be Scrap, No Repairs Needed, Option To Purchase With COE Renew, Easy Drive Away, View To Appreciate, Call Us For More Details. For Viewing Please Visit Us At Lot C17.	\$0 Down Payment Available! Ideal For Short Term Usage! Only 1 Owner! Very Low Mileage! Extended Warranty Available! Well Kept By Previous Owner In Tip Top Condition, With Evident From The Car Itself! Buy It From Us With A Peace Of Mind, A Company Accredited With Outstanding Awards, Professional After Sales Service Assured. Visit Us At Our Showroom To Appreciate It In Pristine Condition Now!
COE	\$18,000	\$19,501	\$14,689
OMV	\$23,528	\$21,556	\$20,495
ARF	\$23,528	\$21,556	\$20,495
Depreciation	-	-	-
No. of Owners	2	3	1
Type of Vehicle	Sedan	Sedan	Sedan
Category	PARF Car	PARF Car	PARF Car
Availability	Available	Available	Available

M3ME18034339 / SME Motor Pte Ltd - Kaki Bukit
 ENTRY DATE & TIME: 12/03/2018 17:45
 SUBMITTED BY: Chia Pei Ying

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	12/03/2018 17:45
Date Of Accident	11/03/2018 12:05
Exact Location Of Accident	CARPARK OF BLK 350 UBI AVE 1
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SJQ788C
Insured/Policyholder	
Name Of Registered Owner	LIM MENG JEOW
Passport No/FIN	-
Email Address	NOEMAIL
Mobile Phone No	(LOCAL) +65-91804246
Alternative Phone No	OFFICE-91804246

Vehicle Particulars

Manufacturer	HONDA
Model	CIVIC
Exact Purpose for which vehicle was being used at time of accident	
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR

Insurance Company

Name of Insurance Company	NTUC INCOME INSURANCE CO-OPERATIVE LTD
Type Of Coverage	THIRD PARTY
Fleet Policy	NO
Policy Number	5095966569
Cover Note Number	

Driver

Name of Driver	GOH JUN YI IAN
NRIC No	S8537386B
Date Of Birth	06/11/1985
Occupation	INDOOR
Date Of Driving Pass	08/11/2005
Driving Experience	12 YEARS AND 4 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-90268185
Fax Number	
Contact Number	
Email Address	NOEMAIL

Address BLK 436 WOODLANDS ST 41 #01-396
 Postcode 730436
 Was driver an employee of the Insured's Company NO
 If No, Relationship of the Driver with the Insured OTHER - -
 Vehicle Registration Number of Driver's Own Vehicle -
 -
 -
 Insurance Company of Driver's Own Vehicle -
 -
 -

General Information of the Accident

Type Of Accident COLLISION - HEAD ON COLLISION
 Weather Conditions CLEAR
 Road Surface DRY

Other Information

Was any foreign vehicle involved in this accident? NO
 Number of vehicles involved in the accident
 Was any body injured in the Accident? NO
 Was any injured conveyed to hospital by ambulance? NO
 Was any other material or property damaged? YES
 I have been approached by unknown person(s) soliciting/offering accident claims assistance. NO
 Number of Passengers (Including Driver) 2
 Passenger 1
 NAME: : SIM YING HUI
 GENDER: : FEMALE

Details of Police Action

Was the accident reported to the police? NO
 If Yes, Please state which Police Station
 Was notice of intended Prosecution given? NO
 If Yes, against whom?

Circumstances of Accident

I WAS TRAVELLING STRAIGHT INSIDE THE CARPARK OF BLK 350 UBI AVE 1 ON 11/03/2018 AT 1205HRS. SUDDENLY, I HEARD A SCRATCH SOUND ON MY LEFT SIDE. VEHICLE B CAME OUT FROM LOT AND COLLIDED ONTO LEFT PORTION OF MY VEHICLE.

Attachment(s)

Are accident photos available for attachment? YES
 Was there any video captured by Car Camera? NO
 Was there any audio recorded? NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number SKP2473R
 Vehicle Make/Model/Colour
 Details Of Properties VEHICLE B
 Vehicle Category PRIVATE CAR
 Name of Driver TAN WEI LONG
 NRIC/Passport Number S9127877D
 Contact Number 92961766
 Address
 Postcode
 Insurance Company Name
 Nature Of Damage

No. Of Passenger (Including Driver)

Sketch Plan Pg. 1

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this form and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.

Policyholder's Signature
Date & Time:


Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

ffua mencia

Sketch Plan #2 Pg. 1

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

I was traveling straight inside the corporate of BIK 450 uls Ave (on 11-03-2018 @ 1205 hrs.

Suddenly I heard a scratch sound of my left side. Vehicle B came out from the lot and collided into left portion of my vehicle.

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature
Date & Time:

Driver's Signature
(if driver is not the policyholder)
Date & Time:

12/3/18 5 PM
Reporting Centre Personnel's Signature
Name:

NRIC/FIN No.:

HUA MENG SPRAY PAINTING WORKSHOP

1, Kaki Bukit Avenue 6, Blk C #01-61 / 01-34, Singapore 417883

Autobay @ Kaki Bukit

Tel: 6747 8064, 6746 5519 / 9666 9680 Fax: 6743 4896

ESTIMATE

LIM MENG JEOW

BLK 436 WOODLANDS ST 41

#01-396

S 730436

TP MS16.

Vaan

Date

:18.04.2018

Vehicle no

:SJQ 788 C

Make/Model

:HONDA CIVIC

Accident date

:11.03.2018

No	Description	Qty	Amount (\$\$)
List Items			
1	Front bumper <i>Repair (No photo)</i>	1	\$ 539 <i>x</i>
2	Front bumper side holder @ \$23.10 <i>1st</i>	2	\$ 46.2 <i>x</i>
3	Front LH fender <i>Dented</i>	1	\$ 418 <i>✓</i>
4	Front LH fender inner shield <i>2 Not Nce</i>	1	\$ 97.9 <i>x</i>
5	Front LH fender inner shield clips (1set)	1	\$ 70 <i>x</i>
6	Front LH mudflap <i>Dented</i>	1	\$ 85.8 <i>✓</i>
7	Front LH door <i>Dented</i>	1	\$ 968 <i>✓</i>
8	Front LH door protector <i>1st</i>	1	\$ 106.7 <i>✓</i>
9	Front LH door protector moulding <i>1st</i>	1	\$ <i>1685.20</i>
10	Front LH door side mirror assy <i>2nd</i>	1	\$ 628.1 <i>x</i>
11	Rear LH door protector <i>1st</i>	1	\$ 106.7 <i>✓</i>
12	Rear LH door protector moulding <i>1st</i>	1	\$ <i>1348.16</i>
13	Front LH lower arm <i>2 Not Nce</i>	1	\$ 253 <i>x</i>
14	Front LH knuckle arm <i>1st</i>	1	\$ 272.8 <i>x</i>
15	Front LH knuckle bearing <i>1st</i>	1	\$ 115.5 <i>x</i>
			\$ 3707.7
Less 20% Disc			\$ 741.54
Total			\$ 2966.16

Special Nett Items

1	Front LH sport rim <i>1st</i>	1	\$ 850 <i>400</i>
2	Front LH tyre <i>Not Nce</i>	1	\$ 380 <i>x</i>
Total			\$ 1230

Labour Costs

1	To check wheel alignment	\$ 100 <i>80</i>
2	Remove & reinstall door glass	\$ 150 <i>80</i>
3	Remove & reinstall Front LH suspension	\$ 200 <i>x</i>
4	Remove, replace & repair consistent to the accident	\$ 1000 <i>400</i>
5	Respray painting	\$ 1300 <i>800</i>
6	Tuff kote	\$ 100 <i>x</i>
Total		\$ 2850

Grand Total \$ 7046.16

Total 3108.16

1/5: 2.4.18 *✓* 04 Days

Like Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

LKK Auto Consultants Pte Ltd (Co.Reg.No.199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC3/MSG18004901/AVBN2

Date: 13/06/2018

REFERENCE

Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd.	Policy No:	80411840AVW
Claimant Vehicle No :	SJQ788C	Insured Vehicle No :	SKP2473R
Date of Loss:	11/03/2018	Nature of Claim:	TP
		Claim No:	552093

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SJQ788C	Engine No:	R18A13034299
Make & Model:	HONDA CIVIC, 1.8 L (A)	Chassis No:	JHMFD16308S215704
Reg. Date:	22/05/2008 (Man. Year: 2008)	Odometer:	302818 km
Colour:	Silver		
Engine Capacity:	1799 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	205/55 R16	Rear Tyre Size:	205/55 R16
Front Left Side:	Falken 6 mm	Rear Left Side:	Falken 6 mm
Front Right Side:	Falken 6 mm	Rear Right Side:	Falken 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS

	Repairer's	Adjuster's	Difference	Diff %
Parts	4,196.16	1,748.16	2,448.00	58.34
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,850.00	1,360.00	1,490.00	52.28
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	7,046.16	3,108.16	3,938.00	55.89
Approved Total (Overridden) (S\$)		2,400.00		
Nett Amount (S\$)	7,046.16	2,400.00	4,646.16	65.94

INSPECTION

Date of Assignment: 21/03/2018

Date Inspected: 14/03/2018 Inspected At:

Hua Meng Spray Painting Workshop (HQ)

No 1 Kaki Bukit Avenue 6, #01-61

Autobay@Kaki Bukit

Singapore 417883

Estimated Period of Repair: 4.0 days

Adjuster: ADRIAN LING

Manager: VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 13 Jun 2018)
Parts:	143	HONDA CIVIC 1.8 L (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SJQ788C)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No. Particulars	Condition	Repairer's	Amount
1	1	*FRONT BUMPER	Repair	539.00 FL	*- FL
2	2	*FRONT BUMPER SIDE HOLDER	Not Necessary	46.20 FL	*- FL
3	1	*FRONT LH FENDER	Dented	418.00 FL	*418.00 FL
4	1	*FRONT LH FENDER INNER SHIELD	Not Necessary	97.90 FL	*- FL
5	1	*SET FRONT LH FENDER INNER SHIELD CLIPS	Not Necessary	70.00 FL	*- FL
6	1	*FRONT LH MUDFLAP	Deformed	85.80 FL	*85.80 FL
7	1	*FRONT LH DOOR	Dented	968.00 FL	*968.00 FL
8	1	*FRONT LH DOOR PROTECTOR }	Cut	106.70 FL	*106.70 FL
9	1	*FRONT LH DOOR PROTECTOR MOULDING }	Necessary	0.00 FL	*- FL
10	1	*FRONT LH DOOR SIDE MIRROR ASSY	Repair	628.10 FL	*- FL
11	1	*REAR LH DOOR PROTECTOR }	Cut	106.70 FL	*106.70 FL
12	1	*REAR LH DOOR PROTECTOR MOULDING }	Necessary	0.00 FL	*- FL
13	1	*FRONT LH LOWER ARM	Not Necessary	253.00 FL	*- FL
14	1	*FRONT LH KNUCKLE ARM	Not Necessary	272.80 FL	*- FL
15	1	*FRONT LH KNUCKLE BEARING	Not Necessary	115.50 FL	*- FL
16	1	*FRONT LH SPORT RIM	Cut	850.00 FS	*400.00 FS
17	1	*FRONT LH TYRE	Not Necessary	380.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	4,937.70	2,085.20
- List Item Discount on L Items 20.00/20.00% (\$\$)	741.54	337.04
Total Parts (\$\$)	4,196.16	1,748.16

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO CHECK WHEEL ALIGNMENT	New	100.00	80.00
2	REMOVE & REINSTALL DOOR GLASS	New	150.00	80.00
3	REMOVE & REINSTALL FRONT LH SUSPENSION	New	200.00	-
4	REMOVE,REPLACE & REPAIR CONSISTENT TO THE ACCIDENT	New	1,000.00	400.00
5	RESPRAY PAINTING	New	1,300.00	800.00
6	TUFF KOTE	New	100.00	-
Gross Labour Cost (S\$)			2,850.00	1,360.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >