

22/03/2002

ASS. REC. BY:

REF: C93 / MSG18004916 / Sbz2

Special Instruction:

Range

Survivor:

Sebastian

ASSIGNMENT (Office)

From (Person):

Christina Wong

of

MSH

Date/Time: 14/3/2018 11:09am

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

GY 68346

Insured:

SL 5587K

at Workshop m/s

Kent Seng

Tel:

of

Blk 107 Yishun Ind Park A #01-240

Policy No:

715996612MY

Claim No:

557200

Sum Insured:

Excess:

Make of Veh:

D.O.A. 09/03/2018

(Client's Record)

CA / REV / REP. / REV 24 HRS WPI

H.O.D. Endorsement:

Date/Time:

15/3/2018 7:46am

Person Contacted:

Kent Seng

Vehicle IN/OUT

Date/Time	Action/Instruction (X) Estimate
	GY 68346 - NA / MSG 100103555
	SL 5587K - x
	Dismantle: 16/3/2018
	After repair: 19/3/2018

D.A.: 26052010

REF:

ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No:

at Workshop mis

of:

Insured:

Policy No:

Claims No:

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.



Bal. or Market Value:

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

4

days

Res: Yes or No

Lump Sum:

%

3 Val: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date:

Person Contacted:

Veh No:

GY 6834G

Yr Regn:

2005 Jul 05

Type: M/Car / M/Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Nissan URVAN

c.c. 2453

Colour:

Silver

A/C Insured / Std / NI / NA

Sp. Reading:

15039

T/Radio Insured / Std / NI / NA

Eng No:

C/No:

JN1M64E 23Z0713354

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modl: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

195 R/15

CST +ve

R:

11

Mic

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal.

6

mm

R/Bal.

6

mm

L/Bal.

6

mm

L/Bal.

6

mm

D.O.A.

D.O.I.

15/3/18

Survey held at

Kant Singh

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

2-3/6

u/c

Submit PRS report.

RECEIVED 14 MAY 2018

Cover/Type: File Pass to?



Preli. Report



Final Report

Date/Time: File Return to?

Days Of Repair:

4

Resurvey No. of Trip:

2

Survey Fee

Transportation

1. S + P.S. 34

2. Photos

3. Other

4

TOTAL

Add Fee:



Site Insp (\$)



Interview (\$)



Tech. Jnvs (\$)



Weekend (\$)

Report Format:

PRS

Lump Sum / L.B.I. (\$)

120

50

10

180

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	12 Mar 2018		14 Mar 2018 11:09 Assign				New Assignment Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS		[Created by insurer]							
Insured:	CHAN CHOON MUI, ID: S1751362A								
Main Claimant:	YUAN SHUN LAUNDRY SERVICE, Co. Reg. No.: 53002045M								
Vehicle Reg. No.:	GY6834G	Date of Loss:	09/03/2018 15:00 - :59						
Claim Type:	TP / 552200	Policy/Cover Note No.:	71599661QMY (Comprehensive) Coverage: 28/02/2018 - 27/02/2019						
Vehicle Reg. No. (Insured):	SLL5587K	Policy No. (Claimant):							
		Excess:	S\$500.00						
Repairer:	Kent Seng Car Services (HQ) BLK 1017 YISHUN INDUSTRIAL PARK A #01-240, 768759 Yishun - Tel:								
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Christina Wong - 6643 1311]								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Imm.Advice due 15/03/2018]								
ASSOCIATED MAIL RECEIVED		View All Compose Case Mail							
There are no mail for this case.									
ALL ASSOCIATED TASKS		View All Search Tasks Create New Task Complete							
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

15/03/2018 @ 9.46am

Kent Seng veh in

S

14. Mar. 2018 10:27

Eileen Koh

No. 4457 P. 1

MPM18055588 / Chang Hee Motor Pte Ltd - Yunnan
 ENTRY DATE & TIME: 12/03/2018 10:10
 SUBMITTED BY: CHARON CHONG BENG CHOON

CS/PAY/FA

14 MAR 2018

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorized Driver.
3. Information provided must be as truthful and accurate as possible. Any willful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report 12/03/2018 10:10
 Date Of Accident 09/03/2018 15:10
 Exact Location Of Accident ALONG CTE
 Country/State of Loss SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number GY6834G
 Insured/Policyholder
 Name Of Registered Owner YUAN SHUN LAUNDRY SERVICE
 Co Reg No 53002045M
 Email Address NOEMAIL
 Mobile Phone No (LOCAL) +65-97979709
 Alternative Phone No OFFICE-84485737
 Vehicle Particulars
 Manufacturer NISSAN
 Model URVAN 5DR
 Exact Purpose for which vehicle was being used at time of accident DELIVERY
 Are you claiming under your own insurance policy for repair to your vehicle? NO
 If No, Please state action to be taken THIRD PARTY
 Vehicle Category COMMERCIAL VEHICLE
 Insurance Company
 Name of Insurance Company SOMPO INSURANCE SINGAPORE PTE, LTD.
 Type Of Coverage THIRD PARTY
 Fleet Policy NO
 Policy Number D18MTPCVE000103
 Cover Note Number 20/01/18 - 19/01/19
 Driver
 Name of Driver LEE ICHIAN AIK
 NRIC No S1677389J
 Date Of Birth 14/03/1964
 Occupation OUTDOOR
 Date Of Driving Pass 02/04/1984
 Driving Experience 33 YEARS AND 11 MONTHS
 Gender MALE
 Mobile Number (LOCAL) +65-93600559
 Fax Number
 Contact Number
 EMail Address NOEMAIL

14. Mar. 2018 10:28

No. 4457 P. 2

Address BLK 425 YISHUN AVE 11 #05-556
 Postcode 760425
 Was driver an employee of the Insured's Company YES
 If No, Relationship of the Driver with the Insured
 Vehicle Registration Number of Driver's Own Vehicle
 Insurance Company of Driver's Own Vehicle

General Information of the Accident

Type Of Accident COLLISION - HEAD TO REAR
 Weather Conditions CLEAR
 Road Surface DRY

Other Information

Was any foreign vehicle involved in this accident? NO

Number of vehicles involved in the accident

Was any body injured in the Accident? NO

Was any injured conveyed to hospital by ambulance?

Was any other material or property damaged? YES

I have been approached by unknown person(s) soliciting/offering accident claims assistance, NO

Number of Passengers (Including Driver) 2

Passenger 1

NAME: COLLEAGUE

GENDER: MALE

Details of Police Action

Was the accident reported to the police? NO

If Yes, Please state which Police Station

Was notice of Intended Prosecution given? NO

If Yes, against whom?

Circumstances of Accident

REFER TO ATTACH. * THIRD PARTY CLAIM BY KENT SENG MOTOR REPAIRER

Attachment(s)

Are accident photos available for attachment? YES

Was there any video captured by Car Camera? NO

Was there any audio recorded? NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number 8LL5587K
 Vehicle Make/Model/Colour
 Details Of Properties
 Vehicle Category PRIVATE CAR
 Name of Driver
 NRIC/Passport Number
 Contact Number
 Address
 Postcode
 Insurance Company Name
 Nature Of Damage
 No. Of Passenger (Including Driver)

14. Mar. 2018 10:28

No. 4457 P. 3

Sketch Plan

SKETCH PLAN

VEHICLE NO: 68746
 INSURER: Sompa
 DATE & TIME: 19/3/18 @ 3:00 PM

IMPORTANT NOTICE

1. Please report promptly the details of the incident to speed up the claims process.
2. The report must be promptly made to the police and/or the authorities if required.
3. Information provided must be truthful and accurate as possible. Any willful misrepresentation or withholding of material facts may allow insurance to deny or rebut its policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any future reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers to the SIA Records Management Centre established by the SIA Insurance Act 2017 of Singapore (SIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the reporting of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available as stated.
8. Consistent with the Personal Data Protection Act (PDPA)
 - (a) I understand, acknowledge, agree and consent that:
 - (i) My insurer may, with my consent, the General Insurance Association of Singapore (GIA) may or be permitted to collect, use, disclose and/or process my personal data/personal information set out in this form and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose it to its agents and/or its subsidiaries for the purpose of all insured(s) who have insured vehicles involved in this accident (all insured(s) who have insured vehicles) involved in this accident shall be collectively referred to as the "Insured(s)"/"Insurers" lawfully, fully, fairly, the Motor Vehicle Unit of Singapore and any relevant regulatory body/authority (such as the police) for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claim in relation to the claim and any necessary investigation relating to the claim;
 - (ii) investigating the claim and/or my claim;
 - (iii) carrying out and/or dealing with my function or responding to any enquiry by me;
 - (iv) conducting my claim in relation to the claim of compensation, damages, reports or notices to me; with my consent, the disclosure of my personal data/personal information to the relevant regulatory body/authority for the purpose(s) of carrying out and/or dealing with my claim in relation to the claim and any necessary investigation relating to the claim;
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claim collectively (the "Purposes").
 - (b) All insured(s) who have insured vehicle(s) involved in this accident and the insurers' lawyers/law firms may be permitted to collect, use, disclose and/or process my personal information for one or more of the above purposes;
 - (c) my personal information may/should be disclosed by any of the insured(s)/insurers to their legal representatives or agents for the purpose(s) of the above purposes, which they have/should have agreed to in writing for one or more of the above purposes;
 - (d) my personal information will also be collected and used to compile a claim history for the purpose of fraud detection, investigation and management to prevent and all future claims;
 - (e) my personal information collected under (a) above may be shared with third parties:
 - (i) to all law enforcement agencies and/or other third parties that have a valid legal right to access or require my personal information for law enforcement and/or other purposes as lawfully required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.



Police Officer's Signature
 Date & Time:

[Signature]

Insurer's Signature
 (if involved in the policyholder's
 Date & Time:

[Signature]
 Reporting Centre Person's Signature
 Name: CYS
 NRIC/FIN No.:


17/3/18 10:28 AM

14. Mar. 2018 10:28

No. 4457 P. 4

Sketch Plan #2

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

Traffic was moderate when front vehicles brake to stop. I followed likewise. However car B behind could not stop in time and hit onto the rear of my vehicle. No one was injured.

Note: Please note that your insurer may have 14 days Time Frame for you to submit an Own Damage claim under your own comprehensive policy. Please check with your policy for more information.

DECLARATION

I/we declare the foregoing particulars are true in every respect.

Policyholder's Signature
Date & Time

Driver's Signature
(If different from the policyholder)
Date & Time

Reporting Officer's Signature
Name
NIC/Passport
Date & Time

Witness's Signature () Claim Own Policy () Claim Third Party - () Reporting Only
() Claim OET/TP at other Workshop () Key to Self () Repairer

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	12 Mar 2018		14 Mar 2018 11:09 Edit Adj Rpt	S\$0.00 Edit Estimates	S\$0.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by insurer]									
Insured: CHAN CHOON MUI , ID: S1751362A									
Main Claimant: YUAN SHUN LAUNDRY SERVICE , Co. Reg. No.: 53002045M									
Vehicle Reg. No.: GY6834G		Date of Loss: 09/03/2018 15:00 - :59 [152 Months and 4 Days From LTA Reg Date (Man Yr)]							
Claim Type: TP / 552200		Policy/Cover Note No.: 71599661QMY (Comprehensive) Coverage: 28/02/2018 - 27/02/2019							
Vehicle Reg. No. (Insured): SLL5587K		Policy No. (Claimant):							
		Excess: S\$500.00							
Repairer: Kent Seng Car Services (HQ) BLK 1017 YISHUN INDUSTRIAL PARK A #01-240, 768759 Yishun - Tel:									
Handling Insurer: MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Christina Wong - 6643 1311]									
Adjuster: LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by Sebastian Yeang Wai Keen] ... [Imm.Advice due 15/03/2018]									
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
There are no mail for this case.									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*GY6834G (552200)
[SLL5587K]
TP
YUAN SHUN LAUNDRY SERVICE
Mar 9 2018 3:00PM
[CHAN CHOON MUI]
Kent Seng Car Services

Upload Documents			Upload Photos		Compose New Letter		View		View in Browser	
Photos/Images							3 per page		☒	
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)						Thumbnail	Print	
1	30/04/18 11:49	General View						Load JPG	☒	
2	30/04/18 11:49	General View						Load JPG	☒	
3	30/04/18 11:49	General View						Load JPG	☒	
4	30/04/18 11:49	General View						Load JPG	☒	
5	30/04/18 11:49	General View						Load JPG	☒	
6	30/04/18 11:49	General View						Load JPG	☒	
7	30/04/18 11:49	General View						Load JPG	☒	
8	30/04/18 11:49	General View						Load JPG	☒	
9	30/04/18 11:49	General View						Load JPG	☒	
10	30/04/18 11:49	General View						Load JPG	☒	
11	30/04/18 11:49	General View						Load JPG	☒	
12	30/04/18 11:49	General View						Load JPG	☒	
13	30/04/18 11:49	General View						Load JPG	☒	
14	30/04/18 11:49	General View						Load JPG	☒	
15	30/04/18 11:49	General View						Load JPG	☒	
16	30/04/18 11:49	General View						Load JPG	☒	
17	30/04/18 11:49	General View						Load JPG	☒	
18	30/04/18 11:49	General View						Load JPG	☒	
19	30/04/18 11:49	General View						Load JPG	☒	
20	30/04/18 11:49	General View						Load JPG	☒	
21	30/04/18 11:49	General View						Load JPG	☒	
22	30/04/18 11:49	General View						Load JPG	☒	
23	30/04/18 11:49	General View						Load JPG	☒	
24	30/04/18 11:49	General View						Load JPG	☒	
25	30/04/18 11:49	General View						Load JPG	☒	
26	30/04/18 11:49	General View						Load JPG	☒	
27	30/04/18 11:49	General View						Load JPG	☒	
28	30/04/18 11:49	General View						Load JPG	☒	
29	30/04/18 11:49	General View						Load JPG	☒	
30	30/04/18 11:49	General View						Load JPG	☒	
31	30/04/18 11:49	General View						Load JPG	☒	
32	30/04/18 11:49	General View						Load JPG	☒	
33	30/04/18 11:49	General View						Load JPG	☒	
34	30/04/18 11:49	General View						Load JPG	☒	
35	30/04/18 11:49	General View						Load JPG	☒	
36	30/04/18 11:49	General View						Load JPG	☒	
37	30/04/18 11:49	General View						Load JPG	☒	

Photos/Images			3 per page	☒
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
38	30/04/18 11:49	General View	 Load JPG	☒
39	30/04/18 11:49	General View	 Load JPG	☒
40	30/04/18 11:49	General View	 Load JPG	☒
41	30/04/18 11:49	General View	 Load JPG	☒
42	30/04/18 11:49	General View	 Load JPG	☒
43	30/04/18 11:49	Photographs of Damaged Parts	 Load JPG	☒
44	30/04/18 11:49	Photographs of Damaged Parts	 Load JPG	☒
45	30/04/18 11:49	Photographs of Damaged Parts	 Load JPG	☒
46	30/04/18 11:49	Photographs of Damaged Parts	 Load JPG	☒
47	30/04/18 11:49	Photographs of Damaged Parts	 Load JPG	☒
48	30/04/18 11:49	Photographs of Damaged Parts	 Load JPG	☒
49	30/04/18 11:49	Photographs of Damaged Parts	 Load JPG	☒
50	30/04/18 11:49	Photographs of Damaged Parts	 Load JPG	☒
51	30/04/18 11:49	Photographs of Damaged Parts	 Load JPG	☒
52	30/04/18 11:49	Photographs of Damaged Parts	 Load JPG	☒
53	30/04/18 11:49	Photographs of Damaged Parts	 Load JPG	☒
54	30/04/18 11:49	Photographs of Damaged Parts	 Load JPG	☒
55	30/04/18 11:49	Photographs of Damaged Parts	 Load JPG	☒
56	30/04/18 11:49	Photographs of Damaged Parts	 Load JPG	☒
57	30/04/18 11:49	Photographs of Damaged Parts	 Load JPG	☒
58	30/04/18 11:49	Photographs of Damaged Parts	 Load JPG	☒
59	30/04/18 11:49	Photographs of Damaged Parts	 Load JPG	☒
60	30/04/18 11:49	Photographs of Damaged Parts	 Load JPG	☒
61	30/04/18 11:49	Photographs of Damaged Parts	 Load JPG	☒
62	30/04/18 11:50	Photo After Spray	 Load JPG	☒
63	30/04/18 11:50	Photo After Spray	 Load JPG	☒
64	30/04/18 11:50	Photo After Spray	 Load JPG	☒
65	30/04/18 11:50	Photo After Spray	 Load JPG	☒
66	30/04/18 11:50	Photo After Spray	 Load JPG	☒
67	30/04/18 11:50	Photo After Spray	 Load JPG	☒
68	30/04/18 11:50	Photo After Spray	 Load JPG	☒
69	30/04/18 11:50	Photo After Spray	 Load JPG	☒
70	30/04/18 11:50	Photo After Spray	 Load JPG	☒
71	30/04/18 11:50	Photo After Spray	 Load JPG	☒
72	30/04/18 11:50	Photo After Spray	 Load JPG	☒
73	30/04/18 11:50	Photo After Spray	 Load JPG	☒
74	30/04/18 11:50	Photo After Spray	 Load JPG	☒
75	30/04/18 11:50	Photo After Spray	 Load JPG	☒
76	30/04/18 11:50	Photo After Spray	 Load JPG	☒
77	30/04/18 11:50	Photo After Spray	 Load JPG	☒
78	30/04/18 11:50	Photo After Spray	 Load JPG	☒
79	30/04/18 11:50	Photo After Spray	 Load JPG	☒
80	30/04/18 11:50	Photo After Spray	 Load JPG	☒
Documentation			1 per page	☒
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
1	14/03/18 11:08	TP GY6834G GIA REPORT.	 Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST

Reset

Save

Print

There are no document checklists configured.

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)**Show Remarks To:** ☐ Handling Insurer

Note: Remarks are private unless you show it to other parties.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS3/MSG18004916/SBE2

Date: 15/05/2018

REFERENCE

Handling Insurer: MSIG Insurance (Singapore) Pte. Ltd.

Policy No: 71599661QMY

Claimant Vehicle No : GY6834G

Insured Vehicle No : SLL5587K

Date of Loss: 09/03/2018

Nature of Claim: TP

Claim No: 552200

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: GY6834G

Make & Model: NISSAN URVAN 5DR(D), 3.0 (A)

Engine No: ZD30002998K

Reg. Date: 05/07/2005 (Man. Year: 2005)

Chassis No: JN1MG4E25Z0713354

Colour: Silver

Odometer: 15039 km

Engine Capacity: 2953 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable):

Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification:

No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 195 R15C

Rear Tyre Size: 195 R15C

Front Left Side: CST 6 mm

Rear Left Side: Michelin 6 mm

Front Right Side: CST 6 mm

Rear Right Side: Michelin 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Nett Amount (S\$)	0.00	0.00	0.00	

INSPECTION

Date of Assignment: 14/03/2018

Date Inspected: 15/03/2018 Inspected At:

Kent Seng Car Services (HQ)
BLK 1017 YISHUN INDUSTRIAL PARK A
#01-240
Singapore 768759

Estimated Period of Repair: 0.0 days

Adjuster: Sebastian Yeang Wai Keen

Manager: CATHERINE CHONG KAI LING

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

- A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
- B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE.
- C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.

THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$2,000.00 - \$3,000.00

REPAIR DETAILS

Reference

Part Source:	(Last Synchronised: 15 May 2018)	
Parts:	N/A	NISSAN URVAN 5DR(D) 3.0 (A) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for GY6834G)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

There are no new parts selected.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.

< END OF ESTIMATES >