

REF: CS3/ALG18004917/Sb52

Special Instruction:

ASS. REC. BY:

Surveyor:

Sebastian

ASSIGNMENT (Office)

From (Person):

Chin Lee Ying

of

ALG

Date/Time: 14/03/2018 2.43pm

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SFV 3715C

Insured:

SLA 4032

at Workshop m/s

Sang Hwee Motor

Tel:

6755 7205

of

81k 1015 Yishun

Ind Park A #01-350

Policy No:

0999994959

Claim No:

G24414261386

Sum Insured:

Excess:

D.O.A.

07/03/2018

Make of Veh:

(Client's Record)

CA / REV / REP. / REV 24 HRS 'Wp'

H.O.D. Endorsement:

Date/Time:

15/03/2018 943am

Person Contacted:

Mr. Kueh

Vehicle IN/OUT

Date/Time	Action/Instruction (X) Estimate
	SFV 3715C - X
	SLA 4032 - CS3/CT116011391/Mipa353
	After repair: 26/3/2018

DA: 160616

REF:

Signature

ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Bal. or Market Value:

IDAC Accident Report:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est Repairs:

6

days

Res.: Yes or No

Lum Sum:

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date:

Person Contacted:

Date / Time / Action / Instruction

30/4

Submit DAR report.

RECEIVED 30 APR 2018

Veh No:

SFV 8725C

Regn: 27/1/2005

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Honda City VTEC A

cc 1497

Colour

Silver

A/C: Insured / Std / NI / NA

Sp. Reading

250867

T/Radio: Insured / Std / NI / NA

Eng/No:

C/No:

MKH90 86505 PG 20072

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modl: Nil / S/Rim / STD A/Rim or

Tyre Size:

F: 175/50R15

R:

BS / DUN / EXNOVA / GY / FS / LZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Falken

Front

Rear

R/Bal.

6

mm

R/Bal.

6

m

L/Bal.

6

mm

L/Bal.

6

m

D.O.A.

7/5/18

D.O.A.

15/3/18

Survey held at

Peng Hwee

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision

Date/Time, File Pass to?

☐

Prel. Report

☐

Final Report

Date/Time, File Return to?

2)

Report Format:

DAR

Lump Sum / I.B.I. (\$

Days Of Repair:

6

Resurvey No. of Trip:

1

Add Fee:

☐

Site Insp (\$

☐

Interview (\$

☐

Tech. Insp (\$

☐

Weekend (\$

Survey Fee:

Transportation:


S + RS \$

Phone

Others

TOTAL

**- FW: PRE-REPAIR INSPECTION - ACCIDENT INVOLVING OUR INSURED
VEHICLE SLA403Z AND SFV8725C ON 07/03/2018**

From: Chin, Lee-Ying
To: 'assignments', Admin A
Cc: Fong, Andy-SY
Sent: Wednesday, 14 March, 2018 2:43:27 PM
Attachments:  FaxB18F.TIF

Hi LKK,

Vehicle in, kindly assist to survey.

Thanks.

Best Regards
Lee Ying, Chin
AIG
Claims | AIG Asia Pacific Insurance Pte. Ltd.
78 Shenton Way #08-16 Singapore 079120
Tel +(65) 6419 1947 | Fax +(65) 6835 7416
Lee-Ying.Chin@aig.com | www.aig.com.sg

15/03/2018 @ 9:15am
Mr Kuch var in
S

IMPORTANT NOTICE:

The information in this email (and any attachments) is confidential. If you are not the intended recipient, you must not use or disseminate the information. If you have received this email in error, please immediately notify me by "Reply" command and permanently delete the original and any copies or printouts thereof. Although this email and any attachments are believed to be free of any virus or other defect that might affect any computer system into which it is received and opened, it is the responsibility of the recipient to ensure that it is virus free and no responsibility is accepted by American International Group, Inc. or its subsidiaries or affiliates either jointly or severally, for any loss or damage arising in any way from its use.

ONG & SHAN LLC

ADVOCATES & SOLICITORS
COMMISSIONERS FOR OATHS
NOTARIES PUBLIC

Our Counter-Signatory's Email Notifications:
Lawyer : ongshanllc@gmail.com
Secretary :

Please send all correspondences to:

- ☐ 2 Kallang Avenue #08-19 Singapore 339407
Tel: 6444 7845 | Fax: 6444 5847
- ☐ 101 Upper Cross Street #06-15B Singapore 058357
Tel: 6536 7991 | Fax: 6536 7995
- ☒ 184 Toa Payoh Central #02-364 Singapore 310184
Tel: 6224 9847 | Fax: 6254 7261

WE DO NOT ACCEPT SERVICE BY FAX

Our Ref : SRSTP.3527A.18
Your Ref : Your Insured SLA 403Z
Date : 14 March 2018

AIG Asia Pacific Insurance Pte Ltd
AIG Building
78 Shenton Way
#07-16
Singapore 079120

BY FAX ONLY 6835 7416

Dear Sirs

**NOTICE OF ACCIDENT
ROAD TRAFFIC ACCIDENT INVOLVING MOTOR VEHICLES SFV 8725C & SLA 403Z
ON 07.03.2018 ALONG ANG MO KIO SOUTH FLYOVER LAMPOST 4164 @ 2315 HRS**

We act for the owner who has appointed the under-mentioned workshop to repair their motor vehicle no. SFV 8725C.

Please be informed that the said vehicle can be inspected at:

Name of workshop : Seng Hwee Motor
Address : Blk 1018 Yishun Industrial Park A #01-350 Singapore 768760
Contact person : Mr. Kueh
Telephone no. : 6755 5205
Fax no. : 6753 4407

We hereby give you 2 clear days' notice to conduct a pre-repair inspection of the said vehicle at the above-mentioned workshop during office hours.

ONG & SHAN LLC

A LIMITED LIABILITY CORPORATION | COMPANY REGISTRATION NUMBER 201408968D

THIS DOCUMENT IS FOR THE ADDRESSEE (S) ONLY & MAY CONTAIN CONFIDENTIAL INFORMATION &/OR MAY BE SUBJECT TO LEGAL PRIVILEGE. IF YOU HAVE RECEIVED THIS IN ERROR, PLEASE CONTACT US IMMEDIATELY.

Please note that if you fail to conduct the pre-repair inspection within the next 2 working days (excluding any intervening Saturday, Sunday and/or Public Holiday) you will be deemed to have waived your rights to a pre-repair inspection. The above-mentioned workshop will commence repairs thereafter without further notice to you. They will also be entitled to claim for the additional loss of use/rental arising as a consequence of this notification.

Yours faithfully,
ONG & SHAN LLC

Cc: Client
(By Fax Only)

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the Insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	08/03/2018 12:11
Date Of Accident	07/03/2018 23:15
Exact Location Of Accident	ANG MO KIO SOUTH FLYOVER LAMPOST 4164
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SFV8725C
Insured/Policyholder	
Name Of Registered Owner	CHIA CHEW LUANG
NRIC No	S1636374Z
Email Address	NOEMAIL
Mobile Phone No	(LOCAL) +65-96278445
Alternative Phone No	OTHERS-96278445

Vehicle Particulars

Manufacturer	HONDA
Model	CITY VTEC CVT

Exact Purpose for which vehicle was being used at time of accident

Are you claiming under your own insurance policy for repair to your vehicle?

NO

If No, Please state action to be taken

THIRD PARTY

Vehicle Category

PRIVATE CAR

Insurance Company

Name of Insurance Company	AIG ASIA PACIFIC INSURANCE PTE. LTD.
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	2100240179-07
Cover Note Number	22/12/2017 TO 21/12/2018

Driver

Name of Driver	GERALD TAN ZHENG YANG
NRIC No	S9504576F
Date Of Birth	11/02/1995
Occupation	INDOOR
Date Of Driving Pass	15/09/2015
Driving Experience	2 YEARS AND 5 MONTHS
Gender	MALE
Mobile Number	+65-91149462

Fax Number

Contact Number

Email Address

GERALDTZY95@HOTMAIL.COM

Address APT BLK 227C COMPASSVALE DRIVE #10-224 (S) 543227
 Postcode
 Was driver an employee of the Insured's Company NO
 If No, Relationship of the Driver with the Insured CHILDREN
 Vehicle Registration Number of Driver's Own Vehicle -
 -
 -
 Insurance Company of Driver's Own Vehicle -
 -
 -

General Information of the Accident

Type Of Accident CHAIN COLLISION
 Weather Conditions CLEAR
 Road Surface DRY

Other Information

Was any foreign vehicle involved in this accident? NO
 Number of vehicles involved in the accident
 Was any body injured in the Accident? NO
 Was any injured conveyed to hospital by ambulance?
 Was any other material or property damaged? YES
 I have been approached by unknown person(s) soliciting/offering accident claims assistance. NO
 Number of Passengers (Including Driver) 1

Details of Police Action

Was the accident reported to the police? NO
 If Yes, Please state which Police Station
 Was notice of intended Prosecution given? NO
 If Yes, against whom?

Circumstances of Accident

refer with attach.

Attachment(s)

Are accident photos available for attachment? YES
 Was there any video captured by Car Camera? NO
 Was there any audio recorded? NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number SLA403Z
 Vehicle Make/Model/Colour NISSAN
 Details Of Properties
 Vehicle Category
 Name of Driver TAN SÖÖ CHAI
 NRIC/Passport Number S1229869B
 Contact Number 97857344
 Address
 Postcode
 Insurance Company Name
 Nature Of Damage
 No. Of Passenger (Including Driver) 2

DETAILS OF OTHER VEHICLE PROPERTY 2

Vehicle Registration Number SLD1681P
 Vehicle Make/Model/Colour TOYOTA

Details Of Properties

Vehicle Category

Name of Driver

ABDULLAH BIN ISMAIL

NRIC/Passport Number

S1193365C

Contact Number

Address

Postcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

2

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.(collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents(including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.


Policyholder's Signature
Date & Time: 8/03/2018
1225 Hrs

Driver's Signature
(If driver is not the policyholder)
Date & Time: 8/03/2018
1225 Hrs.

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:



SKETCH PLAN



A: SFV8725C

B: SLA 403Z

C: SL01681P

DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

I was driving on 3rd lane wanting to exit Ang Mo Kio Ave 3. There was a bus that brake down on the 4th lane. Suddenly, there was a sudden braking of car in front of me. I suspect that there was a few car that jump brake intent. I manage to brake and stop the car from colliding with the car in front. However, the car behind me failed to brake in time and collided with the back of my car. The impact of the collision caused my car to thrust forward colliding with the car in front of me.

Insurance Co.	Ang Asia Insurance
Vehicle No.	SFV8725C 7/3/2018
<input type="checkbox"/>	Reporting Only
<input type="checkbox"/>	Own Damage Claim
<input type="checkbox"/>	Third Party Claim
<input type="checkbox"/>	Other Workshop

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature
Date & Time: 8/03/2018
1225 Hrs.

Driver's Signature
(If driver is not the policyholder)
Date & Time: 8/03/2018
1225 Hrs.

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:



AMENDMENT

9/3/2013

A: SFV8725C

P. SLA 4032

C: ≈ 17.16812



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

[illegible]

I/We declare the foregoing particulars are true in every respect.

Driver's Signature _____
(If driver is not the policyholder)
Date & Time: 9/03/2018
1152 Hrs

Reporting Centre Personnel's Signature

Name: _____

NRIC/FIN No.: _____

9/8/2018

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	6374Z
Vehicle Details	
Vehicle No.:	SFV8725C
Vehicle to be Exported:	No
Intended De-registration Date:	30 Apr 2018
Vehicle Make:	HONDA
Vehicle Model:	CITY VTEC A
Primary Colour:	Silver
Manufacturing Year:	2005
Engine No.:	L15A13801775
Chassis No.:	MRHGD86505P020092
Maximum Power Output:	81.0 kW (108 bhp)
Open Market Value:	\$16,684.00
Original Registration Date:	22 Jun 2005
First Registration Date:	22 Jun 2005
Transfer Count:	2
Actual ARF Paid:	\$18,353.00
Intended PARF Rebate Details	
PARF Eligibility:	Forfeited
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00
Intended COE Rebate Details	
COE Expiry Date:	21 Jun 2020
COE Category:	A - Car (1600cc & below)
COE Period(Years):	5
PQP Paid:	\$33,054.00
COE Rebate Amount:	\$14,158.00
Total Rebate Amount:	\$14,158.00
Message	
Please note that the 5-year COE for this vehicle cannot be further renewed. The vehicle must be de-registered upon COE expiry or when the vehicle reaches its statutory lifespan (if applicable), whichever is earlier.	

The information contained herein is correct as at 30 Apr 2018

OK

IMPORTANT NOTE: Please submit the completed Addendum form to the same Authorised Reporting Centre with whom you submitted the Original Report.

ADDENDUM


(A) PARTICULARS OF PERSON MAKING THE AMENDMENTS:

Original Report No : MKFS18032460 Vehicle Registration No: SFV8725C
Name (as shown in NRIC) : GERALD TAN ZHENG YANG NRIC/FIN/Passport No : S9504576F
(*Vehicle Driver / Vehicle Owner) (*) Please delete as appropriate
Address : apt blk 227c compassvale drive #10-224 (s) 543227 Singapore()
Contact (Tel) : _____ Mobile No. : 91149462
Email Address : geraldtzy95@hotmail.com
Date of Accident : 07/03/2018 Time of Accident : 2315HRS
Place of Accident : ang mo kio south flyover lampost 4164
Insurance Company : AIG Asia Pacific Insurance Pte. Ltd

(B) ADDITIONAL INFORMATION / AMENDMENTS:

I have made a report on the above mentioned accident and would like to include additional information or make the following amendments:

To amend accident sketch plan.


Policyholder / Driver's Signature
Date: 9/03/2018
1152Hrs


Reporting Centre Personnel's Signature
Name: _____
NRIC/FIN No.: _____
Date: 9/3/2018

ONG & SHAN LLC

ADVOCATES & SOLICITORS
COMMISSIONERS FOR OATHS
NOTARIES PUBLIC

Our Counter-Signatory's Email Notifications:
Lawyer : ongshan@ongshanllc.com
Secretary :

Please send all correspondences to:

- ☐ 2 Kallang Avenue #08-19 Singapore 339407
Tel: 6444 7845 | Fax: 6444 5647
- ☐ 101 Upper Cross Street #06-15B Singapore 058357
Tel: 6536 7991 | Fax: 6536 7995
- ☒ 184 Toa Payoh Central #02-364 Singapore 310184
Tel: 6224 9847 | Fax: 6254 7261

WE DO NOT ACCEPT SERVICE BY FAX

Our Ref : SRSTP.3527A.18
Your Ref : Your Insured SLA 403Z
Date : 14 March 2018

AIG Asia Pacific Insurance Pte Ltd
AIG Building
78 Shenton Way
#07-16
Singapore 079120

BY FAX ONLY 6835 7416

Dear Sirs

NOTICE OF ACCIDENT

**ROAD TRAFFIC ACCIDENT INVOLVING MOTOR VEHICLES SFV 8725C & SLA 403Z
ON 07.03.2018 ALONG ANG MO KIO SOUTH FLYOVER LAMPOST 4164 @ 2315 HRS**

We act for the owner who has appointed the under-mentioned workshop to repair their motor vehicle no. SFV 8725C.

Please be informed that the said vehicle can be inspected at:

Name of workshop : Seng Hwee Motor
Address : Blk 1018 Yishun Industrial Park A #01-350 Singapore 768760
Contact person : Mr. Kueh
Telephone no. : 6755 5205
Fax no. : 6753 4407

We hereby give you 2 clear days' notice to conduct a pre-repair inspection of the said vehicle at the above-mentioned workshop during office hours.

ONG & SHAN LLC

A LIMITED LIABILITY CORPORATION | COMPANY REGISTRATION NUMBER 201408968D

THIS DOCUMENT IS FOR THE ADDRESSEE (S) ONLY & MAY CONTAIN CONFIDENTIAL INFORMATION &/OR MAY BE SUBJECT TO LEGAL PRIVILEGE. IF YOU HAVE RECEIVED THIS IN ERROR, PLEASE CONTACT US IMMEDIATELY.

EXTERIOR CAR (Pri)

Front Exterior

PAC	INC	Item	Code	AC	Qty
1001	991339	Fit Bumper Plate	DD	✓	
1002	991337	Fit Bumper Plate Base			
1003	991339	Fit Bumper Plate Garnish			
1004	991300	Fit Bumper			
1005	991341	Fit Bumper Clips	LKT	✓	
1006	991325	Fit Bumper Bracket	NGL	✓	
1007	991462	Fit Bumper Side Retainer	Deton	✓	
1008	991433	Fit Bumper Reinforcement			
1009	991118	Fit Bumper Beam	DD	✓	
1010	991468	Fit Bumper Sponge			
1011	991427	Fit Bumper Protector			
1012	991420	Fit Bumper Pad			
1013	991563	Fit Bumper Grille			
1014	991301	Fit Bumper Moulding			
1015	991407	Fit Bumper Lower Spoiler			
1016	991438	Fit Bumper Sensor			
1017	995100	Fit LH Bumper Fog Lamp Cover			
1018	991355	Fit RH Bumper Fog Lamp Cover			
1019	995079	Fit LH Bumper Fog Lamp			
1020	995080	Fit RH Bumper Fog Lamp			
1021	991793	Fit Grille			
1022	991328	Fit Grille Emblem			
1023	991799	Fit Grille Chrome Moulding	BR	✓	
1024	991222	Fit Apron Panel			
1025	992013	Fit Support Panel	DD	✓	
1026	992025	Fit Support Panel Top Garnish Cover			
1027	992416	Horn			
1028	991277	Fit Brace Panel			
1029	995153	Fit LH Headlamp Assy	CRK	✓	
1030	991821	Fit RH Headlamp Assy	SCR	✓	
1031	995088	Fit LH Side Lamp			
1032	995089	Fit RH Side Lamp			
1033	990245	Bonnet	DD	R	
1034	991323	Bonnet Emblem			
1035	990287	Bonnet Lock			
1036	990285	Bonnet Insulator			
1037	990273	Bonnet Hinge			
1038	990261	Bonnet Damper			
1039	990305	Bonnet Rubber			
1040	990252	Bonnet Cable			
1041	990311	Bonnet Stand			
1042	990119	Air Con Condenser			
1043	990122	Air Con Fan Assy			
1044	990134	Air Con Suction Pipe (Low Pressure)			
1045	990118	Air Con Suction Hose			
1046	990133	Air Con Discharge Pipe (High Pressure)			
1047	990114	Air Con Discharge Hose			
1048	990149	Air Con Liquid Pipe			
1049	995066	Air Con Receiver Drier			
1050	990111	Air Con Compressor Assy			
1051	995394	Air Con Belt			
1052	995072	Radiator			
1053	991732	Radiator Covering			
1054	991743	Radiator Fan Assy			
1055	991745	Radiator Fan Clutch			
1056	991748	Radiator Hose Top			
1057	991752	Radiator Hose Bottom			
1058	991741	Radiator Expansion Tank			
1059	990151	Air Duct			
1060	990070	Air Cleaner Assy			
1061	990056	Air Cleaner Hose			
1062	990059	Air Cleaner Resistor			
1063	991712	Fit Exhaust Manifold			
1064	991713	Fit Exhaust Manifold Cover			
1065	991034	Fit Exhaust Manifold Sensor (Oxygen)			
1066	991711	Front Exhaust Pipe			
1067	990349	Ramsey			
1068	990071	Battery Bracket			

Battery Bracket

Vehicle No: SFV 8705C

PAC	INC	Item	Code	AC	Qty
1071	992205	Fuse Box			
1072	994011	Relay Box			
1073	995053	Wiper Washer Tank	DD	✓	
1074	995052	Wiper Washer Tank Motor			
1075	990159	Alternator Assy			
1076	990160	Alternator Belt			
1077	992688	Power Steering Pump			
1078	992669	Power Steering Belt			
1079	994431	Power Steering Cooler Pipe			
1080	992692	Power Steering Hose			
1081	990010	ABS Pump Control Unit			
1082	990427	Brake Master Pump Assy			
1083	990401	Brake Booster Pump Assy			
1084	991005	Engine Top Cover			
1085	991011	Engine Under Cover			
1086	990946	Engine Mounting			
1087	990949	Engine Mounting Fit			
1088	990950	Engine Mounting LH			
1089	990952	Engine Mounting RH			
1090	990951	Engine Mounting Rear			
1091	992734	Gear Box Moulding			
1092	991520	Fit LH Chassis Member			
1093	991520	Fit RH Chassis Member			
1094	990728	Fit Vertical Cross Member			
1095	991863	Fit Lower Cross Member			
1096	995070	Fit LH Fender			
1097	995072	Fit LH Fender Inner Panel			
1098	995147	Fit LH Fender Lamp			
1099	995148	Fit LH Fender Protector			
1100	991740	Fit LH Fender Inner Shield			
1101	995179	Fit LH Mudflap			
1102	995170	Fit LH Wheel Rim			
1103	994025	Fit LH Rim Cover			
1104	995065	Fit LH Tyre			
1105	995071	Fit RH Fender			
1106	991739	Fit RH Fender Inner Panel			
1107	991744	Fit RH Fender Lamp			
1108	991752	Fit RH Fender Protector			
1109	991740	Fit RH Fender Inner Shield			
1110	991834	Fit RH Mudflap			
1111	992087	Fit RH Wheel Rim			
1112	994025	Fit RH Rim Cover			
1113	995065	Fit RH Tyre			
1114	992093	Fit Windscreen Glass			
1115	992112	Fit Windscreen Rubber			
1116	992105	Fit Windscreen Moulding			
1117	992093	Fit Windscreen Sealant			
1118	991019	ERP Bracket			
1119	991020	ERP Unit			
1120	992140	Fit Wiper Arm			
1121	992142	Fit Wiper Blade			
1122	995045	Wiper Panel Garnish			
1123	991126	Firewall Panel			
1124	990753	Dashboard Assy			
1125	991752	Glove Box Cover			
1126	992281	Glove Box Compartment			
1127	994421	Steering Wheel Airbag			
1128	994425	Steering Wheel Airbag Sensor			
1129	990749	Dashboard Airbag			
1130	990750	Dashboard Airbag Sensor			
1131	990039	Airbag Control Unit			
1132	990364	Fit Driver Seat			
1133	991032	Fit RH Seat Belt Assy			
1134	991299	Fit Passenger Seat			
1135	995182	Fit LH Seat Belt Assy			
1136	990247	Sticker			

...CLAIM SUBFOLDER...(Pending for Survey Report)

PRI

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	08 Mar 2018 Edit Reg		14 Mar 2018 00:00 Edit Adj Rpt	S\$0.00 Edit Estimates	S\$0.00 View Rpt		Pending for Survey Report Cancel Case

Main		Reference		Claim Details		Documents		Show All	
CLAIM SUBFOLDER DETAILS								[Created by adjuster]	
Insured:	BLUE STAR CONCIERGE PTD LTD, Co. Reg. No.: -								
Main Claimant:	-								
Vehicle Reg. No.:	SFV8725C			Date of Loss:	07/03/2018 00:00 - :59 [152 Months and 13 Days From LTA Reg Date (Man Yr)]				
Claim Type:	TP / 6244142613SG			Policy/Cover Note No.:	0999994959 (Comprehensive)				
Vehicle Reg. No. (Insured):	SLA403Z			Policy No. (Claimant):					
				Excess:					
Repairer:	Seng Hwee Motor (HQ) Blk 1018 Yishun Industrial Park A #01-350, 768760 Yishun - Tel: 67555205								
Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd. (Express) - Tel: 65-6419-3000 ... [Handled by Tan, Bennie-WZ - 6419 1718] Bennie-WZ.Tan@aig.com								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by Sebastian Yeang Wai Keen] ... [Final Rpt due 13/04/2018]								
Claimant's Solicitor:	ONG & SHAN LLC - Tel: 62249847								
ASSOCIATED MAIL RECEIVED								View All Compose Case Mail	
<ul style="list-style-type: none"> AIG_SG (05/04/2018): tp gia report 									
ALL ASSOCIATED TASKS								View All Search Tasks Create New Task Complete	
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*SFV8725C (6244142613SG)

[SLA403Z]

TP

-

Mar 7 2018 12:00AM

[BLUE STAR CONCIERGE PTD LTD]

Seng Hwee Motor

[Upload Documents](#)
[Upload Photos](#)
[Compose New Letter](#)
[Upload Video](#)
[Upload Audio](#)
[View](#)
[View in Browser](#)

Assessment Reports

1 per page


















































No	Finalized On	AIG Asia Pacific Insurance Pte. Ltd. (SG)	Thumbnail	Print
1	05/04/18 16:44	Accident Statement From:SC - Reg. No: SLA403Z, Claimant: BLUE STAR CONCIERGE PTE LTD	Load HTM	














































Photos/Images

3 per page



No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	04/04/18 10:04	General View	Load JPG	
2	04/04/18 10:04	General View	Load JPG	
3	04/04/18 10:04	General View	Load JPG	
4	04/04/18 10:04	General View	Load JPG	
5	04/04/18 10:04	General View	Load JPG	
6	04/04/18 10:04	General View	Load JPG	
7	04/04/18 10:04	General View	Load JPG	
8	04/04/18 10:04	General View	Load JPG	
9	04/04/18 10:04	General View	Load JPG	
10	04/04/18 10:04	General View	Load JPG	
11	04/04/18 10:04	General View	Load JPG	
12	04/04/18 10:04	General View	Load JPG	
13	04/04/18 10:04	General View	Load JPG	
14	04/04/18 10:04	General View	Load JPG	
15	04/04/18 10:04	General View	Load JPG	
16	04/04/18 10:04	General View	Load JPG	
17	04/04/18 10:04	General View	Load JPG	
18	04/04/18 10:04	General View	Load JPG	
19	04/04/18 10:04	General View	Load JPG	
20	04/04/18 10:04	General View	Load JPG	
21	04/04/18 10:04	General View	Load JPG	
22	04/04/18 10:04	General View	Load JPG	
23	04/04/18 10:04	General View	Load JPG	
24	04/04/18 10:04	General View	Load JPG	
25	04/04/18 10:04	General View	Load JPG	
26	04/04/18 10:04	General View	Load JPG	
27	04/04/18 10:04	General View	Load JPG	
28	04/04/18 10:04	General View	Load JPG	
29	04/04/18 10:04	General View	Load JPG	
30	04/04/18 10:04	General View	Load JPG	
31	04/04/18 10:04	General View	Load JPG	

Assessment Reports			1 per page ▼	✓
No	Finalized On	AIG Asia Pacific Insurance Pte. Ltd. (SG)	Thumbnail	Print
32	04/04/18 10:04	General View	 Load JPG	✓
33	04/04/18 10:04	General View	 Load JPG	✓
34	04/04/18 10:04	General View	 Load JPG	✓
35	04/04/18 10:04	General View	 Load JPG	✓
36	04/04/18 10:04	General View	 Load JPG	✓
37	04/04/18 10:04	General View	 Load JPG	✓
38	04/04/18 10:04	General View	 Load JPG	✓
39	04/04/18 10:04	General View	 Load JPG	✓
40	04/04/18 10:04	General View	 Load JPG	✓
41	04/04/18 10:04	General View	 Load JPG	✓
42	04/04/18 10:04	General View	 Load JPG	✓
43	04/04/18 10:04	General View	 Load JPG	✓
44	04/04/18 10:04	General View	 Load JPG	✓
45	04/04/18 10:04	General View	 Load JPG	✓
46	04/04/18 10:04	General View	 Load JPG	✓
47	04/04/18 10:04	General View	 Load JPG	✓
48	04/04/18 10:04	General View	 Load JPG	✓
49	04/04/18 10:04	General View	 Load JPG	✓
50	04/04/18 10:04	General View	 Load JPG	✓
51	04/04/18 10:04	General View	 Load JPG	✓
52	04/04/18 10:04	General View	 Load JPG	✓
53	04/04/18 10:04	General View	 Load JPG	✓
54	04/04/18 10:04	General View	 Load JPG	✓
55	04/04/18 10:04	General View	 Load JPG	✓
56	04/04/18 10:04	General View	 Load JPG	✓
57	04/04/18 10:04	General View	 Load JPG	✓
58	04/04/18 10:04	General View	 Load JPG	✓
59	04/04/18 10:04	General View	 Load JPG	✓
60	04/04/18 10:04	General View	 Load JPG	✓
61	04/04/18 10:04	General View	 Load JPG	✓
62	04/04/18 10:04	General View	 Load JPG	✓
63	04/04/18 10:04	General View	 Load JPG	✓
64	04/04/18 10:04	General View	 Load JPG	✓
65	04/04/18 10:04	General View	 Load JPG	✓
66	04/04/18 10:04	General View	 Load JPG	✓
67	04/04/18 10:04	General View	 Load JPG	✓
68	04/04/18 10:04	General View	 Load JPG	✓
69	04/04/18 10:04	General View	 Load JPG	✓
70	04/04/18 10:04	General View	 Load JPG	✓
71	04/04/18 10:04	General View	 Load JPG	✓
72	04/04/18 10:04	General View	 Load JPG	✓
73	04/04/18 10:04	General View	 Load JPG	✓
74	04/04/18 10:04	General View	 Load JPG	✓
75	04/04/18 10:04	General View	 Load JPG	✓
76	04/04/18 10:04	General View	 Load JPG	✓
77	04/04/18 10:04	General View	 Load JPG	✓
78	04/04/18 10:04	General View	 Load JPG	✓
79	04/04/18 10:04	General View	Load JPG	✓

Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	AIG Asia Pacific Insurance Pte. Ltd. (SG)	Thumbnail	Print
80	04/04/18 10:04	General View	 Load JPG	<input checked="" type="checkbox"/>
81	04/04/18 10:04	General View	 Load JPG	<input checked="" type="checkbox"/>
82	04/04/18 10:04	General View	 Load JPG	<input checked="" type="checkbox"/>
83	04/04/18 10:04	General View	 Load JPG	<input checked="" type="checkbox"/>
84	04/04/18 10:04	General View	 Load JPG	<input checked="" type="checkbox"/>
85	04/04/18 10:04	General View	 Load JPG	<input checked="" type="checkbox"/>
86	04/04/18 10:04	General View	 Load JPG	<input checked="" type="checkbox"/>
87	04/04/18 10:04	General View	 Load JPG	<input checked="" type="checkbox"/>
88	04/04/18 10:04	General View	 Load JPG	<input checked="" type="checkbox"/>
89	04/04/18 10:04	General View	 Load JPG	<input checked="" type="checkbox"/>
90	04/04/18 10:04	General View	 Load JPG	<input checked="" type="checkbox"/>
91	04/04/18 10:04	General View	 Load JPG	<input checked="" type="checkbox"/>
92	04/04/18 10:04	General View	 Load JPG	<input checked="" type="checkbox"/>
93	04/04/18 10:04	General View	 Load JPG	<input checked="" type="checkbox"/>
94	04/04/18 10:04	General View	 Load JPG	<input checked="" type="checkbox"/>
95	04/04/18 10:04	General View	 Load JPG	<input checked="" type="checkbox"/>
96	04/04/18 10:04	General View	 Load JPG	<input checked="" type="checkbox"/>
97	04/04/18 10:04	Chassis Number	 Load JPG	<input checked="" type="checkbox"/>
98	04/04/18 10:04	General View	 Load JPG	<input checked="" type="checkbox"/>
99	04/04/18 10:04	General View	 Load JPG	<input checked="" type="checkbox"/>
100	04/04/18 10:04	General View	 Load JPG	<input checked="" type="checkbox"/>
101	04/04/18 10:04	Odometer Reading	 Load JPG	<input checked="" type="checkbox"/>
102	04/04/18 10:04	General View	 Load JPG	<input checked="" type="checkbox"/>
103	04/04/18 10:04	General View	 Load JPG	<input checked="" type="checkbox"/>
104	04/04/18 10:04	General View	 Load JPG	<input checked="" type="checkbox"/>
105	04/04/18 10:04	General View	 Load JPG	<input checked="" type="checkbox"/>
106	04/04/18 10:04	General View	 Load JPG	<input checked="" type="checkbox"/>
107	04/04/18 10:04	General View	 Load JPG	<input checked="" type="checkbox"/>
108	30/04/18 12:27	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
109	30/04/18 12:27	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
110	30/04/18 12:27	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
111	30/04/18 12:27	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
112	30/04/18 12:27	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
113	30/04/18 12:27	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
114	30/04/18 12:27	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
115	30/04/18 12:27	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
116	30/04/18 12:27	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
117	30/04/18 12:27	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
118	30/04/18 12:27	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
119	30/04/18 12:27	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
120	30/04/18 12:27	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
121	30/04/18 12:27	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
122	30/04/18 12:27	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
123	30/04/18 12:27	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
124	30/04/18 12:27	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
125	30/04/18 12:27	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
126	30/04/18 12:27	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
127	30/04/18 12:27	Photo After Spray	Load JPG	<input checked="" type="checkbox"/>

Assessment Reports			1 per page ▼	✓
No	Finalized On	AIG Asia Pacific Insurance Pte. Ltd. (SG)	Thumbnail	Print
128	30/04/18 12:27	Photo After Spray	 Load JPG	✓
129	30/04/18 12:27	Photo After Spray	 Load JPG	✓
130	30/04/18 12:27	Photo After Spray	 Load JPG	✓
131	30/04/18 12:27	Photo After Spray	 Load JPG	✓
132	30/04/18 12:27	Photo After Spray	 Load JPG	✓
133	30/04/18 12:27	Photo After Spray	 Load JPG	✓
134	30/04/18 12:27	Photo After Spray	 Load JPG	✓
135	30/04/18 12:27	Photo After Spray	 Load JPG	✓
136	30/04/18 12:27	Photo After Spray	 Load JPG	✓
137	30/04/18 12:27	Photo After Spray	 Load JPG	✓
138	30/04/18 12:27	Photo After Spray	 Load JPG	✓
139	30/04/18 12:27	Photo After Spray	 Load JPG	✓
140	30/04/18 12:27	Photo After Spray	 Load JPG	✓
141	30/04/18 12:27	Photo After Spray	 Load JPG	✓

Documents Checklist

DOCUMENTS CHECKLIST

Reset

Save

Print

There are no document checklists configured.

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)

Show Remarks To: ☐ Handling Insurer

Note: Remarks are private unless you show it to other parties.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS3/AIG18004917/SBS2

Date: 04/05/2018

REFERENCE

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	0999994959
Claimant Vehicle No :	SFV8725C	Insured Vehicle No :	SLA403Z
Date of Loss:	07/03/2018	Nature of Claim:	TP
		Claim No:	6244142613SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SFV8725C	Engine No:	L15A13801775
Make & Model:	HONDA CITY, 1.5 VTEC (A)	Chassis No:	MRHGD86505P020092
Reg. Date:	22/06/2005 (Man. Year: 2005)	Odometer:	250567 km
Colour:	Silver		
Engine Capacity:	1497 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Fair	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	195/50R15	Rear Tyre Size:	195/50R15
Front Left Side:	Falken 6 mm	Rear Left Side:	Falken 6 mm
Front Right Side:	Falken 6 mm	Rear Right Side:	Falken 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Nett Amount (S\$)	0.00	0.00	0.00	

INSPECTION

Date of Assignment:	14/03/2018	
Date Inspected:	15/03/2018	Inspected At: Seng Hwee Motor (HQ) Blk 1018 Yishun Industrial Park A #01-350 Singapore 768760
Estimated Period of Repair:	6.0 days	

Adjuster: Sebastian Yeang Wai Keen

Manager: CATHERINE CHONG KAI LING

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Damaged	0.00 F	*- F
2	1		*REAR BUMPER CLIPS	Necessary	0.00 F	*- F
3	1		*REAR BUMPER BRACKET	Dented	0.00 F	*- F
4	1		*REAR BUMPER SIDE RETAINER	Cracked	0.00 F	*- F
5	1		*REVERSE SENSOR	Damaged	0.00 F	*- F
6	1		*REAR END PANEL	Damaged	0.00 F	*- F
7	1		*REAR END PANEL TOP GARNISH	Cut	0.00 F	*- F
8	1		*REAR END PANEL INNER TRIM RH	Broken	0.00 F	*- F
9	1		*BOOT COMPARTMENT INNER TRIM	Broken	0.00 F	*- F
10	1		*REAR RH TAILLAMP PANEL	Dented	0.00 F	*- F
11	1		*BOOTLID	Repair	0.00 F	*- F
12	1		*BOOTLID EMBLEM	Necessary	0.00 F	*- F
13	1		*SPARE TYRE BOARD	Broken	0.00 F	*- F
14	1		*SPARE TYRE PANEL	Dented	0.00 F	*- F
15	1		*REAR EXHAUST PIPE	Scratched	0.00 F	*- F
16	1		*REAR EXHAUST MOUNTING	Repair	0.00 F	*- F
17	1		*FRT NUMBER PLATE	Dented	0.00 F	*- F
18	1		*FRT BUMPER	Cut	0.00 F	*- F
19	1		*FRT BUMPER CLIPS	Necessary	0.00 F	*- F
20	1		*FRT BUMPER BRACKET	Deformed	0.00 F	*- F
21	1		*FRT BUMPER REINFORCEMENT	Dented	0.00 F	*- F
22	1		*FRT GRILLE CHROME MOULDING	Broken	0.00 F	*- F
23	1		*FRT SUPPORT PANEL	Dented	0.00 F	*- F
24	1		*FRT LH HEADLAMP ASSY	Cracked	0.00 F	*- F
25	1		*FRT RH HEADLAMP ASSY	Scratched	0.00 F	*- F
26	1		*BONNET	Repair	0.00 F	*- F
27	1		*WIPER WASHER TANK	Dented	0.00 F	*- F
Total Parts (S\$)					0.00	0.00

F=Franchise part.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.

< END OF ESTIMATES >