

22/03/2002

ASS. REC. BY:

REF:

CS3 / MSH / 8004920 / 61622

Special Instruction:

SUPERVISOR:

MORRIS

ASSIGNMENT (Office)

From (Person):

Christina Wong

of

MSH

Date/Time:

14032018 247pm

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MY / CS

To Inspect Vehicle No:

SJB 9570H

Insured:

SJH 2547R

at Workshop m/s

K- Auto Care

Tel:

of

109 Kaki Bukit Ave 1 # 01-00

Policy No:

29069366MTR

Claim No:

552252

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A.

11/032018

CA / REV / REP. / REV 24 HRS 'WP'

H.O.D. Endorsement:

Date/Time:

Person Contacted:

Vehicle IN / OUT

Date/Time	Action/Instruction (X) Estimate
	SJB 9570H - X
	SJH 2547R - X
	Dismantle Part: 15-032018

ASSIGNMENT

From: Date: 15/12/18 Veh No: SJB 9570H Yr Regn: 2008 / Jan 29
 Estimated Cost: Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
 OD (TP) / WS / TP RES / OD RES / EVA / INV / MV Truck / Trailer or
 To Inspect Vehicle No: SJB 9570H Make: Honda Civic VTL (A) c.c 1595
 at Workshop m/s K-auto Care Colour: Grey A/C: Insured / Std / NI / NA
 of 105 Kaki Bukit Ave 1 #01-00 Sp. Reading: 147714 T/Radio: Insured / Std / NI / NA
 Insured: Eng/No:
 Policy No. C/No: JHMFDA6208S200610
 Claims No. Gen. Cond: Good / Fair / Poor / Burnt
 Sum Insured: Excess: Steering: Inorder / Jammed / Leaked / Burnt or
 (Client's Record) Brake: Inorder / Jammed / Leaked / Burnt or
 Make of Veh: Modi: Nil / S/Rim / STD A/Rim or

(Policy Condition) morning
 Remark: The veh had commenced its repair at the time of inspection.
 Bal. or Market Value: Front Rear
 IDAC Accident Rpt: Consistent? : Yes or No R/Bal. 5 mm
 GIA / PR Seen: Consistent? : Yes or No L/Bal. 5 mm
 Est. Repairs: days Res.: Yes or No D.O.A. 11-12-2018 D.O.I. 15/12/18 @ 11:55am
 Lum Sum: % 3 Val: Yes or No Survey held at K-Auto Care
 CA / REV / REP. / 24 HRS Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or
 Date: Person Contacted: Vehicle: IN / OUT o/s Front
 The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction
 Estimate repair range \$7000 - \$8000
 RECEIVED 19 JUL 2018

Date/Time, File Pass to? ☐ : Preli. Report
 1) ☐ : Final Report
 Date/Time, File Return to?
 2)
 Report Format : PRQ
 Lump Sum / I.B.I: (\$)

Days Of Repair:

Resurvey No. of Trip: 1

Add Fee: ☐ : Site Insp (\$)
☐ : Interview (\$)
☐ : Tech. Invs (\$)
☐ : Weekend (\$)

Survey Fee: 120
 Transportation: 50
 S + RS: \$
 Photos
 Others: 10
 TOTAL: 180

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	14 Mar 2018		14 Mar 2018 14:47 Edit Adj Rpt				Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by insurer]									
Insured:	I WALKER AUTOMOBILE, Co. Reg. No.: NA								
Main Claimant:	TEN WEI HUAT(CHEN WEIFA), ID: S7715476J								
Vehicle Reg. No.:	SJB9570H	Date of Loss:	11/03/2018 18:00 - :59 [121 Months and 11 Days From LTA Reg Date (Man Yr)]						
Claim Type:	TP / 552252	Policy/Cover Note No.:	29069366MTR (Third Party Only) Coverage: 18/01/2018 - 17/01/2019						
Vehicle Reg. No. (Insured):	SJH2547R	Policy No. (Claimant):							
		Excess:							
Repairer:	K-auto Care Pte Ltd (HQ) 109, Kaki Bukit Ave 1, #01-00, Shun Li Industrial Park,, 415989 Kaki Bukit - Tel:								
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Christina Wong - 6643 1311]								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by XING GUO QIANG] ... [Imm.Advice due 15/03/2018]								
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
There are no mail for this case.									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete 									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

[> Back to OneMotoring](#)**Enquire PARF/COE Rebate for Registered Vehicle**

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	5476J
Vehicle Details	
Vehicle No.:	SJB9570H
Vehicle to be Exported:	No
Intended De-registration Date:	19 Jul 2018
Vehicle Make:	HONDA
Vehicle Model:	CIVIC 1.6L VTI AUTO
Primary Colour:	Grey
Manufacturing Year:	2007
Engine No.:	R16A13001979
Chassis No.:	JHMF46208S200610
Maximum Power Output:	92.0 kW (123 bhp)
Open Market Value:	\$18,919.00
Original Registration Date:	29 Jan 2008
First Registration Date:	29 Jan 2008
Transfer Count:	4
Actual ARF Paid:	\$20,811.00
Intended PARF Rebate Details	
PARF Eligibility:	Forfeited
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00
Intended COE Rebate Details	
COE Expiry Date:	28 Jan 2023
COE Category:	A - Car (1600cc & below)
COE Period(Years):	5
PQP Paid:	\$21,485.00
COE Rebate Amount:	\$19,440.00
Total Rebate Amount:	\$19,440.00
Message	
Please note that the 5-year COE for this vehicle cannot be further renewed. The vehicle must be de-registered upon COE expiry or when the vehicle reaches its statutory lifespan (if applicable), whichever is earlier.	

The information contained herein is correct as at 19 Jul 2018

OK

MVA318034119 / VAG - Kaki Bukit
 ENTRY DATE & TIME: 12/03/2018 15:13
 SUBMITTED BY: Norhaini Bte Abdul Majid

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	12/03/2018 15:13
Date Of Accident	11/03/2018 18:15
Exact Location Of Accident	LEVEL 3B CARPARK OF B/121 EDGEDALE PLAINS
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SJB9570H
Insured/Policyholder	
Name Of Registered Owner	TEN WEI HUAT (CHEN WEIFA)
NRIC No	S7715476J
Email Address	NOEMAIL
Mobile Phone No	(LOCAL) +65-90063996
Alternative Phone No	OTHERS-90063996

Vehicle Particulars

Manufacturer	HONDA
Model	CIVIC 1.6L VTI AUTO
Exact Purpose for which vehicle was being used at time of accident	
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR

Insurance Company

Name of Insurance Company	NTUC INCOME INSURANCE CO-OPERATIVE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	5097988965 CLASSIC
Cover Note Number	

Driver

Name of Driver	TEN WEI HUAT (CHEN WEIFA)
NRIC No	S7715476J
Date Of Birth	10/06/1977
Occupation	INDOOR
Date Of Driving Pass	22/10/2004
Driving Experience	13 YEARS AND 4 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-90063996
Fax Number	
Contact Number	OTHERS-90063996
Email Address	NOEMAIL

Address	BLK 121B EDGEDALE PLAINS #05-195
Postcode	822121
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OWNER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
Insurance Company of Driver's Own Vehicle	-
	-

General Information of the Accident

Type Of Accident	SIDE SWIPE
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles involved in the accident	2
Was any body injured in the Accident?	NO
Was any Injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

REFER TO SKETCH PLAN ATTACHED

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	YES
Remarks/ Reasons:	WITH OWNER
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SJH2547R
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	MOHAMMAD SUFRI BIN MASOOD
NRIC/Passport Number	
Contact Number	96159369
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

Sketch Plan Pg. 1

SKETCH PLANIMPORTANT NOTICE


1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any willful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. Consent under the Personal Data Protection Act (PDPA)
I understand, acknowledge, agree and consent that :
(a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this form and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of :
(i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
(ii) investigating the accident and/or my claims;
(iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
(iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
(v) complying with applicable law in administering, processing, handling and/or dealing with my claims.
(collectively the "Purposes")
(b) all insurer(s) who have insured vehicle(s) involved in this accident and the insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
(c) my Personal Information may/can be disclosed by any of the insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.

IBAC KAKI BUKIT (VAC)
23 Kaki Bukit Ave 4
Singapore 415933
Tel: 67416697 Fax: 67492305
Email: vackb@singnet.com.sg

Policyholder's Signature / Date & Time

Driver's Signature (if driver is not the policyholder) / Date & Time

Witnessed by Reporting Centre Personnel

Sketch Plan

Vehicle A = SJB 9570 H

Vehicle B = SJH 2547 R

Describe Circumstances of the Accident

Declaration

12/3/18

IDAC KAKI BUKIT (VAC
23 Kaki Bukit Ave 4
Singapore 415933
Tel: 67416697 Fax: 67492300
Email: vackb@singnet.com.sg

Witnessed by Reporting Centre
Personnel

...CLAIM SUBFOLDER...(Pending for Survey Report)



















































CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	14 Mar 2018		14 Mar 2018 14:47 Edit Adj Rpt	\$0.00 Edit Estimates	\$0.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by insurer]									
Insured:	I WALKER AUTOMOBILE , Co. Reg. No.: NA								
Main Claimant:	TEN WEI HUAT(CHEN WEIFA) , ID: S7715476J								
Vehicle Reg. No.:	SJB9570H	Date of Loss:	11/03/2018 18:00 - :59 [121 Months and 11 Days From LTA Reg Date (Man Yr)]						
Claim Type:	TP / 552252	Policy/Cover Note No.:	29069366MTR (Third Party Only) Coverage: 18/01/2018 - 17/01/2019						
Vehicle Reg. No. (Insured):	SJH2547R	Policy No. (Claimant):							
		Excess:							
Repairer:	K-auto Care Pte Ltd (HQ) 109, Kaki Bukit Ave 1, #01-00, Shun Li Industrial Park,, 415989 Kaki Bukit - Tel:								
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Christina Wong - 6643 1311]								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by XING GUO QIANG] ... [Imm.Advice due 15/03/2018]								
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
There are no mail for this case.									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*SJB9570H (552252)
[SJH2547R]
TP
TEN WEI HUAT(CHEN WEIFA)
Mar 11 2018 6:00PM
[I WALKER AUTOMOBILE]
K-auto Care Pte Ltd

Upload Documents			Upload Photos		Compose New Letter		View		View in Browser	
Letters/Correspondences							1 per page		<input checked="" type="checkbox"/>	
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)						Thumbnail	Print	
1	23/03/18 17:02	Acknowledgement Letter to OI From: SC - Reg. No: SJH2547R, Claimant: I WALKER AUTOMOBILE						Load HTM		
Assessment Reports							1 per page		<input checked="" type="checkbox"/>	
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)						Thumbnail	Print	
1	23/03/18 17:05	Accident Statement From: SC - Reg. No: SJH2547R, Claimant: I WALKER AUTOMOBILE						Load HTM		
Photos/Images							3 per page		<input checked="" type="checkbox"/>	
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)						Thumbnail	Print	
1	23/05/18 10:20	General View						Load JPG	<input checked="" type="checkbox"/>	
2	23/05/18 10:20	General View						Load JPG	<input checked="" type="checkbox"/>	
3	23/05/18 10:20	General View						Load JPG	<input checked="" type="checkbox"/>	
4	23/05/18 10:20	General View						Load JPG	<input checked="" type="checkbox"/>	
5	23/05/18 10:20	General View						Load JPG	<input checked="" type="checkbox"/>	
6	23/05/18 10:20	General View						Load JPG	<input checked="" type="checkbox"/>	
7	23/05/18 10:20	General View						Load JPG	<input checked="" type="checkbox"/>	
8	23/05/18 10:20	General View						Load JPG	<input checked="" type="checkbox"/>	
9	23/05/18 10:20	General View						Load JPG	<input checked="" type="checkbox"/>	
10	23/05/18 10:20	General View						Load JPG	<input checked="" type="checkbox"/>	
11	23/05/18 10:20	General View						Load JPG	<input checked="" type="checkbox"/>	
12	23/05/18 10:20	General View						Load JPG	<input checked="" type="checkbox"/>	
13	23/05/18 10:20	General View						Load JPG	<input checked="" type="checkbox"/>	
14	23/05/18 10:20	General View						Load JPG	<input checked="" type="checkbox"/>	
15	23/05/18 10:20	General View						Load JPG	<input checked="" type="checkbox"/>	
16	23/05/18 10:20	General View						Load JPG	<input checked="" type="checkbox"/>	
17	23/05/18 10:20	General View						Load JPG	<input checked="" type="checkbox"/>	
18	23/05/18 10:20	General View						Load JPG	<input checked="" type="checkbox"/>	
19	23/05/18 10:20	General View						Load JPG	<input checked="" type="checkbox"/>	
20	23/05/18 10:20	General View						Load JPG	<input checked="" type="checkbox"/>	
21	23/05/18 10:20	General View						Load JPG	<input checked="" type="checkbox"/>	
22	23/05/18 10:20	General View						Load JPG	<input checked="" type="checkbox"/>	
23	23/05/18 10:20	General View						Load JPG	<input checked="" type="checkbox"/>	
24	23/05/18 10:20	General View						Load JPG	<input checked="" type="checkbox"/>	
25	23/05/18 10:20	General View						Load JPG	<input checked="" type="checkbox"/>	
26	23/05/18 10:20	General View						Load JPG	<input checked="" type="checkbox"/>	
27	23/05/18 10:20	General View						Load JPG	<input checked="" type="checkbox"/>	
28	23/05/18 10:20	General View						Load JPG	<input checked="" type="checkbox"/>	
29	23/05/18 10:20	General View						Load JPG	<input checked="" type="checkbox"/>	

Letters/Correspondences			1 per page	<input checked="" type="checkbox"/>
No	Finalized On		Thumbnail	Print
30	23/05/18 10:20	MSIG Insurance (Singapore) Pte. Ltd. (HQ) General View	 Load JPG	<input checked="" type="checkbox"/>
31	23/05/18 10:20	General View	 Load JPG	<input checked="" type="checkbox"/>
32	23/05/18 10:20	General View	 Load JPG	<input checked="" type="checkbox"/>
33	23/05/18 10:26	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
34	23/05/18 10:26	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
35	23/05/18 10:26	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
36	23/05/18 10:26	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
37	23/05/18 10:26	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
38	23/05/18 10:26	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
39	23/05/18 10:26	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
40	23/05/18 10:26	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
41	23/05/18 10:26	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
42	23/05/18 10:26	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
43	23/05/18 10:26	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
44	23/05/18 10:26	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
45	23/05/18 10:26	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
46	23/05/18 10:26	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
47	23/05/18 10:26	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
48	23/05/18 10:26	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
49	23/05/18 10:26	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
50	23/05/18 10:26	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
51	23/05/18 10:26	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
52	23/05/18 10:26	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
53	23/05/18 10:26	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
54	23/05/18 10:26	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
55	23/05/18 10:26	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
56	23/05/18 10:26	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
57	23/05/18 10:26	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
58	23/05/18 10:26	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
59	23/05/18 10:26	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
60	23/05/18 10:26	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
61	23/05/18 10:26	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
62	23/05/18 10:26	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
63	23/05/18 10:26	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
64	23/05/18 10:26	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
65	23/05/18 10:26	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
66	23/05/18 10:26	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
67	23/05/18 10:26	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
68	23/05/18 10:26	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
69	23/05/18 10:26	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
70	23/05/18 10:26	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
71	23/05/18 10:26	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
72	23/05/18 10:26	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
73	23/05/18 10:26	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
74	23/05/18 10:26	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
75	23/05/18 10:26	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
76	23/05/18 10:26	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
77	23/05/18 10:26	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
78	23/05/18 10:26	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
79	23/05/18 10:26	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>

Letters/Correspondences				1 per page	<input checked="" type="checkbox"/>
No	Finalized On			Thumbnail	Print
80	23/05/18 10:26	MSIG Insurance (Singapore) Pte. Ltd. (HQ)			
		Photographs of Damaged Parts	1	Load JPG	<input checked="" type="checkbox"/>
81	23/05/18 10:26	Photographs of Damaged Parts	1	Load JPG	<input checked="" type="checkbox"/>
82	23/05/18 10:26	Photographs of Damaged Parts	1	Load JPG	<input checked="" type="checkbox"/>
83	23/05/18 10:26	Photographs of Damaged Parts	1	Load JPG	<input checked="" type="checkbox"/>
84	23/05/18 10:26	Photographs of Damaged Parts	1	Load JPG	<input checked="" type="checkbox"/>
Documentation				1 per page	<input checked="" type="checkbox"/>
No	Finalized On			Thumbnail	Print
1	14/03/18 14:44	MSIG Insurance (Singapore) Pte. Ltd. (HQ)			
		TP SJ89570H GIA REPORT	1	Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST		Reset	Save	Print
There are no document checklists configured.				
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ) <div style="border: 1px solid black; height: 40px; margin-top: 5px;"></div>				
Show Remarks To: <input type="checkbox"/> Handling Insurer <small>Note: Remarks are private unless you show it to other parties.</small>				

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS3/MSG18004920/GBE2

Date: 20/07/2018

REFERENCE

Handling Insurer: MSIG Insurance (Singapore) Pte. Ltd. Policy No: 29069366MTR
Claimant Vehicle No : SJB9570H **Insured Vehicle No :** SJH2547R
 Date of Loss: 11/03/2018 Nature of Claim: TP Claim No: 552252

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SJB9570H**
 Make & Model: HONDA CIVIC, 1.6 VTI (A) Engine No: R16A13001979
 Reg. Date: 29/01/2008 (Man. Year: 2007) Chassis No: JHMF46208S200610
 Colour: Grey Odometer: 147794 km
 Engine Capacity: 1595 cc
 Market Value/New Car Price: N/A
 Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition: Yes

CONDITION OF TYRES

Front Tyre Size: 215/45 R17 Rear Tyre Size: 215/45 R17
 Front Left Side: Bridgestone 5 mm Rear Left Side: Bridgestone 5 mm
 Front Right Side: Bridgestone 5 mm Rear Right Side: Bridgestone 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Nett Amount (S\$)	0.00	0.00	0.00	

INSPECTION

Date of Assignment: 14/03/2018
 Date Inspected: 15/03/2018 Inspected At: K-auto Care Pte Ltd (HQ)
 109, Kaki Bukit Ave 1, #01-00, Shun Li Industrial Park, Singapore 415989
 Estimated Period of Repair: 0.0 days

Adjuster: XING GUO QIANG

Manager: CATHERINE CHONG KAI LING

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

- A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
- B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION.
THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE.
- C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.

THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$7,000.00 - \$8,000.00

REPAIR DETAILS

Reference

Part Source: MRM-SG	Version: 1.0 (Last Synchronised: 20 Jul 2018)
Parts: 143	HONDA CIVIC 1.6 VTI (A) (Catalogue:Merimen Singapore 1.0)
Labour: Repairer's	(Price-denominated Standard List)
Print Code: (Unsubmitted, no print-code for SJB9570H)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

There are no new parts selected.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.

< END OF ESTIMATES >