

22/03/2002

ASS. REC. BY:

REF: CS/CTU8004922/Tivbez

Special Instruction:

Surveyor:

ASSIGNMENT (Office)

Mentimen

From (Person):

Irene Tay

of

CTU

Date/Time: 14/03/2018 3:23pm

Estimated Cost:

Bill to:

OD/TP/WS/TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SKX 1848H

Insured:

SLN 1428C

at Workshop m/s

Borneo motor

Tel:

6631 1857 | 9847 679

of

2 Pandan Crescent

Policy No:

DMHCSN 1735 771700

Claim No:

SNM18D01369C02

Sum Insured:

Excess:

Make of Veh:

D.O.A.

12/03/2018

(Client's Record)

CA / REV / REP. / REV 24 HRS wpi

20.03.2018 @ 11:30am - 12pm

H.O.D/Endorsement:

Date/Time:

15/03/2018 9:47am

Person Contacted:

Francis

Vehicle IN/OUT

Date/Time	Action/Instruction (✓) Estimate
	SKX 1848H - x
	SLN 1428C - x
10/4/18	@ 12:14pm Francis said vehicle has not send in for repair
11/6/18	Final fig \$ 1306 confirmed by email (Ref 1381, 5115)

Signature

Tanjong

REF: CTI

ASSIGNMENT

From: Date: 20/3/18

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: SKX 1848 H

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured: Excess:

(Client's Record)

11:30am - 12pm

Make of Veh:

Francis @ 6631 1857

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

Bal. or Market Value:

IDAC Accident Report: Consistent?: Yes or No

GIA / PR Seen: Consistent?: Yes or No

Est. Repairs: days Res.: Yes or No

Lum Sum: % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS up,

Date: Person Contacted:

Vehicle: IN / OUT

Veh No: SKX 18484 Yr Regn: 2018 Nov

Type: M/Car / M/Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Toyota 4/11s.

C.C. 1598

Colour: Grey

A/C: Insured / Std / NI / NA

Sp. Reading: 48557

T/Radio: Insured / Std / NI / NA

Eng/No:

C/No: MRO53REH 104541431

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 205/55R16

R: 11

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Continental

Front

Rear

R/Bal. 6 mm

R/Bal. 6 mm

L/Bal. 6 mm

L/Bal. 6 mm

D.O.A.

D.O.I. 20/3/18 012pm

Survey held at

Borneo Pinden.

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

RECEIVED 11 JUN 2018

Date/Time: File Pass to?

☐: Preli. Report

1)

☐: Final Report

Date/Time: File Return to?

2)

11/6 - typist

Days Of Repair: 3

Resurvey No. of Trip: 1

Survey Fee:

220

Transportation

) \$ + RS \$

) Photos

) Others

TOTAL

220

Report Format:

merimen

Lump Sum / I.B.I.: (\$

1306/-

Add Fee: ☐ Site Insp (\$☐ Interview (\$☐ Tech. Invs (\$☐ Weekend (\$



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

CHINA TAIPING INSURANCE (S) PTE LTD

Ref : CS/CTI18004922/T1vb

3 ANSON ROAD #16-00
SPRINGLEAF TOWERS SINGAPORE 079909

Date : 15-03-2018



Code : CTI

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SLN 1428C	Veh. Inspected	SKX 1848H
Policy No.	DMHCSN1735771700	Coverage (\$)	0.00
Claim No.	SNM18D01369C02	Excess (\$)	0.00
Assign From	MERIMEN (IRENE TAY)	Assign Date	14/03/2018

2. Vehicle Particulars & Condition

Make & Model	c.c	0
Engine No.	HIDDEN	Year of Reg.
Chassis No.		Colour
Odometer	-	Steering
Brakes		Modification
General		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm

4. Description of Damages

--

5. General Information

Accident Date	12/03/2018	Inspection Date	16/03/2018
Survey held at	BORNEO MOTORS (S) PTE LTD 2 PANDAN CRESCENT SINGAPORE 128462		

5a. Remarks

A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	14 Mar 2018		14 Mar 2018 15:23 Assign				New Assignment Cancel Case

Main	Reference	Claim Details	Documents	Show All
------	-----------	---------------	-----------	----------

CLAIM SUBFOLDER DETAILS [Created by insurer]

Insured:	
Main Claimant:	ONG MING HAO
Vehicle Reg. No.:	SKX1848H
Claim Type:	TP / SNM18D01369C02
Vehicle Reg. No. (Insured):	SLN1428C
Date of Loss:	12/03/2018 00:00 - :59
Policy/Cover Note No.:	DMHCSN1735771700
Policy No. (Claimant):	
Excess:	S\$0.00
Repairer:	Borneo Motors (S) Pte Ltd (Pandan) 2 Pandan Crescent, 128462 West Coast - Tel: 66311857
Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Irene Tay Hui Ping - 638986192]
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Final Rpt due 23/03/2018]
Adj Asg. Remarks:	EST \$2875.09, CASE WITH SJE.

ASSOCIATED MAIL RECEIVED View All Compose Case Mail

There are no mail for this case.

ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

15/03/2018 @ 9:47am

Francis veh not in

16/03/2018 @ 11:30am - 12pm

Veron Chen (LKKAUTO)

From: Francis Cher TCBC <francis.cher@borneomotors.com.sg>
Sent: Thursday, 31 May 2018 9:28 AM
To: Veron Chen (LKKAUTO)
Subject: RE: SKX 1848H-DOA: 12/3/18 (CHINA TAIPING TP)

Hi. Veron

Car will be in for repair next Tuesday. Will finalize with you after jobs done.
Thanks

Regards

Francis Cher

From: Veron Chen (LKKAUTO) [mailto:veronchen@lkkauto.com]
Sent: Wednesday, May 30, 2018 10:11 AM
To: Francis Cher TCBC
Subject: SKX 1848H-DOA: 12/3/18 (CHINA TAIPING TP)

Dear Francis,

Kindly advise vehicle status.

If vehicle has been repaired, please finalize with us.

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

This e-mail (and any attachment) is intended for the addressee(s) only and contains information that is legally privileged and confidential. If you are not the intended recipient, please be advised that you have received this e-mail in error and that any use, dissemination, distribution, printing or copying of this communication is unauthorized and strictly prohibited. Kindly notify us by replying to the sender's e-mail address and delete this e-mail immediately. E-mail transmissions cannot be guaranteed to be secure or error-free as information could be intercepted, corrupted, lost, destroyed, delayed or incomplete, or could contain viruses. We therefore do not accept liability for any errors or omissions in the contents of this e-mail which arise as a result of e-mail transmission, and you are advised to carry out your own virus checks and confirm the accuracy of the contents of this e-mail before relying on it for any purpose.

Tokio Marine Insurance Singapore Ltd.

(Company Reg No: 192300014M) (GST Reg No: M2-0000023-4)
20 McCallum Street #09-01 Tokio Marine Centre Singapore 069046
T: (65) 6221 6111 F: (65) 6221 4355 / (65) 6224 0895 E: tmis@tokiomarine.com.sg W: www.tokiomarine.com

A member of the
Tokio Marine Group



TOKIO MARINE
INSURANCE GROUP

Certificate of Insurance

FORM MX1

MOTOR VEHICLES (THIRD-PARTY RISKS AND COMPENSATION) ACT (CHAPTER 189)
MOTOR VEHICLES (THIRD-PARTY RISKS AND COMPENSATION) RULES, 1960
ROAD TRANSPORT ACT, 1987 (MALAYSIA)
MOTOR VEHICLES (THIRD-PARTY RISKS) RULES, 1959 (MALAYSIA)

Policy No.: MU011966 (Private Car)

SKX1848H

Chassis No.: MR053REH104541431

1. Index Mark and Registration Number of Vehicle
2. Name of Policyholder
3. Effective date of the Commencement of Insurance for the purposes of the Act
4. Date of Expiry of Insurance
5. Persons or Class of Persons entitled to drive*
(a) The Policyholder.
(b) Any other person who is driving on the Policyholder's order or with his permission.

ONG MING HAO

30/11/2017 (00:00:00)

29/11/2018

* Provided that the Person driving is permitted in accordance with the licensing or other laws or regulations to drive the Motor Vehicle or has been so permitted and is not disqualified by order of a Court of Law or by reason of any enactment or regulation in that behalf from driving the Motor Vehicle. And provided further that the Motor Vehicle is registered under the Road Traffic Act and its registration under the Road Traffic Act has not been cancelled at the time of the accident loss or damage.

6. Limitations as to use*
Use only for social domestic and pleasure purposes and for the Policyholder's business.
The policy does not cover use for hire or reward, racing, pace-making, reliability trial, speed-testing or the carriage of goods (other than samples) in connection with any trade or business or use for any purpose in connection with the Motor Trade.

* Limitations rendered inoperative by Section 8 of the Motor Vehicles (Third-Party Risks and Compensation) Act (Chapter 189) and Section 95 of the Road Transport Act, 1987 (Malaysia), are not to be included under these headings.

We hereby certify that the Policy to which this Certificate relates is issued in accordance with the provision of the Motor Vehicles (Third-Party Risks and Compensation) Act (Chapter 189) and Part IV of the Road Transport Act, 1987 (Malaysia).

Please refer to the Policy Schedule for full details, terms and conditions of the insurance.

IMPORTANT NOTICE

This Certificate is not transferable. During its currency, if the insurance is cancelled for whatsoever reason, you must return the Certificate to Tokio Marine Insurance Singapore Ltd. within 7 days thereof or, if the Certificate has been lost destroyed, you must make a statutory declaration to that effect. Failure to comply with this duty is an offence under Motor Vehicle (Third-Party Risks and Compensation) Act (Chapter 189).

ADDITIONAL INFORMATION

Account No: 2668DDA

Insurance Plan:	Comprehensive Approved Workshop Plan		
Limit for total loss or theft:	Prevailing Market Value		
Policy Excess:	Own Damage Claims	SGD 600.00	(Original Excess : SGD 600.00)
	Additional Excess for Unnamed Driver(s)	SGD 500.00	
	Additional Excess for Young or Inexperience Driver(s)	SGD 3,500.00	
	WindScreen Excess	SGD 100.00	
Financial Interest:	DBS BANK LTD		

TOKIO MARINE INSURANCE SINGAPORE LTD.

Authorised Signature

REPUBLIC OF SINGAPORE DRIVING LICENCE

Licence Number: **S8539899G**

Name: **ONG MING HAO**

Birth Date: **17 Nov 1985**

Issue Date: **20 Mar 2007**

001486777F



REPUBLIC OF SINGAPORE

IDENTITY CARD NO. **S8539899G**

Name: **ONG MING HAO**

王 銘 豪

Race: **CHINESE**

Date of birth: **17-11-1985**

Sex: **M**

Country/Place of birth: **SINGAPORE**



YOU ARE LICENSED TO DRIVE VEHICLES IN THE FOLLOWING CLASS(ES)

PASS DATE

Class 3 Motor Cars=<3000kg with =<7 passengers, exclusive of the driver; and other motor vehicles =<2500kg 20 Mar 2007

NP 428A



Licence No: S8539899G

5278728



NRIC No: S8539899G



Date of issue
22-02-2014

APT BLK 335C ANCHORVALE CRESCENT #16-70
SINGAPORE 543335
NRIC No: S8539899G

Date: 13/01/2015

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	12/03/2018 17:07
Date Of Accident	12/03/2018 07:15
Exact Location Of Accident	ALONG COMMONWEALTH DRIVE TWDS COMMONWEALTH AVE
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SKX1848H
Insured/Policyholder	
Name Of Registered Owner	ONG MING HAO
NRIC No	S8539899G
Email Address	MINGHAO.ONG@GMAIL.COM
Mobile Phone No	(LOCAL) +65-98341834
Alternative Phone No	OTHERS-98341834

Vehicle Particulars

Manufacturer	TOYOTA
Model	COROLLA ALTIS-1.6 (A)
Exact Purpose for which vehicle was being used at time of accident	NORMAL USAGE
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR

Insurance Company

Name of Insurance Company	TOKIO MARINE INSURANCE SINGAPORE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	MU011966
Cover Note Number	

Driver

Name of Driver	ONG MING HAO
NRIC No	S8539899G
Date Of Birth	17/11/1985
Occupation	INDOOR
Date Of Driving Pass	20/03/2007
Driving Experience	10 YEARS AND 11 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-98341834
Fax Number	
Contact Number	OTHERS-98341834
Email Address	MINGHAO.ONG@GMAIL.COM

Address	BLOCK 335C ANCHORVALE CRESCENT #16-70
Postcode	543335
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OWNER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	COLLISION - HEAD TO REAR
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles involved in the accident	2
Was any body injured in the Accident?	YES
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	4
Passenger 1	NAME: : LAH LIN CHIN GENDER: : FEMALE
Passenger 2	NAME: : ONG RUI ZE, WAYNE GENDER: : MALE
Passenger 3	NAME: : ONG RUI FENS GLEN GENDER: : MALE

Details of Police Action

Was the accident reported to the police?	YES
If Yes, Please state which Police Station	
Police Station Name	TRAFFIC POLICE DIVISION HQ - SINGAPORE CITY
Police Station Address	ROAD: 10 UBI AVENUE 3 , POSTCODE: 408865 , COUNTRY: SINGAPORE
Police Station Contact	TEL NO: 65470000 - FAX NO:
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

PLEASE REFER TO THE SKETCH PLAN & POLICE REPORT NO. T/20180312/7006 FOR THE CIRCUMSTANCE OF ACCIDENT.

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SLN1428C
Vehicle Make/Model/Colour	TOYOTA WISH (BLACK)
Details Of Properties	FRONT BUMPER

TYPE OF CLAIM: ☐ OD ☐ OD/UL ☐ DS

MCA: _____

MOTOR ACCIDENT REPORT

Date Of Report: 12/03/18 Time: 1600h Date Of Accident: 12/03/18 Time: 0715h
Exact Location Of Accident: Along Commonwealth Dr towards Commonwealth Ave
Country/State of Loss: Singapore ☒ / Wilayah Persekutuan ☐ / Selangor Darul Ehsan ☐ / Negeri Sembilan ☐ / Melaka ☐ / Pahang ☐ / Johor

OWN VEHICLE DETAILS (INSURED/POLICY HOLDER)

Vehicle Registration Number: SKX 1848H Co. Reg. No(for Co. Vehicle)/NRIC/PP/FIN No: 885398996
Name Of Registered Owner: Ong Ming Hw
Mobile Number: 98341834 Alternative No: Email Address: minghao.ong@gmail.com

Vehicle Particulars

Manufacturer: Toyota ☒ Lexus ☐ Suzuki ☐ Hino ☐ Model: ALTI 1.6
Exact Purpose for which vehicle was being used at time of accident: Normal Usage ☒ Other ☐ (please specify):
Are you claiming under your own insurance policy for repair to your vehicle? Yes ☐ Reporting Only ☐ Third Party ☒
Vehicle Category: Private Car ☒ Commercial Vehicle ☐ Others ☐

Insurance Company

Name of Insurance Company: Tokio Marine
Type Of Coverage: Comprehensive ☒ Third Party ☐ Third Party Fire and/or Theft ☐
Fleet Policy: Yes ☐ No ☒ Policy / Cover Note No: MU011966

DRIVER DETAILS AT POINT OF ACCIDENT

Name of Driver: Ong Ming Hw NRIC/ Passport / FIN No: 885398996
Date Of Birth: 17 Nov 1985 Occupation: Indoor ☒ Outdoor ☐
Date Of Driving Pass: 20 Mar 2007 Gender: Male ☒ Female ☐
Mobile Number: 98341834 Fax No: Alternative No:
Address: Blk 335C Anchorvale Crescent #16-70 Postal Code: 543335
Email Address:

Was driver an employee of the Insured's Company? Yes ☐ No ☒ State relationship of the driver with the insured:

Vehicle Registration Number of Driver's Own Vehicle (if applicable):

Insurance Company of Driver's Own Vehicle (if applicable):

GENERAL INFORMATION OF THE ACCIDENT

Type Of Accident: Front to back collision
Number of Passengers in the above vehicle (Including Driver): 4 / If more than 2 Pax Please fill ANNEX B

PASSENGER 1

Name: Lai Lin Chin Gender: Male ☐ Female ☒
Weather Conditions: Clear ☒ Raining ☐ Others ☐ (If others, please state condition):
Road Surface: Wet ☐ Dry ☒ Others ☐ (If others, please state condition):
Was any body injured in the Accident? No ☐ Yes ☒
Was any injured conveyed to hospital by ambulance? No ☒ Yes ☐
Was any foreign vehicle involved in this accident? No ☒ Yes ☐ Vehicle No: Vehicle type:
Number of vehicles involved in the accident: 2
Was there any witness? No ☒ Yes ☐ If yes, please furnish witness details column below
Witness Name: | Contact No.: | Email:
Was there any other vehicle or property damaged? No ☒ Yes ☐
Was there any video captured by Car Camera? No ☒ Yes ☐ Are accident scene photos available for attachment? No ☐ Yes ☒
Was the accident reported to the police? No ☐ Yes ☒ (If yes, please state which Police Station): e-reporting T/20180312/7006
Was notice of intended Prosecution given? No ☒ Yes ☐ (If yes, please state against whom):
I have been approached by unknown person(s) soliciting/offering accident claims assistance. No ☒ Yes ☐

DETAILS OF OTHER VEHICLE PROPERTY 1 (Please fill Annex A if more vehicles involved)

Vehicle Registration Number: SLN 1428C Vehicle Make/Model/Colour: Toyota Wish (Black)
Details Of Properties Damage in Accident: Front bumper
Vehicle Category: PHV
Name of Driver:
NRIC/Passport/FIN Number: Contact Number:
Address: Postal Code:
Insurance Company Name:
Nature Of Damage: Front bumper damage No. Of Passenger (Including Driver):

PASSENGER 2

Name: Ong Ruiz, Wayne

Gender: Male ☒ Female ☐

PASSENGER 3

Name: Ong Rui Fong, Glen

Gender: Male ☒ Female ☐

PASSENGER 4

Name:

Gender: Male ☐ Female ☐

PASSENGER 5

Name:

Gender: Male ☐ Female ☐

PASSENGER 6

Name:

NA

Gender: Male ☐ Female ☐

PASSENGER 7

Name:

Gender: Male ☐ Female ☐

PASSENGER 8

Name:

Gender: Male ☐ Female ☐

PASSENGER 9

Name:

Gender: Male ☐ Female ☐

PASSENGER 10

Name:

Gender: Male ☐ Female ☐

SKETCH PLAN

IMPORTANT NOTICE

1. Please report **correctly** the details of the accident to speed up the claims process.
2. This Form must be **completed by the Policyholder and/or the Authorised Driver**.
3. Information provided must be as **truthful and accurate as possible**. Any wilful misrepresentation or withholding of material facts may allow insurance companies to **repudiate policy liability**.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation**.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

(a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:

- (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
- (ii) investigating the accident and/or my claims;
- (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
- (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
- (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.

(collectively the "Purposes")

(b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and


(c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.

Policyholder's Signature / Date & Time
12/3/18
4:20 pm

Driver's Signature (If driver is not the policyholder) / Date & Time
12/3/18
4:20 pm

Witnessed by Reporting Centre Personnel

Sketch Plan



Untitled

On 12 March 2018, at around 7.15am, I was the driver of my car (SKX1848H). There were 3 other passengers in my car, namely my wife and 2 sons. I turned left into Commonwealth Drive from Queensway (after exiting AYE) and was driving along Commonwealth Drive towards Commonwealth Ave. I was driving in the vicinity of Blk 55A when I saw a small animal dash across the road. I reacted by applying an emergency brake to avoid a collision with the small animal and came to a complete stop. A 2nd car (SLN1428C) then hit the back of my vehicle.

The driver of the other car did not appear to be injured. My children did not appear to be injured at the time of making this report. My children are sitting in age appropriate child safety seats/booster seats with seat belts. However, my spouse and I experienced shoulder, neck and upper back discomfort and we went to see the doctor. My doctor issued me with painkillers and a 3 day medical certificate. My spouse has received a 2 day medical certificate from her doctor. We are using seat belts at the time of the accident.

Goh
Eng Mngs Hoo
S 8539899G

Describe Circumstances of the Accident

Please refer to attachment.

Ref: Police report

We declare the foregoing particulars are true in every respect.

Policyholder's Signature / Date &
Time 4.30 PM

Driver's Signature (If driver is not the policyholder) / Date
& Time

Witnessed by Reporting Centre
Personnel



SINGAPORE POLICE FORCE



T/20180312/7006

1 of 4

Police Station Of Origin:
Traffic Police Division HQ
10 Ubi Avenue 3 SINGAPORE 408865
Tel No: 65470000

Report No. T/20180312/7006

REPORT OF A TRAFFIC ACCIDENT

Date/Time Report Made: 12/03/2018 15:37		Vide Report No.:		Station Diary No.:	
Informant's Particulars					
Name of Informant: ONG MING HAO			Address: APT BLK 335C ANCHORVALE CRESCENT #16-70 SINGAPORE 543335		
ID Type / ID No.: NRIC NO / S8539899G			Contact No.: Home/Office: Mobile: 98341834		
Nationality: SINGAPORE CITIZEN			Email: minghao.ong@gmail.com		
Sex: Male	Age: 32	Date of Birth: 17/11/1985	Type of Informant: Driver		
Race: Chinese			Language: English		Institution / School Name:
Occupation: REGULATORY SPECIALIST			Driving Licence Information: Class: 3 Date of Expiry:		

General Information of the Accident

Type of Accident:	Injury Others	Drink Drive: No	Date/Time of Accident: 12/03/2018 07:15	Type of Location: Bend
Location: COMMONWEALTH DRIVE Commonwealth Drive towards Commonwealth Ave				
Weather: Clear		Road Surface: Dry		Road Speed Limit: 40 Km/h
Traffic Flow: Two Way		Traffic Control: Not Controlled		Traffic Volume: Light
Type of Collision: Between Moving Vehicles - Head To Rear				Anyone conveyed by ambulance: No

Details of Vehicle Involved

Vehicle No.	Type	Make	Model	Color	Condition	No of Passenger
SKX1848H	Car	TOYOTA	Altis	Grey	Slightly Damaged	3
SLN1428C	Car	TOYOTA	Wish	Black		0

Details of Vehicle Insurance

Vehicle No.	Insurance Company	Insurance No	Effective	Expiry Date
SKX1848H	TOKIO MARINE INSURANCE SINGAPORE LTD.		30/11/2017	29/11/2018



Police Station Of Origin:
Traffic Police Division HQ
10 Ubi Avenue 3 SINGAPORE 408865
Tel No: 65470000

Report No. T/20180312/7006

CONTINUATION OF REPORT

Details of Person Involved			
Any Pedestrian Involved: No			
No. of Pedestrians Injured: NIL		Use of Pedestrian Crossing: NA	
Driver			
Name	ONG MING HAO	ID No.	S8539899G
Related Vehicle	SKX1848H (Car)	Contact No.	98341834
Hospital/Clinic	NIL	Class of Driving Licence & Expiry Date	Class: 3 Date of Expiry: NIL
Date Treatment	NIL	Date Discharge	NIL
No. of Days granted Medical Leave	03	Degree of Injury	NIL
Passenger			
Name	Lah Lin Chin	ID No.	S8473356C
Related Vehicle	SKX1848H (Car)	Contact No.	96561642
Hospital/Clinic	NIL	Class of Driving Licence & Expiry Date	Class: NIL Date of Expiry: NIL
Date Treatment	NIL	Date Discharge	NIL
No. of Days granted Medical Leave	02	Degree of Injury	Slight
Passenger			
Name	Ong Rui Ze, Wayne	ID No.	T1236571Z
Related Vehicle	NIL	Contact No.	98341834
Hospital/Clinic	NIL	Class of Driving Licence & Expiry Date	Class: NIL Date of Expiry: NIL
Date Treatment	NIL	Date Discharge	NIL
No. of Days granted Medical Leave	NIL	Degree of Injury	NIL



**SINGAPORE
POLICE FORCE**



T/20180312/7006

3 of 4

Police Station Of Origin:
Traffic Police Division HQ
10 Ubi Avenue 3 SINGAPORE 408865
Tel No: 65470000

Report No. T/20180312/7006

CONTINUATION OF REPORT

Passenger			
Name	Ong Rui Feng, Glenn	ID No.	T1639217G
Related Vehicle	NIL	Contact No.	98341834
Hospital/Clinic	NIL	Class of Driving Licence & Expiry Date	Class: NIL Date of Expiry: NIL
Date Treatment	NIL	Date Discharge	NIL
No. of Days granted Medical Leave	NIL	Degree of Injury	NIL

Brief Details.

On 12 March 2018, at around 7.15am, I was the driver of my car (SKX1848H). There were 3 other passengers in my car, namely my wife and 2 sons. I turned left into Commonwealth Drive from Queensway (after exiting AYE) and was driving along Commonwealth Drive towards Commonwealth Ave. I was driving in the vicinity of Blk 55A when I saw a small animal dash across the road. I reacted by applying an emergency brake to avoid a collision with the small animal and came to a complete stop. A 2nd car (SLN1428C) then hit the back of my vehicle.

The driver of the other car did not appear to be injured. My children did not appear to be injured at the time of making this report. My children are sitting in age appropriate child safety seats/booster seats with seat belts. However, my spouse and I experienced shoulder, neck and upper back discomfort and we went to see the doctor. My doctor issued me with painkillers and a 3 day medical certificate (attached). My spouse has received a 2 day medical certificate from her doctor (attached) We are using seat belts at the time of the accident.



**SINGAPORE
POLICE FORCE**



T/20180312/7006

4 of 4

Report No. T/20180312/7006

Police Station Of Origin:
Traffic Police Division HQ
10 Ubi Avenue 3 SINGAPORE 408865
Tel No: 65470000

CONTINUATION OF REPORT

Sketch Plan

Informant is not able to provide sketch plan

Signature Of Officer Recording The Report:
Not applicable

Signature Of Interpreter:
Not applicable

Officer In Charge Of Case:

Authentication Stamp
NP168

Signature Of Informant:
The identity of the person making this report has
been authenticated by SingPass. No signature is
required.

Date/Time:
12/03/2018 15:37

Classification Of Case:



Do Reg No : 196700086Z
GST Reg No : MR-8500000-9

ESTIMATE

Join Toyota ME @ http://toyotame.borneomotors.com.sg & earn points to redeem for attractive items!

Account Detail	Account No	Customer Detail
THIRD PARTY CLAIM	S1000020 / TPCLAIM	Mr Ong Ming Hao
Document No	0	335C Anchorvale Crescent
Document Date	12/03/2018	#16-70
		Singapore 543335
		Mobile: 98341834

Year	Make	Model	Reg Date	Veh Reg No	Kilometers	WIP No	Order No/Remarks
15	GEXGKZ	S2	30/11/2015	SKX1848H	0	29945	5DS/SKX1848H/12031
Chassis No	Engine No	TWC No	Terms	Service Engineer	Vehicle In	Collected On	
MRO53REH104541431	12RY226335	60	Francis Cher T S	--/--/----	0.00	--/--/----	0.00

L	Cd	Job/Parts Description	Qty	Unit Price	Disc %	Amount
1	Z	BP-SUNDRY SUNDRIES T/P INS. : China Taiping Ins. T/P VEH. : SLN1428C ACC DATE : 12.03.18 BY :				✓ 30 50.00
2	B	BP-LAB CHK REAR WIRING SYSTEM AND CONDUCT WATER TEST.				✓ ✓ 154.00
3	B	BP-LAB DRILL HOLE TO INSTALL REVERSE SENSOR.				nnX? 154.00
4	B	BP-LAB STRAIGHTEN TAIL-LAMP PANEL.				✓ 616 770.00
		REPLACE AND REALIGN REAR BUMPER.				✓ 506 632.50
5	B	BP-RES SPRAY PAINT ON REAR BUMPER.	1.00	539.90		R 539.90
6	1	S52159-02904 COVER, RR BUMPER	1.00	386.60		nnX? 386.60
7	2	S52023-02190 REINFORCEMENT, RR				

Tan Jiah 97495749
3 days
sur @ khant.com.
Resurvey before/after repair.
-wp- 2/3/18

Borneo Motors is the only authorised workshop to maintain your Toyota. Service your Toyota every 6 months or 10,000 km (whichever comes first) to enjoy warranty benefits. Conditions apply.

For & on behalf of Borneo Motors	Customer's Signature	Change Summary	Total
	Please acknowledge receipt of vehicle	Parts 926.50 Labour 1,760.50 Materials 0.00 Lubrication/Fluid 0.00 Others 0.00	2,687.00
			GST 7.00% 188.09
			Less 0.00
			Amount Due 2,875.09

KKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

TO SECURITY GUARD

PLEASE ALLOW THE UNDERMENTIONED

VEHICLE TO LEAVE THE WORKING PREMISES.

Signature:

VEHICLE NO SKX1848H

SIGNATURE
FOR BORNEO MOTORS (SINGAPORE) PTE LTD

PLEASE TEAR ALONG PERFORATED LINE

3621472

3621472



Borneo Motor

Veron Chen (LKKAuto)

From: Veron Chen (LKKAuto)
Sent: Monday, 11 June 2018 11:04 AM
To: Francis Cher TCBC; SUR
Subject: RE: SKX1848H FINAL BILL

Dear Francis,

WITHOUT PREJUDICE

Confirmed \$1306 before GST @ 3 working days.

Final invoice and all supporting documents sent over to CHINA TAIPING INSURANCE

Best Regards,
Veron Chen | Case Handler
LKK Auto Consultants Pte Ltd
Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315
Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

-----Original Message-----

From: Francis Cher TCBC [mailto:francis.cher@borneomotors.com.sg]
Sent: Saturday, 9 June 2018 9:44 AM
To: SUR <sur@lkkauto.com>
Subject: SKX1848H FINAL BILL

Hi. Taufikh

Attached the above vehicle final bill for you to finalize.

Regards

Francis Cher

-----Original Message-----

From: francis.cher@borneomotors.com.sg [mailto:francis.cher@borneomotors.com.sg]
Sent: Saturday, June 9, 2018 9:43 AM
To: Francis Cher TCBC
Subject: Scan Data from FX-ODBC96

Sent by: B050589 [francis.cher@borneomotors.com.sg]

Number of Images: 1

Attachment File Type: PDF

Device Name: ApeosPort-V C2276

Device Location:



Co Reg No : 196700086Z
GST Reg No : MR-8500000-9

Join Toyota ME @ <http://toyotame.borneomotors.com.sg> & earn points to redeem for attractive items!

Attn: Taufikh
Final Bill
3days.

TAX INVOICE

Page 2 of 2
Borneo Motors (Singapore) Pte Ltd

Online Service Booking :
www.toyotasingsapore.com.sg
Toyota Bodycare Centre
No. 2 Pandan Crescent
Singapore 128462
Tel no.: 6631 1188

Account Detail	Account No	Customer Detail
China Taiping Insurance (S) Pte Ltd 3 Anson Road #16-00 Springleaf Tower Singapore 079909 Attn: Motor Claims Dept	S1000003 / ICCI1 Document No 38024350 Document Date 08/06/2018	Mr Ong Ming Hao 335C Anchorvale Crescent #16-70 Singapore 543335 Mobile: 98341834

Year	Make	Model	Reg Date	Veh Reg No	Kilometers	WIP No	Order No/Remarks
15	GEXGKZ	S2	ZRE171R	30/11/2015	SKX1848H	53751	31633 :5DS/SKX1848H/12031:
Chassis No	Engine No	TWC No	Terms	Service Engineer	Vehicle In	Collected On	
MRO53REH104541431	1ZRY226335	60	Francis Cher T S	08/06/2018	8.59	08/06/2018	8.59

L	Cd	Job/Parts Description	Qty	Unit Price	Disc %	Amount
1	Z	BP-SUNDRY SUNDRIES T/P INS. : CHINA TAIPING INS. T/P VEH. : SLN1428C ACC DATE : 12.03.18 BY : TAUFIKH	*			30.00
2	S	BP-SUBLET CHK REAR WIRING SYSTEM AND CONDUCT WATER TEST. PO 17079	A45			154.00
3	S	BP-SUBLET STRAIGHTEN TAIL-LAMP PANEL. REMOVE AND REALIGN REAR BUMPER. PO 17079	A45			616.00
4	S	BP-SUBLET SPRAY PAINT ON REAR BUMPER. PO 17079	A45			506.00
Borneo Motors is the only authorised workshop to maintain your Toyota. Service your Toyota every 6 months or 10,000 km (whichever comes first) to enjoy warranty benefits. Conditions apply.						

For & on behalf of Borneo Motors	Customer's Signature	Change Summary	Total
	Please acknowledge receipt of vehicle	Parts 0.00	1,306.00
		Labour 30.00	GST 7.00% 91.42
		Materials 1,276.00	Less 0.00
		Lubrication/Fluid 0.00	
		Others 0.00	Amount Due 1,397.42

PLEASE MAIL YOUR CHEQUE TO 33 LENG KEE ROAD, SINGAPORE 159102

366911:

TO SECURITY GUARD

PLEASE ALLOW THE UNDERMENTIONED
VEHICLE TO LEAVE THE COMPANY PREMISES.

DATE 08/06/2018
TIME 19:16

VEHICLE NO SKX1848H

CUSTOMER

SIGNATURE
FOR BORNEO MOTORS (SINGAPORE) PTE LTD



Borneo Motors

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	14 Mar 2018		14 Mar 2018 15:23 Edit Adj Rpt	S\$1,306.00 Edit Estimates	S\$1,306.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by insurer]									
Insured: -, Co. Reg. No.: -									
Main Claimant: ONG MING HAO									
Vehicle Reg. No.: SKX1848H		Date of Loss: 12/03/2018 00:00 - :59 [27 Months and 12 Days From LTA Reg Date (Man Yr)]							
Claim Type: TP / SNM18D01369C02		Policy/Cover Note No.: DMHCSN1735771700							
Vehicle Reg. No. (Insured): SLN1428C		Policy No. (Claimant):							
		Excess: S\$0.00							
Repairer: Borneo Motors (S) Pte Ltd (Pandan) 2 Pandan Crescent, 128462 West Coast - Tel: 66311857									
Handling Insurer: China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Irene Tay Hui Ping - 638986192]									
Adjuster: LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by MOHD TAUFIKH BIN HAMID] ... [Final Rpt due 23/03/2018]									
Adj Asg. Remarks: EST \$2875.09, CASE WITH SJE.									
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
There are no mail for this case.									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*SKX1848H (SNM18D01369C02)
[SLN1428C]
TP
ONG MING HAO
Mar 12 2018 12:00AM
[-]
Borneo Motors (S) Pte Ltd

Upload Documents			Upload Photos		Compose New Letter		View		View in Browser	
Photos/Images							3 per page		<input checked="" type="checkbox"/>	
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)						Thumbnail	Print	
1	21/03/18 11:03	General View						Load JPG	<input checked="" type="checkbox"/>	
2	21/03/18 11:03	General View						Load JPG	<input checked="" type="checkbox"/>	
3	21/03/18 11:03	General View						Load JPG	<input checked="" type="checkbox"/>	
4	21/03/18 11:03	General View						Load JPG	<input checked="" type="checkbox"/>	
5	21/03/18 11:03	General View						Load JPG	<input checked="" type="checkbox"/>	
6	21/03/18 11:03	General View						Load JPG	<input checked="" type="checkbox"/>	
7	21/03/18 11:03	General View						Load JPG	<input checked="" type="checkbox"/>	
8	21/03/18 11:03	General View						Load JPG	<input checked="" type="checkbox"/>	
9	21/03/18 11:03	General View						Load JPG	<input checked="" type="checkbox"/>	
10	21/03/18 11:03	General View						Load JPG	<input checked="" type="checkbox"/>	
11	21/03/18 11:03	General View						Load JPG	<input checked="" type="checkbox"/>	
12	21/03/18 11:03	General View						Load JPG	<input checked="" type="checkbox"/>	
13	21/03/18 11:03	General View						Load JPG	<input checked="" type="checkbox"/>	
14	21/03/18 11:03	General View						Load JPG	<input checked="" type="checkbox"/>	
15	21/03/18 11:03	General View						Load JPG	<input checked="" type="checkbox"/>	
16	21/03/18 11:03	General View						Load JPG	<input checked="" type="checkbox"/>	
17	21/03/18 11:03	General View						Load JPG	<input checked="" type="checkbox"/>	
18	21/03/18 11:03	General View						Load JPG	<input checked="" type="checkbox"/>	
19	21/03/18 11:03	General View						Load JPG	<input checked="" type="checkbox"/>	
20	21/03/18 11:03	General View						Load JPG	<input checked="" type="checkbox"/>	
21	21/03/18 11:03	General View						Load JPG	<input checked="" type="checkbox"/>	
22	21/03/18 11:03	General View						Load JPG	<input checked="" type="checkbox"/>	
23	21/03/18 11:03	General View						Load JPG	<input checked="" type="checkbox"/>	
24	21/03/18 11:03	General View						Load JPG	<input checked="" type="checkbox"/>	
25	21/03/18 11:03	General View						Load JPG	<input checked="" type="checkbox"/>	
26	21/03/18 11:03	General View						Load JPG	<input checked="" type="checkbox"/>	
27	21/03/18 11:03	General View						Load JPG	<input checked="" type="checkbox"/>	
28	21/03/18 11:03	General View						Load JPG	<input checked="" type="checkbox"/>	
29	21/03/18 11:03	General View						Load JPG	<input checked="" type="checkbox"/>	
30	21/03/18 11:03	General View						Load JPG	<input checked="" type="checkbox"/>	
Documentation							1 per page		<input checked="" type="checkbox"/>	
No	Finalized On	China Taiping Insurance (Singapore) Pte. Ltd. (HQ)						Thumbnail	Print	
1	14/03/18 15:22	TP GIA REPORT						Load PDF		
2	14/03/18 15:22	REPAIR EST						Load PDF		
3	14/05/18 10:28	Singapore Accident Statement						Load PDF		

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)**Show Remarks To:** ☐ Handling Insurer

Note: Remarks are private unless you show it to other parties.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/CTI18004922/T1VBE2

Date: 19/06/2018

REFERENCE

Handling Insurer: China Taiping Insurance
(Singapore) Pte. Ltd.

Policy No: DMHCSN1735771700

Claimant Vehicle
No : SKX1848HInsured Vehicle
No : SLN1428C

Date of Loss: 12/03/2018

Nature of Claim: TP

Claim
No: SNM18D01369C02

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SKX1848H

Make & Model: TOYOTA COROLLA ALTIS, 1.6 (A)

Engine No: 1ZRY226335

Reg. Date: 30/11/2015 (Man. Year: 2015)

Chassis No: MR053REH104541431

Colour: Grey

Odometer: 48557 km

Engine Capacity: 1598 cc

Market Value/New Car Price: N/A

Sum Insured (\$\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	205/55 R16	Rear Tyre Size:	205/55 R16
Front Left Side:	Continental 6 mm	Rear Left Side:	Continental 6 mm
Front Right Side:	Continental 6 mm	Rear Right Side:	Continental 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	976.50	30.00	946.50	96.93
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,710.50	1,276.00	434.50	25.40
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (\$\$)	2,687.00	1,306.00	1,381.00	51.40
+ GST 7.00/7.00% (\$\$)	188.09	91.42	96.67	51.40
Nett Amount (\$\$)	2,875.09	1,397.42	1,477.67	51.40

INSPECTION

Date of Assignment: 14/03/2018

Date Inspected: 20/03/2018 Inspected At:

Borneo Motors (S) Pte Ltd (Pandan)
2 Pandan Crescent
Singapore 128462

Estimated Period of Repair: 3.0 days

Adjuster: MOHD TAUFIKH BIN HAMID

Manager: VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 19 Jun 2018)
 Parts: 143 TOYOTA COROLLA ALTIS 1.6 (A) (Catalogue:Merimen Singapore 1.0)
 Labour: Repairer's (Price-denominated Standard List)
 Print Code: (Unsubmitted, no print-code for SKX1848H)
 Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
 Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*SUNDRIES	Necessary	50.00 FS	*30.00 FS
2	1		*COVER, RR BUMPER	Repair	539.90 FS	*- FS
3	1		*REINFORCEMENT, RR	Not Necessary	386.60 FS	*- FS
Total Parts (S\$)					976.50	30.00

F=Franchise part. S=SpcNett.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	CHK REAR WIRING SYSTEM AND CONDUCT WATER TEST	New	154.00	154.00
2	DRILL HOLE TO INSTALL REVERSE SENSOR	New	154.00	0.00
3	STRAIGHTEN TAIL-LAMP PANEL. REPLACE AND REALIGN REAR BUMPER	New	770.00	616.00
4	SPRAY PAINT ON REAR BUMPER	New	632.50	506.00
Gross Labour Cost (S\$)			1,710.50	1,276.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >