



SMRT Automotive Service Pte Ltd

60 Woodlands Industrial Park E4, Singapore 757705

FAX Number : 63685592



Estimator Telephone Number : 68662623

Accident Reporting Number : 68662672

SMRT Accident Vehicle Repair Estimates

Section A - To be completed by claims Advisor/Duty officer at Accident Reporting Centre

Reg. No : SG5129T
Ref. No : BUS/02/18/7035
Reg. Date : 21/02/2018
Vehicle Type : DOUBLE DECK
Make : VOLVO
Model : Volvo B9TL DD
Name of Driver : Mohamad Sahir Bin Jalal
Type of Accident : SIDE SWIPE
Date / Time of Accident : 19/02/2018 06:16:00 AM
Accident Reported Date / Time : 20/02/2018 12:00:00 AM
Surveyor is Required? : Yes
Survey by : AIG
Vehicle is Towed Back? : No
Towed Back Date/Time :
Replacement Vehicle Issued? : No
Accident Repair Job Card No :
Special Instruction to ARC, if any :
SG5129T - RIGHT REAR PORTION
PA8843L (TP) - INSURED WITH AIG
Prepared Date : 21/02/2018 04:27:19 PM



LRC Auto Consultants hence notify the Registrar of the following:

- To returner's indemnity upon getting
- To display damaged parts during recovery
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary benefit(s) must be returned and is subject to final approval from Insurance Company

Authorized by Registrar

Signature:

Date:

Section

19/3/18

- Part by part repair

- Plate After paint

Chassis No :

Mileage :

0

Work Shop :

Repair Completed Date / Time :

Summary of Repair Estimates

	Quotation from ARC	Adjusted by Surveyor, if applicable
Total Labour Charges	1,060.00	0.00
Total Spray Painting Charges	432.00	0.00
Total Material Charges	0.00	0.00
Other Charges	0.00	0.00
TOTAL	1,492.00	0.00
Lum Sum Total	0.00	0.00
No. of Repair Days	3.00	0.00
Prepared / Adjusted By		2 days
Arc / Surveyor Sing Off Date	14/03/2018 10:02:10 AM	01/01/1900 12:00:00 AM



Prepared / Adjusted Date :

Remarks :

Prepared Date : 14/03/2018 10:02:10 AM

Section C - To be Completed by Admin Assistant, Accident Repair Centre, Upon Completion of Repair

Quotation No :
Quotation Date :
Invoice Amount :

Invoice No :
Invoice Date :
Prepared Date :

Part 4 - Spare Parts / Material Usage

Part Number	Portion	Stock No	Part Name	Qty	List Price (\$)	Discount (%)	Final Price (\$)	ARC Recommended	Surveyor Approved	Photos Attached
-------------	---------	----------	-----------	-----	-----------------	--------------	------------------	-----------------	-------------------	-----------------

TOTAL MATERIALS

TOTAL MATERIALS(Discounted)								0.00	0.00	
-----------------------------	--	--	--	--	--	--	--	------	------	--

Added Spare Parts / Material Usage After Surveyor Signed off

Part Number	Portion	Part Name	Qty	List Price (\$)	Discount (%)	Final Price (\$)	ARC Check	Surveyor Check	LT Check
TOTAL SUPPLEMENTARY MATERIALS									