

PRELIMINARY ADVICE		Date/Time:	Send By:	Post-Repair Photos:	Others:
FINALIZATION		Date/Time:	Confirm with:	Confirm by:	
Repair Cost:	SS	( days)	Reduction:	%	Email <input type="checkbox"/> Call <input type="checkbox"/>
FINAL SETTLEMENT		Date/Time:	Confirm with:	Email <input type="checkbox"/> Call <input type="checkbox"/>	
Final Liability:	%	(Agreed / Assessed)	BOLA S/N No.:	If NO or B 28. Ass. Lia:	
Repair Cost	SS				
Loss of Rental (LOR)	SS	( 2.5 days)			
Loss of Use (LOU):	SS	( 5 x 2.5 days)			
Loss of Income (LOI):	SS	( 5 x 2.5 days)			
LOR only <input type="checkbox"/> LOU only <input type="checkbox"/> LOR + LOU <input type="checkbox"/> LOR + LOI <input checked="" type="checkbox"/>	(Tick only one)				
GI/LTA Search	SS			1) Claim status: None/Reject/Private Settle	
Medical:	SS			2) Report Format:	
Disbursement:	SS	(e.g. Tow/Independent)		3) Survey fee:	
Legal Cost	SS				
Total:	SS		Global Sum SS:		
FINAL PAYMENT		Date/Time:	Confirm with:	Email <input type="checkbox"/> Call <input type="checkbox"/>	
Payee 1:	SS	Name 1:			
Payee 2: (Strike if N.A.)	SS	Name 2:			
Payee 3: (Strike if N.A.)	SS	Name 3:			

Bone Kalinn

REF:

# ASSIGNMENT

From: \_\_\_\_\_ Date: \_\_\_\_\_

Estimate of cost: \_\_\_\_\_

OD / TP / IS / TP RES / OD RES / EVA / INV / MV

To Insp of Vehicle No: \_\_\_\_\_

at Work shop m/s \_\_\_\_\_

if \_\_\_\_\_

Insured: \_\_\_\_\_

Policy No \_\_\_\_\_

Claims No \_\_\_\_\_

Sum Insured: \_\_\_\_\_

Excess: \_\_\_\_\_

(Client Record)

Make of Vh: \_\_\_\_\_

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

Balance Market Value: \_\_\_\_\_

IDAC Accident Report: \_\_\_\_\_ Consistent?: Yes or No

GIA / PR Seen: \_\_\_\_\_ Consistent?: Yes or No

Est. Repair: 2 days Res.: Yes or No

Lum Sum: 2-B-2% 3 Val: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: \_\_\_\_\_ Person Contacted: \_\_\_\_\_

Veh No: \_\_\_\_\_

SH 6678M

Yr Regn: \_\_\_\_\_

12 Nov 2015

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: \_\_\_\_\_

Hyundai 240

1685

Colour: \_\_\_\_\_

Blue

A/C: Ins: 0 / Std / NI / NA

Sp. Reading: \_\_\_\_\_

38673

T/Radio: Ins: 0 / Std / NI / NA

Eng/No: \_\_\_\_\_

C/No: \_\_\_\_\_

KMHCB44A64080839

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inoper / Jammed / Leaked / Burnt or

Brake: Inoper / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD / Rlm or

Tyre Size: \_\_\_\_\_

F: \_\_\_\_\_

205 / 60 R16

R: \_\_\_\_\_

7

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Westler.

Front

Rear

R/Bal: \_\_\_\_\_

7

mm

R/Bal: \_\_\_\_\_

7

mm

L/Bal: \_\_\_\_\_

7

mm

L/Bal: \_\_\_\_\_

7

mm

D.O.A. \_\_\_\_\_

14/3/15

D.O.A. \_\_\_\_\_

15/3/15

Survey held at: \_\_\_\_\_

CDGE (Loyang)

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

N/S Front.

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

Call Lawyer before settle the case.

AJK  
JP

18/11/15

Confirm 2-B-2 \$ 12,240.00 with 2 working day

(Ad. \$ 511.98  
81%)

Dateline, File Pass to?

☐

: Prel. Report

1)

☐

: Final Report

Dateline, File Return to?

2)

Days Of Repair: \_\_\_\_\_

Resurvey No. of Trip: \_\_\_\_\_

Add Fee:

☐

: Site Insp (\$

☐

: Interview (\$

☐

: Truck Insp (\$

☐

: Road Test (\$

☐

: Other (\$

Survey Fee:

Transportation:

\$ + PS \$

Phone

Fuel

Other

Total

Read if Return

Signature of Insured

Signature of Surveyor



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

## Affiliated to Federation Internationale Des Experts En Automobile

AIG ASIA PACIFIC INSURANCE PTE LTD

Ref : CC3/AIG18004948/K1wb3

78 SHENTON WAY #08-16  
CHARTIS BUILDING  
SINGAPORE 079120

Date : 15-03-2018



Code : AIG

### 1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SKS 7887G	Veh. Inspected	SH 6678M
Policy No.		Coverage (\$)	0.00
Claim No.		Excess (\$)	0.00
Assign From		Assign Date	15/03/2018

### 2. Vehicle Particulars & Condition

Make & Model		c.c	0
Engine No.	HIDDEN	Year of Reg.	
Chassis No.		Colour	
Odometer	-	Steering	
Brakes		Modification	
General			

### 3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm

### 4. Description of Damages

--

### 5. General Information

Accident Date	14/03/2018	Inspection Date	15/03/2018
Survey held at	COMFORTDELGRO ENGINEERING PTE LTD 59 LOYANG DRIVE SINGAPORE 508969		

### 5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.
--

## REPAIR ESTIMATE\*

VEHICLE NO : SH 6678M

DATE 14/3/2018 15:21

MAKE :

MODEL : HYUNDAI i40

LKK/Kalwaie - PbyP

Like

AIG

Qty	Parts Description/ Labour	Type	Unit Price	Amount
	Front Wheel Rim (LH) <i>X see</i>			\$ 297.10
	Front Wheel Hub Cap( LH) <i>part</i>			\$ 150.70
	Front Wheel Bearing <i>X see</i>			\$ 258.50
	Front Shock Absorber (Assy) (LH) <i>✓ but</i>			\$ 342.20
	Front Shock Absorber Mounting (LH) <i>X see</i>			\$ 75.10
	Front Drive Shaft (LH) <i>X see</i>			\$ 1,069.55
	Rack & Pinion Assy <i>X see</i>			\$ 2,184.00
	STG Tie End <i>X see</i>			\$ 69.50
	Stabilizer Bar <i>X see</i>			\$ 222.50
	Stabilizer Bar Bush (LH) <i>X see</i>			\$ 13.50
	Stabilizer Bar Link <i>X see</i>			\$ 81.70
	Stabilizer Bracket <i>X see</i>			\$ 24.00
	Front Suspension Lower Arm (LH) <i>X see</i>			\$ 715.10
	Knuckle Arm (LH) <i>X see</i>			\$ 582.95
	Front Bumper side Bracket (LH) <i>ca</i>			\$ 524.60
	SUB TOTAL			\$ 5,956.85
	LESS 20%			\$ 1,191.37
	DISCOUNTED TOTAL			\$ 4,765.48
	Front Fender Advertisement Logo (LH) <i>see</i>			\$ 100.00
	Front Tyre (LH) <i>X see</i>			\$ 216.00
				\$ 316.00
	Labour Charge			
	Panel Beating- Repair Bumper			\$ 250.00
	Spray Painting Charge- Bumper/Fender			\$ 500.00
	Tuff Kote			\$ 50.00
	Remove/Refix Undercarriage (FRT)			\$ 400.00
	FRT Wheel Alignment			\$ 120.00
	TOTAL LABOUR			\$ 1,320.00
	ESTIMATE TOTAL			\$ 6,401.48

Nett

Nett

LKK Auto Consultants hence notify the Repairing Company to do the following:

- To rectify the damage on the body
- To do the necessary survey
- To provide the necessary estimate
- To provide the necessary repair

LKK Auto Consultants and the Repairing Company

Kalwaie

15/3/18 10:00 AM

2 Pys PIP

After Repair photo

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.

Team: ARC Repair TP(CLSO)1 JOB CARD Sales Order: JC NO: 305125049

CUSTOMER AS COMFORT TRANSPORTATION PTE LTD CUSTOMER NO 7010045 ADDRESS 383 SIN MING DRIVE Singapore SINGAPORE 575717 65508755		REGN NO SH 6678M	MILEAGE
		MAKE HYUNDAI	FUEL E 1/2 F
		MODEL I-40	DATE/TIME IN 14.03.2018 11:35
		YR OF MANU 12.11.2015	TARGET DATE
		CHASSIS CODE RMHLB41UMGU080439	COMPLETION DATE/TIME

AIG

Accident Date: 14.03.2018  
Nature: 3P 14.03.2018

JOB DESCRIPTION

/NO LABOR CODE DESCRIPTION

CHECKED & PASSED OUT BY:

SERVICE ADVISOR CUSTOMER'S SIGNATURE

Acknowledgement Slip

Exit Pass

No: SH 6678M LKE/KALVIN

Vehicle No.: SH 6678M

Signature/Date Name of Service Advisor Date

Returned to Service Reception upon collection To be kept by Security Guard

# COMFORTDELGRO ENGINEERING

Our Job Ref No : 305125049  
Date : 26/03/18

ComfortDelGro Engineering Pte Ltd  
59 Loyang Drive Singapore 508989  
Fax: 6546 8156

## FINALIZATION FORM

To : LKK  
Attn : Mr KALVIN ANG  
Vehicle Reg No. : SH6678M CTPL

Fax :

14.03.18

The survey and estimates of the repairs of the above-mentioned vehicle are as follows:-


1. The repair job shall bill to: AIG SKS7887G
2. The finalized amount shall be:
 

(a) Spare Parts after List discount	\$414.00
(b) Labour Charges	\$810.00
<b>Total for Part-By-Part Repair Cost</b>	<b>\$1,224.00</b>
(c.) Lumpsum Repair (if applicable)	
Total for Lumpsum repair cost after Less: <u>20%</u>	
<b>Final Lumpsum Repair cost</b>	

3. Estimated normal period for repairs: 2 working days.
4. **We shall treat the above amount as Correct and Confirmed if there is no reply from you within 7 working days**
5. Thank you for your assistance.

We confirm the estimates and finalized amount

Signature :   
Name : LIM KWOK ENG  
Tel : 62148316  
Fax : 65468156

Signature :   
Name : Kabin  
Date : 28/3/18

## For Official Use Only

Item	Amount	Document Attached Yes or No	Confirm By (Signature)	Remarks
1. Rental Rate P/Day		YES		
2. Loss of Income Paid				
3. Survey Fees				
4. LTA Search Fee				
5. Medical Fees (on behalf of driver, if applicable)				
6. Overrun				

Remarks:

\_\_\_\_\_

TYPE OF CLAIM : TP-SKS7887G  
SURVEY BY : LKR/Kalvin  
DATE : 15/3/18

[illegible]

COMPANY : THIRD PARTY'S CLAIMS (CAS)  
 CUSTOMER: 7010045  
 ADDRESS : COMFORT TRANSPORTATION PTE LTD  
 383 SIN MING DRIVE  
 SINGAPORE SINGAPORE 575717  
 65508755

JOB NO : 305125049  
 REGN NO : SH 6678M  
 MILEAGE : 0000000000  
 MAKE : HYUNDAI  
 MODEL : I-40  
 DATE OF REGN : 12.11.2015  
 DATE/TIME IN : 14.03.2018 11:35  
 ACCIDENT DATE : 14.03.2018

## JOB / PARTS DESCRIPTION

QTY IND UNIT-PRICE DISC% AMOUNT

## PART REQUISITION

0001 04-01-0103-0658-G	I40VC CAP ASSY-WHEEL HUB	1 L	150.70	20.00	120.56
0002 04-01-0103-0639-G	I40VC BRACKET-FR BUMPER S	1 L	24.60	20.00	19.68
0003 03-01-0103-0099-G	I40V2 SHOCK ABSORBER ASSY	1 L	342.20	20.00	273.76

SUB-TOTAL : 414.00

## JOB NATURE

0000 20-05	RENEW ADVERTISMENT STICKER-	100.00
0001 L	PANEL BEATING	200.00
0002 23-502	SPRAYPAINT ON AFFECTED AREA	400.00
0003 20-12	REMOVE/REFIX FRT SUSPENSION ASST REPA	50.00
0004 20-08	ADJUST FRONT WHEEL ALIGNMENT	60.00

SUB-TOTAL : 810.00



COMFORTDELGRO ENGINEERING PTE LTD

Date: 16.03.2018

REPAIR ESTIMATE

Time: 18:57:45

Page: 2

COMPANY : THIRD PARTY'S CLAIMS (CAS)  
CUSTOMER: 7010045  
ADDRESS : COMFORT TRANSPORTATION PTE LTD  
383 SIN MING DRIVE  
SINGAPORE SINGAPORE 575717  
65508755

JOB NO : 305125049  
REGN NO : SH 6678M  
MILEAGE : 0000000000  
MAKE : HYUNDAI  
MODEL : I-40  
DATE OF REGN : 12.11.2015  
DATE/TIME IN : 14.03.2018 11:35  
ACCIDENT DATE : 14.03.2018

JOB / PARTS DESCRIPTION

QTY IND UNIT-PRICE DISC% AMOUNT

TOTAL : 1,224.00

MVA NAME & SIGNATURE  
DATE :

AUTHORISED : YES / NO  
SURVEYOR NAME & SIGNATURE  
DATE :

## COMFORTDELGRO ENGINEERING PTE LTD

## REPAIR ESTIMATE\*

VEHICLE NO : SH 6678M

DATE 14/3/2018 15:21

MAKE :

MODEL : HYUNDAI i40

Qty	Parts Description/ Labour	Type	Unit Price	Amount
	Front Wheel Rim (LH) X			\$ 297.10
	Front Wheel Hub Cap( LH) ✓			\$ 150.70
	Front Wheel Bearing ?			\$ 258.50
	Front Shock Absorber (Assy) (LH) ?			\$ 212.65
	Front Shock Absorber Mounting (LH) ?			\$ 75.10
	Front Drive Shaft (LH) ?			\$ 1,069.55
	Rack & Pinion Assy ?			\$ 2,184.00
	STG Tie End ?			\$ 69.50
	Stabilizer Bar ?			\$ 222.50
	Stabilizer Bar Bush (LH) ?			\$ 13.50
	Stabilizer Bar Link ?			\$ 81.70
	Stabilizer Bracket ?			\$ 24.00
	Front Suspension Lower Arm (LH) ?			\$ 715.10
	Knuckle Arm (LH) ?			\$ 582.95
	<b>SUB TOTAL</b>			<b>\$ 5,956.85</b>
	<b>LESS 20%</b>			<b>\$ 1,191.37</b>
	<b>DISCOUNTED TOTAL</b>			<b>\$ 4,765.48</b>
	<i>Front</i> <del>Base</del> Fender Advertisement Logo (LH) ✓			\$ 100.00 <b>Nett</b>
	Front Tyre (LH) X			\$ 216.00 <b>Nett</b>
				<b>\$ 316.00</b>
	<b>Labour Charge</b>			
	Panel Beating- Repair Bumper			\$ <del>250.00</del> 200
	Spray Painting Charge- Bumper/Fender			\$ <del>500.00</del> 400
	Tuff Kote			\$ <del>50.00</del> X
	Remove/Refix Undercarriage (FRT)			\$ <del>400.00</del> X
	FRT Wheel Alignment			\$ <del>120.00</del> 60
	<b>TOTAL LABOUR</b>			<b>\$ 1,320.00</b>
	<b>ESTIMATE TOTAL</b>			<b>\$ 6,401.48</b>

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey vehicle after spray painting
- To display involved parts during resurvey
- Parts provided subject to confirmation
- Third party survey is on a "No-Prejudice" basis
- Supplementary items are subject to final survey and approval by the Insurance Company

 Acknowledged by:  
 Signature:  
 Date:

Kahru/KK

15/3/18

2 PIP

After Repair photo

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.

W

# COMFORTDELGRO ENGINEERING

Our Ref : T 0318 / SH 6678M /CL(st)  
Your Ref: \_\_\_\_\_  
Date : 3-Apr-18

**AIG ASIA PACIFIC INSURANCE PTE LTD**  
**CHARTIS Buliding**  
**78 Shenton Way**  
**#07-16**  
**Singapore 079120**

**Attn : Motor Claims Department WITHOUT PREJUDICE**

Dear Sir

**ACCIDENT INVOLVING OUR TAXI SH 6678M YOUR INSURED SKS7887G**  
**AND OTHER \_\_\_\_\_ ON 14.03.18**

We are the authorised repair workshop for Comfort Transportation Pte Ltd, the owner of motor Vehicle No : SH 6678M which was involved in the captioned accident with your insured vehicle. The vehicle owner and the taxi driver concerned have requested and authorized us to assist them in presenting their claims against the party responsible for all applicable matters arising from the damage to the vehicle.

As the accident was caused by the negligent act of your insured driving SKS7887G we are submitting these claim for your consideration on behalf of the claimants.

## TAXI OWNER'S CLAIM

1	Cost of Repair	\$ 1,309.68
2	<u>3</u> days Loss of Rental @ \$ 119.28 per day	\$ 357.84
3	Survey Report Fees ( <i>Surveyed by M/s LKK</i> )	\$ -
4	GIA / LTA Search Fees	\$ 7.49
5	GIA / Police Report Fees	\$ -
6	Towing / Medical / Transporation	\$ -
<b>Sub Total :</b>		<b>\$ 1,675.01</b>

## HIRER'S CLAIM

7	<u>3</u> days Loss of Income @ \$ 80.00 per days	\$ 240.00
<b>Total Claims :</b>		<b>\$ 1,915.01</b>

We enclosed herewith the following documents to support the claims: -

- a) Original repair bill and photocopies of photographs : 4 pcs.  
b) LTA search slip/s of : SKS7887G  
c) GIA / Police report/s of : SH 6678M  
d) Letter of authority from owner / hirer / operator  
( X ) Photograph/s of Accident Scene ( ) Certificate of Insurance  
( ) Witness statement/s ( x ) Downtime/Mileage record

Kindly look into the matter and let us hear from you on the settlement of the said claims as soon as possible.

Please note that it is a condition of any settlement reached that it shall be without prejudice to any personal injury claim (if any) of the taxi driver.

Yours faithfully

*Cecilia Lee*

Executive

CDGE Claims Department

Tel : 6214 8354 Fax: 6214 1843 Email : [cecillalee@sparkcarcare.com](mailto:cecillalee@sparkcarcare.com)

This is a computer generated letter. No signature is required.

CDGE Taxi Claims Dept

59 Loyang Drive 4th Floor  
Singapore 508969

ComfortDelGro Engineering Pte Ltd  
205 Braddell Road Singapore 579701

Mainline +65 6383 6280  
Facsimile +65 6280 9755

[www.cdge.com.sg](http://www.cdge.com.sg)

Company Registration No: 196800489

Workshops

**Braddell**  
205 Braddell Road  
Singapore 579701

**Loyang**  
59 Loyang Drive  
Singapore 508969

**Sin Ming**  
383 Sin Ming Drive  
Singapore 575717

**Pandan**  
45 Pandan Road  
Singapore 609286

**Ubi**  
320 Ubi Road 3  
Singapore 408649

**Senoko**  
24 Senoko Loop  
Singapore 758156

**Sungei Kadut**  
7 Sungei Kadut Way  
Singapore 728791

**Yishun**  
501 Yishun Industrial Park A  
Singapore 768732

A member of

**COMFORTDELGRO**



## Hsiao Tong (LKKAUTO)

---

**From:** Loh, Chee-Heng <Chee-Heng.Loh@aig.com>  
**Sent:** Wednesday, 31 October 2018 1:47 PM  
**To:** Vivian Lau (LKKAUTO)  
**Cc:** Thin Thin (LKKAUTO)  
**Subject:** RE: Your Ref : 1514934412SG, Our Ref : CC3/AIG18004948/K1wb3, ACCIDENT INVOLVING SKS 7887G (Insured) & SH 6678M ( Third Party) ON 14/03/2018 ALONG JLN AWAK BUKIT

Dear Vivian,

We will arbitrate the case to GIA if TP repairer insist to do so. We are of the view that the accident fit scenario BOLA 18, reasons as below:

- 1) TPV being the rear vehicle should fall back and not overtook OIV in the merging lanes.
- 2) The point of impact is inside the merging lanes, before the road split into a 2 lanes road.
- 3) Though insured vehicle seemed to drift to the right inside the merging lanes, it is still a merging lanes accident. Thus, highlighting the reason in point 1 that TPV should not overtake OIV in the merging lanes, and this accident could be prevented.

Kindly keep us updated on progress of the case.

Thank you.

Best regards,  
**Loh Chee Heng**  
AIG  
Complex Claims Examiner  
Claims | AIG Asia Pacific Insurance Pte. Ltd

78 Shenton Way #08-16 Singapore(079120)  
Tel +(65) 6419 1881 | Fax +(65) 6835 7416  
[Chee-Heng.Loh@aig.com](mailto:Chee-Heng.Loh@aig.com) | [www.aig.com.sg](http://www.aig.com.sg)

Follow us:



### IMPORTANT NOTICE:

*The information in this email (and any attachments) is confidential. If you are not the intended recipient, you must not use or disseminate the information. If you have received this email in error, please immediately notify me by "Reply" command and permanently delete the original and any copies or printouts thereof. Although this email and any attachments are believed to be free of any virus or other defect that might affect any computer system into which it is received and opened, it is the responsibility of the recipient to ensure that it is virus free and no responsibility is accepted by AIG for any loss or damage arising in any way from its use.*

---

**From:** Vivian Lau (LKKAUTO) [mailto:vivianlau@lkkauto.com]  
**Sent:** Friday, September 28, 2018 10:47 AM  
**To:** Loh, Chee-Heng  
**Cc:** Thin Thin (LKKAUTO)  
**Subject:** RE: Your Ref : 1514934412SG, Our Ref : CC3/AIG18004948/K1wb3, ACCIDENT INVOLVING SKS 7887G (Insured) & SH 6678M ( Third Party) ON 14/03/2018 ALONG JLN AWAK BUKIT

Dear Chee Heng,

We refer to the email below.

AS per instruction we offer TP 50%, TP rejected our offer as below.

Your 50% offer is ungrounded. The collision happened at the single lane while your insured squeezed through from left that caused the accident.

If TP there is no full settlement TP will escalate the matter to GIA DRM for resolution.

Kindly advice on your view/opinion/instruction for this claim

Thank you

Best Regards,

**Vivian Lau** | Case Handler

**LKK Auto Consultants Pte Ltd**

Phone: 6841-8625 | email: [Vivianlau@lkkauto.com](mailto:Vivianlau@lkkauto.com) | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

---

**From:** Loh, Chee-Heng [mailto:[Chee-Heng.Loh@aig.com](mailto:Chee-Heng.Loh@aig.com)]

**Sent:** Wednesday, 23 May, 2018 7:26 PM

**To:** Vivian Lau (LKKAuto) <[vivianlau@lkkauto.com](mailto:vivianlau@lkkauto.com)>

**Cc:** Thin Thin (LKKAuto) <[thinthin@lkkauto.com](mailto:thinthin@lkkauto.com)>

**Subject:** RE: Your Ref : 1514934412SG, Our Ref : CC3/AIG18004948/K1wb3, ACCIDENT INVOLVING SKS 7887G (Insured) & SH 6678M ( Third Party) ON 14/03/2018 ALONG JLN AWAK BUKIT

Dear Vivian,

Ivy has informed OI that will offer 50% for BI claim.

You may proceed to offer 50% per BOLA 18, merging lanes.

Thank you.

Best regards,

**Loh Chee Heng**

**AIG**

Complex Claims Examiner

Claims | AIG Asia Pacific Insurance Pte. Ltd

78 Shenton Way #08-16 Singapore(079120)

Tel +(65) 6419 1881 | Fax +(65) 6835 7416

[Chee-Heng.Loh@aig.com](mailto:Chee-Heng.Loh@aig.com) | [www.aig.com.sg](http://www.aig.com.sg)

**Follow us:**



**IMPORTANT NOTICE:**

*The information in this email (and any attachments) is confidential. If you are not the intended recipient, you must not use or disseminate the information. If you have received this email in error, please immediately notify me by "Reply" command and permanently delete the original and any copies or printouts thereof. Although this email and any attachments are believed to be free of any virus or other defect that might affect any*

---

**From:** Vivian Lau (LKKAuto) [<mailto:vivianlau@lkkauto.com>]  
**Sent:** Thursday, May 17, 2018 2:05 PM  
**To:** Loh, Chee-Heng  
**Cc:** Thin Thin (LKKAuto); Yong, Ivy-AV  
**Subject:** RE: Your Ref : 1514934412SG, Our Ref : CC3/AIG18004948/K1wb3, ACCIDENT INVOLVING SKS 7887G (Insured) & SH 6678M ( Third Party) ON 14/03/2018 ALONG JLN AWAK BUKIT

Dear Chee Heng,

We refer to the email below.

Please be informed that we do not have OI's email address.

Thank you  
Best Regards,  
**Vivian Lau** | Case Handler  
**LKK Auto Consultants Pte Ltd**  
Phone: 6841-8625 | email: [Vivianlau@lkkauto.com](mailto:Vivianlau@lkkauto.com) | fax: 6741-4108  
Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

---

**From:** Loh, Chee-Heng [<mailto:Chee-Heng.Loh@aig.com>]  
**Sent:** Wednesday, 16 May, 2018 11:23 AM  
**To:** Vivian Lau (LKKAuto) <[vivianlau@lkkauto.com](mailto:vivianlau@lkkauto.com)>  
**Cc:** Thin Thin (LKKAuto) <[thinthin@lkkauto.com](mailto:thinthin@lkkauto.com)>; Yong, Ivy-AV <[Ivy-AV.Yong@aig.com](mailto:Ivy-AV.Yong@aig.com)>  
**Subject:** RE: Your Ref : 1514934412SG, Our Ref : CC3/AIG18004948/K1wb3, ACCIDENT INVOLVING SKS 7887G (Insured) & SH 6678M ( Third Party) ON 14/03/2018 ALONG JLN AWAK BUKIT

Dear Vivian,

Ivy is handling the third party BI claim.

Do you have OI's email address? We would like to email TP's video footage for OI's viewing.

Thank you.

Best regards,  
**Loh Chee Heng**  
**AIG**  
Complex Claims Examiner  
Claims | AIG Asia Pacific Insurance Pte. Ltd

78 Shenton Way #08-16 Singapore(079120)  
Tel +(65) 6419 1881 | Fax +(65) 6835 7416  
[Chee-Heng.Loh@aig.com](mailto:Chee-Heng.Loh@aig.com) | [www.aig.com.sg](http://www.aig.com.sg)

**Follow us:**



IMPORTANT NOTICE:

The information in this email (and any attachments) is confidential. If you are not the intended recipient, you must not use or disseminate the information. If you have received this email in error, please immediately notify me by "Reply" command and permanently delete the original and any copies or printouts thereof. Although this email and any attachments are believed to be free of any virus or other defect that might affect any computer system into which it is received and opened, it is the responsibility of the recipient to ensure that it is virus free and no responsibility is accepted by AIG for any loss or damage arising in any way from its use.

---

**From:** Vivian Lau (LKKAuto) [<mailto:vivianlau@lkkauto.com>]

**Sent:** Monday, April 30, 2018 5:46 PM

**To:** Loh, Chee-Heng

**Cc:** Thin Thin (LKKAuto)

**Subject:** RE: Your Ref : 1514934412SG, Our Ref : CC3/AIG18004948/K1wb3, ACCIDENT INVOLVING SKS 7887G (Insured) & SH 6678M ( Third Party) ON 14/03/2018 ALONG JLN AWAK BUKIT

Dear Chee Heng,

We refer to the email below.

We had spoken to OI, she is not willing to settle at 50/50. OI mention that OI vehicle was in front of TP, is TP squeezed through and caused the accident. OI also received lawyer letter for BI. She strongly dispute on the BI.

Kindly advice on your view/opinion/instruction for this claim

Thank you

Best Regards,

**Vivian Lau** | Case Handler

**LKK Auto Consultants Pte Ltd**

Phone: 6841-8625 | email: [Vivianlau@lkkauto.com](mailto:Vivianlau@lkkauto.com) | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

---

**From:** Loh, Chee-Heng [<mailto:Chee-Heng.Loh@aig.com>]

**Sent:** Monday, 23 April, 2018 3:18 PM

**To:** Vivian Lau (LKKAuto) <[vivianlau@lkkauto.com](mailto:vivianlau@lkkauto.com)>

**Cc:** Thin Thin (LKKAuto) <[thinthin@lkkauto.com](mailto:thinthin@lkkauto.com)>

**Subject:** RE: Your Ref : 1514934412SG, Our Ref : CC3/AIG18004948/K1wb3, ACCIDENT INVOLVING SKS 7887G (Insured) & SH 6678M ( Third Party) ON 14/03/2018 ALONG JLN AWAK BUKIT

Dear Vivian,

Since TP video showed OIV cut into TP's path while overtaking, OI is unable to be fully exonerated from liability. You may proceed to offer 50/50 after clearing OI on the circumstances of the accident. To highlight to TP repairer on the below points.

- 1) TPV overtook OIV first whereby TPV should fall back behind OIV at the beginning of the merging lane.
- 2) Subsequently, OIV overtook TPV and side swiped with TPV, just before the merging lane becomes a 2 lanes road. Thus, BOLA 18 apply.

Thank you.

Best regards,  
**Loh Chee Heng**  
**AIG**  
Complex Claims Examiner  
Claims | AIG Asia Pacific Insurance Pte. Ltd

78 Shenton Way #08-16 Singapore(079120)  
Tel +(65) 6419 1881 | Fax +(65) 6835 7416  
[Chee-Heng.Loh@aig.com](mailto:Chee-Heng.Loh@aig.com) | [www.aig.com.sg](http://www.aig.com.sg)

Follow us:



**IMPORTANT NOTICE:**

*The information in this email (and any attachments) is confidential. If you are not the intended recipient, you must not use or disseminate the information. If you have received this email in error, please immediately notify me by "Reply" command and permanently delete the original and any copies or printouts thereof. Although this email and any attachments are believed to be free of any virus or other defect that might affect any computer system into which it is received and opened, it is the responsibility of the recipient to ensure that it is virus free and no responsibility is accepted by AIG for any loss or damage arising in any way from its use.*

---

**From:** Vivian Lau (LKKAUTO) [<mailto:vivianlau@lkkauto.com>]  
**Sent:** Monday, April 23, 2018 3:01 PM  
**To:** Loh, Chee-Heng  
**Cc:** Thin Thin (LKKAUTO)  
**Subject:** RE: Your Ref : 1514934412SG, Our Ref : CC3/AIG18004948/K1wb3, ACCIDENT INVOLVING SKS 7887G (Insured) & SH 6678M ( Third Party) ON 14/03/2018 ALONG JLN AWAK BUKIT

Dear Chee Heng,

We refer to the email below.

Enclosed is TP video.

TP mention that our insured driver was the one who squeezed pass the taxi that caused the accident.

Kindly advice on your view/opinion/instruction for this claim.

Thank you

Best Regards,

**Vivian Lau** | Case Handler

**LKK Auto Consultants Pte Ltd**

Phone: 6841-8625 | email: [Vivianlau@lkkauto.com](mailto:Vivianlau@lkkauto.com) | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

---

**From:** Loh, Chee-Heng [<mailto:Chee-Heng.Loh@aig.com>]  
**Sent:** Monday, 23 April, 2018 2:56 PM  
**To:** Vivian Lau (LKKAUTO) <[vivianlau@lkkauto.com](mailto:vivianlau@lkkauto.com)>  
**Cc:** Thin Thin (LKKAUTO) <[thinthin@lkkauto.com](mailto:thinthin@lkkauto.com)>



**Subject:** RE: Your Ref : 1514934412SG, Our Ref : CC3/AIG18004948/K1wb3, ACCIDENT INVOLVING SKS 7887G (Insured) & SH 6678M ( Third Party) ON 14/03/2018 ALONG JLN AWAK BUKIT

Dear Vivian,

You may proceed to reject claim as suggested at this juncture. Let's see if TP disputes and submit their video or not.

Thank you.

Best regards,

**Loh Chee Heng**

**AIG**

Complex Claims Examiner

Claims | AIG Asia Pacific Insurance Pte. Ltd

78 Shenton Way #08-16 Singapore(079120)

Tel +(65) 6419 1881 | Fax +(65) 6835 7416

[Chee-Heng.Loh@aig.com](mailto:Chee-Heng.Loh@aig.com) | [www.aig.com.sg](http://www.aig.com.sg)

Follow us:



**IMPORTANT NOTICE:**

*The information in this email (and any attachments) is confidential. If you are not the intended recipient, you must not use or disseminate the information. If you have received this email in error, please immediately notify me by "Reply" command and permanently delete the original and any copies or printouts thereof. Although this email and any attachments are believed to be free of any virus or other defect that might affect any computer system into which it is received and opened, it is the responsibility of the recipient to ensure that it is virus free and no responsibility is accepted by AIG for any loss or damage arising in any way from its use.*

---

**From:** Vivian Lau (LKKAUTO) [<mailto:vivianlau@lkkauto.com>]

**Sent:** Tuesday, April 17, 2018 5:03 PM

**To:** Loh, Chee-Heng

**Cc:** Thin Thin (LKKAUTO)

**Subject:** Your Ref : 1514934412SG, Our Ref : CC3/AIG18004948/K1wb3, ACCIDENT INVOLVING SKS 7887G (Insured) & SH 6678M ( Third Party) ON 14/03/2018 ALONG JLN AWAK BUKIT

Your Ref : 1514934412SG

Our Ref : CC3/AIG18004948/K1wb3

Dear Chee Heng,

**ACCIDENT INVOLVING SKS 7887G (Insured) & SH 6678M ( Third Party) ON 14/03/2018 ALONG JLN AWAK BUKIT**

We refer to the above matter

The third party reported that he was driving straight, suddenly OI make a sudden change lane on TP's left and hit onto TP.

Insured reported that he was driving straight when traffic light turn green, merging lane TP attempting to squeeze passed OI's vehicle.

During our tele-conversation with Insured Ms Cecilia Tan, she strongly dispute the claim, she mention that TP squeeze passed her vehicle.

Based on the circumstances of both parties and available information in hand. We are in the opinion that based on OI's video, even is merging lane but OI all the while is in front of TP.

As such, we intend to reject the claim.

Kindly advice on your view/opinion/instruction for this claim.

Thank you

Best Regards,

**Vivian Lau** | Case Handler

**LKK Auto Consultants Pte Ltd**

Phone: 6841-8625 | email: [Vivianlau@lkkauto.com](mailto:Vivianlau@lkkauto.com) | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

**IMPORTANT NOTICE:**

The information in this email (and any attachments) is confidential. If you are not the intended recipient, you must not use or disseminate the information. If you have received this email in error, please immediately notify me by "Reply" command and permanently delete the original and any copies or printouts thereof. Although this email and any attachments are believed to be free of any virus or other defect that might affect any computer system into which it is received and opened, it is the responsibility of the recipient to ensure that it is virus free and no responsibility is accepted by American International Group, Inc. or its subsidiaries or affiliates either jointly or severally, for any loss or damage arising in any way from its use.

**IMPORTANT NOTICE:**

The information in this email (and any attachments) is confidential. If you are not the intended recipient, you must not use or disseminate the information. If you have received this email in error, please immediately notify me by "Reply" command and permanently delete the original and any copies or printouts thereof. Although this email and any attachments are believed to be free of any virus or other defect that might affect any computer system into which it is received and opened, it is the responsibility of the recipient to ensure that it is virus free and no responsibility is accepted by American International Group, Inc. or its subsidiaries or affiliates either jointly or severally, for any loss or damage arising in any way from its use.

**IMPORTANT NOTICE:**

The information in this email (and any attachments) is confidential. If you are not the intended recipient, you must not use or disseminate the information. If you have received this email in error, please immediately notify me by "Reply" command and permanently delete the original and any copies or printouts thereof. Although this email and any attachments are believed to be free of any virus or other defect that might affect any computer system into which it is received and opened, it is the responsibility of the recipient to ensure that it is virus free and no responsibility is accepted by American International Group, Inc. or its subsidiaries or affiliates either jointly or severally, for any loss or damage arising in any way from its use.

**IMPORTANT NOTICE:**

The information in this email (and any attachments) is confidential. If you are not the intended recipient, you must not use or disseminate the information. If you have received this email in error, please immediately notify me by "Reply" command and permanently delete the original and any copies or printouts thereof. Although this email and any attachments are believed to be free of any virus or other defect that might affect any computer system into which it is received and opened, it is the responsibility of the recipient to ensure that it is virus free and no responsibility is accepted by American International Group, Inc. or its subsidiaries or affiliates either jointly or severally, for any loss or damage arising in any way from its use.

**IMPORTANT NOTICE:**

The information in this email (and any attachments) is confidential. If you are not the intended recipient, you must not use or disseminate the information. If you have received this email in error, please immediately notify me by "Reply" command and permanently delete the original and any copies or printouts thereof. Although this email and any attachments are believed to be free of any virus or other defect that might affect any computer system into which it is received and opened, it is the responsibility of the recipient to ensure that it is virus free and no responsibility is accepted by American International Group, Inc. or its subsidiaries or affiliates either jointly or severally, for any loss or damage arising in any way from its use.

## Hsiao Tong (LKKAUTO)

---

**From:** Aileen Tan Lee Noi <aileentan@cdge.com.sg>  
**Sent:** Tuesday, 2 April 2019 2:09 PM  
**To:** Hsiao Tong (LKKAUTO)  
**Subject:** [Accept Offer] AIG/LKK Ref: CC3/AIG18004948/K1wb3 CDGE Ref: T0318/SH6678M/AT >> Acc on 14.03.2018 invlg SH6678M & SKS7887G [AIG]

WITHOUT PREJUDICE

Ms Chew Hsiao Tong  
M/s LKK Auto Consultants Pte Ltd

We refer to subject matter resting with your email dated 21 February 2019.

Strictly without admission of liability and solely to resolve the case amicably at this stage, we accept your global offer of S\$900.00.

Please note that it is a condition of any settlement reached that it shall be without prejudice to any personal injury claim, if any of the taxi driver.

Kindly arrange to let us have discharge voucher for early execution. Thank you.

Best Regards  
Aileen Tan  
Claims Department | ComfortDelGro Engineering Pte Ltd  
Off: 6214 8735 | Fax: 6214 1843

---

**From:** Cecilia Lee Peng Geok  
**Sent:** Friday, 22 February 2019 08:05  
**To:** Aileen Tan Lee Noi  
**Subject:** Fw: Your Ref: T0318/ SH 6678M/CL(st),Our Ref: CC3/AIG18004948/K1wb3,Accident involving Vehicle SH 6678M & SKS 7887G ON 14/03/2018

Hi Aileen

fyna

Thank you.

Best Regards  
Cecilia Lee  
Claims Department | ComfortDelGro Engineering Pte Ltd  
Off: 6214 8354 | Fax: 6214 1843

---

**From:** Hsiao Tong (LKKAUTO) <chewht@lkkauto.com>  
**Sent:** Thursday, 21 February 2019 5:23 PM  
**To:** Cecilia Lee Peng Geok

**Subject:** RE: Your Ref: T0318/ SH 6678M/CL(st),Our Ref: CC3/AIG18004948/K1wb3,Accident involving Vehicle SH 6678M & SKS 7887G ON 14/03/2018

**Without Prejudice**

Dear Sirs/Mdm,

We refer to your below email.

We have reviewed the matter and we are of the view that the accident fit scenario BOLA 18. Our reasons as below: -

- 1) Your vehicle being the rear vehicle should fall back and not overtook our insured vehicle in the merging lanes.
- 2) The point of impact is inside the merging lanes, before the road split into a 2 lanes road.
- 3) Though insured vehicle seemed to drift to the right inside the merging lanes, it is still a merging lanes accident. Thus, highlighting the reason in point 1 that your client should not overtake our vehicle in the merging lanes, and this accident could be prevented.

Attached is a copy of our insured video for your easy reference.

Kindly re-consider our offer.

Best Regards,

**Hsiao Tong, Chew** | Case Handler

**LKK Auto Consultants Pte Ltd**

Phone: 6742-3197 | email: [chewht@lkkauto.com](mailto:chewht@lkkauto.com) | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

---

**From:** Cecilia Lee Peng Geok <[cecilialee@sparkcarcare.com](mailto:cecilialee@sparkcarcare.com)>

**Sent:** Friday, 25 January 2019 4:04 PM

**To:** Hsiao Tong (LKKAuto) <[chewht@lkkauto.com](mailto:chewht@lkkauto.com)>

**Subject:** Fw: Your Ref: T0318/ SH 6678M/CL(st),Our Ref: CC3/AIG18004948/K1wb3,Accident involving Vehicle SH 6678M & SKS 7887G ON 14/03/2018

**Without Prejudice**

Dear Hsiao Tong

Please review and revert.

Thank you.

Best Regards

Cecilia Lee

Claims Department | ComfortDelGro Engineering Pte Ltd

Off: 6214 8354 | Fax: 6214 1843

**From:** Vivian Lau (LKKAuto) <[vivianlau@lkkauto.com](mailto:vivianlau@lkkauto.com)>

**Sent:** Thursday, 13 September 2018 5:43 PM

**To:** Cecilia Lee Peng Geok

**Subject:** RE: Your Ref: T0318/ SH 6678M/CL(st),Our Ref: CC3/AIG18004948/K1wb3,Accident involving Vehicle SH 6678M & SKS 7887G ON 14/03/2018

Your Ref: T0318/ SH 6678M/CL(st)

Our Ref: CC3/AIG18004948/K1wb3

Dear Sir/Madam,

**Accident involving Vehicle SH 6678M & SKS 7887G ON 14/03/2018**

We refer to the above matter

Strictly without admission of liability whatever, but with a view towards a resolutions of your client's claim in the above matter without resort to litigation and not jeopardizing our insured claim against the liable party, we are prepared to offer 50% to your client's claim.

For a quick and amicable settlement, our principal maintain offer to settle global sum at **S\$ 900.00**

Kindly confirm acceptance.

*Kindly note that this negotiation between parties on this matter is purely on a without prejudice basis with the sole intention of resolving the matter amicably without parties resorting to legal proceedings. No admission of liability, whatsoever, should be deemed / inferred from this negotiation of terms/settlement.*

*In the event of new evidence being discovered or subsequently produced by either party that will materially affect/influence on the issues of liability/damages, either party is not bound, thereafter, by the negotiation terms/settlement.*

Thank you

Best Regards,

**Vivian Lau** | Case Handler

**LKK Auto Consultants Pte Ltd**

Phone: 6841-8625 | email: [Vivianlau@lkkauto.com](mailto:Vivianlau@lkkauto.com) | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

---

**From:** Cecilia Lee Peng Geok [<mailto:cecilialee@sparkcarcare.com>]

**Sent:** Thursday, 2 August, 2018 9:19 AM

**To:** Vivian Lau (LKKAuto) <[vivianlau@lkkauto.com](mailto:vivianlau@lkkauto.com)>

**Subject:** Re: Your Ref: T0318/ SH 6678M/CL(st),Our Ref: CC3/AIG18004948/K1wb3,Accident involving Vehicle SH 6678M & SKS 7887G ON 14/03/2018

Without Prejudice

Dear Vivian

Your 50% offer is rejected. Accident happened at the single lane, before it splits into two lanes. Video footage clearly shows that taxi was travelling ahead and it was your insured who squeezed through the

lane that caused the accident. We attached herewith the longer VC. Please note that the video footage is solely for investigation and shall not be reproduced. You undertake to preserve its confidentiality and will not disclose, provide or make available the video footage in whole or in part, to any third party.



We are prepared to wrap up the matter at global sum of \$1740. Please confirm settlement or revert with your principal's consent to escalate the matter to GIA DRM for resolution.

Please revert by 10/08/2018.

Thank you.

Best Regards

Cecilia Lee

Claims Department | ComfortDelGro Engineering Pte Ltd

Off: 6214 8354 | Fax: 6214 1843



**From:** Vivian Lau (LKKAuto) <[vivianlau@lkkauto.com](mailto:vivianlau@lkkauto.com)>

**Sent:** Wednesday, 1 August 2018 5:40 PM

**To:** Cecilia Lee Peng Geok

**Cc:** Thin Thin (LKKAuto)

**Subject:** RE: Your Ref: T0318/ SH 6678M/CL(st),Our Ref: CC3/AIG18004948/K1wb3,Accident involving Vehicle SH 6678M & SKS 7887G ON 14/03/2018

WITHOUT PREJUDICE

Your Ref: T0318/ SH 6678M/CL(st)

Our Ref: CC3/AIG18004948/K1wb3

Dear Sir/Madam,

**Accident involving Vehicle SH 6678M & SKS 7887G ON 14/03/2018**

We refer to the above matter

Strictly without admission of liability whatever, but with a view towards a resolutions of your client's claim in the above matter without resort to litigation and not jeopardizing our insured claim against the liable party, we are prepared to offer 50% to your client's claim.

For a quick and amicable settlement, our principal offer to settle global sum at **S\$ 900.00**

Kindly confirm acceptance.

*Kindly note that this negotiation between parties on this matter is purely on a without prejudice basis with the sole intention of resolving the matter amicably without parties resorting to legal proceedings. No admission of liability, whatsoever, should be deemed / inferred from this negotiation of terms/settlement.*

*In the event of new evidence being discovered or subsequently produced by either party that will materially affect/influence on the issues of liability/damages, either party is not bound, thereafter, by the negotiation terms/settlement.*

Thank you

Best Regards,

**Vivian Lau** | Case Handler

**LKK Auto Consultants Pte Ltd**

Phone: 6841-8625 | email: [vivianlau@lkkauto.com](mailto:vivianlau@lkkauto.com) | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

**From:** Cecilia Lee Peng Geok [<mailto:cecilialee@sparkcarcare.com>]

**Sent:** Wednesday, 18 April, 2018 12:09 PM

**To:** Vivian Lau (LKKAuto) <[vivianlau@lkkauto.com](mailto:vivianlau@lkkauto.com)>

**Cc:** Thin Thin (LKKAuto) <[thinthin@lkkauto.com](mailto:thinthin@lkkauto.com)>

**Subject:** Re: Your Ref: T0318/ SH 6678M/CL(st),Our Ref: CC3/AIG18004948/K1wb3,Accident involving Vehicle SH 6678M & SKS 7887G ON 14/03/2018

Without Prejudice

Dear Sir/Madam



Attached video shows your insured driver was the one who squeezed pass the taxi that caused the accident. Please note that the video footage is solely for investigation and shall not be reproduced. You undertake to preserve its confidentiality and will not disclose, provide or make available the video footage in whole or in part, to any third party.

Thank you.

Best Regards  
Cecilia Lee  
Claims Department | ComfortDelGro Engineering Pte Ltd  
Off: 6214 8354 | Fax: 6214 1843

From: "Vivian Lau (LKKAuto)" <vivianlau@lkkauto.com>  
To: Cecilia Lee Peng Geok <cecilialee@sparkcarcare.com>  
Cc: "Thin Thin (LKKAuto)" <thinthin@lkkauto.com>  
Date: 16/04/2018 03:36 PM  
Subject: Your Ref: T0318/ SH 6678M/CL(st), Our Ref: CC3/AIG18004948/K1wb3, Accident involving Vehicle SH 6678M & SKS 7887G ON 14/03/2018

---

WITHOUT PREJUDICE

Your Ref: T0318/ SH 6678M/CL(st)  
Our Ref: CC3/AIG18004948/K1wb3

Dear Sir/Madam,

**Accident involving Vehicle SH 6678M & SKS 7887G ON 14/03/2018**

We refer to the above matter

We are of the opinion that this is a case of **conflicting versions**. There is no conclusive evidence to substantiate either's parties version. Enclosed herewith a copy of our insured's accident report for your perusal.

Meanwhile, we would like to request the CCTV footage as stated in your client's accident report in order to seek further instruction from our principal.

Kindly take note that the case handler in-charge is Vivian and she can be contacted at her DID 6841 8625.

*Kindly note that this negotiation between parties on this matter is purely on a without prejudice basis with the sole intention of resolving the matter amicably without parties resorting to legal proceedings. No admission of liability, whatsoever, should be deemed / inferred from this negotiation of terms/settlement.*

*In the event of new evidence being discovered or subsequently produced by either party that will materially affect/influence on the issues of liability/damages, either party is not bound, thereafter, by the negotiation terms/settlement.*

Thank you  
Best Regards,  
Vivian Lau | Case Handler  
LKK Auto Consultants Pte Ltd  
Phone: 6841-8625 | email: Vivianlau@lkkauto.com | fax: 6741-4108  
Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

[attachment "Sketch Plan .pdf" deleted by Cecilia Lee Peng Geok/sparkcarcare/cdgc/delgronotes]

---

This message and any attachments may contain confidential, privileged or proprietary information. If you are not the intended recipient, kindly notify us and delete this message and its attachments immediately, and please be advised that using, copying, distributing or disclosing any contents therein is not allowed. Statements pertaining to any matter outside our business are not to be taken as endorsed by ComfortDelGro Corporation Limited or its related companies. The comments/proposals provided are for discussion purposes only and are subject to approvals. Nothing herein shall constitute a binding agreement between the parties. Neither party shall be bound in any way to any term or condition except as agreed in a written agreement signed by the duly authorised representatives of both parties.

ComfortDelGro - a Green Office certified by the Singapore Environment Council - is committed to preserving the environment. We encourage you to print this only if necessary.

ComfortDelGro Engineering Pte Ltd [Registration No. 199506048W]





Auto  
Consultants  
Pte Ltd

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564313

Our Ref: CC3/AIG18004948/K1wb3

03 April 2018

**Tan Bee Ling Cecilia**  
5 Jalan Tumpu  
Singapore 678418

Dear Sir/Madam,

**ACCIDENT INVOLVING SKS 7887G & SH 6678M ON 14/03/2018**

We refer to the above accident where we are acting for AIG Asia Pacific Insurance Pte Ltd to resolve the claim against you and/or your authorized driver under the Auto Insurance policy taken up with them.

Kindly note that we have reviewed this matter and would like to advise that you and/or your authorized driver may not be absolved from blame for this accident.

If you have evidence/information to proof that we should not settle the third party claim, kindly let us have them in writing within the next 10 days i.e. by 13/04/2018, after we shall proceed with negotiation with Third Party claimant on the **without prejudice basis** and any settlement should not bind any claims whatsoever by you/your driver against the other party's insurer arising from this particular accident.

Please note that your No-Claim Discount (NCD) (if any) will be affected and reduced by 30% (20% for commercial vehicles) upon next renewal due to this Third Party claim. However, if your policy has a NCD protector feature, it will be deemed utilized for this claim and your NCD will be protected.

Please call us if you have further queries.

Yours faithfully,

Vivian Lau  
Case Handler  
DID: 6841 8625  
FAX: 6741 4108  
EMAIL: Vivianlau@lkkauto.com

c.c. AIG Asia Pacific Insurance Pte Ltd  
(Motor Claims Dept)

## LETTER OF AUTHORISATION

(NAF / PAF)

ACCIDENT INVOLVING  
ALONG

i 40 SH6678M , SKS7887G

ON 14-Mar-18 08:15

JALAN ANAK BUKIT SLIP RD TOWARD UPP BUKIT TIMAH

I / We

LEE TIANLENG(LI TIAN... (Hirer) NRIC No.: S7621868D

and/or

(Relief) NRIC No.:

Taxi Number

SH6678M

hereby authorise ComfortDelGro Engineering Pte Ltd(CDGE):

1. To submit my/our claims for damages, costs and expense, including loss of income, loss of rental, medical fee and legal costs.
2. To have absolute discretion to agree to any settlement or compensation amount in respect of my/our claim against third party (except personal injuries and medical claims).
3. To sign Discharge Voucher on my/our behalf.
4. To accept any payment (claim proceeds) in respect of the claim against third party and payment by cheque shall be forward directly to CDGE in accordance with CDGE's instruction and made in favour of "ComfortDelGro Engineering Pte Ltd".

Date

14-Mar-2018

Name of Hirer

LEE TIANLENG(LI TIANLONG)

Hirer NRIC

S7621868D

Signature :



Address

289 BISHAN STREET 24 #12-23  
570289

Contact No.

90125447

**RELEASE VOUCHER**  
**(AIG Asia Pacific - Express Third Party Claim)**

"We/I, **COMFORTDELGRO ENGINEERING PTE LTD** ("the workshop") hereby confirm that we/I have reached an agreement with the appointed surveyor of AIG Asia Pacific Insurance Pte Ltd **LKK AUTO CONSULTANTS PTE LTD** (name of surveyor) with respect to the amount claimed for **S\$900.00** (Global Sum) for vehicle no. **SH 6678M** that was damaged pursuant to the accident which occurred on **14/03/2018** (date) along **JALAN ANAK BUKIT SLIP RD TOWARDS UPP BUKIT TIMAH** (location) involving vehicle no/s **SKS 7887G**.

This is pursuant to the inspection conducted on **15/03/2018** (date) at "the workshop".

We/I confirm that we/I are/am authorized by the owner **COMFORT TRANSPORTATION PTE LTD** ("the third party claimant") of vehicle no. **SH 6678M** make the claim as set out in the above paragraph and we/I have full authority to settle the matter on his/her behalf in a manner that we/I deem fit. We/I enclose herein the letter of authority given by "the third party claimant".

We/I further confirm that we/I will indemnify AIG Asia Pacific Insurance Pte Ltd for all damages, loss and/or expense that they will or have already incurred in the event that "the third party claimant" after the above said agreement lodges a further claim against the former for any loss and expenses suffered pertaining to costs of repairs and/or rental and/or loss of use pursuant to the damage to **SH 6678M** (vehicle no.) as a result of the accident.

We/I confirm that the agreement reached above is in full and final settlement of any claim of "the third party claimant" pursuant to the accident and that further this settlement is reached on a without prejudice and without admission of liability basis.

This agreement is subject to the application of Singapore law and the Singapore Courts have exclusive jurisdiction over any dispute arising out of the same.

Dated this 08 (day) of 04 (month) 20 19 (year)



*Auk*

Signed by appointed surveyor

AILEEN TAN  
Manager, Claims

Signed by "the workshop" (with chop)  
CLAIMS DEPARTMENT  
COMFORTDELGRO ENGINEERING PTE LTD  
59 LOYANG DRIVE  
SINGAPORE 508969

"The contents of this document apply to vehicle damages only.  
All personal injuries and damages arising therefrom are excluded  
from the ambit and application of this document"

Please forward your cheque made payable to:  
COMFORTDELGRO ENGINEERING PTE LTD

## TAX INVOICE

8010004

AIG ASIA PACIFIC INSURANCE PTE LTD

#08-16 78 SHENTON WAY, CHARTIS BUILD  
SINGAPORE SG 079120

CONTACT NO: 64193000 3225094

VEHICLE NO  
SH 6678M

MAKE  
HYUNDAI

MODEL  
I-40

DATE OF REG  
12.11.2015

CHASSIS CODE  
KHHLB41UMGU080439

INV. NO/DATE  
91364989 29.03.2018

JOB NO.  
305125049

ODOMETER READING

DATE/TIME IN  
14.03.2018 11:35

Description : 3P 14.03.2018

S/No	Part No.		Qty	Unit Price	%Disc	Net
PART REQUISITION						
0001	03-01-0103-0099	I40V2 SHOCK ABSORBER ASSY	1	342.20	20.00	273.76
0002	04-01-0103-0658	I40VC CAP ASSY-WHEEL HUB	1	150.70	20.00	120.56
0003	04-01-0103-0639	I40VC BRACKET-FR BUMPER S	1	24.60	20.00	19.68
SUB-TOTAL			:			414.00

### JOB NATURE

0001	20-05	RENEW ADVERTISEMENT STICKER-	100.00		100.00
0002	L	PANEL BEATING	200.00		200.00
0003	23-502	SPRAYPAINT ON AFFECTED AREA	400.00		400.00
0004	20-12	REMOVE/REFIX FRT SUSPENSION ASST REPA	50.00		50.00
0005	20-08	ADJUST FRONT WHEEL ALIGNMENT	60.00		60.00

THE CUSTOMER AGREES TO HOLD THE COMPANY HARMLESS FROM ALL LIABILITY FOR LOSS OF OR DAMAGE TO THE VEHICLE OR ANY PARTS THEREOF, INCLUDING BUT NOT LIMITED TO, THE VEHICLE, THE DRIVER AND PASSENGERS, ARISING FROM THE USE OF THE VEHICLE, WHETHER CAUSED BY NEGLIGENCE OR OTHERWISE, AND TO INDEMNIFY THE COMPANY AGAINST ALL SUCH LIABILITY.

THE CUSTOMER SHALL RETURN THE VEHICLE IMMEDIATELY UPON DELIVERY AND SHALL WITHIN 14 DAYS FROM THE DATE OF DELIVERY ADVISE THE COMPANY OF ANY COMPLAINTS. OTHERWISE, THE VEHICLE WILL BE DEEMED TO HAVE BEEN ACCEPTED IN GOOD ORDER.

INTEREST OF 1% PER ANNUM WILL BE CHARGED ON A DAY TO DAY BASIS IN RESPECT OF ANY AMOUNT DUE AND UNPAID TO THE COMPANY BY THE CUSTOMER AND NOT PAID ON THE DATE OF PAYMENT. E.G. AFTER 15 DAYS FROM THE DATE OF DELIVERY, PERIOD OF DEFAULT.

PLEASE SIGNATURE THIS WORK ORDER IMMEDIATELY UPON RECEIPT AND ADVISE THE COMPANY OF ANY PROBLEMS OR COMPLAINTS WITHIN 14 DAYS OF RECEIPT. IF THE COMPANY DOES NOT HEAR FROM THE CUSTOMER, THE COMPANY WILL TREAT THIS INVOICE AS PAID AND PROCEED WITH THE WORK.

ComfortDelGro Engineering Pte Ltd  
A member of COMFORTDELGRO

Head Office:  
205 Braddell Road  
Singapore 579701

Kindly note that no receipt shall be issued unless requested.

CUSTOMER'S COPY

ACCOUNT No.	INVOICE No.	AMOUNT	BANK/CHQ No.
8010004	91364989	1,309.68	

COMPANY REG. NO.: 19950604  
Page:

CONTACT NO: 64193000 3225094

CHASSIS CODE  
KMHLB41UMGU080439

DATE/TIME IN  
14.03.2018 11:35

Qty	Unit Price	%Disc	Net
-----	------------	-------	-----

SUB-TOTAL	:	810.00
-----------	---	--------

Items total		1,224.00
Add GST @	7.000 %	85.68
Invoice amount		1,309.68

Issued by : CHEWSEELING 29.03.2018 11:44:50  
Repair type : CLSO/57/57  
Payment Type/Term: /Credit 30 days

y note that no receipt shall be issued unless requested.

ATOMER'S COPY

ACCOUNT No.	INVOICE No.	AMOUNT	BANK/CHQ No.
8010004	91364989	1,309.68	

Our Ref: CT18030422

Date: 29 March 2018



**TO WHOM IT MAY CONCERN**

Dear Sir/Madam

ACCIDENT ON                      14/03/2018    @ 08:15 hrs  
ALONG                              JALAN ANAK BUKIT SLIP RD TOWARD UPP BUKIT  
   TIMAH  
INVOLVING                        SKS7887G

We refer to the above-mentioned accident and wish to inform that **Comfort Transportation Pte Ltd** is the registered owner of the taxi bearing vehicle registration number **SH6678M** (the "Taxi"). The Taxi was hired to **LEE TIANLENG(LI TIANLONG)** IC NO **S7621868D** a registered hirer-operator of **Comfort Transportation Pte Ltd** at the time of occurrence of the aforementioned accident at a rental rate **\$119.28** per day (inclusive of GST).

Please be advised that the Taxi was insured with **MS First Capital Insurance Ltd** on a third party basis at the material time of the accident.

We wish to confirm that the aforesaid hirer-operator had obtained our permission to undertake repairs for damage on the Taxi arising from the said accident with a motor workshop of his choice.

Please liaise with the said hirer-operator or his authorized workshop directly for settlement of claims with third party's insurance company in respect of the said accident.

Yours faithfully

Christine Tay  
Assistant Manager, Fleet Safety

This is a computer generated letter. No signature is required.



[illegible]

**Enquire Vehicle Insurer**

Vehicle No.	Incident Date/Time	Search Status	Insurance Company Code	Insurance Company Name
SK57887G	14 Mar 2018 / 08:15:00	Successful	A04	AIG ASIA PACIFIC INSURANCE PTE. LTD.

[Previous](#)[OK](#)

Sn 6678W

### ...CLAIM SUBFOLDER...(Pending for Survey Report)

Express

## CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	14 Mar 2018 <a href="#">Edit Reg</a>		15 Mar 2018 00:00 <a href="#">Edit Adj Rpt</a>	<b>S\$1,224.00</b> <a href="#">Edit Estimates</a>	<b>S\$1,224.00</b> <a href="#">View Rpt</a>		<b>Pending for Survey Report</b> <a href="#">Cancel Case</a>

Main	Reference	Claim Details	Documents	Show All					
<b>CLAIM SUBFOLDER DETAILS</b> <span style="float: right;">[Created by adjuster]</span>									
Insured:	Tan Bee Ling Cecilia, ID: S7044578F								
Main Claimant:	COMFORT TRANSPORTATION PTE LTD, Co. Reg. No.: 199303821R								
Vehicle Reg. No.:	SH6678M	Date of Loss:	14/03/2018 00:00 - :59 [28 Months and 2 Days From LTA Reg Date (Man Yr)]						
Claim Type:	TP / 1514934412SG	Policy/Cover Note No.:	2100255236 (Comprehensive)						
Vehicle Reg. No. (Insured):	SKS7887G	Policy No. (Claimant):	D-18088936MFSH						
		Excess:							
Repairer:	ComfortDelGro Engineering Pte Ltd (Loyang) 59 Loyang Drive, 508969 Loyang - Tel: 6214 8300								
Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd. (Express) - Tel: 65-6419-3000 ... [Handled by Loh, Chee-Heng] Chee-Heng.Loh@aig.com								
Claimant's Insurer:	MS First Capital Insurance Ltd (HQ) - Tel: 62222311								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by KALVIN ANG WEI KUN] ... [Final Rpt due 26/03/2018]								
<b>ASSOCIATED MAIL RECEIVED</b> <span style="float: right;"><a href="#">View All</a> <a href="#">Compose Case Mail</a></span>									
• AIG_SG (16/03/2018): Request To Upload TP GIA Report									
<b>ALL ASSOCIATED TASKS</b> <span style="float: right;"><a href="#">View All</a> <a href="#">Search Tasks</a> <a href="#">Create New Task</a> <a href="#">Complete</a></span>									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

## Claim Documents

\*SH6678M (1514934412SG)  
[SK57887G]  
TP  
COMFORT TRANSPORTATION PTE LTD  
Mar 14 2018 12:00AM  
[Tan Bee Ling Cecilia]  
ComfortDelGro Engineering Pte Ltd

Upload Documents

Upload Photos

Compose New Letter

Upload Video

Upload Audio

View

View in Browser

Video						1 per page	
No	Finalized On	AIG Asia Pacific Insurance Pte. Ltd. (SG)		Thumbnail	Print		
1	23/04/18 15:09	TP video -SH6678M		1 Load AVI			
2	21/02/19 16:45	OI video - front From:SC - Reg. No: SK57887G, Claimant: TAN BEE LING CECILIA		1 Load MP4			
3	21/02/19 16:45	OI video - rear From:SC - Reg. No: SK57887G, Claimant: TAN BEE LING CECILIA		1 Load MP4			

Letters/Correspondences						1 per page	
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print		
1	(Draft)	Third Party Express Settlement – Payment Breakdown		1 Edit			

Assessment Reports						1 per page	
No	Finalized On	AIG Asia Pacific Insurance Pte. Ltd. (SG)		Thumbnail	Print		
1	16/03/18 11:39	Accident Statement From:SC - Reg. No: SK57887G, Claimant: TAN BEE LING CECILIA		1 Load HTM			

Photos/Images						3 per page	
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print		
1	15/03/18 17:04	General View		1 Load JPG	<input checked="" type="checkbox"/>		
2	15/03/18 17:04	General View		1 Load JPG	<input checked="" type="checkbox"/>		
3	15/03/18 17:04	General View		1 Load JPG	<input checked="" type="checkbox"/>		
4	15/03/18 17:04	General View		1 Load JPG	<input checked="" type="checkbox"/>		
5	15/03/18 17:04	General View		1 Load JPG	<input checked="" type="checkbox"/>		
6	15/03/18 17:04	General View		1 Load JPG	<input checked="" type="checkbox"/>		
7	15/03/18 17:04	General View		1 Load JPG	<input checked="" type="checkbox"/>		
8	15/03/18 17:04	General View		1 Load JPG	<input checked="" type="checkbox"/>		
9	15/03/18 17:04	General View		1 Load JPG	<input checked="" type="checkbox"/>		
10	15/03/18 17:04	General View		1 Load JPG	<input checked="" type="checkbox"/>		
11	15/03/18 17:04	General View		1 Load JPG	<input checked="" type="checkbox"/>		
12	15/03/18 17:04	General View		1 Load JPG	<input checked="" type="checkbox"/>		
13	15/03/18 17:04	General View		1 Load JPG	<input checked="" type="checkbox"/>		
14	15/03/18 17:04	General View		1 Load JPG	<input checked="" type="checkbox"/>		
15	15/03/18 17:04	General View		1 Load JPG	<input checked="" type="checkbox"/>		
16	15/03/18 17:04	General View		1 Load JPG	<input checked="" type="checkbox"/>		
17	15/03/18 17:04	General View		1 Load JPG	<input checked="" type="checkbox"/>		
18	15/03/18 17:04	General View		1 Load JPG	<input checked="" type="checkbox"/>		
19	15/03/18 17:04	General View		1 Load JPG	<input checked="" type="checkbox"/>		
20	27/03/18 08:29	Reinspection Photo		1 Load JPG	<input checked="" type="checkbox"/>		
21	27/03/18 08:29	Reinspection Photo		1 Load JPG	<input checked="" type="checkbox"/>		
22	27/03/18 08:29	Reinspection Photo		1 Load JPG	<input checked="" type="checkbox"/>		
23	27/03/18 08:29	Reinspection Photo		1 Load JPG	<input checked="" type="checkbox"/>		
24	27/03/18 08:29	Reinspection Photo		1 Load JPG	<input checked="" type="checkbox"/>		

Video			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	AIG Asia Pacific Insurance Pte. Ltd. (SG)	Thumbnail	Print
25	27/03/18 08:29	Reinspection Photo		Load JPG <input checked="" type="checkbox"/>
26	27/03/18 08:29	Reinspection Photo		Load JPG <input checked="" type="checkbox"/>
27	27/03/18 08:29	Reinspection Photo		Load JPG <input checked="" type="checkbox"/>
28	27/03/18 08:29	Reinspection Photo		Load JPG <input checked="" type="checkbox"/>
Documentation			1 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	16/03/18 17:41	TP ESTIMATE- MARKED		Load PDF
2	16/03/18 17:41	TP GIA REPORT		Load PDF
3	17/04/18 17:05	Email to AIG to seek advise SH 6678M		Load PDF
4	11/04/19 08:42	WORKSHOP INVOICE		Load PDF
5	11/04/19 08:42	AUTHORISATION TO ACT FORM		Load PDF
6	11/04/19 08:42	Release Voucher		Load PDF
7	11/04/19 08:42	RENTAL RECEIPT		Load PDF
8	11/04/19 08:42	RENTAL MILEAGE		Load PDF
9	11/04/19 08:42	LTA SEARCH		Load PDF
10	11/04/19 08:42	LETTER TO OI		Load PDF
No	Finalized On	AIG Asia Pacific Insurance Pte. Ltd. (SG)	Thumbnail	Print
1	16/03/18 16:47	OI GIA addendum 1		Load PDF
2	16/03/18 16:47	TP GIA		Load PDF

## Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
<b>Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)</b> <div style="border: 1px solid black; height: 40px; margin-top: 5px;"></div>			
<b>Show Remarks To:</b> <input type="checkbox"/> Handling Insurer <small>Note: Remarks are private unless you show it to other parties.</small>			

NOTE: TO BE COMPLETED BY SURVEYOR

TEAM \_\_\_\_\_

### THIRD PARTY EXPRESS SETTLEMENT (PAYMENT BREAKDOWN)

Vehicle No:	SKS7887G (Insd veh)	Model:	HYUNDAI I40 1.7 D (A)
	SH6678M (TP veh)		
Date of Accident:	14/03/2018		

Global Sum Settlement	: [ X ] Yes	: [ ] No
Repair Estimate	: \$	6,981.54
Final Repair Cost	: \$	900.00
Loss of Use	: \$	2.50 days at \$50.00 per day
Rental (if any)	: \$	2.50 days
LTA / GIA Search Fee	: \$	
Others:	: \$	
	: \$	
Final Settlement Sum (Global Sum)	: \$	900.00

Is Third Party Workshop GIA Registered? [ X ] YES [ ] NO (Kindly indicate below)

A) For Non GIA Registered Workshop: Agreed Liability \_\_\_\_\_ (%)

B) For GIA Registered Workshop: BOLA Applicable: ~~Yes~~/ No BOLA Scenario No: \_\_\_\_\_

NIL

BOLA Liability: \_\_\_\_\_ 50 \_\_\_\_\_ (%) Assessed Liability (\*): \_\_\_\_\_ (%)

\* Assessed Liability to be filled only for chain collisions and for cases where BOLA does not apply.

Remarks \_\_\_\_\_

Payment instruction: Payee's Breakdown			
1)	ComfortDelGro Engineering Pte Ltd	: \$	900.00
2)		: \$	
3)		: \$	
4)		: \$	
5)		: \$	

JOANNE LEE KHANG MIN

11 Apr  
2019

LKK Auto Consultants Pte Ltd

Date

Please attach all the supporting documents to the form.  
(Final Repair Bill; Rental Invoice; Release Voucher; Authorisation to Act; Survey Report; Medical Report/ Bill (if any))

## LKK Auto Consultants Pte Ltd (Co.Reg No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park  
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC3/AIG18004948/K1PB3Q2

Date: 11/04/2019

## REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 2100255236  
**Claimant Vehicle No :** SH6678M **Insured Vehicle No :** SKS7887G  
 Date of Loss: 14/03/2018 Nature of Claim: TP Claim No: 1514934412SG

## DESCRIPTION &amp; IDENTIFICATION OF VEHICLE

Reg No: **SH6678M**  
 Make & Model: HYUNDAI I40, 1.7 D (A) Engine No: D4FDFU561968  
 Reg. Date: 12/11/2015 (Man. Year: 2015) Chassis No: KMHLB41UMGU080439  
 Colour: Blue Odometer: 386273 km  
 Engine Capacity: 1685 cc  
 Market Value/New Car Price: N/A  
 Sum Insured (S\$): **Market Value/New Car Price**

## CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes  
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

## CONDITION OF TYRES

Front Tyre Size: 205/60 R16 Rear Tyre Size: 205/60 R16  
 Front Left Side: West Lake 7 mm Rear Left Side: West Lake 7 mm  
 Front Right Side: West Lake 7 mm Rear Right Side: West Lake 7 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	5,204.80	514.00	4,690.80	90.12
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,320.00	710.00	610.00	46.21
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Gross Total (S\$)</b>	<b>6,524.80</b>	<b>1,224.00</b>	<b>5,300.80</b>	<b>81.24</b>
<b>+ GST 7.00/7.00% (S\$)</b>	<b>456.74</b>	<b>85.68</b>	<b>371.06</b>	<b>81.24</b>
<b>Nett Amount (S\$)</b>	<b>6,981.54</b>	<b>1,309.68</b>	<b>5,671.86</b>	<b>81.24</b>
<b>+ Loss of Use (2.5 x S\$50.00/day) (S\$)</b>		125.00		
<b>+ Car Rental (2.5 x S\$119.28/day) (S\$)</b>		298.20		
		<b>(S\$) 1,732.88</b>		
<b>Liabe Amount (50.00%) (S\$)</b>		<b>866.44</b>		
<b>+ Doc/Search Fee (S\$)</b>		7.49		
		<b>873.93</b>		
<b>Global Sum Settlement (S\$)</b>		<b>900.00</b>		

## INSPECTION

Date of Assignment: 15/03/2018

Date Inspected: 15/03/2018 Inspected At: ComfortDelGro Engineering Pte Ltd  
(Loyang)  
59 Loyang Drive  
Singapore 508969

Estimated Period of Repair: 2.0 days

---

**Adjuster:** KALVIN ANG WEI KUN

**Manager:** CHEW HSIAO TONG

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*



## REPAIR DETAILS

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT WHEEL RIM (LH)	Serviceable	297.10 FL	*- FL
2	1		*FRONT WHEEL HUB CAP (LH)	Grazed	150.70 FL	*150.70 FL
3	1		*FRONT WHEEL BEARING	Serviceable	258.50 FL	*- FL
4	1		*FRONT SHOCK ABSORBER (ASSY) (LH)	Bent	342.20 FL	*342.20 FL
5	1		*FRONT SHOCK ABSORBER MOUNTING (LH)	Serviceable	75.10 FL	*- FL
6	1		*FRONT DRIVE SHAFT (LH)	Serviceable	1,069.55 FL	*- FL
7	1		*RACK & PINION ASSY	Serviceable	2,184.00 FL	*- FL
8	1		*STG TIE END	Serviceable	69.50 FL	*- FL
9	1		*STABILIZER BAR	Serviceable	222.50 FL	*- FL
10	1		*STABILIZER BAR BUSH (LH)	Serviceable	13.50 FL	*- FL
11	1		*STABILIZER BAR LINK	Serviceable	81.70 FL	*- FL
12	1		*STABILIZER BRACKET	Serviceable	24.00 FL	*- FL
13	1		*FRONT SUSPENSION LOWER ARM (LH)	Serviceable	715.10 FL	*- FL
14	1		*KNUCKLE ARM (LH)	Serviceable	582.95 FL	*- FL
15	1		*FRONT BUMPER SIDE BRACKET (LH)	Cracked	24.60 FL	*24.60 FL
16	1		*FRONT FENDER ADVERTISEMENT LOGO (LH)	Necessary	100.00 FS	*100.00 FS
17	1		*FRONT TYRE (LH)	Serviceable	216.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

<b>Sub Total (\$\$)</b>	<b>6,427.00</b>	<b>617.50</b>
<b>- List Item Discount on L Items 20.00/20.00% (\$\$)</b>	<b>1,222.20</b>	<b>103.50</b>
<b>Total Parts (\$\$)</b>	<b>5,204.80</b>	<b>514.00</b>

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	PANEL BEATING-REPAIR BUMPER	New	250.00	200.00
2	SPRAY PAINTING CHARGE-BUMPER/FENDER	New	500.00	400.00
3	TUFF KOTE	New	50.00	0.00
4	REMOVE/REFIX UNDERCARRIAGE (FRT)	New	400.00	50.00
5	FRT WHEEL ALIGNMENT	New	120.00	60.00
Gross Labour Cost (\$\$)			<b>1,320.00</b>	<b>710.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >