

EDIT	SR NO	REPAIR/REPLACE (LABOUR)	PART NAME	LABOUR R&R	LABOUR REPAIR	PAINT	ACTION (LABOUR)	COMMENT
	7		TO PUTTY & SPRAY PAINT ON THE AFFECTED AREAS. ETC BOOT LID INNER & OUTER. REAR BUMPER, LHS & RHS REAR FENDER, REAR END PANEL & REAR SPARE TYRE COMPARTMENT.	1000	0	0	Reviewing	

EDIT	SR NO	QUAN TITY	MATERIAL	SIDE	PART NAME	PART NUMBER	REPAIR/REPLACE (PARTS)	CONDITION	LIST PRICE	DEPRJ BTTR%	DISC OUNT%	SALV AGE%	PART PRICE(NET)
	10	1			BOOT LID "TOYOTA" EMBLEM			Necessary	68		25		51
	11	1			BOOT LID "COROLLA" BADGE			Necessary	64		25		48
	12	1			BOOT LID "ALTIS" BADGE			Necessary	64		25		48
	13	2			BOOT LID HINGES			Serviceable	0		25		0
	14	1			BOOT LID LOCK			Bent	355		25		266.25
	15	1			BOOT LID OUTER CHROME GARNISH			Serviceable	0		25		0
	16	2			BOOT LID LICENCE PLATE LAMPS			Serviceable	0		25		0
	17	1			REAR END PANEL			Bent	705		25		528.75
	18	1			REAR END PANEL TOP GARNISH			Deformed	345		25		258.75
	19	10			REAR END PANEL TOP GARNISH CLIPS			Necessary	3.5		25		26.25
	20	1			REAR END PANEL WEATHERSTRIP			Necessary	185		25		138.75
	21	1			REAR END PANEL INNER CENTER TRIM			Serviceable	0		25		0
	22	1			REAR SPARE TYRE COMPARTMENT			Serviceable	0		25		0

Detailed Assessment

Inspection Date *

03/15/2018



Total Loss

Yes No

Towing Charges

0

Voluntary Excess

0

Compulsory Excess

0

Young/Inexperienced/Unnamed Driver Excess

0

Other Excess

Age of Tyres

Front Tyre Size

205/55R16

Condition of Vehicle at time of survey

General condition

Fair

Steering (Serviceable)

Yes No

Footbrake (Serviceable)

Yes No

Handbrake (Serviceable)

Yes No

Engine Modification

Yes No

Pre-accident condition

Good

Tyre Condition

Spare wheel

Rear Tyre Size

205/55R16

FNOL INFORMATION... 247 JALAN BUJAN LAY, Singapore

POST SURVEY INF...

CATEGORY

Address type

FNOL INFORMATION...

Personal Correspondence

POST SURVEY INF...

CATEGORY

Gender

FNOL INFORMATION...

Male

POST SURVEY INF...

CATEGORY

Marital status

FNOL INFORMATION...

Unknown

POST SURVEY INF...

CATEGORY

Identification #

FNOL INFORMATION...

07/11/1995

POST SURVEY INF...

POLICY INFORMAT... TPVD TOYOTA

ASSESSMENT INFO... TOYOTA

CATEGORY Model

POLICY INFORMAT... COROLLA ALTIS-1.6 CLASSIC CVT (A)

ASSESSMENT INFO... COROLLA ALTIS CLASSIC 1.6 CVT

CATEGORY Type

POLICY INFORMAT...

ASSESSMENT INFO...

CATEGORY Type of Paint

POLICY INFORMAT...

ASSESSMENT INFO...

CATEGORY Chassis No

POLICY INFORMAT...

ASSESSMENT INFO... MR053REH104559092

CATEGORY Date of Birth

FNOL INFORMATI... November 7, 1995

POST SURVEY INF... mm/dd/yyyy



CATEGORY Age

FNOL INFORMATI... 22

POST SURVEY INF...

CATEGORY Occupation

FNOL INFORMATI... Unknown

POST SURVEY INF...

CATEGORY Education Qualification

FNOL INFORMATI... Other

POST SURVEY INF...

CATEGORY Driving Experience

HO Winnie
6568804833
winnie.ho@axa.com.sg

Pending verification -
Direct Settlement

- Messages
- Invoices
- History

Additional Instructions

Documents		Assessment	Metrics	Notes	Add	
CREATED USER	VERSION DATE	ESTIMATED AMOUNT	APPROVED AMOUNT	STATUS	SHARE	CLONE
User Portal	6/5/18 8:59 AM	4900	4900	Open	Share	Clone
NIKAM Santosh Pandurang	3/14/18 9:11 AM	6298	6298	Open	Share	Clone

NAME	TYPE	SUB-TYPE	AUTHOR	DATE UPLOADED
SLH3086Z TP GIA.PDF	Reports & Statement	GIA Report	NIKAM Santosh Pandurang	March 14, 2018

HO Winnie
6568804833
winnie.ho@axa.com.sg

[Messages](#)[Invoices](#)[History](#)[Additional Instructions](#)

Pending verification -
Direct Settlement

Documents	Assessment	Metrics	Notes	Document Type	Document SubType

[Upload Documents](#)

NAME	TYPE	SUB-TYPE	AUTHOR	DATE UPLOADED
LKK REINSPECTION PHOTOS.pdf	Reports & Statement	Others	LKK AUTO CONSULTANTS PTE LTD (TP)	June 20, 2018
LKK INSPECTION PHOTOS.pdf	Reports & Statement	Others	LKK AUTO CONSULTANTS PTE LTD (TP)	June 20, 2018
AXA MANDATE REQUEST.pdf	Forms / Claim Documents	Others	LKK AUTO CONSULTANTS PTE LTD (TP)	June 6, 2018
GIA SEARCH.pdf	Forms / Claim Documents	Others	LKK AUTO CONSULTANTS PTE LTD (TP)	June 5, 2018