

ASS. REC. BY:

REF: CS/SMO18004958 / 4thth Special Instruction:

Surveyor: Marcellus ASSIGNMENT (Office)

From (Person): Irene of SMO Date/Time: 15/03/2018 3:33pm

Estimated Cost: _____ Bill to: _____

OD / ~~TP~~ WS / TP RES / OD RES / EVA / INV / MV / CS
To Inspect Vehicle No: SJT 1981M Insured: SKX 8258P

at Workshop m/s ZOOM Autowerks Tel: 9450 7920
of 15 Kaki Bukit Rd 4 #01-53

Policy No: _____ Claim No: CTMD1801161

Sum Insured: _____ Excess: _____

Make of Veh: _____ D.O.A. 14/03/2018
(Client's Record)

CA / REV / REP. / REV 24 HRS Wp 16-03-2018 H.O.D. Endorsement: _____

Date/Time: 15/03/2018 4:25pm Person Contacted: Z/m Vehicle IN/OUT

Date/Time	Action/Instruction (✓) Estimate
	SJT 1981M - (REP/REG/16011953) / Uwb3g? D.O.A: 240616
	SKX 8258P - x
21/3/18 @	4.25pm Informed Mr Gnoh, we are paying estimate from repairer.

REF: SMO

ASSIGNMENT

From: Date: 16/3/18

Estimated Cost:

OD TP / WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No: SJT 1981M
at Workshop m/s Zoom atwerkes
of 15 Kaki Bkt Rd 4 # 01-53

Insured:

Policy No:

Claims No:

Sum Insured: Excess:

(Client's Record)

Make of Veh: Elin - 9450 7920

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

Bal. or Market Value:

IDAC Accident Rpt: Consistent? : Yes or No

GIA / PR Seen: Consistent? : Yes or No

Est. Repairs: 4 days Res.: Yes or No

Lump Sum: 20 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS ^{1wp}

Date: Person Contacted: Vehicle: IN / OUT

Veh No: SJT 1981M Yr Regn: 9 09

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or (A)

Make: VOLVO 540 C.C. 1999

Colour: Red A/C: Insured / Std / NI / NA

Sp. Reading: 190/76 T/Radio: Insured / Std / NI / NA

Eng/No:

C/No: YVIMS434BA 248871

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 205/55-R18

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front R/Bal. 6 mm Rear R/Bal. 6 mm

L/Bal. 6 mm L/Bal. 6 mm

D.O.A. 14/3/18 D.O.I. 19/3/18

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / UIC / Rooftop or

The UIC / Chassis frame / Body Structure affected due to collision. Rear

22/3/18 Confirmed d/s @ 4000 with Eater.
(Red: 12263 30; 75%)

RECEIVED 23 MAR 2018

Date/Time File Pass to? : Preli. Report

1) 23/3 Typist : Final Report

Date/Time. File Return to?

2)

Report Format: TP
Lump Sum / I.B.I: (\$) 4000/-

Days Of Repair: 4

Resurvey No. of Trip: 1

- Add Fee: Site Insp (\$)
- Interview (\$)
- Tech. Invs (\$)
- Weekend (\$)

- Survey Fee:
- Transportation
- Photos
- Other

\$ + RS \$
TOTAL
450



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

SOMPO INSURANCE SINGAPORE PL

Ref : CS/SMO18004958/Utb

50 RAFFLES PLACE

#05-01/06

SINGAPORE LAND TOWERSINGAPORE 048623

Date : 15-03-2018



Code : SMO

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SKX 8258P	Veh. Inspected	SJT 1981M
Policy No.		Coverage (\$)	0.00
Claim No.	CMTD1801161	Excess (\$)	0.00
Assign From	IRENE	Assign Date	15/03/2018

2. Vehicle Particulars & Condition

Make & Model		c.c	0
Engine No.	HIDDEN	Year of Reg.	
Chassis No.		Colour	
Odometer	-	Steering	
Brakes		Modification	
General			

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm

4. Description of Damages

--

5. General Information

Accident Date	14/03/2018	Inspection Date	16/03/2018
Survey held at	15 KAKI BUKIT RD 4 #01-53		
Repairer	ZOOM AUTOWERKS PTE LTD		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.
--

Catherine Chong (LKK Auto)

From: Henry, Irene James <irene.henry@sompo.com.sg>
Sent: Thursday, 15 March, 2018 3:33 PM
To: assignments
Cc: Nivitha (LKK Auto)
Subject: FW: SOMPO REF: CMTD1801161/RE: Pre-Repair Inspection for SJT 1981 M // Accident on 14/03/2018 @ 12:00HR at along Bt Timah Rd, U-Turn to Dunearn Rd involving Vehicle Number SJT 1981 M & SKX 8258 P
Attachments: New Doc 2018-03-15.pdf

Our Claim Reference: CMTD1801161

Dear LKK AUTO,

Kindly assist to arrange to conduct motor survey of the mentioned vehicle (SJT 1981M)

Please refer to the correspondence below.

Best Regards

Irene Henry

Claims Division

D: 6322 4618 | T: 6461 6555 | F: 6221 3147



Innovation for Wellbeing

SOMPO

A Century of Trust

Sompo Insurance Singapore Pte. Ltd.

50 Raffles Place, #05-01/06 Singapore Land Tower, Singapore 048623

Website: www.sompo.com.sg | **Facebook:** www.facebook.com/SompoSG

Disclaimer: This e-mail, including attachments, is intended for the person(s) or company named and may contain confidential and/or legally privileged information. Unauthorised disclosure, copying or use of this information may be unlawful and is prohibited. If you are not the intended recipient, please delete this message.

Privacy Policy Notice: Sompo Insurance Singapore Pte. Ltd. may collect, use and disclose your personal data for the purposes stated in our Privacy Policy. This may include disclosure to holding and associated companies, credit bureau, parties to whom disclosure is permitted/required by laws, our third party service providers and agents (acting on our behalf). Please click [here](#) for our Privacy Policy.

From: Zoom Autowerks [mailto:zoomautowerks@gmail.com]

Sent: Thursday, 15 March, 2018 3:28 PM

To: Henry, Irene James <irene.henry@sompo.com.sg>

Subject: Re: SOMPO REF: CMTD1801161/RE: Pre-Repair Inspection for SJT 1981 M // Accident on 14/03/2018 @ 12:00HR at along Bt Timah Rd, U-Turn to Dunearn Rd involving Vehicle Number SJT 1981 M & SKX 8258 P

Dear All,

Please arrange Marcus Chua - LKK.

On Thu, Mar 15, 2018, 15:15 Henry, Irene James <irene.henry@sompo.com.sg> wrote:

Our Reference: CMTD1801161/

Your Reference: SJT 1981M

Date: 15th March 2018

Without Prejudice

BY EMAIL ONLY

Attention:

M/S ZOOM AUTOWERKS PTE LTD

ACCIDENT INVOLVING SLP 2948B & SKX 8258P ON 14.03.2018

Dear Sir

We refer to your Notice of Accident via email dated 15/03/2018.

For future motor survey requests, kindly re-direct them to motorsurvey@sompo.com.sg

We intend to conduct a pre-repair survey of the damage to your client's/your customer's vehicle jointly with your client/your motor workshop. We propose to use one of the motor surveyors named in the attached list to conduct the joint pre-repair survey as a single joint expert.

Pre-Repair Survey

	Motor Surveyor	Surveyor	Selection (Indicate as tick)
1	Raleigh Services	Andrew Ow Yong	
		Vincent Ng	
2	LKK Auto Consultants	Kenneth Kong (North area)	
		Marcus Chua (East area)	

		Ma Chin Fook (North area)	
		Mohd Rasul (West area)	
		Mohd Taufikh (West area)	
3	Priority Services	Jimmy Lee	
		Lawrence Ng	
		Jeffery Ong	
4	JP Knights Adjusters & Surveyors	Jason Lek	
5	In House surveyor	Teo See Ling	

Please let us know within two (2) working days whether you agree to the appointment of any of these motor surveyors as a single joint expert. You may select up to two of the listed motor surveyors. We will bear the cost of the pre-repair survey carried out by the single joint expert.

Best Regards

Irene Henry

Claims Division

D: 6322 4618 | T: 6461 6555 | F: 6221 3147



Sompo Insurance Singapore Pte. Ltd.

50 Raffles Place, #05-01/06 Singapore Land Tower, Singapore 048623

Website: www.sompo.com.sg | **Facebook:** www.facebook.com/SompoSG

Disclaimer: This e-mail, including attachments, is intended for the person(s) or company named and may contain confidential and/or legally privileged information. Unauthorised disclosure, copying or use of this information may be unlawful and is prohibited. If you are not the intended recipient, please delete this message.

Privacy Policy Notice: Sompo Insurance Singapore Pte. Ltd. may collect, use and disclose your personal data for the purposes stated in our Privacy Policy. This may include disclosure to holding and associated companies, credit bureau, parties to whom disclosure is permitted/required by laws, our third party service providers and agents (acting on our behalf). Please click [here](#) for our Privacy Policy.

From: Zoom Autowerks [mailto:zoomautowerks@gmail.com]

Sent: Thursday, 15 March, 2018 12:54 PM

To: claimsreport <claimsreport@sompo.com.sg>

Subject: Pre-Repair Inspection for SJT 1981 M // Accident on 14/03/2018 @ 12:00HR at along Bt Timah Rd, U-Turn to Dunearn Rd involving Vehicle Number SJT 1981 M & SKX 8258 P

Dear Sir/Madam,

We are instructed by Chew Tsuey Ngor Grace to notify you of a road traffic accident on 14/03/2018 at about 12:00HR at along Bt Timah Rd, U-Turn to Dunearn Rd involving our client's vehicle registration number

SJT 1981 M

and vehicle registration number SKX 8258 P driven by your insured at the material time.

A copy of the Singapore Accident Statement/Traffic Police Report filed is enclosed. As a result of the accident, our client's vehicle has been damaged. Before our client proceed to repair the damaged vehicle, please let us know within 2 working days of your receipt of this notice whether you would like to conduct a pre-repair survey of the vehicle. If we do not receive any reply from you within the stipulated time, our client shall proceed to repair the vehicle without further reference to you.

Please contact me @ 9450 7920, should you require more information.

Kindly arrange survey at Blk 15 Kaki Bukit Road 4, Bartley Biz Centre, #01-53, Singapore 4178

08.

Warmest Regards,

Elin Cai

Zoom Autowerks Pte Ltd

832 Sims Avenue, Eunosville

#12-884, Singapore 400832

☎9450 7920

Shiau Chan (LKKAuto)

From: Shiau Chan (LKKAuto)
Sent: Wednesday, 21 March 2018 4:25 PM
To: Gnoh, Pau Loong; assignments; SUR
Cc: Henry, Irene James
Subject: RE: Direct Settle ; RE: SOMPO REF: CMTD1801161/RE: Pre-Repair Inspection for SJT 1981 M // Accident on 14/03/2018 @ 12:00HR at along Bt Timah Rd, U-Turn to Dunearn Rd involving Vehicle Number SJT 1981 M & SKX 8258 P

Dear Mr Gnoh,

Please be informed that we have inspected the vehicle SJT 1981M on 14/03/2018.

We are pending for estimate from repairer.

Best Regards,

Shiau Chan (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: siewsc@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Gnoh, Pau Loong [mailto:PauLoong.Gnoh@sompo.com.sg]
Sent: Tuesday, 20 March 2018 8:43 AM
To: Denise Tay (LKKAuto) <denisetay@lkkauto.com>; Admin-D (LKKAuto) <admin-d@lkkauto.com>; assignments <assignments@lkkauto.com>; SUR <sur@lkkauto.com>
Cc: Henry, Irene James <irene.henry@sompo.com.sg>
Subject: RE: Direct Settle ; RE: SOMPO REF: CMTD1801161/RE: Pre-Repair Inspection for SJT 1981 M // Accident on 14/03/2018 @ 12:00HR at along Bt Timah Rd, U-Turn to Dunearn Rd involving Vehicle Number SJT 1981 M & SKX 8258 P

Dear Ms Tay,

Enclosed as requested, are the respective e-file reports.

Best Regards

Gnoh Pau Loong

Claims Division

D: 6329 5217 | T: 6461 6555 | F: 6221 3147



Innovation for Wellbeing

SOMPO

A Century of Trust

Sompo Insurance Singapore Pte. Ltd.

50 Raffles Place, #05-01/06 Singapore Land Tower, Singapore 048623

Website: www.sompo.com.sg | **Facebook:** www.facebook.com/SompoSG

Disclaimer: This e-mail, including attachments, is intended for the person(s) or company named and may contain confidential and/or legally privileged information. Unauthorised disclosure, copying or use of this information may be unlawful and is prohibited. If you are not the intended recipient, please delete this message.

Privacy Policy Notice: Sompo Insurance Singapore Pte. Ltd. may collect, use and disclose your personal data for the purposes stated in our Privacy Policy. This may include disclosure to holding and associated companies, credit bureau, parties to whom

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type: Singapore NRIC

Owner ID: 0539Z

Vehicle Details

Vehicle No.: SJT1981M

Vehicle to be Exported: No

Intended De-registration Date: 19 Mar 2018

Vehicle Make: VOLVO

Vehicle Model: S40 2.0L AT ABS D/AB 2WD 4DR

Primary Colour: Red

Manufacturing Year: 2009

Engine No.: B4204S3166598

Chassis No.: YV1MS434BA2485871

Maximum Power Output: 107.0 kW (143 bhp)

Open Market Value: \$31,443.00

Original Registration Date: 28 Sep 2009

First Registration Date: 28 Sep 2009

Transfer Count: 0

Actual ARF Paid: \$31,443.00

Intended PARF Rebate Details

PARF Eligibility: Yes

PARF Eligibility Expiry Date: 27 Sep 2019

PARF Rebate Amount: \$17,293.00

Intended COE Rebate Details

COE Expiry Date: 27 Sep 2019

COE Category: E - Open Category

COE Period(Years): 10

QP Paid: \$18,189.00

COE Rebate Amount: \$2,768.00

Total Rebate Amount: \$20,061.00

The information contained herein is correct as at 19 Mar 2018

OK



Post an Advertisement
Sell it yourself! Advertise it at just **\$58 until it's SOLD!**

Post an Ad Advertiser Login Ways of Selling

New 5 Year Coe Renewal Honda Stream 1.8A RSZ



\$2800 Downpayment Monthly
From \$738 Onwards. Lowest
3.68%P.A@GV Cars Financing
GV Credit Pte Ltd StarAd

HIN LUNG AUTO
Ho Bee Group
One Stop Car Hub
Finance, Insurance, Workshop
New and Used Cars
30 years of car sale

Browse by Category

Sort by Date Posted 20 results/page

1 vehicles

Citroen DS4

Advanced Search Submit

Make	Model	Price	Depreciation	Reg Date	Eng Cap	Mileage	Veh Type	Status
------	-------	-------	--------------	----------	---------	---------	----------	--------

Search Selection	Citroen DS4	Any	Any	2013	Any	Any	Any	Available
-------------------------	-------------	-----	-----	------	-----	-----	-----	-----------



Citroen DS4 1.6A e-HDi	\$55,800	\$9,780 /yr	21-Feb-2013	1,560 cc	68,339 km	Hatchback	Available
-------------------------------	-----------------	--------------------	--------------------	-----------------	------------------	------------------	------------------

Fuel Type: Diesel (Euro 5 Engine and Above) **Graded B by STV**
Export Value At \$50k! 1 Year Free Servicing! \$6K Down Payment! STA Certified Accident Free Quality Pre Owned With Low Mileage & Agent Service History For Peace Of Mind. 100% Loan Approval With Our Fin...

Cosmo Automobiles
Posted: 19-Mar-2018 Tags: 2013 Citroen DS4, Citroen DS4, Citroen, DS4, Used Citroen

Save this search criteria, to get email alerts whenever a match is found.

Make	Model	Price	Depreciation	Reg Date	Eng Cap	Mileage	Veh Type	Status
------	-------	-------	--------------	----------	---------	---------	----------	--------

For old advertisements, view Expired ads

20 results/page

sgCarMart is the number one car classified for parallel import cars, Toyota, Honda, Nissan, Mitsubishi & BMW. There are plenty of cars for sale, from vans, trucks, sedan cars, luxury cars, sports cars or stationwagons, SUV, MPV, hatchback, to COE cars & OPC cars. You can also buy from a car auction, look up car loans, low mileage cars, car brands, carpark rates & car insurance. Find buy used Citroen DS4, Citroen DS4 Singapore, used Citroen DS4 Singapore, used Citroen DS4, used vehicles Singapore or even buy used Citroen DS4 Singapore. We have new car dealers comprising parallel importers, authorised car dealers, and used car dealers on our site. Find new car price lists, new car launches and new car promotions. Visit our partner sites for job openings for Singapore jobs, real estate properties for sale, mover, car performance parts, car discussion, forum discussion, commercial vehicle leasing & COE results.

All prices and other information displayed on sgCarMart.com are gathered from sources and based on algorithms that are believed by sgCarMart.com to be reliable, but no assurance can be given that this information is accurate, complete or current. sgCarMart.com does not assume any responsibility for errors or omissions or warrant the accuracy of this information.

- Home
- New Car
- Used Car
- Sell Car
- Motoring Directory
- Products Guide
- Article
- Forum
- Tool & Tip

- About Us
- Careers
- Contact Us
- Sitemap

© 2004-2018 sgCarMart. All rights reserved.

- Terms of Service
- Privacy Policy
- Personal Data Protection Statement

Compare

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	15/03/2018 14:55
Date Of Accident	14/03/2018 12:00
Exact Location Of Accident	FROM BUKIT TIMAH RD U-TURN TO DUNEARN RD
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SJT1981M
Insured/Policyholder	
Name Of Registered Owner	CHEW TSUEY NGOR GRACE
NRIC No	S2630539Z
Email Address	NOEMAIL
Mobile Phone No	(LOCAL) +65-97241006
Alternative Phone No	OFFICE-97241006

Vehicle Particulars

Manufacturer	VOLVO
Model	S40 2.0L AT ABS D/AB 2WD 4DR
Exact Purpose for which vehicle was being used at time of accident	PRIVATE USE
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR

Insurance Company

Name of Insurance Company	MSIG INSURANCE (SINGAPORE) PTE. LTD.
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	A28816839QMY
Cover Note Number	

Driver

Name of Driver	GRACE CHEW TSUEY NGOR
NRIC No	S2630539Z
Date Of Birth	29/10/1966
Occupation	INDOOR
Date Of Driving Pass	07/05/1998
Driving Experience	19 YEARS AND 10 MONTHS
Gender	FEMALE
Mobile Number	(LOCAL) +65-97241006
Fax Number	
Contact Number	OFFICE-97241006
EMAIL Address	NOEMAIL

Address	18 LIMAU RISE
Postcode	465843
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OWNER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	COLLISION - HEAD TO REAR
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles involved in the accident	2
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

REFER TO STATEMENT.

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SKX8258P
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	
NRIC/Passport Number	
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

Accident Sketch Plan

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ii. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes").
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes;
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims;
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.


Policyholder's Signature
Date & Time



Driver's Signature
(if driver is not the policyholder)
Date & Time


Reporting Centre Personnel's Signature
Name:
NRIC/TIN No.:

Accident Sketch Plan

SKETCH PLAN

VEHICLE A: SJT 1981M
VEHICLE B: SLX 825BP



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT


On the stated date & time, I, vehicle "A", SJT 1981M, was stationary on the stated vehicle as I was checking on on-coming traffic before the give-way line. Suddenly, vehicle "B", SLX 825BP, hit into my stationary vehicle's rear portion.

DECLARATION

I/We declare the foregoing particulars are true in every respect



Policyholder's Signature
Date & Time:



Driver's Signature
(If driver is not the policyholder)
Date & Time:



Reporting Centre Person's Signature
Name:
NRIC/ID No.:



ZOOM AUTOWERKS PTE LTD

832 Sims Avenue, Eunosville

#12-884 Singapore 400832

Tel: 9450 7920

* zoomautowerks@gmail.com

1/11/18

D.O.A: 14 March 2018

OWNER: CHEW TSUEY NGOR GRACE

16 March 2018

REG NO.: SJT 1981 M

MAKE/MODEL: VOLVO S40

Not Insured
 2/5 \$4000/-
 4 day.
 19/3/18
 take photo after repair

ESTIMATED REPAIR COST FOR THE VEHICLE MENTIONED ABOVE

QTY	DESCRIPTION	LIST ITEMS	AMT(\$)
1	Boot lid	1815	\$ 22/24 1,895.00
2	Boot lid hinges		\$ 27 270.00
1	Boot lid lock		\$ 27 248.00
1	Boot lid rubber		\$ 27 189.00
1	Boot lid "S40" emblem		\$ 27 62.00
1	Boot lid "VOLVO" emblem		\$ 27 68.00
1	Boot lid "2.0i" emblem		\$ 27 48.00
2	Rear taillamps		\$ 27 1,116.00
1	Rear end panel	v/san	\$ 27 780.00
1	Rear end panel inner garnish		\$ 27 115.00
1	Rear bumper	1215	\$ 27 1,655.00
1	Rear bumper clip (1 set)		\$ 27 80.00
1	Rear bumper inner sponge		\$ 27 189.00
1	Rear bumper lower guard		\$ 27 559.00
2	Rear bumper reflectors		\$ 27 370.00
1	Rear bumper reinforcement	2/san	\$ 27 842.00
2	Rear bumper side retainers		\$ 27 192.00
1	Rear bumper tow hook cover		\$ 27 50.00
1	Rear bumper top beam		\$ 27 89.00
1	Rear spare tyre board		\$ 27 445.00
1	Rear spare tyre panel		\$ 27 1,165.00
1	Rear exhaust silencer		\$ 27 1,085.00
2	Rear exhaust mountings		\$ 27 96.00
1	Rear fender		\$ 27 1,679.00
			\$ 13,287.00
Less 10%			\$ 1,328.70
			\$ 11,958.30

Less 10%

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

PAGE 1 OF 2 by Repairer

Signature: _____

Date: _____

4130
3717

<u>SPECIAL NETT ITEMS</u>	
1	Rear number plate with holder
1	Rear reverse sensor (1 set)

\$	11	50.00	X
\$	11	350.00	X
\$		<u>400.00</u>	

<u>S/N</u>	<u>LABOUR CHARGES</u>
1	To remove, replaced damaged lamps and check up rear wiring.
2	To remove and refit inner garnishes.
3	To remove and refit rear reverse sensor.
4	To transfer rear boot lid mechanism and wiring assembly.
5	To remove, refit and replace exhaust silencer and mountings.
6	To apply undercoating.
7	Panel beating.
8	To re-spray painting on the affected areas.

\$		80.00	20
\$		180.00	60
\$		120.00	50
\$		80.00	60
\$	11	150.00	X
\$		200.00	30
\$		1,600.00	480
\$		<u>1,500.00</u>	600
\$		3,910.00	

5017

GRAND TOTAL :

<u>\$</u>	<u>16,268.30</u>
-----------	------------------



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

SOMPO INSURANCE SINGAPORE PL

Ref : CS/SMO18004958/Utbn2

50 RAFFLES PLACE

#05-01/06

SINGAPORE LAND TOWERSINGAPORE 048623

Date : 27-03-2018



Code : SMO

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SKX 8258P	Veh. Inspected	SJT 1981M
Policy No.		Coverage (\$)	0.00
Claim No.	CMTD1801161	Excess (\$)	0.00
Assign From	IRENE	Assign Date	15/03/2018

2. Vehicle Particulars & Condition

Make & Model	VOLVO S40 (A)	c.c	1999
Engine No.	HIDDEN	Year of Reg.	2009
Chassis No.	YV1MS434BA2485871	Colour	RED
Odometer	190176	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	GOOD		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	205/55 R16	PIRELLI	6 mm
L/H Front Tyre	205/55 R16	PIRELLI	6 mm
R/H Rear Tyre	205/55 R16	PIRELLI	6 mm
L/H Rear Tyre	205/55 R16	PIRELLI	6 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION.
DAMAGES SEE DETAILS.

5. General Information

Accident Date	14/03/2018	Inspection Date	19/03/2018
Survey held at	15 KAKI BUKIT RD 4 #01-53		
Repairer	ZOOM AUTOWERKS PTE LTD		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS.
B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR: **4 Working Days**



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SJT 1981M

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	BOOT LID	DENTED / BENT	1,895.00	1,815.00
2	BOOT LID HINGES	NOT NECESSARY	270.00	-
1	BOOT LID LOCK	NOT NECESSARY	248.00	-
1	BOOT LID RUBBER	NOT NECESSARY	189.00	-
1	BOOT LID "S40" EMBLEM	NECESSARY	62.00	62.00
1	BOOT LID "VOLVO" EMBLEM	NECESSARY	68.00	68.00
1	BOOT LID "2.0I" EMBLEM	NECESSARY	48.00	48.00
2	REAR TAILLAMPS (N/S CRACKED)	OS NOT NECESSARY/NS NOT CONSISTENT WITH THE IMPACT	1,116.00	-
1	REAR END PANEL	TO REPAIR SEE LABOUR	780.00	-
1	REAR END PANEL INNER GARNISH	NOT NECESSARY	115.00	-
1	REAR BUMPER	DENTED / DEFORMED	1,655.00	1,215.00
1	SET REAR BUMPER CLIP	NECESSARY	80.00	80.00
1	REAR BUMPER INNER SPONGE	NOT FITTED	189.00	-
1	REAR BUMPER LOWER GUARD	NOT NECESSARY	559.00	-
2	REAR BUMPER REFLECTORS (N/S CRACKED)	OS NOT NECESSARY/NS NOT CONSISTENT WITH THE IMPACT	370.00	-
1	REAR BUMPER REINFORCEMENT	DENTED	842.00	842.00
2	REAR BUMPER SIDE RETAINERS	NOT NECESSARY	192.00	-
1	REAR BUMPER TOW HOOK COVER	NOT NECESSARY	50.00	-
1	REAR BUMPER TOP BEAM	NOT NECESSARY	89.00	-
1	REAR SPARE TYRE BOARD	NOT NECESSARY	445.00	-
1	REAR SPARE TYRE PANEL	NOT NECESSARY	1,165.00	-
1	REAR EXHAUST SILENCER	NOT NECESSARY	1,085.00	-
2	REAR EXHAUST MOUNTINGS	NOT NECESSARY	96.00	-
1	REAR FENDER	NOT NECESSARY	1,679.00	-
	LESS 10% DISCOUNT		-1,328.70	-413.00
			11,958.30	3,717.00
SPECIAL NETT ITEMS				
1	REAR NUMBER PLATE WITH HOLDER (SN)	NOT NECESSARY	50.00	-



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	SET REAR REVERSE SENSOR (SN)	NOT NECESSARY	350.00	-
			400.00	-
	LABOUR			
	TO REMOVE,REPLACED DAMAGED LAMPS AND CHECK UP REAR WIRING.		80.00	20.00
	TO REMOVE AND REFIT INNER GARNISHES.		180.00	60.00
	TO REMOVE AND REFIT REAR REVERSE SENSOR.		120.00	50.00
	TO TRANSFER REAR BOOT LID MECHANISM AND WIRING ASSEMBLY.		80.00	60.00
	TO REMOVE,REFIT AND REPLACE EXHAUST SILENCER AND MOUNTINGS.	NOT NECESSARY	150.00	-
	TO APPLY UNDERCOATING.		200.00	30.00
	PANEL BEATING.INCLUSIVE OF THE REPAIR OF REAR END PANEL.		1,600.00	480.00
	TO RE-SPRAY PAINTING ON THE AFFECTED AREAS.		1,500.00	600.00
			3,910.00	1,300.00
	GRAND TOTAL		16,268.30	5,017.00
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				4,000.00

Report Ref No. CS/SMO18004958/Utbn2

CHUA KANG SENG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.