

ASS. REC. BY:

REF:

CS/MSG 18004961 / Rmbez / Special Instruction:

Survivor:

Rosul

**ASSIGNMENT (Office)**

From (Person):

Elaine Ngu

of

MSG

Date/Time:

15/03/2018 2.13pm

Estimated Cost:

Bill to:

**OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS**

To Inspect Vehicle No:

FBL 1877T

Insured:

FBF 15508

at Workshop m/s

SG 98 motor

Tel:

of

dk 4001 Amk Ind Park 1 #01-21

Policy No:

MSD/VMT /18-989961 -WTT

Claim No:

MSC/V/18-000391

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A.

07/03/2018

CA / REV / REP. / REV 24 HRS 'wp'

16-03-2018

H.O.D. Endorsement:

Date/Time:

15/03/2018 3:44pm

Person Contacted:

Linda

Vehicle IN/OUT

Date/Time

Action/Instruction ( ✓ ) Estimate

FBL 1877T - X

FBF 15508 - X

sent pending estimate through memos

Confirm

L/S \$750 @ 3 days (Recl \$1360.50, 64%)

Signature *P. P. P.*

REF: MSIG

4335B

# ASSIGNMENT

From: \_\_\_\_\_ Date: 16/3/18

Estimated Cost: \_\_\_\_\_

OD/TP/WS/TP RES/OD RES/EVA/INV/MV

To Inspect Vehicle No: FBL 1877T

at Workshop m/s SG 98 Motor

of Blk 4001 A Mlc Ind Park 1 # 01-21

Insured: \_\_\_\_\_

Policy No. \_\_\_\_\_

Claims No. \_\_\_\_\_

Sum Insured: \_\_\_\_\_ Excess: \_\_\_\_\_

(Client's Record)

Make of Veh: \_\_\_\_\_

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value: \_\_\_\_\_

IDAC Accident Rpt: \_\_\_\_\_ Consistent? : Yes or No

GIA / PR Seen: \_\_\_\_\_ Consistent? : Yes or No

Est. Repairs: \_\_\_\_\_ days Res.: Yes or No

Lum Sum: \_\_\_\_\_ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS (wp)

Date: \_\_\_\_\_ Person Contacted: \_\_\_\_\_

Vehicle: IN / OUT

Veh No: FBL 1877T Yr Regn: 2015 / MAR

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover / Truck / Trailer or

Make: YAMAHA JUPITER MX C.C. 134

Colour: MULTI A/C: Insured / Std / NI / NA

Sp. Reading: 45595 T/Radio: Insured / Std / NI / NA

Eng/No: \_\_\_\_\_

C/No: MH 350C 006 EK 734877

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 70/90-17 R: 160/70-17

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI / TOYO / YOKO or MAXXIS

Front R/Bal. 3 mm Rear R/Bal. 3 mm

L/Bal. mm L/Bal. mm

D.O.A. 07/03/18 D.O.I. 16/03/18

Survey held at SG 98 Motor

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

RECEIVED 10 SEP 2018

Date/Time: File Pass to?

1) *typist*

Date/Time: File Return to?

2)

Report Format: TP

Lump Sum / B.I: (\$750.00)

Days Of Repair: 3

Resurvey No. of Trip: 1

Add Fee: ☐ Site Insp (\$)  
☐ Interview (\$)  
☐ Tech. Invs (\$)  
☐ Weekend (\$)

Survey Fee:

Transportation

☐ S+RS ☐ SI

☐ Photos

☐ Others

TOTAL

200

10

210

## ...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	12 Mar 2018		15 Mar 2018 14:13 <a href="#">Assign</a>				<b>New Assignment</b> <a href="#">Cancel Case</a>

Main	Reference	Claim Details	Documents	Show All
------	-----------	---------------	-----------	----------

**CLAIM SUBFOLDER DETAILS** [Created by insurer]

<b>Insured:</b>	MOHAMMAD AZREERUDIN BIN AMIRRUDIN, ID: S9419376A, Tel: +6596393524, Email: NOEMAIL		
<b>Main Claimant:</b>	MOHAMED RAMDAN BIN JAMALUDIN, ID: S9404335B		
<b>Vehicle Reg. No.:</b>	FBL1877T	<b>Date of Loss:</b>	07/03/2018 23:00 - :59
<b>Claim Type:</b>	TP / MSC/V/18-000391	<b>Policy/Cover Note No.:</b>	MSD/VMT/18-989961-WTT (Third Party Only) Coverage: 12/03/2017 - 11/03/2018
<b>Vehicle Reg. No. (Insured):</b>	FBF1550S	<b>Policy No. (Claimant):</b>	
		<b>Excess:</b>	
<b>Repairer:</b>	Sg 98 Motor Pte Ltd (HQ) BLK 4001 ANG MO KIO INDUSTRIAL PARK 1 #01-21, 569622 Ang Mo Kio - Tel: 64524898		
<b>Handling Insurer:</b>	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Elaine Ngu Siau Mei - 6594 2540]		
<b>Adjuster:</b>	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Imm.Advice due 16/03/2018]		
<b>Driver/Custodian (Insured):</b>	MOHAMMAD AZREERUDIN BIN AMIRRUDIN (23 / Male), NRIC: S9419376A, Tel: +6596393524		
<b>Adj Asg. Remarks:</b>	Please arrange LKK Rasul for the pre repair inspection.		

**ASSOCIATED MAIL RECEIVED** View All Compose Case Mail

There are no mail for this case.

☐ **ALL ASSOCIATED TASKS** View All Search Tasks Create New Task Complete

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									




# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
MSIG INSURANCE (SINGAPORE) PTE LTD		Ref : CS/MSG18004961/R1rb	
16 RAFFLES QUAY #24-01 HONG LEONG BLDG SINGAPORE 048581		Date : 15-03-2018	
		Code : MSG	
<b>1. Policy Particulars :- THIRD PARTY CLAIM</b>			
Insured Veh.	FBF 1550S	Veh. Inspected	FBL 1877T
Policy No.	MSD/VM/18-989961-WTT	Coverage (\$)	0.00
Claim No.	MSC/V/18-000391	Excess (\$)	0.00
Assign From	MERIMEN (ELAINE NGU)	Assign Date	15/03/2018
<b>2. Vehicle Particulars &amp; Condition</b>			
Make & Model		c.c	0
Engine No.	HIDDEN	Year of Reg.	
Chassis No.		Colour	
Odometer	-	Steering	
Brakes		Modification	
General			
<b>3. Conditions of Tyres</b>			
	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm
<b>4. Description of Damages</b>			
<b>5. General Information</b>			
Accident Date	07/03/2018	Inspection Date	16/03/2018
Survey held at	SG 98 MOTOR PTE LTD BLK 4001 ANG MO KIO INDUSTRIAL PARK 1 #01-21 SINGAPORE 569622		
<b>5a. Remarks</b>			
A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			

## Print Sent Message

This mail is associated with :

**\*FBL1877T (MSC/V/18-000391)**  
**[FBF1550S]**

TP

MOHAMED RAMDAN BIN JAMALUDIN  
Mar 7 2018 11:00PM  
[MOHAMMAD AZREERUDIN BIN AMIRRUDIN]  
Sg 98 Motor Pte Ltd

**From** LKK Auto Consultants Pte Ltd (LKK\_HQ), sent on 19/03/2018 17:14 PM.  
**To** elaine\_ngu@sg.msig-asia.com  
**Subject** FBL1877T (MSC/V/18-000391)

Dear Elaine,

Please be informed that we have inspected the vehicle **FBL 1877T** on 16/03/2018.

We are pending for estimate from repairer.

Thank you.

Regards,  
Jannice

## SINGAPORE ACCIDENT STATEMENT

### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

### ACCIDENT STATEMENT

Date Of Report	12/03/2018 13:51
Date Of Accident	07/03/2018 23:00
Exact Location Of Accident	PUNGGOL CENTRAL / PUNGGOL WALK
Country/State of Loss	SINGAPORE

### DETAILS OF OWN VEHICLE

Vehicle Registration Number	FBL1877T
<b>Insured/Policyholder</b>	
Name Of Registered Owner	MOHAMED RAMDAN BIN JAMALUDIN
NRIC No	S9404335B
Email Address	NOEMAIL
Mobile Phone No	(LOCAL) +65-81158661
Alternative Phone No	OTHERS-81158661

### Vehicle Particulars

Manufacturer	YAMAHA
Model	JUPITER MX 135
Exact Purpose for which vehicle was being used at time of accident	PRIVATE USE
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	MOTORCYCLE

### Insurance Company

Name of Insurance Company	NTUC INCOME INSURANCE CO-OPERATIVE LTD
Type Of Coverage	THIRD PARTY
Fleet Policy	NO
Policy Number	5094400884
Cover Note Number	

### Driver

Name of Driver	MUHAMMAD FAZELLI BIN KARAMDA
NRIC No	S8526519I
Date Of Birth	02/07/1985
Occupation	OUTDOOR
Date Of Driving Pass	07/12/2007
Driving Experience	10 YEARS AND 3 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-81158661
Fax Number	
Contact Number	OTHERS 81158661

Address BLK 308A PUNGGOL WALK  
#04-444  
Postcode 821308  
Was driver an employee of the Insured's Company NO  
If No, Relationship of the Driver with the Insured FRIEND  
Vehicle Registration Number of Driver's Own Vehicle -  
-  
Insurance Company of Driver's Own Vehicle -  
-  
-

#### General Information of the Accident

Type Of Accident COLLISION - HEAD TO REAR  
Weather Conditions CLEAR  
Road Surface DRY

#### Other Information

Was any foreign vehicle involved in this accident? NO  
Number of vehicles involved in the accident 2  
Was any body injured in the Accident? YES  
Was any injured conveyed to hospital by ambulance? YES  
Was any other material or property damaged? YES  
I have been approached by unknown person(s) soliciting/offering accident claims assistance. NO  
Number of Passengers (Including Driver) 2  
Passenger 1  
NAME: : FARADILAH BTE ABDULLAH SHIRAT  
GENDER: : FEMALE

#### Details of Police Action

Was the accident reported to the police? YES  
If Yes, Please state which Police Station  
Police Station Name PUNGGOL N.P.C  
Police Station Address ROAD: 21A TEBING LANE , POSTCODE: 828837 , COUNTRY: SINGAPORE  
Police Station Contact TEL NO: - FAX NO:  
Was notice of intended Prosecution given? NO  
If Yes, against whom?

#### Circumstances of Accident

REFER ATTACHED

#### Attachment(s)

Are accident photos available for attachment? YES  
Was there any video captured by Car Camera? NO  
Was there any audio recorded? NO

#### DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number FBF1550S  
Vehicle Make/Model/Colour  
Details Of Properties  
Vehicle Category MOTORCYCLE  
Name of Driver  
NRIC/Passport Number  
Contact Number

Postcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

#### DETAILS OF INJURED PERSON 1

Name	MUHAMMAD FAZELLI BIN KARAMDA
Approximate Age	
Injuries Sustain	REFER POLICE REPORT
Injured person in which vehicle?	FBL1877T
Were seat belts worn?	
Was this injured conveyed to hospital by ambulance?	YES
Address	
Postcode	

#### DETAILS OF INJURED PERSON 2

Name	FARADILAH BTE ABDULLAH SHIRAT
Approximate Age	
Injuries Sustain	REFER POLICE REPORT
Injured person in which vehicle?	FBL1877T
Were seat belts worn?	
Was this injured conveyed to hospital by ambulance?	NO
Address	
Postcode	

#### DETAILS OF INJURED PERSON 3

Name	NA
Approximate Age	
Injuries Sustain	REFER POLICE REPORT
Injured person in which vehicle?	FBF1550S
Were seat belts worn?	
Was this injured conveyed to hospital by ambulance?	YES
Address	
Postcode	



**SKETCH PLAN**

**IMPORTANT NOTICE**

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the Insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the Insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

**8. Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:


- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
  - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
  - (ii) investigating the accident and/or my claims;
  - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
  - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
  - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims. (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
  - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
  - (ii) for complying with requirements under any regulations, laws or court orders.

\_\_\_\_\_  
Policyholder's Signature  
Date & Time:

\_\_\_\_\_  
Driver's Signature  
(If driver is not the policyholder)  
Date & Time:

\_\_\_\_\_  
Reporting Centre Personnel's Signature  
Name:  
NRIC/FIN No:

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

Refer to police Report M: T/20180308/2194

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature  
Date & Time:

Driver's Signature  
(If driver is not the policyholder)  
Date & Time:

Reporting Centre Personnel's Signature  
Name:  
NRIC/FIN No.:

Sent on  
24/3/2018

# SG 98 MOTOR PTE LTD

4001, Ang Mo Kio Industrial Park 1 #01-21 SINGAPORE 569622

Tel: 6452 4898 Fax: 6452 4868

Email: sg\_motor\_enterprise@yahoo.com.sg

Date: 23 March 2018

To : LKK

By Fax: 6256-4315

Attn : Rasul

Tel : 90010068

VEHICLE NO : FBL 1877T

Yamaha Jupiter MX

ACCIDENT DATE: 7 March 2018

Description	Qty	Quotation \$
1 Rear Mudguard	1	150 180.00 <i>scr</i>
2 Rear Exhaust Pipe	1	560.00 <i>repair</i>
3 Rear Footrest Bracket	1	80 120.00 <i>chk</i>
4 Rear RH Side Fairing	1	185.00 <i>scr</i>
5 Tail Light	1	130 150.00 <i>scr</i>

Sub-Total 545 1,195.00  
Less 10% 10% 119.50  
Sub-Total 490.50 1,075.50

## Nett items

- 1 Rear box rack
- 2 Rear box - Kappa
- 3 Rear number plate
- 4 Towing fee
- 5 To check rear wheel & swing arm, alignment
- 6 Remove & replace necessary parts, exhaust pipe, align & etc
- 7 Supply body decal sticker

180.00 *X m*  
350.00 *150 scr*  
15.00 *mt*  
40.00  
80.00 *40*  
250.00 *150*  
120.00 *60*

Sub-Total 1,035.00  
Nett Total 2,110.50

**LKK Auto Consultants** hence notify  
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey

NB: This estimate was made from a visual inspection  
only. any other damage parts or labour require when  
repair commences, we will advise you and submit  
supplementary item to you accordingly. surveyed and  
is subject to final approval from Insurance Company

Kindly revert upon completion. Thank you.

Signature: \_\_\_\_\_  
Date: \_\_\_\_\_

SG 98 MOTOR PTE LTD

Rasul  
Hp 90010068  
3 days  
4/3  
16/03/18 @ 1400

490.50  
455.00  
945.50  
20%  
756.40  
43.750  
3 days

### ...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	12 Mar 2018		15 Mar 2018 14:13 <a href="#">Edit Adj Rpt</a>	<b>S\$750.00</b> <a href="#">Edit Estimates</a>	<b>S\$750.00</b> <a href="#">View Rpt</a>		<b>Pending for Survey Report</b> <a href="#">Cancel Case</a>

Main	Reference	Claim Details	Documents	Show All					
<b>CLAIM SUBFOLDER DETAILS</b> <span style="float: right;">[Created by insurer]</span>									
Insured: <b>MOHAMMAD AZREERUDIN BIN AMIRRUDIN</b> , ID: S9419376A, Tel: +6596393524, Email: NOEMAIL									
Main Claimant: <b>MOHAMED RAMDAN BIN JAMALUDIN</b> , ID: S9404335B									
Vehicle Reg. No.: <b>FBL1877T</b>		Date of Loss: 07/03/2018 23:00 - :59 [35 Months and 19 Days From LTA Reg Date (Man Yr)]							
Claim Type: <b>TP / MSC/V/18-000391</b>		Policy/Cover Note No.: MSD/VMT/18-989961-WTT (Third Party Only) Coverage: 12/03/2017 - 11/03/2018							
Vehicle Reg. No. (Insured): <b>FBF1550S</b>		Policy No. (Claimant):							
		Excess:							
Repairer: <b>Sg 98 Motor Pte Ltd (HQ)</b> BLK 4001 ANG MO KIO INDUSTRIAL PARK 1 #01-21, 569622 Ang Mo Kio - Tel: 64524898									
Handling Insurer: <b>MSIG Insurance (Singapore) Pte. Ltd. (HQ)</b> - Tel: +65 6827 7888 ... [Handled by <b>Elaine Ngu Siau Mei</b> - 6594 2540]									
Adjuster: <b>LKK Auto Consultants Pte Ltd (HQ)</b> - Tel: 6256-3561 ... [Handled by <b>MOHD RASUL</b> ] ... [Imm.Advice due 16/03/2018]									
Driver/Custodian (Insured): <b>MOHAMMAD AZREERUDIN BIN AMIRRUDIN</b> (23 / Male), NRIC: S9419376A, Tel: +6596393524									
Adj Asg. Remarks: Please arrange LKK Rasul for the pre repair inspection.									
<b>ASSOCIATED MAIL RECEIVED</b> <span style="float: right;"><a href="#">View All</a> <a href="#">Compose Case Mail</a></span>									
There are no mail for this case.									
<b>ALL ASSOCIATED TASKS</b> <span style="float: right;"><a href="#">View All</a> <a href="#">Search Tasks</a> <a href="#">Create New Task</a> <a href="#">Complete</a></span>									
<b>Due Date</b>	<b>Priority</b>	<b>Type</b>	<b>Task Group</b>	<b>Subject</b>	<b>Handler</b>	<b>Assigned By</b>	<b>Completed On</b>	<b>Created On</b>	<b>Done?</b>
No results.									

## Claim Documents

**\*FBL1877T (MSC/V/18-000391)**  
**[FBF1550S]**  
**TP**  
**MOHAMED RAMDAN BIN JAMALUDIN**  
**Mar 7 2018 11:00PM**  
**[MOHAMMAD AZREERUDIN BIN AMIRRUDIN]**  
**Sg 98 Motor Pte Ltd**


[Upload Documents](#)
[Upload Photos](#)
[Compose New Letter](#)

**View** View in Browser

Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
1	15/03/18 14:13	<b>Accident Statement</b> <small>From: SC - Reg. No: FBF1550S, Claimant: MOHAMMAD AZREERUDIN BIN AMIRRUDIN</small>	Load HTM	

Photos/Images			3 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	11/09/18 08:58	General View	Load JPG	<input checked="" type="checkbox"/>
2	11/09/18 08:58	General View	Load JPG	<input checked="" type="checkbox"/>
3	11/09/18 08:58	General View	Load JPG	<input checked="" type="checkbox"/>
4	11/09/18 08:58	General View	Load JPG	<input checked="" type="checkbox"/>
5	11/09/18 08:58	General View	Load JPG	<input checked="" type="checkbox"/>
6	11/09/18 08:58	General View	Load JPG	<input checked="" type="checkbox"/>
7	11/09/18 08:58	General View	Load JPG	<input checked="" type="checkbox"/>
8	11/09/18 08:58	General View	Load JPG	<input checked="" type="checkbox"/>
9	11/09/18 08:58	General View	Load JPG	<input checked="" type="checkbox"/>
10	11/09/18 08:58	General View	Load JPG	<input checked="" type="checkbox"/>
11	11/09/18 08:58	General View	Load JPG	<input checked="" type="checkbox"/>
12	11/09/18 08:58	General View	Load JPG	<input checked="" type="checkbox"/>
13	11/09/18 08:58	General View	Load JPG	<input checked="" type="checkbox"/>
14	11/09/18 08:58	General View	Load JPG	<input checked="" type="checkbox"/>
15	11/09/18 08:58	General View	Load JPG	<input checked="" type="checkbox"/>
16	11/09/18 08:58	General View	Load JPG	<input checked="" type="checkbox"/>
17	11/09/18 08:58	General View	Load JPG	<input checked="" type="checkbox"/>
18	11/09/18 08:58	General View	Load JPG	<input checked="" type="checkbox"/>
19	11/09/18 08:58	General View	Load JPG	<input checked="" type="checkbox"/>
20	11/09/18 08:58	General View	Load JPG	<input checked="" type="checkbox"/>
21	11/09/18 08:58	General View	Load JPG	<input checked="" type="checkbox"/>
22	11/09/18 08:58	General View	Load JPG	<input checked="" type="checkbox"/>
23	11/09/18 08:58	General View	Load JPG	<input checked="" type="checkbox"/>
24	11/09/18 08:58	General View	Load JPG	<input checked="" type="checkbox"/>
25	11/09/18 08:58	General View	Load JPG	<input checked="" type="checkbox"/>
26	11/09/18 08:58	General View	Load JPG	<input checked="" type="checkbox"/>
27	11/09/18 08:58	General View	Load JPG	<input checked="" type="checkbox"/>
28	11/09/18 08:58	General View	Load JPG	<input checked="" type="checkbox"/>
29	11/09/18 08:58	General View	Load JPG	<input checked="" type="checkbox"/>
30	11/09/18 08:58	General View	Load JPG	<input checked="" type="checkbox"/>
31	11/09/18 08:58	General View	Load JPG	<input checked="" type="checkbox"/>
32	11/09/18 08:58	General View	Load JPG	<input checked="" type="checkbox"/>
33	11/09/18 08:58	General View	Load JPG	<input checked="" type="checkbox"/>

Assessment Reports				1 per page	✓
No	Finalized On		MSIG Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
Documentation				1 per page	✓
No	Finalized On		MSIG Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
1	15/03/18 14:13		TPD FBL1877T GIA REPORT	 Load PDF	

## Documents Checklist

DOCUMENTS CHECKLIST				Reset	Save	Print
There are no document checklists configured.						

<b>Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)</b>	
<div></div>	
<b>Show Remarks To:</b> <input type="checkbox"/> Handling Insurer	
Note: Remarks are private unless you show it to other parties.	

# LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/MSG18004961/R1RBE2

Date: 11/09/2018

### REFERENCE

Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd.	Policy No:	MSD/VMT/18-989961-WTT
Claimant Vehicle No :	FBL1877T	Insured Vehicle No :	FBF1550S
Date of Loss:	07/03/2018	Nature of Claim:	TP
		Claim No:	MSC/V/18-000391

### DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	<b>FBL1877T</b>	Engine No:	50C734658
Make & Model:	YAMAHA JUPITER MX, 134cc HC	Chassis No:	MH350C006EK734877
Reg. Date:	16/03/2015 (Man. Year: 2014)	Odometer:	45595 km
Colour:	Multi-colour		
Engine Capacity:	134 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	<b>Market Value/New Car Price</b>		

### CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

### CONDITION OF TYRES

Front Tyre Size:	70/90-17	Rear Tyre Size:	110/70-17
Front Left Side:	Maxxis 3 mm	Rear Left Side:	Maxxis 3 mm
Front Right Side:	0 mm	Rear Right Side:	0 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	1,620.50	655.50	965.00	59.55
Miscellaneous Items	0.00	0.00	0.00	
Labour	490.00	290.00	200.00	40.82
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (S\$)</b>	<b>2,110.50</b>	<b>945.50</b>	<b>1,165.00</b>	<b>55.20</b>
<b>Approved Total (Overridden) (S\$)</b>		<b>750.00</b>		
<b>Nett Amount (S\$)</b>	<b>2,110.50</b>	<b>750.00</b>	<b>1,360.50</b>	<b>64.46</b>

### INSPECTION

Date of Assignment:	15/03/2018	
Date Inspected:	16/03/2018 Inspected At:	Sg 98 Motor Pte Ltd (HQ) BLK 4001 ANG MO KIO INDUSTRIAL PARK 1 #01-21 Singapore 569622
Estimated Period of Repair:	3.0 days	

**Adjuster:** MOHD RASUL

**Manager:** Janice Lee Si Hua

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*



## REPAIR DETAILS

Reference		
Part Source:	(Last Synchronised: 11 Sep 2018)	
Parts:	N/A	YAMAHA JUPITER MX 134cc HC (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for FBL1877T)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

## Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR MUDGUARD	Scratched	180.00 FL	*150.00 FL
2	1		*REAR EXHAUST PIPE	Repair	560.00 FL	*- FL
3	1		*REAR FOOTREST BRACKET	Cracked	120.00 FL	*80.00 FL
4	1		*REAR RH SIDE FAIRING	Scratched	185.00 FL	*185.00 FL
5	1		*TAIL LIGHT	Scratched	150.00 FL	*130.00 FL
6	1		*REAR BOX RACK	Not Necessary	180.00 FS	*- FS
7	1		*REAR BOX - KAPPA	Scratched	350.00 FS	*150.00 FS
8	1		*REAR NUMBER PLATE	Bent	15.00 FS	*15.00 FS
					<b>Sub Total (S\$)</b>	<b>1,740.00</b>
					<b>- List Item Discount on L Items 10.00/10.00% (S\$)</b>	<b>119.50</b>
					<b>Total Parts (S\$)</b>	<b>1,620.50</b>
						<b>655.50</b>

F=Franchise part. S=SpcNett. L=ListItemDisc.

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	TOWING FEE	New	40.00	40.00
2	TO CHECK REAR WHEEL & SWING ARM, ALIGNMENT	New	80.00	40.00
3	REMOVE & REPLACE NECESSARY PARTS, EXHAUST PIPE, ALIGN & ETC	New	250.00	150.00
4	SUPPLY BODY DECAL STICKER	New	120.00	60.00
Gross Labour Cost (\$\$)			<b>490.00</b>	<b>290.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >