Surveyor Tanjh 'Virtual'

REF: ASM (AXA) 4964 | Rear | - (e)

ASSIGNMENT

From: Date: 16.03.2018

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: SLT 7523P

at Workshop m/s Autofrance

of 305 Alexandra Rd

Insured:

Policy No.

Claims No.

Sum Insured: Excess:

(Client's Record)

Make of Veh: Guo Xiang

12.30pm - 3pm

(Policy Condition) Do Not Finalize

Remark: The veh had commenced its repair at the time of inspection. Confirmed

N/S	O/S

Bal. or Market Value:

IDAC Accident Rport: Consistent? : Yes or No

GIA / PR Seen: Consistent? : Yes or No

Est. Repairs: days Res.: Yes or No

Lum Sum: % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: Person Contacted:

Veh No: SLT 7523P Yr Regn: 2017 / New

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover / Truck / Trailer or

Make: Peugeot 308 c.c 1199

Colour Grey A/C: Insured / Std / NI / NA

Sp.Reading 4172 T/Radio: Insured / Std / NI / NA

Eng/No:

C/No: VF3LPHNYWHS153323

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi : Nil / S/Rim / STD A/Rim or

Tyre Size: F: 225/45R17

R: 7 1

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI / TOYO / YOKO or

Front		Rear	
R/Bal.	6 mm	R/Bal.	6 mm
L/Bal.	6 mm	L/Bal.	6 mm
D.O.A.		D.O.I.	16/5/18 @ 3pm

Survey held at Autofrance.

Des. of Damages : Frt / Rear / O/S / N/S / U/C / Rooftop or Rear o/s.

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction

Date/Time. File Pass to? ☐ : Preli. Report

1) ☐ : Final Report

Date/Time. File Return to?

2)

Report Format :

Lump Sum / I.B.I: ($)

Days Of Repair:

Resurvey No. of Trip:

Add Fee: ☐ : Site Insp ($) __S + RS __SI

☐ : Interview ($) Photos

☐ : Tech. Invs ($) Others

☐ : Weekend ($)

Survey Fee:

Transportation:

TOTAL

SKT 2217L
Shl auto