

ASS. REC. BY:

REF: CS3/CTI18004995/Sd307 Special Instruction:

Survivor:
Menmen

Sebastian

ASSIGNMENT (Office)

From (Person):

Sharon Han

of

CTI

Date/Time: 16/3/18 @ 9:50am

Estimated Cost:

Bill to:

OD/TP/WS/TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

FBJ 5722R

Insured:

SJQ 5209A

at Workshop m/s

Chek Kong Motor

Tel:

6769 8793

of

Blk 1, Woodlands Rd, Yew Tee Ind

Policy No:

DMPCSN3080301702

Claim No:

SNM18D01353C02

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A. 12/03/2018

CA / REV / REP. / REV 24 HRS

lwp

H.O.D. Endorsement:

Date/Time:

10:52am @ 16/3/18

Person Contacted:

Ms. Tan

Vehicle IN/OUT

Date/Time

Action/Instruction (X) Estimate

FBJ 5722R-X

SJQ 5209A-CS/CTI17006862/Gvh 3e2

D.O.A: 4/4/17

REF:

Simulator

ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value:

IDAG Accident Report:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

days

Res.: Yes or No

Turn Sum:

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Date / Time | Action / Instruction

16/3/18 : No Estimate

* Repair Estimate : \$5,800 - \$7,500

RECEIVED 21 JUN 2018

* 4 days

18/6/2018

Date/Time, File Pass to?

☐

Prel. Report

Date/Time, File Return to?

2)

Report Format :

Lump Sum / I.B.I. (\$

PRE

Days Of Repair:

4

Resurvey No. of Trip:

1

Survey Fee:

Transportation:

S + RS. SI

Photos

Copies

TOTAL

Add Fee:

☐

Site Insp (\$

☐

Interview (\$

☐

Tech. Insp (\$

☐

Weekend (\$

Veh No:

FB35722R

Yr Rog: 24/7/2014

Type: M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Honda CB400

cc 399

Colour

Black

A/C: Insured / Std / NI / NA

Sp. Reading

No Display

T/Radio: Insured / Std / NI / NA

Eng/No:

C/No:

NC 421601011

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modl: NI / S/Rim / STD A/Rim or

Tyre Size:

F: 120/60ZR17

R: 160/60ZR17

BS / DUN / EXNOVA / GY / FS / LZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Metzeleer

Front

Rear

R/Bal.

6

mm

R/Bal.

6

L/Bal.

6

mm

L/Bal.

6

D.O.A.

12/3/16

D.O.I.

16/3/18

Survey held at

Chet Kong Motor 3876

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

CHINA TAIPING INSURANCE (S) PTE LTD

Ref : CS3/CTI18004995/Sd3

3 ANSON ROAD #16-00
SPRINGLEAF TOWERS SINGAPORE 079909

Date : 16-03-2018



Code : CTI

1. Policy Particulars :- (THIRD PARTY CLAIM)

Insured Veh.	SJQ 5209A	Veh. Inspected	FBJ 5722R
Policy No.	DMPCSN3080301702	Coverage (\$)	0.00
Claim No.	SNM18D01353C02	Excess (\$)	0.00
Assign From	MERIMEN (SHARON HAN)	Assign Date	16/03/2018

2. Vehicle Particulars & Condition

Make & Model	c.c	0
Engine No.	HIDDEN	Year of Reg.
Chassis No.		Colour
Odometer	-	Steering
Brakes		Modification
General		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm

4. Description of Damages

--

5. General Information

Accident Date	12/03/2018	Inspection Date	16/03/2018
Survey held at	CHEK KONG MOTOR 387B YEW YEE INDUSTRIAL ESTATE WOODLANDS ROAD SINGAPORE 677948		

5a. Remarks

A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.
--

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	15 Mar 2018		16 Mar 2018 09:50 Assign				New Assignment Cancel Case

Main

Reference

Claim Details

Documents

[Show All](#)

CLAIM SUBFOLDER DETAILS

[Created by insurer]

Insured:	WENG WANYI, ID: S8411453		
Main Claimant:	MOHD RAFEE B M MAKSUDI, ID: S1724106J		
Vehicle Reg. No.:	FBJ5722R	Date of Loss:	12/03/2018 18:00 - :59
Claim Type:	TP / SNM18D01353C02	Policy/Cover Note No.:	DMPCSN3080301702 (Comprehensive)
Vehicle Reg. No. (Insured):	SJQ5209A	Policy No. (Claimant):	5091599151
		Excess:	\$0.00
Repairer:	Chek Kong Motor Pte Ltd (HQ) BLK 1 387B WOODLANDS ROAD, YEW TEE INDUSTIRL ESTATE, 677948 Woodlands - Tel:		
Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Sharon Han - 63896]		
Claimant's Insurer:	NTUC Income Insurance Co-operative Ltd (HQ) - Tel:		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Final Rpt due 27/03/2018]		
Driver/Custodian (Insured):	DANIEL ALEXANDER MEZZANOTTE (34 / Male), NRIC: S8381812C, Tel: +6581893701		
Adj Asg. Remarks:	NO EST, CASE W/O SJE.		

ASSOCIATED MAIL RECEIVED

[View All](#)[Compose Case Mail](#)

There are no mail for this case.

ALL ASSOCIATED TASKS

[View All](#)[Search Tasks](#)[Create New Task](#)[Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Lucas Lee

From: Mail office <mail@gohjpwong.com>
Sent: Friday, 16 March, 2018 9:18 AM
To: Lucas Lee
Cc: Adeline Chng
Subject: Re: PRS FOR FBJ5722R (CTI REF: SNM18D01353C02) (YrRef: GTW.ACC.3032.18.WK)

Dear Sir/Mdm

Our client's motorcycle FBJ 5722R is now at Chek Kong Motor Pte Ltd located at Block 1, 387B Woodlands Road, Yew Tee Industrial Estate Singapore 677948 (Tel: 6769 8793 - Mr Lionel).

Kindly proceed to conduct the pre-repair inspection forthwith and let us know once the pre-repair inspections has been conducted, failing which we shall assume that the pre-repair inspection is conducted within the next 2 working days.

Lee Wee Ka
for and on behalf of Goh Teck Wee
GOH JP & WONG LLC
Advocates & Solicitors
Commissioner for Oaths
133 New Bridge Road #16-09
Chinatown Point
Singapore 059413
Tel : 6538 5868
Fax: 6538 4898

We do not accept service of documents by facsimile or email. Our business hours are from Mondays to Fridays from 9 am to 5 pm and we are closed on Saturday, Sundays and Public Holidays. UEN/GST Regn No: 201406078M

-- Email Disclaimer --

This message contains information that may be privileged and confidential. If you are not the intended recipient, you are hereby notified that any dissemination, distribution or copying of this message is strictly prohibited. If you have received this message in error, please delete it from your system and notify the sender. You are advised to carry out your own checks on this message for computer viruses and other defects. Please note that we disclaim liability for any loss or damage caused by computer viruses and/or other defects.

On Fri, Mar 16, 2018 at 9:01 AM, Lucas Lee <lucas.lee@sg.cntaiping.com> wrote:

Dear Sirs,

Kindly refer to the above attachment.

Case Handler: Adeline Chng

Regards,

Lucas Lee

Claims Department (Motor)

China Taiping Insurance (Singapore) Pte. Ltd.

3, Anson Road, #16-00

Springleaf Tower,

Singapore 079909

Co. Reg. No. 200208384E

DID: 6389 6181

Fax: 6224 7175

Email: claimsdept@sg.cntaiping.com

Email: lucas.lee@sg.cntaiping.com

Website: www.sg.cntaiping.com

From: Mail office [mailto:mail@gohjpwong.com]

Sent: Thursday, 15 March, 2018 5:17 PM

To: Lucas Lee

Cc: Adeline Chng

Subject: Re: PRS FOR FBJ5722R (CTI REF: SNM18D01353C02) (YrRef: GTW.ACC.3032.18.WK)

Dear Sir/Mdm

We are not agreeable to your proposed motor surveyors.

Our list of proposed Single Joint Expert ("SJE") as follows:-

1. Teo Liak Hoo of L H Teo Appraisal Services
2. Jayson Liaw Leong San of Pro-Option Services
3. Seah Kwang Boon of Absolute Appraisal Services
4. Oh Han Cheong of Oh Appraisal

5. Bok Jee Tan of Prudent Adjustors Services
6. Fong Kok Heng Stanley of Automax Survey
7. Sebastian Lim Yong Tian of Constant Appraiser Services
8. Lek Boon Hwee of Auto Performance Appraisal
9. Louis S C Ng Cae Amimi of Prestige Appraiser Services
10. Richard Wong Ah Kow of R W Automotive Appraiser Services

Kindly let us hear from you soonest.

Lee Wee Ka
for and on behalf of Goh Teck Wee
GOH JP & WONG LLC
Advocates & Solicitors
Commissioner for Oaths
133 New Bridge Road #16-09
Chinatown Point
Singapore 059413
Tel : 6538 5868
Fax: 6538 4898

We do not accept service of documents by facsimile or email. Our business hours are from Mondays to Fridays from 9 am to 5 pm and we are closed on Saturday, Sundays and Public Holidays. UEN/GST Regn No: 201406078M

-- Email Disclaimer --

This message contains information that may be privileged and confidential. If you are not the intended recipient, you are hereby notified that any dissemination, distribution or copying of this message is strictly prohibited. If you have received this message in error, please delete it from your system and notify the sender.

You are advised to carry out your own checks on this message for computer viruses and other defects. Please note that we disclaim liability for any loss or damage caused by computer viruses and/or other defects.

On Thu, Mar 15, 2018 at 5:09 PM, Lucas Lee <lucas.lee@sg.cntaiping.com> wrote:

Without Prejudice

Dear Sirs

We intend to conduct a pre-repair survey of the damage to your client's vehicle jointly with your client/your motor workshop. We propose to use one of the following motor surveyors to conduct the joint pre-repair survey as a single joint expert.

TAY BENG HEE
DERECK OH SIONG WEE
SEE CHEW SENG
MOHD FADHILAH BIN OSMAN
XING QUO QIANG
KENNETH KONG
SIMON HO
CHUA WEIJIE

MARCUS CHUA
HENRY NG

Please let us know within two(2) working days whether you agree to the appointment of any of these motor surveyors as a single joint expert.

You may select one of the listed motor surveyors and we will bear the cost of the pre-repair survey carried out by the single joint expert.

Case Handler: Adeline Chng

Regards,

Lucas Lee

Claims Department (Motor)

China Taiping Insurance (Singapore) Pte. Ltd.

3, Anson Road, #16-00

Springleaf Tower,

Singapore 079909

Co. Reg. No. 200208384E

DID: 6389 6181

Fax: 6224 7175

Email: claimsdept@sg.cntaiping.com

Email: lucas.lee@sg.cntaiping.com

Website: www.sg.cntaiping.com

This email has been scanned by the Symantec Email Security.cloud service.

For more information please visit <http://www.symanteccloud.com>

This email has been scanned by the Symantec Email Security.cloud service.
For more information please visit <http://www.symanteccloud.com>

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	4106J
Vehicle Details	
Vehicle No.:	FBJ5722R
Vehicle to be Exported:	No
Intended De-registration Date:	19 Mar 2018
Vehicle Make:	HONDA
Vehicle Model:	CB400 SUPER FOUR MANUAL
Primary Colour:	Black
Manufacturing Year:	2014
Engine No.:	NC42E1201010
Chassis No.:	NC421601011
Maximum Power Output:	-
Open Market Value:	\$7,800.00
Original Registration Date:	24 Jul 2014
First Registration Date:	24 Jul 2014
Transfer Count:	3
Actual ARF Paid:	\$1,170.00
Intended PARF Rebate Details	
PARF Eligibility:	No
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00
Intended COE Rebate Details	
COE Expiry Date:	23 Jul 2024
COE Category:	D - Motorcycle
COE Period(Years):	10
QP Paid:	\$4,252.00
COE Rebate Amount:	\$2,697.00
Total Rebate Amount:	\$2,697.00

The information contained herein is correct as at 19 Mar 2018

OK

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the Insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the Insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	13/03/2018 13:54
Date Of Accident	12/03/2018 18:15
Exact Location Of Accident	AYE TOWARDS CTE (LP : 232)
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	FBJ5722R
Insured/Policyholder	
Name Of Registered Owner	MOHD RAFEE B M MAKSUDI
NRIC No	S1724106J
Email Address	NOEMAIL
Mobile Phone No	(LOCAL) +65-92966515
Alternative Phone No	OFFICE-92966515
Vehicle Particulars	
Manufacturer	HONDA
Model	CB400-399CC
Exact Purpose for which vehicle was being used at time of accident	
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	MOTORCYCLE
Insurance Company	
Name of Insurance Company	NTUC INCOME INSURANCE CO-OPERATIVE LTD
Type Of Coverage	THIRD PARTY
Fleet Policy	NO
Policy Number	5091599151
Cover Note Number	
Driver	
Name of Driver	PUTRA MOHAMMAD DANISH BIN MOHD RAFEE
NRIC No	S9636342G
Date Of Birth	14/10/1996
Occupation	OUTDOOR
Date Of Driving Pass	27/04/2016
Driving Experience	1 YEAR AND 10 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-92966515
Fax Number	
Contact Number	OFFICE-92966515
Email Address	NOEMAIL

Address	704 CHOA CHU KANG STREET 53 #11-82
Postcode	S680704
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	CHILDREN
Vehicle Registration Number of Driver's Own Vehicle	-
Insurance Company of Driver's Own Vehicle	-

General Information of the Accident

Type Of Accident	SIDE SWIPE
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles involved in the accident	
Was any body injured in the Accident?	YES
Was any injured conveyed to hospital by ambulance?	YES
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	2
Passenger 1	NAME: : - GENDER: : FEMALE

Details of Police Action

Was the accident reported to the police?	YES
If Yes, Please state which Police Station	
Police Station Name	UBI AVE 3
Police Station Address	ROAD: 10 UBI AVE 3 , POSTCODE: 408865 , COUNTRY: SINGAPORE
Police Station Contact	TEL NO: - FAX NO:
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

PLEASE SEE ATTACHED POLICE REPORT. ATTENDED BY : SUSAN

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	YES
Remarks/ Reasons:	SENT TO INSURANCE
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SJQ5209A
Vehicle Make/Model/Colour	NISSAN LATIO
Details Of Properties	
Vehicle Category	PRIVATE HIRE
Name of Driver	
NRIC/Passport Number	
Contact Number	
Address	

Postcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

DETAILS OF INJURED PERSON 1

Name NUR AMALINA BINTE JAMALUDIN

Approximate Age

Injuries Sustain

REFER TO POLICE REPORT

Injured person in which vehicle?

FBJ5722R

Were seat belts worn?

Was this injured conveyed to hospital by ambulance?

YES

Address

Postcode

DETAILS OF INJURED PERSON 2

Name PUTRA MOHAMMAD DANISH BIN MOHD RAFEE

Approximate Age

Injuries Sustain

REFER TO POLICE REPORT

Injured person in which vehicle?

FBJ5722R

Were seat belts worn?

Was this injured conveyed to hospital by ambulance?

YES

Address

Postcode

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the Insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the Insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims. (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.

IDAC BUKIT BATOK (VAC)
 511 Bukit Batok Street 23
 Singapore 659545
 Tel: 6560 3312 Fax: 6569 0722
 Email: vacbb@singnet.com.sg

Policyholder's Signature
 Date & Time:


Driver's Signature
 (If driver is not the policyholder)
 Date & Time:

Reporting Centre Personnel's Signature
 Name:
 NRIC/FIN No.:

Sketch Plan #2 Pg. 1

SKETCH PLAN

15.



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

Refer to police Report

IDAO BUKIT BATOK (VAC)
511 Bukit Batok Street 23
Singapore 659545
Tel: 6560 3312 Fax: 6569 0722
Email: vacbb@singnet.com.sg

DECLARATION

I/We declare the foregoing particulars are true in every respect.



Policyholder's Signature
Date & Time:



Driver's Signature
(If driver is not the policyholder)
Date & Time:

13 MAR 2010

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	15 Mar 2018		16 Mar 2018 09:50 Edit Adj Rpt	S\$0.00 Edit Estimates	S\$0.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by insurer]									
Insured:	WENG WANYI , ID: S8411453								
Main Claimant:	MOHD RAFEE B M MAKSUDI , ID: S1724106J								
Vehicle Reg. No.:	FBJ5722R	Date of Loss:	12/03/2018 18:00 - :59 [43 Months and 16 Days From LTA Reg Date (Man Yr)]						
Claim Type:	TP / SNM18D01353C02	Policy/Cover Note No.:	DMPCSN3080301702 (Comprehensive)						
Vehicle Reg. No. (Insured):	SJQ5209A	Policy No. (Claimant):	5091599151						
		Excess:	S\$0.00						
Repairer:	Chek Kong Motor Pte Ltd (HQ) BLK 1 387B WOODLANDS ROAD, YEW TEE INDUSTIRL ESTATE, 677948 Woodlands - Tel:								
Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Sharon Han - 63896]								
Claimant's Insurer:	NTUC Income Insurance Co-operative Ltd (HQ) - Tel:								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by Sebastian Yeang Wai Keen] ... [Final Rpt due 27/03/2018]								
Driver/Custodian (Insured):	DANIEL ALEXANDER MEZZANOTTE (34 / Male), NRIC: S8381812C, Tel: +6581893701								
Adj Asg. Remarks:	NO EST, CASE W/O SJE.								
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
There are no mail for this case.									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*FBJ5722R (SNM18D01353C02)
[SJQ5209A]
TP
MOHD RAFEE B M MAKSUDI
Mar 12 2018 6:00PM
[WENG WANYI]
Chek Kong Motor Pte Ltd

[Upload Documents](#) |
 [Upload Photos](#) |
 [Compose New Letter](#)

View View in Browser

Assessment Reports				1 per page	<input checked="" type="checkbox"/>
No	Finalized On	VAC (Bukit Batok)		Thumbnail	Print
1	13/03/18 14:12	Accident Statement		Load HTM	

Photos/Images				3 per page	<input checked="" type="checkbox"/>
No	Finalized On	VAC (Bukit Batok)		Thumbnail	Print
1	13/03/18 14:12	Accident Photo [Linked Accident Report Documents]		Load JPG	<input checked="" type="checkbox"/>
2	13/03/18 14:12	Accident Photo [Linked Accident Report Documents]		Load JPG	<input checked="" type="checkbox"/>
3	13/03/18 14:12	Accident Photo [Linked Accident Report Documents]		Load JPG	<input checked="" type="checkbox"/>
4	13/03/18 14:12	Accident Photo [Linked Accident Report Documents]		Load JPG	<input checked="" type="checkbox"/>
5	13/03/18 14:12	Accident Photo [Linked Accident Report Documents]		Load JPG	<input checked="" type="checkbox"/>
6	13/03/18 14:12	Accident Photo [Linked Accident Report Documents]		Load JPG	<input checked="" type="checkbox"/>
7	13/03/18 14:12	Accident Photo [Linked Accident Report Documents]		Load JPG	<input checked="" type="checkbox"/>

No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
1	21/06/18 14:43	General View		Load PDF	
2	21/06/18 14:43	Photo After Spray		Load PDF	

Documentation				1 per page	<input checked="" type="checkbox"/>
No	Finalized On	China Taiping Insurance (Singapore) Pte. Ltd. (HQ)		Thumbnail	Print
1	16/03/18 09:49	PRS		Load PDF	
2	16/03/18 09:49	OI GIA REPORT		Load PDF	














No	Finalized On	VAC (Bukit Batok)		Thumbnail	Print
1	13/03/18 14:05	Sketch Plan [Linked Accident Report Documents]		Load TIF	
2	13/03/18 14:05	Sketch Plan #2 [Linked Accident Report Documents]		Load TIF	
3	13/03/18 14:05	PR [Linked Accident Report Documents]		Load TIF	
4	13/03/18 14:05	PR [Linked Accident Report Documents]		Load TIF	
5	13/03/18 14:05	PR [Linked Accident Report Documents]		Load TIF	
6	13/03/18 14:05	PR [Linked Accident Report Documents]		Load TIF	

Linked Accident Report Documents

View View in Browser

Assessment Reports				1 per page	<input checked="" type="checkbox"/>
No	Finalized On	VAC (Bukit Batok)		Thumbnail	Print
1	13/03/18 14:12	Accident Statement		Load HTM	

Photos/Images				3 per page	<input checked="" type="checkbox"/>
---------------	--	--	--	------------	-------------------------------------

Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	VAC (Bukit Batok)	Thumbnail	Print
No	Finalized On	VAC (Bukit Batok)	Thumbnail	Print
1	13/03/18 14:12	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
2	13/03/18 14:12	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
3	13/03/18 14:12	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
4	13/03/18 14:12	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
5	13/03/18 14:12	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
6	13/03/18 14:12	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
7	13/03/18 14:12	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
Documentation			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	VAC (Bukit Batok)	Thumbnail	Print
1	13/03/18 14:05	Sketch Plan	 Load TIF	
2	13/03/18 14:05	Sketch Plan #2	 Load TIF	
3	13/03/18 14:05	PR	 Load TIF	
4	13/03/18 14:05	PR	 Load TIF	
5	13/03/18 14:05	PR	 Load TIF	
6	13/03/18 14:05	PR	 Load TIF	

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ) <div style="border: 1px solid black; height: 40px; margin-top: 5px;"></div>			
Show Remarks To: <input type="checkbox"/> Handling Insurer <small>Note: Remarks are private unless you show it to other parties.</small>			

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS3/CTI18004995/SD3E2

Date: 27/06/2018

REFERENCE

Handling Insurer: China Taiping Insurance
(Singapore) Pte. Ltd.

Policy No: DMPCSN3080301702

Claimant Vehicle
No: FBJ5722RInsured Vehicle
No: SJQ5209A

Date of Loss: 12/03/2018

Nature of Claim: TP

Claim
No: SNM18D01353C02

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: FBJ5722R

Make & Model: HONDA CB400, 399cc

Reg. Date: 24/07/2014 (Man. Year: 2014)

Colour: Black

Engine Capacity: 399 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): Market Value/New Car Price

Engine No: NC42E1201010

Chassis No: NC421601011

Odometer: 0 km

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 120/60Z R17

Rear Tyre Size: 160/60Z R17

Front Left Side: Metzeler 6 mm

Rear Left Side: Metzeler 6 mm

Front Right Side: 0 mm

Rear Right Side: 0 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Nett Amount (S\$)	0.00	0.00	0.00	

INSPECTION

Date of Assignment: 16/03/2018

Date Inspected: 16/03/2018 Inspected At:

Chek Kong Motor Pte Ltd (HQ)
BLK 1 387B WOODLANDS ROAD, YEW
TEE INDUSTIRL ESTATE
Singapore 677948

Estimated Period of Repair: 4.0 days

Adjuster: Sebastian Yeang Wai Keen

Manager: Nivitha Govindasamy

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

- A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
- B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION.
THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE.
- C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.

THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$5,800.00 -\$7,500.00

REPAIR DETAILS

Reference

Part Source: (Last Synchronised: 27 Jun 2018)

Parts: N/A HONDA CB400 399cc (Model not available in database)

Labour: Repairer's (Price-denominated Standard List)

Print Code: (Unsubmitted, no print-code for FBJ5722R)

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

There are no new parts selected.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.

< END OF ESTIMATES >