

ASS. REC. BY:

REF:

CS/MSG/1800-1999/4nd3

Special Instruction:

Surveyor:

Marcus

ASSIGNMENT (Office)

From (Person):

Jasmine Lok

of

MSG

Date/Time:

16/3/18 @ 9:06am

Estimated Cost:

Bill to:

OD ~~TP~~ WS/TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SLS 7578L

Insured:

SKQ 5254G

at Workshop m/s

Borneo Motor (Incheupe)

Tel:

6631 1687

of

17 Ubi Road 4

Policy No:

A80449646 AT2

Claim No:

552055

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A.

8/3/2018

CA / REV / REP. / REV 24 HRS

lwp)

19/03/18

H.O.D. Endorsement:

Date/Time:

9:32am @ 16/2/18

Person Contacted:

Sam

Vehicle IN OUT

Date/Time

Action/Instruction

(✓)

Estimate

SLS 7578L - x

SKQ 5254G - x

20/3/18

Send preli revised by merimen

REF: MS/G

## ASSIGNMENT

Front: \_\_\_\_\_ Date: 19/3/18

Estimated Cost: \_\_\_\_\_

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: SLS 7578 L

at Workshop m/s Borneo Motor (Incheepe)

of 17 ubi Road 4

Insured: \_\_\_\_\_

Policy No: \_\_\_\_\_

Claims No: \_\_\_\_\_

Sum Insured: \_\_\_\_\_ Excess: \_\_\_\_\_

(Client's Record)

Make of Veh: Sam

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

|     |     |
|-----|-----|
|     |     |
| N/S | O/S |
|     |     |

Bal. or Market Value: \_\_\_\_\_

IDAC Accident Rpt: \_\_\_\_\_ Consistent? : Yes or No

GIA / PR Seen: \_\_\_\_\_ Consistent? : Yes or No

Est. Repairs: \_\_\_\_\_ days Res: Yes or No

Lum Sum: 131 % 3 Val: Yes or No

CA / REV / REP. / 24 HRS <sup>1 up</sup>

Date: \_\_\_\_\_ Person Contacted: \_\_\_\_\_ Vehicle: IN / OUT

Veh No: SLS 7578 L Yr Regn: 10 / 17

Type: ☒ M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or CA /

Make: Toyota corolla Altis G.C. 15-98

Colour: Grey A/C: Insured / Std / NI / NA

Sp. Reading: 6978 T/Radio: Insured / Std / NI / NA

Eng/No: \_\_\_\_\_

C/No: MR053RE H6045-71654

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 195 / 65 R15

R: \_\_\_\_\_

BS / ☒ DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal. <sup>2</sup> mm R/Bal. <sup>2</sup> mmL/Bal. <sup>2</sup> mm L/Bal. <sup>2</sup> mm

D.O.A. 8/3/18 D.O.I. 19/3/18

Survey held at \_\_\_\_\_

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

<sup>Ree</sup>

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

7/6/18 <sup>7791.53</sup> confirmed final by \$7791.53 with Sam. (Recd 2574.74, 2874)

RECEIVED 08 JUN 2018

Date/Time File Pass to? ☐ : Preli. Report☐ : Final Report

Date/Time File Return to?

2) 8/6 - typist

Days Of Repair: 8

Resurvey No. of Trip: 1

Add Fee: ☐ Site Insp (\$)☐ Interview (\$)☐ Tech. Invs (\$)☐ Weekend (\$)

Survey Fee: \_\_\_\_\_

Transportation: \_\_\_\_\_

) \$ + RS \$

) Photos

) Other

TOTAL: \_\_\_\_\_

Report Format: merimen

Lump Sum / I.B.L: (\$ 7791.53)




# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

| Affiliated to Federation Internationale Des Experts En Automobile  |  |                           |   |
|--|--|---------------------------|---|
| MSIG INSURANCE (SINGAPORE) PTE LTD   |  | Ref : CS/MSG18004999/Uvd3 |   |
| 16 RAFFLES QUAY<br>#24-01 HONG LEONG BLDG SINGAPORE 048581   |  | Date : 16-03-2018         |  |
|  |  | Code : MSG                |   |
| <b>1. Policy Particulars :- THIRD PARTY CLAIM</b>  |  |                           |   |
| Insured Veh.   | SKQ 5254G  | Veh. Inspected            | SLS 7578L   |
| Policy No.   | A80449646AT2   | Coverage (\$)             | 0.00  |
| Claim No.  | 552055   | Excess (\$)               | 0.00  |
| Assign From  | MERIMEN (JASMINE LOK)  | Assign Date               | 16/03/2018  |
| <b>2. Vehicle Particulars &amp; Condition</b>  |  |                           |   |
| Make & Model   |  | c.c                       | 0   |
| Engine No.   | HIDDEN   | Year of Reg.              |   |
| Chassis No.  |  | Colour                    |   |
| Odometer   | -  | Steering                  |   |
| Brakes   |  | Modification              |   |
| General  |  |                           |   |
| <b>3. Conditions of Tyres</b>  |  |                           |   |
|  | Size   | Make                      | Balance   |
| R/H Front Tyre   |  |                           | mm  |
| L/H Front Tyre   |  |                           | mm  |
| R/H Rear Tyre  |  |                           | mm  |
| L/H Rear Tyre  |  |                           | mm  |
| <b>4. Description of Damages</b>   |  |                           |   |
|  |  |                           |   |
| <b>5. General Information</b>  |  |                           |   |
| Accident Date  | 08/03/2018   | Inspection Date           | 19/03/2018  |
| Survey held at   | BORNEO MOTORS (S) PTE LTD<br>17 UBI ROAD 4<br>SINGAPORE 408611 |                           |   |
| <b>5a. Remarks</b>   |  |                           |   |
| A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS.<br>B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS. |  |                           |   |

## ...CLAIM SUBFOLDER...(New Assignment)

### CLAIM SUBFOLDER TRACKING

| Case | Notified    | Est Submitted | Adj Assigned                                   | Adj Rpt | Adj Submitted | Ins Auth'd | Status   |
|------|-------------|---------------|--|---------|---------------|------------|--|
| Main | 09 Mar 2018 |               | 16 Mar 2018<br>09:06<br><a href="#">Assign</a> |         |               |            | <b>New Assignment</b><br><a href="#">Cancel Case</a> |

Main

Reference

Claim Details

Documents

[Show All](#)

### CLAIM SUBFOLDER DETAILS

[Created by insurer]

|                             |  |                        |   |
|-----------------------------|--|------------------------|---|
| Insured:                    | LEE CHING TEEK, ID: S2553608H  |                        |   |
| Main Claimant:              | JIMMY LIM YONG, ID: S7876700F  |                        |   |
| Vehicle Reg. No.:           | SLS7578L   | Date of Loss:          | 08/03/2018 12:00 - :59  |
| Claim Type:                 | TP / 552055  | Policy/Cover Note No.: | A80449646AT2 (Comprehensive)<br>Coverage: 05/12/2017 - 04/12/2018 |
| Vehicle Reg. No. (Insured): | SKQ5254G   | Policy No. (Claimant): |   |
|                             |  | Excess:                | S\$1,000.00   |
| Repairer:                   | - Not Applicable - (-)   |                        |   |
| Handling Insurer:           | MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Jasmine Lok Kheng Kwei - 6594 2550] |                        |   |
| Adjuster:                   | LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Imm.Advice due 17/03/2018]                                 |                        |   |
| Adj Asg. Remarks:           | Car will be in on 19/03/18. Please attend.   |                        |   |

### ASSOCIATED MAIL RECEIVED

[View All](#)[Compose Case Mail](#)

There are no mail for this case.

### ALL ASSOCIATED TASKS

[View All](#)[Search Tasks](#)[Create New Task](#)[Complete](#)

| Due Date    | Priority | Type | Task Group | Subject | Handler | Assigned By | Completed On | Created On | Done? |
|-------------|----------|------|------------|---------|---------|-------------|--------------|------------|-------|
| No results. |          |      |            |         |         |             |              |            |       |

## Hasrianah Binte Hassan

---

**From:** Woon Choo Kwok  
**Sent:** Monday, 12 March, 2018 10:19 AM  
**To:** Jasmine Lok Kheng Kwei; Katherine Wong; Hasrianah Binte Hassan  
**Cc:** Christopher Chionh; Foo Ai Ngho; Jason Sim  
**Subject:** FW: Direct Settlement (SM) - Accident Involving SLS7578L & SKQ5254G DOA 08.03.2018  
**Attachments:** img-180309112435-0001.pdf; DSC08532.JPG; DSC08533.JPG; DSC08534.JPG; DSC08535.JPG; DSC08536.JPG; DSC08537.JPG

Dear KW & HAS

FYA

Best Regards

**Kwok Woon Choo**  
Senior Administrative Officer, Claims Services  
Direct line +65 6643 1330 | Direct fax +65 6225 7402 | [woonchoo\\_kwok@sg.msig-asia.com](mailto:woonchoo_kwok@sg.msig-asia.com)



**MSIG**



Insurer Claims  
Team of the Year  
2016

MSIG Insurance (Singapore) Pte Ltd 16 Raffles Quay, #24-01 Hong Leong Building, Singapore 048581 | T: +65 6220 9644 | F: +65 6225 6371 | Co. Reg. No. 200412212G | [msig.com.sg](http://msig.com.sg)



A Member of **MS&AD** INSURANCE GROUP

---

**From:** Agnes Lee  
**Sent:** Monday, March 12, 2018 10:13 AM  
**To:** Woon Choo Kwok <[WoonChoo\\_Kwok@sg.msig-asia.com](mailto:WoonChoo_Kwok@sg.msig-asia.com)>  
**Subject:** FW: Direct Settlement (SM) - Accident Involving SLS7578L & SKQ5254G DOA 08.03.2018

**From:** Suraidah B Saidi PTCBC [<mailto:SuraidahB.Saidi@inchcape.com.sg>]  
**Sent:** 12 March 2018 09:07  
**To:** Claims <[claims@sg.msig-asia.com](mailto:claims@sg.msig-asia.com)>  
**Cc:** Siti Nabilah PTCBC <[Siti.Nabilah@inchcape.com.sg](mailto:Siti.Nabilah@inchcape.com.sg)>  
**Subject:** Direct Settlement (SM) - Accident Involving SLS7578L & SKQ5254G DOA 08.03.2018

Hi,

Reference to the above-mentioned.

Please find attached herein a copy of our client's Accident Report, Damaged Photos & Estimate Invoice for your kind perusal.

As our client is claiming against your insured SKQ5254G thus would appreciate if you could revert to us on the liability urgently or we could settle the case under Direct Settlement with Car Rental of @ \$100 per day x no. of days as recommended by your appointed surveyor.

Kindly have your surveyor to contact our Motor Claim Assessor, **Sam Joi @ 9847 6209 / 6631 1687** is located at **17 Ubi Road 4** for an appointment to inspect our client's vehicle.

As for liability clearance, kindly revert to this email.

Your kind attention into the above is greatly appreciated.

Thank you.

Warmest Regards,

SURAIDAH

TPR TEAM, CLAIMS DEPT

D: 6631 1887 | F: 6872 7260 | E: [suraidahb.saidi@inchcape.com.sg](mailto:suraidahb.saidi@inchcape.com.sg)

Inchcape Centre

Level 4, Bodycare Centre

2 Pandan Crescent

Singapore 128462

[www.borneomotors.com.sg](http://www.borneomotors.com.sg) | [www.lexus.com.sg](http://www.lexus.com.sg) | [www.toyotasingapore.com.sg](http://www.toyotasingapore.com.sg) | [www.hino.com.sg](http://www.hino.com.sg)

This e-mail (and any attachment) is intended for the addressee(s) only and contains information that is legally privileged and confidential. If you are not the intended recipient, please be advised that you have received this e-mail in error and that any use, dissemination, distribution, printing or copying of this communication is unauthorized and strictly prohibited. Kindly notify us by replying to the sender's e-mail address and delete this e-mail immediately. E-mail transmissions cannot be guaranteed to be secure or error-free as information could be intercepted, corrupted, lost, destroyed, delayed or incomplete, or could contain viruses. We therefore do not accept liability for any errors or omissions in the contents of this e-mail which arise as a result of e-mail transmission, and you are advised to carry out your own virus checks and confirm the accuracy of the contents of this e-mail before relying on it for any purpose.

---

#### CONFIDENTIALITY NOTICE

This e-mail (including any attachments) may contain information that is privileged or confidential. The sending of this e-mail to any person other than the intended recipient is not a waiver of the privilege or confidentiality that attaches to it. If you are not the intended recipient, please notify the sender immediately, delete the email and do not copy, distribute or disclose its contents.

# LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

|  |   |
|--|---|
| To: MSIG Insurance (Singapore) Pte. Ltd.<br>4 Shenton Way<br>#21-01 SGX Centre 2<br>Singapore 068807 | From: LKK Auto Consultants Pte Ltd<br>51 Ubi Ave 1 #01-25<br>Paya Ubi Industrial Park<br>Singapore 408933 |
| Attn: Jasmine Lok Kheng Kwei   | Date: 20 Mar 2018   |
| <b><u>Preliminary Advice</u></b>   |   |

|                    |                        |                         |              |
|--------------------|------------------------|-------------------------|--------------|
| Insured Vehicle No | : SKQ5254G             | Accident Date           | : 08/03/2018 |
| TP Vehicle No      | : SLS7578L             | Assignment Date         | : 16/03/2018 |
| Make               | : TOYOTA COROLLA ALTIS | Est. Duration of Repair | : 8.00       |
| Date of Inspection | : 19/03/2018           |                         |              |
| Inspection At      | :                      |                         |              |

## **Point of Impact / General Description of Damages**

The vehicle sustained impact / damages rear portion and parts claimed are consistent to the accident.

|                             |      |           |
|-----------------------------|------|-----------|
| Repairer's Estimate (Gross) | :S\$ | 10,766.27 |
| Revised Amount              | :S\$ | 7,791.53  |
| Check Items (Estimated)     | :S\$ | 125.12    |
| Total                       | :S\$ | 7,916.65  |
| Lump Sum Repair             | :S\$ |           |

## **Total Loss Consideration**

|                    |      |  |
|--------------------|------|--|
| New for Old Value  | :S\$ |  |
| Pre-Accident Value | :S\$ |  |
| COE / PARF Rebate  | :S\$ |  |
| Salvage Value      | :S\$ |  |
| Margin for Repair  | :S\$ |  |

## **Remarks**

|                                     |  |
|-------------------------------------|--|
| <input type="checkbox"/>            | The vehicle is economical/not economical for repair.           |
| <input checked="" type="checkbox"/> | The above survey was conducted on a 'without prejudice' basis. |

## Enquire PARF/COE Rebate for Registered Vehicle

|                                |                                      |
|--------------------------------|--------------------------------------|
| Vehicle Owner Particulars      |                                      |
| Owner ID Type:                 | Singapore NRIC                       |
| Owner ID:                      | 6700F                                |
| Vehicle Details                |                                      |
| Vehicle No.:                   | SLS7578L                             |
| Vehicle to be Exported:        | No                                   |
| Intended De-registration Date: | 19 Mar 2018                          |
| Vehicle Make:                  | TOYOTA                               |
| Vehicle Model:                 | COROLLA ALTIS ECO AUTO               |
| Primary Colour:                | Grey                                 |
| Manufacturing Year:            | 2017                                 |
| Engine No.:                    | 1ZR1986386                           |
| Chassis No.:                   | MR053REH604571654                    |
| Maximum Power Output:          | 96.0 kW (128 bhp)                    |
| Open Market Value:             | \$19,990.00                          |
| Original Registration Date:    | 03 Oct 2017                          |
| First Registration Date:       | 03 Oct 2017                          |
| Transfer Count:                | 0                                    |
| Actual ARF Paid:               | \$14,990.00                          |
| Intended PARF Rebate Details   |                                      |
| PARF Eligibility:              | Yes                                  |
| PARF Eligibility Expiry Date:  | 02 Oct 2027                          |
| PARF Rebate Amount:            | \$11,242.00                          |
| Intended COE Rebate Details    |                                      |
| COE Expiry Date:               | 02 Oct 2027                          |
| COE Category:                  | A - Car up to 1600cc & 97kW (130bhp) |
| COE Period(Years):             | 10                                   |
| QP Paid:                       | \$42,900.00                          |
| COE Rebate Amount:             | \$40,909.00                          |
| <b>Total Rebate Amount:</b>    | <b>\$52,151.00</b>                   |

The information contained herein is correct as at 19 Mar 2018

OK



REPUBLIC OF SINGAPORE  
IDENTITY CARD NO. S7876700F



Name

JIMMY LIM YONG



Race

CHINESE

Date of Birth

20-12-1978

Sex

M

Country of Birth

MALAYSIA

8473693



NRIC No. S7876700F



Nationality

MALAYSIAN

Blood Group

O+

Date of issue

05-09-2002

1 SUNSHINE TERRACE #09-04  
SINGAPORE 535669

S7876700F

30/09/2014

**REPUBLIC OF SINGAPORE DRIVING LICENCE**

Licence Number: **S7876700F**

Person:

**JIMMY LIM YONG**

Birth Date: **20 Dec 1978**

Issue Date: **05 Mar 2005**

001326000F



**YOU ARE LICENSED TO DRIVE VEHICLES IN THE FOLLOWING CLASS(ES)**

|   | PASS DATE   |
|---|-------------|
| Class 3 Motor cars $\leq$ 3000 kg with $\leq$ 7 passengers, exclusive of the driver, and motor tractors / vehicles $\leq$ 2500 kg | 05 Mar 2005 |

NP 428A

Licence No: S7876700F



## SINGAPORE ACCIDENT STATEMENT

### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

### ACCIDENT STATEMENT

|                            |  |
|----------------------------|--|
| Date Of Report             | 09/03/2018 10:56                         |
| Date Of Accident           | 08/03/2018 12:00                         |
| Exact Location Of Accident | BEDOK NORTH AVE 3 TURN TO BEDOK NORTH RD |
| Country/State of Loss      | SINGAPORE                                |

### DATA KEOWN VEHICLE

|                             |                      |
|-----------------------------|----------------------|
| Vehicle Registration Number | SLS7578L             |
| <b>Insured/Policyholder</b> |                      |
| Name Of Registered Owner    | JIMMY LIM YONG       |
| NRIC No                     | S7876700F            |
| Email Address               | NOEMAIL              |
| Mobile Phone No             | (LOCAL) +65-81260658 |
| Alternative Phone No        | OFFICE-81260658      |

### Vehicle Particulars

|              |                       |
|--------------|-----------------------|
| Manufacturer | TOYOTA                |
| Model        | COROLLA ALTIS-1.6 (A) |

Exact Purpose for which vehicle was being used at time of accident

Are you claiming under your own insurance policy for repair to your vehicle? NO

If No, Please state action to be taken THIRD PARTY

Vehicle Category PRIVATE CAR

### Insurance Company

|                           |                       |
|---------------------------|-----------------------|
| Name of Insurance Company | AXA INSURANCE PTE LTD |
| Type Of Coverage          | COMPREHENSIVE         |
| Fleet Policy              | NO                    |
| Policy Number             | P1998143              |
| Cover Note Number         |                       |

### Driver

|                      |                       |
|----------------------|-----------------------|
| Name of Driver       | JIMMY LIM YONG        |
| NRIC No              | S7876700F             |
| Date Of Birth        | 20/12/1978            |
| Occupation           | INDOOR                |
| Date Of Driving Pass | 05/03/2005            |
| Driving Experience   | 13 YEARS AND 0 MONTHS |
| Gender               | MALE                  |
| Mobile Number        | (LOCAL) +65-81260658  |
| Fax Number           |                       |
| Contact Number       | OFFICE-81260658       |
| EMail Address        | NOEMAIL               |

|   |                           |
|---|---------------------------|
| Address   | 1 SUNSHINE TERRACE #09-04 |
| Postcode  | 535689                    |
| Was driver an employee of the Insured's Company     | NO                        |
| If No, Relationship of the Driver with the Insured  | OWNER                     |
| Vehicle Registration Number of Driver's Own Vehicle | -                         |
|   | -                         |
|   | -                         |
| Insurance Company of Driver's Own Vehicle           | -                         |
|   | -                         |
|   | -                         |

#### General Information of the Accident

|                    |                          |
|--------------------|--------------------------|
| Type Of Accident   | COLLISION - HEAD TO REAR |
| Weather Conditions | CLEAR                    |
| Road Surface       | DRY                      |

#### Other Information

|   |     |
|---|-----|
| Was any foreign vehicle involved in this accident?  | NO  |
| Number of vehicles involved in the accident   | 2   |
| Was any body injured in the Accident?   | NO  |
| Was any injured conveyed to hospital by ambulance?  | NO  |
| Was any other material or property damaged?   | YES |
| I have been approached by unknown person(s) soliciting/offering accident claims assistance. | NO  |
| Number of Passengers (Including Driver)   | 1   |

#### Details of Police Action

|   |    |
|---|----|
| Was the accident reported to the police?  | NO |
| If Yes, Please state which Police Station |    |
| Was notice of intended Prosecution given? | NO |
| If Yes, against whom?                     |    |

#### Circumstances of Accident

PLEASE REFER TO SKETCH PLAN.

#### Attachment(s)

|   |                        |
|---|------------------------|
| Are accident photos available for attachment? | YES                    |
| Was there any video captured by Car Camera?   | YES                    |
| Remarks/ Reasons:                             | VIDEO FOOTAGE WITH MCA |
| Was there any audio recorded?                 | NO                     |

**DATA IS SENSITIVE - DO NOT DISCLOSE**

|                                     |             |
|-------------------------------------|-------------|
| Vehicle Registration Number         | SKQ5254G    |
| Vehicle Make/Model/Colour           |             |
| Details Of Properties               |             |
| Vehicle Category                    | PRIVATE CAR |
| Name of Driver                      |             |
| NRIC/Passport Number                |             |
| Contact Number                      |             |
| Address                             |             |
| Postcode                            |             |
| Insurance Company Name              |             |
| Nature Of Damage                    |             |
| No. Of Passenger (Including Driver) |             |

## SKETCH PLAN

### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any willful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

(a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:

(i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;

(ii) investigating the accident and/or my claims;

(iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;

(iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or

(v) complying with applicable law in administering, processing, handling and/or dealing with my claims.

(collectively the "Purposes")

(b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and

(c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.


*[Signature]*

Policyholder's Signature / Date & Time

Driver's Signature (if driver is not the policyholder) / Date & Time

*[Signature]*  
Witnessed by Reporting Centre Personnel

### Sketch Plan



I was driving on Beclaire Ave 3 turning to Beclaire North Road.  
As the car in front of my stop for pedestrian to cross the zebra  
crossing, I stop as well. Then a few second later ~~some~~ the car  
in the back hit into my car

We declare the foregoing particulars are true in every respect.

Driver's Signature (If driver is not the policyholder) / Date  
& Time

Witnessed by Reporting Centre Personnel



Borneo Motors (Singapore) Pte Ltd

Online Service Booking :  
www.toyotasingsapore.com.sgToyota Bodycare Centre  
17 Ubi Road 4  
Singapore 409611  
Tel no.: 6631 1188Co Reg No.: 196700086Z  
GST Reg No.: MR-8500000-9

## ESTIMATE

Join Toyota ME @ http://toyotame.borneomotors.com.sg &amp; earn points to redeem for attractive items!

| Account Detail  | Account No                  | Customer Detail   |
|---|-----------------------------|---|
| MSIG Insurance (Singapore) Pte Ltd<br>4 Shenton Way<br>#21-01 SGX Centre 2<br>Singapore 068807<br>Attn: Motor Claims Dept | S1000004 / ICCU1            | Mr Jimmy Lim Yong<br>1 Sunshine Terrace<br>#09-04<br>Singapore 535698<br>Mobile: 81260658 |
|   | Document No<br>0            |   |
|   | Document Date<br>09/03/2018 |   |

| Year              | Make       | Model  | Reg Date    | Veh Reg No       | Kilometers | WIP No       | Order No/Remarks   |
|-------------------|------------|--------|-------------|------------------|------------|--------------|--------------------|
| 17                | GEXGP2     | E1     | 03/10/2017  | SLS7578L         | 5110       | 16156        | 7DS/SLS7578L/08031 |
| Chassis No        | Engine No  | TWC No | Terms       | Service Engineer | Vehicle In | Collected On |                    |
| MR053REH604571654 | 12R1986386 | 60     | Sam San Joi | 09/03/2018       | 8.00       | --/--/----   | 0.00               |

| L  | Cd | Job/Parts Description  | Qty  | Unit Price | Disc % | Amount  |
|----|----|--|------|------------|--------|---------|
| 1  | I  | BP-SUNDRY SUNDRIES TP-DIRECT SETTLEMENT <i>NA</i><br>TP-SKQ5254G ACC DATE:08/03/2018<br>DRIVE IN:08/03/2018<br>DATE-IN: DATE SURVEY:<br>NO OF REPAIR DAYS:<br>BY: AUTHORIZED ON: |      |            |        | 30.00   |
| 2  | S  | BP-SUBLET DRILL HOLE & INSTALL REAR REVERSE SENSOR   |      |            |        | 154.00  |
| 3  | S  | BP-SUBLET CHECK LIGHTING & CONDUCT WATER LEAK TEST   |      |            |        | 154.00  |
| 4  | S  | BP-SUBLET SEALANT - BOOTLID, REAR END PANEL  |      |            |        | 160.00  |
| 5  | S  | BP-SUBLET REMOVE & INSTALL BOOTLID CARPET, GARNISH AND TRIMMI TO ASSIST REPAIR   |      |            |        | 308.00  |
| 6  | S  | BP-SUBLET REPLACE REAR BUMPER, REAR END PANEL, ETC STRAIGHTEN & ALIGN REAR ACCIDENT AFFECTED AREAS   | 616  |            |        | 3080.00 |
| 7  | S  | BP-SUBLET RESPRAY JOB ON REAR ACCIDENT AFFECTED AREAS  | 506  |            |        | 2530.00 |
| 8  | 1  | S52159-02904 COVER, RR BUMPER  | 1.00 | 539.90     | 15.00  | 458.91  |
| 9  | 2  | S52563-02250 RETAINER, RR BUMPER L   | 1.00 | 58.30      | 15.00  | 49.55   |
| 10 | 3  | S52576-02140 RETAINER, RR BUMPER L   | 1.00 | 105.70     | 15.00  | 89.84   |
| 11 | 4  | S52562-02250 RETAINER, RR BUMPER R   | 1.00 | 58.30      | 15.00  | 49.55   |
| 12 | 5  | S52575-02140 RETAINER, RR BUMPER R   | 1.00 | 105.70     | 15.00  | 89.84   |

Borneo Motors is the only authorised workshop to maintain your Toyota. Service your Toyota every 6 months or 10,000 km (whichever comes first) to enjoy warranty benefits. Conditions apply.

| For on behalf of Borneo Motors | Customer's Signature                  | Change Summary  | Total      |
|--------------------------------|---------------------------------------|---|------------|
|                                | Please acknowledge receipt of vehicle | Parts<br>Labour<br>Materials<br>Lubrication/Fluid<br>Others | Less       |
|                                |                                       |   | Amount Due |

PLEASE TEAR ALONG PERFORATED LINE

3627708

TO SECURITY GUARD

3627708

PLEASE ALLOW THE UNDERMENTIONED  
VEHICLE TO LEAVE THE COMPANY PREMISES.DATE 09/03/2018  
TIME 08:31

VEHICLE NO SLS7578L

CUSTOMER

SIGNATURE  
FOR BORNEO MOTORS (SINGAPORE) PTE LTD.

Borneo Motors

Co Reg No: 196700086Z  
GST Reg No: MR-8500000-9

## ESTIMATE

Join Toyota ME @ http://toyotame.borneomotors.com.sg &amp; earn points to redeem for attractive items!

| Account Detail  | Account No                  | Customer Detail   |
|---|-----------------------------|---|
| MSIG Insurance (Singapore) Pte Ltd<br>4 Shenton Way<br>#21-01 SGX Centre 2<br>Singapore 068807<br>Attn: Motor Claims Dept | S1000004 / ICCU1            | Mr Jimmy Lim Yong<br>1 Sunshine Terrace<br>#09-04<br>Singapore 535698<br>Mobile: 81260658 |
|   | Document No<br>0            |   |
|   | Document Date<br>09/03/2018 |   |

| Year              | Make       | Model  | Reg Date    | Veh Reg No       | Kilometers | WIP No       | Order No/Remarks           |
|-------------------|------------|--------|-------------|------------------|------------|--------------|----------------------------|
| 17                | GEXGP2     | E1     | 3RE171R     | 03/10/2017       | SLS7578L   | 5110         | 16156 -7DS/SLS7578L/08031: |
| Chassis No        | Engine No  | TWC No | Terms       | Service Engineer | Vehicle In | Collected On |                            |
| MR053REH604571654 | 12R1986386 | 60     | Sam San Joi | 09/03/2018       | 8.00       | --/--/----   | 0.00                       |

| L  | Cd | Job/Parts Description                          | Qty   | Unit Price | Disc % | Amount |
|----|----|--|-------|------------|--------|--------|
| 13 | 6  | S52161-0K040 CLIPS                             | 10.00 | 3.90       | 15.00  | 33.10  |
| 14 | 7  | S52023-02190 REINFORCEMENT, RR                 | 1.00  | 386.60     | 15.00  | 328.61 |
| 15 | 8  | S52182-02160 ARM, RR BUMPER, OUTE              | 1.00  | 66.20      | 15.00  | 56.27  |
| 16 | 9  | S52181-02190 ARM, RR BUMPER, OUTE              | 1.00  | 66.20      | 15.00  | 56.27  |
| 17 | 0  | S58307-02380 PANEL, LAMP LOWER                 | 1.00  | 649.20     | 15.00  | 551.82 |
| 18 | 1  | S58387-02240 PLATE, RR FLOOR                   | 1.00  | 234.30     | 15.00  | 199.15 |
| 19 | 2  | S64771-02390 CO COVER, SPARE WHEEL             | 1.00  | 259.10     | 15.00  | 220.23 |
| 20 | 3  | S64401-02861 PANEL SUB-ASSY, LUGG              | 1.00  | 715.10     | 15.00  | 607.83 |
| 21 | 4  | S64461-02220 WEATHERSTRIP, LUGGAG              | 1.00  | 170.20     | 15.00  | 144.67 |
| 22 | 5  | S64600-02080 LOCK ASSY, LUGGAGE C              | 1.00  | 386.60     | 15.00  | 328.61 |
| 23 | 6  | S64621-06080 STRIKER, LUGGAGE COM              | 1.00  | 14.80      | 15.00  | 12.58  |
| 24 | 7  | S75431-02090 LUGGAGE COMP EMBLEM,              | 1.00  | 59.70      | 15.00  | 50.74  |
| 25 | 8  | S75442-02330 EMBLEM, SYMBOL                    | 1.00  | 39.70      | 15.00  | 33.74  |
| 26 | 9  | S75442-02340 EMBLEM, SYMBOL                    | 1.00  | 44.10      | 15.00  | 37.48  |
| 27 | 0  | S81560-02B20 LAMP ASSY, RR COMBIN              | 1.00  | 482.10     | 15.00  | 409.78 |
| 28 | 1  | S81550-02B20 LAMP ASSY, RR COMBIN              | 1.00  | 482.10     | 15.00  | 409.78 |
| 29 | 2  | SP2061-12028 76 GREY METALLIC 2 REVERSE SENSOR | 1.00  | 155.20     | 15.00  | 131.92 |

Borneo Motors is the only authorised workshop to maintain your Toyota. Service your Toyota every 6 months or 10,000 km (whichever comes first) to enjoy warranty benefits. Conditions apply.

| For & on behalf of<br>Borneo Motors | Customer's Signature                  | Charge Summary         | Total                |
|-------------------------------------|---------------------------------------|------------------------|----------------------|
|                                     | Please acknowledge receipt of vehicle | Parts 4,350.27         | 10,766.27            |
|                                     |                                       | Labor 30.00            |                      |
|                                     |                                       | Materials 6,386.00     | GST 7.00%            |
|                                     |                                       | Lubrication/Fluid 0.00 | 753.64               |
|                                     |                                       | Others 0.00            | Less 0.00            |
|                                     |                                       |                        | Amount Due 11,519.91 |

LKK Auto Consultants hence notify  
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer DATE 09/03/2018  
Signature TIME 08:31

TO SECURITY GUARD

PLEASE ALLOW THE UNDERMENTIONED  
VEHICLE TO LEAVE THE COMPANY PREMISES.

VEHICLE NO SLS7578L

CUSTOMER

SIGNATURE  
FOR BORNEO MOTORS (SINGAPORE) PTE LTD

Borneo Motors



# TAX INVOICE

Toyota Bodycare Centre  
17 Ubi Road 4  
Singapore 409611  
Tel no.: 6631 1188

MSIG Insurance (Singapore) Pte Ltd  
4 Shenton Way  
#21-01 SGX Centre 2  
Singapore 068807  
Attn: Motor Claims Dept

S1000004/ICCUA1

39006463

17/04/2018

Mr Jimmy Lim Yong  
1 Sunshine Terrace  
#09-04  
Singapore 535698  
Mobile: 81260658

17 GEXGPZ E1 ZRE171R 03/10/2017 SLS7578L 5110 16156 7DS/SLS7578L/08031

MR053REH604571654 1ZR1986386 60 Sam San Joi 09/03/2018 8.15 26/03/2018 8.51

|    |   |              |   |                          |      |        |       |  |         |
|----|---|--------------|---|--------------------------|------|--------|-------|--|---------|
| 1  | Z | BP-SUNDRY    | SUNDRIES  | TP-DIRECT SETTLEMENT     |      |        |       |  | 30.00   |
|    |   |              |   | TP-SKQ5254G              |      |        |       |  |         |
|    |   |              |   | ACC DATE:08/03/2018      |      |        |       |  |         |
|    |   |              |   | DRIVE IN:08/03/2018      |      |        |       |  |         |
|    |   |              |   | DATE-IN:19/03/2018       |      |        |       |  |         |
|    |   |              |   | DATE SURVEY:19/03/2018   |      |        |       |  |         |
|    |   |              |   | NO OF REPAIR DAYS:8 DAYS |      |        |       |  |         |
|    |   |              |   | BY:MARCUS(LKK)           |      |        |       |  |         |
| 2  | S | BP-SUBLET    | DRILL HOLE & INSTALL REAR REVERSE SENSOR        | A45                      |      |        |       |  | 154.00  |
| 3  | S | BP-SUBLET    | CHECK LIGHTING & CONDUCT WATER LEAK TEST        | A45                      |      |        |       |  | 154.00  |
| 4  | S | BP-SUBLET    | SEALANT - REAR END PANEL                        | A45                      |      |        |       |  | 80.00   |
| 5  | S | BP-SUBLET    | REMOVE & INSTALL BOOTLID CARPET, GARNISH        | A45                      |      |        |       |  | 308.00  |
|    |   |              | AND TRIMMI TO ASSIST REPAIR                     |                          |      |        |       |  |         |
| 6  | S | BP-SUBLET    | REPLACE REAR BUMPER, REAR END PANEL, ETC        | A45                      |      |        |       |  | 2464.00 |
|    |   |              | STRAIGHTEN & ALIGN REAR ACCIDENT AFFECTED AREAS |                          |      |        |       |  |         |
| 7  | S | BP-SUBLET    | RESPRAY JOB ON REAR ACCIDENT AFFECTED AR        | A45                      |      |        |       |  | 2024.00 |
|    |   |              | EAS   |                          |      |        |       |  |         |
| 8  | 1 | S52159-02904 | COVER, RR BUMPER                                |                          | 1.00 | 539.90 | 15.00 |  | 458.91  |
| 9  | 2 | S52563-02250 | RETAINER, RR BUMPER L                           |                          | 1.00 | 58.30  | 15.00 |  | 49.55   |
| 10 | 3 | S52576-02140 | RETAINER, RR BUMPER L                           |                          | 1.00 | 105.70 | 15.00 |  | 89.84   |
| 11 | 4 | S52562-02250 | RETAINER, RR BUMPER R                           |                          | 1.00 | 58.30  | 15.00 |  | 49.55   |
| 12 | 5 | S52575-02140 | RETAINER, RR BUMPER R                           |                          | 1.00 | 105.70 | 15.00 |  | 89.84   |

17/04/2018  
16:56

SLS7578L

# TAX INVOICE

Toyota Bodycare Centre  
17 Ubi Road 4  
Singapore 409611  
Tel no.: 6631 1188

MSIG Insurance (Singapore) Pte Ltd  
4 Shenton Way  
#21-01 SGX Centre 2  
Singapore 068807  
Attn: Motor Claims Dept

S1000004 /ICCUA1

39006463

17/04/2018

Mr Jimmy Lim Yong  
1 Sunshine Terrace  
#09-04  
Singapore 535698  
Mobile: 81260658

17 GEXGPZ E1 ZRE171R 03/10/2017 SLS7578L 5110 16156 7DS/SLS7578L/08031:

MR053REH604571654 12R1986386 60 Sam San Joi 09/03/2018 8.15 26/03/2018 8.51

|    |   |                 |                                |       |        |       |        |
|----|---|-----------------|--------------------------------|-------|--------|-------|--------|
| 13 | 6 | S52161-0K040    | PIECE,RR BUMPER                | 10.00 | 3.90   | 15.00 | 33.10  |
| 14 | 7 | S52023-02190    | REINFORCEMENT,RR               | 1.00  | 386.60 | 15.00 | 328.61 |
| 15 | 8 | S58307-02380    | PANEL,LAMP LOWER               | 1.00  | 649.20 | 15.00 | 551.82 |
| 16 | 9 | S58387-02240    | PLATE,RR FLOOR                 | 1.00  | 234.30 | 15.00 | 199.15 |
| 17 | 0 | S64461-02220    | WEATHERSTRIP,LUGGAGE           | 1.00  | 170.20 | 15.00 | 144.67 |
| 18 | 1 | S64600-02080    | LOCK ASSY,LUGGAGE              | 1.00  | 386.60 | 15.00 | 328.61 |
| 19 | 2 | S75431-02090    | EMBLEM, LUGGAGE COMP           | 1.00  | 59.70  | 15.00 | 50.74  |
| 20 | 3 | S75442-02330    | PLATE,LUGGAGE DOOR             | 1.00  | 39.70  | 15.00 | 33.74  |
| 21 | 4 | S75442-02340    | PLATE,LUGGAGE DR               | 1.00  | 44.10  | 15.00 | 37.48  |
| 22 | 5 | SP2061-12028 76 | GREY METALLIC 2 REVERSE SENSOR | 1.00  | 155.20 | 15.00 | 131.92 |

|          |           |  |          |
|----------|-----------|--|----------|
|          |           |  | 7,791.53 |
| 2,577.53 | GST 7.00% |  | 545.41   |
| 30.00    |           |  |          |
| 5,184.00 |           |  | 0.00     |
| 0.00     |           |  |          |
| 0.00     |           |  |          |
|          |           |  | 8,336.94 |

PLEASE MAIL YOUR CHEQUE TO 33 LENG KEE ROAD, SINGAPORE 159102

17/04/2018  
16:56

SLS7578L

## ...CLAIM SUBFOLDER...(Pending for Survey Report)

| CLAIM SUBFOLDER TRACKING |             |               |  |  |  |             |   |
|--------------------------|-------------|---------------|--|--|--|-------------|---|
| Case                     | Notified    | Est Submitted | Adj Assigned   | Adj Rpt  | Adj Submitted                                  | Ins Auth'ed | Status  |
| Main                     | 09 Mar 2018 |               | 16 Mar 2018<br>09:06<br><a href="#">Edit Adj Rpt</a> | <b>S\$7,791.53</b><br><a href="#">Edit Estimates</a> | <b>S\$7,791.53</b><br><a href="#">View Rpt</a> |             | <b>Pending for Survey Report</b><br><a href="#">Cancel Case</a> |
































  

| Main  | Reference  | Claim Details          | Documents  | Show All |         |             |              |            |       |
|---|--|------------------------|--|----------|---------|-------------|--------------|------------|-------|
| <b>CLAIM SUBFOLDER DETAILS</b> <span style="float: right;">[Created by insurer]</span>  |  |                        |  |          |         |             |              |            |       |
| Insured:  | <b>LEE CHING TEEK</b> , ID: S2553608H  |                        |  |          |         |             |              |            |       |
| Main Claimant:  | <b>JIMMY LIM YONG</b> , ID: S7876700F  |                        |  |          |         |             |              |            |       |
| Vehicle Reg. No.:   | <b>SLS7578L</b>  | Date of Loss:          | 08/03/2018 12:00 - :59<br>[5 Months and 5 Days From LTA Reg Date (Man Yr)] |          |         |             |              |            |       |
| Claim Type:   | <b>TP / 552055</b>   | Policy/Cover Note No.: | A80449646AT2 (Comprehensive)<br>Coverage: 05/12/2017 - 04/12/2018          |          |         |             |              |            |       |
| Vehicle Reg. No. (Insured):   | <b>SKQ5254G</b>  | Policy No. (Claimant): |  |          |         |             |              |            |       |
|   |  | Excess:                | S\$1,000.00  |          |         |             |              |            |       |
| Repairer:   | <b>- Not Applicable - (-)</b>  |                        |  |          |         |             |              |            |       |
| Handling Insurer:   | <b>MSIG Insurance (Singapore) Pte. Ltd. (HQ)</b> - Tel: +65 6827 7888 ... [Handled by <b>Jasmine Lok Kheng Kwei</b> - 6594 2550]     |                        |  |          |         |             |              |            |       |
| Adjuster:   | <b>LKK Auto Consultants Pte Ltd (HQ)</b> - Tel: 6256-3561 ... [Handled by <b>MARCUS CHUA</b> ] ... <b>[Final Rpt due 15/04/2018]</b> |                        |  |          |         |             |              |            |       |
| Adj Asg. Remarks:   | Car will be in on 19/03/18. Please attend.   |                        |  |          |         |             |              |            |       |
| <b>ASSOCIATED MAIL RECEIVED</b> <span style="float: right;"><a href="#">View All</a> <a href="#">Compose Case Mail</a></span>   |  |                        |  |          |         |             |              |            |       |
| There are no mail for this case.  |  |                        |  |          |         |             |              |            |       |
| <b>ALL ASSOCIATED TASKS</b> <span style="float: right;"><a href="#">View All</a> <a href="#">Search Tasks</a> <a href="#">Create New Task</a> <a href="#">Complete</a></span> |  |                        |  |          |         |             |              |            |       |
| Due Date  | Priority   | Type                   | Task Group   | Subject  | Handler | Assigned By | Completed On | Created On | Done? |
| No results.   |  |                        |  |          |         |             |              |            |       |

## Claim Documents

\*SLS7578L (552055)  
[SKQ5254G]  
TP  
JIMMY LIM YONG  
Mar 8 2018 12:00PM  
[LEE CHING TEEK]

|                    |                 |                                   |               |  |                    |  |            |  |                                     |  |
|--------------------|-----------------|-----------------------------------|---------------|--|--------------------|--|------------|--|-------------------------------------|--|
| Upload Documents   |                 |                                   | Upload Photos |  | Compose New Letter |  | View       |  | View in Browser                     |  |
| Assessment Reports |                 |                                   |               |  |                    |  | 1 per page |  | <input checked="" type="checkbox"/> |  |
| No                 | Finalized On    | LKK Auto Consultants Pte Ltd (HQ) |               |  |                    |  | Thumbnail  |  | Print                               |  |
| 1                  | 20/03/18 09:44  | Adjuster Immediate Advice         |               |  |                    |  | 1 Load HTM |  |                                     |  |
| Photos/Images      |                 |                                   |               |  |                    |  | 3 per page |  | <input checked="" type="checkbox"/> |  |
| No                 | Relabel/Reorder | LKK Auto Consultants Pte Ltd (HQ) |               |  |                    |  | Thumbnail  |  | Print                               |  |
| 1                  | 19/03/18 16:23  | General View                      |               |  |                    |  | 1 Load JPG |  | <input checked="" type="checkbox"/> |  |
| 2                  | 19/03/18 16:23  | General View                      |               |  |                    |  | 1 Load JPG |  | <input checked="" type="checkbox"/> |  |
| 3                  | 19/03/18 16:23  | General View                      |               |  |                    |  | 1 Load JPG |  | <input checked="" type="checkbox"/> |  |
| 4                  | 19/03/18 16:23  | General View                      |               |  |                    |  | 1 Load JPG |  | <input checked="" type="checkbox"/> |  |
| 5                  | 19/03/18 16:23  | General View                      |               |  |                    |  | 1 Load JPG |  | <input checked="" type="checkbox"/> |  |
| 6                  | 19/03/18 16:23  | General View                      |               |  |                    |  | 1 Load JPG |  | <input checked="" type="checkbox"/> |  |
| 7                  | 19/03/18 16:23  | General View                      |               |  |                    |  | 1 Load JPG |  | <input checked="" type="checkbox"/> |  |
| 8                  | 19/03/18 16:23  | General View                      |               |  |                    |  | 1 Load JPG |  | <input checked="" type="checkbox"/> |  |
| 9                  | 19/03/18 16:23  | General View                      |               |  |                    |  | 1 Load JPG |  | <input checked="" type="checkbox"/> |  |
| 10                 | 19/03/18 16:23  | General View                      |               |  |                    |  | 1 Load JPG |  | <input checked="" type="checkbox"/> |  |
| 11                 | 19/03/18 16:23  | General View                      |               |  |                    |  | 1 Load JPG |  | <input checked="" type="checkbox"/> |  |
| 12                 | 19/03/18 16:23  | General View                      |               |  |                    |  | 1 Load JPG |  | <input checked="" type="checkbox"/> |  |
| 13                 | 19/03/18 16:23  | General View                      |               |  |                    |  | 1 Load JPG |  | <input checked="" type="checkbox"/> |  |
| 14                 | 19/03/18 16:23  | General View                      |               |  |                    |  | 1 Load JPG |  | <input checked="" type="checkbox"/> |  |
| 15                 | 19/03/18 16:23  | General View                      |               |  |                    |  | 1 Load JPG |  | <input checked="" type="checkbox"/> |  |
| 16                 | 19/03/18 16:23  | General View                      |               |  |                    |  | 1 Load JPG |  | <input checked="" type="checkbox"/> |  |
| 17                 | 19/03/18 16:23  | General View                      |               |  |                    |  | 1 Load JPG |  | <input checked="" type="checkbox"/> |  |
| 18                 | 19/03/18 16:23  | General View                      |               |  |                    |  | 1 Load JPG |  | <input checked="" type="checkbox"/> |  |
| 19                 | 19/03/18 16:23  | General View                      |               |  |                    |  | 1 Load JPG |  | <input checked="" type="checkbox"/> |  |
| 20                 | 19/03/18 16:23  | General View                      |               |  |                    |  | 1 Load JPG |  | <input checked="" type="checkbox"/> |  |
| 21                 | 19/03/18 16:23  | General View                      |               |  |                    |  | 1 Load JPG |  | <input checked="" type="checkbox"/> |  |
| 22                 | 19/03/18 16:24  | General View                      |               |  |                    |  | 1 Load JPG |  | <input checked="" type="checkbox"/> |  |
| 23                 | 19/03/18 16:24  | General View                      |               |  |                    |  | 1 Load JPG |  | <input checked="" type="checkbox"/> |  |
| 24                 | 19/03/18 16:24  | General View                      |               |  |                    |  | 1 Load JPG |  | <input checked="" type="checkbox"/> |  |
| 25                 | 19/03/18 16:24  | General View                      |               |  |                    |  | 1 Load JPG |  | <input checked="" type="checkbox"/> |  |
| 26                 | 19/03/18 16:24  | General View                      |               |  |                    |  | 1 Load JPG |  | <input checked="" type="checkbox"/> |  |
| 27                 | 19/03/18 16:24  | General View                      |               |  |                    |  | 1 Load JPG |  | <input checked="" type="checkbox"/> |  |
| 28                 | 19/03/18 16:24  | General View                      |               |  |                    |  | 1 Load JPG |  | <input checked="" type="checkbox"/> |  |
| 29                 | 19/03/18 16:24  | General View                      |               |  |                    |  | 1 Load JPG |  | <input checked="" type="checkbox"/> |  |
| 30                 | 19/03/18 16:24  | General View                      |               |  |                    |  | 1 Load JPG |  | <input checked="" type="checkbox"/> |  |
| 31                 | 19/03/18 16:24  | General View                      |               |  |                    |  | 1 Load JPG |  | <input checked="" type="checkbox"/> |  |
| 32                 | 19/03/18 16:24  | General View                      |               |  |                    |  | 1 Load JPG |  | <input checked="" type="checkbox"/> |  |
| 33                 | 19/03/18 16:24  | General View                      |               |  |                    |  | 1 Load JPG |  | <input checked="" type="checkbox"/> |  |
| 34                 | 19/03/18 16:24  | General View                      |               |  |                    |  | 1 Load JPG |  | <input checked="" type="checkbox"/> |  |

| Assessment Reports |                |   | 1 per page   | <input checked="" type="checkbox"/> |
|--------------------|----------------|---|--|-------------------------------------|
| No                 | Finalized On   | LKK Auto Consultants Pte Ltd (HQ)         | Thumbnail  | Print                               |
| 35                 | 19/03/18 16:24 | General View                              |  Load JPG   | <input checked="" type="checkbox"/> |
| 36                 | 19/03/18 16:24 | General View                              |  Load JPG   | <input checked="" type="checkbox"/> |
| 37                 | 19/03/18 16:24 | General View                              |  Load JPG   | <input checked="" type="checkbox"/> |
| 38                 | 19/03/18 16:24 | General View                              |  Load JPG   | <input checked="" type="checkbox"/> |
| 39                 | 19/03/18 16:24 | General View                              |  Load JPG   | <input checked="" type="checkbox"/> |
| 40                 | 19/03/18 16:24 | General View                              |  Load JPG   | <input checked="" type="checkbox"/> |
| 41                 | 19/03/18 16:24 | General View                              |  Load JPG   | <input checked="" type="checkbox"/> |
| 42                 | 19/03/18 16:24 | General View                              |  Load JPG   | <input checked="" type="checkbox"/> |
| 43                 | 19/03/18 16:24 | General View                              |  Load JPG   | <input checked="" type="checkbox"/> |
| 44                 | 19/03/18 16:24 | General View                              |  Load JPG   | <input checked="" type="checkbox"/> |
| 45                 | 19/03/18 16:24 | General View                              |  Load JPG   | <input checked="" type="checkbox"/> |
| 46                 | 19/03/18 16:24 | General View                              |  Load JPG   | <input checked="" type="checkbox"/> |
| 47                 | 19/03/18 16:24 | General View                              |  Load JPG   | <input checked="" type="checkbox"/> |
| 48                 | 19/03/18 16:24 | General View                              |  Load JPG   | <input checked="" type="checkbox"/> |
| 49                 | 19/03/18 16:24 | General View                              |  Load JPG   | <input checked="" type="checkbox"/> |
| 50                 | 19/03/18 16:24 | General View                              |  Load JPG   | <input checked="" type="checkbox"/> |
| 51                 | 19/03/18 16:24 | General View                              |  Load JPG   | <input checked="" type="checkbox"/> |
| 52                 | 19/03/18 16:24 | General View                              |  Load JPG   | <input checked="" type="checkbox"/> |
| 53                 | 19/03/18 16:24 | Odometer Reading                          |  Load JPG   | <input checked="" type="checkbox"/> |
| 54                 | 19/03/18 16:24 | General View                              |  Load JPG   | <input checked="" type="checkbox"/> |
| 55                 | 19/03/18 16:24 | Chassis Number                            |  Load JPG   | <input checked="" type="checkbox"/> |
| 56                 | 08/06/18 14:28 | Reinspection Photo                        |  Load JPG  | <input checked="" type="checkbox"/> |
| 57                 | 08/06/18 14:28 | Reinspection Photo                        |  Load JPG | <input checked="" type="checkbox"/> |
| 58                 | 08/06/18 14:28 | Reinspection Photo                        |  Load JPG | <input checked="" type="checkbox"/> |
| 59                 | 08/06/18 14:28 | Reinspection Photo                        |  Load JPG | <input checked="" type="checkbox"/> |
| 60                 | 08/06/18 14:28 | Reinspection Photo                        |  Load JPG | <input checked="" type="checkbox"/> |
| 61                 | 08/06/18 14:28 | Reinspection Photo                        |  Load JPG | <input checked="" type="checkbox"/> |
| Documentation      |                |   | 1 per page   | <input checked="" type="checkbox"/> |
| No                 | Finalized On   | MSIG Insurance (Singapore) Pte. Ltd. (HQ) | Thumbnail  | Print                               |
| 1                  | 12/03/18 16:03 | Email frm TP - PRI                        |  Load PDF |                                     |
| 2                  | 12/03/18 16:04 | SLS7578L GIA Rpt                          |  Load PDF |                                     |
| 3                  | 12/03/18 16:04 | SKQ5254G GIA Rpt                          |  Load PDF |                                     |
| 4                  | 12/03/18 16:05 | Estimate                                  |  Load PDF |                                     |

## Documents Checklist

| DOCUMENTS CHECKLIST  | Reset | Save | Print |
|--|-------|------|-------|
| There are no document checklists configured.   |       |      |       |
| <b>Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)</b> <div style="border: 1px solid black; height: 40px; margin-top: 5px;"></div>       |       |      |       |
| <b>Show Remarks To:</b> <input type="checkbox"/> Handling Insurer<br><small>Note: Remarks are private unless you show it to other parties.</small> |       |      |       |

# LKK Auto Consultants Pte Ltd (Co. Reg No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/MSG18004999/UVD3Q2

Date: 08/06/2018

### REFERENCE

Handling Insurer: MSIG Insurance (Singapore) Pte. Ltd.

Policy No: A80449646AT2

Claimant Vehicle No : SLS7578L

Insured Vehicle No : SKQ5254G

Date of Loss: 08/03/2018

Nature of Claim: TP

Claim No: 552055

### DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SLS7578L

Make &amp; Model: TOYOTA COROLLA ALTIS, 1.6 E (A)

Reg. Date: 03/10/2017 (Man. Year: 2017)

Colour: Grey

Engine Capacity: 1598 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): Market Value/New Car Price

Engine No: 1ZR1986386

Chassis No: MR053REH604571654

Odometer: 6978 km

### CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

### CONDITION OF TYRES

Front Tyre Size: 195/65 R15

Rear Tyre Size: 195/65 R15

Front Left Side: Dunlop 8 mm

Rear Left Side: Dunlop 8 mm

Front Right Side: Dunlop 8 mm

Rear Right Side: Dunlop 8 mm

The above values represent the remaining tyre treads depth

| COST OF CLAIMS                | Repairer's       | Adjuster's      | Difference      | Diff %       |
|-------------------------------|------------------|-----------------|-----------------|--------------|
| Parts                         | 4,380.27         | 2,607.53        | 1,772.74        | 40.47        |
| Miscellaneous Items           | 0.00             | 0.00            | 0.00            |              |
| Labour                        | 6,386.00         | 5,184.00        | 1,202.00        | 18.82        |
| Paintwork Labour              | 0.00             | 0.00            | 0.00            |              |
| Towing                        | 0.00             | 0.00            | 0.00            |              |
| <b>Gross Total (S\$)</b>      | <b>10,766.27</b> | <b>7,791.53</b> | <b>2,974.74</b> | <b>27.63</b> |
| <b>+ GST 7.00/7.00% (S\$)</b> | <b>753.64</b>    | <b>545.41</b>   | <b>208.23</b>   | <b>27.63</b> |
| <b>Nett Amount (S\$)</b>      | <b>11,519.91</b> | <b>8,336.94</b> | <b>3,182.97</b> | <b>27.63</b> |

### INSPECTION

Date of Assignment: 16/03/2018

Date Inspected: 19/03/2018 Inspected At:

BORNEO MOTORS (S) PTE LTD

17 UBI ROAD 4

SINGAPORE 408611

Estimated Period of Repair: 8.0 days

Adjuster: MARCUS CHUA

Manager: VERON CHEN

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

|                      |  |  |
|----------------------|--|--|
| <b>Reference</b>     |  |  |
| <b>Part Source:</b>  | MRM-SG   | Version: 1.0 (Last Synchronised: 08 Jun 2018)                    |
| <b>Parts:</b>        | 143  | TOYOTA COROLLA ALTIS 1.6 E (A) (Catalogue:Merimen Singapore 1.0) |
| <b>Labour:</b>       | Repairer's   | (Price-denominated Standard List)                                |
| <b>Print Code:</b>   | (Unsubmitted, no print-code for SLS7578L)  |  |
| <b>Validity:</b>     | These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page |  |
| <b>Further Info:</b> | Items/values not in reference catalogue are prefixed with an asterisk *.   |  |

## Recommended Parts

| No. | Qty | Part No. | Particulars                     | Condition         | Repairer's | Amount     |
|-----|-----|----------|---------------------------------|-------------------|------------|------------|
| 1   | 1   |          | *SUNDRIES                       | Necessary         | 30.00 FS   | *30.00 FS  |
| 2   | 1   |          | *COVER,RR BUMPER                | Dented / Deformed | 458.91 FS  | *458.91 FS |
| 3   | 1   |          | *RETAINER ,RR BUMPER L          | Necessary         | 49.55 FS   | *49.55 FS  |
| 4   | 1   |          | *RETAINER ,RR BUMPER L          | Necessary         | 89.84 FS   | *89.84 FS  |
| 5   | 1   |          | *RETAINER ,RR BUMPER R          | Necessary         | 49.55 FS   | *49.55 FS  |
| 6   | 1   |          | *RETAINER ,RR BUMPER R          | Necessary         | 89.84 FS   | *89.84 FS  |
| 7   | 10  |          | *CLIPS                          | Necessary         | 33.10 FS   | *33.10 FS  |
| 8   | 1   |          | *REINFORCEMENT ,RR              | Dented            | 328.61 FS  | *328.61 FS |
| 9   | 1   |          | *ARM ,RR BUMPER ,OUTE           | Not Necessary     | 56.27 FS   | *- FS      |
| 10  | 1   |          | *ARM ,RR BUMPER ,OUTE           | Not Necessary     | 56.27 FS   | *- FS      |
| 11  | 1   |          | *PANEL ,LAMP LOWER              | Badly Dented      | 551.82 FS  | *551.82 FS |
| 12  | 1   |          | *PLATE ,RR FLOOR                | Twisted           | 199.15 FS  | *199.15 FS |
| 13  | 1   |          | *COVER ,SPARE WHEEL             | Not Necessary     | 220.23 FS  | *- FS      |
| 14  | 1   |          | *PANEL SUB-ASSY ,LUGG           | Repair            | 607.83 FS  | *- FS      |
| 15  | 1   |          | *WEATHERSTRIP ,LUGGAG           | Twisted           | 144.67 FS  | *144.67 FS |
| 16  | 1   |          | *LOCK ASSY ,LUGGAGE C           | Twisted           | 328.61 FS  | *328.61 FS |
| 17  | 1   |          | *STRIKER ,LUGGAGE COM           | Not Necessary     | 12.58 FS   | *- FS      |
| 18  | 1   |          | *LUGGAGE COMP EMBLEM            | Necessary         | 50.74 FS   | *50.74 FS  |
| 19  | 1   |          | *EMBLEM ,SYMBOL                 | Necessary         | 33.74 FS   | *33.74 FS  |
| 20  | 1   |          | *EMBLEM ,SYMBOL                 | Necessary         | 37.48 FS   | *37.48 FS  |
| 21  | 1   |          | *LAMP ASSY ,RR COMBIN           | Not Necessary     | 409.78 FS  | *- FS      |
| 22  | 1   |          | *LAMP ASSY ,RR COMBIN           | Not Necessary     | 409.78 FS  | *- FS      |
| 23  | 1   |          | *GREY METALLIC 2 REVERSE SENSOR | Shorted           | 131.92 FS  | *131.92 FS |

F=Franchise part. S=SpcNett.

|                           |                 |                 |
|---------------------------|-----------------|-----------------|
| <b>Total Parts (\$\$)</b> | <b>4,380.27</b> | <b>2,607.53</b> |
|---------------------------|-----------------|-----------------|

Report was unsubmitted during this print-out.



## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

| No                              | Particulars   | Lab.Type | Repairer's      | Amount          |
|---------------------------------|---|----------|-----------------|-----------------|
| <b>Labour Items</b>             |   |          |                 |                 |
| 1                               | DRILL HOLE & INSTALL REAR REVERSE SENSOR  | New      | 154.00          | 154.00          |
| 2                               | CHECK LIGHTING & CONDUCT WATER LEAK TEST  | New      | 154.00          | 154.00          |
| 3                               | SEALANT -BOOTLID ,REAR END PANEL  | New      | 160.00          | 80.00           |
| 4                               | REMOVE & INSTALL BOOTLID CARPET ,GARNISH AND TRIMMI TO ASSIST REPAIR                        | New      | 308.00          | 308.00          |
| 5                               | REPLACE REAR BUMPER ,REAR END PANEL ,ETC<br>STRAIGHTEN & ALIGN REAR ACCIDENT AFFECTED AREAS | New      | 3,080.00        | 2,464.00        |
| 6                               | RESPRAY JOB ON REAR ACCIDENT AFFECTED AREAS   | New      | 2,530.00        | 2,024.00        |
| <b>Gross Labour Cost (\$\$)</b> |   |          | <b>6,386.00</b> | <b>5,184.00</b> |

Report was unsubmitted during this print-out.

< END OF ESTIMATES >