
ずれない ないかい ひかい REF: C83 C1118005002 ASS. REC. BY: ASSIGNMENT (Office) From (Person): (IN) Estimated Cost: Bill to: OD HTP WS+TP RES / OD RES / EVA / INV / MV / CS Insured: SIK 2234 C To Inspect Vehicle No: Tel: 6748 1141 at Workshop m/s Claim No: SNM18 001382CO2 Policy No: Sum Insured: Excess: D.O.A. 05 03 2018 Make of Veh: (Client's Record) CA / REV / REP. / REV 24 HRS wp) H.O.D. Endorsement: Date/Time: 9:20am 16/3/18 Person Contacted: Wayne Vehicle IN OUT Action/Instruction (X) Estimate Date/Time SIL 95911-08/108/1002/973/Rlvbn2 D.O.A: 12/11/16 SK 2234C-X


(08/1.1/13) wef	
ASS. REC. BY: Mercus	C+1/
ASS	SIGNMENT
From: Date:	Veh No: SJL 95941 Yr Regn: 14 08
Estimated Cost:	Type: M.Carl M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
OD TE I WS / TP RES / OD RES / EVA / INV / MV	Truck / Trailer or
To Inspect Vehicle No:	Make: 1042 le VW C.C 1497
at Workshop m/s	Colour A/C: Insured / Std / NI / NA
of	Sp.Reading 2370,7 T/Radio: Insured / Std / NI / NA
Insured:	Eng/No:
Policy No.	C/NO: MROS3HY93050f49f1-
Claims No.	Gen. Cond: Gred / Fair / Poor / Burnt
Sum Insured: Excess:	Steering: Inorder / Jammed / Leaked / Burnt or
(Client's Record)	Brake: Interior Jammed / Leaked / Burnt or
Make of Veh:	Modi: Nil S/Rim / STD A/Rim or
· · · · · ·	Tyre Size: F: [
(Policy Condition)	R:
Remark: The veh had commenced its N/S O/S	BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
repair at the time of inspection.	TOYO/YOKO or hifly
Bal. or Market Value:	Front Rear Rear
IDAC Accident Rport: Consistent? : Yes or No	R/Bal mm R/Bal mm
GIA / PR Seen: Consistent? : Yes or No	L/Bal. 6 mm L/Bal. 6 mm
Est. Repairs: days Res.: Yes or No	D.O.A. S/3/18 D.O.I. 19/3/18
Lum Sum: % 3 Val.: Yes or No	Survey held at
CA / REV / REP. / 24 HRS	Des. of Damages : Frt / Rear / O/S / N/S / U/C / Roofton or
Date: Person Contacted: Vehicle: IN / OUT	Rear NS & RP.
Date / Time Action / Instruction	The U/C / Chassis frame / Body Structure affected due to collision.
Ers No settler. LIA	648 5-
	4
16-6/ Repair Estima	e ; 3\$ 7000 - 8000
3 0 K	L I.
19/4 Rubnit PRR report.	* 3 days
Date/Time, File Pass to? : Preli. Report	Days Of Repair:
4)	
Date/Time, File Return to?	Survey Fee: 190
2) Add Fee:	
	: Interview (\$) Photos
Report Format: PRO	: Tech. Invs (\$) Others
Lump Sum / I.B.I: (\$)	:Weekend (\$
	TOTAL

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars Owner ID Type: **Business** 9206C Owner ID: Vehicle Details Vehicle No.: SJL9594L Vehicle to be Exported: Yes Intended De-registration Date: 19 Mar 2018 Vehicle Make: TOYOTA Vehicle Model: **VIOSE AUTO** Primary Colour: Silver 2008 Manufacturing Year: 1NZX815387 Engine No.: Chassis No.: MR053HY9305084985 Maximum Power Output: 80.0 kW (107 bhp) \$11,834.00 Open Market Value: 17 Dec 2008 **Original Registration Date:** First Registration Date: 17 Dec 2008 **Transfer Count:** 1 Actual ARF Paid: \$11,834.00 Intended PARF Rebate Details PARF Eligibility: Yes PARF Eligibility Expiry Date: 16 Dec 2018 PARF Rebate Amount: \$5,917.00 Intended COE Rebate Details COE Expiry Date: 16 Dec 2018 COE Category: A - Car (1600cc & below) COE Period(Years): 10 QP Paid: \$7,721.00 **COE** Rebate Amount: \$571.00 \$6,488.00 **Total Rebate Amount:**

The information contained herein is correct as at 19 Mar 2018





Your NCD will be affected due to late reporting Actual e-Filling Submission Date & Time: 13/03/2018 16:20

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

- 1. Please report correctly the details of the accident to speed up the claims process.
- 2. This Form must be completed by the Policyholder and/or the Authorised Driver.
- 3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or witholding of material facts may allow insurance companies to repudiate policy ability.
- 4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
- 5. Any false reporting may be referred to the Police for investigation.
- 6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
- 7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

	ACCIDENT STATEMENT
Date Of Report	13/03/2018 16:08
Date Of Accident	05/03/2018 21:15
Exact Location Of Accident	TAMPINES AVE 5 SLIP RD - TUAS
Country/State of Loss	SINGAPORE
	DETAILS OF OWN VEHICLE

	DL	I AILS OF	JAAIA AFLIICEE
Vehicle Registration Number	S	SJL9594L	

Vehicle Registration Number

Insured/Policyholder

Name Of Registered Owner

Co Reg No

Email Address

Mobile Phone No

Alternative Phone No

Vehicle Particulars

Manufacturer

Model

Exact Purpose for which vehicle was being used at time of accident

Are you claiming under your own insurance policy

for repair to your vehicle?

If No, Please state action to be taken

Vehicle Category

Insurance Company

Name of Insurance Company

Type Of Coverage Fleet Policy

Policy Number

Cover Note Number

Driver

Name of Driver

NRIC No Date Of Birth Occupation

Date Of Driving Pass Driving Experience

Gender Mobile Number

Fax Number Contact Number

EMail Address

TOYOTA

KEN JIE CARS 53339206C

OFFICE-85806762

KENSONG23@GMAIL.COM

VIOS

THIRD PARTY

PRIVATE HIRE

NTUC INCOME INSURANCE CO-OPERATIVE LTD

THIRD PARTY

NO

5091995537

LIM CHENG CHIAP

S9007755D 04/03/1990 **OUTDOOR** 29/05/2012

MALE

5 YEARS AND 9 MONTHS

(LOCAL) +65-90175270

KENSONG23@GMAIL.COM

Page 1 of 33

DETAILS OF OTHER VEHICLE PROPERTY 2

Vehicle Registration Number

Vehicle Make/Model/Colour

Details Of Properties

Vehicle Category

Name of Driver

NRIC/Passport Number

Contact Number

Address

Postcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

SGZ266E

PRIVATE CAR


NA


NA


NΑ

SKETCH PLAN


C		B		A		
					egend SGZZLGE	
					SJL9594 L	
DESCRIBE CIRCUMSTANCES OF	THE ACCIDENT				SJK2234C	
I was driving	on 5/3/2	cl8 at 1	2115, ente			1
PIE (Tuas) along Ta	mpines Alen	ue 5 whe	n car A	(SG726E)	slowed	
down and halt	and I	did the	Same Slow	ved down	and halt.	
Out of a sudden,	a loud	bane from	my rear	from (iar C(SSK223H	
knocked anto me.	My vehicl	e inch	forward	and hif	onto	
(ar A (SGZ4GE).						
				-		
PECLARATION		***************************************				
We declare the foregoins perticulars	are true in every ri	espect.				
olicyholder's Signature ate & Time:	Driver's Signature (if driver is not the Date & Time:		Name	rting Centre Personre: FIN No.:	nel's Signature	




































Merimen e-Claims Page 1 of 1

...CLAIM SUBFOLDER...(Pending for Survey Report)

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt		Adj S	Submitted	Ins Auth'ed	Status	
Main	15 Mar 2018		15 Mar 2018 16:38 Edit Adj Rpt	S\$0.00 Edit Es	timates	S\$0. Vie	w Rpt		Pending Report Cancel C	for Survey ase
	Main	R	eference		laim Deta	ills		Docume	ents	Show All
CLAIM SU	BFOLDER DE	TAILS					[Created	by insurer]	• • • • • • • • • • • • • • • • • • • •	
Insured:	-, Co. Re	g. No.: -								
Main Claimant:	KEN JIE C	ARS								
Vehicle Reg No.:	^{3.} SJL9594	IL			Date of L			3 00:00 - :59 ns and 16 Day	s From LTA Reg C	ate (Man Yr)]
Claim Type	: TP/SNN	418D01382C02			Policy/Co Note No.:		DMHCSN17	18221700		
Vehicle Reg No. (Insured):	SJK22340				Policy No (Claimant					
			· · · · · · · · · · · · · · · · · · ·	w	Excess:		S\$0.00			
Repairer:	Sat Motor	's (HQ) 24 Defu L	ane 12, 539131 Def	u Lane - Te	el:					
Handling Insurer:			(Singapore) Pte. Lt	,				·		
Adjuster:	LKK Auto	Consultants Pte	Ltd (HQ) - Tel: 62!	56-3561	. [Handled	by XI	ING GUO Q	IANG] [Fii	nai Rpt due 26	5/03/2018]
Adj Asg. Remarks:	NO EST, C	ASE W/O SJE.								
ASSOCIA	TED MAIL RE	CEIVED							View All Com	pose Case Mail
There are r	no mail for this	case.								· · · · · · · · · · · · · · · · · · ·
ALL ASSO	CIATED TAS	KS⊟				V	iew All S	earch Tasks	Create New Task	Complete
Due Dat	e Priority	Type Task	Group Subject	t Hand	ier As	signe	ed By	Completed C	n Created	On Done

Claim Documents

*SJL9594L (SNM18D01382C02)
[SJK2234C]
TP
KEN JIE CARS
Mar 5 2018 12:00AM
[-]
Sat Motors

Up	load Documents Up	oload Photos Compose New Letter	View 🔽	ew in Brows	er 🗸
Pho	tos/Images		3 per pag	e 🗸	4
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	t	humbnail	Print
1	19/04/18 09:54	General View	0	Load PDF	
					······
Doc	umentation		1 per pag	e 🗸	✓
No	Finalized On	China Taiping Insurance (Singapore) Pte. Ltd. (HQ)	T	humbnail	Print
1	15/03/18 16:38	PRS	0	Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST	Reset Save Print
There are no document checklists configured.	
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)	
	^
	~
Show Remarks To: Handling Insurer Note: Remarks are private unless you show it to other parties.	

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No:

CS3/CTI18005002/UD3E2

Date:

19/04/2018

REFERENCE

Handling Insurer: (C)

China Taiping Insurance (Singapore) Pte. Ltd.

Policy No:

DMHCSN1718221700

Claimant Vehicle

SJL9594L

Insured Vehicle No :

SJK2234C

Date of Loss:

05/03/2018

Nature of Claim: TP

Claim No:

SNM18D01382C02

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:

No:

SJL9594L

Make & Model:

TOYOTA VIOS, 1.5 (A)

Engine No:

1NZX815387

237807 km

Reg. Date:

17/12/2008 (Man. Year: 2008)

Chassis No: Odometer: MR053HY9305084985

Colour: Engine Capacity: Silver 1497 cc

Market Value/New Car Price: N/A

· N/A

Sum Insured (S\$):

Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:

Steering (Serviceable):

Yes Footbrake (Serviceable):

Yes

Handbrake (Serviceable):

Yes Engine Modification:

No Pre-accident Condition:

1 65

CONDITION OF TYRES

Front Tyre Size:

185/60 R15

Rear Tyre Size:

185/60 R15

Front Left Side: Front Right Side:

HIFLY 6 mm

Rear Left Side: Rear Right Side: Bridgestone 6 mm Bridgestone 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Nett Amount (S\$)	0.00	0.00	0.00	

INSPECTION

Date of Assignment:

15/03/2018

Date Inspected:

19/03/2018

Inspected At:

Sat Motors (HQ)

24 Defu Lane 12 Singapore 539131

Estimated Period of Repair:

7.0 days

Adjuster: XING GUO QIANG

Manager:

Nivitha Govindasamy

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

Adjuster Report Page 2 of 5 https://singapore.merimen.com/claims/index.cfm?fusebox=MTRadjuster&fuseaction=gen_... 19/4/2018 Adjuster Report Page 3 of 5

A)THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.

B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION.

THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE.

C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.

THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$5,000.00 -\$6,000.00

Adjuster Report Page 4 of 5

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 19 Apr 2018)

Parts: 143 TOYOTA VIOS 1.5 (A) (Catalogue:Merimen Singapore 1.0)

Labour: Repairer's (Price-denominated Standard List)

Print Code: (Unsubmitted, no print-code for SJL9594L)

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page

numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

There are no new parts selected.

Report was unsubmitted during this print-out.

Adjuster Report Page 5 of 5

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.

< END OF ESTIMATES >