

ASS. REC. BY:

REF: CS3/FWD18005009/Gd3⁶²

Special Instruction:

Surveyor: GO

ASSIGNMENT (Office)

From (Person): Clara Li

of FWD

Date/Time: 15/3/18 @ 6:11pm

Estimated Cost: _____ Bill to: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: SKV 6177M

Insured: SKH 1336 C

at Workshop m/s Sin Seng Hong Spray Painting

Tel: 9627 8521

of 3022A # 01-53 Ubi Road 1

Policy No: _____ Claim No: 120180003203

Sum Insured: _____ Excess: _____

Make of Veh: _____ D.O.A. 9/3/18
(Client's Record)

CA / REV / REP. / REV 24 HRS 'wp'

H.O.D. Endorsement: _____

Date/Time: 9:25am @ 16/3/18 Person Contacted: andy

Vehicle IN/OUT

Date/Time	Action/Instruction (X) Estimate
	SKV 6177M - X
	SKH 1336M - X

PRS
XPR

REF: FWD

ASSIGNMENT

(-2018)

From: _____ Date: 16/3/18

Estimated Cost: _____

OD TP WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No: SKV 6177M

at Workshop m/s: Sin & ng Hong Spray Painting

of 3022A # 01-53, Ubi Rd 1

Insured: _____

Policy No. _____

Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record) Andy @ 9627 8521

Make of Veh: _____

Veh No: SKV 6177M Yr Regn: 30 Jun 2008

Type: Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or _____

Make: chevrolet AVEO c.c. 1399

Colour: yellow A/C: Insured / Std / NI / NA

Sp. Reading: 106019 T/Radio: Insured / Std / NI / NA

Eng/No: _____


C/No: KLISA48719-B 279503

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or



(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value: \$8600

IDAC Accident Rpt: _____ Consistent?: Yes or No

GIA / PR Seen: _____ Consistent?: Yes or No

Est. Repairs: _____ days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS ^{1wp}

Date: _____ Person Contacted: _____ Vehicle: IN / OUT

Tyre Size: F: 185/60R14

R: 11

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or westlake.

Front	Rear
R/Bal. 5 mm	R/Bal. 5 mm
L/Bal. 5 mm	L/Bal. 5 mm
D.O.A. _____	D.O.I. 16-03-18

Survey held at: w/s 4:45pm

Des. of Damages: Frt / Rear / O/S / N/S / UIC / Rooftop or

The UIC / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

87000 - \$9,200

* Repair Estimate: \$25,000 - 26,000

* 8 days

21/6/18 submit PRS report.

[Signature]

18/6/2018

Date/Time File Pass to? : Preli. Report

1) : Final Report

Days Of Repair: 8

Resurvey No. of Trip: _____

Survey Fee:	
Transportation:	
_____ \$ + RE _____ \$	
Photos:	
Others:	
TOTAL:	

Date/Time File Return to? _____

2) _____

Add Fee: Site Insp (\$)

Interview (\$)

Tech. Invs (\$)

Weekend (\$)

Report Format: PRS

Lump Sum / I.B.I: (\$)



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
FWD SINGAPORE PTE LTD		Ref : CS3/FWD18005009/Gd3	
6 TEMASEK BOULEVARD #18-01 SUNTEC TOWER 4SINGAPORE 038986		Date : 16-03-2018	
		Code : FWD	
1. Policy Particulars :- (THIRD PARTY CLAIM)			
Insured Veh.	SKH 1336M	Veh. Inspected	SKV 6177M
Policy No.	1201800003203	Coverage (\$)	0.00
Claim No.	TCMG/SKV6177M/0318/SSH	Excess (\$)	0.00
Assign From	CLARA LI	Assign Date	16/03/2018
2. Vehicle Particulars & Condition			
Make & Model		c.c	0
Engine No.	HIDDEN	Year of Reg.	
Chassis No.		Colour	
Odometer	-	Steering	
Brakes		Modification	
General			
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm
4. Description of Damages			
5. General Information			
Accident Date	09/03/2018	Inspection Date	16/03/2018
Survey held at	SIN SENG HONG SPRAY PAINTING & SERVICES BLK 3022A UBI ROAD 1 #01-53 . SINGAPORE 408716		
5a. Remarks			
A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.			

Nivitha (LKK Auto)

From: motorclaims.sg@fwd.com
Sent: Thursday, 15 March 2018 6:11 PM
To: assignments@lkkauto.com; admin-a@lkkauto.com; admin-d@lkkauto.com; sur@lkkauto.com
Subject: FW: [PRS] Your Ref: TCMG/SKV6177M/0318/SSH Our Ref: 1201800003203
Attachments: 20180315174043710.pdf

Hi LKK team,

Please refer to the email below and liaise with TP repairer for PRS.

Please create the case in Merimen.

Thank you.

Kind Regards
Clara Li
Senior Executive, Claims

FWD Singapore Pte. Ltd.
6 Temasek Boulevard, #18-01 Suntec Tower Four, Singapore 038986

T (65) 6727 5722
E clara.li@fwd.com
W fwd.com.sg



	Endowment Plan Get the biggest guaranteed return for a 3 year plan available online. Limited time offer!		2.02% p.a. fwd.com.sg save now
---	--	--	---

From: Motor Claims SG - SG Common
Sent: Thursday, 15 March, 2018 6:11 PM
To: 'Ling Leong Hui'
Cc: mdmling@tcmg.com.sg
Subject: RE: [PRS] Your Ref: TCMG/SKV6177M/0318/SSH Our Ref: 1201800003203

WITHOUT PREJUDICE

Dear Mr Ling,

We regret that we are objecting to your proposed list of surveyors.

We will be appointing, M/s LKK AUTO CONSULTANTS PTE LTD, to conduct the pre-repair survey (PRS) on your

client's vehicle, SKV6177M. We seek your cooperation to inform your client's workshop to arrange the vehicle readily for dismantling with repair estimates during the pre-repair survey.

If there is a change in your client's workshop, please inform us soon. We reserve our rights for re-inspection.

****Please note that we do not accept fax. Hence, please send in any correspondences related to Motor Claims via e-mail to motorclaims.sg@fwd.com. Thank you.***

Kind Regards
Clara Li
Senior Executive, Claims

FWD Singapore Pte. Ltd.
6 Temasek Boulevard, #18-01 Suntec Tower Four, Singapore 038986

T (65) 6727 5722
E clara.li@fwd.com
W fwd.com.sg



FWD
insurance

Endowment Plan
Get the biggest guaranteed return for a 3 year plan available online.
Limited time offer!

2.02% p.a.
fwd.com.sg
save now

From: Ling Leong Hui [<mailto:lhling@tcmg.com.sg>]
Sent: Thursday, 15 March, 2018 5:58 PM
To: Motor Claims SG - SG Common
Cc: mdmling@tcmg.com.sg
Subject: RE: [Spam-pop3] [PRS] Your Ref: TCMG/SKV6177M/0318/SSH Our Ref: 1201800003203

WITHOUT PREJUDICE

Dear Sirs,

We refer to the above matter and to your mail of even date.

Our client is not agreeable to any of your appointed panel of surveyors as the Single Joint Expert.

Our client's panel of surveyors nominated as the Single Joint Expert is as attached.

Yours faithfully,

Ling Leong Hui
TOMMY CHOO MARK GO LLC

From: motorclaims.sg@fwd.com [mailto:motorclaims.sg@fwd.com]
Sent: Thursday, March 15, 2018 5:48 PM
To: lhling@tcmg.com.sg; mdmling@tcmg.com.sg
Subject: [Spam-pop3] [PRS] Your Ref: TCMG/SKV6177M/0318/SSH Our Ref: 1201800003203

WITHOUT PREJUDICE

Dear Sir/ Madam,

We refer to your letter dated 12 March of the PRI Notice of your client's vehicle SKV6177M.

Please find our panel surveyors as follows: -

1. LKK AUTO CONSULTANTS PTE LTD
2. INFINITI APPRAISAL SERVICE
3. AJAX INSPECTION SERVICES PTE LTD
4. Appraisals Associates Pte Ltd
5. VICOM Ltd

If you are not agreeable to any of the above, we reserve our rights to request for pre-repair inspection of your client's vehicle.

We look forward to receiving your reply.

Thank you.

**Please note that we do not accept fax. Hence, please send in any correspondences related to Motor Claims via e-mail to motorclaims.sg@fwd.com. Thank you.*

Kind Regards

Clara Li

Senior Executive, Claims

FWD Singapore Pte. Ltd.

6 Temasek Boulevard, #18-01 Suntec Tower Four, Singapore 038986

T (65) 6727 5722

E clara.li@fwd.com

W fwd.com.sg



FWD Insurance

Endowment Plan
Get the biggest guaranteed return for a 3 year plan available online.
Limited time offer!

2.02% p.a.
fwd.com.sg
save now

ATTENTION:

The email and any attachments transmitted with it are private and confidential and intended solely for the use of the individual or entity to whom they are addressed. If you have received this email in error, please notify the sender immediately and delete this email and any attachments from your system. You should not

use, disclose, copy or store this email and any attachments.

Messages and attachments are scanned for all viruses known. However, you are advised that you open any attachments at your own risk. If this message contains password-protected attachments, the files have NOT been scanned for viruses by our mail domain. Please always scan for viruses before opening any attachments.

ATTENTION:

The email and any attachments transmitted with it are private and confidential and intended solely for the use of the individual or entity to whom they are addressed. If you have received this email in error, please notify the sender immediately and delete this email and any attachments from your system. You should not use, disclose, copy or store this email and any attachments.

Messages and attachments are scanned for all viruses known. However, you are advised that you open any attachments at your own risk. If this message contains password-protected attachments, the files have NOT been scanned for viruses by our mail domain. Please always scan for viruses before opening any attachments.



65389850

TOMMY CHOO, MARK GO LLC

Advocates & Solicitors Commissioner For Oaths Notary Public
UEN NO : 201523418E
(a law corporation with limited liability)

151 CHIN SWEE ROAD #14-15/16
MANHATTAN HOUSE
SINGAPORE 169876
TEL : (65) 6532 2455
FAX : (65) 6538 9850 (Services of Court Documents By Fax Not Accepted)

EMAIL: lhling@tcmg.com.sg;mdmling@tcmg.com.sg
Our Ref: TCMG/SKV6177M/0318/SSH

Your Ref: SKH 1336 C

12 March 2018

M/S FWD SINGAPORE PTE LTD
6 Temasek Boulevard
#18-01
Suntec Tower 4
Singapore 038986

BY FAX NO. 6727 5799 ONLY

Attn: Motor Claims Department

Dear Sirs,

PRE-REPAIR INSPECTION NOTICE

We act for M/s Ally Car Rental Pte Ltd, the owner and/or driver of motor vehicle no. SKV 6177 M, which was involved in an accident along AYE towards CTE after Corporation Road on 9 March 2018 at 17:55 hrs.

We hereby give you **NOTICE** that we are claiming against your insured motor vehicle no. SKH 1336 C for damages and/or injuries, costs and disbursements as a result of your insured's negligence.

Kindly let us know if you wish to conduct a pre-repair inspection on our client's motor vehicle at M/s Sin Seng Hong Spray Painting & Service, (3022A #01-53, Ubi Road 1, Singapore 408716 – Andy Yeo @ 9627 8521).

If we do not hear from you within the next **two (2) working days**, we shall deem that you have waived the requirement for the pre-repair inspection.

Yours faithfully,



LING LEONG HUI (MR)

cc. M/s Sin Seng Hong Spray Painting & Svc
(Yref: SKV6177M)

BY E-MAIL ONLY

DIRECTOR : LING LEONG HUI

CONSULTANTS : TOMMY CHOO TUCK SOON
FOOTS LAWRENCE JAMES

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	10/03/2018 10:16
Date Of Accident	09/03/2018 17:55
Exact Location Of Accident	AYE (CTE) AFTER CORPORATION RD
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SKV6177M
Insured/Policyholder	
Name Of Registered Owner	ALLY CAR RENTAL PTE LTD
Co Reg No	201700606C
Email Address	SINSENGHONGSPRAY@HOTMAIL.COM
Mobile Phone No	(LOCAL) +65-87982721
Alternative Phone No	OFFICE-67422035

Vehicle Particulars

Manufacturer	CHEVROLET
Model	AVEO5-1.4 (A)
Exact Purpose for which vehicle was being used at time of accident	RENTAL USE
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE HIRE

Insurance Company

Name of Insurance Company	NTUC INCOME INSURANCE CO-OPERATIVE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	YES
Policy Number	5095279990
Cover Note Number	27/10/2017 - 29/06/2018

Driver

Name of Driver	TAN PANG KUAN JASON
NRIC No	S9029668Z
Date Of Birth	08/08/1990
Occupation	INDOOR
Date Of Driving Pass	24/02/2009
Driving Experience	9 YEARS AND 0 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-97324440
Fax Number	
Contact Number	
EEmail Address	JASONTPK@HOTMAIL.COM

Address	6 LIM AH PIN ROAD #04-03
Postcode	547822
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OTHER - HIRER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	SIDE SWIPE
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles involved in the accident	2
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

MY VEHICLE WAS TRAVELLING ALONG THE RIGHT LANE OF AYE(CTE) NEAR CORPORATION RD. VEHICLE B WAS IN FRONT OF MY VEHICLE. VEHICLE B CHANGED LANE TO THE SECOND RIGHT LANE. I PROCEED TO MOVE FORWARD ALONG THE RIGHT LANE. AS I WAS GOING STRAIGHT, VEHICLE B SUDDENLY SWERVE BACK TO THE RIGHT LANE AND HIT ONTO MY VEHICLE FRONT LEFT PORTION. MY VEHICLE WAS FURTHER PUSHED TO THE RIGHT SIDE AND HIT ONTO THE SIDE RAILINGS. NO ONE WAS INJURED.

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SKH1336C
Vehicle Make/Model/Colour	RENAULT
Details Of Properties	RIGHT PORTION
Vehicle Category	PRIVATE CAR
Name of Driver	YONG YAN KIT NICHOLAS
NRIC/Passport Number	S8629434F
Contact Number	
Address	BLK 77A REDHILL ROAD #02-24
Postcode	151077
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	1

Sketch Plan Pg. 1

RTUC Insurance Motor Service Centre
 Report No. MT _____ D.O.A. _____ Vehicle No. SLV61-DA7 Report Date: 3/10/2018 Report Time: 10:38 AM
 Make/Model: ANOS Reporting Type: P End Time: _____

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this form and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all Insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonable required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, law or court orders.



[Signature]
3/10/2018 10:38

Policyholder's Signature
Date & Time:

[Signature]


Driver's Signature (If driver is not the policyholder)
Date & Time:

3/10/2018 10:38

[Signature]
Reporting Centre Personnel's Signature
Name: Chan JunLiang
NRIC/ Fin No: 6990765

Sketch Plan Pg. 2

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

MY VEHICLE WAS TRAVELLING ALONG THE RIGHT LANE OF AYE(CTE) NEAR CORPORATION RD. VEHICLE B WAS IN FRONT OF MY VEHICLE. VEHICLE B CHANGED LANE TO THE SECOND RIGHT LANE. I PROCEEDED TO MOVE FORWARD ALONG THE RIGHT LANE. AS I WAS GOING STRAIGHT, VEHICLE B SUDDENLY SWERVE BACK TO THE RIGHT LANE AND HIT ONTO MY VEHICLE FRONT LEFT PORTION. MY VEHICLE WAS FURTHER PUSHED TO THE RIGHT SIDE AND HIT ONTO THE SIDE RAILINGS. NO ONE WAS INJURED.

DECLARATION


We declare the foregoing particulars are true in every respect.


 3/10/2018 10:38

Policyholder's Signature
 Date & Time:


 3/10/2018 10:38

Driver's Signature (If driver is not the policyholder)
 Date & Time:


 3/10/2018 10:38

Reporting Centre Personnel's Signature
 Name: Chen Junkiang
 NRJC/ Fin No: S990765

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Company
Owner ID:	0606C
Vehicle Details	
Vehicle No.:	SKV6177M
Vehicle to be Exported:	No
Intended De-registration Date:	20 Mar 2018
Vehicle Make:	CHEVROLET
Vehicle Model:	AVEO 1.4AT 5DR T255
Primary Colour:	Yellow
Manufacturing Year:	2008
Engine No.:	F14D36931031
Chassis No.:	KL1SA48719B279503
Maximum Power Output:	69.0 kW (92 bhp)
Open Market Value:	\$10,399.00
Original Registration Date:	30 Jun 2008
First Registration Date:	30 Jun 2008
Transfer Count:	2
Actual ARF Paid:	\$10,399.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	29 Jun 2018
PARF Rebate Amount:	\$5,199.00
Intended COE Rebate Details	
COE Expiry Date:	29 Jun 2018
COE Category:	A - Car (1600cc & below)
COE Period(Years):	10
QP Paid:	\$14,590.00
COE Rebate Amount:	\$401.00
Total Rebate Amount:	\$5,600.00

The information contained herein is correct as at 20 Mar 2018

OK

▶ aveo Used Vehicle List (2 vehicles)

Car Model	Price	Depreciation	Reg Date	Eng Cap	Mileage	Company	Availability
Chevrolet Aveo5 1.4M	\$8,500	-	29-Jul-2008	1,399 cc	125,000 km	Car Lingual	Available

Well Maintained Condition, No Repairs Required, Perfect For Short Term Drive. Flexible Loan Scheme Available! Please Feel Free To Call Our Friendly Sales Consultants Now For More Details.

Chevrolet Aveo5 1.4A	\$10,460	-	24-Jun-2008	1,399 cc	130,000 km		Available
-----------------------------	-----------------	---	-------------	----------	------------	--	------------------

Regularly Serviced E-TecII 16-valves In-line 4-cylinder Fuel Efficient Engine. Ease Of Handling, Economy 11 To 15km/l Ct~hw And Good Cargo Space. Water Pump And Timing Belt Replaced Last Year. New Fro...

Office No. - -

Joe - 90102502

sgCarMart is the number one car classifieds for parallel import cars, Toyota, Honda, Nissan, Mitsubishi & BMW. There are plenty of cars for sale, even for COE cars, OPC cars, vans, trucks, hybrid cars, sports cars or stationwagons. You can also buy from a car auction, look up car loans, low mileage cars, car brands, carpark rates & car insurance. We have new car dealers comprising parallel importers, authorised car dealers, and used car dealers on our site. Find new car price lists, new car launches and new car promotions, and also motoring advice, car reviews & car news on the latest models. Visit our partner sites for job openings for Singapore jobs, real estate properties for sale, mover, car performance parts, car discussion, forum discussion, commercial vehicle leasing & COE results.

© 2004-2018 sgCarMart. All rights reserved.

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	25 Jun 2018 13:11 Edit Reg		15 Mar 2018 00:00 Edit Adj Rpt	S\$0.00 Edit Estimates	S\$0.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS				[Created by adjuster]					
Insured:	-, Co. Reg. No.: -								
Main Claimant:	ALLY CAR RENTAL PTE LTD , Co. Reg. No.: 201700606C								
Vehicle Reg. No.:	SKV6177M	Date of Loss:	09/03/2018 17:00 - :59 [116 Months and 9 Days From LTA Reg Date (Man Yr)]						
Claim Type:	TP	Policy/Cover Note No.:							
Vehicle Reg. No. (Insured):	SKH1336C	Policy No. (Claimant):							
		Excess:							
Repairer:	Sin Seng Hong Spray Painting & Services (HQ) Blk 3022A Ubi Road 1, #01-53, 408716 Ubi - Tel:								
Handling Insurer:	FWD Singapore Pte. Ltd. (HQ) - Tel: 6727 5700								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by XING GUO QIANG] ... [Final Rpt due 04/07/2018]								
ASSOCIATED MAIL RECEIVED				View All Compose Case Mail					
There are no mail for this case.									
ALL ASSOCIATED TASKS <input type="checkbox"/>				View All Search Tasks Create New Task Complete					
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

***SKV6177M**
[SKH1336C]
TP
ALLY CAR RENTAL PTE LTD
Mar 9 2018 5:00PM
[-]
Sin Seng Hong Spray Painting & Services

Upload Documents Upload Photos Compose New Letter			View <input type="button" value="View in Browser"/>
Photos/Images			3 per page <input type="button" value="v"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail <input type="button" value="Print"/>
1	25/06/18 12:15	General View	<input type="button" value="1"/> Load JPG <input checked="" type="checkbox"/>
2	25/06/18 12:15	General View	<input type="button" value="1"/> Load JPG <input checked="" type="checkbox"/>
3	25/06/18 12:15	General View	<input type="button" value="1"/> Load JPG <input checked="" type="checkbox"/>
4	25/06/18 12:15	General View	<input type="button" value="1"/> Load JPG <input checked="" type="checkbox"/>
5	25/06/18 12:15	General View	<input type="button" value="1"/> Load JPG <input checked="" type="checkbox"/>
6	25/06/18 12:15	General View	<input type="button" value="1"/> Load JPG <input checked="" type="checkbox"/>
7	25/06/18 12:15	General View	<input type="button" value="1"/> Load JPG <input checked="" type="checkbox"/>
8	25/06/18 12:15	General View	<input type="button" value="1"/> Load JPG <input checked="" type="checkbox"/>
9	25/06/18 12:15	General View	<input type="button" value="1"/> Load JPG <input checked="" type="checkbox"/>
10	25/06/18 12:15	General View	<input type="button" value="1"/> Load JPG <input checked="" type="checkbox"/>
11	25/06/18 12:15	General View	<input type="button" value="1"/> Load JPG <input checked="" type="checkbox"/>
12	25/06/18 12:15	General View	<input type="button" value="1"/> Load JPG <input checked="" type="checkbox"/>
13	25/06/18 12:15	General View	<input type="button" value="1"/> Load JPG <input checked="" type="checkbox"/>
14	25/06/18 12:15	General View	<input type="button" value="1"/> Load JPG <input checked="" type="checkbox"/>
15	25/06/18 12:15	General View	<input type="button" value="1"/> Load JPG <input checked="" type="checkbox"/>
16	25/06/18 12:15	General View	<input type="button" value="1"/> Load JPG <input checked="" type="checkbox"/>
17	25/06/18 12:15	General View	<input type="button" value="1"/> Load JPG <input checked="" type="checkbox"/>
18	25/06/18 12:15	General View	<input type="button" value="1"/> Load JPG <input checked="" type="checkbox"/>
19	25/06/18 12:15	General View	<input type="button" value="1"/> Load JPG <input checked="" type="checkbox"/>
20	25/06/18 12:15	General View	<input type="button" value="1"/> Load JPG <input checked="" type="checkbox"/>
21	25/06/18 12:15	General View	<input type="button" value="1"/> Load JPG <input checked="" type="checkbox"/>
22	25/06/18 12:15	General View	<input type="button" value="1"/> Load JPG <input checked="" type="checkbox"/>
23	25/06/18 12:15	General View	<input type="button" value="1"/> Load JPG <input checked="" type="checkbox"/>
24	25/06/18 12:15	General View	<input type="button" value="1"/> Load JPG <input checked="" type="checkbox"/>
25	25/06/18 12:15	General View	<input type="button" value="1"/> Load JPG <input checked="" type="checkbox"/>
26	25/06/18 12:15	General View	<input type="button" value="1"/> Load JPG <input checked="" type="checkbox"/>
27	25/06/18 12:15	General View	<input type="button" value="1"/> Load JPG <input checked="" type="checkbox"/>
28	25/06/18 12:15	General View	<input type="button" value="1"/> Load JPG <input checked="" type="checkbox"/>
29	25/06/18 12:15	General View	<input type="button" value="1"/> Load JPG <input checked="" type="checkbox"/>
30	25/06/18 12:15	General View	<input type="button" value="1"/> Load JPG <input checked="" type="checkbox"/>
31	25/06/18 12:15	General View	<input type="button" value="1"/> Load JPG <input checked="" type="checkbox"/>
32	25/06/18 12:15	General View	<input type="button" value="1"/> Load JPG <input checked="" type="checkbox"/>
33	25/06/18 12:15	General View	<input type="button" value="1"/> Load JPG <input checked="" type="checkbox"/>
34	25/06/18 12:15	General View	<input type="button" value="1"/> Load JPG <input checked="" type="checkbox"/>
35	25/06/18 12:15	General View	<input type="button" value="1"/> Load JPG <input checked="" type="checkbox"/>

Photos/Images				
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail Print
36	25/06/18 12:15	General View		Load JPG
37	25/06/18 12:15	General View		Load JPG
38	25/06/18 12:15	General View		Load JPG
39	25/06/18 12:15	General View		Load JPG
40	25/06/18 12:15	General View		Load JPG
41	25/06/18 12:15	General View		Load JPG
42	25/06/18 12:15	General View		Load JPG
43	25/06/18 12:15	General View		Load JPG

Documents Checklist

DOCUMENTS CHECKLIST

There are no document checklists configured.

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)

Show Remarks To: Handling Insurer

Note: Remarks are private unless you show it to other parties.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS3/FWD18005009/GD3S2
Date: 25/06/2018

REFERENCE

Handling Insurer:	FWD Singapore Pte. Ltd.	Policy No:	
Claimant Vehicle No :	SKV6177M	Insured Vehicle No :	SKH1336C
Date of Loss:	09/03/2018	Nature of Claim:	TP
		Claim No:	N/A

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SKV6177M	Engine No:	F14D36931031
Make & Model:	CHEVROLET AVEO5, 1.4 (A)	Chassis No:	KL1SA48719B279503
Reg. Date:	30/06/2008 (Man. Year: 2008)	Odometer:	106019 km
Colour:	Yellow		
Engine Capacity:	1399 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Good	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	185/60R14	Rear Tyre Size:	185/60R14
Front Left Side:	West Lake 5 mm	Rear Left Side:	West Lake 5 mm
Front Right Side:	West Lake 5 mm	Rear Right Side:	West Lake 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Nett Amount (S\$)	0.00	0.00	0.00	

INSPECTION

Date of Assignment:	15/03/2018	
Date Inspected:	16/03/2018	Inspected At: Sin Seng Hong Spray Painting & Services (HQ) Blk 3022A Ubi Road 1, #01-53 Singapore 408716
Estimated Period of Repair:	8.0 days	

Adjuster: XING GUO QIANG

Manager: Nivitha Govindasamy

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

- A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
- B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION.
THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE.
- C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.

THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$8,000.00 - \$9,800.00

REPAIR DETAILS

Reference

Part Source: MRM-SG	Version: 1.0 (Last Synchronised: 25 Jun 2018)
Parts: 144	CHEVROLET AVEO5 1.4 (A) (Catalogue:Merimen Singapore 1.0)
Labour: Repairer's	(Price-denominated Standard List)
Print Code: (Unsubmitted, no print-code for SKV6177M)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

There are no new parts selected.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.

< END OF ESTIMATES >