CHUNNI MOTOR WORK PTE LTD

REPAIR ESTIMATE*

VEHICLE NO: SHC 8101D

DATE: 14.03.2018

MAKE

:

TEL: 6542 5119

MODEL: HYUNDAI i40	FAX	: 6542 6039	INDIA
--------------------	-----	-------------	-------

	· III UNDAI 140	FAA	r -	72 0039	IINL		٦.
Qty	Parts Description/ Labour	Type	U	nit Price		Amount	╛
	Bonnet		i		\$	1,526.00	
	Bonnet Hinge (LH/RH)		\$	91.30	\$	182.60	l
	Bonnet Lock				\$	50.90	
	Radiator Grille				\$	294.35	
	Radiator Grille H Emblem				\$	113.65	
	Front Bumper Cover				\$	562.30	l
	Front Bumper Sponge				\$	142.20	
	Front Bumper Reinforcement				\$	526.10	
	Front Bumper Centre Grille				\$	178.60	1
	Front Bumper Bracket Top (LH/RH)		\$	22.40	\$	44.80	l
	Front Bumper Bracket (LH/RH)		\$	24.60	\$	49.20	
	Front Bumper Retainer Mounting		\$	9.20	\$	18.40	
	Headlamp Support Top Cover				\$	398.00	
	Headlamp Support Panel Assy				\$	1,067.50	Ì
	Headlamp (LH/RH)		\$	1,388.00	\$	2,776.00	l
	Radiator		*	1,500.00	\$	850.20	
	Radiator Fan Blade, Cowling, Motor Assy				\$	792.95	1
	Radiator Bracket (RH/LH)		\$	6.50	\$	13.00	
	Radiator Guard		\$	35.00	\$	70.00	
	Horn Unit (LH/RH)		\$	86.75	\$	173.50	1
	Aircon Condenser		J	80.75	\$	1,137.35	ŀ
	Inter Cooler				\$	921.90	
					1		l
	Inter Cooler Mounting (2 PCS)				\$	25.90	
	SUB TOTAL				\$	11,915.40	1
	LESS 20%				\$	2,383.08	
	DISCOUNTED TOTAL				\$	9,532.32]
	Front Number Plate				\$	25.00	
	Front No Plate Trim Cover				\$	30.00	1
	Tion two riate fram cover				"	50.00	ľ
					\$	55.00	1
	Labour Charge				=		
	Panel Beating				\$	1,000.00	
	Spray Painting Charge				\$	400.00	1
	Wiring Charge				\$	50.00	1
	Tuff Kote				\$	50.00	-
	Towing Charge				\$	50.00	-
	Remove/Refix Aircon & Refill Gas				\$	150.00	
	Tomovo Rolly I mooil & Rollin Gas				"	150.00	
	TOTAL LABOUR				\$	1,700.00	1
			1			-	7

SHC 8101D

	Danda Danda (17.1)	Tr	жт	de Dede		Amount	
Qty	Parts Description/ Labour	Type	Ur	nit Price		Amount	
	Boot Lid				\$	1,681.40	
	Boot Lid Rubber		ď	178.10	\$	115.80	
	Boot Lid Hinge (LH/RH)		\$	1/8.10	\$	356.20	
	Boot Lid Lock Upper				\$	137.90	
	Boot Lid Lock Lower				\$	31.70	
	Boot Lid 'H' Emblem				\$	27.20	
	Boot Lid CRDI Plate		6	556 90	\$	41.00	
	Boot Lid Lamp (LH/RH)		\$	556.80	\$	1,113.60	
	Boot Lid Trimboard				\$	172.70	
	Boot Lid Trimboard Clips (10pcs)				\$	11.00	
	Bootlid Moulding				\$	85.00	
	Bootlid i40 Emblem				\$	41.00	
	Bootlid Lower Garnish				\$	398.00	
	Rear Bumper				\$	603.60	
	Rear Bumper Reinforcement		_	100.00	\$	504.35	
	Rear Bumper Reinforcement Bracket (LH/RH)		\$	180.00	\$	360.00	
	Rear Bumper Clip 10 pcs			40.00	\$	22.00	
	Rear Bumper Bracket (LH/RH)		\$	49.00	\$	98.00	<u> </u>
	Rear Bumper Sponge				\$	143.40	
	Rear Bumper Under Cover				\$	225.00	
	Rear Bumper Reflector Lamp (RH)				\$	32.00	
	Tail Lamp (LH/RH)		\$	565.60	\$	1,131.20	
	Rear Panel				\$	592.30	
	Rear Panel Garnish				\$	57.70	
	Rear Panel Lower Panel				\$	495.50	
	Exhaust Pipe Insulator		\$	58.55	\$	117.10	
	Exhaust Silencer		\$	954.00	\$	1,908.00	
	Exhaust Pipe Hanger		\$	58.55	\$	117.10	
	Exhaust Pipe Centre				\$	1,150.30	
					<u> </u>		ļ
	SUB TOTAL				l .	11,770.05	
	LESS 20%				\$	2,354.01	-
	DISCOUNTED TOTAL				\$	9,416.04	
	D AND COLUMN COLUMN				_	20.00	NT 44
	Boot Lid Comfort Logo & Tel No. Sticker				\$	30.00	1
	Rear Bumper Reverse Sensor				\$		Nett
	Rear Bumper Rubber Mat				\$	50.00	Nett
]			_	215 50	1
			1		\$	215.70	1
	I shawy Charge						
	Labour Charge				0	1 000 00	
	Panel Beating				\$	1,000.00	
	Spray Painting Charge				\$	800.00	
	Wiring Charge				\$	50.00	
	Tuff Kote				\$	50.00	
	Remove/Refix Reverse Sensor				\$	120.00	
	Remove/Refix Exhaust Pipe				\$	360.00	
						2 200 00	1
	TOTAL LABOUR				\$	2,380.00	1
	DOWN A AND MORE A				6	22 200 07	-
	ESTIMATE TOTAL	·I	1		1 3	23,299.06	1

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

- 1. Please report correctly the details of the accident to speed up the claims process.
- 2. This Form must be completed by the Policyholder and/or the Authorised Driver.
- 3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or witholding of material facts may allow insurance companies to repudiate policy ability.
- 4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
- 5. Any false reporting may be referred to the Police for investigation.
- 6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
- 7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available

	ACCIDENT STATEMENT	
Date Of Report	14/03/2018 11:41	
Date Of Accident	13/03/2018 18:10	
Exact Location Of Accident	ALONG MCE TOWARD ECP	
Country/State of Loss	SINGAPORE	

DETAILS OF O	WN VEHICLE	

Vehicle Registration Number

SHC8101D

Insured/Policyholder

Name Of Registered Owner

COMFORT TRANSPORTATION PTE LTD

Co Reg No 199303821R

Email Address

FLEETSAFETY@CDGTAXI.COM.SG

Mobile Phone No

Alternative Phone No

OFFICE-65508768

Vehicle Particulars

Manufacturer HYUNDAI Model 140

Exact Purpose for which vehicle was being used at

time of accident

Are you claiming under your own insurance policy

for repair to your vehicle?

NO

If No, Please state action to be taken

THIRD PARTY

Vehicle Category

TAXI

Insurance Company

Name of Insurance Company

INDIA INTERNATIONAL INSURANCE PTE LTD

Type Of Coverage THIRD PARTY FIRE AND/OR THEFT

Fleet Policy YES

Policy Number MCOM0015

Cover Note Number

Driver

Name of Driver TEO YONG HUAT

Passport No/FIN S0920963H
Date Of Birth 03/05/1949
Occupation OUTDOOR
Date Of Driving Pass 06/03/1990

Driving Experience 28 YEARS AND 0 MONTHS

Gender MALE

Mobile Number Fax Number

Contact Number

EMail Address NOEMAIL

Address BLK 513 WEST COAST ROAD #02-485

Postcode 120513

Was driver an employee of the Insured's Company NO

If No, Relationship of the Driver with the Insured OTHER - TAXI DRIVER

Vehicle Registration Number of Driver's Own

Vehicle

Insurance Company of Driver's Own Vehicle

General Information of the Accident

CHAIN COLLISION Type Of Accident

CLEAR Weather Conditions Road Surface DRY

Other Information

NO Was any foreign vehicle involved in this accident?

Number of vehicles involved in the accident

Was any body injured in the Accident? NO

Was any injured conveyed to hospital by

ambulance?

Was any other material or property damaged?

I have been approached by unknown person(s) soliciting/offering accident claims assistance.

Number of Passengers (Including Driver)

Passenger 1

YES NO

2

NAME:

GENDER:

: FEMALE

Details of Police Action

Was the accident reported to the police?

NO

NO

If Yes, Please state which Police Station

Was notice of intended Prosecution given?

If Yes, against whom?

Circumstances of Accident

PLS REFER TO ATTACHED

Attachment(s)

Are accident photos available for attachment?

YES NO

Was there any video captured by Car Camera?

Was there any audio recorded?

NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number SHA2543L

Vehicle Make/Model/Colour

Details Of Properties

TAXI Vehicle Category

Name of Driver

NRIC/Passport Number

Contact Number

Address

Postcode

INDIA INTERNATIONAL INSURANCE PTE LTD Insurance Company Name

FRT Nature Of Damage

No. Of Passenger (Including Driver)

Page 2 of 20

DETAILS OF OTHER VEHICLE PROPERTY 2

Vehicle Registration Number SLC6101U

Vehicle Make/Model/Colour

Details Of Properties

Vehicle Category PRIVATE CAR

Name of DriverMURTYNRIC/Passport NumberS1597488EContact Number96324563

Address Postcode

Insurance Company Name

Nature Of Damage REAR

No. Of Passenger (Including Driver)

IMPORTANT NOTICE

- 1. Please report correctly the details of the accident to speed up the claims process.
- 2. This Form must be completed by the Policyholder and/or the Authorised Driver.
- 3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
- 4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
- 5. Any false reporting may be referred to the Police for investigation.
- 6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
- 7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
- 8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s)
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.(collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents(including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.

COMFORT TRANSPORTATION PTF LTD CO. REG. NO. 199303821R

Policyholder's Signature

Date & Time: 1 4 MAR 2018 Driver's Signature

(If driver is not the policyholder)


Date & Time:

Reporting Centre Personnel's Signature Name:

NRIC/FIN No.: LISA DIONG

GIARMC SketchPlanForm V3

14-3-18



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

DESCRIBE CINCORD PARTIES OF THE MODIFIES
on 13/3/80 k @ 18-10/s. my lax (A) was eraveling along Mcd lume!
sowance fer at Baychore exist. with I fende properger on board.
I was on the exercise left lanes, I faw the infront of me whiches. How
down and slopped, to I follow 200. addenly, verisis SNA 25421 a conform
elixi, come from behind and has onlo my laxi (A) rear portion, my laxi (A)
no lose control and Ruge forward and collecting onto the vehicl rew portion.
My laxi (x) from and rear was damaged. I assessed the damages so
my lax's MI and come to know that there were 3 rehicles involved in
the chain accident.
the parates avolved in the accident are:
A, GNL 81010.
B. GHA 2543L. a confort lAxi. Female driver.
Cr SLC biol U a Privade On. Mr. Calvin R Musly. Nric no: 5 15974886.
MP no: 9632. 4563.
no unjuly in this accident.

DECLARATION

OMFORT TRANSPORTATION PTE LTD

CO. REG. NO. 199303821R

Policyholder's Signature Date & Time: 1 4 MAR 2018 Driver's Signature (If driver is not the policyholder)

Date & Time:

14-3-18 ,050AM

Reporting Centre Personnel's Signature Name: NRIC/FIN No.:

LISA DIONG