

22/03/2012

ASS. FEC. BY:

REF:

CS/EG718005079/U4b2

Special Instruction:

Surveyor:

ASSIGNMENT (Office)

From (Person):

Yee Pei Li

of

EGL

Date/Time:

26032018 353pm

Estimated Cost:

Bill to:

OD / ~~ET~~ / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SJR 4190U

Insured:

Ym 9994H

at Workshop m/s

Fastech

Tel:

6746 5405

of

Blk 1 Kaki Bukit Ave 6 #01-46

Policy No:

Claim No:

DBM CV 1800172

Sum Insured:

Excess:

Make of Veh:

D.O.A.

24012018

(Client's Record)

CA / REV / REP. / REV 24 HRS Wp

H.O.D. Endorsement:

Date/Time:

Person Contacted:

Nancy

Vehicle: IN OUT

Date/Time

Action/Instruction

(✓) Estimate

SJR 4190U - x

Ym 9994H - CS/CT16004614/6

DFA: 21.12.16

(08/11/13) wef

ASS. REC. BY: Marius

REF:

EN1/**ASSIGNMENT**

From: _____ Date: _____

Estimated Cost: _____

OD / ☒ TP / WS / TP RES / OD RES / EVA / INV / MVTo Inspect Vehicle No: SJR 41904at Workshop m/s LLof 1/m 9994H

Insured: _____

Policy No. _____


Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value: _____

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: re Consistent? : Yes or NoEst. Repairs: 4 days Res.: Yes or NoLum Sum: 20 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: SJR 41904Yr Regn: 6.09Type: ☒ M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /Truck / Trailer or CAIMake: mathe 3c.c. 1598Colour: blue

A/C: Insured / Std / NI / NA

Sp. Reading: 138375

T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: JM6BL102/A0106934Gen. Cond: ☒ Good / Fair / Poor / BurntSteering: ☒ In order / Jammed / Leaked / Burnt or alrightBrake: ☒ In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 205/55R16

R: _____

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / ☒ PIR / SUMI /
TOYO / YOKO orFront 6Rear 6

R/Bal. _____ mm

R/Bal. _____ mm

L/Bal. 6 mmL/Bal. 6 mmD.O.A. 21/1/18D.O.I. 19/3/18

Survey held at _____

Des. of Damages: Frt / Rear / O/S / N/S / UIC / Rooftop or

The O/S / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

26/3/18 have h14 474 12667
confirmed L/S & 2700 with Alan. Cred: 638660 : 70%

RECEIVED 27 MAR 2018

Date/Time File Pass to?

1) 213 Typist

Date/Time File Return to?

2) _____



: Preli. Report



: Final Report

Days Of Repair: 4Resurvey No. of Trip: 2

Add Fee:



: Site Insp (\$ _____)



: Interview (\$ _____)



: Tech. Invs (\$ _____)



: Weekend (\$ _____)

Survey Fee:

Transportation:

S + RS, SI

Photos

Others

TOTAL

250Report Format: TPLump Sum / I.B.I. (\$) 2700/-



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

ERGO INSURANCE PTE LTD

Ref : CS/EGI18005099/Utb

5 TEMASEK BOULEVARD
#04-01 SUNTEC TOWER FIVE
SINGAPORE 038985

Date : 19-03-2018



Code : EGI

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	YM 9994H	Veh. Inspected	SJR 4190U
Policy No.		Coverage (\$)	0.00
Claim No.	DSMCV1800172	Excess (\$)	0.00
Assign From	YEE PEI LI	Assign Date	19/03/2018

2. Vehicle Particulars & Condition

Make & Model		c.c	0
Engine No.	HIDDEN	Year of Reg.	
Chassis No.		Colour	
Odometer	-	Steering	
Brakes		Modification	
General			

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm

4. Description of Damages

--

5. General Information

Accident Date	24/01/2018	Inspection Date	19/03/2018
Survey held at	FASTECH AUTO PTE LTD 1 KAKI BUKIT AVENUE 6 #01-46/48/50 AUTOBAY SINGAPORE 417883		

5a. Remarks

A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

Catherine Chong (LKK Auto)

From: Survey Report (ERGO Insurance Pte. Ltd.) <Survey.Report@ergo.com.sg>
Sent: Monday, 26 March, 2018 3:53 PM
To: 'admin-d@lkkauto.com'
Subject: OI : YM9994H / TP : SJR4190U/LKK / DOA : 24/01/2018 (DSMCV1800172)
Attachments: YM9994H - SAS.pdf; SJR4190U - SAS.pdf; SJR4190U - PRS FORM - FASTECH.pdf
Importance: High

Dear Catherine,

In compliance with "State Courts Practice Directions Amendment No.1 of 2016" in regards to the Pre Repair Survey, both TP repairer and ERGO Insurance Pte Ltd have agreed on your company **LKK AUTO CONSULTANTS PTE LTD** to be the "Single Joint Expert".

Please conduct this survey request from **FASTECH AUTO PTE LTD.**

ADDRESS : 1 KAKI BUKIT AVENUE 6
#01-46/48/50 AUTOBAY
SINGAPORE 417883

PERSON TO CONTACT : NANCY LAM @ 6746 5405

ERGO OFFICER-IN-CHARGE : STEVE LIM

Note: To survey on without prejudice basis. Obtain estimate and advise the consistency of damages to third party vehicle that you are require to conduct a re-survey before vehicle is returned to claimant. They are to contact your office directly. Please do keep us in the loop.

Please fill up the necessary on ERGO PRS Form from workshop and return to us together on your update of the survey status via Survey.Report@ergo.com.sg.

Attached are insured and TP's SAS (**note: reports not to be released to any Third Party**). No estimates was provided.

Kindly acknowledge receipt of this email.

Thank you.

Yee Pei Li

Claims Assistant (Motor)
ERGO Insurance Pte. Ltd.
5 Temasek Boulevard
#04-01 Suntec Tower Five
Singapore 038985
Tel.: 65 6829 9199 DID: 65 6829 9194
Website: www.ergo.com.sg

ERGO is one of the major insurance groups in Germany and Europe. Worldwide, ERGO is represented in more than 30 countries and concentrates on Europe and Asia. ERGO is part of Munich Re (Group), one of the world's leading risk carriers.

ERGO

Date: 19.03.2018
Our Reference: DSMCV1800172/SE/pl
Your Reference: SJR 4190U
To: FASTECH AUTO PTE LTD

Sent via Fax ☐
or ☐
Email ☐ nancy.lam@fastechauto.com.sg

Pre-Repair Survey (PRS) Acknowledgement

Vehicle For Inspection: SJR 4190U
Insured's Vehicle: YM 9994H
Date Of Accident: 24.01.2018


We acknowledge receipt of your request for PRS on: 19.03.2018

In compliance with "State Courts Practice Directions Amendment No.1 of 2016", do select an assessor from the list below and indicate your selection in the box marked *.

* LKK

AIS	Automobile Inspection Services Pte Ltd	LBS	L.B.S Auto Consultants Pte Ltd
FTA	FormTeam Consultancy Pte Ltd	LKK	LKK Auto Consultants Pte Ltd
IAS	Infiniti Appraisal Service	PS	Priority Services
JPK	JP Knights Pte Ltd	VAC	Vicom Ltd

- ☒ Your request for inspection does not have your client's cost of repair estimate, kindly forward a copy.
☐ Your request for inspection does not have your client's GIA report, kindly forward a copy.
☐ We acknowledge your interest for direct settlement, we will assess & revert soon upon receipt of estimate.
☐ Our Insured's driver has not reported the accident to us to date.
☒ Others: OFFICER-IN-CHARGE - STEVE LIM

Prepared by:	<u>Pei Li</u>	6829 9194	<u>claims@ergo.com.sg</u>
Signature:			FAX : 6829 9247

Assessor use only:

Assignment Date: _____
Assignment Time: _____

Remarks:

Workshop use only:

Assessor attended workshop on:

Date: _____
Time: _____
Inspector: _____

☐ Vehicle not available at the appointed date and time.

Kindly acknowledge our Assessor presence for the above job .



Workshop Acknowledgement & Stamp.

Note: Our Inspection is on a without admission to liability basis.

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type: Singapore NRIC

Owner ID: 2222H

Vehicle Details

Vehicle No.: SJR4190U

Vehicle to be Exported: No

Intended De-registration Date: 19 Mar 2018

Vehicle Make: MAZDA

Vehicle Model: MAZDA3 1.6L SDN

Primary Colour: Silver

Manufacturing Year: 2009

Engine No.: Z6797151

Chassis No.: JM6BL10Z1A0106934

Maximum Power Output: 77.0 kW (103 bhp)

Open Market Value: \$20,080.00

Original Registration Date: 23 Jun 2009

First Registration Date: 23 Jun 2009

Transfer Count: 0

Actual ARF Paid: \$20,080.00

Intended PARF Rebate Details

PARF Eligibility: Yes

PARF Eligibility Expiry Date: 22 Jun 2019

PARF Rebate Amount: \$11,044.00

Intended COE Rebate Details

COE Expiry Date: 22 Jun 2019

COE Category: A - Car (1600cc & below)

COE Period(Years): 10

QP Paid: \$12,899.00

COE Rebate Amount: \$1,623.00

Total Rebate Amount: \$12,667.00

The information contained herein is correct as at 19 Mar 2018

OK

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type:	Singapore NRIC
Owner ID:	2222H

Vehicle Details

Vehicle No.:	SJR4190U
Vehicle to be Exported:	No
Intended De-registration Date:	19 Mar 2018
Vehicle Make:	MAZDA
Vehicle Model:	MAZDA3 1.6L SDN
Primary Colour:	Silver
Manufacturing Year:	2009
Engine No.:	Z6797151
Chassis No.:	JM6BL10Z1A0106934
Maximum Power Output:	77.0 kW (103 bhp)
Open Market Value:	\$20,080.00
Original Registration Date:	23 Jun 2009
First Registration Date:	23 Jun 2009
Transfer Count:	0
Actual ARF Paid:	\$20,080.00

Intended PARF Rebate Details

PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	22 Jun 2019
PARF Rebate Amount:	\$11,044.00

Intended COE Rebate Details

COE Expiry Date:	22 Jun 2019
COE Category:	A - Car (1600cc & below)
COE Period(Years):	10
QP Paid:	\$12,899.00
COE Rebate Amount:	\$1,623.00
Total Rebate Amount:	\$12,667.00

The information contained herein is correct as at 19 Mar 2018

OK

FASTECH AUTO PTE LTD

1 KAKI BUKIT AVENUE 6

#01-46/48/50, AUTOBAY,

SINGAPORE 417883

VEHCILE NO: SJR 4190U

Not Authorised
2/5 \$2700
4 days
19/3/18

QTY	PARTICULAR	AMOUNT
1PCS	FRONT FENDER O/S 485.20	Body \$650.00
1PCS	FRONT FENDER INNER SHIELD O/S 188.30	Torn \$218.00
1SET	FRONT FENDER INNER SHIELD CLIPS O/S	ren \$50.00
1PCS	FRONT FENDER SIGNAL LAMP O/S	510 \$62.30
1PCS	FRONT BUMPER	2 \$1,011.30
1SET	FRONT BUMPER CLIPS	ren \$50.00
1PCS	FRONT DOOR O/S	2 \$1,248.20
1PCS	FRONT DOOR MIRROR O/S	2 \$824.30
1PCS	FRONT DOOR MIRROR COVER O/S	cut \$152.00
1PCS	FRONT LOWER ARM O/S	111 \$488.20
1PCS	FRONT KNUCKLE ARM O/S	51 \$512.30
1PCS	FRONT KNUCKLE ARM BEARING O/S 165	ren \$250.00
1PCS	FRONT SPORT RIM O/S	cut/24 \$1,200.00
		\$6,716.60
	TO CHECK WIRING 1665-1	\$50.00 20
	TO SPRAY RUST PROOFING 1332-08	\$80.00 30
	TO CONDUCT WHEEL ALIGNMENT	\$80.00 60
	TO DISMANTLE & REPLACING FRONT UNDERCARRIAGE	\$180.00 120
	TO TRANSFER DOOR MECHANISM	111 \$100.00
	LABOUR FOR PANEL BEATING	\$800.00 480
	TO PUTTY & SPRAY PINTING	\$1,080.00 900
	TOTAL	\$9,086.60

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:




LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
ERGO INSURANCE PTE LTD		Ref : CS/EGI18005099/Utn2		
5 TEMASEK BOULEVARD #04-01 SUNTEC TOWER FIVE SINGAPORE 038985		Date : 28-03-2018		
		Code : EGI		
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	YM 9994H	Veh. Inspected	SJR 4190U	
Policy No.		Coverage (\$)	0.00	
Claim No.	DSMCV1800172/SE/pl	Excess (\$)	0.00	
Assign From	YEE PEI LI	Assign Date	26/03/2018	
2. Vehicle Particulars & Condition				
Make & Model	MAZDA 3 (A)	c.c	1598	
Engine No.	HIDDEN	Year of Reg.	2009	
Chassis No.	JM6BL10Z1A0106934	Colour	GREY	
Odometer	138375	Steering	AFFECTED	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	205/55 R16	PIRELLI	6 mm	
L/H Front Tyre	205/55 R16	PIRELLI	6 mm	
R/H Rear Tyre	205/55 R16	PIRELLI	6 mm	
L/H Rear Tyre	205/55 R16	PIRELLI	6 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE O/S FRONT PORTION.THE UNDERCARRIAGE AFFECTED DUE TO COLLISION.				
DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	24/01/2018	Inspection Date	19/03/2018	
Survey held at	FASTECH AUTO PTE LTD 1 KAKI BUKIT AVENUE 6 #01-46/48/50 AUTOBAY SINGAPORE 417883			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		4 Working Days		



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SJR 4190U

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	FRONT FENDER O/S	BADLY DENTED	650.00	485.20
1	FRONT FENDER INNER SHIELD O/S	TORN	218.00	188.30
1	SET FRONT FENDER INNER SHIELD CLIPS O/S	NECESSARY	50.00	50.00
1	FRONT FENDER SIGNAL LAMP O/S	BROKEN	62.30	62.30
1	FRONT BUMPER	TO REPAIR SEE LABOUR	1,011.30	-
1	SET FRONT BUMPER CLIPS	NECESSARY	50.00	50.00
1	FRONT DOOR O/S	TO REPAIR SEE LABOUR	1,248.20	-
1	FRONT DOOR MIRROR O/S	TO REPAIR SEE LABOUR	824.30	-
1	FRONT DOOR MIRROR COVER O/S	CUT	152.00	152.00
1	FRONT LOWER ARM O/S	NOT NECESSARY	488.20	-
1	FRONT KNUCKLE ARM O/S	BENT	512.30	512.30
1	FRONT KNUCKLE ARM BEARING O/S	NECESSARY	250.00	165.00
	LESS 20% DISCOUNT		-	-333.02
			5,516.60	1,332.08
SPECIAL NETT ITEMS				
1	FRONT SPORT RIM O/S (SN)	CUT / BENT	1,200.00	480.00
			1,200.00	480.00
LABOUR				
	TO CHECK WIRING.		50.00	20.00
	TO SPRAY RUST PROOFING.		80.00	30.00
	TO CONDUCT WHEEL ALIGNMENT.		80.00	60.00
	TO DISMENTLE & REPLACING FRONT UNDERCARRIAGE.		180.00	120.00
	TO TRANSFER DOOR MECHANISM.	NOT NECESSARY	100.00	-
	LABOUR FOR PANEL BEATING.INCLUSIVE OF THE REPAIR OF FRONT BUMPER,FRONT DOOR O/S AND FRONT DOOR MIRROR O/S.		800.00	480.00
	TO PUTTY & SPRAY PAINTING.		1,080.00	900.00
			2,370.00	1,610.00

Report Ref No. CS/EGI18005099/Utnb2



GRAND TOTAL		9,086.60	3,422.08
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)			2,700.00

Report Ref No. CS/EGI18005099/Utn2

CHUA KANG SENG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.