

60 Woodlands Industrial Park E4, Singapore 757705

FAX Number : 63685592

Estimator Telephone Number : 68662623

Accident Reporting Number : 68662672

SMRT Accident Vehicle Repair Estimates

Section A - To be completed by claims Advisor/Duty officer at Accident Reporting Centre

Reg. No

SHC4752B

Ref. No

TAX/03/18/2081

Reg. Date

01/04/2016

Vehicle Type

TAXI

Make

TOYOTA PRIUS

Model

PRIUS

Name of Driver

ABDULLAH BIN MOHAMED

NOR

Type of Accident

HEAD TO REAR

Date / Time of Accident

16/03/2018 03:55:00 AM

Accident Reported Date / Time:

16/03/2018 12:00:00 AM

Surveyor is Required?

Yes

Survey by

Vehicle is Towed Back?

No

Towed Back Date/Time

Replacement Vehicle issued? :

Accident Repair Job Card No :

000024095077

Special Instruction to ARC, if any :

SHC5139R (TRANSCAB) - AXA

Prepared Date

16/03/2018 10:28:43 AM



- Part by part repair.
- Question Mark Item
Photo.
- Photo Before Paint

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- . To display damaged part(s) during resurvey
- · Parts prices are subject to confirmation
- . Third party survey is on a "Without Prejudice" basis
- · No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Section B - 10 be Completed by Service Advisor, Accident Repair Centre

Chassis No: JTDKN36U505767755

Mileage

: 0

Work Shop :

Repair Completed Date / Time :

Summary of Repair Estimates

Quotation from ARC

Adjusted by Surveyor, if applicable

Total Labout Charges

338.00

0.00

Total Spray Painting Charges

558.00

0.00

Total Material Charges

1,321.49

1,321.49

Other Charges

556.88

0.00

TOTAL

2,774.37

0.00

Lum Sum Total

0.00

0.00

No. of Repair Days

3.00

0.00 2 days

Prepared / Adjusted By

Arc / Surveyor Sing Off Date

: 16/03/2018 01:30:35 PM

01/01/1900 12:00:00 AM

Prepared / Adjusted Date

Remarks :

Prepared Date : 16/03/2018 01:30:14 PM

Section C - To be Completed by Admin Assistant, Accident Repair Centre, Upon Completion of Repair

Quotation No

Invoice No

Quotation Date :

Invoice Date :

Invoice Amount :

Prepared Date:

TAX/03/18/2081 Page: 2

Part 1 - Labour Works

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO REPAIR REAR PORTION	338.00	0.00 200
Total Labour	338.00	0.00

Part 2 - Spray Painting & Panel Beating Related Works

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable			
TO REPSRAY REAR BUMPER	378.00	0.00 200			
TO RESPRAY BUMPER BEAM	180.00	0.00 7			
Total Spray Painting & Panel Beating	558.00	0.00			

Part 3 - Other Costs - Accident and Accident Repair Related Expenses

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable			
TO CHECK WIRING AND SYSTEM FUNCTION	80.00	0.00 ×			
TO PROVIDE LABOUR & MATERIAL FOR ADVERTISEMENT STICKER(NET)	296.88	0.00 ✓			
TO TEST AND REFIX REVERSE SENSOR SYSTEM	120.00	0.00 30			
TO WASH AND VACUUM	60.00	0.00 ×			
Total Other Costs	556.88	0.00			

AX/03/18/2081 Page: 3

Part 4 - Spare Parts / Material Usage

Part Number	Portion	Stock No	Part Name	Qty	List Price (\$)	Discount (%)	Final Price (\$)	ARC Recommen d	Surveyor Approved	Photos Attached
52159- 47905		6505548	BUMPER REAR	1	458.60	25.00	343.95	Replace	Replace R	No
76891- 47020		6505619	BUMPER LIP REAR	1	228.90	25.00	171.67	Replace	Replace X	No
52023- 12240		6505547	BUMPER REINFORCEMENT REAR	1	205.70	25.00	154.27	Replace	Replace 7	No
52016- 47030			ARM SUB-ASSY, RR BUMPER LH	1	139.60	25.00	104.70	Replace	Replace 7	No
52015- 47050			ARM SUB-ASSY, RR BUMPER RH	1	139.60	25.00	104.70	Replace	Replace 7	No
			SENSOR REVERSE	1	180.00	0.00	180.00	Replace	Replace 7	No
			PIXEL STICKER	2	60.00	0.00	120.00	Replace	Replace/No.	No
52576- 47020		6505550	BUMPER SIDE RETAINER RR/LH	1	94.80	25.00	71.10	Replace	Replace 7	No
52575- 47020		6505549	BUMPER SIDE RETAINER RR/RH	1	94.80	25.00	71.10	Replace	Replace 7	No
TOTAL MATERIALS								1,321.50	1,321.49	
TOTAL MATERIALS(Discounted)							1,321.49 1,321.49			

Added Spare Parts / Material Usage After Surveyor Signed off

Part Number	Portion	Part Name	Qty	List Price (\$)	Discount (%)	Final Price	ARC Check	Surveyor Check	LT Check
	TOTAL SUPPLEMENTARY MATERIALS								Oncon