

OL

S3  
CP# Asm1800 5126, M/ea322

LKK: 35413  
IDAC:

MA CP

ASSIGNMENT

DOI: 27/3/18

Date / Time: 16/3/2018

Registered in Merimen:

Pre-assign / CCU / FTE

S6T 7676R



Insured Vehicle No.:  
Name of Insured: Jay Lee Bron Yong  
Insured Tel No.: HP: 97867860  
Excess Sec II :SS D.O.A: 15/3/2018  
Is driver the owner? (YES / NO) Nature of Accident:

Claim No.: 58M 00B02  
Policy No.: P1581737  
Make / Model: BMW 318  
Place of Accident: Balestian Rd

If NO, Driver Name / Age:

OI GIA REPORT: YES / NO ; TP GIA REPORT: YES / NO

Driver Tel No.:

(V/L: YES / NO)

Insured Liability: % Final ? Yes / No

6x321P



INSRS:  
WSP: FM-1  
Tel:  
Liability:  
RMKS:



INSRS:  
WSP:  
Tel:  
Liability:  
RMKS:



INSRS:  
WSP:  
Tel:  
Liability:  
RMKS:



INSRS:  
WSP:  
Tel:  
Liability:  
RMKS:

Date / Time	STAGE	DATE / PIC
27/3	6x321P. 66/16611025617/ K2024 (A: 3011/11)	
ASW	S6T 7676R - X	
	* Family vs & Est.	
27/3/18 + 10:55	CAUSED OI CONFIRMED ACCIDENT. OI CHANGED LANE AND COLLIDED WITH TP. INFORM TP CLAIM AGENT TO SETTLE AND MAKE ABOUT NO ISSUE.	
	to submit PRS 1-3-17	
13.5.18	REPAIR INFROM NOT DOING D/S. NO ESTIMATE SUBMITTED	
	RECEIVED 15 AUG 2018	

PRELIMINARY ADVICE Date/Time: Sent By:

FINALIZATION Date/Time: Confirm with: Confirm by:

Repair Cost: \$\$ ( days) Reduction: % Email Call

FINAL SETTLEMENT Date/Time: Confirm with: Email Call

Final Liability: % 80-100 (Agreed / Assessed) BOLA S/N No.: 15 / MAR 20. If NO or B 28, Ass. Lia:

Repair Cost: \$\$ OI CHANGED LANE

Loss of Rental (LOR): \$\$ ( days)

Loss of Use (LOU): \$\$ (\$ x days)

Loss of Income (LOI): \$\$ (\$ x days)

LOR only LOU only LOR + LOU LOR + LOI [Tick only one]

GIA/LTA Search: \$\$

Medical: \$\$

Disbursement: \$\$ (e.g. Tow/ Independent)

Legal Cost: \$\$

Total: \$\$ Global Sum \$\$:

FINAL PAYMENT Date/Time: Confirm with: Email Call

Payee 1: \$\$ Name 1:

Payee 2: (Strike if N.A.) \$\$ Name 2:

Payee 3: (Strike if N.A.) \$\$ Name 3:

COPIED 15/8/18





## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
AXA INSURANCE PTE LTD		Ref : CC4/ASM18005126/M1ea3	
8 SHENTON WAY #24-01 AXA TOWERSINGAPORE 068811		Date : 19-03-2018	
		Code : ASM	
<b>1. Policy Particulars :- THIRD PARTY CLAIM</b>			
Insured Veh.	SGT 7676R	Veh. Inspected	GX 321P
Policy No.		Coverage (\$)	0.00
Claim No.	S8M00B02	Excess (\$)	0.00
Assign From		Assign Date	19/03/2018
<b>2. Vehicle Particulars &amp; Condition</b>			
Make & Model		c.c	0
Engine No.	HIDDEN	Year of Reg.	
Chassis No.		Colour	
Odometer	-	Steering	
Brakes		Modification	
General			
<b>3. Conditions of Tyres</b>			
	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm
<b>4. Description of Damages</b>			
<b>5. General Information</b>			
Accident Date	15/03/2018	Inspection Date	22/03/2018
Survey held at	EM-1 AUTO PTE LTD BLK 8 SIN MING INDUSTRIAL ESTATE SECTOR C #01-68 SINGAPORE 575643		
<b>5a. Remarks</b>			
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			

## Service Request Details

11:30am @ 19/3/18  
Mr Cheah  
vehicle Not In

Claim

S8M00B02

Reference

None 

Loss Date

March 15, 2018

LKK AUTO CONSULTANTS PTE LTD (TP) ▾

Request Date

March 16, 2018

Due Date

March 23, 2018

Vendor Name

LKK AUTO CONSULTANTS PTE LTD (TP)

Type of Loss

Third Party Vehicle Damage

Services

Pending verification - Direct Settlement

### Actions

---

Next Step

Agree to perform service

Decline Work

Accept Work

### Vehicle Information

---

Incident Vehicle Registration #

GX321P

Make

TPVD TOYOTA

Service Address

---

...

Primary Contact/Insured

---

LEE BOON YONG JAY  
BLK 617D PUNGGOL DRIVE, #15-823, 824617, Singapore  
97867860  
jaylee\_1976@yahoo.com.sg

Claim Handler

---

LOH Cynthia  
6568804843  
cynthia.loh@axa.com.sg

Additional Instructions

- 
- Messages
  - Invoices
  - History
  - Documents
  - Assessment
  - Metrics
  - Notes

New Message

## Catherine Chong (LKK Auto)

---

**From:** Chia Sin Muk <em1autopteltd@gmail.com>  
**Sent:** Friday, 16 March, 2018 5:46 PM  
**To:** SG AXA Insurance SM AXA SGP - Motor Survey; SG AXA Insurance SM Claims Service Team  
**Subject:** ARRANGE SURVEY GX 321P DOA 15.03.2018  
**Attachments:** 321-16032018174356.pdf  
  
**Categories:** Kushal

### WITHOUT PREJUDICE

Dear Sir/Madam,

Kindly arrange survey at our workshop.

### **Thanks & Best Regards,**

Nicole, on behalf of,  
Chia Sin Muk (Mr)

**m: (65) 9666 6556 | o: (65) 6452 3298 | f: (65) 6457 5776**

### **EM-1 Auto Pte Ltd**

Blk 8 #01-68 Sin Ming Rd Industrial Estate Sector C Singapore 575643

Co. / GST Registration Number: 201316380R

Important: This email is confidential and may be privileged. If you are not the intended recipient, please delete it and notify us immediately; you should not copy or use it for any purpose, nor disclose its contents to any other person. Thank you.

# EM-1 AUTO TRADE

BLK 8 SIN MING INDUSTRIAL ESTATE SECTOR C  
#01-68 SINGAPORE 575643

Contact Number: 6452 3298 (O) 9666 6556 (H/P) 6457 5776 (F)

Email Address: emlautopteltd@gmail.com

COMPANY REG NO : 53105453E

Your Vehicle: SGT7676R (3<sup>rd</sup> Party Vehicle)

Our Vehicle: GX321P

Date: 16/3/18

M/s AXA Insurance Pte Ltd  
8 Shenton Way  
#27-01  
Singapore 068811

By fax 6880 4838 only

Dear Sir/Madam,

ACCIDENT INVOLVING GX 321P & SGT7676R ON 15/3/18

We refer to the above matter.

I hereby give you 2 days' notice to conduct a pre-repair survey of vehicle  
GX321P at my premises.

Yours faithfully

Chwa

## Asher Sng (LKKAuto)

---

**From:** Asher Sng (LKKAuto)  
**Sent:** Wednesday, 4 April 2018 5:42 PM  
**To:** 'jaylee\_1976@yahoo.com.sg'  
**Subject:** ACCIDENT INVOLVING SGT 7676R AND GX 321P ALONG BALESTIER ROAD OPPOSITE KEMPAS ROAD ON 15/03/2018

04 APRIL 2018

**JAY LEE BOON YONG**

Dear Sir/ Mdm

**OUR REF : CC4/ASM18005126/M1ea3**  
**YOUR REF : SGT 7676R**  
**ACCIDENT INVOLVING SGT 7676R AND GX 321P ALONG BALESTIER ROAD OPPOSITE KEMPAS ROAD ON 15/03/2018**

We refer to the above subject matter. We write to inform you that we are the loss adjuster appointed by your motor insurer, AXA Insurance Pte Ltd to deal with the third party claim against your policy.

We have received a claim from M/s EM-1 AUTO PTE LTD acting on behalf of the owner of GX 321P against your motor insurance policy.

Based on the accident report and accident scenario, it was reported that your vehicle had collided the Third Party vehicle GX 321P. As such, liability is down against us.

Please be informed that your No Claim Discount (NCD) may be affected as a result of the claim against your policy.

We shall proceed to deal with the claim(s) subject to the merits of the case and according to the rights afforded under the policy. Should you not be seeking the protection of your policy and seek to take conduct of third party claim(s) arising from this incident, at your own cost and defence, please reply to us within 7 days from the date of this letter. Your intent must be formally expressed to us and acknowledged by us.

Your full co-operation in the handling of the claim is required and kindly submit the following to [ashersng@lkkauto.com](mailto:ashersng@lkkauto.com) within 7 days from the date of this letter **if not provided at our reporting centre**. The list below is not all inclusive and further document may be required:

- Police report, Police Investigation result, appeal against the Traffic Police offence and status (if any)
- Driver's driving license or foreign driving license (if any)
- Coloured photographs of accident scene (if any)
- Coloured photographs of damage to all vehicles involved (If any)
- Video footage of accident (if any)
- Statement and/or police report from independent witness(es) (if any)
- If you or your passenger(s) are filing a claim against any of the involved Third Party(s), you are to keep us informed of your legal representative(s) and the status of the claim

To protect your interest(s) in the handling of this claim, please do not discuss liability with any of the Third Party(s) and/or their legal representatives, or make any compromise or settlement without AXA's prior knowledge and consent.

This letter should **not** be regarded as a waiver by AXA of their rights to repudiate any claim because of any breach of policy terms and conditions you and/or your authorised driver may have committed.

In the event of receiving and handling of any third party injury claim(s), AXA shall keep you informed of the final indemnity upon conclusion of the matter(s).

If you need any clarification, please do not hesitate to contact us at 6256 3561 or email us at [ashersng@lkkauto.com](mailto:ashersng@lkkauto.com).

Please quote the claim reference when you contact us that we can assist you more effectively.

Yours sincerely,

Asher  
Case Handler  
DID: 6841 6051  
FAX: 6741 4108  
Email: [ashersng@lkkauto.com](mailto:ashersng@lkkauto.com)

c.c. AXA Insurance Pte Ltd (AXA)  
(Motor Claims Dept)

◀◀ **RE: Please proceed DS**

Type

🔍 Question

Message

TP repairer did not do D/S claim, no estimate submitted during inspection. In view on above we will submit PRS to you. Thank You - Asher (13/08/2018)

Reply



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

PRE-REPAIR INSPECTION REPORT			
AXA INSURANCE PTE LTD 8 SHENTON WAY #24-01 AXA TOWERSINGAPORE 068811 ATTN: CYNTHIA LOH		Ref: CS3/ASM18005126/M1ea3s2 Date: 17-08-2018 Code: ASM	
<b>1. Policy Particulars :- (THIRD PARTY CLAIM)</b>			
Insured Veh.	SGT 7676R	Veh. Inspected	GX 321P
Policy No.	CN873576	Coverage (\$)	0.00
Claim No.	S8M00B02	Excess (\$)	0.00
Assign From	CYNTHIA LOH	Assign Date	16/03/2018
<b>2. Vehicle Particulars &amp; Condition</b>			
Make & Model	TOYOTA DYNA	c.c	2986
Engine No.	HIDDEN	Year of Reg.	2004
Chassis No.	JTFUF34Y303002008	Colour	SILVER
Odometer	108930 KM	Steering	IN ORDER
Brakes	IN ORDER	Modification	NIL
General	GOOD		
<b>3. Conditions of Tyres</b>			
	Size	Make	Balance
R/H Front Tyre	185 R14	MICHELIN	7 mm
L/H Front Tyre	185 R14	MICHELIN	7 mm
R/H Rear Tyre	155 R12	FIRENZA	7 mm
L/H Rear Tyre	155 R12	FIRENZA	7 mm
<b>4. Description of Damages</b>			
THE VEHICLE SUSTAINED DAMAGES AT THE N/S FRONT PORTION.			
<b>5. General Information</b>			
Accident Date	15/03/2018	Inspect Date / Time	22/03/2018 ( 05:57 PM )
Survey held at	EM-1 AUTO PTE LTD BLK 8 SIN MING INDUSTRIAL ESTATE SECTOR C #01-68 SINGAPORE 575643		
<b>5a. Remarks</b>			
A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.			

Report Ref No. CS3/ASM18005126/M1ea3s2

Inspected By

MA CHIN FOOK

Automotive Assessor

K.K.LAU CPT(RET)

BEng(Hons),B.Bus,MBA,PEng,PE, MinstAEA,MASME,MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.