

Letter of Claims Request of direct settlement.

We are sub	omitting a	claim on be	half of	our customer	Sumi	+ro	OPOE	Taslim
NRIC 87	1811979]		insure	d of vehicle	8F (12	444		_ against
your insure	ed vehicle	number 🤱	k77	2 200	(AIG)	
On the acc	ident date	1 on 93	18	(ddmmyy	yy) along	SLE	H ff	EXIT 3
Jonards	CPE C	16				÷		
Dated this	19	_(day) of	3	_(month) 20_	18.			
				veniele in 71	JAD .			
			T.	ACLIENCE .				



Volkswagen Group Singapore

1 Kampong Ampat

Singapore 368314

DID: 69223502

HP: 93867833

shushi.tang@vw.com.sg

Service Order Confirmation

SA: Tang Shu Shi

SERVICE ORDER NO: 18IP0743

CUSTOMER NO.: CV034264

CUSTOMER NAME: SUMITRO JOYO TASLIM

TELEPHONE NO.:

ADDRESS: 50 LORONG 40 GEYLANG #08-39

Singapore

VEH No.: SLD7844Y

Order Date:

19/03/18

Reg Date: 28/06/16

KM: 41,218

VIN NO.:

WVGZZZ5NZGW094282

ENGINE NO:

MODEL: TiguanGP 1.4 TSI 118 DSG6 VNA MODEL NO.: 5N22QY

	No.	<u>DESCRIPTION</u>		<u>UOM</u>	UNIT PRICE	DISC %	AMOUNT
	Labor						
1	B&P MECH	ELECT WIRING & MECH COMPONENT CHECK NETT	1	TU	1.25		1.25
2	B&P DIAG	PROGRAMMING & CALIBRATION- NETT	1	TU	1.25		1.25
3	B&P MACP LABOUR	LABOUR (REAR)	5	UNIT	840		4,200
4	B&P MACP PAINT	SPRAY PAINT (REAR)	5	UNIT	800		4,000
5	B&P MACP LABOUR	LABOUR (FRT)	3	UNIT	840		2,520
6	B&P MACP PAINT	SPRAY PAINT (REAR)	2	UNIT	800		1,600
7	B&P NUMBER PLATE	B&P NUMBER PLATE -NETT (FRT)	2	ST	80		160
8	EXT00037	Tow SVC- Quality Recovery Services	1	UNIT	0		0
	Item						
9	5N0807421G GRU	REAR BUMPER (TOP)	1	PCS	1,138.50		1,138,50
10	5N0807521AFGRU	REAR BUMPER (CENTRE)	1	PCS	398.19		398.19
11	5N0807568 2Z0	REAR BUMPER SPOILER (LOWER)	1	PCS	441,47		441.47
12	5N0807305	REINFORCEMENT	1	PCS	480.96		480.96
13	5N0807393E	LHR BUMPER BRACKET	1	PCS	23.80		23.80
14	5N0807394D	RHR BUMPER BRACKET	1	PCS	23.80		23.80
15	1K0807300	RIVET	4	PCS	2.24		8.96
16	N 10621301	NUT	6	PCS	1.85		11.10
17	5N0807441A GRU	TOW COVER	1	PCS	48.58		48.58
18	5N0945105	REFELCTOR REAR LH	1	PCS	67.37		67.37
19	5N0945106	REFELCTOR REAR RH	1	PCS	52.53		52,53
20	5N0941071	REVERSING LIGHT LH	1	PCS	75.95		75,95
21	5N0941072	REVERSING LIGHT RH	1	PCS	75.95		75.95
22	5N0853817C 9B9	LHR BUMPER PROTECTOR	1	PCS	356.42		356.42
23	5N0853818C 9B9	RHR BUMPER PROTECTOR	1	PCS	356.42		356.42
24	5N0853818E 9B9	RHR FENDER PROTECTOR	1	PCS	613.41		613.41
25	5N0853817E 9B9	LHR FENDER PROTECTOR	1	PCS	613.41		613.41
26	3C0853586	GROMMET	12	PCS	2.01		24.12
27	5N0810972	RHR FENDER LINER	1	PCS	182.00		182.00
28	1S0919275C GRU	REAR SENSOR	3	PCS	175.10		525.29

Service Order Confirmation

SERVICE ORDER NO: 18IP0743

CUSTOMER NO.: CV034264

CUSTOMER NAME: SUMITRO JOYO TASLIM

TELEPHONE NO.:

ADDRESS: 50 LORONG 40 GEYLANG #08-39

Singapore

VEH No.: \$LD7844Y

Order Date: 19/03/18

Reg Date: 28/06/16 **KM:** 41,218

VIN NO.: WVGZZZ5NZGW094282 ENGINE NO: SA: Tang Shu Shi

MODEL: TiguanGP 1,4 TSI 118 DSG6 VNA MODEL NO.: 5N22QY

	No.	DESCRIPTION	QTY	<u>UOM</u>	UNIT PRICE	DISC %	AMOUNT
29	1T0919133C 9B9	PARKING SENSOR O RING	3	PCS	0.65		1.95
30	5N0919503D	SENSOR BRACKET (INNER)CENTRE	1	PCS	14.78		14.78
31	5N0919503E	SENSOR BRACKET (INNER)CENTRE	1	PCS	14,78		14,78
32	5N0919491D	SENSOR BRACKET (OUTER)CENTRE	1	PCS	14.78		14,78
33	5N0919491E	SENSOR BRACKET (OUTER)CENTRE	1	PCS	14.78		14.78
34	5N0919398	SENSOR BRACKET (SIDE)OUTER RH	1	PCS	13.36		13.36
35	5N0919504B	SENSOR BRACKET (SIDE)INNER RH	1	PCS	25,66		25,66
36	5N0853687B 739	TIGUAN EMBLEM	1	PCS	90,62		90.62
37	1Q0853675Q GQF	TSI EMBLEM	1	PCS	57,84		57.84
38	5N0853675M CWB	BLUEMOTION EMBLEM	1	PCS	69.58		69.58
39	5N0853630 FXC	VW SIGN	1	PCS	79,95		79,95
40	5M0819466A	RHS REAR FENDER AIR DUCT	1	PCS	32,47		32.47
41	5N0807217EHGRU	FRT BUMPER	1	PCS	1,245.38		1,245.38
42	5N0807287D 9B9	FRT NUMBER PLATE BRACKET	1	PCS	93.15		93,15
43	N 0385491	RIVET	6	PCS	0.68		4.08
44	5N0807248D	BUMPER FOAM FRT	1	PCS	45,26		45.26
45	5N0807183D	BUMPER SIDE BRACKET LH	1	PCS	21.09		21.09
46	5N0807184D	BUMPER SIDE BRACKET RH	1	PCS	21,09		21.09
47	5N0807109F	FRT REINFORCEMENT	1	PCS	445.19		445.19
48	5N0807651B	MEMBER	ì	PCS	153.12		153,12
49	5N0998494B	SENSOR BRACKET FRT	1	PCS	53.15		53,15
50	5N0919493H	SENSOR BRACKET FRT	1	PCS	13.36		13.36
51	5N0919494H	SENSOR BRACKET FRT	1	PCS	13.36		13.36
52	5N0919493G	SENSOR BRACKET FRT	Ĭ	PCS	13,36		13.36
53	5N0919494G	SENSOR BRACKET FRT	1	PCS	13,36		13,36
54	5N0853671B 82V	CENTRE LOWER GRILLE (FRT)	1	PCS	160.33		160.33
55	5N0121341B	AIR GUIDE LOWER	1	PCS	47.15		47.15

Remarks : AIG DIRECT SETTLEMENT

DOA: 09/03/2018

TP VEHCILE: SKT7206S

Service Order Confirmation

CUSTOMER NO	.:	CV034264								
CUSTOMER NA	ME:	SUMITRO JOYO TASLIM								
TELEPHONE NO	D.:									
ADDRESS:		50 LORONG 40 GEYLANG	#08-39							
		Singapore								
VEH No.	.:	SLD7844Y								
Order Date:	19/03	/18								
Reg Date:	28/06	/16	KM:	41,218						
VIN NO.:	WVG	ZZZ5NZGW094282	ENGINE NO:						SA: Ta	ng Shu Shi
MODEL:	Tigua	nGP 1.4 TSI 118 DSG6 VNA	MODEL NO.:	: 5N22QY						
No.		DESCRIPTION				QTY	<u>UOM</u>	UNIT PRICE	DISC %	AMOUNT
SURVEY BY:										
					3.					
							TOTA	L		20,773.71
								AMOUNT		1,454.16
								L AMOUNT		22,227.87
			On Beha	If Of "COMPANY"			С	ertified Goods/Se	rvice received:	
			Au	thorized Sign	ature		1.5		Customer	
NOTE: T	TIC I	S NOT AN OFFICIA	I DECE	IDT						

NOTE: THIS IS NOT AN OFFICIAL RECEIPT

SERVICE ORDER NO: 18/P0743

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

- 1. Please report correctly the details of the accident to speed up the claims process.
- 2. This Form must be completed by the Policyholder and/or the Authorised Driver.
- 3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or witholding of material facts may allow insurance companies to repudiate policy ability.
- 4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
- 5. Any false reporting may be referred to the Police for investigation.
- 6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
- 7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid

	ACCIDENT STATEMENT
D-4- Of D-1	
Date Of Assidant	19/03/2018 08:46
Date Of Accident	09/03/2018 18:00
Exact Location Of Accident	SLE AFTER EXIT3 TOWARDS TPE/CTE
Country/State of Loss	SINGAPORE
	ETAILS OF OWN VEHICLE
Vehicle Registration Number	SLD7844Y
Insured/Policyholder	
Name Of Registered Owner	SUMITRO JOYO TASLIM
NRIC No	\$78119791
Email Address	SUMITRO_ZOEY@SINGNET.COM.SG
Mobile Phone No	(LOCAL) +65-98287461
Alternative Phone No	OFFICE-98287461
Vehicle Particulars	
Manufacturer	VOLKSWAGEN
Model	TIGUANGP 1.4 TSI 118 DSG6 VNA
Exact Purpose for which vehicle was being used at time of accident	PRIVATE
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR
Insurance Company	
Name of Insurance Company	MSIG INSURANCE (SINGAPORE) PTE. LTD.
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	A 28788813 AVW
Cover Note Number	

Driver

Name of Driver SUMITRO JOYO TASLIM

NRIC No S7811979I
Date Of Birth 25/05/1978
Occupation INDOOR
Date Of Driving Pass 13/05/2015

Driving Experience 2 YEARS AND 9 MONTHS

Gender MALE

Mobile Number (LOCAL) +65-98287461

Fax Number

Contact Number OFFICE-98287461

EMail Address SUMITRO ZOEY@SINGNET.COM.SG

BLK 677C PUNGGOL DRIVE Address

#15-764

Postcode 823677

Was driver an employee of the Insured's Company NO

If No, Relationship of the Driver with the Insured **OWNER**

Vehicle Registration Number of Driver's Own

Vehicle

Insurance Company of Driver's Own Vehicle

General Information of the Accident

Type Of Accident CHAIN COLLISION

Weather Conditions **CLEAR** Road Surface DRY

Other Information

Was any foreign vehicle involved in this accident? NO

Number of vehicles involved in the accident

Was any body injured in the Accident? NO

Was any injured conveyed to hospital by

ambulance?

NO

Was any other material or property damaged? YES

I have been approached by unknown person(s) soliciting/offering accident claims assistance.

NO 1

Number of Passengers (Including Driver)

Details of Police Action

Was the accident reported to the police? NO

If Yes, Please state which Police Station

Was notice of intended Prosecution given? NO

If Yes, against whom?

Circumstances of Accident

refer to sketch plan

Attachment(s)

Are accident photos available for attachment?

YES

Was there any video captured by Car Camera?

YES

Remarks/ Reasons:

FORMATE NOT AVAILABLE VIDEO AVAILABLE UPON REQUEST

Was there any audio recorded? NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number SKT7206S Vehicle Make/Model/Colour 3RD CAR

Details Of Properties

Vehicle Category PRIVATE CAR Name of Driver NGOH CHIN HWA NRIC/Passport Number S6930134G

Contact Number

Address Postcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

DETAILS OF OTHER VEHICLE PROPERTY 2

Vehicle Registration Number Vehicle Make/Model/Colour SJY2535K 1ST CAR

Details Of Properties

Vehicle Category

PRIVATE CAR

Name of Driver

WEE SUI BOON

NRIC/Passport Number

S7819797H

Contact Number

Address Postcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

DETAILS OF OTHER VEHICLE PROPERTY 3

Vehicle Registration Number

SHC2723Z

Vehicle Make/Model/Colour

4TH CAR

Details Of Properties

Vehicle Category

PRIVATE CAR

Name of Driver

SOH KWEE SENG

NRIC/Passport Number

S1155946H

Contact Number

Address

Postcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

DETAILS OF OTHER VEHICLE PROPERTY 4

Vehicle Registration Number

SJU2474Z

Vehicle Make/Model/Colour

Details Of Properties

Vehicle Category

PRIVATE CAR

Name of Driver

RAGAVENDRAN SRINIVASAN

NRIC/Passport Number

S2728273C

Contact Number

Address Postcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

Sketch Plan #2 Pg. 1

SKETCH PLAN 15+ SKT 72065 SHC 27232 **DESCRIBE CIRCUMSTANCES OF THE ACCIDENT** chain collision was involved in 9 Mar 2018, around 6 pm Exit 3 towards TPE/CTE. There were 5 cars involved. The order follows: IC: 5781979H 1st : 574 2535 K Wee Sui Boon SLD 78444 IC: 57811979 I Sumitro Joyo Taslim my Car IC: 5693 0134G Nach Chin 3-01: SKT 7 2065 Seng 4th : SHC 27232 IC : S 1155946 H 25F585F52: JI Stinivagn Ragavendran has settled with car owner (S)YZSZSK) \$0 as he said only he was left scratch for his ear and 2 more would odge SKT 72065) claim incurred reporting 9 Mar 2018 via email ging accident on evenina 19 Mar 2018 I am inspection DECLARATION VOLKSWAGEN I/We declare the foregoing particulars are true in every respect. GROUP SINGAPORE Policyholder's Signature Drivers Signature nel's Signature 8 1 0 3 0 0 0 2 Date & Time: 17 Mgr 2018 (If driver is not the policyholder)

Date & Time: 19 Mar 2018

9am

gam

NRIC/FIN No .:



MSIG Insurance (Singapore) Pte. Ltd. 4 Shenton Way, # 21-01, SGX Centre 2, Singapore 068807 Tel +65 6827 7888, Fax +65 6827 7800 Co. Reg. No. 200412212G GST Reg. No. 20-0412212G

Certificate of Insurance

ROAD TRANSPORT ACT 1987 (MALAYSIA)

THE MOTOR VEHICLES (THIRD-PARTY RISKS) RULES, 1959 (FEDERATION OF MALAYSIA)

THE MOTOR VEHICLES (THIRD-PARTY RISKS AND COMPENSATION) ACT (CAP. 189 OF THE REVISED EDITION)

(REPUBLIC OF SINGAPORE)

THE MOTOR VEHICLES (THIRD-PARTY RISK AND COMPENSATION) RULES, 1996 EDITION (REPUBLIC OF SINGAPORE)

OR ANY AMENDMENT, ACT OR ACTS PASSED IN SUBSTITUTION THEREOF.

Form M.X.1

Individual Ownership

VW DRIVEEASY Comprehensive

Certificate No. A 28788813 AVW

Excess: SGD500

Windscreen Excess: SGD100

1. Index Mark and Registration Number of Vehicle

SLD7844Y

2. Name of Policyholder

Sumitro Joyo Taslim

Effective Date of the Commencement of Insurance for the purposes of the Act 28/06/2017

4. Date of Expiry of Insurance

27/06/2018

5. Persons or Classes of Persons entitled to drive*

Sumitro Joyo Taslim

Tan Mee Kim

Any other person provided he is driving on the Policyholder's order or with the Policyholder's permission.

- * Provided that the person driving is permitted in accordance with the licensing or other laws or laws or regulations to drive the Motor Vehicle or has been so permitted and is not disqualified by order of a Court of Law or by reason of any enactment or regulation in that behalf from driving the Motor Vehicle.
- 6. Limitations as to use*

Use only for social domestic and pleasure purposes and for the Policyholder's business. The Policy does not cover use for hire or reward racing pace-making reliability trial speed-testing the carriage of goods other than samples in connection with any trade or business or use for any purpose in connection with the Motor Trade.

Limitations rendered inoperative by Section 8 of the Motor Vehicles (Third-Party Risks and Compensation) Act (Chapter 189) and Section 95 of the Road Transport Act, 1987 (Malaysia), are not to be included under these headings.

PLEASE NOTE ALL CLAIMS RELATED REPAIR MUST BE CARRIED OUT AT VOLKSWAGEN CENTRE SINGAPORE.

This Certificate is not transferable to a new owner of the vehicle. If for any reason the Policy is terminated during its currency, the Certificate must be returned to the Insurer within 7 days of the termination or if the Certificate has been lost or destroyed, a Statutory Declaration to that effect must be made. Failure to comply with this obligation is an offence under the Motor Vehicles (Third-Party Risks and Compensation) Act (Cap. 189).

I/WE HEREBY CERTIFY that the Policy to which this Certificate relates is issued in accordance with the provisions of the Motor Vehicles (Third-Party Risks and Compensation) Act (Chapter 189) and Part IV of the Road Transport Act, 1987 (Malaysia) or any Amendment, Act or Acts passed in substitution thereof.

MSIG Insurance (Singapore) Pte. Ltd. Approved Insurers

for Chief Executive Officer



