

ASS. REC. BY:

REF: CS/EGI18005185/ Uq03n2 Special Instruction:

Surveyor: Marcel

ASSIGNMENT (Office)

From (Person): Yee Pei Li of EGI Date/Time: 20/3/18 @ 10 07am

Estimated Cost: \_\_\_\_\_ Bill to: \_\_\_\_\_

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: SLL 3066K Insured: XD 9891Eat Workshop m/s: Pegasus Engineering Tel: 6858 1846of SI Defu Lane TOPolicy No: \_\_\_\_\_ Claim No: XD 9891E / RH / p

Sum Insured: \_\_\_\_\_ Excess: \_\_\_\_\_

Make of Veh: \_\_\_\_\_ D.O.A. 17/03/18

(Client's Record)

CA / REV / REP. / REV 24 HRS

H.O.D. Endorsement: \_\_\_\_\_

Date/Time: 1:25pm @ 20/3/18 Person Contacted: William Vehicle IN OUT

| Date/Time        | Action/Instruction (✓) Estimate |
|------------------|---------------------------------|
|                  | SLL 3066K-x                     |
|                  | XD 9891E - NA. INC 16011504/h4  |
| 20/3/18 @ 5:12pm | revised to Reclaim by email.    |
|                  |                                 |
|                  |                                 |
|                  |                                 |
|                  |                                 |

D.O.A: 20/6/16

(08/11/13) wef

ASS. REC. BY: Marius

REF:

## ASSIGNMENT

From: \_\_\_\_\_ Date: \_\_\_\_\_

Estimated Cost: \_\_\_\_\_

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: SL 3066Kat Workshop m/s Pegasus

of \_\_\_\_\_

Insured: \_\_\_\_\_

Policy No. \_\_\_\_\_

Claims No. \_\_\_\_\_

Sum Insured: \_\_\_\_\_


Excess: \_\_\_\_\_

(Client's Record)

Make of Veh: \_\_\_\_\_

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Bal. or Market Value: \_\_\_\_\_

IDAC Accident Rpt: \_\_\_\_\_

Consistent? : Yes or No

GIA / PR Seen: 1

Consistent? : Yes or No

Est. Repairs: 6 days

Res.: Yes or No

Lum Sum: 20 %

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: \_\_\_\_\_ Person Contacted: \_\_\_\_\_

Vehicle: IN / OUT

Veh No: SL 3066K Yr Regn: 2 17Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /Truck / Trailer or CAMake: noode 3C.C. 1496Colour: Blue

A/C: Insured / Std / NI / NA

Sp. Reading: 94211

T/Radio: Insured / Std / NI / NA

Eng/No: \_\_\_\_\_

C/No: JM6BN22ABH0142997Gen. Cond: Good / Fair / Poor / BurntSteering: In order / Jammed / Leaked / Burnt orBrake: In order / Jammed / Leaked / Burnt orModi: Nil / S/Rim / STD A/Rim orTyre Size: F: 205-160R16

R: \_\_\_\_\_

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or Triangle

Front

Rear

R/Bal. 6 mmR/Bal. 6 mmL/Bal. 8 mmL/Bal. 6 mmD.O.A. 17/3/18D.O.I. 20/3/18

Survey held at \_\_\_\_\_

Des. of Damages: Front / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

28/3/18confirmed 45 & 4100 with willian.  
(check 371.44, 44%)

RECEIVED 04 APR 2018

Date/Time, File Pass to?

☐

: Preli. Report

1) only 4 days☐

: Final Report

Date/Time, File Return to?

2) \_\_\_\_\_

Days Of Repair: 6

Resurvey No. of Trip: \_\_\_\_\_

Add Fee:

☐

: Site Insp (\$

☐

: Interview (\$

☐

: Tech. Invs (\$

☐

: Weekend (\$

Survey Fee:

Transportation:

S + RS, SI

Photos

Others

TOTAL

250

Report Format: TPLump Sum / I.B.I: (\$ 4100)



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

ERGO INSURANCE PTE LTD

Ref : CS/EGI18005185/Uqd3

5 TEMASEK BOULEVARD  
#04-01 SUNTEC TOWER FIVE  
SINGAPORE 038985

Date : 20-03-2018



Code : EGI

### 1. Policy Particulars :- THIRD PARTY CLAIM

|              |                |                |            |
|--------------|----------------|----------------|------------|
| Insured Veh. | XD 9891E       | Veh. Inspected | SLL 3066K  |
| Policy No.   |                | Coverage (\$)  | 0.00       |
| Claim No.    | XD 9891E/RH/pl | Excess (\$)    | 0.00       |
| Assign From  | YEE PEI LI     | Assign Date    | 20/03/2018 |

### 2. Vehicle Particulars & Condition

|              |        |              |   |
|--------------|--------|--------------|---|
| Make & Model |        | c.c          | 0 |
| Engine No.   | HIDDEN | Year of Reg. |   |
| Chassis No.  |        | Colour       |   |
| Odometer     | -      | Steering     |   |
| Brakes       |        | Modification |   |
| General      |        |              |   |

### 3. Conditions of Tyres

|                | Size | Make | Balance |
|----------------|------|------|---------|
| R/H Front Tyre |      |      | mm      |
| L/H Front Tyre |      |      | mm      |
| R/H Rear Tyre  |      |      | mm      |
| L/H Rear Tyre  |      |      | mm      |

### 4. Description of Damages

|  |
|--|
|  |
|--|

### 5. General Information

|                |                                                                              |                 |            |
|----------------|------------------------------------------------------------------------------|-----------------|------------|
| Accident Date  | 17/03/2018                                                                   | Inspection Date | 20/03/2018 |
| Survey held at | PEGASUS ENGINEERING & TRADING PTE LTD<br>51 DEFU LANE 10<br>SINGAPORE 539216 |                 |            |

### 5a. Remarks

|                                                                                                                                        |
|----------------------------------------------------------------------------------------------------------------------------------------|
| A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS.<br>B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS. |
|----------------------------------------------------------------------------------------------------------------------------------------|



Auto  
Consultants  
Pte Ltd

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your Ref: XD9891E/RH/pl

Date: 21<sup>st</sup> March 2018

Our Ref: CS/EG18005185/Uqd3

The Motor Claims Department  
ERGO Insurance

Attn: Pei Li

Dear Sirs/Mdm

**PRELIMINARY ADVICE OF VEHICLE NO. SLL 3066K**


We thank you for the instruction on 20/03/2018.

Please be informed that we had conducted the inspection of the abovementioned vehicle on 20/03/2018 at the premises of M/s PEGASUS ENGINEERING and have the following to report:-

|                                 |                       |
|---------------------------------|-----------------------|
| Workshop Estimate Amount        | : S\$ <u>6,984.70</u> |
| Revised Estimate Amount         | : S\$ <u>5,364.70</u> |
| "Check" Items Amount            | : S\$ <u>-</u>        |
| Lump Sum Repair Estimate Amount | : S\$ <u>-</u>        |
| Market Value                    | : S\$ <u>-</u>        |
| LTA Reimbursement Value         | : S\$ <u>-</u>        |
| Nett Value                      | : S\$ <u>-</u>        |

Description of Damage:

The vehicle sustained damages at the o/s rear portion.



Comments/ Present Status:

Damages consistent.

Pending for some parts prices.

Days of repair: 6 days.

We have NOT authorize repair.

Yours faithfully

CHUA KANG SENG  
Licensed Appraiser

## Nivitha (LKK Auto)

---

**From:** Survey Report (ERGO Insurance Pte. Ltd.) <Survey.Report@ergo.com.sg>  
**Sent:** Tuesday, 20 March 2018 10:07 AM  
**To:** 'admin-d@lkkauto.com'  
**Subject:** OI : XD9891E / TP : SLL3066K/LKK / DOA : 17/03/2018  
**Attachments:** XD9891E - SAS.pdf; SLL3066K - SAS.pdf; SLL3066K - ESTIMATE.pdf; SLL3066K - PRS FORM.pdf; Re: Third Party Survey - SLL3066K Your Insured - XD9891E D.O.A - 17.03.2018 (24.3 KB)

Dear Catherine,

In compliance with "State Courts Practice Directions Amendment No.1 of 2016" in regards to the Pre Repair Survey, both TP repairer and ERGO Insurance Pte Ltd have agreed on your company **LKK AUTO CONSULTANTS PTE LTD** to be the "Single Joint Expert".

Please assist to conduct this survey from **PEGASUS ENGINEERING & TRADING PTE LTD,**

ADDRESS : NO 51 DEFU LANE 10  
SINGAPORE 539216

PERSON TO CONTACT : ALVIN LOW@ 6858 1846

ERGO OFFICER-IN-CHARGE : ROHAINI

***Note: To survey on DIRECT SETTLEMENT basis. Please advise the consistency of damages to third party vehicle and Inform the repairer in writing, that you are require to conduct a re-survey before vehicle is returned to claimant. They are to contact your office directly. Please do keep us in the loop.***

Please fill up the necessary on ERGO PRS Form from workshop and return to us together on your update of the survey status via [Survey.Report@ergo.com.sg](mailto:Survey.Report@ergo.com.sg).

Attached are estimate, insured and TP's SAS. (note: reports not to be released to any Third Party).

Kindly acknowledged receipt of this email.

Thank you.

**Yee Pei Li**

Claims Assistant (Motor)  
ERGO Insurance Pte. Ltd.  
5 Temasek Boulevard  
#04-01 Suntec Tower Five  
Singapore 038985  
Tel.: 65 6829 9199 DID: 65 6829 9194  
Website: [www.ergo.com.sg](http://www.ergo.com.sg)

ERGO is one of the major insurance groups in Germany and Europe. Worldwide, ERGO is represented in more than 30 countries and concentrates on Europe and Asia. ERGO is part of Munich Re (Group), one of the world's leading risk carriers.

# ERGO

Date: 19.03.2018  
Our Reference: XD 9891E/RH/pl  
Your Reference: SLL 3066K

Sent via Fax

or

Email

claims@pegasusengrg.com.sg

To: PEGASUS ENGINEERING & TRADING P/L

### Pre-Repair Survey (PRS) Acknowledgement

Vehicle For Inspection: SLL 3066K  
Insured's Vehicle: XD 9891E  
Date Of Accident: 17.03.2018

We acknowledge receipt of your request for PRS on: 19.03.2018

In compliance with "State Courts Practice Directions Amendment No.1 of 2016", do select an assessor from the list below and indicate your selection in the box marked \*.

\*

|     |                                        |     |                                |
|-----|----------------------------------------|-----|--------------------------------|
| AIS | Automobile Inspection Services Pte Ltd | LBS | L.B.S Auto Consultants Pte Ltd |
| FTA | FormTeam Consultancy Pte Ltd           | LKK | LKK Auto Consultants Pte Ltd   |
| IAS | Infiniti Appraisal Service             | PS  | Priority Services              |
| JPK | JP Knights Pte Ltd                     | VAC | Vicom Ltd                      |
|     |                                        |     |                                |

- ☒ Your request for inspection does not have your client's complete cost of repair estimate, kindly forward a copy.  
☐ Your request for inspection does not have your client's GIA report, kindly forward a copy.  
☐ We acknowledge your interest for direct settlement, we will assess & revert soon upon receipt of estimate.  
☐ Our Insured's driver has not reported the accident to us todate.

☒ Others: We write to confirm our agreement to have a direct settlement of this claim with quantum to be agreed. OFFICER-IN-CHARGE - ROHAINI

|              |                                                                                     |        |           |                    |
|--------------|-------------------------------------------------------------------------------------|--------|-----------|--------------------|
| Prepared by: |  | Pei Li | 6829 9194 | claims@ergo.com.sg |
| Signature:   |                                                                                     |        |           | FAX : 6829 9247    |

#### Assessor use only:

Assignment Date: \_\_\_\_\_  
Assignment Time: \_\_\_\_\_

Remarks:

#### Workshop use only:

##### Assessor attended workshop on:

Date: \_\_\_\_\_  
Time: \_\_\_\_\_  
Inspector: \_\_\_\_\_

☐ Vehicle not available at the appointed date and time.

Kindly acknowledge our Assessor presence for the above job .

Workshop Acknowledgement & Stamp.

Note: Our Inspection is on a without admission to liability basis.

**Shiau Chan (LKKAUTO)**

---

**From:** Shiau Chan (LKKAUTO)  
**Sent:** Wednesday, 21 March 2018 5:12 PM  
**To:** 'Survey Report (ERGO Insurance Pte. Ltd.)'; assignments; Rohaini Bte Hussain  
**Cc:** SUR  
**Subject:** RE: XD9891E / TP : SLL3066K/LKK / DOA : 17/03/2018  
**Attachments:** CSEGI18005185Uqd3.pdf

Dear Rohaini,

Enclosed herewith preliminary advice of SLL 3066K.

Best Regards,

**Shiau Chan (Ms)** | Case Handler

**LKK Auto Consultants Pte Ltd**

Phone: 6256-3561 | email: [siewsc@lkkauto.com](mailto:siewsc@lkkauto.com) | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

---

**From:** Admin-D (LKKAUTO)  
**Sent:** Tuesday, 20 March 2018 1:27 PM  
**To:** 'Survey Report (ERGO Insurance Pte. Ltd.)' <[Survey.Report@ergo.com.sg](mailto:Survey.Report@ergo.com.sg)>; assignments <[assignments@lkkauto.com](mailto:assignments@lkkauto.com)>  
**Cc:** SUR <[sur@lkkauto.com](mailto:sur@lkkauto.com)>  
**Subject:** RE: XD9891E / TP : SLL3066K/LKK / DOA : 17/03/2018

Dear Sir/Mdm,

Thank you for the assignment.

BEST REGARDS,

**G.Nivitha** | Admin

**LKK Auto Consultants Pte Ltd**

Phone: 6841-1972 | email: [assignments@lkkauto.com](mailto:assignments@lkkauto.com) | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

---

**From:** Survey Report (ERGO Insurance Pte. Ltd.) [<mailto:Survey.Report@ergo.com.sg>]  
**Sent:** Tuesday, 20 March 2018 10:07 AM  
**To:** 'admin-d@lkkauto.com' <[admin-d@lkkauto.com](mailto:admin-d@lkkauto.com)>  
**Subject:** OI : XD9891E / TP : SLL3066K/LKK / DOA : 17/03/2018

Dear Catherine,

In compliance with "State Courts Practice Directions Amendment No.1 of 2016" in regards to the Pre Repair Survey, both TP repairer and ERGO Insurance Pte Ltd have agreed on your company **LKK AUTO CONSULTANTS PTE LTD** to be the "Single Joint Expert".

Please assist to conduct this survey from **PEGASUS ENGINEERING & TRADING PTE LTD.**

ADDRESS : NO 51 DEFU LANE 10  
SINGAPORE 539216

## Enquire PARF/COE Rebate for Registered Vehicle

|                                |                                         |
|--------------------------------|-----------------------------------------|
| Vehicle Owner Particulars      |                                         |
| Owner ID Type:                 | Company                                 |
| Owner ID:                      | 7200G                                   |
| Vehicle Details                |                                         |
| Vehicle No.:                   | SLL3066K                                |
| Vehicle to be Exported:        | Yes                                     |
| Intended De-registration Date: | 17 Mar 2018                             |
| Vehicle Make:                  | MAZDA                                   |
| Vehicle Model:                 | MAZDA3 4-DOOR SEDAN<br>1.5L SP.6EAT     |
| Primary Colour:                | Blue                                    |
| Manufacturing Year:            | 2017                                    |
| Engine No.:                    | P520430458                              |
| Chassis No.:                   | JM6BN22A8H0142997                       |
| Maximum Power Output:          | 88.0 kW (118 bhp)                       |
| Open Market Value:             | \$14,951.00                             |
| Original Registration Date:    | 21 Feb 2017                             |
| First Registration Date:       | 21 Feb 2017                             |
| Transfer Count:                | 0                                       |
| Actual ARF Paid:               | \$9,951.00                              |
| Intended PARF Rebate Details   |                                         |
| PARF Eligibility:              | Yes                                     |
| PARF Eligibility Expiry Date:  | 20 Feb 2027                             |
| PARF Rebate Amount:            | \$7,463.00                              |
| Intended COE Rebate Details    |                                         |
| COE Expiry Date:               | 20 Feb 2027                             |
| COE Category:                  | A - Car up to 1600cc &<br>97kW (130bhp) |
| COE Period(Years):             | 10                                      |
| QP Paid:                       | \$48,000.00                             |
| COE Rebate Amount:             | \$38,400.00                             |
| <b>Total Rebate Amount:</b>    | <b>\$45,863.00</b>                      |

The information contained herein is correct as at 17 Mar 2018

# PEGASUS ENGINEERING & TRADING PTE LTD

GST / ROC COMPANY NO : 201101753C

## Quotation

**From :**

**PEGASUS ENGINEERING & TRADING PTE LTD**  
C/O 51 DEFU LANE 10  
539216

Officer in Charge : ALVIN LOW WAI LUN  
Tel :  
Email :

**Customer :**

**GRAB RENTALS PTE LTD**  
18 SIN MING LANE  
#01-08 MIDVIEW CITY  
SINGAPORE 573960

Attn :  
Tel :  
Fax :

*Not Alvin  
dick  
2/59  
6 days  
2013/1/1  
The other  
rep -*

|                                                                                  |                                |                       |
|----------------------------------------------------------------------------------|--------------------------------|-----------------------|
| Quotation No : QO18/03-1156                                                      | Quotation Date : 19/03/2018    | Terms : 30 DAYS       |
| Vehicle No : SLL3066K                                                            | Chassis No : JM6BN22A8H0142997 | Third Party Insurer : |
| Model : MAZDA 3                                                                  |                                | Date of Accident :    |
| Remarks : TP INSURER: ERGO, TP VEHICLE NO: XD9891E, DATE OF ACCIDENT: 17.03.2018 |                                |                       |

| ITEM | DESCRIPTION                                           | QTY | UNIT PRICE | AMOUNT (SGD) |
|------|-------------------------------------------------------|-----|------------|--------------|
| 1    | O/S REAR DOOR <i>to door</i>                          | 1   | 1,000.0000 | 1,000.00     |
| 2    | REAR DOOR INNER LOCK <i>7m/1/3m</i>                   | 1   | 180.0000   | 180.00       |
| 3    | REAR DOOR INNER LOCK STRIKER <i>11</i>                | 1   | 26.0000    | 26.00        |
| 4    | REAR DOOR WINDOW GLASS <i>Shutter</i>                 | 1   |            |              |
| 5    | REAR DOOR WINDOW GLASS CHANNEL WEATHERSTRIP <i>11</i> | 1   | 117.0000   | 117.00       |
| 6    | REAR DOOR WINDOW GLASS GARNISH FRONT <i>7m/1</i>      | 1   |            |              |
| 7    | REAR DOOR WINDOW GLASS GARNISH TOP <i>7m/1</i>        | 1   |            |              |
| 8    | REAR DOOR WINDOW GLASS 1/4 GARNISH REAR <i>11X</i>    | 1   |            |              |
| 9    | REAR DOOR OUTER WEATHERSTRIP MOLDING <i>11</i>        | 1   | 140.0000   | 140.00       |
| 10   | REAR DOOR 1/4 GLASS PILLAR <i>11</i>                  | 1   | 110.0000   | 110.00       |
| 11   | REAR DOOR 1/4 GLASS WEATHERSTRIP <i>11</i>            | 1   | 41.0000    | 41.00        |
| 12   | REAR DOOR INNER TRIMBOARD <i>w/ 11x/12</i>            | 1   | 424.0000   | 424.00       |
| 13   | REAR DOOR OUTER HANDLE <i>11X</i>                     | 1   |            |              |
| 14   | REAR DOOR OUTER HANDLE INNER BASE <i>11X</i>          | 1   |            |              |
| 15   | REAR DOOR OUTER HANDLE EXTENSION <i>11X</i>           | 1   |            |              |
| 16   | REAR DOOR POWER WINDOW MOTOR <i>3m</i>                | 1   | 290.0000   | 290.00       |
| 17   | REAR DOOR REGULATOR <i>11</i>                         | 1   | 120.7000   | 120.70       |
| 18   | REAR DOOR WEATHERSTRIP <i>11</i>                      | 1   | 121.0000   | 121.00       |
| 19   | REAR DOOR RUBBER STOPPER <i>11X</i>                   | 1   |            |              |
| 20   | REAR DOOR SIDE CATCH BOTTOM <i>11X</i>                | 1   |            |              |
| 21   | REAR DOOR CHANNEL WEATHERSTRIP <i>11X</i>             | 1   |            |              |
| 22   | REAR DOOR HINGE TOP <i>7m/1</i>                       | 1   |            |              |
| 23   | REAR DOOR HINGE BOTTOM <i>7m/1</i>                    | 1   |            |              |

C/F 0.00  
Page 1 of 3

# PEGASUS ENGINEERING & TRADING PTE LTD

GST / ROC COMPANY NO : 201101753C

## Quotation

|                                                                                                                                                                         |
|-------------------------------------------------------------------------------------------------------------------------------------------------------------------------|
| <b>From :</b><br><br><b>PEGASUS ENGINEERING &amp; TRADING PTE LTD</b><br>C/O 51 DEFU LANE 10<br>539216<br><br>Officer in Charge : ALVIN LOW WAI LUN<br>Tel :<br>Email : |
|-------------------------------------------------------------------------------------------------------------------------------------------------------------------------|

|                                                                                                                                                     |
|-----------------------------------------------------------------------------------------------------------------------------------------------------|
| <b>Customer :</b><br><br><b>GRAB RENTALS PTE LTD</b><br>18 SIN MING LANE<br>#01-08 MIDVIEW CITY<br>SINGAPORE 573960<br><br>Attn :<br>Tel :<br>Fax : |
|-----------------------------------------------------------------------------------------------------------------------------------------------------|

|                                                                                  |                                |                       |
|----------------------------------------------------------------------------------|--------------------------------|-----------------------|
| Quotation No : QO18/03-1156                                                      | Quotation Date : 19/03/2018    | Terms : 30 DAYS       |
| Vehicle No : SLL3066K                                                            | Chassis No : JM6BN22A8H0142997 | Third Party Insurer : |
| Model : MAZDA 3                                                                  | Date of Accident :             |                       |
| Remarks : TP INSURER: ERGO, TP VEHICLE NO: XD9891E, DATE OF ACCIDENT: 17.03.2018 |                                |                       |

| ITEM | DESCRIPTION                                                                                                                                                            | QTY | UNIT PRICE          | AMOUNT (SGD)        |
|------|------------------------------------------------------------------------------------------------------------------------------------------------------------------------|-----|---------------------|---------------------|
|      |                                                                                                                                                                        |     | B/F                 | 0.00                |
| 24   | REAR DOOR CHECKER/ARRESTOR <i>11X</i>                                                                                                                                  | 1   |                     |                     |
| 25   | REAR WINDSHIELD GLASS WEATHERSTRIP <i>but ✓</i>                                                                                                                        | 1   | 124.0000            | 124.00              |
| 26   | N/S REAR FENDER <i>30450/Buc ✓</i>                                                                                                                                     | 1   | 1,175.0000          | 1,175.00            |
| 27   | N/S REAR FENDER INNER LINER <i>11X</i>                                                                                                                                 | 1   | 146.0000            | 146.00              |
| 28   | REAR FENDER INNER LINER CLIPS <i>11X</i>                                                                                                                               | 4   | 5.0000              | 20.00               |
| 29   | LESS 20% (ITEMS 1-28)                                                                                                                                                  | 1   |                     |                     |
| 30   | REAR DOOR AUDIO SPEAKER <i>11X</i>                                                                                                                                     | 1   |                     |                     |
| 31   | REAR WINDSHIELD GLASS SEALANT <i>rec 405.2</i>                                                                                                                         | 1   | 180.0000            | 180.00              |
| 32   | REAR WINDSHIELD GLASS SPONGE SEAL <i>rec 30</i>                                                                                                                        | 1   | 100.0000            | 100.00              |
| 33   | PANEL BEATING, KNOCKING AND STRAIGHTEN THE NECESSARY PORTION, REMOVE AND RENEWAL OF PARTS, ADJUST AND REALIGN THE SAME AND REPAIR O/S ROCKER PANEL AND O/S FRONT DOOR. | 1   | 1,000.0000          | 1,000.00 <i>700</i> |
| 34   | PUTTY AND SPRAY PAINTING OF THE AFFECTED PORTION.                                                                                                                      | 1   | 950.0000            | 950.00 <i>700</i>   |
| 35   | TO REMOVE AND REFIT REAR WINDSCREEN GLASS.                                                                                                                             | 1   | 150.0000            | 150.00 <i>120</i>   |
| 36   | TO REMOVE AND REFIT INTERIOR FITTINGS, TRIMMINGS, GARNISH AND OTHER, TO ENABLE REPAIR.                                                                                 | 1   | 120.0000            | 120.00 <i>80</i>    |
| 37   | TO TRANSFER OF O/S REAR DOOR FITTINGS AND PERFORM WATER SEEPAGE TEST.                                                                                                  | 1   | 150.0000            | 150.00 <i>60</i>    |
| 38   | TO RUST-PROOFING OF THE AFFECTED AREAS.                                                                                                                                | 1   | 180.0000            | 180.00 <i>60</i>    |
| 39   | TO CHECK STEERING GEOMETRY AND COMPUTER WHEEL ALIGNMENT.                                                                                                               | 1   | 120.0000 <i>rec</i> | 120.00 <i>✓</i>     |

C/F 0.00

  
**PEGASUS**  
**ENGINEERING & TRADING PTE LTD**

GST / ROC COMPANY NO : 201101753C

**Quotation**

|                                                                                                                                                                         |                                                                                                                                                     |
|-------------------------------------------------------------------------------------------------------------------------------------------------------------------------|-----------------------------------------------------------------------------------------------------------------------------------------------------|
| <b>From :</b><br><br><b>PEGASUS ENGINEERING &amp; TRADING PTE LTD</b><br>C/O 51 DEFU LANE 10<br>539216<br><br>Officer in Charge : ALVIN LOW WAI LUN<br>Tel :<br>Email : | <b>Customer :</b><br><br><b>GRAB RENTALS PTE LTD</b><br>18 SIN MING LANE<br>#01-08 MIDVIEW CITY<br>SINGAPORE 573960<br><br>Attn :<br>Tel :<br>Fax : |
|-------------------------------------------------------------------------------------------------------------------------------------------------------------------------|-----------------------------------------------------------------------------------------------------------------------------------------------------|

|                                                                                         |                                       |                              |
|-----------------------------------------------------------------------------------------|---------------------------------------|------------------------------|
| <b>Quotation No :</b> QO18/03-1156                                                      | <b>Quotation Date :</b> 19/03/2018    | <b>Terms :</b> 30 DAYS       |
| <b>Vehicle No :</b> SLL3066K                                                            | <b>Chassis No :</b> JM6BN22A8H0142997 | <b>Third Party Insurer :</b> |
| <b>Model :</b> MAZDA 3                                                                  | <b>Date of Accident :</b>             |                              |
| <b>Remarks :</b> TP INSURER: ERGO, TP VEHICLE NO: XD9891E, DATE OF ACCIDENT: 17.03.2018 |                                       |                              |

| ITEM | DESCRIPTION | QTY | UNIT PRICE | AMOUNT (SGD) |
|------|-------------|-----|------------|--------------|
|      |             |     |            | B/F 0.00     |

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

|                    |          |
|--------------------|----------|
| <b>Sub Total</b>   | 6,984.70 |
| <b>GST(7.00%)</b>  | 488.93   |
| <b>Total (SGD)</b> | 7,473.63 |

Please conduct the survey at  
Pegasus Engineering @ Tan Lim Motor Pte Ltd c/o 51 Defu Lane 10 Singapore 539216

# PEGASUS ENGINEERING & TRADING PTE LTD

GST / ROC COMPANY NO : 201101753C

## Quotation

|                                                                                                                                                                 |                                                                                                                                             |
|-----------------------------------------------------------------------------------------------------------------------------------------------------------------|---------------------------------------------------------------------------------------------------------------------------------------------|
| <b>From :</b><br><b>PEGASUS ENGINEERING &amp; TRADING PTE LTD</b><br>C/O 51 DEFU LANE 10<br>539216<br>Officer in Charge : ALVIN LOW WAI LUN<br>Tel :<br>Email : | <b>Customer :</b><br><b>GRAB RENTALS PTE LTD</b><br>18 SIN MING LANE<br>#01-08 MIDVIEW CITY<br>SINGAPORE 573960<br>Attn :<br>Tel :<br>Fax : |
|-----------------------------------------------------------------------------------------------------------------------------------------------------------------|---------------------------------------------------------------------------------------------------------------------------------------------|

|                                                                                         |                                       |                              |
|-----------------------------------------------------------------------------------------|---------------------------------------|------------------------------|
| <b>Quotation No :</b> QO18/03-1156                                                      | <b>Quotation Date :</b> 19/03/2018    | <b>Terms :</b> 30 DAYS       |
| <b>Vehicle No :</b> SLL3066K                                                            | <b>Chassis No :</b> JM6BN22A8H0142997 | <b>Third Party Insurer :</b> |
| <b>Model :</b> MAZDA 3                                                                  | <b>Date of Accident :</b>             |                              |
| <b>Remarks :</b> TP INSURER: ERGO, TP VEHICLE NO: XD9891E, DATE OF ACCIDENT: 17.03.2018 |                                       |                              |

| ITEM | DESCRIPTION                                           | QTY | UNIT PRICE | AMOUNT (SGD) |
|------|-------------------------------------------------------|-----|------------|--------------|
| 1    | O/S REAR DOOR <i>Body</i>                             | 1   | 1,000.0000 | 1,000.00     |
| 2    | REAR DOOR INNER LOCK <i>Tw/3m</i>                     | 1   | 180.0000   | 180.00       |
| 3    | REAR DOOR INNER LOCK STRIKER <i>11</i>                | 1   | 26.0000    | 26.00        |
| 4    | REAR DOOR WINDOW GLASS <i>shattered</i>               | 1   | 285.0000   | 285.00       |
| 5    | REAR DOOR WINDOW GLASS CHANNEL WEATHERSTRIP <i>11</i> | 1   | 117.0000   | 117.00       |
| 6    | REAR DOOR WINDOW GLASS GARNISH FRONT <i>Tw/1</i>      | 1   | 111.0000   | 111.00       |
| 7    | REAR DOOR WINDOW GLASS GARNISH TOP <i>Tw/1</i>        | 1   | 71.4000    | 71.40        |
| 8    | REAR DOOR WINDOW GLASS 1/4 GARNISH REAR <i>11</i>     | 1   | 75.0000    | 75.00        |
| 9    | REAR DOOR OUTER WEATHERSTRIP MOLDING <i>3m</i>        | 1   | 140.0000   | 140.00       |
| 10   | REAR DOOR 1/4 GLASS PILLAR <i>11</i>                  | 1   | 110.0000   | 110.00       |
| 11   | REAR DOOR 1/4 GLASS WEATHERSTRIP <i>11</i>            | 1   | 41.0000    | 41.00        |
| 12   | REAR DOOR INNER TRIMBOARD <i>neg 1/2</i>              | 1   | 424.0000   | 424.00       |
| 13   | REAR DOOR OUTER HANDLE <i>11</i>                      | 1   | 65.7000    | 65.70        |
| 14   | REAR DOOR OUTER HANDLE INNER BASE <i>11</i>           | 1   | 57.0000    | 57.00        |
| 15   | REAR DOOR OUTER HANDLE EXTENSION <i>11</i>            | 1   | 18.0000    | 18.00        |
| 16   | REAR DOOR POWER WINDOW MOTOR <i>3m</i>                | 1   | 290.0000   | 290.00       |
| 17   | REAR DOOR REGULATOR <i>3m</i>                         | 1   | 120.7000   | 120.70       |
| 18   | REAR DOOR WEATHERSTRIP <i>11</i>                      | 1   | 121.0000   | 121.00       |
| 19   | REAR DOOR RUBBER STOPPER <i>11</i>                    | 1   | 6.0000     | 6.00         |
| 20   | REAR DOOR SIDE CATCH BOTTOM <i>11</i>                 | 1   | 15.0000    | 15.00        |
| 21   | REAR DOOR CHANNEL WEATHERSTRIP <i>11</i>              | 1   | 50.0000    | 50.00        |
| 22   | REAR DOOR HINGE TOP <i>Tw/1</i>                       | 1   | 46.0000    | 46.00        |
| 23   | REAR DOOR HINGE BOTTOM <i>Tw/1</i>                    | 1   | 58.0000    | 58.00        |

C/F 0.00

Page 1 of 3

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

*Not Allowed*  
*1/5 @ 4100*  
*6 day.*  
*20/3/18*  
*To be paid After rep.*

# PEGASUS ENGINEERING & TRADING PTE LTD

GST / ROC COMPANY NO : 201101753C

## Quotation

|                                                                                                                                                                         |                                                                                                                                                     |
|-------------------------------------------------------------------------------------------------------------------------------------------------------------------------|-----------------------------------------------------------------------------------------------------------------------------------------------------|
| <b>From :</b><br><br><b>PEGASUS ENGINEERING &amp; TRADING PTE LTD</b><br>C/O 51 DEFU LANE 10<br>539216<br><br>Officer in Charge : ALVIN LOW WAI LUN<br>Tel :<br>Email : | <b>Customer :</b><br><br><b>GRAB RENTALS PTE LTD</b><br>18 SIN MING LANE<br>#01-08 MIDVIEW CITY<br>SINGAPORE 573960<br><br>Attn :<br>Tel :<br>Fax : |
|-------------------------------------------------------------------------------------------------------------------------------------------------------------------------|-----------------------------------------------------------------------------------------------------------------------------------------------------|

|                                                                                  |                                |                       |
|----------------------------------------------------------------------------------|--------------------------------|-----------------------|
| Quotation No : QO18/03-1156                                                      | Quotation Date : 19/03/2018    | Terms : 30 DAYS       |
| Vehicle No : SLL3066K                                                            | Chassis No : JM6BN22A8H0142997 | Third Party Insurer : |
| Model : MAZDA 3                                                                  | Date of Accident :             |                       |
| Remarks : TP INSURER: ERGO, TP VEHICLE NO: XD9891E, DATE OF ACCIDENT: 17.03.2018 |                                |                       |

| ITEM | DESCRIPTION                                                                                                                                                            | QTY | UNIT PRICE  | AMOUNT (SGD) |       |
|------|------------------------------------------------------------------------------------------------------------------------------------------------------------------------|-----|-------------|--------------|-------|
|      |                                                                                                                                                                        |     |             | B/F          | 0.00  |
| 24   | REAR DOOR CHECKER/ARRESTOR <i>11</i>                                                                                                                                   | 1   | 124.0000    | 124.00       | X     |
| 25   | REAR WINDSHIELD GLASS WEATHERSTRIP <i>5ul</i>                                                                                                                          | 1   | 124.0000    | 124.00       | —     |
| 26   | N/S REAR FENDER <i>5.650/3ul</i>                                                                                                                                       | 1   | 1,175.0000  | 1,175.00     | ✓     |
| 27   | N/S REAR FENDER INNER LINER <i>11</i>                                                                                                                                  | 1   | 146.0000    | 146.00       | X     |
| 28   | REAR FENDER INNER LINER CLIPS <i>11</i>                                                                                                                                | 4   | 5.0000      | 20.00        | X     |
| 29   | LESS 20% (ITEMS 1-28)                                                                                                                                                  | 1   | -1,003.3600 | -1,003.36    |       |
| 30   | REAR DOOR AUDIO SPEAKER <i>11</i>                                                                                                                                      | 1   | 350.0000    | 350.00       | X     |
| 31   | REAR WINDSHIELD GLASS SEALANT <i>11</i>                                                                                                                                | 1   | 180.0000    | 180.00       | 405.~ |
| 32   | REAR WINDSHIELD GLASS SPONGE SEAL <i>11</i>                                                                                                                            | 1   | 100.0000    | 100.00       | 305.~ |
| 33   | PANEL BEATING, KNOCKING AND STRAIGHTEN THE NECESSARY PORTION, REMOVE AND RENEWAL OF PARTS, ADJUST AND REALIGN THE SAME AND REPAIR O/S ROCKER PANEL AND O/S FRONT DOOR. | 1   | 1,000.0000  | 1,000.00     | 700   |
| 34   | PUTTY AND SPRAY PAINTING OF THE AFFECTED PORTION.                                                                                                                      | 1   | 950.0000    | 950.00       | 700   |
| 35   | TO REMOVE AND REFIT REAR WINDSCREEN GLASS.                                                                                                                             | 1   | 150.0000    | 150.00       | 120   |
| 36   | TO REMOVE AND REFIT INTERIOR FITTINGS, TRIMMINGS, GARNISH AND OTHER, TO ENABLE REPAIR.                                                                                 | 1   | 120.0000    | 120.00       | 80    |
| 37   | TO TRANSFER OF O/S REAR DOOR FITTINGS AND PERFORM WATER SEEPAGE TEST.                                                                                                  | 1   | 150.0000    | 150.00       | 60    |
| 38   | TO RUST-PROOFING OF THE AFFECTED AREAS.                                                                                                                                | 1   | 180.0000    | 180.00       | 80    |
| 39   | TO CHECK STEERING GEOMETRY AND COMPUTER WHEEL ALIGNMENT. <i>11</i>                                                                                                     | 1   | 120.0000    | 120.00       | X     |

C/F 0.00  
Page 2 of 3

*4146.1  
3316.88*

*5126.88*

  
**PEGASUS**  
**ENGINEERING & TRADING PTE LTD**

GST / ROC COMPANY NO : 201101753C

**Quotation**

|                                                                                                                                                          |                                                                                                                                          |
|----------------------------------------------------------------------------------------------------------------------------------------------------------|------------------------------------------------------------------------------------------------------------------------------------------|
| <b>From :</b><br>PEGASUS ENGINEERING & TRADING PTE LTD<br>C/O 51 DEFU LANE 10<br>539216<br><br>Officer in Charge : ALVIN LOW WAI LUN<br>Tel :<br>Email : | <b>Customer :</b><br>GRAB RENTALS PTE LTD<br>18 SIN MING LANE<br>#01-08 MIDVIEW CITY<br>SINGAPORE 573960<br><br>Attn :<br>Tel :<br>Fax : |
|----------------------------------------------------------------------------------------------------------------------------------------------------------|------------------------------------------------------------------------------------------------------------------------------------------|

|                                                                                  |                                |                       |
|----------------------------------------------------------------------------------|--------------------------------|-----------------------|
| Quotation No : QO18/03-1156                                                      | Quotation Date : 19/03/2018    | Terms : 30 DAYS       |
| Vehicle No : SLL3066K                                                            | Chassis No : JM6BN22A8H0142997 | Third Party Insurer : |
| Model : MAZDA 3                                                                  | Date of Accident :             |                       |
| Remarks : TP INSURER: ERGO, TP VEHICLE NO: XD9891E, DATE OF ACCIDENT: 17.03.2018 |                                |                       |

| ITEM | DESCRIPTION | QTY | UNIT PRICE | AMOUNT (SGD) |
|------|-------------|-----|------------|--------------|
|      |             |     |            | B/F 0.00     |

|                    |          |
|--------------------|----------|
| <b>Sub Total</b>   | 7,313.44 |
| <b>GST(7.00%)</b>  | 511.94   |
| <b>Total (SGD)</b> | 7,825.38 |

Please conduct the survey at  
Pegasus Engineering @ Tan Lim Motor Pte Ltd c/o 51 Defu Lane 10 Singapore 539216



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

| Affiliated to Federation Internationale Des Experts En Automobile                                                                         |                                                                              |                             |            |                                                                                     |
|-------------------------------------------------------------------------------------------------------------------------------------------|------------------------------------------------------------------------------|-----------------------------|------------|-------------------------------------------------------------------------------------|
| ERGO INSURANCE PTE LTD                                                                                                                    |                                                                              | Ref : CS/EGI18005185/Uqd3n2 |            |                                                                                     |
| 5 TEMASEK BOULEVARD<br>#04-01 SUNTEC TOWER FIVE<br>SINGAPORE 038985                                                                       |                                                                              | Date : 09-04-2018           |            |  |
|                                                                                                                                           |                                                                              | Code : EGI                  |            |                                                                                     |
| <b>1. Policy Particulars :- THIRD PARTY CLAIM</b>                                                                                         |                                                                              |                             |            |                                                                                     |
| Insured Veh.                                                                                                                              | XD 9891E                                                                     | Veh. Inspected              | SLL 3066K  |                                                                                     |
| Policy No.                                                                                                                                |                                                                              | Coverage (\$)               | 0.00       |                                                                                     |
| Claim No.                                                                                                                                 | XD 9891E/RH/pl                                                               | Excess (\$)                 | 0.00       |                                                                                     |
| Assign From                                                                                                                               | YEE PEI LI                                                                   | Assign Date                 | 20/03/2018 |                                                                                     |
| <b>2. Vehicle Particulars &amp; Condition</b>                                                                                             |                                                                              |                             |            |                                                                                     |
| Make & Model                                                                                                                              | MAZDA 3 (A)                                                                  | c.c                         | 1496       |                                                                                     |
| Engine No.                                                                                                                                | HIDDEN                                                                       | Year of Reg.                | 2017       |                                                                                     |
| Chassis No.                                                                                                                               | JM6BN22A8H0142997                                                            | Colour                      | BLUE       |                                                                                     |
| Odometer                                                                                                                                  | 94211                                                                        | Steering                    | IN ORDER   |                                                                                     |
| Brakes                                                                                                                                    | IN ORDER                                                                     | Modification                | NIL        |                                                                                     |
| General                                                                                                                                   | GOOD                                                                         |                             |            |                                                                                     |
| <b>3. Conditions of Tyres</b>                                                                                                             |                                                                              |                             |            |                                                                                     |
|                                                                                                                                           | Size                                                                         | Make                        | Balance    |                                                                                     |
| R/H Front Tyre                                                                                                                            | 205/60 R16                                                                   | TRIANGLE                    | 6 mm       |                                                                                     |
| L/H Front Tyre                                                                                                                            | 205/60 R16                                                                   | TRIANGLE                    | 6 mm       |                                                                                     |
| R/H Rear Tyre                                                                                                                             | 205/60 R16                                                                   | TRIANGLE                    | 6 mm       |                                                                                     |
| L/H Rear Tyre                                                                                                                             | 205/60 R16                                                                   | TRIANGLE                    | 6 mm       |                                                                                     |
| <b>4. Description of Damages</b>                                                                                                          |                                                                              |                             |            |                                                                                     |
| THE VEHICLE SUSTAINED DAMAGES AT THE O/S REAR PORTION.<br>DAMAGES SEE DETAILS.                                                            |                                                                              |                             |            |                                                                                     |
| <b>5. General Information</b>                                                                                                             |                                                                              |                             |            |                                                                                     |
| Accident Date                                                                                                                             | 17/03/2018                                                                   | Inspection Date             | 20/03/2018 |                                                                                     |
| Survey held at                                                                                                                            | PEGASUS ENGINEERING & TRADING PTE LTD<br>51 DEFU LANE 10<br>SINGAPORE 539216 |                             |            |                                                                                     |
| <b>5a. Remarks</b>                                                                                                                        |                                                                              |                             |            |                                                                                     |
| A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.<br>B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS. |                                                                              |                             |            |                                                                                     |
| <b>5b. Estimate Days of Repair</b>                                                                                                        |                                                                              |                             |            |                                                                                     |
| ESTIMATED NORMAL PERIOD FOR REPAIR:                                                                                                       |                                                                              | 6 Working Days              |            |                                                                                     |



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

## ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLL 3066K

| Qty | Description of Parts                        | Condition              | Estimate By Workshop (\$) | Our Adjusted (\$) |
|-----|---------------------------------------------|------------------------|---------------------------|-------------------|
|     | <b>REPLACEMENT OF PARTS</b>                 |                        |                           |                   |
| 1   | O/S REAR DOOR                               | BADLY DENTED           | 1,000.00                  | 1,000.00          |
| 1   | REAR DOOR INNER LOCK                        | TWISTED / JAMMED       | 180.00                    | 180.00            |
| 1   | REAR DOOR INNER LOCK STRIKER                | NOT NECESSARY          | 26.00                     | -                 |
| 1   | REAR DOOR WINDOW GLASS                      | SHATTERED              | 285.00                    | 285.00            |
| 1   | REAR DOOR WINDOW GLASS CHANNEL WEATHERSTRIP | NOT NECESSARY          | 117.00                    | -                 |
| 1   | REAR DOOR WINDOW GLASS GARNISH FRONT        | TWISTED                | 111.00                    | 111.00            |
| 1   | REAR DOOR WINDOW GLASS GARNISH TOP          | TWISTED                | 71.40                     | 71.40             |
| 1   | REAR DOOR WINDOW GLASS 1/4 GARNISH REAR     | NOT NECESSARY          | 75.00                     | -                 |
| 1   | REAR DOOR OUTER WEATHERSTRIP MOLDING        | BENT                   | 140.00                    | 140.00            |
| 1   | REAR DOOR 1/4 GLASS PILLAR                  | NOT NECESSARY          | 110.00                    | -                 |
| 1   | REAR DOOR 1/4 GLASS WEATHERSTRIP            | NOT NECESSARY          | 41.00                     | -                 |
| 1   | REAR DOOR INNER TRIMBOARD                   | WARPED / DEFORMED      | 424.00                    | 424.00            |
| 1   | REAR DOOR OUTER HANDLE                      | NOT NECESSARY          | 65.70                     | -                 |
| 1   | REAR DOOR OUTER HANDLE INNER BASE           | NOT NECESSARY          | 57.00                     | -                 |
| 1   | REAR DOOR OUTER HANDLE EXTENSION            | NOT NECESSARY          | 18.00                     | -                 |
| 1   | REAR DOOR POWER WINDOW MOTOR                | JAMMED                 | 290.00                    | 290.00            |
| 1   | REAR DOOR REGULATOR                         | BENT                   | 120.70                    | 120.70            |
| 1   | REAR DOOR WEATHERSTRIP                      | NECESSARY              | 121.00                    | 121.00            |
| 1   | REAR DOOR RUBBER STOPPER                    | NOT NECESSARY          | 6.00                      | -                 |
| 1   | REAR DOOR SIDE CATCH BOTTOM                 | NOT NECESSARY          | 15.00                     | -                 |
| 1   | REAR DOOR CHANNEL WEATHERSTRIP              | NOT NECESSARY          | 50.00                     | -                 |
| 1   | REAR DOOR HINGE TOP                         | TWISTED                | 46.00                     | 46.00             |
| 1   | REAR DOOR HINGE BOTTOM                      | TWISTED                | 58.00                     | 58.00             |
| 1   | REAR DOOR CHECKER/ARRESTOR                  | NOT NECESSARY          | 124.00                    | -                 |
| 1   | REAR WINDSHIELD GLASS WEATHERSTRIP          | BENT                   | 124.00                    | 124.00            |
| 1   | N/S REAR FENDER                             | BADLY DENTED / BUCKLED | 1,175.00                  | 1,175.00          |
| 1   | N/S REAR FENDER INNER LINER                 | NOT NECESSARY          | 146.00                    | -                 |
| 4   | REAR FENDER INNER LINER CLIPS @\$5.00       | NOT NECESSARY          | 20.00                     | -                 |

Report Ref No. CS/EG18005185/Uqd3n2



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

| Qty                                                                         | Description of Parts                                                                                                                                                | Condition     | Estimate By Workshop (\$) | Our Adjusted (\$) |
|-----------------------------------------------------------------------------|---------------------------------------------------------------------------------------------------------------------------------------------------------------------|---------------|---------------------------|-------------------|
|                                                                             | LESS 20% DISCOUNT                                                                                                                                                   |               | -1,003.36                 | -829.22           |
|                                                                             |                                                                                                                                                                     |               | 4,013.44                  | 3,316.88          |
|                                                                             | <b>SPECIAL NETT ITEMS</b>                                                                                                                                           |               |                           |                   |
| 1                                                                           | REAR DOOR AUDIO SPEAKER (SN)                                                                                                                                        | NOT NECESSARY | 350.00                    | -                 |
| 1                                                                           | REAR WINDSHIELD GLASS SEALANT (SN)                                                                                                                                  | NECESSARY     | 180.00                    | 40.00             |
| 1                                                                           | REAR WINDSHIELD GLASS SPONGE SEAL (SN)                                                                                                                              | NECESSARY     | 100.00                    | 30.00             |
|                                                                             |                                                                                                                                                                     |               | 630.00                    | 70.00             |
|                                                                             | <b>LABOUR</b>                                                                                                                                                       |               |                           |                   |
|                                                                             | PANEL BEATING,KNOCKING AND STRAIGHTEN THE NECESSARY PORTION,REMOVE AND RENEWAL OF PARTS,ADJUST AND REALIGN THE SAME AND REPAIR O/S ROCKER PANEL AND O/S FRONT DOOR. |               | 1,000.00                  | 700.00            |
|                                                                             | PUTTY AND SPRAY PAINTING OF THE AFFECTED PORTION.                                                                                                                   |               | 950.00                    | 700.00            |
|                                                                             | TO REMOVE AND REFIT REAR WINDSCREEN GLASS.                                                                                                                          |               | 150.00                    | 120.00            |
|                                                                             | TO REMOVE AND REFIT INTERIOR FITTINGS,TRIMMINGS,GARNISH AND OTHER,TO ENABLE REPAIR.                                                                                 |               | 120.00                    | 80.00             |
|                                                                             | TO TRANSFER OF O/S REAR DOOR FITTINGS AND PERFORM WATER SEEPAGE TEST.                                                                                               |               | 150.00                    | 60.00             |
|                                                                             | TO RUST-PROOFING OF THE AFFECTED AREAS.                                                                                                                             |               | 180.00                    | 80.00             |
|                                                                             | TO CHECK STEERING GEOMETRY AND COMPUTER WHEEL ALIGNMENT.                                                                                                            | NOT NECESSARY | 120.00                    | -                 |
|                                                                             |                                                                                                                                                                     |               | 2,670.00                  | 1,740.00          |
|                                                                             | <b>GRAND TOTAL</b>                                                                                                                                                  |               | <b>7,313.44</b>           | <b>5,126.88</b>   |
| <b>RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)</b> |                                                                                                                                                                     |               |                           | <b>4,100.00</b>   |

Report Ref No. CS/EG18005185/Uqd3n2

CHUA KANG SENG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.