

Muslim

Special Instructions

ASSIGNMENT (Office)

US\$ 400.00

### Third Parties

### Claimants

Surveyor: Auto Performance

Workshop: King's Auto

OD/TP Re-inspection / (Evaluation)

To Inspect Vehicle No: SCM 7857m Insured: SKS 3706Y

at Workshop m/s King's Auto Tel: 0157 8629

of 176 Sin Ming Ave # 03-10

Policy No: \_\_\_\_\_ Claim No: 552933

Sum Insured: \_\_\_\_\_ Excess: \_\_\_\_\_

Make of Veh: \_\_\_\_\_ DOA: 1513208

(Client's Record)

Don't finalize  
H.O.D. Enforcement/Date:

Date/Time: \_\_\_\_\_ Person Contacted: \_\_\_\_\_ Vehicle IN / OUT \_\_\_\_\_

Date/Time: 1/12 Confirmed with 118 Final Fig         ,          days (Red \$          /          %; Original 6 days)

Date/Time: 12/6/18 Submit Final Fig 3100.00, 5 days (Red \$ 1000 / 24 %; Original 6 days)

RECEIVED 12 JUN 2018

Para(1) : Parts found not replaced	(To highlight <i>R or UB, LR, Etc</i> )
------------------------------------	---

Para(2) : Comments on consistency of damages (Parts Not Consistent : NC)
--

**Para(3) : Nett Value**

Market Value : \_\_\_\_\_

Salvage Value :

Nett Value	1
------------	---

1) Date/Time 12/6/18 File Pass to Aug 1st

3) Date/Time \_\_\_\_\_ File Pass to \_\_\_\_\_

5) Date/Time \_\_\_\_\_ File Pass to \_\_\_\_\_

Inspected/  
Evaluated by:

*Fee Charged:*

Basic &amp; Add

Transport

### Photos

Others

Total

Date: \_\_\_\_\_

2) Date/Time

File Return to

#### 4) Date/Time

File Return to

6) Date/Time

File Return to:



## Catherine Chong (LKK Auto)

---

**From:** Pang Xiu Shi <xiushi\_pang@sg.msig-asia.com>  
**Sent:** Friday, 18 May, 2018 5:58 PM  
**To:** assignments  
**Cc:** Catherine Thia  
**Subject:** Paper Survey for SGW7557M  
**Attachments:** SGM7557M E-FILE REPORT.pdf; OI SKS3706Y E-FILE REPORT.pdf; TP Survey Report.pdf

Dear LKK,

We would like to appoint your firm to do a paper survey on the third party's vehicle.

Our Claim Ref No: 552933

Please see attach the following documents:

- 1) OI SKS3706Y GIA Report
- 2) TP SGW7557M GIA Report
- 3) TP Survey Report

Please acknowledge upon receipt of the assignment.

Thank you !

*Have a great week ahead!*

Pang Xiu Shi

Admin Officer, Claims Services (Motor)

Direct line +65 6594 2586 | Direct fax +65 6225 7402 | [xiushi\\_pang@sg.msig-asia.com](mailto:xiushi_pang@sg.msig-asia.com)



**MSIG**



Insurer Claims  
Team of the Year  
2016

MSIG Insurance (Singapore) Pte Ltd 16 Raffles Quay, #24-01 Hong Leong Building, Singapore 048581 | T: +65 6220 9644 | F: +65 6225 6371 | Co. Reg. No. 200412212G | [msig.com.sg](http://msig.com.sg)



A Member of **MS&AD** INSURANCE GROUP

---

### CONFIDENTIALITY NOTICE

This e-mail (including any attachments) may contain information that is privileged or confidential. The sending of this e-mail to any person other than the intended recipient is not a waiver of the privilege or confidentiality that attaches to it. If you are not the intended recipient, please notify the sender immediately, delete the email and do not copy, distribute or disclose its contents.

ASS. REC BY

REF

c83/MSG18005190/Gd3

Special Instructions

SURVEYOR  
Mennen

GR

ASSIGNMENT (Office)

From (Person)

Catherine Thia

of

MSG

Date/Time

20/3/18 @ 1:11pm

Estimated Cost

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SGM7557M

Insured:

SKS3706Y

at Workshop m/s

King's Auto

Tel:

64578629

of

Blk 176 Sin Ming Drive # 02-10

Policy No:

29040568 MCY

Claim No:

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A

15/3/18

CA / REV / REP. / REV 24 HRS

'wp'

H.O.D. Endorsement

Date/Time

2:50pm @ 20/3/18

Person Contacted:

Annie

Vehicle

IN OUT

Date/Time

Action/Instruction (X) Estimate

SGM7557M-x

SKS3706Y-NBA/MSG118005023/Y

D.O.A: 15/3/18

## ...CLAIM SUBFOLDER...(New Assignment)

### CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	20 Mar 2018		20 Mar 2018 13:11 <a href="#">Assign</a>				<b>New Assignment</b> <a href="#">Cancel Case</a>

Main

Reference

Claim Details

Documents

[Show All](#)

### CLAIM SUBFOLDER DETAILS

[Created by insurer]

Insured:	SIME DARBY SERVICES PTE LTD, Co. Reg. No.: 197501065W		
Main Claimant:	NG ZHEREN NIGEL, ID: S8633994C		
Vehicle Reg. No.:	SGM7557M	Date of Loss:	15/03/2018 00:00 - :59
Claim Type:	TP	Policy/Cover Note No.:	29040568MCY Coverage: 01/10/2017 - 30/09/2018
Vehicle Reg. No. (Insured):	SKS3706Y	Policy No. (Claimant):	
		Excess:	
Repairer:	Kings Auto Air-conditioning Service (HQ) Blk 176 Sin Ming Dr #02-10 Singapore 575721, 575721 Sin Ming - Tel:		
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Catherine Thia Shi Yi - 6594 2545]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Imm.Advice due 21/03/2018]		
Driver/Custodian (Insured):	MUHAMMAD HAMDAN FATHULLAH BIN ABDUL HALIM (), NRIC: S9411637F		

### ASSOCIATED MAIL RECEIVED

[View All](#)[Compose Case Mail](#)

There are no mail for this case.

### ALL ASSOCIATED TASKS

[View All](#)[Search Tasks](#)[Create New Task](#)[Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

**Pang Xiu Shi**

---

**From:** Kuru & Co <kurulegal@yahoo.com.sg>  
**Sent:** Tuesday, 20 March, 2018 2:03 PM  
**To:** Pang Xiu Shi  
**Subject:** Re: RE: Our ref: SKS3706Y DOA: 15/03/2018 Your ref: L18.0472.AT

Hi Xiu Shi

We confirm that you have objected to our client's list of surveyors. Our client's vehicle is at the following address:

**KING'S AUTO AIR-CONDITIONING SERVICE**

**Blk 176 Sin Ming Drive  
#02-10 Sin Ming Autocare  
Singapore 575721  
Tel: 6457 8629**

Please inform your surveyor to conduct the pre-repair survey within 2 working days, failing which our client will have no alternative but to proceed with the repair of his vehicle.

Best regards  
Anne  
Kuru & Co  
150 South Bridge Road  
#04-06 Fook Hai Building  
Singapore 058727  
Tel: 6532 2009  
Fax: 6532 2007

On Tuesday, 20 March 2018 01:35:17 PM, Pang Xiu Shi <xiushi\_pang@sg.msig-asia.com> wrote:

Dear Anne,

Please also provide me with the workshop details. Thank You.

**Have a great week ahead!**

**Pang Xiu Shi**

Admin Officer, Claims Services (Motor)



Insurer Claims  
Team of the Year  
2016

**MSIG Insurance (Singapore) Pte Ltd** 16 Raffles Quay, #24-01 Hong Leong Building, Singapore 048581 | T: +65 6220 9644 | F: +65 6225 6371 | Co. Reg. No. 200412212G | [msig.com.sg](http://msig.com.sg)



A Member of **MS&AD** INSURANCE GROUP

---

**From:** Pang Xiu Shi  
**Sent:** Tuesday, 20 March, 2018 1:10 PM  
**To:** 'Kuru & Co' <[kurulegal@yahoo.com.sg](mailto:kurulegal@yahoo.com.sg)>; [kurulegal@yahoo.com](mailto:kurulegal@yahoo.com)  
**Cc:** Catherine Thia <[catherine\\_thia@sg.msig-asia.com](mailto:catherine_thia@sg.msig-asia.com)>  
**Subject:** RE: Our ref: SKS3706Y DOA: 15/03/2018 Your ref: L.18.0472.AT

Hi Anne,

We refer to your email dated 20/03/2018.

We regret to inform you that we are unable to accept your list of nominated Single Joint Experts( SJE)

We will proceed to appoint the following surveyor **LKK Auto Consultants Pte Ltd** for your claim.

Please be informed that our surveyor will also be conducting the post repair inspection within the timeline stipulated under the protocol.

Thank you.

Have a great week ahead!

Pang Xiu Shi

Admin Officer, Claims Services (Motor)

Direct line +65 6594 2586 | Direct fax +65 6225 7402 | [xiushi\\_pang@sg.msig-asia.com](mailto:xiushi_pang@sg.msig-asia.com)



MSIG



Insurer Claims  
Team of the Year  
2016

**MSIG Insurance (Singapore) Pte Ltd** 16 Raffles Quay, #24-01 Hong Leong Building, Singapore 048581 | T: +65 6220 9644 | F: +65 6225 6371 | Co. Reg. No. 200412212G | [msig.com.sg](http://msig.com.sg)



A Member of **MS&AD** INSURANCE GROUP

---

**From:** Kuru & Co [<mailto:kurulegal@yahoo.com.sg>]  
**Sent:** Tuesday, 20 March, 2018 11:26 AM  
**To:** [kurulegal@yahoo.com](mailto:kurulegal@yahoo.com); Pang Xiu Shi <[xiushi\\_pang@sg.msig-asia.com](mailto:xiushi_pang@sg.msig-asia.com)>  
**Cc:** Catherine Thia <[catherine\\_thia@sg.msig-asia.com](mailto:catherine_thia@sg.msig-asia.com)>  
**Subject:** Re: Our ref: SKS3706Y DOA: 15/03/2018 Your ref: L.18.0472.AT

Dear Sirs

Our client is objecting to your list of surveyors. Attached is our client's list of proposed surveyors for your consideration.

Please state the surveyor you will be appointing to be the single joint expert or that you are objecting to our client's proposed list of surveyors.

If we do not hear from you within 2 working days, it shall be deemed that you have agreed to the appointment of any of the surveyors listed by our client.



Best regards

Anne

Kuru & Co  
150 South Bridge Road  
#04-06 Fook Hai Building  
Singapore 058727  
Tel: 6532 2009  
Fax: 6532 2007

On Tuesday, 20 March 2018 11:15:12 AM, Pang Xiu Shi <[xiushi\\_pang@sg.msig-asia.com](mailto:xiushi_pang@sg.msig-asia.com)> wrote:

Dear Sirs

We refer to your email dated 20/03/2018.

Please choose one surveyor from the list that you wish for us to appoint to conduct the pre-repair inspection:

- 1) LKK Auto Consultants Pte Ltd
- 2) Formteam Consultancy Pte Ltd
- 3) Automobile Inspection Services Pte Ltd

To facilitate an expeditious claim settlement, we hope you are agreeable for the above surveyor to be the SJE (Single Joint Expert)

If not, you may wish to nominate any of the 10 surveyors listed below as the SJE, depending on their availability:

1. Adrian Ling	6. Frankie Pang
2. Kenneth Kong	7. Ng You Han
3. Marcus Chua	8. Gary Soon
4. Henry Ng	9. Chow Bo Xiong
5. Lau Kwok Kwong	10. Benjamin Chua

NB: If both of us could not agree with each other's list of nominated SJE, we may still proceed to appoint a motor surveyor to conduct a pre repair survey & post repair inspection within the timeline stipulated under the NIMA protocol.

Thank You.

Have a great week ahead!

Pang Xiu Shi

Admin Officer, Claims Services (Motor)

Direct line +65 6594 2586 | Direct fax +65 6225 7402 | [xiushi\\_pang@sg.msig-asia.com](mailto:xiushi_pang@sg.msig-asia.com)



**MSIG**



Insurer Claims  
Team of the Year  
2016

**MSIG Insurance (Singapore) Pte Ltd** 16 Raffles Quay, #24-01 Hong Leong Building, Singapore 048581 | T: +65 6220 9644 | F: +65 6225 6371 | Co. Reg. No. 200412212G | [msig.com.sg](http://msig.com.sg)



A Member of **MS&AD** INSURANCE GROUP

---

**CONFIDENTIALITY NOTICE**

This e-mail (including any attachments) may contain information that is privileged or confidential. The sending of this e-mail to any person other than the intended recipient is not a waiver of the privilege or confidentiality that attaches to it. If you are not the intended recipient, please notify the sender immediately, delete the email and do not copy, distribute or disclose its contents.

## SINGAPORE ACCIDENT STATEMENT

### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

### ACCIDENT STATEMENT

Date Of Report	16/03/2018 13:46
Date Of Accident	15/03/2018 19:20
Exact Location Of Accident	T-JUNC OF PRINCEP ST & MIDDLE RD
Country/State of Loss	SINGAPORE

### DETAILS OF OWN VEHICLE

Vehicle Registration Number	SGM7557M
<b>Insured/Policyholder</b>	
Name Of Registered Owner	NG ZHEREN NIGEL
NRIC No	S8633994C
Email Address	NIGELNG@GMAIL.COM
Mobile Phone No	(LOCAL) +65-91504831
Alternative Phone No	Others-NOPHONE

### Vehicle Particulars

Manufacturer	MAZDA
Model	MX 5
Exact Purpose for which vehicle was being used at time of accident	
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR

### Insurance Company

Name of Insurance Company	FWD SINGAPORE PTE. LTD.
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	PNPV2018-00000088
Cover Note Number	

### Driver

Name of Driver	NG ZHEREN NIGEL
NRIC No	S8633994C
Date Of Birth	22/11/1986
Occupation	INDOOR
Date Of Driving Pass	06/02/2006
Driving Experience	12 YEARS AND 1 MONTH
Gender	MALE
Mobile Number	(LOCAL) +65-91504831

Fax Number	
Contact Number	OTHERS-NOPHONE
Email Address	NIGELNG@GMAIL.COM
Address	26 PARK VILLAS TERRACE
Postcode	545299
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OWNER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

#### General Information of the Accident

Type Of Accident	COLLISION - HEAD TO REAR
Weather Conditions	CLEAR
Road Surface	DRY

#### Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles involved in the accident	
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	2
Passenger 1	Name: : AMEER MOSHIEN Gender: : Male

#### Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

#### Circumstances of Accident

REFER TO ATTACHED

#### Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	YES
Was there any audio recorded?	NO

#### DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SKS3706Y
Vehicle Make/Model/Colour	BMW
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	MUHAMMAD HAMDAN FATHULLAH BIN ABDUL HALIM
NRIC/Passport Number	S9411637F
Contact Number	82338145
Address	

Postcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

# Sketch Plan

## SKETCH PLAN

### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

### 8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
- (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
  - (ii) investigating the accident and/or my claims;
  - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
  - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
  - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
- (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
  - (ii) for complying with requirements under any regulations, laws or court orders.

Policyholder's Signature

Date & Time: 16 MAR 18  
1108

Driver's Signature

(If driver is not the policyholder)  
Date & Time:

Reporting Centre Person's Signature

Name:  
NRIC/VIN No.:

GIA/IRAC SketchPlanForm\_V3

1

### SKETCH PLAN

Date of Accident: 15 MAR 18 Time: 123 Location: PRINSEP ST / MIDDLE RD  
My Vehicle A: 5RAM7557M Vehicle B: SKS 37064 Vehicle C/Others:







## YOUR CLASSIC CAR INSURANCE SUMMARY

Please call +65-6322-2072 for FWD Emergency Assistance  
if Your Car breaks down or is involved in an accident.  
All accidents must be reported within 24 hours or the next working day of the incident  
regardless of whether it will lead to a claim.

POLICY NUMBER : PNPV2018-00000088

### About this policy

Premium paid : S\$1,435.58  
(Inclusive of GST)  
Coverage start date : 18/01/2018  
Coverage end date : 17/01/2019  
Who is insured to drive: : You and any Authorised Driver  
Policy Type : CLASSIC

### About you (As the policyholder)

Your name : Ng Zheren Nigel  
Address : 26 Park Villas Terrace Singapore S45299  
Email : nigelng@gmail.com  
NRIC/FIN : S8633994C  
Date of birth : 22/11/1986  
Marital status : Single  
Gender : Male  
Current no claims discount : 50%  
Mobile Number : 91504831  
Years of driving experience : Three or more  
Certificate of merit : No

### About your car

Car make and model : MAZDA MX5 2.0  
Car plate number : sgm7557m  
Year of first registration : 2016

Issued on: : 23/11/2017

Abhishek Bhatia  
Chief Executive Officer  
FWD Singapore Pte Ltd

Please refer to contract for specific terms, conditions  
and exclusions of this policy.

Please immediately inform us at +65-6820-8888  
or email us to [contact.sg@fwd.com](mailto:contact.sg@fwd.com) if any details in  
this Car Insurance Summary need to be changed.

REPUBLIC OF SINGAPORE DRIVING LICENCE

License No. S8633994C

Name: NG ZHEREN, NIGEL (HUANG ZHEREN)

Date of Birth: 22 Nov 1986

Issue Date: 06 Feb 2006

Barcode: S8633994C

REPUBLIC OF SINGAPORE

IDENTITY CARD NO. S8633994C

Name: NG ZHEREN, NIGEL (HUANG ZHEREN)  
黄哲仁

Race: CHINESE

Date of Birth: 22-11-1986

Sex: M

Country of Birth: SINGAPORE

YOU ARE LICENSED TO DRIVE VEHICLES IN THE FOLLOWING CLASSES

Class	Description	Valid Until
Class 2B	Motorcycles up to 200 CC	20 Apr 2011
Class 2A	Motorcycles between 201 CC and 400 CC	20 Apr 2011
Class 2	Motor cars up to 3500 kg with up to 7 passengers, exclusive of the driver, and motor vehicles up to 3500 kg	20 Apr 2011

Barcode: S8633994C

License No. S8633994C

NP 425A

5749602

Barcode: S8633994C

Address: 26 PARK VILLAS TERRACE  
SINGAPORE 245299

## SINGAPORE ACCIDENT STATEMENT

### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

### ACCIDENT STATEMENT

Date Of Report	16/03/2018 12:11
Date Of Accident	15/03/2018 19:45
Exact Location Of Accident	FROM PRINSEP STREET TO MIDDLE ROAD
Country/State of Loss	SINGAPORE

### DETAILS OF OWN VEHICLE

Vehicle Registration Number	SKS3706Y
<b>Insured/Policyholder</b>	
Name Of Registered Owner	SIME DARBY SERVICES PTE LTD
Co Reg No	197501065W
Email Address	94MILESAWAY@GMAIL.COM
Mobile Phone No	(LOCAL) +65-98331860
Alternative Phone No	Office-98331860

### Vehicle Particulars

Manufacturer	BMW
Model	520i
Exact Purpose for which vehicle was being used at time of accident	WORKING PURPOSES
Are you claiming under your own insurance policy for repair to your vehicle?	YES
If No, Please state action to be taken	
Vehicle Category	COMMERCIAL VEHICLE

### Insurance Company

Name of Insurance Company	MSIG INSURANCE (SINGAPORE) PTE. LTD.
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	B 29040568 MCY
Cover Note Number	

### Driver

Name of Driver	MUHAMMAD HAMDAN FATHULLAH BIN ABDUL HALIM
NRIC No	S9411637F
Date Of Birth	10/04/1994
Occupation	OUTDOOR
Date Of Driving Pass	12/05/2015
Driving Experience	2 YEARS AND 10 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-98331860

Fax Number	
Contact Number	OTHERS-98331860
Email Address	94MILES AWAY@GMAIL.COM
Address	BLK 615 ELIAS ROAS #03-108
Postcode	510615
Was driver an employee of the Insured's Company	YES
If No, Relationship of the Driver with the Insured	
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

#### General Information of the Accident

Type Of Accident	COLLISION - HEAD TO REAR
Weather Conditions	CLEAR
Road Surface	DRY

#### Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles involved in the accident	
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance,	NO
Number of Passengers (Including Driver)	1

#### Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

#### Circumstances of Accident

PLEASE REFER TO SKETCH PLAN

#### Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

#### DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SGW7557M
Vehicle Make/Model/Colour	MAZDA MX5
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	NIGEL NG ZHEREN
NRIC/Passport Number	S8633994C
Contact Number	91504831
Address	
Postcode	

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

1

## Sketch Plan

### SKETCH PLAN

#### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorized Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to renew/reject policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. Consent under the Personal Data Protection Act (PDPA)  
I understand, acknowledge, agree and consent that:  
(a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this form and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"); the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:  
(i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;  
(ii) investigating the accident and/or my claims;  
(iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;  
(iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or  
(v) complying with applicable law in administering, processing, handling and/or dealing with my claims.  
(collectively the "Purposes")  
(b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and  
(c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.




Policyholder's Signature / Date & Time

Driver's Signature (If driver is not the policyholder) / Date & Time

Witnessed by Reporting Centre Personnel

#### **Sketch Plan**



Describe Circumstances of the Accident

On 15 March @ 1945 I was driving along Princep St turning to Middle Road. I stopped at the traffic light before turning to middle road. There was a white Mazda in front. When the traffic light turned green, we both moved off slowly, and stopped again as there were pedestrians crossing. Once clear, the Mazda moved off but a jammed brake. For me, I moved off also but there was a cyclist on my right side, coming from middle road. I was distracted by the cyclist's movement and therefore failed to stop in time to avoid the white Mazda.

NOTE: PLEASE NOTE THAT YOUR INSURER MAY HAVE 14 DAYS TIME FRAME FOR YOU TO SUBMIT AN OWN DAMAGE CLAIM UNDER YOUR OWN POLICY. PLEASE CHECK YOUR POLICY FOR MORE INFORMATION.

Please State:

☐ Claim Own Policy ☐ Claim Third Party ☐ Claim OD/TP at other workshop ☒ Reporting only

Declaration

We declare the foregoing particulars are true in every respect.



Policyholder's Signature / Date & Time

Driver's Signature (If driver is not the policyholder) / Date & Time

Witnessed by Reporting Centre Personnel

16/03/2018

# AUTO PERFORMANCE APPRAISAL

APA

## TAX INVOICE

Ng Zheren Nigel  
C/O King's Auto Air-Conditioning Service  
176 Sin Ming Drive  
Sin Ming AutoCare #02-10  
Singapore 575721

INVOICE NO : APA18001520

DATE : 29/03/2018

VEHICLE NO : SGM7557M

JOB REFERENCE NO : 18/001618

ACCIDENT DATE : 15/03/2018

SURVEY DATE : 19/03/2018

<u>DESCRIPTION</u>	<u>AMOUNT</u>
Survey Fees Inclusive Of Transportation	\$410.00
Photographs (\$1) Per Copies : 53	\$53.00

TOTAL AMOUNT : \$463.00

Notes :

All cheque payment should be "Crossed" and made payable to "Auto Performance Appraisal"

Auto Performance Appraisal





# AUTO PERFORMANCE APPRAISAL

APA

VEHICLE SURVEY REPORTS																																				
<p>Ng Zheren Nigel  C/O King's Auto Air-Conditioning Service  176 Sin Ming Drive  Sin Ming AutoCare #02-10  Singapore 575721</p>																																				
1	<b>Reference</b> Job Reference No : 18/001618 Claim No : - Claim Type : Third Party Accident Date : 15/03/2018 Survey Date : 19/03/2018 Survey Report Date : 29/03/2018																																			
2	<b>Particulars Of Vehicle</b> Vehicle Registration No : SGM7557M Make & Model : Mazda MX-5 Vehicle Registration Date : 18/01/2016 Chassis No : JM6ND2E7600100229 Engine No : Blocked Colour : White																																			
3	<b>Condition Of Vehicle And Tyres</b> <table border="0"> <tr> <td><u>Mileage (KM)</u></td> <td><u>Brakes</u></td> <td><u>Steering</u></td> <td><u>Modification</u></td> </tr> <tr> <td>44075</td> <td>Serviceable</td> <td>Serviceable</td> <td>None</td> </tr> <tr> <td colspan="4"> </td> </tr> <tr> <td><u>Tyres</u></td> <td><u>Make</u></td> <td><u>Size</u></td> <td><u>Balance (MM)</u></td> </tr> <tr> <td>Front RHS</td> <td>Michelin</td> <td>215/45ZR17</td> <td>5</td> </tr> <tr> <td>Front LHS</td> <td>Michelin</td> <td>215/45ZR17</td> <td>5</td> </tr> <tr> <td>Rear RHS</td> <td>Michelin</td> <td>215/45ZR17</td> <td>6</td> </tr> <tr> <td>Rear LHS</td> <td>Michelin</td> <td>215/45ZR17</td> <td>6</td> </tr> </table>				<u>Mileage (KM)</u>	<u>Brakes</u>	<u>Steering</u>	<u>Modification</u>	44075	Serviceable	Serviceable	None	 				<u>Tyres</u>	<u>Make</u>	<u>Size</u>	<u>Balance (MM)</u>	Front RHS	Michelin	215/45ZR17	5	Front LHS	Michelin	215/45ZR17	5	Rear RHS	Michelin	215/45ZR17	6	Rear LHS	Michelin	215/45ZR17	6
<u>Mileage (KM)</u>	<u>Brakes</u>	<u>Steering</u>	<u>Modification</u>																																	
44075	Serviceable	Serviceable	None																																	
<u>Tyres</u>	<u>Make</u>	<u>Size</u>	<u>Balance (MM)</u>																																	
Front RHS	Michelin	215/45ZR17	5																																	
Front LHS	Michelin	215/45ZR17	5																																	
Rear RHS	Michelin	215/45ZR17	6																																	
Rear LHS	Michelin	215/45ZR17	6																																	
4	<b>Description Of Damages</b> The vehicle sustained damages at rear left hand portion. (For information of damages please refer to Parts/Labour/Photographs attached)																																			
5	<b>Instruction</b> This survey was conducted entirely on a "WITHOUT PREJUDICE" basis, and we have not authorised any repair.																																			

# AUTO PERFORMANCE APPRAISAL

## Vehicle Assessment Reports

Annex A

Ref No : 18/001618

### Damage And Repair Cost Adjustment

<u>S/No</u>	<u>Qty</u>	<u>Parts Description</u>	<u>Comments/condition</u>	<u>Workshop Estimate (\$)</u>	<u>Our Assessment (\$)</u>
			<u>List Items</u>		
1	1	Rear bumper	Deformed	1,052.30	1,052.30
2	2	Rear bumper reverse sensor	Malfunction	316.00	316.00
3	1	Rear bumper LH lamp	Broken/cut	263.00	263.00
4	1	Rear bumper LH lower splash cover	Deformed/broken	76.00	76.00
5	2	Rear bumper lower bracket	Broken/deformed	52.00	52.00
6	1	Rear bumper inner reinforcement	Bent/dented	617.80	X 617.80 N/V
7	1	Rear bumper LH corner retainer (Below taillamp)	Broken	62.00	62.00
8	1	Rear LH corner blind spot module/sensor	Broken/malfunction	432.00	432.00
9	1	Rear bumper LH side retainer	Deformed	49.00	49.00
10	1 set	Rear bumper clips	Broken/necessary	40.00	40.00
11	1	Rear LH splash shield	Reuse	72.00	-
12	1 set	Rear splash shield clips	Necessary	30.00	30.00
13	1	LH taillamp	Broken/cut	532.00	532.00
14	1	Rear end panel	Dented/bent	485.20	X 485.20 Repair
15	1	Rear LH corner panel	Dented/bent	286.30	286.30
				4,365.60	4,293.60
Less discount 20%				873.12	858.72
Total :				3,492.48	3,434.88
Total Spare Parts :				3,492.48	3,434.88

2552.48

# AUTO PERFORMANCE APPRAISAL

Annex B

## Vehicle Assessment Reports

Ref No : 18/001618

### Damage And Repair Cost Adjustment

<u>Items</u>	<u>Job Description</u>	<u>Workshop Estimate (\$)</u>	<u>Adjusted Costs (\$)</u>	
1	To remove, jack out, straighten, panel beating, align and renew replaced parts.	1,000.00	700.00	600
2	To putty and respray painting on affected areas.	1,200.00	800.00	600
3	To check lightings, wirings and re-install reverse sensors..	80.00	50.00	30
4	To remove, refix rear upholstery, carpet and trims.	120.00	80.00	60
5	To supplied and applied anti rust treatments.	100.00	60.00	40
Total Labour :		2,500.00	1,690.00	1330
Total Spare Parts :		3,492.48	3,434.88	
Total Labour :		2,500.00	1,690.00	
Total Repair Costs :		5,992.48	5,124.88	

### Assessor's Recommendation

Repairer Estimate : 5,992.48  
Our Adjustment : 5,124.88

#### Remarks

The repairer has agreed to undertake the repair on a lump sum basis of \$4,100.00, with a repair period of 6 working days.

Surveyed By:

  
Lek Boon Hwee  
Automobile Appraiser

3882.48  
20%: 3/00  
5 Days.

## ...CLAIM SUBFOLDER...(Pending for Survey Report)

































Paper Survey

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	20 Mar 2018		20 Mar 2018 13:11 <a href="#">Edit Adj Rpt</a>	<b>S\$3,100.00</b> <a href="#">Edit Estimates</a>	<b>S\$3,100.00</b> <a href="#">View Rpt</a>		<b>Pending for Survey Report</b> <a href="#">Cancel Case</a>

Main	Reference	Claim Details	Documents	Show All					
<b>CLAIM SUBFOLDER DETAILS</b> <span style="float: right;">[Created by insurer]</span>									
Insured: <b>SIME DARBY SERVICES PTE LTD</b> , Co. Reg. No.: 197501065W									
Main Claimant: <b>NG ZHEREN NIGEL</b> , ID: S8633994C									
Vehicle Reg. No.:	<b>SGM7557M</b>	Date of Loss:	15/03/2018 19:00 - :59 [25 Months and 25 Days From LTA Reg Date (Man Yr)]						
Claim Type:	<b>TP / 552933</b>	Policy/Cover Note No.:	B29040568MCY (Comprehensive) Coverage: 01/10/2017 - 30/09/2018						
Vehicle Reg. No. (Insured):	<b>SKS3706Y</b>	Policy No. (Claimant):							
		Excess:	S\$4,000.00						
Repairer:	<b>Kings Auto Air-conditioning Service (HQ)</b> Blk 176 Sin Ming Dr #02-10 Singapore 575721, 575721 Sin Ming - Tel:								
Handling Insurer:	<b>MSIG Insurance (Singapore) Pte. Ltd. (HQ)</b> - Tel: +65 6827 7888 ... [Handled by <b>Catherine Thia Shi Yi</b> - 6594 2545]								
Adjuster:	<b>LKK Auto Consultants Pte Ltd (HQ)</b> - Tel: 6256-3561 ... [Handled by <b>XING GUO QIANG</b> ] ... [Imm.Advice due 21/03/2018]								
Driver/Custodian (Insured):	<b>MUHAMMAD HAMDAN FATHULLAH BIN ABDUL HALIM ()</b> , NRIC: S9411637F								
<b>ASSOCIATED MAIL RECEIVED</b> <span style="float: right;"><a href="#">View All</a> <a href="#">Compose Case Mail</a></span>									
There are no mail for this case.									
<b>ALL ASSOCIATED TASKS</b> <span style="float: right;"><a href="#">View All</a> <a href="#">Search Tasks</a> <a href="#">Create New Task</a> <a href="#">Complete</a></span>									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

## Claim Documents

**\*SGM7557M (552933)**  
**[SK53706Y]**  
**TP**  
**NG ZHEREN NIGEL**  
**Mar 15 2018 7:00PM**  
**[SIME DARBY SERVICES PTE LTD]**  
**Kings Auto Air-conditioning Service**

<a href="#">Upload Documents</a> <a href="#">Upload Photos</a> <a href="#">Compose New Letter</a>			<b>View</b> <a href="#">View in Browser</a>	
<b>Photos/Images</b>			3 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	12/06/18 08:47	General View	 Load JPG	<input checked="" type="checkbox"/>
2	12/06/18 08:47	General View	 Load JPG	<input checked="" type="checkbox"/>
3	12/06/18 08:47	General View	 Load JPG	<input checked="" type="checkbox"/>
4	12/06/18 08:47	General View	 Load JPG	<input checked="" type="checkbox"/>
5	12/06/18 08:47	General View	 Load JPG	<input checked="" type="checkbox"/>
6	12/06/18 08:47	General View	 Load JPG	<input checked="" type="checkbox"/>
7	12/06/18 08:47	General View	 Load JPG	<input checked="" type="checkbox"/>
8	12/06/18 08:47	General View	 Load JPG	<input checked="" type="checkbox"/>
9	12/06/18 08:47	General View	 Load JPG	<input checked="" type="checkbox"/>
10	12/06/18 08:47	General View	 Load JPG	<input checked="" type="checkbox"/>
11	12/06/18 08:47	General View	 Load JPG	<input checked="" type="checkbox"/>
12	12/06/18 08:47	General View	 Load JPG	<input checked="" type="checkbox"/>
13	12/06/18 08:47	General View	 Load JPG	<input checked="" type="checkbox"/>
14	12/06/18 08:47	General View	 Load JPG	<input checked="" type="checkbox"/>
15	12/06/18 08:47	General View	 Load JPG	<input checked="" type="checkbox"/>
16	12/06/18 08:47	General View	 Load JPG	<input checked="" type="checkbox"/>
17	12/06/18 08:47	General View	 Load JPG	<input checked="" type="checkbox"/>
18	12/06/18 08:47	General View	 Load JPG	<input checked="" type="checkbox"/>
19	12/06/18 08:47	General View	 Load JPG	<input checked="" type="checkbox"/>
20	12/06/18 08:47	General View	 Load JPG	<input checked="" type="checkbox"/>
21	12/06/18 08:47	General View	 Load JPG	<input checked="" type="checkbox"/>
22	12/06/18 08:47	General View	 Load JPG	<input checked="" type="checkbox"/>
23	12/06/18 08:47	General View	 Load JPG	<input checked="" type="checkbox"/>
24	12/06/18 08:47	General View	 Load JPG	<input checked="" type="checkbox"/>
25	12/06/18 08:47	General View	 Load JPG	<input checked="" type="checkbox"/>
26	12/06/18 08:47	General View	 Load JPG	<input checked="" type="checkbox"/>
<b>Documentation</b>			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
1	20/03/18 11:11	SGM7557M E-FILE REPORT	 Load PDF	
2	20/03/18 11:18	TP PRI Request	 Load PDF	
3	20/03/18 13:12	TP Reject SJE - assign LKK	 Load PDF	
4	20/03/18 13:13	SK53706Y E-FILE REPORT	 Load PDF	
5	20/03/18 14:11	TP Workshop Details	 Load PDF	
6	16/05/18 17:36	ACK TO TP	 Load PDF	
7	16/05/18 17:38	LOD-Repair Bill - Rental Receipt - CI - LTA Search	 Load PDF	
8	16/05/18 17:41	survey report	 Load PDF	
9	16/05/18 17:42	survey photos	 Load PDF	
10	16/05/18 17:43	SURVEY PHOTOS	 Load PDF	

## Documents Checklist

**DOCUMENTS CHECKLIST**

Reset

Save

Print

There are no document checklists configured.

**Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)****Show Remarks To:** ☐ Handling InsurerNote: Remarks are private unless you show it to other parties.

## LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS3/MSG18005190/GRD3E2

Date: 12/06/2018

## REFERENCE

Handling Insurer: MSIG Insurance (Singapore) Pte. Ltd. Policy No: B29040568MCY  
 Claimant Vehicle No: SGM7557M Insured Vehicle No: SKS3706Y  
 Date of Loss: 15/03/2018 Nature of Claim: TP Claim No: 552933

## DESCRIPTION &amp; IDENTIFICATION OF VEHICLE

Reg No: SGM7557M  
 Make & Model: MAZDA MX-5 SKYACTIV-G, 2.0 SP.6MT 2WD (A) Engine No: PE30856881  
 Reg. Date: 18/01/2016 (Man. Year: 2015) Chassis No: JM6ND2E7600100229  
 Colour: White Odometer: 44075 km  
 Engine Capacity: 1998 cc  
 Market Value/New Car Price: N/A  
 Sum Insured (S\$): Market Value/New Car Price

## CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes  
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition: Yes

## CONDITION OF TYRES

Front Tyre Size: 215/45Z R17 Rear Tyre Size: 215/45Z R17  
 Front Left Side: Michelin 6 mm Rear Left Side: Michelin 6 mm  
 Front Right Side: Michelin 6 mm Rear Right Side: Michelin 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	3,492.48	2,552.48	940.00	26.91
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,500.00	1,330.00	1,170.00	46.80
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (S\$)</b>	<b>5,992.48</b>	<b>3,882.48</b>	<b>2,110.00</b>	<b>35.21</b>
<b>Approved Total (Overridden) (S\$)</b>		<b>3,100.00</b>		
<b>Nett Amount (S\$)</b>	<b>5,992.48</b>	<b>3,100.00</b>	<b>2,892.48</b>	<b>48.27</b>

## INSPECTION

Date of Assignment: 20/03/2018  
 Date Inspected: 20/03/2018 Inspected At: Kings Auto Air-conditioning Service (HQ)  
 Blk 176 Sin Ming Dr #02-10 Singapore  
 575721  
 Singapore 575721  
 Estimated Period of Repair: 5.0 days

Adjuster: XING GUO QIANG

Manager: Janice Lee Si Hua

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*



## REPAIR DETAILS

## Reference

<b>Part Source:</b>	(Last Synchronised: 12 Jun 2018)	
<b>Parts:</b>	N/A	MAZDA MX-5 SKYACTIV-G 2.0 SP.6MT 2WD (A) (Model not available in database)
<b>Labour:</b>	Repairer's	(Price-denominated Standard List)
<b>Print Code:</b>	(Unsubmitted, no print-code for SGM7557M)	
<b>Validity:</b>	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
<b>Further Info:</b>	Items/values not in reference catalogue are prefixed with an asterisk *.	

## Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Deformed	1,052.30 FL	*1,052.30 FL
2	2		*REAR BUMPER REVERSE SENSOR	Malfunction	316.00 FL	*316.00 FL
3	1		*REAR BUMPER LH LAMP	Broken / Cut	263.00 FL	*263.00 FL
4	1		*REAR BUMPER LH LOWER SPLASH COVER	Deformed / Broken	76.00 FL	*76.00 FL
5	2		*REAR BUMPER LOWER BRACKET	Broken / Deformed	52.00 FL	*52.00 FL
6	1		*REAR BUMPER INNER REINFORCEMENT	Not Necessary	617.80 FL	*- FL
7	1		*REAR BUMPER LH CORNER RETAINER (BELOW TAILLAMP)	Broken	62.00 FL	*62.00 FL
8	1		*REAR LH CORNER BLIND SPOT MODULE / SENSOR	Broken / Malfunction	432.00 FL	*432.00 FL
9	1		*REAR BUMPER LH SIDE RETAINER	Deformed	49.00 FL	*49.00 FL
10	1		*SET REAR BUMPER CLIPS	Broken / Necessary	40.00 FL	*40.00 FL
11	1		*REAR LH SPLASH SHIELD	Reuse	72.00 FL	*- FL
12	1		*SET REAR SPLASH SHIELD CLIPS	Necessary	30.00 FL	*30.00 FL
13	1		*LH TAILLAMP	Broken / Cut	532.00 FL	*532.00 FL
14	1		*REAR END PANEL	Repair	485.20 FL	*- FL
15	1		*REAR LH CORNER PANEL	Dented / Bent	286.30 FL	*286.30 FL

F=Franchise part. L=ListItemDisc.

<b>Sub Total (\$\$)</b>	<b>4,365.60</b>	<b>3,190.60</b>
<b>- List Item Discount on L Items 20.00/20.00% (\$\$)</b>	<b>873.12</b>	<b>638.12</b>
<b>Total Parts (\$\$)</b>	<b>3,492.48</b>	<b>2,552.48</b>

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO REMOVE, JACK OUT, STRAIGHTEN, PANEL BEATING, ALIGN AND RENEW REPLACED PARTS	New	1,000.00	600.00
2	TO PUTTY AND RESPRAY PAINTING ON AFFECTED AREAS	New	1,200.00	600.00
3	TO CHECK LIGHTINGS, WIRINGS AND RE-INSTALL REVERSE SENSORS	New	80.00	30.00
4	TO REMOVE, REFIX REAR UPHOLSTERY, CARPET AND TRIMS	New	120.00	60.00
5	TO SUPPLIED AND APPLIED ANTI RUST TREATMENTS	New	100.00	40.00
Gross Labour Cost (S\$)			2,500.00	1,330.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >