

ASS. REC. BY:

REF: CS/AWA1800 5194 / TICD301 Special Instruction:

Taufik

ASSIGNMENT (Office)From (Person): Kin Wong of AWAC Date/Time: 19/3/18 @ 11:06am

Estimated Cost: _____ Bill to: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CSTo Inspect Vehicle No: SLN 2657B Insured: GBG 8180Aat Workshop m/s Performance Motors Tel: 6319 0174of 303 Alexandra RoadPolicy No: AVCP SB008768170D Claim No: NSV1800180/BT

Sum Insured: _____ Excess: _____

Make of Veh: _____ D.O.A. 15/03/18
(Client's Record)CA / REV / REP. / REV 24 HRS ^{hp} H.O.D. Endorsement: _____Date/Time: 11:51am @ 19/3/18 Person Contacted: Caroline Vehicle IN / OUT

Date/Time	Action/Instruction
	<u>SLN 2657B -X</u>
	<u>GBG 8180A -X</u>
<u>12/6 2.23pm</u>	<u>Caroline sold owner, revert to CD claim.</u>
	<u>Submit preli report. (Preli fig \$6503.55; Check Items: 2, 17, 25)</u>

SYNOPSIS

Taufik

REF:

AWA.

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD ☒ TP / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured _____

Policy No. _____

Claims No. _____

Sum Insured: _____

Excess _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

N/S	O/S

Bal. or Market Value: _____

IDAC Accident Report: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: _____ days Res.: Yes or No

Lump Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

WP

Vehicle IN / OUT

Date: _____ Person Contacted: _____

Gary

Date / Time Action / Instruction

Van No: D SLN 2657B Vt Regn: 2017 April

Type: Motor / M Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: BMW 3181

1499

Colour: Grey

A/C Insured / Std / NI / NA

Sp. Reading: 3156

T/Radio Insured / Std / NI / NA

Eng No: _____

O No: _____

WBH8E 3604 0NM 78919

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Mod: Nil / S/Rim / STD A/Rim or

Tyre Size F: 225/50R17

R: 2-

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

R/Bal: 6 mm

Rear

R/Bal: 6 mm

L/Bal: 6 mm

L/Bal: 6 mm

D.O.A. _____

D.O.I. 22/5/18 @ 1550

Survey held at: pml

Des. of Damages: Fnt / Rear / O/S / N/S / U/C / Rooftop or

fnt o/s

The U/C / Chassis frame / Body Structure affected due to collision

Date/Time: File Pass to:

☒ : Preli. Report

Days Of Repair: 3

1)

☐ : Final Report

Resurvey No. of Trip: -

Survey Fee

Date/Time: File Return to:

Transportation

2)

Add Fee: ☐ Site Insp \$☐ Inter. \$☐ Tech. Insp \$☐ Weekend \$

Photos

Chart

Report Format: Preli report.

Lump Sum / I.B.U: \$

200

200




LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
ALLIED WORLD ASSURANCE COMPANY LTD		Ref : CS/AWA18005194/T1rd3		
(SINGAPORE BRANCH) 60 ANSON ROAD #08-01 (8th FLOOR) MAPLETREE ANSON SINGAPORE 079914		Date : 20-03-2018		
		Code : AWA		
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	GBG 8180A	Veh. Inspected	SLN 2657B	
Policy No.		Coverage (\$)	0.00	
Claim No.	NSV1800180/BT	Excess (\$)	0.00	
Assign From	AVCPSB0087681700	Assign Date	20/03/2018	
2. Vehicle Particulars & Condition				
Make & Model		c.c	0	
Engine No.	HIDDEN	Year of Reg.		
Chassis No.		Colour		
Odometer	-	Steering		
Brakes		Modification		
General				
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre			mm	
L/H Front Tyre			mm	
R/H Rear Tyre			mm	
L/H Rear Tyre			mm	
4. Description of Damages				
5. General Information				
Accident Date	15/03/2018	Inspection Date		
Survey held at	PERFORMANCE MOTORS LTD 303 ALEXANDRA ROAD SINGAPORE 159941			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				

Nivitha (LKK Auto)

From: Wong, Kin <Kin.Wong@awac.com> on behalf of Motorsurvey
<Motorsurvey@awac.com>
Sent: Monday, 19 March 2018 11:06 AM
To: 'assignments@lkkauto.com'
Cc: 'sur@lkkauto.com'; 'PBSP'
Subject: TP Survey assignment for SLN 2657 B DOA: 15.03.2018 Our ref: NSV1800180/BT

The above captioned accident refers.

Pursuant to the Practice Directions Amendment No. 1 of 2016 which was effective on 1 April 2016, we like to advise that the third party claimant and us have consensus in the appointment of Mr Steven Foong / Mr Chua Weijie as the Single Joint Expert to conduct the pre-repair survey of the third party claimant's vehicle.

Please conduct "THIRD PARTY" survey on without prejudice basis. The information as are follows:

3 rd Party Vehicle	:	SLN 2657 B
Insured Vehicle	:	GBG 8180 A
Policy Number	:	AVCPSB0087681700
Name of Workshop	:	Performance Motors Limited
Contact Number	:	6319 0174
Person to Contact	:	Ms Caroline
Estimated Cost of repairs	:	\$ 10,480.86

Regards,
Claims Division

Copy to Performance Motors Limited (Your Ref: SLN2657B) via Email

Note – Please send a copy of the video footage to us for our claim assessment.

- (x)
1. This is to keep you informed that we have appointed surveyors to conduct inspection to your client's damaged vehicle on a without prejudice basis.
 2. **Please keep our motor surveyor and us informed so as to enable the surveyor to conduct a post repair inspection once your client's vehicle has been repaired and before returning the repaired vehicle to your customer.**
 3. Please quantify your client's claim with all relevant supporting documents once your client's vehicle has been repaired.
 4. Please do not construe this appointment of surveyor and our above request as an admission of liability.

Regards
Motor Claims
Claims Group
Global Market

The information contained in this e-mail and any attachments hereto is confidential. If you are not the intended recipient, you must not use or disseminate any of this information. If you have received this e-mail in error, please immediately notify the sender by reply e-mail and permanently delete the original e-mail (and any attachments hereto) and any copies or printouts thereof. Although this e-mail and any attachments hereto are believed to be free of any virus or other defect that might affect any computer system into which it is received and opened, it is the responsibility of the recipient to ensure that it is virus free and no responsibility is accepted by Allied World Assurance Company Holdings, GmbH or its subsidiaries or affiliates, either jointly or severally, for any loss or damage arising in any way from its use.

Celine Fong (LKKAUTO)

From: PBSP <pml-pbsp@simedarby.com.sg>
Sent: Wednesday, 12 June 2019 2:23 PM
To: Celine Fong (LKKAUTO)
Subject: Fw: Pre-Repair Survey (Single Joint Expert) - Accident involving potential defendant veh GBG 8180A and claimant's SLN 2657B on 15/03/2018; Our Ref: NSV1800180

FYI

From: PBSP
Sent: Thursday, 29 March 2018 2:48 PM
To: Tang, Ben; Wong, Kin
Subject: Re: Pre-Repair Survey (Single Joint Expert) - Accident involving potential defendant veh GBG 8180A and claimant's SLN 2657B on 15/03/2018; Our Ref: NSV1800180

Dear Ben,

Owner revert to Uninsured recovery claims.

Thank you.

Regards,
Caroline
C/o Performance Motors Limited - Body and Paint
303 Alexandra Road Singapore 159941
DID: 6319 0174 Fax: 6479 4601

From: Tang, Ben <Ben.Tang@awac.com>
Sent: Thursday, 29 March 2018 1:16:23 PM
To: PBSP; Wong, Kin
Subject: RE: Pre-Repair Survey (Single Joint Expert) - Accident involving potential defendant veh GBG 8180A and claimant's SLN 2657B on 15/03/2018; Our Ref: NSV1800180

Dear Caroline

We have received the CD but unable to view.

Please resent video footage via email.

Thank you.

Best Regards
Ben Tang
Claims Analyst
Claims Group
Global Markets

Allied World Assurance Company, Ltd
60 Anson Road #08-01 Mapletree Anson Singapore 079914
T: +65 6423 0816
F: +65 6423 0864

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	5535B
Vehicle Details	
Vehicle No.:	SLN2657B
Vehicle to be Exported:	No
Intended Deregistration Date:	17 Apr 2019
Vehicle Make:	B.M.W.
Vehicle Model:	318i LED NAV
Primary Colour:	Grey
Manufacturing Year:	2017
Engine No.:	F9991572B38B15A
Chassis No.:	WBA8E36040NU78919
Maximum Power Output:	100.0 kW (134 bhp)
Open Market Value:	\$31,229.00
Original Registration Date:	27 Apr 2017
First Registration Date:	27 Apr 2017
Transfer Count:	0
Actual ARF Paid:	\$30,721.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	26 Apr 2027
PARF Rebate Amount:	\$23,040.00
Intended COE Rebate Details	
COE Expiry Date:	26 Apr 2027
COE Category:	B - Car above 1600cc or 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$54,405.00
COE Rebate Amount:	\$43,660.00
Total Rebate Amount:	\$66,700.00

The information contained herein is correct as at 17 Apr 2019

OK

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT	
Date Of Report	16/03/2018 13:42
Date Of Accident	15/03/2018 12:05
Exact Location Of Accident	FORUM SHOPPING CENTRE
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE	
Vehicle Registration Number	SLN2657B
Insured/Policyholder	
Name Of Registered Owner	LAURENCE VICTORIN TJIA
NRIC No	S2745535B
Email Address	NOEMAIL
Mobile Phone No	(LOCAL) +65-97366095
Alternative Phone No	OFFICE-97366095
Vehicle Particulars	
Manufacturer	BMW
Model	318
Exact Purpose for which vehicle was being used at time of accident	NORMAL USAGE
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR
Insurance Company	
Name of Insurance Company	AXA INSURANCE PTE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	CN825019
Cover Note Number	
Driver	
Name of Driver	LAURENCE VICTORIN TJIA
NRIC No	S2745535B
Date Of Birth	08/11/1957
Occupation	INDOOR
Date Of Driving Pass	26/02/1983
Driving Experience	35 YEARS AND 0 MONTHS
Gender	FEMALE
Mobile Number	(LOCAL) +65-97366095
Fax Number	
Contact Number	OFFICE-97366095
EEmail Address	NOEMAIL

Address	10 WALSHE ROAD #02-08
Postcode	257654
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OWNER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	COLLISION - CHANGE/CROSS LANE
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles involved in the accident	
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

REFER TO ATTACH.

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	YES
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	GBG8180A
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	GOODS VEHICLE
Name of Driver	GO HUI SAN
NRIC/Passport Number	
Contact Number	91372290
Address	
Postcode	
Insurance Company Name	ALLIED WORLD ASSURANCE COMPANY, LTD
Nature Of Damage	
No. Of Passenger (Including Driver)	

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for Investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.(collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents(including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.

LAURENCE VICTORIN

Policyholder's Signature

Date & Time:

15 March 2018
4 PM

Driver's Signature

(If driver is not the policyholder)

Date & Time:

GARY POH
Performance Motors
303 Alexandra Road
Sime Darby Performance
Singapore


Reporting Centre Personnel's Signature

Name:

NRIC/FIN No.:

15/3/18
4 PM

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

I am driving out from taxi stand slowly. I already stop. I see the main road then after other party GBG 8180 A want to turn left just bump my car.

DECLARATION

I/We declare the foregoing particulars are true in every respect.

[Signature] 15 March 2018
time 4 PM.

Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

GARY CHAI HOON
Performance Motors Limited
303 Alexandra Road
Sime Darby Performance Centre
Singapore 159951

15/3/18
4pm

Performance Motors Limited

A member of the Sime Darby Group
Co. Reg. No. 197401559W GST Reg. No M2-0020081-X



303, Alexandra Road
Sime Darby Performance Centre
Singapore 159941

Tel. 63190100 (Sales & Admin)
63190111 (AfterSales)
Fax. 64747770

280, Kampong Arang Road
East Coast Centre
Singapore 438180

Tel. 63190888 (AfterSales)
Fax. 63449773

315, Alexandra Road
Sime Darby Business Centre
Singapore 159944

Tel. 63190528 (AfterSales)
63190533/530 (Motorrad)
Fax. 64796601 (AfterSales)
64796624 (Motorrad)

GST REG. NO : M2 - 0020081 - X

ESTIMATE

16 MAR 2018

Estimate No. : b1 46253
Date Estimated : 15/03/2018
Prepared By : Gary Poh Chai Hoon

Page No. : 1 of 2

- ESTIMATE REPAIR FOR -

Laurence Victorin Tjia
10 Walshe Road
#02-08

Singapore 257654

- ACCOUNT - 40000

Cash Sales - Service
Singapore

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SLN2657B	NU78919	27/04/2017	318iA/4Dr	0

DESCRIPTION

To replace front bumper and attachment include knocking
cause by the accident

VALUE
850 1,700.00

Painting front bumper

934 1,038.00

To replace right headlight including program
and conduct tests for proper function.

451 531.00

To check electrical wiring systems at the front section
for proper function including adjustments of headlights.

150 177.00

Sundries.

? 80.00

Total Labour 1: 3,526.00

DESCRIPTION

FRT BUMPER TOP MOUNT
FRT RH DEFORMATION ELEMENT
INSERT AIR INLET MIDDLE
RH FOG LAMP SUPPORT
FINISHER ROD CENTRE (SPORT)
RH FINISHER ROD (SPORT)
RH AIR INLET FINISHER (SPORT)
RH PARTIALLY OPEN GRID (SPORT)
FRT SHOCK ABSORBER ECE
FRT BUMPER PANEL PRIMED (SPORT LINE
GROMMET
FRT BUMPER LOWER MOUNT
PLAQUE 82MM
RH HEADLIGHT LED TECHNOLOGY
LH FOG LIGHT LED
DECOUPLING RING PDC TORQUE CONVERTE
PDC SENSOR MINERAL GREY (B39)

QTY	PRIC	VALUE
1	361.65	? 361.65
1	97.40	? 97.40
1	121.95	? 121.95
1	37.60	? 37.60
1	53.40	NN X 53.40
1	39.25	? 39.25
1	51.90	? 51.90
1	78.65	? 78.65
1	52.15	? 52.15
1	982.75	de 982.75
2	0.75	ne 1.50
1	128.00	? 128.00
1	69.50	ne 69.50
1	3,044.60	crv 3,044.60
1	391.10	? 391.10
4	5.05	ne 20.20
2	368.80	? 737.60

Total Parts : 6,269.20

Performance Motors Limited

A member of the Sime Darby Group

Co. Reg. No. 197401559W GST Reg. No M2-0020081-X



303, Alexandra Road
Sime Darby Performance Centre
Singapore 159941
Tel. 63190100 (Sales & Admin)
63190111 (AfterSales)
Fax. 64747770

280, Kampong Arang Road
East Coast Centre
Singapore 438180
Tel. 63190888 (AfterSales)
Fax. 63449773

315, Alexandra Road
Sime Darby Business Centre
Singapore 159944
Tel. 63190528 (AfterSales)
63190533/530 (Motorrad)
64796601 (AfterSales)
64796624 (Motorrad)

GST REG. NO : M2 - 0020081 - X

E S T I M A T E

Estimate No. : b1 46253
Date Estimated : 15/03/2018
Prepared By : Gary Poh Chai Hoon

Page No. : 2 of 2

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SLN2657B	NU78919	27/04/2017	318iA/4Dr	0

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Claims OD / 3rd Party / Uninsured losses / Direct

Regn No. 12/3/18 @ 1615

Date/time Tanpin

Surveyor's Name 97495749

Surveyor's Tel - WP

Authorized By WP

REGISTRATION NO. WP

Surveyor's Email tanpin@lkkauto.com

No. of Working Days 03 days - 4 days

[Signature]
26/3/18

9299.20

Labour 1	:	3,526.00
Parts	:	6,269.20
Labour 2	:	0.00
Excess	:	0.00
Total GST @ 7%	:	685.66
Grand Total	:	10,480.86

** THIS ESTIMATE IS VALID FOR A PERIOD OF 30 DAYS ONLY**

** PRICE FOR PARTS ARE SUBJECTED TO CHANGE WITHOUT PRIOR NOTICE **



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
ALLIED WORLD ASSURANCE COMPANY LTD		Ref : CS/AWA18005194/T1cd3e2		
(SINGAPORE BRANCH) 60 ANSON ROAD #08-01 (8th FLOOR) MAPLETREE ANSON SINGAPORE 079914		Date : 01-07-2019		
Code : AWA				
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	GBG 8180A	Veh. Inspected	SLN 2657B	
Policy No.	AVCPSB0087681700	Coverage (\$)	0.00	
Claim No.	NSV1800180/BT	Excess (\$)	0.00	
Assign From		Assign Date	19/03/2018	
2. Vehicle Particulars & Condition				
Make & Model	B.M.W. 318i	c.c	1499	
Engine No.	HIDDEN	Year of Reg.	2017	
Chassis No.	WBA8E36040NU78919	Colour	GREY	
Odometer	3156	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	225/50 R17	BRIDGESTONE	6 mm	
L/H Front Tyre	225/50 R17	BRIDGESTONE	6 mm	
R/H Rear Tyre	225/50 R17	BRIDGESTONE	6 mm	
L/H Rear Tyre	225/50 R17	BRIDGESTONE	6 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE FRONT O/S PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	15/03/2018	Inspection Date	22/03/2018	
Survey held at	PERFORMANCE MOTORS LTD 303 ALEXANDRA ROAD SINGAPORE 159941			
5a. Remarks				
A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		3 Working Days		



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLN 2657B

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	SUNDRIES (SN)	* CHECK	80.00	-
1	FRT BUMPER TOP MOUNT (SN)	* CHECK	361.65	-
1	FRT RH DEFORMATION ELEMENT (SN)	* CHECK	97.40	-
1	INSERT AIR INLET MIDDLE (SN)	* CHECK	121.95	-
1	RH FOG LAMP SUPPORT (SN)	* CHECK	37.60	-
1	FINISHER ROD CENTRE (SPORT) (SN)	NOT NECESSARY	53.40	-
1	RH FINISHER ROD (SPORT) (SN)	* CHECK	39.25	-
1	RH AIR INLET FINISHER (SPORT) (SN)	* CHECK	51.90	-
1	RH PARTIALLY OPEN GRID (SPORT) (SN)	* CHECK	78.65	-
1	FRT SHOCK ABSORBER ECE (SN)	* CHECK	52.15	-
1	FRT BUMPER PANEL PRIMED (SPORT LINE) (SN)	DEFORMED	982.75	982.75
2	GROMMET (SN)	NECESSARY	1.50	1.50
1	FRT BUMPER LOWER MOUNT (SN)	* CHECK	128.00	-
1	PLAQUE 82MM (SN)	NECESSARY	69.50	69.50
1	RH HEADLIGHT LED TECHNOLOGY (SN)	CRACKED	3,044.60	3,044.60
1	LH FOG LIGHT LED (SN)	* CHECK	391.10	-
4	DECOUPLING RING PDC TORQUE CONVERTE (SN)	NECESSARY	20.20	20.20
2	PDC SENSOR MINERAL GREY (B39) (SN)	* CHECK	737.60	-
			6,349.20	4,118.55
LABOUR				
TO REPLACE FRONT BUMPER AND ATTACHMENT INCLUDE KNOCKING CAUSE BY THE ACCIDENT.			1,700.00	850.00
PAINTING FRONT BUMPER.			1,038.00	934.00
TO REPLACE RIGHT HEADLIGHT INCLUDING PROGRAM AND CONDUCT TESTS FOR PROPER FUNCTION.			531.00	451.00
TO CHECK ELECTRICAL WIRING SYSTEMS AT THE FRONT SECTION FOR PROPER FUNCTION INCLUDING ADJUSTMENTS OF HEADLIGHTS.			177.00	150.00
			-	-
			-	-
			3,446.00	2,385.00
GRAND TOTAL			9,795.20	6,503.55



RECOMMENDED COST OF REPAIRS (REPAIR COST NOT CONCLUDE) (EXCLUDE CHECK ITEMS S\$2,177.25 NETT)				6,503.55
---	--	--	--	----------

Report Ref No. CS/AWA18005194/T1cd3e2

MOHAMAD TAUFIKH

M.MATAI, AMSAE-A

Automotive Assessor

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.