

ASS. REC. BY:

REF:

CS/AIG/18005201/Kvd3n2

Special Instruction:

Surveyor:

Kenneth

ASSIGNMENT (Office)

Meimien

From (Person):

Supremacy Dakhene

of

AIG

Date/Time:

20/3/18 @ 11:17am

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

GBE 8738C

Insured:

YN3417S

at Workshop m/s

Trust Autoworks

Tel:

9108 2728

of

BLK 5035 # 01-345 AMK Ind. Park 2

Policy No:

Claim No:

Sum Insured:

Excess:

Make of Veh:

D.O.A.

14/3/18

(Client's Record)

CA / REV / REP. / REV 24 HRS

'wp'

H.O.D. Endorsement:

Date/Time:

1:27pm @ 20/3/18

Person Contacted:

Anthony

Vehicle IN/OUT

Date/Time

Action/Instruction ( - ) Estimate

GBE 8738C - CS/MSG/18000732/Kvd3n2

D.O.A: 10/01/18

YN3417S - CCG/AIG/17023014/Hea3

D.O.A: 28/11/17

6/4/18

L18 8155a Cadmus Anthony (Real 1238.93, 4413)

ASS. REC. BY:

REF:

A161

Kenneth

## ASSIGNMENT

From: \_\_\_\_\_ Date: \_\_\_\_\_

Estimated Cost: \_\_\_\_\_

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: \_\_\_\_\_

at Workshop m/s Trust Auto

of \_\_\_\_\_

Insured: \_\_\_\_\_

Policy No. \_\_\_\_\_

Claims No. \_\_\_\_\_

Sum Insured: \_\_\_\_\_ Excess: \_\_\_\_\_

(Client's Record)

Make of Veh: \_\_\_\_\_

(Policy Condition)

Remark: The veh had commenced its  
repair at the time of inspection.

N/S	O/S

Bal. or Market Value: \_\_\_\_\_

IDAC Accident Rpt: \_\_\_\_\_ Consistent? : Yes or No

GIA / PR Seen: \_\_\_\_\_ Consistent? : Yes or No

Est. Repairs: \_\_\_\_\_ days Res.: Yes or No

Lum Sum: \_\_\_\_\_ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: \_\_\_\_\_ Person Contacted: \_\_\_\_\_ Vehicle: IN / OUT

Veh No: GBE8738 Yr Regn: 04, 16

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: NIS Cabria c.c. 2953Colour: Dark Blue A/C: Insured / Std / NI / NASp. Reading: 68634 T/Radio: Insured / Std / NI / NA

Eng/No: \_\_\_\_\_

C/No: JN1SC 21-2470858386Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modl: NI1 / S/Rim / STD A/Rim orTyre Size: F: 195 R15 X8

R: \_\_\_\_\_

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

R/Bal. 8 mmL/Bal. 8 mmD.O.A. 19/3/18

Rear

R/Bal. 4 4 mmL/Bal. 4 4 mmD.O.I. 20/3/18

Survey held at \_\_\_\_\_

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

O/S Rm

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

20/3 En not ready  
21/3 1st pass to Catherine

RECEIVED 8 APR 2018

Date/Time, File Pass to?

☐ : Prel. Report

1)

☐ : Final Report

Date/Time, File Return to?

2) 6/4 - typist

Report Format :

Lump Sum / I.B.I. (\$) 1550Days Of Repair: 2Resurvey No. of Trip: —Add Fee: ☐ : Site Insp (\$)☐ : Interview (\$)☐ : Tech Invs (\$)☐ : Weekend (\$)

Survey Fee:

Transportation:

S + RS. \$

Photos

Others

TOTAL

250

20

270



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

AIG ASIA PACIFIC INSURANCE PTE LTD

Ref : CS/AIG18005201/Kvd3

78 SHENTON WAY #08-16  
CHARTIS BUILDING  
SINGAPORE 079120

Date : 20-03-2018



Code : AIG

### 1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	YN 3417S	Veh. Inspected	GBE 8738C
Policy No.		Coverage (\$)	0.00
Claim No.		Excess (\$)	0.00
Assign From	SUPRAMANIAM DARSHENE	Assign Date	20/03/2018

### 2. Vehicle Particulars & Condition

Make & Model		c.c	0
Engine No.	HIDDEN	Year of Reg.	
Chassis No.		Colour	
Odometer	-	Steering	
Brakes		Modification	
General			

### 3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm

### 4. Description of Damages

--	--

### 5. General Information

Accident Date	14/03/2016	Inspection Date	20/03/2018
Survey held at	BLK 5035 # 01-345 AMK		
Repairer	TRUST AUTOWORKS		

### 5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.
--

**: PRE-REPAIR INSPECTION - ACCIDENT INVOLVING OUR INSURED VEHICLE YN3417S & GBE8738C ON 14 MARCH 2018**

From: Supramaniam, Darshene  
To: admin-a@ikkauto.com, assignments@ikkauto.com  
Cc: Tan, Lily (AIG), Fong, Andy-SY, Kaur, Baljit, Chin, Lee-Ying, Abu Kassim, Noor Mariesa, Md Ishak, Mohd Imran, Chan, Yoke Shi, Lim, Sheng Yang  
Sent: 20/3/2018 11:17:33 AM  
Attachments:  20180316171518607.pdf

---

Hi,

Please refer to the enclosed request from M/s Chia S Arul LLC.

Kindly carry out Policy coverage verification first before conducting the pre-repair inspection within 48 hours

If you have any queries/concerns, please let us know.  
Kindly assist to assign Kenneth Kong as Single Joint Expert as requested.

Thank you.

Best Regards,

**Darshene Supramaniam**  
AIG  
Express Claims Adjuster II, FNOL SG Claims Operations - Auto  
Shared Services - Malaysia | Global Business Services

Level 12, Menara Worldwide, 198 Jalan Bukit Bintang. 55100 Kuala Lumpur, Malaysia  
Tel +603 2719 6000 ext 100-2208 | Fax +603 2719 6150

**IMPORTANT NOTICE:**

The information in this email (and any attachments) is confidential. If you are not the intended recipient, you must not use or disseminate the information. If you have received this email in error, please immediately notify me by "Reply" command and permanently delete the original and any copies or printouts thereof. Although this email and any attachments are believed to be free of any virus or other defect that might affect any computer system into which it is received and opened, it is the responsibility of the recipient to ensure that it is virus free and no responsibility is accepted by American International Group, Inc. or its subsidiaries or affiliates either jointly or severally, for any loss or damage arising in any way from its use.

---

From: kelley@chiaarul.com  
To: Darshene.Supramaniam@aig.com  
Cc: Lily.Tan@aig.com, Andy-SY.Fong@aig.com, Baljit.Kaur@aig.com, Lee-Ying.Chin@aig.com, NoorMariesa.AbuKassim@aig.com, Imran.Ishak@aig.com, yokeshi.chan@aig.com  
Subject: RE: PRE-REPAIR INSPECTION - ACCIDENT INVOLVING OUR INSURED VEHICLE YN3417S & GBE8738C ON 14 MARCH 2018  
Date: Tue, 20 Mar 2018 02:08:24 +0000  
Yes we are agreeable to Kenneth Kong.

Regards,

**Ms Kelley Choong**  
M/s Chia S Arul LLC  
151 Chin Swee Road  
#03-09 Manhattan House  
Singapore 169876  
Tel: (65) 6733 4647 Fax: (65) 6733 8183

This e-mail is from M/s Chia S Arul LLC, a firm of Advocates and Solicitors in Singapore, and is intended solely for the named addressee. It contains confidential and /or legally privileged information. If the e-mail has reached you in error, please delete the e-mail immediately and inform us of the error. You may contact us at [info@chiaarul.com](mailto:info@chiaarul.com). Internet communications cannot be guaranteed to be secured or error-free as information could be intercepted, corrupted, lost, arrive late or contain viruses. The sender therefore does not accept liability for any errors or omissions in the context of this message which arise as a result of Internet transmission.

---

From: Supramaniam, Darshene [mailto:Darshene.Supramaniam@aig.com]  
Sent: Tuesday, March 20, 2018 9:40 AM  
To: kelley@chiaarul.com  
Cc: Tan, Lily (AIG) <Lily.Tan@aig.com>; Fong, Andy-SY <Andy-SY.Fong@aig.com>; Kaur, Baljit <Baljit.Kaur@aig.com>; Chin, Lee-Ying <Lee-Ying.Chin@aig.com>; Abu Kassim, Noor Mariesa <NoorMariesa.AbuKassim@aig.com>; Md Ishak, Mohd Imran <Imran.Ishak@aig.com>; Chan, Yoke Shi <yokeshi.chan@aig.com>  
Subject: FW: PRE-REPAIR INSPECTION - ACCIDENT INVOLVING OUR INSURED VEHICLE YN3417S & GBE8738C ON 14 MARCH 2018

Hi Ms Kelley Choong

Please advise whether you agree to the appoint Kenneth Kong from LKK Auto Consultants Pte Ltd as a single joint expert.

**Darshene Supramaniam**  
AIG  
Express Claims Adjuster II, FNOL SG Claims Operations - Auto  
Shared Services - Malaysia | Global Business Services

**From:** Kelley Choong [mailto:kelley@chiaarul.com]

**Sent:** Tuesday, March 20, 2018 7:56 AM

**To:** Supramaniam, Darshene; wengkit@chiaarul.com

**Cc:** Tan, Lily (AIG); Fong, Andy-SY; Kaur, Baljit; Chin, Lee-Ying; Lim, Sheng Yang; Md Ishak, Mohd Imran; Chan, Yoke Shi; Abu Kassim, Noor Mariesa

**Subject:** RE: PRE-REPAIR INSPECTION - ACCIDENT INVOLVING OUR INSURED VEHICLE YN3417S & GBE8738C ON 14 MARCH 2018

Dear Sirs,

Our client is agreeable to your proposed surveyor:

Kenneth Kong	LKK Auto Consultants Pte Ltd
--------------	------------------------------

Regards,

**Ms Kelley Choong**

M/s Chia S Arul LLC

151 Chin Swee Road

#03-09 Manhattan House

Singapore 169876

Tel: (65) 6733 4647 Fax: (65) 6733 8183

This e-mail is from M/s Chia S Arul LLC, a firm of Advocates and Solicitors in Singapore, and is intended solely for the named addressee. It contains confidential and/or legally privileged information. If the e-mail has reached you in error, please delete the e-mail immediately and inform us of the error. You may contact us at [info@chiaarul.com](mailto:info@chiaarul.com). Internet communications cannot be guaranteed to be secured or error-free as information could be intercepted, corrupted, lost, arrive late or contain viruses. The sender therefore does not accept liability for any errors or omissions in the context of this message which arise as a result of Internet transmission.

**From:** Supramaniam, Darshene [mailto:Darshene.Supramaniam@aig.com]

**Sent:** Monday, March 19, 2018 9:54 AM

**To:** wengkit@chiaarul.com; info@chiaarul.com

**Cc:** Tan, Lily (AIG) <Lily.Tan@aig.com>; Fong, Andy-SY <Andy-SY.Fong@aig.com>; Kaur, Baljit <Baljit.Kaur@aig.com>; Chin, Lee-Ying <Lee-Ying.Chin@aig.com>; Lim, Sheng Yang <ShengYang.Lim@aig.com>; Md Ishak, Mohd Imran <Imran.Ishak@aig.com>; Chan, Yoke Shi <yokeshi.chan@aig.com>; Abu Kassim, Noor Mariesa <NoorMariesa.AbuKassim@aig.com>

**Subject:** PRE-REPAIR INSPECTION - ACCIDENT INVOLVING OUR INSURED VEHICLE YN3417S & GBE8738C ON 14 MARCH 2018

**WITHOUT PREJUDICE**

Your Reference : GBE 8738C (kc)

Our Reference : YN3417S

Dear Sir/Madam,

We refer to your Notice of Accident of even date.

We intend to conduct a pre-repair survey of the damage to your client's/your customer's vehicle jointly with your client/your motor workshop. We propose to use one of the motor surveyors named in the attached list to conduct the joint pre-repair survey as a single joint expert:

Name of Surveyor	Company Name
Lim Kok Chong	AIG Asia Pacific Insurance Pte Ltd
Kumar Uthaya	AIG Asia Pacific Insurance Pte Ltd
Ken Wong	AIG Asia Pacific Insurance Pte Ltd
Lawrence Ng Chun Kee	Priority Services
Jeffrey Ong Leng Kiat	Priority Services
Jimmy Lee	Priority Services
EC Looi	Automobile Inspection Services Pte Ltd
Ricky Teng	RT Appraisal Pte Ltd
Elson Teng	RT Appraisal Pte Ltd
Michael Cheong	RT Appraisal Pte Ltd
Pang Kiah Keen (Frankie)	Formteam Adjusters Pte Ltd
Ng You Han	Formteam Adjusters Pte Ltd
Soon HanXin (Gary)	Formteam Adjusters Pte Ltd

Chow Bo Xiong	Formteam Adjusters Pte Ltd
Chua Soo Teck (Benjamin)	Formteam Adjusters Pte Ltd
Kalvin Ang	LKK Auto Consultants Pte Ltd
Xing Guo Qiang	LKK Auto Consultants Pte Ltd
Marcus Chua	LKK Auto Consultants Pte Ltd
Mohamad Taufikh	LKK Auto Consultants Pte Ltd
Adrian Ling	LKK Auto Consultants Pte Ltd
Henry Ng	LKK Auto Consultants Pte Ltd
Mohammed Rasul	LKK Auto Consultants Pte Ltd
Steven Foong	LKK Auto Consultants Pte Ltd
Wei Jie	LKK Auto Consultants Pte Ltd
Ma Chin Fook	LKK Auto Consultants Pte Ltd
Kenneth Kong	LKK Auto Consultants Pte Ltd

Please let us know within two (2) working days whether you agree to the appointment of any of these motor surveyors as a single joint expert. You may select one or more of the listed motor surveyors. We will bear the cost of the pre-repair survey carried out by the single joint expert.

Thank you

**Darshene Supramaniam**

AIG

Express Claims Adjuster II, FNOL SG Claims Operations - Auto  
Shared Services - Malaysia | Global Business Services

Level 12, Menara Worldwide, 198 Jalan Bukit Bintang, 55100 Kuala Lumpur, Malaysia  
Tel +603 2719 6000 ext 100-2208 | Fax +603 2719 6150

**IMPORTANT NOTICE:**

The information in this email (and any attachments) is confidential. If you are not the intended recipient, you must not use or disseminate the information. If you have received this email in error, please immediately notify me by "Reply" command and permanently delete the original and any copies or printouts thereof. Although this email and any attachments are believed to be free of any virus or other defect that might affect any computer system into which it is received and opened, it is the responsibility of the recipient to ensure that it is virus free and no responsibility is accepted by American International Group, Inc. or its subsidiaries or affiliates either jointly or severally, for any loss or damage arising in any way from its use.

**IMPORTANT NOTICE:**

The information in this email (and any attachments) is confidential. If you are not the intended recipient, you must not use or disseminate the information. If you have received this email in error, please immediately notify me by "Reply" command and permanently delete the original and any copies or printouts thereof. Although this email and any attachments are believed to be free of any virus or other defect that might affect any computer system into which it is received and opened, it is the responsibility of the recipient to ensure that it is virus free and no responsibility is accepted by American International Group, Inc. or its subsidiaries or affiliates either jointly or severally, for any loss or damage arising in any way from its use.

**CHIA S ARUL LLC**  
ADVOCATES & SOLICITORS  
UEN 201330709H

ARULCHELVAN S

Our Ref : GBE 8738C (kc)

Your Ref : -

16 March 2018

AIG Asia Pacific Insurance Pte Ltd  
AIG Building  
78 Shenton Way  
#07-16  
Singapore 079120

BY EMAIL ONLY

Dear Sir,

RE: PROPERTY DAMAGE CLAIM  
CLAIMANT : LAU(INTERNATIONAL)DISTRIBUTION PTE LTD  
ACCIDENT INVOLVING GBE 8738C & YN 3417S ALONG HIGH STREET  
CENTRE LOADING BAY ON 14 MARCH 2018  
PRE-REPAIR INSPECTION NOTICE

1. We act for Lau(International)Distribution Pte Ltd, the owner of motor vehicle no GBE 8738C, which was involved in the aforesaid accident.
2. We hereby give you NOTICE that we are claiming against your insured motor vehicle no. YN 3417S damages, costs and disbursements as a result of your insured driver's negligence.
3. Kindly let us know if you wish to conduct a pre-repair inspection on our client's motor vehicle at Trust Autoworks of Blk 5035 #01-345 Ang Mo Kio Industrial Pk 2 Singapore 569538 (Anthony - 91082728).
4. If we do not hear from you within the next two (2) working days, we shall advise our client to proceed with their own inspection and repairs.

Yours faithfully,

MR ARULCHELVAN S

cc: Client

---

151 CHIN SWEE ROAD • #03-09  
MANHATTAN HOUSE • SINGAPORE 169876  
TEL : (65) 6733 4647 • FAX : (65) 6733 8183 (not for Service of Court documents)  
EMAIL : info@chiaarul.com



## Enquire PARF/COE Rebate for Registered Vehicle

<b>Vehicle Owner Particulars</b>	
Owner ID Type:	Company
Owner ID:	0331R
<b>Vehicle Details</b>	
Vehicle No.:	GBE8738C
Vehicle to be Exported:	Yes
Intended De-registration Date:	23 Mar 2018
Vehicle Make:	NISSAN
Vehicle Model:	CABSTAR 3.0 5M/T ABS 2DR 2WD EURO 5
Primary Colour:	Blue
Manufacturing Year:	2016
Engine No.:	ZD30010140N
Chassis No.:	JN1SC2F24Z0858386
Maximum Power Output:	-
Open Market Value:	\$24,867.00
Original Registration Date:	15 Apr 2016
First Registration Date:	15 Apr 2016
Transfer Count:	0
Actual ARF Paid:	\$1,244.00
<b>Intended PARF Rebate Details</b>	
PARF Eligibility:	No
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00
<b>Intended COE Rebate Details</b>	
COE Expiry Date:	14 Apr 2026
COE Category:	C - Goods Vehicle & Bus



3/22/2018

PARF/COE Rebate Enquiry

COE Period(Years):	10
PQP Paid:	\$22,224.00
COE Rebate Amount:	\$17,779.00
<b>Total Rebate Amount:</b>	<b>\$17,779.00</b>

The information contained herein is correct as at 22 Mar 2018

OK

Att: Kelly

MCD518035450 / ComfortDelGro Engineering Pte Ltd - Braddell  
 ENTRY DATE & TIME: 15/03/2018 10:15  
 SUBMITTED BY: Patrick Tie Jee Kiang

## SINGAPORE ACCIDENT STATEMENT

### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

### ACCIDENT STATEMENT

Date Of Report	15/03/2018 10:15
Date Of Accident	14/03/2018 13:55
Exact Location Of Accident	HIGH STREET CENTRE LOADING BAY
Country/State of Loss	SINGAPORE

### DETAILS OF OWN VEHICLE

Vehicle Registration Number	GBE8738C
<b>Insured/Policyholder</b>	
Name Of Registered Owner	LAU(INTERNATIONAL)DISTRIBUTION PTE LTD
Co Reg No	201000331R
Email Address	NOEMAIL
Mobile Phone No	
Alternative Phone No	OFFICE-83887611

### Vehicle Particulars

Manufacturer	NISSAN
Model	CABSTAR-3.0 D F24 (M)
Exact Purpose for which vehicle was being used at time of accident	
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	COMMERCIAL VEHICLE

### Insurance Company

Name of Insurance Company	AIG ASIA PACIFIC INSURANCE PTE. LTD.
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	2100460921
Cover Note Number	

### Driver

Name of Driver	KOH WEI CHIANG
NRIC No	S8624177C
Date Of Birth	28/08/1986
Occupation	OUTDOOR
Date Of Driving Pass	08/12/2006
Driving Experience	11 YEARS AND 3 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-83887611
Fax Number	
Contact Number	
EMail Address	SIMONKWQ@GMAIL.COM

Address	BLK 287 YISHUN AVE 6#09-68
Postcode	760287
Was driver an employee of the Insured's Company	YES
If No, Relationship of the Driver with the Insured	
Vehicle Registration Number of Driver's Own Vehicle	-
	-
Insurance Company of Driver's Own Vehicle	-
	-

### General Information of the Accident

Type Of Accident	COLLIDED INTO PARKED VEHICLE
Weather Conditions	CLEAR
Road Surface	DRY

### Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles involved in the accident	
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	0

### Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

### Circumstances of Accident

REFER TO REPORT ATTACHED

### Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	YES
Was there any audio recorded?	NO

### DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	YN3417S
Vehicle Make/Model/Colour	LORRY
Details Of Properties	
Vehicle Category	COMMERCIAL VEHICLE
Name of Driver	
NRIC/Passport Number	S9521313H
Contact Number	91660610
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

## SKETCH PLAN

A) GBE8738C

B) YN3417S



Loading Bay

## DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

I was Parked my lorry at the loading bay. I went up to my office when I <sup>came</sup> back I noted my lorry was hit by other lorry beside me I went to watch the CCTV then I realized that vehicle (B) was reversing in and out at the loading bay I have taken down the picture to show that my lorry paint was stuck at the vehicle (B) rear portion and the driver has sign the acknowledgement letter for me I have video with me.

## DECLARATION

I/We declare the foregoing particulars are true in every respect.

1000 Ang Mo Kio Ave 5 #03-05  
Singapore 660220  
Tel: 6345 4707/03 Fax: 6345 4705  
Comp. & GST Reg. No: 2010003318

15/3/18

Policyholder's Signature  
Date & Time:

Driver's Signature  
(If driver is not the policyholder)  
Date & Time:

Reporting Centre Personnel's Signature  
Name:  
NRIC/FIN No.:

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this (form) and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
  - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
  - (ii) investigating the accident and/or my claims;
  - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
  - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
  - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
  - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
  - (ii) for complying with requirements under any regulations, laws or court orders.

REPORTING CENTRE PERSONNEL  
 7500 Ang Mo Kio Ave 5 #08-05  
 Northstar Singapore 569880  
 Tel: 6843 4707/08 Fax: 6843 4705  
 GST Reg. No. GST Reg. No. 2010000218

L. 15/3/18

Policyholder's Signature  
 Date & Time:

Driver's Signature  
 (If driver is not the policyholder)  
 Date & Time:

Reporting Centre Personnel's Signature  
 Name:  
 NRIC/FIN No.:

KV

# Trust Autoworks

Mailing address : Blk 225 #07-579 Ang Mo Kio Ave 1 Singapore 560225  
Tel : 91082728

Lau ( International ) Distribution Pte Ltd  
7030 Ang Mo Kio Ave 5  
#08-85  
Northstar Singapore 569880

Vehicle No : GBE 8738 C  
Make/Model : Nissan Cabstar  
Year : 2016

*Not Authorized  
L1Png @ 1550h  
Resurvey After Paint*

Qty	Description	Unit Price	Amount
<b>Estimate Cost Of Repair</b>			
1 pc	Front o/s door assy ✓		<i>Bz</i> \$1,866.70 ✓
		Less 30 %	\$560.01
			\$1,306.69
<b>Nett Item</b>			
1 pc	Front o/s door glass outer moulding ✓		<i>SR</i> \$126.70 ✓
1 pc	Front o/s door view mirror ✓		<i>W</i> \$105.10 ✓
			\$231.80
		Less 10 %	\$23.18
		Nett total	\$208.62
<b>S Nett</b>			
1 pc	Front o/s door black sticker		<i>m</i> \$30.00 ✓
<b>Labour Charges</b>			
	Remove/renew the above accident parts including knocking, welding & cutting.		\$500.00 <i>200</i>
	To putty and spray paint on front accident portion.		\$500.00 <i>220</i>
	Check & reconnect wiring.		\$35.00 <i>20</i>
	<b>Total</b>		<u>\$2,788.93</u>
			2580.31

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer  
Signature:  
Date:



## LKK Auto Consultants Pte Ltd (Co. Reg. No: 199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/AIG18005201/KVD3N2  
Date: 09/04/2018

## REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No:  
Claimant: GBE8738C Insured Vehicle No: YN3417S  
Vehicle No: GBE8738C Nature of Claim: TP Claim No: 2399611827SG  
Date of Loss: 14/03/2018

## DESCRIPTION &amp; IDENTIFICATION OF VEHICLE

Reg No: GBE8738C Engine No: ZD30010140N  
Make & Model: NISSAN CABSTAR, 3.0 D F24 (M) Chassis No: JN1SC2F24Z0858386  
Reg. Date: 15/04/2016 (Man. Year: 2016) Odometer: 68634 km  
Colour: Metallic Blue  
Engine Capacity: 2953 cc  
Market Value/New Car Price: N/A  
Sum Insured (S\$): Market Value/New Car Price

## CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes  
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition: Yes

## CONDITION OF TYRES

Front Tyre Size: 195R15X8 Rear Tyre Size: 195R15X8(D)  
Front Left Side: Yokohama 8 mm Rear Left Side: Yokohama 4/4 mm  
Front Right Side: Yokohama 8 mm Rear Right Side: Yokohama 4/4 mm

The above values represent the remaining tyre treads depth

## COST OF CLAIMS

	Repairer's	Adjuster's	Difference	Diff %
Parts	1,545.31	1,545.31	0.00	0.00
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,035.00	440.00	595.00	57.49
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	2,580.31	1,985.31	595.00	23.06
Approved Total (Overridden) (S\$)		1,550.00		
Nett Amount (S\$)	2,580.31	1,550.00	1,030.31	39.93

## INSPECTION

Date of Assignment: 20/03/2018  
Date Inspected: 20/03/2018 Inspected At: Trust Autoworks - Ang Mo Kio (HQ)  
Blk 5035, #01-345 Ang Mo Kio Industrial Pk 2  
Singapore 569538

Estimated Period of Repair: 2.0 days

Adjuster: KENNETH KONG

Manager: VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

## REPAIR DETAILS

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT O/S DOOR ASSY	Bent	1,866.70 FL	*1,866.70 FL
2	1		*FRONT O/S DOOR GLASS OUTER MOULDING	Scratched	126.70 FN	*126.70 FN
3	1		*FRONT O/S DOOR VIEW MIRROR	Cut	105.10 FN	*105.10 FN
4	1		*FRONT O/S DOOR BLACK STICKER	Necessary	30.00 FS	*30.00 FS

F=Franchise part, S=SpcNett, L=ListItemDisc, N=NettItemDisc.

<b>Sub Total (\$\$)</b>	<b>2,128.50</b>	<b>2,128.50</b>
- List Item Discount on L Items 30.00/30.00% (\$\$)	560.01	560.01
- Nett Item Discount on N Items 10.00/10.00% (\$\$)	23.18	23.18
<b>Total Parts (\$\$)</b>	<b>1,545.31</b>	<b>1,545.31</b>

Report was unsubmitted during this print-out.

**Recommended Miscellaneous Items**

There are no new miscellaneous items selected.

**Recommended Labour**

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	REMOVE/RENEW THE ABOVE ACCIDENT PARTS INCLUDING KNOCKING,WELDING & CUTTING	New	500.00	200.00
2	TO PUTTY AND SPRAY PAINT ON FRONT ACCIDENT PORTION	New	500.00	220.00
3	CHECK & RECONNECT WIRING	New	35.00	20.00
Gross Labour Cost (\$\$)			<b>1,035.00</b>	<b>440.00</b>

Report was unsubmitted during this print-out.

&lt; END OF ESTIMATES &gt;