

7/7/03/2002

ASS. REC. BY:

REF: CS/SPF/18005224/MJrd3n2 Special Instruction:

Surveyor: Ma ASSIGNMENT (Office)From (Person): Abdul Rehman of SPF Date/Time: 20/3/2018

Estimated Cost: \_\_\_\_\_ Bill to: \_\_\_\_\_

OD (TP) WS / TP RES / OD RES / EVA / INV / MV / CSTo Inspect Vehicle No: SIP 5064 G Insured: QX 319Dat Workshop m/s Falcon - Air Auto Services Tel: 67795665of 8 pendam loup (Blk 1 / Blk K)Policy No: \_\_\_\_\_ Claim No: AFMD / 105 / 009 / 2018 / 026Sum Insured: \_\_\_\_\_ Excess: \_\_\_\_\_ D.O.A. 12/02/2018Make of Veh: \_\_\_\_\_  
(Client's Record)CA / REV / REP. / REV 24 HRS lwp 28-03-2018 H.O.D. Endorsement: \_\_\_\_\_Date/Time: 4:30pm 20/3/18 Person Contacted: Andy Vehicle-IN/OUT (OUT)

Date/Time	Action/Instruction (✓) Estimate	Do not Finalize
	<u>SIP 5064 G - X</u>	
	<u>QX 319D - X</u>	
	<u>Submit \$700, 3 days</u>	
	<u>Red: \$343.60, 33%.</u>	

REF: SPF

## ASSIGNMENT

From:

Date: 28/3/18

Estimated Cost:

OD ☒ TP / WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No:

SLP 5064G

at Workshop m/s

Falcon-Air Auto Services

of 8pendan loop (Blk 1 / Blk K)

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

Andy

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value:

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

days

Res.: Yes or No

Lum Sum:

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

lwp

Date:

Person Contacted:

Vehicle: IN / OUT

Date / Time

Action / Instruction

Veh No:

SLP 5064G

Yr Regn:

2009

Type: ☒ M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

JOHN AVANTE

CC

1891

Colour:

Grey

A/C: Insured / Std / NI / NA

Sp. Reading:

119731

T/Radio: Insured / Std / NI / NA

Eng/No:

C/No:

KMH DU 41BR 94762488

Gen. Cond: ☒ Good / Fair / Poor / BurntSteering: ☒ In order / Jammed / Leaked / Burnt orBrake: ☒ In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

R:

185/65/215

BS / DUN / EXNOVA / GY / FS / LIZA / ☒ MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal.

mm

R/Bal.

mm

L/Bal.

mm

L/Bal.

mm

D.O.A.

12/02/2018

D.O.I.

28/3/2018

Survey held at:

Des. of Damages: Frt / ☒ Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

RECEIVED 09 APR 2018

Date/Time: File Pass to?

1)

typist

Date/Time: File Return to?

2)



Preli. Report



Final Report

Days Of Repair:

Resurvey No. of Trip:

Add Fee:



Site Insp (\$)



Interview (\$)



Tech. Invs (\$)



Weekend (\$)

Survey Fee:

Transportation

) \$ + RS \$

) Photos

) Others

TOTAL

Report Format :

Lump Sum / I.B.I: (\$)

280



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

SINGAPORE POLICE FORCE

Ref : CS/SPF18005224/M1rd3

?? POLICE DIVISIONSINGAPORE &nbsp;

Date : 21-03-2018



Code : SPF1

## 1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	QX 319D	Veh. Inspected	SLP 5064G
Policy No.		Coverage (\$)	0.00
Claim No.	AEMD/105/009/2018/026	Excess (\$)	0.00
Assign From	ABDUL RAHMAN	Assign Date	21/03/2018

## 2. Vehicle Particulars & Condition

Make & Model	c.c	0
Engine No.	HIDDEN	Year of Reg.
Chassis No.		Colour
Odometer	-	Steering
Brakes		Modification
General		

## 3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm

## 4. Description of Damages

--	--

## 5. General Information

Accident Date	12/02/2018	Inspection Date
Survey held at	FALCON-AIR AUTO SERVICES PTE LTD BLK 8 PANDAN LOOP SINGAPORE 128226	

## 5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.
--



# SINGAPORE POLICE FORCE

SPF Accidents Claims Section  
Automotive Engg & Mgmt Div  
Police Logistics Department  
No. 1 Mount Pleasant Road  
Block 8 Old Police Academy  
#02-12 Singapore 298333

Your Ref : SLP5064G

Our Ref : AEMD/105/009/2018/026

Date : 20 March 2018

Tel: 64784840

Fax: 64784848

M/s LKK Auto Consultants Pte Ltd  
Paya Ubi Industrial Park  
51 Ubi Avenue 1 #01/02-25  
Singapore 408933

Via Fax Only: 62564315

Dear Sir,

**RTA ON 12 FEBRUARY 2018 INVOLVING GOVT VEHICLE QX319D AND OTHER VEHICLE  
SLP5064G**

We refer to the above matter.

- 2 Please arrange for a Pre- Repair Inspection of vehicle no. SLP5064G at M/s Falcon-Air Auto Services Pte Ltd of 8 Pandan Loop (Blk 1 / Blk K), Singapore 128226.
- 3 For appointment kindly contact Mr Andy at Tel: 67795665.
- 4 Estimates were provided by the workshop.
- 5 Thank you.

Yours faithfully,

Abdul Rahman  
Accident Claims Officer  
for ASST DIRECTOR

## SINGAPORE ACCIDENT STATEMENT

### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

### ACCIDENT STATEMENT

Date Of Report 13/02/2018 16:55  
Date Of Accident 12/02/2018 17:55  
Exact Location Of Accident ALONG JURONG WEST AVE 1 FILTER LANE  
Country/State of Loss SINGAPORE

### DETAILS OF OWN VEHICLE

Vehicle Registration Number SLP5064G  
**Insured/Policyholder**  
Name Of Registered Owner RUCHI BHASIN  
NRIC No G5464438N  
Email Address RUCHIB3@GMAIL.COM  
Mobile Phone No (LOCAL) +65-86618707  
Alternative Phone No OTHERS-86618707  
**Vehicle Particulars**  
Manufacturer HYUNDAI  
Model AVANTE-1.6 (A)  
Exact Purpose for which vehicle was being used at time of accident  
Are you claiming under your own insurance policy for repair to your vehicle? NO  
If No, Please state action to be taken THIRD PARTY  
Vehicle Category PRIVATE CAR  
**Insurance Company**  
Name of Insurance Company NTUC INCOME INSURANCE CO-OPERATIVE LTD  
Type Of Coverage COMPREHENSIVE  
Fleet Policy NO  
Policy Number 5092065609  
Cover Note Number  
**Driver**  
Name of Driver RUCHI BHASIN  
NRIC No G5464438N  
Date Of Birth 03/08/1981  
Occupation INDOOR  
Date Of Driving Pass 26/03/2016  
Driving Experience 1 YEAR AND 10 MONTHS  
Gender FEMALE  
Mobile Number (LOCAL) +65-86618707  
Fax Number OTHERS-86618707  
Contact Number RUCHIB3@GMAIL.COM  
Email Address

Address N.A.  
Postcode  
Was driver an employee of the Insured's Company NO  
If No, Relationship of the Driver with the Insured OWNER  
Vehicle Registration Number of Driver's Own Vehicle -  
Vehicle -  
Insurance Company of Driver's Own Vehicle -

### General Information of the Accident

Type Of Accident COLLISION - HEAD TO REAR  
Weather Conditions CLEAR  
Road Surface DRY

### Other Information

Was any foreign vehicle involved in this accident? NO  
Number of vehicles involved in the accident  
Was any body injured in the Accident? NO  
Was any injured conveyed to hospital by ambulance?  
Was any other material or property damaged? YES  
I have been approached by unknown person(s) soliciting/offering accident claims assistance. NO  
Number of Passengers (Including Driver) 4  
Passenger 1

NAME: : AKSHIT JAGGI  
GENDER: : MALE

Passenger 2

NAME: : ANISHA JAGGI  
GENDER: : FEMALE

Passenger 3

NAME: : SOE SOE MYINT  
GENDER: : FEMALE

### Details of Police Action

Was the accident reported to the police? YES  
If Yes, Please state which Police Station  
Police Station Name  
Police Station Address  
Police Station Contact  
Was notice of intended Prosecution given? NO  
If Yes, against whom?

JURONG WEST NEIGHBOURHOOD POLICE CENTRE  
ROAD: 700 CORPORATION ROAD , POSTCODE: 649818 , COUNTRY:  
SINGAPORE  
TEL NO: 1800-2689999 - FAX NO: 62672438

### Circumstances of Accident

AS PER POLICE REPORT


### Attachment(s)

Are accident photos available for attachment? YES  
Was there any video captured by Car Camera? NO  
Was there any audio recorded? NO

### DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number QX319D  
Vehicle Make/Model/Colour  
Details Of Properties

# SKETCH PLAN



## DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

AS PER POLICE REPORT:

## DECLARATION

I/We declare the foregoing particulars are true in every respect.

*Pandi*  
Policyholder's Signature  
Date & Time:

*Pandi*  
Driver's Signature  
(If driver is not the policyholder)  
Date & Time:

*F.*  
Reporting Centre Personnel's Signature  
Name: GAIL NG  
NRIC/FIN No.: S8604533E






## SKETCH PLAN


### IMPORTANT NOTICE


1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
  - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
  - (ii) investigating the accident and/or my claims;
  - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
  - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
  - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims. (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
  - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
  - (ii) for complying with requirements under any regulations, laws or court orders.

  
Policyholder's Signature  
Date & Time:

  
Driver's Signature  
(If driver is not the policyholder)  
Date & Time:

  
Reporting Centre Personnel's Signature  
Name: GAILIN G  
NRIC/FIN No.: S8604538E







# SINGAPORE POLICE FORCE



T/20180212/2217

1 of 4

Police Station Of Origin:  
Jurong West N.P.C  
700 Corporation Road SINGAPORE 649818  
Tel No: 1800-2689999

Report No. T/20180212/2217

**REPORT OF A TRAFFIC ACCIDENT**

Date/Time Report Made: 12/02/2018 20:38		Vide Report No.:		Station Diary No.: 124	
<b>Informant's Particulars</b>					
Name of Informant: BHASIN RUCHI			Address: APT BLK 456 CORPORATION ROAD #02-03 PARC VISTA SINGAPORE 649813		
ID Type / ID No.: FIN NO / G5464438N			Contact No.: Home/Office:		Mobile: 86618707
Nationality: INDIAN			Email:		
Sex: Female	Age: 36	Date of Birth: 03/08/1981	Type of Informant: Driver		
Race: Indian			Language:		Institution / School Name:
Occupation: Housewife			Driving Licence Information: Class: 2B,3		Date of Expiry:

<b>General Information of the Accident</b>				
Type of Accident:	Non-Injury Police Vehicle	Drink Drive: No	Date/Time of Accident: 12/02/2018 17:55	Type of Location: Bend
Location: Along Road 1 Traveling Toward Road 2 JURONG WEST AVENUE 1 CORPORATION ROAD ACCIDENT HAPPEN ON FILTER LANE BETWEEN JURONG WEST AVENUE 1 AND CORPORATION RD				
Weather: Clear		Road Surface: Dry		Road Speed Limit:
Traffic Flow: One Way		Traffic Control: Not Controlled		Traffic Volume: Heavy
Type of Collision: Between Moving Vehicles - Head To Rear				Anyone conveyed by ambulance: No

Details of Vehicle Involved						
Vehicle No.	Type	Make	Model	Color	Condition	No of Passenger
QX319D	Car	TOYOTA	COROLLA ALTIS 1.6 AUTO	White	Slightly Damaged	1
SLP5064G	Car	HYUNDAI	HD AVANTE 1.6 A	Grey	Slightly Damaged	3

Details of Vehicle Insurance			
Vehicle No.	Insurance Company	Insurance No	Effective      Expiry Date



# SINGAPORE POLICE FORCE

Police Station Of Origin:  
Jurong West N.P.C  
700 Corporation Road SINGAPORE 649818  
Tel No: 1800-2689999



T/20180212/2217

2 of 4

Report No: T/20180212/2217

## CONTINUATION OF REPORT

Details of Vehicle Insurance		Insurance No	Effective	Expiry Date
Vehicle No.	Insurance Company	5092065609	21/06/2017	20/06/2018
SLP5064G	NTUC Income Insurance Co-Operative Limited			

Limited			
Details of Person Involved			
Any Pedestrian Involved: No		Use of Pedestrian Crossing: NA	
No. of Pedestrians Injured: NIL			
Driver		ID No.	S8318092G
Name	Saravanan	Contact No.	91274564
Related Vehicle	QX319D (Car)	Class of Driving Licence & Expiry Date	Class: NIL Date of Expiry: NIL
Hospital/Clinic	NIL	Date Treatment	NIL
No. of Days granted Medical Leave		Date Discharge	NIL
NIL		Degree of Injury	NIL
Driver			
Name		ID No.	G5464438N
BHASIN RUCHI		Contact No.	86618707
Related Vehicle	SLP5064G (Car)	Class of Driving Licence & Expiry Date	Class: 2B,3 Date of Expiry: NIL
Hospital/Clinic	NIL	Date Treatment	NIL
No. of Days granted Medical Leave		Date Discharge	NIL
NIL		Degree of Injury	NIL

### Brief Details.

On 12/02/2018 at 1755hrs I was driving a grey Hyundai HD Avante , SLP5064G along Jurong West Avenue 1 and turned left on the filter lane to head towards Corporation Rd. I then stopped at the stop line and waited for the road to clear to move off when I suddenly felt a small impact at my rear. I exited my vehicle and observed a police vehicle a Toyota Corolla , QX319D had collided against my rear body panel. There was no medical attention required at scene. My vehicle suffered slight scratches and a small dent.

Police vide incident report no: J/20180212/0228. I do not have any dash camera on my vehicle.



SINGAPORE  
POLICE FORCE



T/20180212/2217

3 of 4

Police Station Of Origin:

Jurong West N.P.C

700 Corporation Road SINGAPORE 649818

Tel No: 1800-2689999

Report No. T/20180212/2217

CONTINUATION OF REPORT



SINGAPORE  
POLICE FORCE



T/20180212/2217

4 of 4

Report No. T/20180212/2217

Police Station Of Origin:  
Jurong West N.P.C  
700 Corporation Road SINGAPORE 649818  
Tel No: 1800-2689999

CONTINUATION OF REPORT

Sketch Plan

Informant is not able to provide sketch plan

IMPORTANT: Please attach a copy of your vehicle's Insurance Certificate to this report. If you don't have the certificate with you now, please fax a copy to 65474885 stating the report number as reference.

Signature Of Officer Recording The Report:  
J/  
Sgt 2 SITI KHAIRUNNISA BINTE RAMANAH

Signature Of Interpreter:  
Not applicable

Officer In Charge Of Case:  
TP / DDGVT /  
Sr Staff Sgt CHONG GUAN FATT  
Contact No.: 65476198


Authentication Stamp  
NP168

Signature Of Informant:

*Rueh*

Date/Time:  
12/02/2018 20:38

Classification Of Case:



FALCON-AIR

RUCHI BHASIN

BLK456 CORPORATION ROAD #02-03 PARC VISTA 649813  
SINGAPORE

Attention : Motor Claim Department

Contact : 86618707

FALCON-AIR AUTO SERVICES PTE LTD

CO. REG. NO.: 1995-01140-D

GST REG. NO.: 19-9501140-D

Estimate : ES003140

Date : 19/03/2018

Vehicle Num. : SLP5064G

Make/Model : HYUNDAI AVANTE

Chassis/Eng# : KMHU41BR9U762488

Accident Date : 12/02/2018

Claim No. :

Reference : TP NTUC VS SPF

Policy No. :

S/N	Quantity	Particular	Unit Price	Amount S\$
1.	1	LIST ITEMS :		
2.	1	BOOTLID LOGO		23.30
		BOOTLID EMBLEM AVANTE		31.20
		List TotalS\$ :		54.50
		20.00% Discount S\$ :		10.90
				43.60
		LABOUR :		
		SPRAY PAINTING ON ACCIDENT DAMAGED AREAS		
		TO REPAIR BOOTLID, REAR BUMPER REAR END PANEL		
		Labour Total S\$ :		1,000.00

HA Author  
Labour only  
28/3/2018  
3w days

E. & O.E.

Total S\$ : 1,043.60



for FALCON AIR AUTO SERVICES PTE LTD

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

FALCON-AIR AUTO SERVICES PTE LTD

(a subsidiary of Falcon-Air Holdings Pte Ltd)

Head Office: 176 Sin Ming Drive #01-06/07/13, #05-17 Sin Ming Autocare Singapore 575721 Tel: 6452-0880/6458-0880 Fax: 6454-7862

Branches: Tampines St 93 Blk 9006 #01-200 S(528840) Tel: 6789-7997 Fax: 6788-7997 • No. 8 Pandan Loop (Blk I / Blk K) S(128226) Tel: 6779-5665 Fax: 6779-1110

Websites: www.falconair.com.sg E-mail: email@falconair.com.sg



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

AUTOMOTIVE ENGINEERING & MGT DIVISION

Ref : CS/SPF18005224/M1rd3n2

ACCIDENT CLAIM SECTION  
(SINGAPORE POLICE FORCE)

1 MOUNT PLEASANT ROAD

BLK 8 OLD POLICE ACADEMYSINGAPORE 298333

Date : 11-04-2018



Code : SPF

## 1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	QX 319D	Veh. Inspected	SLP 5064G
Policy No.		Coverage (\$)	0.00
Claim No.	AEMD/105/009/2018/026	Excess (\$)	0.00
Assign From	ABDUL RAHMAN	Assign Date	20/03/2018

## 2. Vehicle Particulars & Condition

Make & Model	HYUNDAI AVANTE	c.c	1591
Engine No.	HIDDEN	Year of Reg.	200
Chassis No.	KMH DU41BR9U762488	Colour	GREY
Odometer	119731	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	GOOD		

## 3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	185/65 R15	MICHELIN	8 mm
L/H Front Tyre	185/65 R15	MICHELIN	8 mm
R/H Rear Tyre	185/65 R15	MICHELIN	8 mm
L/H Rear Tyre	185/65 R15	MICHELIN	8 mm

## 4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.
--

## 5. General Information

Accident Date	12/02/2018	Inspection Date	28/03/2018
Survey held at	FALCON-AIR AUTO SERVICES PTE LTD BLK 8 PANDAN LOOP SINGAPORE 128226		

## 5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.
--

## 5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	3 Working Days
-------------------------------------	----------------



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

## ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLP 5064G

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<b><u>REPLACEMENT OF PARTS</u></b>			
1	BOOTLID LOGO	NOT NECESSARY	23.30	-
1	BOOTLID EMBLEM AVANTE	NOT NECESSARY	31.20	-
	LESS 20% DISCOUNT		-10.90	-
			43.60	-
	<b><u>LABOUR</u></b>			
	SPRAY PAINTING ON ACCIDENT DAMAGED AREAS.		650.00	400.00
	TO REPAIR BOOTLID,REAR BUMPER,REAR END PANEL.		350.00	300.00
			1,000.00	700.00
	<b>GRAND TOTAL</b>		<b>1,043.60</b>	<b>700.00</b>

<b>RECOMMENDED COST OF REPAIRS</b>			<b>700.00</b>
------------------------------------	--	--	---------------

Report Ref No. CS/SPF18005224/M1rd3n2

MA CHIN FOOK

Automotive Assessor

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

**DISCLAIMER OF LIABILITY TO THIRD PARTIES:-** This Report is made solely for the use and benefit of the Client named on the front page of this Report. No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.