

11/02/2003

ASS. REC. BY:

REF: CS3/MSG18005239/Rld302

Range

Surveyor
Menimen

Rasul

ASSIGNMENT (Office)

From (Person):

Christina Wong

of

MSG

Date/Time: 20/3/18 @

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SLV 4604Z

Insured:

SJU 3887J

at Workshop m/s

United SG Automobile

Tel:

9007 7556

of

53 Ubi Ave 1 # 01-56

Policy No:

A29054489QMX

Claim No:

552783

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A

16/3/2018

CA / REV / REP. / REV 24 HRS lwp

Date/Time:

4:03pm @ 20/3/18

Person Contacted:

Sharon

H.O.D. Endorsement:

Vehicle

IN OUT

Date/Time	Action/Instruction (✓) Estimate	
	SLV 4604Z - NA/INC18005051/h4	D.O.A. 16/3/18
	SJU 3887J - NA/INC18005051/h4	D.O.A. 16/3/18
	Dismantle: 22/3/2018 (Naz)	
	After repair: 26/3/2018 (Naz)	

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	20 Mar 2018		20 Mar 2018 15:25 Assign				New Assignment Cancel Case

Main

Reference

Claim Details

Documents

[Show All](#)

CLAIM SUBFOLDER DETAILS

[Created by insurer]

Insured:	KAMAL BATCHA, ID: S1388859J, Tel: +6590613500, Email: ADAMNSK2@GMAIL.COM		
Main Claimant:	H & H RENTAL & LEASING PTE. LTD, Co. Reg. No.: 201703965Z		
Vehicle Reg. No.:	SLV4604Z	Date of Loss:	16/03/2018 15:00 - :59
Claim Type:	TP / 552783	Policy/Cover Note No.:	A29054489QMX (Comprehensive) Coverage: 02/12/2017 - 01/12/2018
Vehicle Reg. No. (Insured):	SJU3887J	Policy No. (Claimant):	
		Excess:	
Repairer:	United SG Automobile Pte Ltd (HQ) 53 Ubi Avenue 1, #01-56 Paya Ubi Industrial Park, 408934 Ubi - Tel: 9007 7556		
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Christina Wong - 6643 1311]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Imm.Advice due 21/03/2018]		
Driver/Custodian (Insured):	KAMAL BATCHA (60 / Male), NRIC: S1388859J, Tel: +6590613500		

ASSOCIATED MAIL RECEIVED

[View All](#)[Compose Case Mail](#)

There are no mail for this case.

ALL ASSOCIATED TASKS

[View All](#)[Search Tasks](#)[Create New Task](#)[Complete](#)

Due Date Priority Type Task Group Subject Handler Assigned By Completed On Created On Done?

No results.

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Company
Owner ID:	3965Z
Vehicle Details	
Vehicle No.:	SLV4604Z
Vehicle to be Exported:	Yes
Intended De-registration Date:	07 May 2018
Vehicle Make:	TOYOTA
Vehicle Model:	SIENTA HYBRID 1.5G CVT
Primary Colour:	Blue
Manufacturing Year:	2017
Engine No.:	1NZ8319856
Chassis No.:	NHP1707102791
Maximum Power Output:	73.0 kW (97 bhp)
Open Market Value:	\$25,875.00
Original Registration Date:	29 Dec 2017
First Registration Date:	29 Dec 2017
Transfer Count:	0
Actual ARF Paid:	\$5,000.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	28 Dec 2027
PARF Rebate Amount:	\$3,750.00
Intended COE Rebate Details	
COE Expiry Date:	28 Dec 2027
COE Category:	A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$42,339.00
COE Rebate Amount:	\$33,871.00
Total Rebate Amount:	\$37,621.00

The information contained herein is correct as at 07 May 2018

OK

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	16/03/2018 17:23
Date Of Accident	16/03/2018 15:05
Exact Location Of Accident	CLAYMORE RD
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SLV4604Z
Insured/Policyholder	
Name Of Registered Owner	H & H RENTAL & LEASING PTE. LTD.
Co Reg No	201703965Z
Email Address	NOEMAIL
Mobile Phone No	
Alternative Phone No	OFFICE-67433291

Vehicle Particulars

Manufacturer	TOYOTA
Model	SIENTA
Exact Purpose for which vehicle was being used at time of accident	COMMERCIAL USE
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE HIRE

Insurance Company

Name of Insurance Company	NTUC INCOME INSURANCE CO-OPERATIVE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	5090735902
Cover Note Number	-

Driver

Name of Driver	JEFFREY LIM CHYE HUA
NRIC No	S1444672I
Date Of Birth	21/05/1960
Occupation	OUTDOOR
Date Of Driving Pass	11/08/1980
Driving Experience	37 YEARS AND 7 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-96254084
Fax Number	
Contact Number	
EMail Address	NOEMAIL

Address	BLK 510A YISHUN ST 51 #07-565
Postcode	761510
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OTHER - HIRER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	COLLISION - HEAD TO REAR
Weather Conditions	RAINING
Road Surface	WET

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles involved in the accident	
Was any body injured in the Accident?	YES
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	2
Passenger 1	NAME: : UNKNOWN GENDER: : FEMALE

Details of Police Action

Was the accident reported to the police?	YES
If Yes, Please state which Police Station	
Police Station Name	YISHUN SOUTH NEIGHBOURHOOD POLICE CENTRE
Police Station Address	ROAD: 32 YISHUN ST 81 , POSTCODE: 768456 , COUNTRY: SINGAPORE
Police Station Contact	TEL NO: 1800-8522999 - FAX NO: 68522239
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

I WAS TRAVELLING ALONG CLAYMORE RD, WHEN NOTICED MY FRONT VEH SLOW DOWN AND STOP FOR TURNING INTO ETON HOUSE, AS SUCH I FOLLOW TO SLOW DOWN AND STOPPED. ALL OF A SUDDEN, I FELT AN IMPACT FROM BEHIND. AFTER THE INCIDENT, I ALIGHTED FROM MY VEH AND REALIZED VEH B (BEARING NO SJU3887J) FROM BEHIND COLLIDED ONTO MY VEH REAR PORTION.

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	YES
Remarks/ Reasons:	WITH DRIVER
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SJU3887J
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	ADAM
NRIC/Passport Number	

Contact Number	90613500
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	1

DETAILS OF INJURED PERSON 1

Name	JEFFREY LIM CHYE HUA
Approximate Age	
Injuries Sustain	NECK & BACK
Injured person in which vehicle?	SLV4604Z
Were seat belts worn?	YES
Was this injured conveyed to hospital by ambulance?	NO
Address	
Postcode	

Accident Sketch Plan

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this form and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purposes of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes");
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.




Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

Accident Sketch Plan

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

Please Refer to statement

DECLARATION
I/We declare that the above particulars are true in every respect.



Policyholder's Signature
Date & Time:

Driver's Signature
(if driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

POLICE REPORT



**SINGAPORE
POLICE FORCE**



1/201803162197

Police Station Of Origin
Yishun South N.P.C.
32 Yishun Street B1 SINGAPORE 768450
Tel No 1800-8522999

Page 1
Report No: 7501303/02197

REPORT OF A TRAFFIC ACCIDENT

Date/Time Report Made 16/03/2018 22:58	Video Report No	Station Diary No 84
---	-----------------	------------------------

Informant's Particulars

Name of Informant JEFFREY LIM CHYE HUA			Address APT BLK 510A YISHUN STREET 51 #07-565 SINGAPORE 761510		
ID Type / ID No NRIC NO / S14446721			Contact No Home/Office: Mobile: 96254084		
Nationality SINGAPORE CITIZEN			Email		
Sex Male	Age 57	Date of Birth 21/05/1960	Type of Informant Driver		
Race Chinese			Language		Institution / School Name
Occupation UBER DRIVER			Driving Licence Information Class: 2B,3		Date of Expiry

General Information of the Accident

Type of Accident	Injury Others	Drink Drive No	Date/Time of Accident 16/03/2018 15:10	Type of Location Straight Road
Location Along Road 1 CLAYMORE ROAD				
towards orchard tower				
Weather Drizzling		Road Surface Wet		Road Speed Limit 1
Traffic Flow Two Way		Traffic Control Not Controlled		Traffic Volume No Traffic
Type of Collision Between Moving Vehicles - Head To Rear				Anyone conveyed by ambulance No

Details of Vehicle Involved

Vehicle No.	Type	Make	Model	Color	Condition	No of Passenger
SJU1887J	Car				No Damage	0
SLV4604Z	Car				Slightly Damaged	1

Details of Person Involved

Any Pedestrian Involved: No	
No. of Pedestrians Injured: NIL	Use of Pedestrian Crossing: NA

POLICE REPORT



SINGAPORE
POLICE FORCE



T/20180316/2197

Police Station Of Origin
Yishun South N.P.C.
32 Yishun Street B1 SINGAPORE 768456
Tel No. 1800-8522999

3 of 3

Report No. T/20180316/2197

CONTINUATION OF REPORT

Sketch Plan

Informant is not able to provide sketch plan

IMPORTANT: Please attach a copy of your vehicle's Insurance Certificate to this report. If you don't have the certificate with you now, please fax a copy to 65474885 stating the report number as reference

Signature Of Officer Recording The Report:

F /

Sgt 2 LUM JUN KAI

Signature Of Informant:

Signature Of Interpreter:

Not applicable

Date/Time:

16/03/2018 22:58

Officer In Charge Of Case:

TP / AEIT /

Staff Sgt TANG SIEW PING

Contact No. 65476430



Signature:

Classification Of Case:

IN 000

Authentication Stamp

NP 168

Singapore Police Force

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	20 Mar 2018		20 Mar 2018 15:25 Edit Adj Rpt	S\$0.00 Edit Estimates	S\$0.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All
-------------	------------------	----------------------	------------------	--------------------------

CLAIM SUBFOLDER DETAILS [Created by insurer]

Insured:	KAMAL BATCHA , ID: S1388859J, Tel: +6590613500, Email: ADAMNSK2@GMAIL.COM		
Main Claimant:	H & H RENTAL & LEASING PTE. LTD. , Co. Reg. No.: 201703965Z		
Vehicle Reg. No.:	SLV4604Z	Date of Loss:	16/03/2018 15:00 - :59 [2 Months and 16 Days From LTA Reg Date (Man Yr)]
Claim Type:	TP / 552783	Policy/Cover Note No.:	A29054489QMX (Comprehensive) Coverage: 02/12/2017 - 01/12/2018
Vehicle Reg. No. (Insured):	SJU3887J	Policy No. (Claimant):	
		Excess:	
Repairer:	United SG Automobile Pte Ltd (HQ) 53 Ubi Avenue 1, #01-56 Paya Ubi Industrial Park, 408934 Ubi - Tel: 9007 7556		
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Christina Wong - 6643 1311]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by MOHD RASUL] ... [Imm.Advice due 21/03/2018]		
Driver/Custodian (Insured):	KAMAL BATCHA (60 / Male), NRIC: S1388859J, Tel: +6590613500		

ASSOCIATED MAIL RECEIVED [View All](#) [Compose Case Mail](#)



































There are no mail for this case.




























ALL ASSOCIATED TASKS [View All](#) [Search Tasks](#) [Create New Task](#) [Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*SLV4604Z (552783)
[SJU3887J]
TP
H & H RENTAL & LEASING PTE. LTD
Mar 16 2018 3:00PM
[KAMAL BATCHA]
United SG Automobile Pte Ltd

Upload Documents			Upload Photos		Compose New Letter		View		View in Browser		
Assessment Reports							1 per page		<input checked="" type="checkbox"/>		
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail		Print						
1	20/03/18 15:27	Accident Statement From: SC - Reg. No: SJU3887J, Claimant: KAMAL BATCHA			Load HTM						
							3 per page		<input checked="" type="checkbox"/>		
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail		Print						
1	07/05/18 12:06	General View			Load JPG		<input checked="" type="checkbox"/>				
2	07/05/18 12:06	General View			Load JPG		<input checked="" type="checkbox"/>				
3	07/05/18 12:06	General View			Load JPG		<input checked="" type="checkbox"/>				
4	07/05/18 12:06	General View			Load JPG		<input checked="" type="checkbox"/>				
5	07/05/18 12:06	General View			Load JPG		<input checked="" type="checkbox"/>				
6	07/05/18 12:06	General View			Load JPG		<input checked="" type="checkbox"/>				
7	07/05/18 12:06	General View			Load JPG		<input checked="" type="checkbox"/>				
8	07/05/18 12:06	General View			Load JPG		<input checked="" type="checkbox"/>				
9	07/05/18 12:06	General View			Load JPG		<input checked="" type="checkbox"/>				
10	07/05/18 12:06	General View			Load JPG		<input checked="" type="checkbox"/>				
11	07/05/18 12:06	General View			Load JPG		<input checked="" type="checkbox"/>				
12	07/05/18 12:06	General View			Load JPG		<input checked="" type="checkbox"/>				
13	07/05/18 12:06	General View			Load JPG		<input checked="" type="checkbox"/>				
14	07/05/18 12:06	General View			Load JPG		<input checked="" type="checkbox"/>				
15	07/05/18 12:06	General View			Load JPG		<input checked="" type="checkbox"/>				
16	07/05/18 12:06	General View			Load JPG		<input checked="" type="checkbox"/>				
17	07/05/18 12:06	General View			Load JPG		<input checked="" type="checkbox"/>				
18	07/05/18 12:06	General View			Load JPG		<input checked="" type="checkbox"/>				
19	07/05/18 12:06	General View			Load JPG		<input checked="" type="checkbox"/>				
20	07/05/18 12:06	General View			Load JPG		<input checked="" type="checkbox"/>				
21	07/05/18 12:06	General View			Load JPG		<input checked="" type="checkbox"/>				
22	07/05/18 12:06	General View			Load JPG		<input checked="" type="checkbox"/>				
23	07/05/18 12:06	General View			Load JPG		<input checked="" type="checkbox"/>				
24	07/05/18 12:06	General View			Load JPG		<input checked="" type="checkbox"/>				
25	07/05/18 12:13	Photographs of Damaged Parts			Load JPG		<input checked="" type="checkbox"/>				
26	07/05/18 12:13	Photographs of Damaged Parts			Load JPG		<input checked="" type="checkbox"/>				
27	07/05/18 12:13	Photographs of Damaged Parts			Load JPG		<input checked="" type="checkbox"/>				
28	07/05/18 12:13	Photographs of Damaged Parts			Load JPG		<input checked="" type="checkbox"/>				
29	07/05/18 12:13	Photographs of Damaged Parts			Load JPG		<input checked="" type="checkbox"/>				
30	07/05/18 12:13	Photographs of Damaged Parts			Load JPG		<input checked="" type="checkbox"/>				
31	07/05/18 12:13	Photographs of Damaged Parts			Load JPG		<input checked="" type="checkbox"/>				
32	07/05/18 12:13	Photographs of Damaged Parts			Load JPG		<input checked="" type="checkbox"/>				
33	07/05/18 12:13	Photographs of Damaged Parts			Load JPG		<input checked="" type="checkbox"/>				

Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
34	07/05/18 12:13	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
35	07/05/18 12:13	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
36	07/05/18 12:13	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
37	07/05/18 12:13	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
38	07/05/18 12:13	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
39	07/05/18 12:13	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
40	07/05/18 12:13	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
41	07/05/18 12:13	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
42	07/05/18 12:13	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
43	07/05/18 12:13	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
44	07/05/18 12:13	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
45	07/05/18 12:13	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
46	07/05/18 12:13	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
47	07/05/18 12:13	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
48	07/05/18 12:13	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
49	07/05/18 12:13	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
50	07/05/18 12:13	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
51	07/05/18 12:13	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
52	07/05/18 12:13	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
53	07/05/18 12:13	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
54	07/05/18 12:13	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
55	07/05/18 12:13	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
56	07/05/18 12:13	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
57	07/05/18 12:13	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
58	07/05/18 12:13	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
59	07/05/18 12:13	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
60	07/05/18 12:13	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
61	07/05/18 12:13	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
62	07/05/18 12:13	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
63	07/05/18 12:13	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
64	07/05/18 12:13	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
65	07/05/18 12:13	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
66	07/05/18 12:13	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
67	07/05/18 12:13	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
68	07/05/18 12:13	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
69	07/05/18 12:13	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
70	07/05/18 12:13	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
71	07/05/18 12:13	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
72	07/05/18 12:13	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
73	07/05/18 12:13	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
74	07/05/18 12:13	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
75	07/05/18 12:13	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
76	07/05/18 12:13	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
77	07/05/18 12:13	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
78	07/05/18 12:13	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
79	07/05/18 12:13	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
80	07/05/18 12:13	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
81	07/05/18 12:13	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
82	07/05/18 12:13	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
83	07/05/18 12:13	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>

Assessment Reports				1 per page	<input checked="" type="checkbox"/>
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)		Thumbnail	Print
84	07/05/18 12:13	Photo After Spray		Load JPG	<input checked="" type="checkbox"/>
85	07/05/18 12:13	Photo After Spray		Load JPG	<input checked="" type="checkbox"/>
86	07/05/18 12:13	Photo After Spray		Load JPG	<input checked="" type="checkbox"/>
87	07/05/18 12:13	Photo After Spray		Load JPG	<input checked="" type="checkbox"/>
88	07/05/18 12:13	Photo After Spray		Load JPG	<input checked="" type="checkbox"/>
89	07/05/18 12:13	Photo After Spray		Load JPG	<input checked="" type="checkbox"/>
90	07/05/18 12:13	Photo After Spray		Load JPG	<input checked="" type="checkbox"/>
91	07/05/18 12:13	Photo After Spray		Load JPG	<input checked="" type="checkbox"/>
92	07/05/18 12:13	Photo After Spray		Load JPG	<input checked="" type="checkbox"/>
93	07/05/18 12:13	Photo After Spray		Load JPG	<input checked="" type="checkbox"/>
94	07/05/18 12:13	Photo After Spray		Load JPG	<input checked="" type="checkbox"/>
95	07/05/18 12:13	Photo After Spray		Load JPG	<input checked="" type="checkbox"/>
96	07/05/18 12:13	Photo After Spray		Load JPG	<input checked="" type="checkbox"/>
97	07/05/18 12:13	Photo After Spray		Load JPG	<input checked="" type="checkbox"/>
98	07/05/18 12:13	Photo After Spray		Load JPG	<input checked="" type="checkbox"/>
99	07/05/18 12:13	Photo After Spray		Load JPG	<input checked="" type="checkbox"/>
100	07/05/18 12:13	Photo After Spray		Load JPG	<input checked="" type="checkbox"/>
101	07/05/18 12:13	Photo After Spray		Load JPG	<input checked="" type="checkbox"/>
102	07/05/18 12:13	Photo After Spray		Load JPG	<input checked="" type="checkbox"/>
103	07/05/18 12:13	Photo After Spray		Load JPG	<input checked="" type="checkbox"/>
104	07/05/18 12:13	Photo After Spray		Load JPG	<input checked="" type="checkbox"/>
105	07/05/18 12:13	Photo After Spray		Load JPG	<input checked="" type="checkbox"/>
106	07/05/18 12:13	Photo After Spray		Load JPG	<input checked="" type="checkbox"/>
107	07/05/18 12:13	Photo After Spray		Load JPG	<input checked="" type="checkbox"/>
108	07/05/18 12:13	Photo After Spray		Load JPG	<input checked="" type="checkbox"/>
109	07/05/18 12:13	Photo After Spray		Load JPG	<input checked="" type="checkbox"/>
110	07/05/18 12:13	Photo After Spray		Load JPG	<input checked="" type="checkbox"/>
111	07/05/18 12:13	Photo After Spray		Load JPG	<input checked="" type="checkbox"/>
112	07/05/18 12:13	Photo After Spray		Load JPG	<input checked="" type="checkbox"/>
113	07/05/18 12:13	Photo After Spray		Load JPG	<input checked="" type="checkbox"/>
114	07/05/18 12:13	Photo After Spray		Load JPG	<input checked="" type="checkbox"/>
Documentation				1 per page	<input checked="" type="checkbox"/>
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)		Thumbnail	Print
1	20/03/18 15:19	Email frm TP - PRI		Load PDF	
2	20/03/18 15:20	Notice to conduct PRI		Load PDF	
3	20/03/18 15:27	SLV4604Z GIA Rpt From:SC - Reg. No: SJU3887, Claimant: KAMAL BATCHA		Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST		Reset	Save	Print
There are no document checklists configured.				
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ) <div style="border: 1px solid black; height: 100px; width: 100%;"></div>				
Show Remarks To: <input type="checkbox"/> Handling Insurer <small>Note: Remarks are private unless you show it to other parties.</small>				

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS3/MSG18005239/R1D3E2

Date: 07/05/2018

REFERENCE

Handling Insurer: MSIG Insurance (Singapore) Pte. Ltd.

Policy No:

A29054489QMX

Claimant Vehicle
No : SLV4604Z

Insured Vehicle No :

SJU3887J

Date of Loss: 16/03/2018

Nature of Claim:

TP

Claim No: 552783

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SLV4604Z

Make & Model: TOYOTA SIENTA HYBRID, 1.5 X CVT (A)

Engine No: 1NZ8319856

Reg. Date: 29/12/2017 (Man. Year: 2017)

Chassis No: NHP1707102791

Colour: Blue

Odometer: 22258 km

Engine Capacity: 1496 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable):

Yes

Footbrake (Serviceable):

Yes

Handbrake (Serviceable): Yes Engine Modification:

No

Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 185/60 R15

Rear Tyre Size:

185/60 R15

Front Left Side: Toyo 6 mm

Rear Left Side:

Toyo 6 mm

Front Right Side: Toyo 6 mm

Rear Right Side:

Toyo 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Nett Amount (S\$)	0.00	0.00	0.00	

INSPECTION

Date of Assignment: 20/03/2018

Date Inspected: 21/03/2018 Inspected At:

United SG Automobile Pte Ltd (HQ)
53 Ubi Avenue 1, #01-56 Paya Ubi
Industrial Park
Singapore 408934

Estimated Period of Repair: 0.0 days

Adjuster: MOHD RASUL

Manager: Nivitha Govindasamy

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

A)THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.

B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION.

THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE.

C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.

THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$3,000.00 -\$4,000.00

REPAIR DETAILS

Reference

Part Source: MRM-SG	Version: 1.0 (Last Synchronised: 07 May 2018)
Parts: M1-MPV	TOYOTA SIENTA HYBRID 1.5 X CVT (A) (Catalogue:Merimen Singapore 1.0)
Labour: Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SLV4604Z)
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

There are no new parts selected.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.

< END OF ESTIMATES >