

Consent

ASS. REC. BY:

REF:

CS/MSG18005252/Rld3

Special Instructions

Surveyor
Menmen

Rosa

ASSIGNMENT (Office)

From (Person):

Christina Wong

v

MSG

Date/Time:

19/3/18 @ 6:08pm

Estimated Cost:

Bill by:

OD / TI / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SHA 3157L

Insured:

FBG 4497M

at Workshop in/:

Comfort Delgro

Tel:

62148300

of

59 Layang Drive

Policy No:

MSD/VMS/17-367237-CA

Claim No:

MSC/v/18-000412

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A.

17/03/2018

CA / REV / REP. / REV 24 HRS

wp

H.O.D. Endorsement:

Date/Time:

20/3/18 @ 9.21am

Person Contacted:

Vehicle

IN/OUT

Date/Time:

Action/Instruction (✓) Estimate

SHA 3157L-CC3/FC 15009385/Kay 3k3

D.O.A. 4/3/15

FBG 4497M-x

Sent poli thru menmen

Accident *Pass*

REF: MSIG

3821R

ASSIGNMENT

From: _____ Date: **20/3/18**
 Estimated Cost: _____
 OD / (TP) / WS / TP RES / OD RES / EVA / INV / MV
 To Inspect Vehicle No: **SHA 3157L**
 at Workshop no/s: **Comfort Delgro**
 of: **59 kayong Drive**
 Insured: _____
 Policy No: _____
 Claims No: _____
 Sum Insured: _____ Excess: _____
 (Client's Record)
 Make of Veh: _____

(Policy Condition)
 Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

Bal. or Market Value: _____
 IDAC Accident Report: _____ Consistent? : Yes or No
 GIA / PR Seen: _____ Consistent? : Yes or No
 Est. Repairs: _____ days Res: Yes or No
 Lump Sum: _____ % 3 Val: Yes or No
 CA / REV / REP. / 24 HRS *wp*
 Date: _____ Person Contacted: _____ Vehicle: IN / OUT

Veh No: **SHA 3157L** Yr Regn: **2017** *Jan*
 Type: M.Car / M.Cycle / Bus / Van / Lorry (Car) / Prime Mover /
 Truck / Trailer or
 Make: **Hyundai** 140 C.C. **1685**
 Colour: **Blue** A/C: Insured / Std / NI / NA
 Sp. Reading: **152828** T/Radio: Insured / Std / NI / NA
 Eng/No: _____
 C/No: **KMH LB4AMH 098224**
 Gen. Cond: Good / Fair / Poor / Burnt
 Steering: Inorder / Jammed / Leaked / Burnt or
 Brake: Inorder / Jammed / Leaked / Burnt or
 Modi: NK / S/Rim / STD A/Rim or
 Tyre Size: F: **205/60R16**
 R: _____
 BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
 TOYO / YOKO or **Hankook**
 Front: _____ Rear: _____
 R/Bal. **S** mm R/Bal. **S** mm
 L/Bal. **S** mm L/Bal. **S** mm
 D.O.A. **17/03/18** D.O.I. **20/03/18**
 Survey held at **Comfort Delgro**
 Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or
Rear O/S
 The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

*Confirm \$3109.60, 5 days
 Ref: \$ 305.60, 8%.*

[Signature]
9/4/2018

RECEIVED 09 APR 2018

Date/Time: File Pass to? ☐ : Preli. Report
☒ : Final Report
 Date/Time: File Return to? _____

Days Of Repair: **5**
 Resurvey No. of Trip: **1**

Survey Fee: _____
 Transportation: _____

 TOTAL: _____

Add Fee: ☐ Site Insp \$
☐ Interview \$
☐ Tech. Insp \$
☐ Weekend \$

Report Format: **TP**
 Lump Sum / I.B.I: **\$3109.60**

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	19 Mar 2018		19 Mar 2018 18:08 Assign				New Assignment Cancel Case

Main

Reference

Claim Details

Documents

[Show All](#)

CLAIM SUBFOLDER DETAILS

[Created by insurer]

Insured:	ERFAN HUSAIN RAJIWATE, ID: S7868631F		
Main Claimant:	COMFORT TRANSPORTATION PTE LTD, Co. Reg. No.: 199303821R		
Vehicle Reg. No.:	SHA3157L	Date of Loss:	17/03/2018 12:00 - :59
Claim Type:	TP / MSC/V/18-000412	Policy/Cover Note No.:	MSD/VMS/17-367237-CA (TP, Fire & Theft) Coverage: 21/07/2017 - 20/07/2018
Vehicle Reg. No. (Insured):	FBG4497M	Policy No. (Claimant):	
		Excess:	
Repairer:	ComfortDelGro Engineering Pte Ltd (Loyang) 59 Loyang Drive, 508969 Loyang - Tel: 6214 8300		
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Christina Wong - 6643 1311]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Imm.Advice due 20/03/2018]		

ASSOCIATED MAIL RECEIVED

[View All](#)[Compose Case Mail](#)

There are no mail for this case.

ALL ASSOCIATED TASKS

[View All](#)[Search Tasks](#)[Create New Task](#)[Complete](#)

Due Date Priority Type Task Group Subject Handler Assigned By Completed On Created On Done?

No results.



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

MSIG INSURANCE (SINGAPORE) PTE LTD

Ref : CS/MSG18005252/R1rd3

16 RAFFLES QUAY
#24-01 HONG LEONG BLDG SINGAPORE 048581

Date : 21-03-2018



Code : MSG

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	FBG 4497M	Veh. Inspected	SHA 3157L
Policy No.	MSD/VMS/17-367237-CA	Coverage (\$)	0.00
Claim No.	MSC/V/18-000412	Excess (\$)	0.00
Assign From	MERIMEN (CHRISTINA WONG)	Assign Date	21/03/2018

2. Vehicle Particulars & Condition

Make & Model	c.c	0
Engine No.	HIDDEN	Year of Reg.
Chassis No.		Colour
Odometer	-	Steering
Brakes		Modification
General		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm

4. Description of Damages

--	--

5. General Information

Accident Date	17/03/2018	Inspection Date	19/03/2018
Survey held at	COMFORTDELGRO ENGINEERING PTE LTD 59 LOYANG DRIVE SINGAPORE 508969		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.
--

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: MSIG Insurance (Singapore) Pte. Ltd.
4 Shenton Way
#21-01 SGX Centre 2
Singapore 068807

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Christina Wong

Date: 23 Mar 2018

Preliminary Advice

Insured Vehicle No : FBG4497M

TP Vehicle No : SHA3157L

Make : HYUNDAI I40

Date of Inspection : 20/03/2018

Inspection At : COMFORTDELGRO ENGINEERING PTE LTD (LOYANG)
59 LOYANG DRIVE
SINGAPORE 508969

Accident Date : 17/03/2018

Assignment Date : 19/03/2018

Est. Duration of Repair : 5.00

Point of Impact / General Description of Damages

The vehicle sustained impact / damages rear o/s portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	3,415.20
Revised Amount	:S\$	3,069.60
Check Items (Estimated)	:S\$	25.60
Total	:S\$	3,095.20

Lump Sum Repair :S\$

Total Loss Consideration

New for Old Value	:S\$
Pre-Accident Value	:S\$
COE / PARF Rebate	:S\$
Salvage Value	:S\$
Margin for Repair	:S\$

Remarks

() The vehicle is economical/not economical for repair.

(X) The above survey was conducted on a 'without prejudice' basis.

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	19/03/2018 08:46
Date Of Accident	17/03/2018 13:00
Exact Location Of Accident	EDGEDALE PLAINS X SLIP RD TWDS PUNGGOL DRIVE
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SHA3157L
Insured/Policyholder	
Name Of Registered Owner	COMFORT TRANSPORTATION PTE LTD
Co Reg No	199303821R
Email Address	FLEETSAFETY@CDGTAXI.COM.SG
Mobile Phone No	
Alternative Phone No	OFFICE-65508768

Vehicle Particulars

Manufacturer	HYUNDAI
Model	I40
Exact Purpose for which vehicle was being used at time of accident	
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	TAXI

Insurance Company

Name of Insurance Company	MS FIRST CAPITAL INSURANCE LTD
Type Of Coverage	THIRD PARTY FIRE AND/OR THEFT
Fleet Policy	YES
Policy Number	D-18088936MFSH
Cover Note Number	

Driver

Name of Driver	YUSOFF B YAHYA
NRIC No	S0211651J
Date Of Birth	21/02/1953
Occupation	OUTDOOR
Date Of Driving Pass	08/03/1977
Driving Experience	41 YEARS AND 0 MONTHS
Gender	MALE
Mobile Number	
Fax Number	
Contact Number	
Email Address	NOEMAIL

Address	BLK 139 BEDOK RESERVOIR ROAD #09-1497
Postcode	470139
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OTHER - TAXI DRIVER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	COLLISION - HEAD TO REAR
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles involved in the accident	
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

PLS REFER TO ATTACHED

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	YES
Remarks/ Reasons:	-
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	FBG4497M
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	MOTORCYCLE
Name of Driver	ERFAN RAJIWATE
NRIC/Passport Number	
Contact Number	91463215
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	FRT
No. Of Passenger (Including Driver)	

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodging of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.

COMFORT TRANSPORTATION PTE LTD
CO. REG. NO. 199303821R

Policyholder's Signature
Date & Time:


Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

GIA/IMAC SketchPlanForm_V3



SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

ON 17 March 2018 @ 2:00 pm I

veh-A was along Edgeclate plain x

turning of Punggol drive. I veh A

turn left to Punggol drive. I veh A

Slow down and stop. Suddenly veh-B

from Rear hit veh-A. at the point of

accident veh-A no passenger.

DECLARATION

I/We declare the foregoing particulars are true in every respect.

COMFORT TRANSPORTATION PTE LTD
CO REG. NO. 199303821R

Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

SIAMAC SketchPlanForm_V3

COMFORTDELGRO ENGINEERING PTE LTD

REPAIR ESTIMATE

Date: 19.03.2018

Time: 10:30:56

Page: 4

MS14-CP/P)

TS

COMPANY : THIRD PARTY'S CLAIMS (CAS)
 CUSTOMER: 7010045
 ADDRESS : COMFORT TRANSPORTATION PTE LTD
 383 SIN MING DRIVE
 SINGAPORE SINGAPORE 575717
 65508755

JOB NO : 305126146
 REGN NO : SHA3157L
 MILEAGE : 0000000000
 MAKE : HYUNDAI
 MODEL : I-40
 DATE OF REGN : 11.01.2017
 DATE/TIME IN : 18.03.2018 08:50
 ACCIDENT DATE : 17.03.2018

1035

JOB / PARTS DESCRIPTION

QTY IND UNIT-PRICE DISC% AMOUNT

PART REQUISITION

0001	04-01-0103-0579-G	REAR BUMPER	DE ✓	1	603.60	20.00	482.88	✓
0002	04-01-0103-0738-G	REAR BUMPER UNDER COVER	SEA ✓	1	225.00	20.00	180.00	✓
0003	04-01-0103-0784-G	BOOTLID GARNISH	SEA ✓	1	398.00	20.00	318.40	✓
0004	04-01-0103-0787-G	BOOTLID EMBLEM-I40	SEA ✓	1	41.00	20.00	32.80	✓
0005	04-01-0103-0786-G	BOOTLID EMBLEM-CRDI	SEA ✓	1	41.00	20.00	32.80	✓
0006	04-01-0101-0111-G	REAR BUMPER CLIPS	SEA ✓	10 L	22.00	20.00	17.60	✓
0007	04-01-0103-0783-G	REAR BUMPER SIDE BRKT RH	SEA ✓	1	49.00	20.00	39.20	✓
0008	04-01-0103-0852-G	REAR BUMPER REFLECTOR RH	? ✓	1	32.00	20.00	25.60	✓ nn
0009	04-01-0103-0585-A	TAILLAMP RH	SEA ✓	1	565.60	20.00	452.48	✓
0010	04-01-0103-0583-G	BOOTLID LAMP RH	SEA ✓	1	556.80	20.00	445.44	✓
0011	04-01-0103-0785-G	BOOTLID CHROME MOULDING	SEA ✓	1	85.00	20.00	68.00	✓

SUB-TOTAL : 2,095.20

JOB NATURE

MS14 - CP/P

TS

COMPANY : THIRD PARTY'S CLAIMS (CAS)
 CUSTOMER: 7010045
 ADDRESS : COMFORT TRANSPORTATION PTE LTD
 383 SIN MING DRIVE
 SINGAPORE SINGAPORE 575717
 65508755

JOB NO : 305126146
 REGN NO : SHA3157L
 MILEAGE : 0000000000
 MAKE : HYUNDAI
 MODEL : I-40
 DATE OF REGN : 11.01.2017
 DATE/TIME IN : 18.03.2018 08:50
 ACCIDENT DATE : 17.03.2018

JOB / PARTS DESCRIPTION

QTY IND UNIT-PRICE DISC% AMOUNT

0000 L PANEL BEATING- Rear Fender RH
 0001 23-502 SPRAYPAINT ON AFFECTED AREA
 0002 17-01 CHECK ALL LIGHTING
 0003 20-00 TUFF COAT ON AFFECTED PARTS.
 0004 L R/I UPHOLSTERY ETC

~~560.00~~ 400 /
~~600.00~~ 540 /
 40.00 /
~~40.00~~ 20 /
~~80.00~~ 40 /

SUB-TOTAL : 1,320.00

TOTAL : 3,415.20

AUTHORISED : YES / NO

MVA NAME & SIGNATURE
 DATE :

SURVEYOR NAME & SIGNATURE
 DATE :

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature:
 Date:

Rasul
 Hp 90060068
 5 days
 P/P
 20/03/18 P1215
 Resurvey by paint

23/3/18

COMFORTDELGRO ENGINEERING

Our Job Ref No : 305126146

Date : 26/03/18

ComfortDelGro Engineering Pte Ltd
59 Loyang Drive Singapore 508969
Fax: 6546 8156

FINALIZATION FORM

To : LKK

Fax :

Attn : RASUL

Vehicle Reg No. : SHA3157L

Date of Accident : 17-Mar-18

The survey and estimates of the repairs of the above-mentioned vehicle are as follows:-

1. The repair job shall bill to: MSIG — FBG4497M
2. The finalized amount shall be:
 - (a) Spare Parts after List discount \$2,069.60
 - (b) Labour Charges \$1,040.00
 - Total for Part-By-Part Repair Cost \$3,109.60**
 - (c) Lumpsum Repair (if applicable)
Total for Lumpsum repair cost after Less: 20%
Final Lumpsum Repair cost

3. Estimated normal period for repairs: 5 working days.

4. We shall treat the above amount as Correct and Confirmed if there is no reply from you within 7 working days

5. Thank you for your assistance.

We confirm the estimates and finalized amount

Signature : 

Name : LIM T S

Tel : 62148398

Fax : 65468156

Signature : _____

Name : RASUL

Date : _____

For Official Use Only

Item	Amount	Document Attached Yes or No	Confirm By (Signature)	Remarks
1. Rental Rate P/Day		YES		
2. Loss of Income Paid				
3. Survey Fees	-----			
4. LTA Search Fee				
5. Medical Fees (on behalf of driver, if applicable)				
6. Overrun				

Remarks:

COMFORTDELGRO ENGINEERING PTE LTD

REPAIR ESTIMATE

Date: 24.03.2018

Time: 10:28:35

Page: 1

COMPANY: THIRD PARTY'S CLAIMS (CAS)
CUSTOMER: 7010045
ADDRESS: COMFORT TRANSPORTATION PTE LTD
383 SIN MING DRIVE
SINGAPORE SINGAPORE 575717
65508755

JOB NO : 305126146
REGN NO : SHA3157L
MILEAGE : 0000000000
MAKE : HYUNDAI
MODEL : I-40
DATE OF REGN : 11.01.2017
DATE/TIME IN : 18.03.2018 08:50
ACCIDENT DATE : 17.03.2018

JOB / PARTS DESCRIPTION

QTY IND UNIT-PRICE DISC% AMOUNT

PART REQUISITION

0001	04-01-0103-0579-G	REAR BUMPER	1	603.60	20.00	482.88
0002	04-01-0103-0738-G	REAR BUMPER UNDER COVER	1	225.00	20.00	180.00
0003	04-01-0103-0784-G	BOOTLID GARNISH	1	398.00	20.00	318.40
0004	04-01-0103-0787-G	BOOTLID EMBLEM-I40	1	41.00	20.00	32.80
0005	04-01-0103-0786-G	BOOTLID EMBLEM-CRDI	1	41.00	20.00	32.80
0006	04-01-0101-0111-G	REAR BUMPER CLIPS	10 L	22.00	20.00	17.60
0007	04-01-0103-0783-G	REAR BUMPER SIDE BRKT RH	1	49.00	20.00	39.20
0008	04-01-0103-0585-A	TAILLAMP RH	1	565.60	20.00	452.48
0009	04-01-0103-0583-G	BOOTLID LAMP RH	1	556.80	20.00	445.44
0010	04-01-0103-0785-G	BOOTLID CHROME MOULDING	1	85.00	20.00	68.00

SUB-TOTAL : 2,069.60

JOB NATURE

0000 L	PANEL BEATING- Rear Fender RH	400.00
--------	-------------------------------	--------

COMFORTDELGRO ENGINEERING PTE LTD

REPAIR ESTIMATE

Date: 24.03.2018

Time: 10:28:35


Page: 2

COMPANY: THIRD PARTY'S CLAIMS (CAS)
CUSTOMER: 7010045
ADDRESS: COMFORT TRANSPORTATION PTE LTD
383 SIN MING DRIVE
SINGAPORE SINGAPORE 575717
65508755

JOB NO : 305126146
REGN NO : SHA3157L
MILEAGE : 0000000000
MAKE : HYUNDAI
MODEL : I-40
DATE OF REGN : 11.01.2017
DATE/TIME IN : 18.03.2018 08:50
ACCIDENT DATE : 17.03.2018

JOB / PARTS DESCRIPTION		QTY	IND	UNIT-PRICE	DISC%	AMOUNT
0001 23-502	SPRAYPAINT ON AFFECTED AREA			540.00		
0002 17-01	CHECK ALL LIGHTING			40.00		
0003 20-00	TUFF COAT ON AFFECTED PARTS.			20.00		
0004 L	R/I UPHOLSTERY ETC			40.00		
SUB-TOTAL						: 1,040.00

TOTAL : 3,109.60


MVA NAME & SIGNATURE
DATE:

SURVEYOR NAME & SIGNATURE
DATE:

AUTHORISED : YES / NO




































...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	19 Mar 2018		19 Mar 2018 18:08 Edit Adj Rpt	S\$3,109.60 Edit Estimates	S\$3,109.60 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by insurer]									
Insured:	ERFAN HUSAIN RAJIWATE, ID: 57868631F								
Main Claimant:	COMFORT TRANSPORTATION PTE LTD, Co. Reg. No.: 199303821R								
Vehicle Reg. No.:	SHA3157L	Date of Loss:	17/03/2018 12:00 - :59 [14 Months and 6 Days From LTA Reg Date (Man Yr)]						
Claim Type:	TP / MSC/V/18-000412	Policy/Cover Note No.:	MSD/VMS/17-367237-CA (TP, Fire & Theft) Coverage: 21/07/2017 - 20/07/2018						
Vehicle Reg. No. (Insured):	FBG4497M	Policy No. (Claimant):							
		Excess:							
Repairer:	ComfortDelGro Engineering Pte Ltd (Loyang) 59 Loyang Drive, 508969 Loyang - Tel: 6214 8300								
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Christina Wong - 6643 1311]								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by MOHD RASUL] ... [Final Rpt due 18/04/2018]								
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
There are no mail for this case.									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*SHA3157L (MSC/V/18-000412)
[FBG4497M]
TP
COMFORT TRANSPORTATION PTE LTD
Mar 17 2018 12:00PM
[ERFAN HUSAIN RAJIWATE]
ComfortDelGro Engineering Pte Ltd

Upload Documents			Upload Photos		Compose New Letter		View		View in Browser	
Assessment Reports							1 per page		<input checked="" type="checkbox"/>	
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)					Thumbnail		Print	
1	23/03/18 11:40	Adjuster Immediate Advice					 Load HTM		<input checked="" type="checkbox"/>	
Photos/Images							3 per page		<input checked="" type="checkbox"/>	
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)					Thumbnail		Print	
1	09/04/18 11:26	General View					 Load JPG		<input checked="" type="checkbox"/>	
2	09/04/18 11:26	General View					 Load JPG		<input checked="" type="checkbox"/>	
3	09/04/18 11:26	General View					 Load JPG		<input checked="" type="checkbox"/>	
4	09/04/18 11:26	General View					 Load JPG		<input checked="" type="checkbox"/>	
5	09/04/18 11:26	General View					 Load JPG		<input checked="" type="checkbox"/>	
6	09/04/18 11:26	General View					 Load JPG		<input checked="" type="checkbox"/>	
7	09/04/18 11:26	General View					 Load JPG		<input checked="" type="checkbox"/>	
8	09/04/18 11:26	General View					 Load JPG		<input checked="" type="checkbox"/>	
9	09/04/18 11:26	General View					 Load JPG		<input checked="" type="checkbox"/>	
10	09/04/18 11:26	General View					 Load JPG		<input checked="" type="checkbox"/>	
11	09/04/18 11:26	General View					 Load JPG		<input checked="" type="checkbox"/>	
12	09/04/18 11:26	General View					 Load JPG		<input checked="" type="checkbox"/>	
13	09/04/18 11:26	General View					 Load JPG		<input checked="" type="checkbox"/>	
14	09/04/18 11:26	General View					 Load JPG		<input checked="" type="checkbox"/>	
15	09/04/18 11:26	General View					 Load JPG		<input checked="" type="checkbox"/>	
16	09/04/18 11:26	General View					 Load JPG		<input checked="" type="checkbox"/>	
17	09/04/18 11:26	General View					 Load JPG		<input checked="" type="checkbox"/>	
18	09/04/18 11:26	General View					 Load JPG		<input checked="" type="checkbox"/>	
19	09/04/18 11:26	General View					 Load JPG		<input checked="" type="checkbox"/>	
20	09/04/18 11:26	General View					 Load JPG		<input checked="" type="checkbox"/>	
21	09/04/18 11:26	General View					 Load JPG		<input checked="" type="checkbox"/>	
22	09/04/18 11:26	General View					 Load JPG		<input checked="" type="checkbox"/>	
23	09/04/18 11:26	General View					 Load JPG		<input checked="" type="checkbox"/>	
24	09/04/18 11:26	General View					 Load JPG		<input checked="" type="checkbox"/>	
25	09/04/18 11:26	General View					 Load JPG		<input checked="" type="checkbox"/>	
26	09/04/18 11:26	General View					 Load JPG		<input checked="" type="checkbox"/>	
27	09/04/18 11:26	General View					 Load JPG		<input checked="" type="checkbox"/>	
28	09/04/18 11:26	General View					 Load JPG		<input checked="" type="checkbox"/>	
29	09/04/18 11:26	General View					 Load JPG		<input checked="" type="checkbox"/>	
30	09/04/18 11:26	General View					 Load JPG		<input checked="" type="checkbox"/>	
31	09/04/18 11:26	General View					 Load JPG		<input checked="" type="checkbox"/>	
32	09/04/18 11:26	General View					 Load JPG		<input checked="" type="checkbox"/>	
33	09/04/18 11:26	General View					 Load JPG		<input checked="" type="checkbox"/>	
34	09/04/18 11:26	General View					 Load JPG		<input checked="" type="checkbox"/>	

Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No.	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
				<input checked="" type="checkbox"/>
35	09/04/18 11:26	General View	 Load JPG	<input checked="" type="checkbox"/>
36	09/04/18 11:28	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
37	09/04/18 11:28	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
38	09/04/18 11:28	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
39	09/04/18 11:28	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
40	09/04/18 11:28	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
41	09/04/18 11:28	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
Documentation			1 per page	<input checked="" type="checkbox"/>
No.	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
1	19/03/18 11:48	SHA3157L GIA Rpt	 Load PDF	
2	19/03/18 11:49	FBG4497M GIA Rpt	 Load PDF	
3	19/03/18 11:51	PRI	 Load PDF	
4	19/03/18 11:51	Estimate	 Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ) <div style="border: 1px solid black; height: 40px; margin-top: 5px;"></div>			
Show Remarks To: <input type="checkbox"/> Handling Insurer <small>Note: Remarks are private unless you show it to other parties.</small>			

LKK Auto Consultants Pte Ltd

(Co.Reg No. 199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/MSG18005252/R1RD3Q2

Date: 11/04/2018

REFERENCE

Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd.	Policy No:	MSD/VMS/17-367237-CA
Claimant Vehicle No :	SHA3157L	Insured Vehicle No :	FBG4497M
Date of Loss:	17/03/2018	Nature of Claim:	TP
		Claim No:	MSC/V/18-000412

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SHA3157L		
Make & Model:	HYUNDAI I40, 1.7 D CRDI F/L ABS AIRBAG 4DR (A)	Engine No:	D4FDGU705751
Reg. Date:	11/01/2017 (Man. Year: 2016)	Chassis No:	KMHLB41UMHU098224
Colour:	Blue	Odometer:	152828 km
Engine Capacity:	1685 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	205/60 R16	Rear Tyre Size:	205/60 R16
Front Left Side:	Hankook 5 mm	Rear Left Side:	Hankook 5 mm
Front Right Side:	Hankook 5 mm	Rear Right Side:	Hankook 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	2,095.20	2,069.60	25.60	1.22
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,320.00	1,040.00	280.00	21.21
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	3,415.20	3,109.60	305.60	8.95
+ GST 7.00/7.00% (S\$)	239.06	217.67	21.39	8.95
Nett Amount (S\$)	3,654.26	3,327.27	326.99	8.95

INSPECTION

Date of Assignment:	19/03/2018		
Date Inspected:	20/03/2018	Inspected At:	ComfortDelGro Engineering Pte Ltd (Loyang) 59 Loyang Drive Singapore 508969
Estimated Period of Repair:	5.0 days		

Adjuster: MOHD RASUL**Manager:** Janice Lee Si Hua

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 10 Apr 2018)
Parts:	143	HYUNDAI I40 1.7 D CRDI F/L ABS AIRBAG 4DR (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SHA3157L)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Deformed	603.60 FL	*603.60 FL
2	1		*REAR BUMPER UNDER COVER	Scratched	225.00 FL	*225.00 FL
3	1		*BOOTLID GARNISH	Scratched	398.00 FL	*398.00 FL
4	1		*BOOTLID EMBLEM -I40	Necessary	41.00 FL	*41.00 FL
5	1		*BOOTLID EMBLEM -CRDI	Necessary	41.00 FL	*41.00 FL
6	10		*REAR BUMPER CLIPS	Necessary	22.00 FL	*22.00 FL
7	1		*REAR BUMPER SIDE BRKT RH	Necessary	49.00 FL	*49.00 FL
8	1		*REAR BUMPER REFLECTOR RH	Not Necessary	32.00 FL	*- FL
9	1		*TAILLAMP RH	Cracked	565.60 FL	*565.60 FL
10	1		*BOOTLID LAMP RH	Cracked	556.80 FL	*556.80 FL
11	1		*BOOTLID CHROME MOULDING	Necessary	85.00 FL	*85.00 FL

F=Franchise part. L=ListItemDisc.

Sub Total (\$\$)	2,619.00	2,587.00
- List Item Discount on L Items 20.00/20.00% (\$\$)	523.80	517.40
Total Parts (\$\$)	2,095.20	2,069.60

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	PANEL BEATING -REAR FENDER RH	New	560.00	400.00
2	SPRAYPAINT ON AFFECTED AREA	New	600.00	540.00
3	CHECK ALL LIGHTING	New	40.00	40.00
4	TUFF COAT ON AFFECTED PARTS	New	40.00	20.00
5	R/I UPHOLSTERY ETC	New	80.00	40.00
Gross Labour Cost (S\$)			1,320.00	1,040.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >