

5/20/18

INS. CASE OWNER:

Shenim

CC 4/1111800

5258, V mb39

LKK:

IDAC:

Surveyor:

Marion

DOI:

ASSIGNMENT

26/7/18

Date / Time:

21/7/18

Registered in Merimen:

21/7/18

Pre-assign / CCU / FTE



Insured Vehicle No.:

SHA 3352P

Name of Insured:

CPL

Insured Tel No.:

HP:

Excess Sec II :SS

D.O.A.:

20/7/18

Is driver the owner?

( YES / NO )

Nature of Accident:

DELTA

If NO, Driver Name / Age:

TAN PECK HONG A TAN HONG

OI GIA REPORT: YES / NO

TP GIA REPORT: YES / NO

Driver Tel No.:

(V/L: YES / NO) 76E

Insured Liability: %

Final ? Yes / No

GBF 96390



INSRS:

WSP:

Tel:

Liability:

RMKS:

Tan Lim



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:

Date/ Time

21/7/18  
Buran

GBF 96390 - 4  
SHA 3352P - 26/7/2018 9:49/13:00/3:00 - 4/18/18

RECEIVED 24 APR 2018

RECEIVED 21 MAY 2018

STAGE

DATE / PIC

Non-Reporting ltr (1st):

Non-Reporting ltr (2nd):

Non-Reporting ltr (Final):

Notification ltr (if non-pickup):

Call OI:

After call ltr to OI:

Documentation Check List: Handler Typist

Notification ltr (if non-pickup)

After call ltr to OI:

Authorisation To Act:

Release Voucher:

Final Repair Bill:

Car Rental Invoice:

Towing Invoice:

LTA / GIA :

Medical Bill:

PIR:

Mandate/Reject Instruction:

LOD

Payment Breakdown Form:

Post-Repair Photos:

Others:

PRELIMINARY ADVICE

Date/Time:

Sent By:

FINALIZATION

Date/Time:

Confirm with:

Confirm by:

Repair Cost:

SS

( days)

Reduction:

%

Email

Call

FINAL SETTLEMENT

Date/Time:

Confirm with:

Johnson

Email

Call

Final Liability:

%

100

(Agreed / Assessed) BOLA S/N No. : 15

If NO or B 28, Ass. Lia :

Repair Cost:

SS

1765.5

Loss of Rental (LOR):

SS

( days)

Loss of Use (LOU):

SS

600 (5/50 x 4 days)

Loss of Income (LOI):

SS

(S - x - days)

LOR only ☐ LOU only ☒ LOR + LOU ☐ LOR + LOI ☐ [Tick only one]

GIA/LTA Search

SS

Medical:

SS

Disbursement:

SS

(e.g. Tow/ Independent )

Legal Cost

SS

Total:

SS

2765.50

Global Sum SS:

FINAL PAYMENT

Date/Time:

Confirm with:

Email

Call

Payee 1:

SS

2365.50

Name 1:

TAN LIM MOTOR PTE LTD

Payee 2: (Strike if N.A.)

SS

Name 2:

Payee 3: (Strike if N.A.)

SS

Name 3:

1) Claim status: Normal/Reject/Private Se  
2) Report Format: 7D  
3) Survey fee: 8350

21/5/18





# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
INDIA INTERNATIONAL INSURANCE PL		Ref : CC4/III18005258/mb3		
64 CECIL STREET #05-02 IOB BUILDING SINGAPORE 049711		Date : 21-03-2018		
		Code : III2		
<b>1. Policy Particulars :- THIRD PARTY CLAIM</b>				
Insured Veh.	SHA 3352P	Veh. Inspected	GBF 9439D	
Policy No.		Coverage (\$)	0.00	
Claim No.		Excess (\$)	0.00	
Assign From		Assign Date	21/03/2018	
<b>2. Vehicle Particulars &amp; Condition</b>				
Make & Model		c.c	0	
Engine No.	HIDDEN	Year of Reg.		
Chassis No.		Colour		
Odometer	-	Steering		
Brakes		Modification		
General				
<b>3. Conditions of Tyres</b>				
	Size	Make	Balance	
R/H Front Tyre			mm	
L/H Front Tyre			mm	
R/H Rear Tyre			mm	
L/H Rear Tyre			mm	
<b>4. Description of Damages</b>				
<b>5. General Information</b>				
Accident Date	20/03/2018	Inspection Date		
Survey held at	TAN LIM MOTOR PTE LTD 51 DEFU LANE 10 SINGAPORE 539216			
<b>5a. Remarks</b>				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				



陳林摩哆私人有限公司  
TAN LIM MOTOR PTE LTD

TP INSURER: India International Insurance Pte Ltd (HQ)  
Comfortdelgo Transportation Pte Ltd  
Singapore

Claimant Insurer: NTUC Income Insurance Co-operative Ltd

*Not Allowed*  
*2/5/18*  
*Hday*  
*26/3/18*  
*Thy... Office*

PARTICULARS OF CLAIM

Claim Type:	THIRD PARTY	Ref. No:	TP015032018
Policy No:		Date of Loss:	20/03/2018
Vehicle Reg. No.:	GBF9439D	Driveable?	YES
Pa At Fault:	UNKNOWN		
Driver (TP):	ZHAO JIANG		

Make/Model:	ISUZU NHR85AUE4AA, 3.0 D (M)	Vehicle Reg. Date:	26/04/2017
Vehicle Colour:	BLUE	Gen Condition:	GOOD
Engine No:	4JJ12X3910	Chassis No:	JAANHR85EH7100049
Odometer:	0 KM		
Paint Type:			
List Item Discount:	10.00 %		
Total Loss?	NO		
Est. Duration of Repair 3 (day)			

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

*LKK*  
*26/03/18*  
*1120h*

Description of Accident/Loss

ON 20/03/208 AT ABOUT 1100HRS, I STOPPED MY VEHICLE (A: GBF9439D) ON THE CENTRE LANE ALONG JALAN BUKIT MERAH HEADING TOWARDS CITY DIRECTION DUE TO TRAFFIC LIGHT WAS RED. SUDDENLY I FELT AN IMPACT FROM MY VEHICLE'S RIGHT REAR PORTION, I IMMEDIATELY VIEW MY LEFT SIDE MIRROR AND RECOVERED THAT VEHICLE (B: SHA3352P) WHICH WAS TRAVELLING BEHIND OF MY VEHICLE, OVERTOOK AND HIT ONTO MY VEHICLE'S RIGHT REAR PORTION. NOBODY WAS INJURED IN THIS ACCIDENT,

VEHICLE A (GBF9439D) - NO PASSENGER ON BOARD.

VEHICLE B (SHA3352P) - 1 FEMALE ADULT PASSENGER ON BOARD.

Present Location: TAN LIM MOTOR PTE LTD (DEFU)

COST OF CLAIMS	Amount
Parts	0.00
Miscellaneous Items	10.00
Labour	3,200.00
Paintwork Labour	0.00
Towing	0.00
Gross Total (S\$)	3,210.00

+ GST 7.00% (S\$)	224.70
Nett Amount (S\$)	<b>3,434.70</b>

This claim is handled by: LAM WEI SHONG

*Generated using Merimen e-Claims Internet Estimation & Adjusting System*

REPAIR DETAILS	
Reference	
Part Source:	(Last Synchronised: 20 Mar 2018)
Parts:	N/A ISUZU NHR85AUE4AA 3.0 D (M) (Model not available in database)
Labour:	Repairer's (Price-denominated Standard List)
Print Code:	Tan Lim Motor Pte Ltd/GBF9439D/20/03/2018 19:09
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.

Estimates on Parts

There are no new parts selected.

Tan Lim Motor Pte Ltd/GBF9439D/20/03/2018 19:09. Not valid without Reference section. Generated using Merimen e-Claims IEAS
--

Estimates on Miscellaneous Items

No	Qty	Particulars	Amount
<u>Miscellaneous Items</u>			
1	1	OD/TP Case (Insurer)	<i>ner</i> 10.00
Sub Total (S\$)			10.00

Estimates on Labour

No	Particulars	Lab.Type	Amount
<u>Labour Items</u>			
1	To make good repair to o/s rear end aluminum box and supply 1pc of track-alumium.	<i>cm</i> New <i>1000</i>	1,500.00
2	To supply and redo graphic display sticker and corporate logo.	<i>ner</i> New <i>680</i>	1,000.00
3	Putty and spray painting of the affected portion.	New <i>400</i>	700.00
Gross Labour Cost (S\$)			3,200.00

Tan Lim Motor Pte Ltd/GBF9439D/20/03/2018 19:09. Not valid without Reference section.  
Generated using Merimen e-Claims IEAS  
< END OF ESTIMATES >

51 Defu Lane 10 Singapore 539216  
Tel : 6858 5151 (24 hours) Fax : 6858 0877  
email@tlmotor.com.sg www.tlmotor.com.sg  
Co. Reg. No.: 199503965M GST Reg. No. : M2-8922054-2

**Enquire PARF/COE Rebate for Registered Vehicle****Vehicle Owner Particulars**

Owner ID Type: Company

Owner ID: 6791K

**Vehicle Details**

Vehicle No.: GBF9439D

Vehicle to be Exported: No

Intended De-registration Date: 26 Mar 2018

Vehicle Make: ISUZU

Vehicle Model: NHR85AUE4AA

Primary Colour: White

Manufacturing Year: 2016

Engine No.: 4JJ12X3910

Chassis No.: JAANHR85EH7100049

Maximum Power Output: -

Open Market Value: \$24,989.00

Original Registration Date: 26 Apr 2017

First Registration Date: 26 Apr 2017

Transfer Count: 1

Actual ARF Paid: \$1,250.00

**Intended PARF Rebate Details**

PARF Eligibility: No

PARF Eligibility Expiry Date: -

PARF Rebate Amount: \$0.00

**Intended COE Rebate Details**

COE Expiry Date: 25 Apr 2027

COE Category: C - Goods Vehicle &amp; Bus

COE Period(Years): 10

QP Paid: \$47,036.00

COE Rebate Amount: \$42,722.00

**Total Rebate Amount: \$42,722.00**

The information contained herein is correct as at 26 Mar 2018

OK



**Enquire PARF/COE Rebate for Registered Vehicle****Vehicle Owner Particulars**

Owner ID Type: Company  
Owner ID: 6791K

**Vehicle Details**

Vehicle No.: GBF9439D  
Vehicle to be Exported: Yes  
Intended De-registration Date: 20 Mar 2018  
Vehicle Make: ISUZU  
Vehicle Model: NHR85AUE4AA  
Primary Colour: White  
Manufacturing Year: 2016  
Engine No.: 4JJ12X3910  
Chassis No.: JAANHR85EH7100049  
Maximum Power Output: -  
Open Market Value: \$24,989.00  
Original Registration Date: 26 Apr 2017  
First Registration Date: 26 Apr 2017  
Transfer Count: 1  
Actual ARF Paid: \$1,250.00

**Intended PARF Rebate Details**

PARF Eligibility: No  
PARF Eligibility Expiry Date: -  
PARF Rebate Amount: \$0.00

**Intended COE Rebate Details**

COE Expiry Date: 25 Apr 2027  
COE Category: C - Goods Vehicle & Bus  
COE Period(Years): 10  
QP Paid: \$47,036.00  
COE Rebate Amount: \$37,628.00  
**Total Rebate Amount: \$37,628.00**

The information contained herein is correct as at 20 Mar 2018

OK



陳林摩哆私人有限公司  
TAN LIM MOTOR PTE LTD

TP INSURER: India International Insurance Pte Ltd (HQ)  
Comfortdelgo Transportation Pte Ltd

Singapore

Claimant Insurer: NTUC Income Insurance Co-operative Ltd

#### PARTICULARS OF CLAIM

Claim Type: THIRD PARTY  
Policy No:  
Vehicle Reg. No.: GBF9439D  
Pa At Fault: UNKNOWN  
Driver (TP): ZHAO JIANG

Ref. No: TP015032018  
Date of Loss: 20/03/2018  
Driveable? YES

Make/Model: ISUZU NHR85AUE4AA 3.0 D (M)

Vehicle Reg. Date: 26/04/2017

Vehicle Colour: BLUE  
Engine No: 4JJ12X3910  
Odometer: 0 KM

Gen Condition: GOOD  
Chassis No: JAANHR85EH7100049

Paint Type:  
List Item Discount: 10.00 %  
Total Loss? NO  
Est. Duration of Repair 3 (day)

LKK Auto Consultants hence notify the Repairer of the following:  
• To resurvey before spray painting  
• To display damaged parts during resurvey  
• Parts prices are subject to confirmation  
• Third party survey is on a "Without Prejudice" basis  
• No illegal modifications is allowed  
• Supplementary items must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Description of Accident/Loss

ON 20/03/2018 AT ABOUT 1100HRS, I STOPPED MY VEHICLE (A: GBF9439D) ON THE CENTRE LANE ALONG JALAN BUKIT MERAH HEADING TOWARDS CITY DIRECTION DUE TO TRAFFIC LIGHT WAS RED. SUDDENLY I FELT AN IMPACT FROM MY VEHICLE'S RIGHT REAR PORTION. I IMMEDIATELY VIEW MY LEFT SIDE MIRROR AND RECOVERED THAT VEHICLE (B: SHA3352P) WHICH WAS TRAVELLING BEHIND OF MY VEHICLE. OVERTOOK AND HIT ONTO MY VEHICLE'S RIGHT REAR PORTION. NOBODY WAS INJURED IN THIS ACCIDENT.

VEHICLE A (GBF9439D) - NO PASSENGER ON BOARD

VEHICLE B (SHA3352P) - 1 FEMALE ADULT PASSENGER ON BOARD.  
Present Location: TAN LIM MOTOR PTE LTD (DEFU)

#### COST OF CLAIMS

	Amount
Parts	0.00
Miscellaneous Items	10.00
Labour	3,200.00
Paintwork Labour	0.00
Towing	0.00
<b>Gross Total (S\$)</b>	<b>3,210.00</b>

+ GST 7.00% (S\$)	224.70
Nett Amount (S\$)	<b>3,434.70</b>

This claim is handled by: LAM WEI SHONG

*Generated using Merimen e-Claims Internet Estimation & Adjusting System*

**REPAIR DETAILS****Reference****Part Source:** (Last Synchronised: 20 Mar 2018)**Parts:** N/A ISUZU NHR85AUE4AA 3.0 D (M) (Model not available in database)**Labour:** Repairer's (Price-denominated Standard List)**Print Code:** Tan Lim Motor Pte Ltd/GBF9439D/20/03/2018 19:09**Validity:** These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page**Further Info:** Items/values not in reference catalogue are prefixed with an asterisk \***Estimates on Parts****There are no new parts selected.**

Tan Lim Motor Pte Ltd/GBF9439D/20/03/2018 19:09. Not valid without Reference section.  
Generated using Merimen e-Claims IEAS

## Estimates on Miscellaneous Items

No	Qty	Particulars	Amount
<u>Miscellaneous Items</u>			
1	1	OD/TP Case (Insurer)	10.00
Sub Total (S\$)			10.00

## Estimates on Labour

No	Particulars	Lab.Type	Amount
<u>Labour Items</u>			
1	To make good repair to o/s rear end aluminum box and supply 1pc of track-aluminium.	CM New 1000	1,500.00
2	To supply and redo graphic display sticker and corporate logo.	RM New 680	1,000.00
3	Putty and spray painting of the affected portion.	New 400	700.00
Gross Labour Cost (S\$)			3,200.00

Tan Lim Motor Pte Ltd/GBF9439D/20/03/2018 19:09 Not valid without Reference section.

Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >

51 Defu Lane 10 Singapore 539216  
 Tel : 6858 5151 (24 hours) Fax : 6858 0877  
 email@tlmotor.com.sg www.tlmotor.com.sg  
 Co. Reg. No.: 199503965M GST Reg. No. : M2-8922054-2

## Print Received Message

This mail is associated with :

**GBF9439D (MCT18030616)**

**[SHA3352P]**

TP

SEMGAS SUPPLY PTE LTD

Mar 20 2018 11:00AM

[Comfortdelgo Transportation Pte Ltd]

Tan Lim Motor Pte Ltd

**From** India International Insurance Pte Ltd (HQ) (III\_SG), sent on 09/05/2018 08:43 AM.  
**To** LKK\_HQ  
**Subject** Alert - Adj Mandate Approved (S\$2365.50) - GBF9439D - Claim Handler: Sherini Pillai

Approved:2365.50.



陳林摩哆私人有限公司  
**TAN LIM MOTOR PTE LTD**

Address: 51 Defu Lane 10 Singapore 539216

Tel: 6858 5151 Fax: 6858 0877

Our Ref TP015.03.2018

Date 12.04.18

Your Ref SHA 3352P

**WITHOUT PREJUDICE**

Claims Department - Executive in charge \_\_\_\_\_

India International Insurance Pte Ltd

Dear Sir/Madam,

**ACCIDENT INVOLVING** GBF9439D / SHA3352P on 20.03.18

Refer to the above accident and please acknowledge receipt of this letter within 14 days.

It appears that the accident was caused by your insured. Enclosed documents to substantiate our client's property damaged claim as our client had authorized us to quantify, to act and to reach settlement within 6 weeks on their behalf: -

- |  |   |
|--|---|
| <input type="checkbox"/> Original survey report/ _____ copies of photographs _____ |   |
| <input checked="" type="checkbox"/> Original Tax-invoice number <u>TP0418/004</u>  | <input type="checkbox"/> Original rental invoice number _____ |
| <input checked="" type="checkbox"/> SAS / AS & IS / police report                  | <input type="checkbox"/> police result                        |
| <input checked="" type="checkbox"/> Certificate Of Insurance _____                 | <input type="checkbox"/> Vehicle search result                |
| <input checked="" type="checkbox"/> Authorization to act                           | <input checked="" type="checkbox"/> Driver's IC & DL          |

\*Survey under insurance instruction / Independent surveyor / No survey.

	<u>LKK</u>	
a)	Cost of repair (inclusive GST)	\$ <u>1765.50</u>
b)	Survey fees / Photographs as per request	\$ <u>-</u>
c)	Vehicle Search fees / GIA fees / Police Report fees / Reporting fees	\$ <u>-</u>
d)	Loss of hire / use / rental / earnings / rental fees <u>(4 days)</u>	\$ <u>600.00</u>
e)	Scene photographs	\$ <u>-</u>
f)	Administrative charges to negotiate settlement (Waive if 100% offer made within acknowledge timeframe)	\$ <u>-</u>
g)	_____	\$ _____
	<b>Total</b>	\$ <u>2,365.50</u> =====

\* Driver's injury and other losses exclude in this claim.

If you are agreeable to the above, please forward discharge voucher for our client's signature and payment issued directly to "Tan Lim Motor Pte Ltd" within 28 days.

Yours faithfully,

**Patricia Tan / Sam Low / Johnson Chua**

Email: [pt@tlimotor.com.sg](mailto:pt@tlimotor.com.sg) / [sam@tlimotor.com.sg](mailto:sam@tlimotor.com.sg) / [johnson.chua@tlimotor.com.sg](mailto:johnson.chua@tlimotor.com.sg)

## AUTHORIZATION TO ACT

TO : TAN LIM MOTOR PTE LTD

FROM : OWNER OF VEHICLE NUMBER GBF 9439D

ACCIDENT INVOLVING SHA 3352P

ALONG/AT Jalan Bukit merah ON 20/03/2018

I/We hereby authorize you to act on my/our behalf in pursuance of my/our claim for losses arising out of the above accident.

This letter serves as the 'AUTHORITY TO ACT'

I/We also hereby authorize all agreed settlement payment be made in favour to TAN LIM MOTOR PTE LTD.

Name Semgas Supply Pte Ltd

NRIC 70120 6791 K

Address 25 Genting Road Singapore 349482

Contact 6603 1796

Date 21/03/2018

Signature



Owner's / Hirer's signature / RTP  
(Company's stamp if applicable)

"The contents of this document apply to vehicle damages only. All personal injuries and damages arising therefrom are excluded from the ambit and application of this document."



## EXPRESS SETTLEMENT

### DISCHARGE VOUCHER III-Direct Settlement (PODS)

"The contents of this document apply to vehicle damages only. All personal injuries and damages arising therefrom are excluded from the ambit and application of this document."

India Ref: MCT18030616

Claimant Ref: TPB15032018 *16th 94390*

We/I, TAN LIM MOTOR PTE LTD ("the workshop") hereby confirm that we/I have reached an agreement with the appointed Surveyor of India International Insurance Pte Ltd LKK AUTO CONSULTANTS PTE LTD (name of Surveyor) with respect to the amount claimed for S\$ 1765.50 (repair cost), S\$ 600.00 (loss of use/rental), S\$ - (search fee), vehicle no. GBF 9439D that was damaged pursuant to the accident which occurred on 20/03/2018 (date) at JALAN BUKIT MERAH (location) involving vehicle no. SHA3352P (insured vehicle). This is pursuant to the inspection conducted on 26/03/2018 (date) at "the workshop".

We/I confirm that we/I are/am authorized by the owner SEMGAS SUPPLY PTE LTD ("the third party claimant") of vehicle no. GBF 9439D to make the claim as set out in the above paragraph and we/I have full authority to settle the matter on his/her behalf in a manner that we/I deem fit. We/I enclose herein the letter of authority given by "the third party claimant".

We/I further confirm that we/I will indemnify India International Insurance Pte Ltd for all damages, loss and/or expense that they will or have already incurred in the event that "the third party claimant" after the above said agreement lodges a further claim against the former for any loss and expenses suffered pertaining to cost of repairs and/or rental and/or loss of use pursuant to the damage to GBF 9439D (vehicle no.) as a result of the accident.

We/I confirm that the agreement reached above is in full and final settlement of all claims of "the third party claimant" pursuant to the accident and that further this settlement is reached on a without prejudice and without admission of liability basis.

This agreement is subject to the application of Singapore law and the Singapore Courts have exclusive jurisdiction over any dispute arising out of the same.

We/I authorize you to pay the total amount of S\$ 2365.50 to TAN LIM MOTOR PTE LTD

Dated this 16th day of MAY 20 18

#### CLAIMANT:

Signature:

*[Signature]*  
Signed by "the workshop" (with chop)

Name:

Johnson Chua

NRIC:

569177240

Address:

51 DEPU LANE 10

SINGAPORE 539 216

S'POREAN

Nationality:

Occupation:

Manager

#### WITNESS:

Signature:

*[Signature]*  
Signed by appointed Surveyor

Name:

LKK AUTO CONSULTANTS PTE LTD

NRIC:

199607198R

Address:

51 UBI AVENUE 1 #01-25

PAYA UBI INDUSTRIAL PARK (S) 408933

Nationality:

Occupation:



*LKS*



**TAX-INVOICE**  
**NUMBER: TP0418/004**

(Please quote our reference number TP015032018 for payment)

陳林摩哆私人有限公司  
**TAN LIM MOTOR PTE LTD**

Semgas Supply Pte Ltd

Date: 13/04/2018

Vehicle No: GBF9439D  
Model: ISUZU NHR85A

Description	Amount
To lump sum repair as recommended by surveyor.	\$1,650.00

Sub Total	\$1,650.00
Add 7% GST	\$115.50
Total	\$1,765.50

  
\_\_\_\_\_  
Tan Lim Motor Pte Ltd

## ...CLAIM SUBFOLDER...(Pending for Survey Report)

Direct Settlement



































## CLAIM SUBFOLDER TRACKING


Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	20 Mar 2018 <a href="#">Sendback Est</a>	20 Mar 2018 19:09 <b>\$53,210.00</b>	21 Mar 2018 08:29 <a href="#">Edit Adj Rpt</a>	<b>\$51,650.00</b> <a href="#">Edit Estimates</a>	<b>\$51,650.00</b> <a href="#">View Rpt</a>		<b>Pending for Survey Report</b> <a href="#">Cancel Case</a>

Main	Reference	Claim Details	Documents	Show All					
<b>CLAIM SUBFOLDER DETAILS</b>									
Insured:	<b>Comfortdelgo Transportation Pte Ltd</b> , Co. Reg. No.: 199303821R								
Main Claimant:	<b>SEMGAS SUPPLY PTE LTD</b> , Co. Reg. No.: A05791/2002K								
Vehicle Reg. No.:	<b>GBF9439D</b>	Date of Loss:	20/03/2018 11:00 - :59 [10 Months and 22 Days From LTA Reg Date (Man Yr)]						
Claim Type:	<b>TP / MCT18030616</b>	Policy/Cover Note No.:	MCOM0015						
Vehicle Reg. No. (Insured):	<b>SHA3352P</b>	Policy No. (Claimant):	5097795728						
		Excess:							
Repairer:	<b>Tan Lim Motor Pte Ltd (Defu)</b> 51 Defu Lane 10, 539216 Defu Lane - Tel: 6858 5151								
Handling Insurer:	<b>India International Insurance Pte Ltd (HQ)</b> - Tel: 63476100 ... [Handled by <b>Sherini Pillai</b> ]								
Claimant's Insurer:	<b>NTUC Income Insurance Co-operative Ltd (HQ)</b> - Tel:								
Adjuster:	<b>LKK Auto Consultants Pte Ltd (HQ)</b> - Tel: 6256-3561 ... [Handled by <b>MARCUS CHUA</b> ] ... [Final Rpt due 02/04/2018]								
<b>ASSOCIATED MAIL RECEIVED</b> <a href="#">View All</a> <a href="#">Compose Case Mail</a>									
<ul style="list-style-type: none"> <li>III_SG (09/05/2018): Alert - Adj Mandate Approved (\$2365.50) - GBF9439D - Claim Handler: Sherini Pil...</li> <li>III_SG (30/04/2018): Alert - Adj Mandate Approved (\$2165.50) - GBF9439D - Claim Handler: Sherini Pil...</li> <li>III_SG (05/04/2018): Alert - Adj Mandate Approved (\$50.00) - GBF9439D - Claim Handler: Sherini Pillai</li> </ul>									
<b>ALL ASSOCIATED TASKS</b> <a href="#">View All</a> <a href="#">Search Tasks</a> <a href="#">Create New Task</a> <a href="#">Complete</a>									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

## Claim Documents

GBF9439D (MCT18030616)  
[SHA3352P]  
TP  
SEMGAS SUPPLY PTE LTD  
Mar 20 2018 11:00AM  
[Comfortdelgo Transportation Pte Ltd]  
Tan Lim Motor Pte Ltd

<a href="#">Upload Documents</a> <a href="#">Upload Photos</a> <a href="#">Compose New Letter</a>			<b>View</b> <a href="#">View in Browser</a>	
<b>Assessment Reports</b>			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	Tan Lim Motor Pte Ltd (Defu)	Thumbnail	Print
1	20/03/18 19:09	<b>Repairer Estimates</b>	 Load HTML	<input type="checkbox"/>
<b>Photos/Images</b>			3 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	26/03/18 19:57	<b>Chassis Number</b>	 Load JPG	<input checked="" type="checkbox"/>
2	26/03/18 19:57	<b>Odometer Reading</b>	 Load JPG	<input checked="" type="checkbox"/>
3	26/03/18 19:57	<b>General View</b>	 Load JPG	<input checked="" type="checkbox"/>
4	26/03/18 19:57	<b>General View</b>	 Load JPG	<input checked="" type="checkbox"/>
5	26/03/18 19:57	<b>General View</b>	 Load JPG	<input checked="" type="checkbox"/>
6	26/03/18 19:57	<b>General View</b>	 Load JPG	<input checked="" type="checkbox"/>
7	26/03/18 19:57	<b>General View</b>	 Load JPG	<input checked="" type="checkbox"/>
8	26/03/18 19:57	<b>General View</b>	 Load JPG	<input checked="" type="checkbox"/>
9	26/03/18 19:57	<b>General View</b>	 Load JPG	<input checked="" type="checkbox"/>
10	26/03/18 19:57	<b>General View</b>	 Load JPG	<input checked="" type="checkbox"/>
11	26/03/18 19:57	<b>General View</b>	 Load JPG	<input checked="" type="checkbox"/>
12	26/03/18 19:57	<b>General View</b>	 Load JPG	<input checked="" type="checkbox"/>
13	26/03/18 19:57	<b>General View</b>	 Load JPG	<input checked="" type="checkbox"/>
14	26/03/18 19:57	<b>General View</b>	 Load JPG	<input checked="" type="checkbox"/>
15	26/03/18 19:57	<b>General View</b>	 Load JPG	<input checked="" type="checkbox"/>
16	26/03/18 19:57	<b>General View</b>	 Load JPG	<input checked="" type="checkbox"/>
17	26/03/18 19:57	<b>General View</b>	 Load JPG	<input checked="" type="checkbox"/>
18	26/03/18 19:57	<b>General View</b>	 Load JPG	<input checked="" type="checkbox"/>
19	26/03/18 19:57	<b>General View</b>	 Load JPG	<input checked="" type="checkbox"/>
20	26/03/18 19:57	<b>General View</b>	 Load JPG	<input checked="" type="checkbox"/>
21	26/03/18 19:57	<b>General View</b>	 Load JPG	<input checked="" type="checkbox"/>
22	26/03/18 19:57	<b>General View</b>	 Load JPG	<input checked="" type="checkbox"/>
23	26/03/18 19:57	<b>General View</b>	 Load JPG	<input checked="" type="checkbox"/>
24	26/03/18 19:57	<b>General View</b>	 Load JPG	<input checked="" type="checkbox"/>
25	26/03/18 19:57	<b>General View</b>	 Load JPG	<input checked="" type="checkbox"/>
26	26/03/18 19:57	<b>General View</b>	 Load JPG	<input checked="" type="checkbox"/>
27	26/03/18 19:57	<b>General View</b>	 Load JPG	<input checked="" type="checkbox"/>
28	28/03/18 20:36	<b>Reinspection Photo</b>	 Load JPG	<input checked="" type="checkbox"/>
29	28/03/18 20:36	<b>Reinspection Photo</b>	 Load JPG	<input checked="" type="checkbox"/>
30	28/03/18 20:36	<b>Reinspection Photo</b>	 Load JPG	<input checked="" type="checkbox"/>
31	28/03/18 20:36	<b>Reinspection Photo</b>	 Load JPG	<input checked="" type="checkbox"/>
32	11/04/18 20:12	<b>Reinspection Photo</b>	 Load JPG	<input checked="" type="checkbox"/>
33	11/04/18 20:12	<b>Reinspection Photo</b>	 Load JPG	<input checked="" type="checkbox"/>
34	11/04/18 20:12	<b>Reinspection Photo</b>	 Load JPG	<input checked="" type="checkbox"/>

Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	Tan Lim Motor Pte Ltd (Defu)	Thumbnail	Print
35	11/04/18 20:12	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
Documentation			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	India International Insurance Pte Ltd (HQ)	Thumbnail	Print
1	21/03/18 08:28	Singapore Accident Statement	 Load PDF	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	27/03/18 17:41	TP ESTIMATE- MARKED	 Load PDF	<input checked="" type="checkbox"/>
2	22/05/18 10:25	WORKSHOP INVOICE	 Load PDF	<input checked="" type="checkbox"/>
3	22/05/18 10:25	AUTHORISATION TO ACT FORM	 Load PDF	<input checked="" type="checkbox"/>
4	22/05/18 10:25	DISCHARGE VOUCHER	 Load PDF	<input checked="" type="checkbox"/>
5	22/05/18 10:25	LOD	 Load PDF	<input checked="" type="checkbox"/>

## Linked Accident Report Documents

Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	Tan Lim Motor Pte Ltd (Defu)	Thumbnail	Print
1	20/03/18 17:42	Accident Statement	 Load HTM	<input checked="" type="checkbox"/>
2	20/03/18 18:42	Addendum Sheet	 Load TIF	<input checked="" type="checkbox"/>
3	20/03/18 18:42	Accident Statement Addm. #1	 Load HTM	<input checked="" type="checkbox"/>
Photos/Images			3 per page	<input checked="" type="checkbox"/>
No	Finalized On	Tan Lim Motor Pte Ltd (Defu)	Thumbnail	Print
1	20/03/18 14:16	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
2	20/03/18 14:16	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
3	20/03/18 14:16	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
4	20/03/18 14:16	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
5	20/03/18 14:16	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
6	20/03/18 14:16	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
7	20/03/18 17:20	Accident Scene Photo	 Load JPG	<input checked="" type="checkbox"/>
8	20/03/18 17:20	Accident Scene Photo	 Load JPG	<input checked="" type="checkbox"/>
9	20/03/18 17:20	Accident Scene Photo	 Load JPG	<input checked="" type="checkbox"/>
Documentation			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	Tan Lim Motor Pte Ltd (Defu)	Thumbnail	Print
1	20/03/18 17:40	Sketch Plan	 Load TIF	<input checked="" type="checkbox"/>

## Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
<b>Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)</b> <div style="border: 1px solid black; height: 40px; margin-top: 5px;"></div>			
<b>Show Remarks To:</b> <input type="checkbox"/> Repairer <input type="checkbox"/> Handling Insurer <small>Note: Remarks are private unless you show it to other parties.</small>			

# LKK Auto Consultants Pte Ltd (Co Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/III18005258/UMB3Q2

Date: 22/05/2018

### REFERENCE

Handling Insurer: India International Insurance Pte Ltd Policy No: MCOM0015  
 Claimant Vehicle No: GBF9439D Insured Vehicle No: SHA3352P  
 Date of Loss: 20/03/2018 Nature of Claim: TP Claim No: MCT18030616

### DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **GBF9439D**  
 Make & Model: ISUZU NHR85AUE4AA, 3.0 D (M) Engine No: 4JJ12X3910  
 Reg. Date: 26/04/2017 (Man. Year: 2016) Chassis No: JAANHR85EH7100049  
 Colour: White/Blue Odometer: 23411 km  
 Engine Capacity: 2999 cc  
 Market Value/New Car Price: N/A  
 Sum Insured (S\$): **Market Value/New Car Price**

### CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Good Steering (Serviceable): Yes Footbrake (Serviceable): Yes  
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

### CONDITION OF TYRES

Front Tyre Size: 185/75 R15 Rear Tyre Size: 145 R13 (D)  
 Front Left Side: Goodyear 6 mm Rear Left Side: Goodyear 6/6 mm  
 Front Right Side: Goodyear 6 mm Rear Right Side: Goodyear 6/6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	10.00	10.00	0.00	0.00
Labour	3,200.00	2,080.00	1,120.00	35.00
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (S\$)</b>	<b>3,210.00</b>	<b>2,090.00</b>	<b>1,120.00</b>	<b>34.89</b>
<b>Approved Total (Overridden) (S\$)</b>		<b>1,650.00</b>		
(S\$)	3,210.00	1,650.00	1,560.00	48.60
<b>+ GST 7.00/7.00% (S\$)</b>	<b>224.70</b>	<b>115.50</b>	<b>109.20</b>	<b>48.60</b>
<b>Nett Amount (S\$)</b>	<b>3,434.70</b>	<b>1,765.50</b>	<b>1,669.20</b>	<b>48.60</b>
<b>+ Loss of Use (4.0 x S\$150.00/day) (S\$)</b>		<b>600.00</b>		
<b>Nett Liability (S\$)</b>		<b>2,365.50</b>		

### INSPECTION

Date of Assignment: 21/03/2018 Present Location: Tan Lim Motor Pte Ltd (Defu)  
 Date Inspected: 26/03/2018 Inspected At: Tan Lim Motor Pte Ltd (Defu)  
 51 Defu Lane 10  
 Singapore 539216

Estimated Period of Repair: 4.0 days

---

**Adjuster:** MARCUS CHUA**Manager:** Lim Chin Siong Bevan

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

### Reference

**Part Source:** (Last Synchronised: 26 Apr 2018)

**Parts:** N/A ISUZU NHR85AUE4AA 3.0 D (M) (Model not available in database)

**Labour:** Repairer's (Price-denominated Standard List)

**Print Code:** (Unsubmitted, no print-code for GBF9439D)

**Validity:** These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

**Further Info:** Items/values not in reference catalogue are prefixed with an asterisk \*.

### Recommended Parts

There are no new parts selected.

Report was unsubmitted during this print-out.



## Recommended Miscellaneous Items

No	Qty	Particulars	Repairer's	Amount
<u>Miscellaneous Items</u>				
1	1	OD/TP Case (Insurer) (NECESSARY)	10.00	10.00
Sub Total (S\$)			10.00	10.00

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	To make good repair to o/s rear end aluminum box and supply 1pc of track-alumium.	New	1,500.00	1,000.00
2	To supply and redo graphic display sticker and corporate logo.	New	1,000.00	680.00
3	Putty and spray painting of the affected portion.	New	700.00	400.00
Gross Labour Cost (S\$)			3,200.00	2,080.00

Report was unsubmitted during this print-out.
---

&lt; END OF ESTIMATES &gt;