

CC 6 ^{LKR} /AIG1800 5262, Aylor

Surveyor: Adnan

DOI: 20/7/18

Date / Time: 20/7/18

Registered in Merimen: 21/7/18

Pre-assign / CCU / FTE



Insured Vehicle No.: SLF 5268H

Claim No.: 890448963836

Name of Insured: URP

Policy No.: 94445053

Insured Tel No.: _____ HP: _____

Make / Model: MAZDA

Excess Sec II :SS _____ D.O.A: 18/7/18

Place of Accident: WANTONMENT UNF TRNS

Is driver the owner? (YES / NO) Nature of Accident: WANTONMENT RO

If NO, Driver Name / Age: OMN LITE SIAMA (WAMY BRIXIMU) GIA REPORT: YES NO ; TP GIA REPORT: YES NO

Driver Tel No.: _____ (V/L: YES / NO) Insured Liability: _____ % Final ? Yes / No

SJK 94489



INSRS: _____
WSP: Hua meng
Tel: _____
Liability: _____
RMKS: _____



INSRS: _____
WSP: _____
Tel: _____
Liability: _____
RMKS: _____



INSRS: _____
WSP: _____
Tel: _____
Liability: _____
RMKS: _____



INSRS: _____
WSP: _____
Tel: _____
Liability: _____
RMKS: _____

Date/ Time

20/7/18
27-11-18
28/11/18

SJK 94489 - 2
supor 5268H - 2
- CONFLICTING VERSIONS
50% REJECTED BY TP.
CHECKED WITH VIEW DAMAGE PRO
TUGEST IT MORE RELIABLE.
MANDATE FROM AIG TO SETTLE
AT BEST.

STAGE DATE / PIC

Non-Reporting ltr (1st):
Non-Reporting ltr (2nd):
Non-Reporting ltr (Final):
Notification ltr (if non-pickup):
Call OE: 241-8-18
After call ltr to OE:

Documentation Check List: Handler Typist

Notification ltr (if non-pickup)	<input checked="" type="checkbox"/>	<input type="checkbox"/>
After call ltr to OE	<input checked="" type="checkbox"/>	<input type="checkbox"/>
Authorisation To Act	<input checked="" type="checkbox"/>	<input type="checkbox"/>
Release Voucher	<input checked="" type="checkbox"/>	<input type="checkbox"/>
Final Repair Bill	<input checked="" type="checkbox"/>	<input type="checkbox"/>
Car Rental Invoice	<input checked="" type="checkbox"/>	<input type="checkbox"/>
Towing Invoice	<input checked="" type="checkbox"/>	<input type="checkbox"/>
LTA / GIA	<input checked="" type="checkbox"/>	<input type="checkbox"/>
Medical Bill	<input checked="" type="checkbox"/>	<input type="checkbox"/>
PIR	<input checked="" type="checkbox"/>	<input type="checkbox"/>
Mandate/Reject Instruction	<input type="checkbox"/>	<input type="checkbox"/>
LOD	<input type="checkbox"/>	<input type="checkbox"/>
Payment Breakdown Form	<input type="checkbox"/>	<input type="checkbox"/>
Post-Repair Photos	<input type="checkbox"/>	<input type="checkbox"/>
Others	<input type="checkbox"/>	<input type="checkbox"/>

PRELIMINARY ADVICE Date/Time: _____ Sent By: _____

FINALIZATION Date/Time: _____ Confirm with: _____ Confirm by: _____

Repair Cost: \$5 _____ (days) Reduction: _____ % Email Call

FINAL SETTLEMENT Date/Time: 28-11-18 Confirm with: JUNE Email Call

Final Liability: % 100 (Agreed / Assessed) BOLA S/N No.: 110 If NO or B 28, Ass. Lia: _____

Repair Cost: \$5 6,800.xx

Loss of Rental (LOR): \$5 200.xx (2 days) 100

Loss of Use (LOU): \$5 - (5 x days)

Loss of Income (LOI): \$5 - (5 x days)

LOR only LOU only LOR + LOU LOR + LOI [Tick only one]

GIA/LTA Search: \$5 7.45

Medical: \$5 -

Disbursement: \$5 - (e.g. Tow/ Independent)

Legal Cost: \$5 -

Total: \$5 7,007.45 Global Sum \$5: 7,000.xx

FINAL PAYMENT Date/Time: _____ Confirm with: _____ Email Call

Payee 1: \$5 7,000.xx Name 1: HUA MENG SPRAY PAINTING WORKSHOP

Payee 2: (Strike if N.A.) \$5 x Name 2: x

Payee 3: (Strike if N.A.) \$5 _____ Name 3: _____

COMMENT
15/11/18

- 1) Claim status: Normal/Reject/Private Settle
- 2) Report Format:
- 3) Survey fee:

ASS. REC. BY: Adrian Ling

REF:

ASSIGNMENT

11/01/08

From: _____ Date: _____

Veh No: SJK5448G Yr Regn: 2008, Nov

Estimated Cost: _____

Type: M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

Truck / Trailer or _____

To Inspect Vehicle No: _____

Make: Toyota Altis c.c. 1598

at Workshop m/s _____

Colour: Gold A/C: Insured / Std / NI / NA

of _____

Sp. Reading: 192506 T/Radio: Insured / Std / NI / NA

Insured: _____

Eng/No: _____

Policy No. _____

C/No: MROS37EE106119238

Claims No. _____

Gen. Cond: Good / Fair / Poor / Burnt

Sum Insured: _____ Excess: _____

Steering: In order / Jammed / Leaked / Burnt or _____

(Client's Record)

Brake: In order / Jammed / Leaked / Burnt or _____

Make of Veh: _____

Modi: Nil / S/Rim / STD A/Rim or _____

(Policy Condition)

Tyre Size: F: 195/65R15

R: 195/65R15

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or _____

Bal. or Market Value: _____

Front 06 mm Rear 06 mm

IDAC Accident Rpt: _____ Consistent? : Yes or No

L/Bal. 06 mm L/Bal. 06 mm

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: 4 days Res.: Yes or No

D.O.A. _____ D.O.I. 29/03/18

Lum Sum: _____ % 3 Val.: Yes or No

Survey held at Hua Meng

CA / REV / REP. / 24 HRS

Des. of Damages: Frt / Rear O/S / N/S / UIC / Rooftop or _____

Date: _____ Person Contacted: _____ Vehicle: IN / OUT

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
	TPALG.
10-5-18	L/S \$6,500
	MV: 15.9k
	PV: 8.8k
	Net: 71c.
	R (\$ 6,164.75 / 48%)

Date/Time, File Pass to? : Prel. Report

Days Of Repair: _____

1) : Final Report

Resurvey No. of Trip: _____

Date/Time, File Return to?

2) _____

Report Format : _____

Lump Sum / I.B.I: (\$) _____

Add Fee: : Site Insp (\$ _____) : Interview (\$ _____) : Tech. Invs (\$ _____) : Weekend (\$ _____)

Survey Fee:	
Transportation:	_____ \$ + RS _____ \$
Photos:	
Others:	
TOTAL	

HUA MENG SPRAY PAINT NG WORKSHOP

1, Kaki Bukit Avenue 6, Blk C #01-61 / 01-34, Singapore 417883

Autobay @ Kaki Bukit

Tel: 6747 8064, 6746 5519 / 9666 9680 Fax: 6743 4896

ESTIMATE

MR 0537EE10615238

KS LEASING
606 WOODLANDS RING ROAD
#11-267
S 730606

TP2CR
Joy

Date :28.03.2018
Vehicle no :SJK 9448 G
Make/Model :TOYOTA ALTIS
Accident date :18.03.2018

No	Description	Qty	Amount (\$)
<u>List Items</u>			
1	Rear windscreen rubber <i>new</i>	1	\$ 53.8 ✓
2	Rear RH fender <i>Distorted</i>	1	\$ 758.2 ✓
3	Rear RH door <i>Distorted</i>	1	\$ 858.8 ✓
4	Rear RH door protector <i>Distorted</i>	1	\$ 92 ✓
5	Rear RH door glass outer moulding <i>not new</i>	1	\$ 124.5 x
6	Rear RH door outer handle <i>not new</i>	1	\$ 68.1 x
7	Rear RH door top hinge	1	\$ 91.1 ✓
8	Rear RH door lower hinge <i>not new</i>	1	\$ 91.1 x
9	Rear RH door stopper <i>not new</i>	1	\$ 161.4 x
10	Rear RH door weather strip <i>new</i>	1	\$ 145.9 ✓
11	Rear RH door inner board <i>cracked</i>	1	\$ 623.8 ✓
12	Rear RH door power window motor <i>damaged</i>	1	\$ 583.9 ✓
13	Rear RH door power window regulator <i>damaged</i>	1	\$ 214.3 ✓
14	Rear RH door frame black sticker(1set) <i>new</i>	1	\$ 70.7 ✓
15	Front RH door <i>Distorted</i>	1	\$ 970.1 ✓
16	Front RH door protector <i>defend</i>	1	\$ 138.3 ✓
17	Front RH door glass outer moulding <i>not new</i>	1	\$ 132.3 x
18	Front RH door outer handle <i>not new</i>	1	\$ 68.9 x
19	Front RH door top hinge	1	\$ 91.1 ✓
20	Front RH door lower hinge <i>not new</i>	1	\$ 91.1 ✓
21	Front RH door stopper	1	\$ 152 x
22	Front RH door weather strip <i>new</i>	1	\$ 173.5 ✓
23	Front RH door inner board <i>cracked</i>	1	\$ 840.2 ✓ <i>680.30</i>
24	Front RH door power window motor <i>not new</i>	1	\$ 839.4 x
25	Front RH door power window regulator <i>not new</i>	1	\$ 236.6 ✓ <i>73027</i>
26	Front RH door frame black sticker (1set) <i>not new</i>	1	\$ 68.1 ✓ <i>547702</i>
27	Front RH door side mirror <i>not new</i>	1	\$ 558.1 x
28	Front RH door inner lock <i>not new</i>	1	\$ 480.9 ✓
29	Rear RH door inner lock <i>not new</i>	1	\$ 433.1 ✓
30	RH door centre pillar <i>not new</i>	1	\$ 381 x
31	RH rocker panel <i>not new</i>	1	\$
32	RH rocker panel garnish <i>defend</i>	1	\$ 720.7 ✓
			\$ 10313
	Less 25% Disc		\$ 2578.25
	Total		\$ 7734.75

HUA MENG SPRAY PAINTING WORKSHOP

1, Kaki Bukit Avenue 6, Blk C #01-61 / 01-34, Singapore 417883

Autobay @ Kaki Bukit

Tel: 6747 8064, 6746 5519 / 9666 9680 Fax: 6743 4896

ESTIMATE

KS LEASING
606 WOODLANDS RING ROAD
#11-267
S 730606

Date :28.03.2018
Vehicle no :SJK 9448 G
Make/Model :TOYOTA ALTIS
Accident date :18.03.2018

No	Description	Qty	Amount (S\$)
Special Nett Items			
1	Rear RH sport rim <i>ut</i>	1	\$ 800 ¹⁸⁰
2	Rear RH tyre <i>Hot slow</i>	1	\$ 380 ^x
		Total	\$ 1180
Labour Costs			
1	To supply rear windscreen sealant		\$ 50 ✓
2	Remove & reinstall door glass <i>fitting</i>		\$ 200 ¹⁶⁰
3	Remove & reinstall roof lining & cushion		\$ 200 ⁵⁰
4	Remove & reinstall rear windscreen	2620	\$ 150 ²⁰
5	Remove, replace & repair consistent to the accident		\$ 1800 ¹²⁰⁰
6	Respray painting		\$ 1500 ¹⁰⁰⁰
7	Tuff kote		\$ 150 ⁴⁰
		Total	\$ 4050
		Grand Total	\$ 12964.75

total: 8577.02

l/s: 6-812

06 Days

68K

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modifications is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Business
Owner ID:	7173J
Vehicle Details	
Vehicle No.:	SJK9448G
Vehicle to be Exported:	Yes
Intended De-registration Date:	20 Mar 2018
Vehicle Make:	TOYOTA
Vehicle Model:	COROLLA ALTIS 1.6 AUTO
Primary Colour:	Beige
Manufacturing Year:	2008
Engine No.:	3ZZ4798261
Chassis No.:	MR053ZEE106119238
Maximum Power Output:	80.0 kW (107 bhp)
Open Market Value:	\$16,084.00
Original Registration Date:	11 Nov 2008
First Registration Date:	11 Nov 2008
Transfer Count:	1
Actual ARF Paid:	\$16,084.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	10 Nov 2018
PARF Rebate Amount:	\$8,042.00
Intended COE Rebate Details	
COE Expiry Date:	10 Nov 2018
COE Category:	A - Car (1600cc & below)
COE Period(Years):	10
QP Paid:	\$10,989.00
COE Rebate Amount:	\$704.00
Total Rebate Amount:	\$8,746.00

The information contained herein is correct as at 20 Mar 2018

OK

- ALL consolidated SMRT/NEL/KT.. simisal BREAKDOWNS here...
- Another term for China's President.
- MAZDA 6

Post an Advertisement
Sell it yourself! Advertise it at just
\$58 until it's SOLD!

[Post an Ad](#) [Advertiser Login](#) [Ways of Selling](#)

2011 C180K Face Lifted Model Tip Top Condition!



Up To 95% Loan Package
Available, Very Low Mileage,
Dearest Warranty Available.
Straits Drive Start!



Browse by Category

« Back (1 2 3 4 5) Next »

Sort by Date Posted

20 results/page

89 vehicles

toyota altis

Advanced Search

Make	Model	Price	Depreciation	Reg Date	Eng Cap	Mileage	Veh Type	Status
Search Selection								
toyota altis		Any	Any	2008	Any	Any	Any	Available
	Toyota Corolla Altis 1.6A (New 5-yr COE)	\$35,999	\$7,200 /yr	14-Oct-2008	1,598 cc	-	Sedan	Available
1 Owner New Arrival! Sporty White In Grey Toyota Corolla Altis 1.6 Auto Sports! Most Popular Toyota For Your Family And Daily Usage. Very Clean Interior And Own By Non Smoker. Fuel Saving Yet Powerful...								
Posted: 12-Feb-2018 Tags: 2008 Toyota Corolla, Toyota Corolla, Toyota, Corolla, Used Toyota								
	Toyota Corolla Altis 1.6A (New 5-yr COE)	\$38,800	\$7,760 /yr	31-Oct-2008	1,598 cc	110,300 km	Sedan	Available
One Owner, \$5,800 Down Payment, \$696 Monthly Installment, New Coat Of Paintwork, Wear & Tear Parts Replaced, Excellent Condition, View To Believe!								
Posted: 17-Mar-2018 Tags: 2008 Toyota Corolla, Toyota Corolla, Toyota, Corolla, Used Toyota								
	Toyota Corolla Altis 1.6A	\$16,888	\$13,980 /yr	07-Nov-2008	1,598 cc	109,000 km	Sedan	Available
Trade In All Available, Interested Please Call For Viewing, Viewing By Appointment Only.								
Boeki Auto & Marine								
Posted: 15-Mar-2018 Tags: 2008 Toyota Corolla, Toyota Corolla, Toyota, Corolla, Used Toyota								
	Toyota Corolla Altis 1.6A	\$13,800	\$9,100 /yr	07-Nov-2008	1,598 cc	-	Sedan	Available
\$0 Down-payment Available! 1 Owner Only! High Trade-in! STA Certified Cars! All Time Favourite, Reliable Sedan Well Kept In Excellent Condition, View It To Believe! Buy It From Us With A Peace Of Mind...								
Dickson Automobile								
Posted: 18-Jan-2018 Tags: 2008 Toyota Corolla, Toyota Corolla, Toyota, Corolla, Used Toyota								
Car Buying	Car Selling	Car Ownership	Buying a pre-owned car, but Unsure of its Conditions? Get STA Car Evaluation					
Car Aftermarket	On The Move	Lifestyle						
	Toyota Corolla Altis 1.6A	\$16,500	\$13,190 /yr	10-Nov-2008	1,598 cc	-	Sedan	Available
Condition So Good, Great For COE Renewal, Grab It Fast Before It's Sold! Bank Loan / In-house Loan All Available!								
Swee Seng Motors								
Posted: 17-Mar-2018 Tags: 2008 Toyota Corolla, Toyota Corolla, Toyota, Corolla, Used Toyota								
	Toyota Corolla Altis 1.6A (New 5-yr COE)	\$35,800	\$7,160 /yr	13-Nov-2008	1,598 cc	-	Sedan	Available
Graded B by STP								
\$2800 Down Payment, Monthly From \$688 Onwards. Lowest Interest At 3.68% Per Annum By GV Cars Financing. 100% Loan Approval. 2 Years Warranty By GV In House Workshop. New Paintwork And Leather Seats. 1...								
\$2800 Downpayment Monthly From \$688 Onwards. Lowest 3.68% P.A. @ GV Cars Financing								
GV Credit Pte Ltd								
Posted: 20-Mar-2018 Tags: 2008 Toyota Corolla, Toyota Corolla, Toyota, Corolla, Used Toyota								
	Toyota Corolla Altis 1.6A (OPC) (New 5-yr COE)	\$39,777	\$7,950 /yr	25-Nov-2008	1,598 cc	90,403 km	Sedan	Available
New 5 Years COE! 1st Owner. Low Mileage. Regularly Serviced. Fully Refurbished Condition. Smooth Engine. Affordable Depreciation. Easy Financing. Probably Most Reliable, Comfortable, Yet Fuel Efficient...								

Posted: 08-Mar-2018 Tags: 2008 Toyota Corolla, Toyota Corolla, Toyota, Corolla, Used Toyota



Toyota Corolla Altis 1.6A **\$18,000** **\$13,720 /yr** **11-Dec-2008** **1,598 cc** **313,200 km** **Sedan** **Available**

Posted: 29-Jan-2018 Tags: 2008 Toyota Corolla, Toyota Corolla, Toyota, Corolla, Used Toyota

Direct Contact

Toyota Corolla Altis 1.6A **\$16,800** **\$11,840 /yr** **16-Dec-2008** **1,598 cc** **-** **Sedan** **Available**

Buy This Elegant Yet Fuel Efficient Sedan From Us With A Peace Of Mind! A Company Accredited With Outstanding Awards, Professional After Sales Service Assured. In House Grooming Available To Service/M...

Dickson Automobile

Posted: 14-Mar-2018 Tags: 2008 Toyota Corolla, Toyota Corolla, Toyota, Corolla, Used Toyota

Save this search criteria, to get email alerts whenever a match is found.

Make Model Price Depreciation Reg Date Eng Cap Mileage Veh Type Status

[View Expired ads](#)[Compare](#)[Back \(1 2 3 4 5 \) Next >](#)

20 results/page

sgCarMart is the number one car classifieds for parallel import cars, Toyota, Honda, Nissan, Mitsubishi & BMW. There are plenty of cars for sale, from vans, trucks, sedan cars, luxury cars, sports cars or station wagons, SUV, MPV, hatchback, to COE cars & CPC cars. You can also buy from a car auction, look up car loans, low mileage cars, car brands, carpark rates & car insurance. Find buy used toyota altis, toyota altis Singapore, used toyota altis Singapore, used toyota altis, used vehicles Singapore or even buy used toyota altis Singapore. We have new car dealers comprising parallel importers, authorised car dealers, and used car dealers on our site. Find new car price lists, new car launches and new car promotions. Visit our partner sites for job openings for Singapore jobs, real estate properties for sale, mover, car performance parts, car discussion, forum discussion, commercial vehicle leasing & COE results.

All prices and other information displayed on sgCarMart.com are gathered from sources and based on algorithms that are believed by sgCarMart.com to be reliable, but no assurance can be given that this information is accurate, complete or current. sgCarMart.com does not assume any responsibility for errors or omissions or warrant the accuracy of this information.

- Home
- New Car
- Used Car
- Sell Car
- Motoring Directory
- Products Guide
- Article
- Forum
- Tool & Tip

- About Us
- Careers
- Contact Us
- Sitemap

© 2004-2018 sgCarMart. All rights reserved.

- Terms of Service
- Privacy Policy
- Personal Data Protection Statement



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
AIG ASIA PACIFIC INSURANCE PTE LTD		Ref : CC6/LCR18005262/Ajb3	
78 SHENTON WAY #08-16 CHARTIS BUILDINGSINGAPORE 079120		Date : 21-03-2018	
		Code : LCR	
1. Policy Particulars :- THIRD PARTY CLAIM			
Insured Veh.	SLF 5368H	Veh. Inspected	SJK 9448G
Policy No.		Coverage (\$)	0.00
Claim No.		Excess (\$)	0.00
Assign From		Assign Date	21/03/2018
2. Vehicle Particulars & Condition			
Make & Model		c.c	0
Engine No.	HIDDEN	Year of Reg.	
Chassis No.		Colour	
Odometer	-	Steering	
Brakes		Modification	
General			
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm
4. Description of Damages			
5. General Information			
Accident Date	18/03/2018	Inspection Date	20/03/2018
Survey held at	HUA MENG SPRAY PAINTING WKSP 1 KAKI BUKIT AVE 6 #01-61 AUTOBAY SINGAPORE 417883		
5a. Remarks			
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			



華 明 噴 漆 廠
HUA MENG SPRAY PAINTING WORKSHOP

AUTOBAY@KAKIBUKIT

1, Kaki Bukit Avenue 6 Blk C #01-34/#01-61, Singapore 417883
 Tel: 6747 8064, 6746 5519 Fax: 6743 4896 H/P: 9666 9680
 Reg. No.: 254678/00M



350

Your Ref :

Our Ref :

Date: 04-05-2018

Attn: Motor Claims Dept

ACCIDENT ON 18.03.2018 INVOLVING VEHICLE SJK 9448 G & SLF 5368 H ALONG CANTONMENT ROAD

With regards to the above, we are writing on behalf of the registered owner of vehicle SJK 9448 G which was involved in the above mentioned accident.

We are informed that the above accident was caused solely by the negligence of your insured vehicle SLF 5368 H. As a result of the accident, our client's vehicle was damaged and our client had instructed us to submit his claims for loss and expenses, particulars of which are follows:

1) Repair Cost	\$	6,800.00
2) Loss of rental-\$120 X 02days	\$	480.00
3) LTA serach	\$	7.45
Total	\$	7,287.45

We hereby enclosed herewith the following documents for your consideration of the above claim.

- a) Final Repair Bill Of SJK 9448 G
- b) GIA report
- c) LTA SEARCH
- d) Owner / Driver NRIC & Driving License

華 明 噴 漆 廠
 HUA MENG SPRAY PAINTING WORKSHOP
 AUTOBAY@KAKI BUKIT
 #01-34 SINGAPORE 417883
 TEL: 6747 8064 6746 5519 FAX: 6743 4896

Yours faithfully,
HUA MENG SPRAY PAINTING WORKSHOP

Joy Irene (LKKAuto)

From: Joy Irene (LKKAuto)
Sent: Wednesday, 1 August 2018 2:35 PM
To: Eileen Yap
Cc: Admin A; Vivian Lau (LKKAuto); Hsiao Tong (LKKAuto)
Subject: ACCIDENT INVOLVING SLF 5368h & SJK 9448G ON 18/03/2018 (00:45) ALONG CANTONMENT LINK

01 August 2018

LCRF PTE LTD

Policy Holder

Your Ref: SJK 9448G
Our Ref: CC6/LCR18005262/Ajb3

Dear Sir/Madam,

ACCIDENT INVOLVING SLF 5368h & SJK 9448G ON 18/03/2018 (00:45) ALONG CANTONMENT LINK

We refer to the above accident where we are acting for AIG Asia Pacific Insurance Pte Ltd to resolve the claim against you and/or your authorized driver under the Auto Insurance policy taken up with them.

We have received a claim from **SJK 9448G** against your insurance policy.

Based on the information on hand, we are of the opinion that we cannot be absolved from liability without concrete evidence presented.

We will therefore proceed to negotiate for an amicable settlement with the Third Party.

Should you however wish to further discuss on the matter prior to our negotiations and settlement, please contact us within 10 days from the date of this letter.

Please call us if you have further queries.

Best Regards,
Joy Irene | Case Handler
LKK Auto Consultants Pte Ltd
DID: 6841-2409 | email: joyirene@lkkauto.com | Fax: 6741-4108
Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

All contents of this email is intended strictly for the addressee(s) only. It may contain confidential and/or privileged information. If you are not the intended recipient (or have received this email in error) please notify the sender immediately and destroy this email. Any unauthorized copying, disclosure or distribution of the material in this email is strictly forbidden.

AUTHORISATION TO ACT

I/We, KS Leasing ("the third party claimant") of
606 Woodlands Ring Road #11-267, S(730606) (address),
owner of SJK94X8G (vehicle no.) hereby authorise **HUA MENG SPRAY PAINTING**
WORKSHOP ("the workshop") to act for me with respect to my claim for repair costs and/or
rental and/or loss of use ("claim") for my vehicle no. SJK94X8G that was damaged pursuant
to the accident which occurred on 18.03.2018 (date) along Cantonment Road
(location) involving vehicle no/s SLF5368H ("the accident").

I further authorize the workshop to settle my above mentioned claim in a manner that they deem
fit and the workshop is further authorized to receive payment further to settlement of my claim
with payment cheque/s being made in favour of the workshop.

I further acknowledge that any settlement the workshop may reach on my behalf is on a without
prejudice and without admission of liability basis insofar as the driver/owner/insurers of the other
vehicle/s is concerned.

Dated this 19 (day) of 03 (month) 2018 (year)



Signed by "the third party claimant"
(with company stamp if applicable)

華明噴漆廠
HUA MENG SPRAY PAINTING WORKSHO
AUTOBAY@KAKI BUKIT
1 KAKI BUKIT AVE 8 #01-34 SINGAPORE 41788
TEL: 6747 8804, 6747 5319 FAX: 6743 485

Signed by "the workshop"
(with company stamp)

RELEASE VOUCHER
(AIG Asia Pacific - Express Third Party Claim)

WITHOUT PREJUDICE
TO OUR CLIENT'S PERSONAL INJURY
CLAIM (PRESENT OR FUTURE) WHICH IS
EXPRESSLY RESERVED

"We/I, HUA MENG SPRAY PAINTING WORKSHOP ("the workshop") hereby confirm that we/I have reached an agreement with the appointed surveyor of AIG Asia Pacific Insurance Pte Ltd LKK AUTO CONSULTANTS PTE LTD (name of surveyor) with respect to the amount claimed for S\$7,000.00 (Global Sum) for vehicle no. SJK 9448G that was damaged pursuant to the accident which occurred on 18/03/2018 (date) along CANTONMENT ROAD (location) involving vehicle no/s SLF 5368H. This is pursuant to the inspection conducted on 20/03/2018 (date) at "the workshop".

We/I confirm that we/I are/am authorized by the owner KS LEASING ("the third party claimant") of vehicle no. SJK 9448G make the claim as set out in the above paragraph and we/I have full authority to settle the matter on his/her behalf in a manner that we/I deem fit. We/I enclose herein the letter of authority given by "the third party claimant".

We/I further confirm that we/I will indemnify AIG Asia Pacific Insurance Pte Ltd for all damages, loss and/or expense that they will or have already incurred in the event that "the third party claimant" after the above said agreement lodges a further claim against the former for any loss and expenses suffered pertaining to costs of repairs and/or rental and/or loss of use pursuant to the damage to SJK 9448G (vehicle no.) as a result of the accident.

We/I confirm that the agreement reached above is in full and final settlement of any claim of "the third party claimant" pursuant to the accident and that further this settlement is reached on a without prejudice and without admission of liability basis.

This agreement is subject to the application of Singapore law and the Singapore Courts have exclusive jurisdiction over any dispute arising out of the same.

Dated this 29 (day) of 11 (month) 2018 (year)

Signed by appointed surveyor

華明噴漆廠
HUA MENG SPRAY PAINTING WORKSHOP
ANTOBAY@KAKI BUKIT
1 KAKI BUKIT AVENUE #01-34 SINGAPORE 417881
TEL: 6747 8064, 6746 5519 FAX: 6743 4891
Signed by "the workshop" (with chop)



華明噴漆廠
HUA MENG SPRAY PAINTING WORKSHOP

AUTOBAY@KAKIBUKIT

1, Kaki Bukit Avenue 6 Blk C #01-34/#01-61, Singapore 417883
Tel: 6747 8064, 6746 5519 Fax: 6743 4896 H/P: 9666 9680
Reg. No.: 254678/00M



Your Ref : SF 5368H

18/5/2018

Our Ref : SJK 9448G

Date:.....

VEHICLE NO :SJK 9448 G
MAKE / MODEL :TOYOTA ALTIS
NAME :KS LEASING
ADDRESS :606 WOODLANDS RING ROAD
#11-267
S 730606

FINAL REPAIR BILL FOR VEHICLE NO:SJK 9448 G

TO SUPPLY AND REPLACE PARTS, LABOUR CHARGES FOR
REPAIRING, KNOCKING, WELDING AND TO RESPRAY PAINTING
(LUMP SUM REPAIR)

\$ 6,800.00

SINGAPORE DOLLARS:SIX THOUSAND EIGHT HUNDRED ONLY



INVOICE

KS LEASING
 BLK 606 WOODLANDS RING ROAD
 #11-267 S'PORE 730606
 ROB: 53367173J
 Singapore

9387 4964

BILL TO
 TAN KAELYNN

Invoice Number: 97820304

Invoice Date: March 27, 2018

Payment Due: March 27, 2018

Amount Due (SGD): \$0.00

Rental	Days	Rate	Amount
CAR DAILY RENTAL	4	\$120.00	\$480.00

Total:	\$480.00
Payment on March 27, 2018 using cash:	\$480.00
Amount Due (SGD) :	\$0.00



ROB No: 53367173J
 Contact: 9387 4964
 Email: kelvinsimba@gmail.com

S/NO: _____

DATE: _____

RENTAL AGREEMENT

HIRER'S PARTICULARS

Name: _____

Address: _____

NRIC/Passport No: _____ Country: _____

Occupation: _____

Date of Birth: _____ Age: _____

Driving Licence No: _____ Date Passed: _____

Tel (Mobile): _____ (Residence): _____

DRIVER'S PARTICULARS

Name: TAN Kaelyn

Address: 81K 85 Whampoa Drive

02-268. 5(320085)

NRIC/Passport No: S742182A Country: SG

Occupation: _____

Date of Birth: 20-04-1974 Age: _____

Driving Licence No: _____ Date Passed: _____

Tel (Mobile): 82227800 (Residence): _____

Make/Model: <u>Mitsubishi Lancer</u>	Vehicle No: <u>SJK 9782R</u>						
Date & Time Out: <u>19.03.2018 @ 1425hrs</u>	Date & Time In: _____						
<table border="1" style="width: 100%; border-collapse: collapse;"> <tr> <td style="width: 33%; text-align: center;">0</td> <td style="width: 33%; text-align: center;">1/2</td> <td style="width: 33%; text-align: center;">Full</td> </tr> </table> Mileage Out: _____	0	1/2	Full	<table border="1" style="width: 100%; border-collapse: collapse;"> <tr> <td style="width: 33%; text-align: center;">0</td> <td style="width: 33%; text-align: center;">1/2</td> <td style="width: 33%; text-align: center;">Full</td> </tr> </table> Mileage In: _____	0	1/2	Full
0	1/2	Full					
0	1/2	Full					
DAILY RENTAL CHARGES: \$ _____	DEPOSIT: \$ _____						
TOTAL DAYS USAGES: _____	TOTAL RENTAL: \$ _____						

Remarks: _____

Terms & Conditions:

- 1 No Insurance Coverage if the driver is below 24 years old or less than 2 years driving licence.
- 2 This vehicle is licenced to carry _____ passengers only.
- 3 Hirer is liable to pay first \$ _____ as excess all claims any accident plus loss of earning while damaged vehicle is under repair.
- 4 For usage to Malaysia subject to higher excess all claim of S\$5000/- and different rental rate.
- 5 Please notify our office should there be any accident involving this hired vehicle within 24 hrs.
- 6 No refund will be given for vehicle which returns early.
- 7 No refund will be given for petrol left in the vehicle.
- 8 Hirer is liable to pay all parking fines and traffic summonses should there be any during renting period.
- 9 Vehicle to be return during office hour only.

 Hirer's Signature

[Signature]
 Driver's Signature


 KS Leasing

* I/We have read and understood the Terms & Conditions above and hereby agreed to abide.

...CLAIM SUBFOLDER...(Pending for Survey Report)

Fastlane

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	20 Mar 2018 Edit Reg		20 Mar 2018 00:00 Edit Adj Rpt	S\$6,800.00 Edit Estimates	S\$6,800.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by adjuster]									
Insured:	LCRF PTE LTD, Co. Reg. No.: 201624597K								
Main Claimant:	KS LEASING, Co. Reg. No.: 533671733								
Vehicle Reg. No.:	SJK9448G	Date of Loss:	18/03/2018 12:00 - :59 [112 Months and 7 Days From LTA Reg Date (Man Yr)]						
Claim Type:	TP / 8907489638SG	Policy/Cover Note No.:	0999994780 (Comprehensive)						
Vehicle Reg. No. (Insured):	SLF5368H	Policy No. (Claimant):	5094541586						
Repairer:	Hua Meng Spray Painting Workshop (HQ) No 1 Kaki Bukit Avenue 6, #01-61 Autobay@Kaki Bukit, 417883 Kaki Bukit - Tel: 67478064, 67465519								
Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd. (Express) - Tel: 65-6419-3000 ... [Handled by Gan, Angle-GL] Angiegeokling.Gan@aig.com								
Claimant's Insurer:	NTUC Income Insurance Co-operative Ltd (HQ) - Tel:								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by ADRIAN LING] ... [Final Rpt due 02/04/2018]								
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
There are no mail for this case.									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

***SJK9448G (8907489638SG)**
[SLF5368H]
TP
KS LEASING
Mar 18 2018 12:00PM
[LCRF PTE LTD]
Hua Meng Spray Painting Workshop

Upload Documents Upload Photos Compose New Letter Upload Video Upload Audio			View	View in Browser
Letters/Correspondences			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	(Draft)	Third Party Express Settlement - Payment Breakdown	1 Edit	
Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	AIG Asia Pacific Insurance Pte. Ltd. (SG)	Thumbnail	Print
1	22/03/18 12:07	Accident Statement <small>From: SC - Reg. No: SLF5368H, Claimant: LCRF PTE LTD</small>	1 Load HTM	
Photos/Images			3 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	10/05/18 19:36	General View	1 Load JPG	<input checked="" type="checkbox"/>
2	10/05/18 19:36	General View	1 Load JPG	<input checked="" type="checkbox"/>
3	10/05/18 19:36	General View	1 Load JPG	<input checked="" type="checkbox"/>
4	10/05/18 19:36	General View	1 Load JPG	<input checked="" type="checkbox"/>
5	10/05/18 19:36	General View	1 Load JPG	<input checked="" type="checkbox"/>
6	10/05/18 19:36	General View	1 Load JPG	<input checked="" type="checkbox"/>
7	10/05/18 19:36	General View	1 Load JPG	<input checked="" type="checkbox"/>
8	10/05/18 19:36	General View	1 Load JPG	<input checked="" type="checkbox"/>
9	10/05/18 19:36	General View	1 Load JPG	<input checked="" type="checkbox"/>
10	10/05/18 19:36	General View	1 Load JPG	<input checked="" type="checkbox"/>
11	10/05/18 19:36	General View	1 Load JPG	<input checked="" type="checkbox"/>
12	10/05/18 19:36	General View	1 Load JPG	<input checked="" type="checkbox"/>
13	10/05/18 19:36	General View	1 Load JPG	<input checked="" type="checkbox"/>
14	10/05/18 19:36	General View	1 Load JPG	<input checked="" type="checkbox"/>
15	10/05/18 19:36	General View	1 Load JPG	<input checked="" type="checkbox"/>
16	10/05/18 19:36	General View	1 Load JPG	<input checked="" type="checkbox"/>
17	10/05/18 19:36	General View	1 Load JPG	<input checked="" type="checkbox"/>
18	10/05/18 19:36	General View	1 Load JPG	<input checked="" type="checkbox"/>
19	10/05/18 19:36	General View	1 Load JPG	<input checked="" type="checkbox"/>
20	10/05/18 19:36	General View	1 Load JPG	<input checked="" type="checkbox"/>
21	10/05/18 19:36	General View	1 Load JPG	<input checked="" type="checkbox"/>
22	10/05/18 19:36	General View	1 Load JPG	<input checked="" type="checkbox"/>
23	10/05/18 19:36	General View	1 Load JPG	<input checked="" type="checkbox"/>
24	10/05/18 19:36	General View	1 Load JPG	<input checked="" type="checkbox"/>
25	10/05/18 19:36	General View	1 Load JPG	<input checked="" type="checkbox"/>
26	10/05/18 19:36	General View	1 Load JPG	<input checked="" type="checkbox"/>
27	10/05/18 19:36	General View	1 Load JPG	<input checked="" type="checkbox"/>
28	10/05/18 19:36	General View	1 Load JPG	<input checked="" type="checkbox"/>
29	10/05/18 19:36	General View	1 Load JPG	<input checked="" type="checkbox"/>
30	10/05/18 19:36	General View	1 Load JPG	<input checked="" type="checkbox"/>

Letters/Correspondences			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
31	10/05/18 19:36	General View	 Load JPG	<input checked="" type="checkbox"/>
32	10/05/18 19:36	General View	 Load JPG	<input checked="" type="checkbox"/>
33	10/05/18 19:36	General View	 Load JPG	<input checked="" type="checkbox"/>
34	10/05/18 19:36	General View	 Load JPG	<input checked="" type="checkbox"/>
35	10/05/18 19:36	General View	 Load JPG	<input checked="" type="checkbox"/>
36	10/05/18 19:36	General View	 Load JPG	<input checked="" type="checkbox"/>
37	10/05/18 19:36	General View	 Load JPG	<input checked="" type="checkbox"/>
38	10/05/18 19:36	General View	 Load JPG	<input checked="" type="checkbox"/>
39	10/05/18 19:36	General View	 Load JPG	<input checked="" type="checkbox"/>
40	10/05/18 19:36	General View	 Load JPG	<input checked="" type="checkbox"/>
41	10/05/18 19:36	General View	 Load JPG	<input checked="" type="checkbox"/>
42	10/05/18 19:36	General View	 Load JPG	<input checked="" type="checkbox"/>
43	10/05/18 19:36	General View	 Load JPG	<input checked="" type="checkbox"/>
44	10/05/18 19:36	General View	 Load JPG	<input checked="" type="checkbox"/>
45	10/05/18 19:36	General View	 Load JPG	<input checked="" type="checkbox"/>
46	10/05/18 19:36	General View	 Load JPG	<input checked="" type="checkbox"/>
47	10/05/18 19:36	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
48	10/05/18 19:36	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
49	10/05/18 19:36	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
50	10/05/18 19:36	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
51	10/05/18 19:36	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
52	10/05/18 19:36	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
53	10/05/18 19:36	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
54	10/05/18 19:36	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
55	10/05/18 19:36	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
56	10/05/18 19:36	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
57	10/05/18 19:36	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
58	10/05/18 19:36	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
59	10/05/18 19:36	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
60	10/05/18 19:36	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
61	10/05/18 19:36	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
62	10/05/18 19:36	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
63	10/05/18 19:36	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
64	10/05/18 19:36	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
65	10/05/18 19:36	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
66	10/05/18 19:36	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
67	10/05/18 19:36	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
68	10/05/18 19:36	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
69	10/05/18 19:36	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
70	10/05/18 19:36	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
71	10/05/18 19:36	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
72	10/05/18 19:36	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
73	10/05/18 19:36	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
74	10/05/18 19:36	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
75	10/05/18 19:36	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
76	10/05/18 19:36	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
77	10/05/18 19:36	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
78	10/05/18 19:36	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
79	10/05/18 19:36	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
80	10/05/18 19:36	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>

Letters/Correspondences			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
81	10/05/18 19:36	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
82	10/05/18 19:36	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
83	10/05/18 19:36	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
84	10/05/18 19:36	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
85	10/05/18 19:36	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
86	10/05/18 19:36	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
87	10/05/18 19:36	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
88	10/05/18 19:36	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
89	10/05/18 19:36	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
90	10/05/18 19:36	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
91	10/05/18 19:36	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>

Documentation			1 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	21/03/18 17:44	TP GIA REPORT	 Load PDF	
2	18/01/19 08:25	WORKSHOP INVOICE	 Load PDF	
3	18/01/19 08:25	AUTHORISATION TO ACT FORM	 Load PDF	
4	18/01/19 08:25	Release Voucher	 Load PDF	
5	18/01/19 08:25	RENTAL RECEIPT	 Load PDF	
6	18/01/19 08:25	LTA SEARCH	 Load PDF	
7	18/01/19 08:25	LETTER TO OI	 Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ) <div style="border: 1px solid black; height: 40px; margin-top: 5px;"></div>			
Show Remarks To: <input type="checkbox"/> Handling Insurer <small>Note: Remarks are private unless you show it to other parties.</small>			

NOTE: TO BE COMPLETED BY SURVEYOR

TEAM _____

**THIRD PARTY EXPRESS SETTLEMENT
(PAYMENT BREAKDOWN)**

Vehicle No:	SLF5368H (Insd veh)	Model:	TOYOTA COROLLA ALTIS 1.6 (A)
	SJK9448G (TP veh)		
Date of Accident:	18/03/2018		

Global Sum Settlement	:	<input checked="" type="checkbox"/> Yes	<input type="checkbox"/> No
Repair Estimate	: \$		12,964.75
Final Repair Cost	: \$		7,000.00
Loss of Use	: \$		_____ days at \$0.00 per day
Rental (if any)	: \$		2 days
LTA / GIA Search Fee	: \$		
Others:	: \$		
	: \$		
Final Settlement Sum (Global Sum)	: \$		7,000.00

Is Third Party Workshop GIA Registered? YES NO (Kindly indicate below)

A) For Non GIA Registered Workshop: Agreed Liability ___ 100 ___ (%)

B) For GIA Registered Workshop: BOLA Applicable: Yes/ No BOLA Scenario No: _____

BOLA Liability: _____ (%) Assessed Liability (*): _____ (%)

** Assessed Liability to be filled only for chain collisions and for cases where BOLA does not apply.*

Remarks _____

Payment Instruction: Payee's Breakdown		
1)	Hua Meng Spray Painting Workshop	: \$ 7,000.00
2)		: \$
3)		: \$

JOANNE LEE KHANG MIN

LKK Auto Consultants Pte Ltd

18 Jan
2019

Date

Please attach all the supporting documents to the form.
(Final Repair Bill; Rental Invoice; Release Voucher; Authorisation to Act; Survey Report; Medical Report/ Bill (if any))

LKK Auto Consultants Pte Ltd

(Co. Reg. No: 199607198R)
51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC6/LCR18005262/AJB3Q2
Date: 18/01/2019

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	0999994780
Claimant Vehicle No : SJK9448G	Insured Vehicle No :	SLF5368H
Date of Loss: 18/03/2018	Nature of Claim:	TP
		Claim No: 8907489638SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SJK9448G	Engine No:	3ZZ4798261
Make & Model:	TOYOTA COROLLA ALTIS, 1.6 (A)	Chassis No:	MR053ZEE106119238
Reg. Date:	11/11/2008 (Man. Year: 2008)	Odometer:	192506 km
Colour:	Gold		
Engine Capacity:	1598 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	195/65 R15	Rear Tyre Size:	195/65 R15
Front Left Side:	Bridgestone 6 mm	Rear Left Side:	Bridgestone 6 mm
Front Right Side:	Bridgestone 6 mm	Rear Right Side:	Bridgestone 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	8,914.75	5,957.25	2,957.50	33.18
Miscellaneous Items	0.00	0.00	0.00	
Labour	4,050.00	2,620.00	1,430.00	35.31
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	12,964.75	8,577.25	4,387.50	33.84
Approved Total (Overridden) (S\$)		6,800.00		
Nett Amount (S\$)	12,964.75	6,800.00	6,164.75	47.55
+ Car Rental (2.0 x S\$100.00/day) (S\$)		200.00		
+ Doc/Search Fee (S\$)		7.45		
Nett Liability (S\$)		7,007.45		
Global Sum Settlement (S\$)		7,000.00		

INSPECTION

Date of Assignment:	20/03/2018	
Date Inspected:	20/03/2018 Inspected At:	Hua Meng Spray Painting Workshop (HQ) No 1 Kaki Bukit Avenue 6, #01-61 Autobay@Kaki Bukit Singapore 417883

Estimated Period of Repair: 6.0 days

Adjuster: ADRIAN LING

Manager: Joy Irene Bascao

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR WINDSCREEN RUBBER	Necessary	53.80 FL	*53.80 FL
2	1		*REAR RH FENDER	Distorted	758.20 FL	*758.20 FL
3	1		*REAR RH DOOR	Distorted	858.80 FL	*858.80 FL
4	1		*REAR RH DOOR PROTECTOR	Distorted	92.00 FL	*92.00 FL
5	1		*REAR RH DOOR GLASS OUTER MOULDING	Not Necessary	124.50 FL	*- FL
6	1		*REAR RH DOOR OUTER HANDLE	Not Necessary	68.10 FL	*- FL
7	1		*REAR RH DOOR TOP HINGE	Not Necessary	91.10 FL	*- FL
8	1		*REAR RH DOOR LOWER HINGE	Not Necessary	91.10 FL	*- FL
9	1		*REAR RH DOOR STOPPER	Not Necessary	161.40 FL	*- FL
10	1		*REAR RH DOOR WEATHER STRIP	Necessary	145.90 FL	*145.90 FL
11	1		*REAR RH DOOR INNER BOARD	Cracked	623.80 FL	*623.80 FL
12	1		*REAR RH DOOR POWER WINDOW MOTOR	Damaged	583.90 FL	*583.90 FL
13	1		*REAR RH DOOR POWER WINDOW REGULATOR	Damaged	214.30 FL	*214.30 FL
14	1		*SET REAR RH DOOR FRAME BLACK STICKER	Necessary	70.70 FL	*70.70 FL
15	1		*FRONT RH DOOR	Distorted	970.10 FL	*970.10 FL
16	1		*FRONT RH DOOR PROTECTOR	Deformed	138.30 FL	*138.30 FL
17	1		*FRONT RH DOOR GLASS OUTER MOULDING	Not Necessary	132.30 FL	*- FL
18	1		*FRONT RH DOOR OUTER HANDLE	Not Necessary	68.90 FL	*- FL
19	1		*FRONT RH DOOR TOP HINGE	Not Necessary	91.10 FL	*- FL
20	1		*FRONT RH DOOR LOWER HINGE	Not Necessary	91.10 FL	*- FL
21	1		*FRONT RH DOOR STOPPER	Not Necessary	152.00 FL	*- FL
22	1		*FRONT RH DOOR WEATHERSTRIP STRIP	Necessary	173.50 FL	*173.50 FL
23	1		*FRONT RH DOOR INNER BOARD	Cracked	840.20 FL	*680.30 FL
24	1		*FRONT RH DOOR POWER WINDOW MOTOR	Not Necessary	839.40 FL	*- FL
25	1		*FRONT RH DOOR POWER WINDOW REGULATOR	Damaged	236.60 FL	*236.60 FL
26	1		*SET FRONT RH DOOR FRAME BLACK STICKER	Necessary	68.10 FL	*68.10 FL
27	1		*FRONT RH DOOR SIDE MIRROR	Not Necessary	558.10 FL	*- FL
28	1		*FRONT RH DOOR INNER LOCK	Damaged	480.90 FL	*480.90 FL
29	1		*REAR RH DOOR INNER LOCK	Damaged	433.10 FL	*433.10 FL
30	1		*RH DOOR CENTRE PILLAR	Repair	381.00 FL	*- FL
31	1		*RH ROCKER PANEL	Repair	0.00 FL	*- FL
32	1		*RH ROCKER PANEL GARNISH	Deformed	720.70 FL	*720.70 FL
33	1		*REAR RH SPORT RIM	Cut	800.00 FS	*480.00 FS
34	1		*REAR RH TYRE	Not Necessary	380.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (S\$)	11,493.00	7,783.00
- List Item Discount on L Items 25.00/25.00% (S\$)	2,578.25	1,825.75
Total Parts (S\$)	8,914.75	5,957.25

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO SUPPLY REAR WINDSCREEN SEALANT	New	50.00	50.00
2	REMOVE & REINSTALL DOOR FITTING	New	200.00	160.00
3	REMOVE & REINSTALL ROOF LINING & CUSHION	New	200.00	50.00
4	REMOVE & REINSTALL REAR WINDSCREEN	New	150.00	120.00
5	REMOVE, REPLACE & REPAIR CONSISTENT TO THE ACCIDENT	New	1,800.00	1,200.00
6	RESPRAY PAINTING	New	1,500.00	1,000.00
7	TUFF KOTE	New	150.00	40.00
Gross Labour Cost (S\$)			4,050.00	2,620.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >