

ASS. REC. BY

REP

CS/FCI 18005280/ D-103

Special Instructions

Surveyor  
CWSBryan  
Eileen Lee

ASSIGNMENT (Office)

From (Person)

of

FCI

Date/Time

20/3/18 @ 3:36pm

Estimated Cost

Bill to

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No.

SLG 301

Insured:

SHD 4868X

at Workshop m/s

volks wagen centre

Tel:

93867833

of

1 kampong Ampat

Policy No.

Claim No:

D18002274 MFSH

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A. 17/03/18

CA / REV / REP. / REV 24 HRS

'up'

R.O.D. Endorsement

Date/Time:

9:57am @ 21/03/18

Person Contacted:

Shu Shi

Vehicle IN/OUT

Date/Time

Action/Instruction (✓) Estimate

SLG 301 - CS/CTI 17006289 / T/Ham2

D.O.A. 26/3/17

SHD 4868X - CS/TMI 17017268 / K/vbn2

D.O.A. 5/9/2017

REF: FCI

## ASSIGNMENT SLG 30J

From Date: 23/03/18

Veh No: SLG 30J

Yr Regn: 2016 April

Estimated Cost:

Type: Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

Truck / Trailer or

To Inspect Vehicle No: SLG 30J

Make: Volkswagen Jetta cc: 1390

at Workshop m/s: volkswagen

Colour: white A/C Insured / Std / NI / NA

of 1 Kampong Ampat (Maepherson)

Sp Reading: 47882 T/Radio: Insured / Std / NI / NA

Insured:

Eng/No: CAXF75034

Policy No:

C/No: WVW222162FM050769

Claims No:

Gen. Cond: Good / Fair / Poor / Burnt

Sum Insured:

Excess:

Steering: In order / Jammed / Leaked / Burnt or

(Client's Record)

11 am

Brake: In order / Jammed / Leaked / Burnt or

Make of Veh:

Modi: Nil / STD A/Rim or

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

Tyre Size: F: 225/45 R17

R: ———

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI / TOYO / YOKO or Continental

Bal. or Market Value:

Front

Rear

IDAC Accident Report: Consistent? : Yes or No

R/Bal: 6 mm

R/Bal: 6 mm

GIA / FR Seen: Consistent? : Yes or No

L/Bal: 6 mm

L/Bal: 6 mm

Est. Repairs: 4 days Res: Yes or No

D.O.A: 17/03/2018

D.O.I: 23/03/2018

Lum Sum: 717 % 3 Val: Yes or No

Survey held at Volkswagen .Kg Ampat

CA / REV / REP. / 24 HRS 1 up

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

O/S Front

Date: Person Contacted:

Vehicle: IN / OUT

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

FCI SHIP 4868X

10/04/18 Jinnam 717 6145.87  
(Red. 6724.33 : 52%)

-it 4 days 7 2

RECEIVED 11 APR 2018

Date/Time: File Pass to:

☐ : Preli. Report

Days Of Repair: 4

11/4 Typist

☒ : Final Report

Resurvey No. of Trip: 1

Date/Time: File Return to:

Survey Fee:

Transportation:

3.3 - P.C. 0

Priced

Costed

Total

Add Fee: ☐ Site Insp: \$☐ Interview: \$☐ Tech. Insp: \$☐ Workshop: \$

Report Format: TP

Lump Sum / (B): \$ 6145.87

275-30

170+30
50
50
30
320

### MOTOR SURVEY ASSIGNMENT

<b>Date</b>	20-03-2018	<b>Our Ref No.</b> D18002274MFSH
<b>Accident Date</b>	17-03-2018	<b>Claim Type.</b> Third Party
<b>Insured Vehicle</b>	SHD4868X	<b>Third Party Vehicle.</b> SLG30J
<b>Survey Location</b>	1 KAMPONG AMPAT	
<b>Contact Person.</b>	TANG SHU SHI	
<b>Contact No.</b>	69223502/ 93867833	<b>Fax No.</b> 62858620
<b>Survey Type</b>	DIRECT SETTLEMENT:	
<b>Appointed Surveyor</b>	LKK AUTO CONSULTANTS PTE LTD	
<b>Contact Person</b>	NA	<b>Fax No.</b> 68416315
<b>Contact Number.</b>	NA	

### FOR DIRECT SETTLEMENT

Please submit to us the Tax Invoice together with letter of claim for Rental OR Loss of use (based on NIMA Benchmark rates) together with your survey report.

### THIRD PARTY SURVEY REQUEST

<b>Cc : Workshop</b>	VOLKSWAGEN CENTRE SINGAPORE	<b>Attention.</b> NIL
<b>Cc : TP Solicitor</b>	NA	<b>TP Solicitor Fax No.</b> NA
<b>Officer Incharge</b>	EILEEN LEE	

### IMPORTANT NOTE

Kindly submit the survey report via CWS within 14 days for survey assignment and 7 days for re-inspection.  
 This is a computer generated letter, no signature required.

Job Sheet (/ClaimWS/Surveyor/JobSheet/236148)



PRI Documents



Close



## PRI Header Details

Claim No	D18002274MFSH	Policy No	D-18088936MFSH	Claimant S.No & Name	1 & VOLKSWA
Workshop Name	VOLKSWAGEN CENTRE SINGAPORE (Contact Person : TANG SHU SHI)	Survey Location & Contact Details	1 KAMPONG AMPAT Mobile: 93867833 , Phone: 69223502 , Fax: 62858621 EmailId: SHUSHI.TANG@VW.COM.SG		
Our Surveyor	LKK AUTO CONSULTANTS PTE LTD	Instructions To Surveyor	DIRECT SETTLEMENT:		
Insured Name	COMFORT TRANSPORTATION PTE LTD	Insured Vehicle No	SHD4868X	TP Vehicle No	SLG30J
PRI Recieved Date	20-03-2018 03:50:30 PM	Surveyor Appointed Date	20-03-2018 03:35:26 PM	Surveyor Accept Date	21-03-2018 0

## Survey Report Upload

Surveyor Inspection Date *:	<input type="text"/>	Surveyor Report Date	21-03-2018	Upload Survey Report *:	<input type="button" value="Choose File"/>
-----------------------------	----------------------	----------------------	------------	-------------------------	--

## Vehicle Particulars

Make	<input type="text" value="Please Select Make"/>	Model	<input type="text" value="Please Select Model"/>	Year	<input type="text" value="Select Year"/>
Chasis No	<input type="text"/>	Engine No	<input type="text"/>	Mileage	<input type="text"/>
Color	<input type="text"/>	Cubic Capacity	<input type="text"/>		

## Multiple Documents Upload

File Name

Action

## Surveyor Job Remarks

Remarks



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
FIRST CAPITAL INSURANCE LTD		Ref : CS/FC118005280/Dtd3		
36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877		Date : 21-03-2018		
		Code : FCI2		
<b>1. Policy Particulars :- THIRD PARTY CLAIM</b>				
Insured Veh.	SHD 4868X	Veh. Inspected	SLG 30J	
Policy No.		Coverage (\$)	0.00	
Claim No.	D18002274MFSH	Excess (\$)	0.00	
Assign From	CWS (EILEEN LEE)	Assign Date	21/03/2018	
<b>2. Vehicle Particulars &amp; Condition</b>				
Make & Model		c.c	0	
Engine No.	HIDDEN	Year of Reg.		
Chassis No.		Colour		
Odometer	-	Steering		
Brakes		Modification		
General				
<b>3. Conditions of Tyres</b>				
	Size	Make	Balance	
R/H Front Tyre			mm	
L/H Front Tyre			mm	
R/H Rear Tyre			mm	
L/H Rear Tyre			mm	
<b>4. Description of Damages</b>				
<b>5. General Information</b>				
Accident Date	17/03/2018	Inspection Date		
Survey held at	PERFORMANCE MOTORS LTD 303 ALEXANDRA ROAD SINGAPORE 159941			
<b>5a. Remarks</b>				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				

## SINGAPORE ACCIDENT STATEMENT

### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

### ACCIDENT STATEMENT

Date Of Report	19/03/2018 10:42
Date Of Accident	17/03/2018 10:40
Exact Location Of Accident	CARPARK ALONG KANDAHAR STREET
Country/State of Loss	SINGAPORE

### DETAILS OF OWN VEHICLE

Vehicle Registration Number	SLG30J
<b>Insured/Policyholder</b>	
Name Of Registered Owner	VICTOR KUAH CHUAN CHEE
NRIC No	S8930121A
Email Address	VICTOR@TECKCHEONG.COM
Mobile Phone No	(LOCAL) +65-94230969
Alternative Phone No	OFFICE-94230969

### Vehicle Particulars

Manufacturer	VOLKSWAGEN
Model	JETTA TSI (DSG) SPORTLINE HIDS
Exact Purpose for which vehicle was being used at time of accident	PRIVATE
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR

### Insurance Company

Name of Insurance Company	MSIG INSURANCE (SINGAPORE) PTE. LTD.
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	A 28736267 AVW
Cover Note Number	

### Driver

Name of Driver	VICTOR KUAH CHUAN CHEE
NRIC No	S8930121A
Date Of Birth	31/08/1989
Occupation	INDOOR
Date Of Driving Pass	11/02/2010
Driving Experience	8 YEARS AND 1 MONTH
Gender	MALE
Mobile Number	(LOCAL) +65-94230969
Fax Number	
Contact Number	OFFICE-94230969
Email Address	VICTOR@TECKCHEONG.COM

Address	BLK 808 THOMASON ROAD #16-19
Postcode	298190
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OWNER
Vehicle Registration Number of Driver's Own Vehicle	- - -
Insurance Company of Driver's Own Vehicle	- - -

#### General Information of the Accident

Type Of Accident	HIT AND RUN / VANDALISM / DAMAGED WHILST PARKED
Weather Conditions	CLEAR
Road Surface	DRY

#### Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles involved in the accident	
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	0

#### Details of Police Action

Was the accident reported to the police?	YES
If Yes, Please state which Police Station	
Police Station Name	KOLAM AYER NEIGHBOURHOOD POLICE POST
Police Station Address	ROAD: BLK 72 GEYLANG BAHRU #01-3038 , POSTCODE: 330072 , COUNTRY: SINGAPORE
Police Station Contact	TEL NO: 1800-2969999 - FAX NO: 62937659
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

#### Circumstances of Accident

REFER TO POLICE REPORT

#### Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

#### Details of Witness 1

Name	NAFISAH
Phone Number	97719207
Email Address	

#### DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SHD4868X
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	TAXI
Name of Driver	
NRIC/Passport Number	
Contact Number	

Address

Postcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)



**SKETCH PLAN**

**IMPORTANT NOTICE**

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:


- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
  - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
  - (ii) investigating the accident and/or my claims;
  - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
  - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
  - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims. (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
  - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
  - (ii) for complying with requirements under any regulations, laws or court orders.

\_\_\_\_\_  
Policyholder's Signature  
Date & Time:

\_\_\_\_\_  
Driver's Signature  
(if driver is not the policyholder)  
Date & Time:

\_\_\_\_\_  
Reporting Centre Personnel's Signature  
Name: **87030002**  
NRIC/FIN No.:  
 19/3/18

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

MY VEHICLE WAS PARKED along KENDALAN STREET & a taxi came to park in a lot in front of my vehicle I was not present at the time of the accident but there was a witness that left a note saying that my vehicle was hit. It was at 1040hrs when the accident occurred and she was not sure about the last alphabet of the car but got his number plate.

Witness: 9771 9207.

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature  
Date & Time:

Driver's Signature  
(if driver is not the policyholder)  
Date & Time:



9/3/18.

Reporting Center Personnel's Signature



**SINGAPORE  
POLICE FORCE**



T/20180317/2048

1 of 3

Police Station Of Origin:  
Kolam Ayer NPP  
72 Geylang Bahru #01-3038 SINGAPORE  
330072  
Tel No: 1800-2969999

Report No. T/20180317/2048

**REPORT OF A TRAFFIC ACCIDENT**

Date/Time Report Made: 17/03/2018 12:25		Vide Report No.:		Station Diary No.: 11	
<b>Informant's Particulars</b>					
Name of Informant: VICTOR KUAH CHUAN CHEE			Address: BLK 808 THOMSON ROAD #16-19 SINGAPORE 298190		
ID Type / ID No.: NRIC NO / S8930121A			Contact No.: Home/Office: Mobile: 94230969		
Nationality: SINGAPORE CITIZEN			Email:		
Sex: Male	Age: 28	Date of Birth: 31/08/1989	Type of Informant: Vehicle Owner		
Race: Chinese			Language:		Institution / School Name:
Occupation: SELF EMPLOYED			Driving Licence Information: Class: 3 Date of Expiry:		

**General Information of the Accident**

Type of Accident:	Non-Injury Hit and Run	Drink Drive: No	Date/Time of Accident: 17/03/2018 10:40	Type of Location: Straight Road
Location: Along Road 1 KANDAHAR STREET				
parked at lot along Kandahar Street, carpark code no. K0005				
Weather: Clear		Road Surface: Dry		Road Speed Limit:
Traffic Flow:		Traffic Control: Not Controlled		Traffic Volume: Moderate
Type of Collision: Moving Vehicle Against - Parked Vehicle				Anyone conveyed by ambulance: No

**Details of Vehicle Involved**

Vehicle No.	Type	Make	Model	Color	Condition	No of Passenger
SHD4868J (Not Accurate)	Taxi			Blue		0
SLG30J	Car	VOLKSWAGO N	JETTA 1.4 TSI 1633G5 HID SR NAV	White	Slightly Damaged	0

**Details of Person Involved**

Any Pedestrian Involved: No	
No. of Pedestrians Injured: NIL	Use of Pedestrian Crossing: NA



**SINGAPORE  
POLICE FORCE**



T/20180317/2048

2 of 3

Police Station Of Origin:  
Kolam Ayer NPP  
72 Geylang Bahru #01-3038 SINGAPORE  
330072  
Tel No: 1800-2969999

Report No. T/20180317/2048

## CONTINUATION OF REPORT

<b>Vehicle Owner</b>			
Name	VICTOR KUAH CHUAN CHEE	ID No.	S8930121A
Related Vehicle	SLG30J (Car)	Contact No.	94230969
Hospital/Clinic	NIL	Class of Driving Licence & Expiry Date	Class: 3 Date of Expiry: NIL
Date Treatment	NIL	Date Discharge	NIL
No. of Days granted Medical Leave	NIL	Degree of Injury	NIL
<b>Driver</b>			
Name	QUAH LAY TING	ID No.	S1454394E
Related Vehicle	SLG30J (Car)	Contact No.	96259650
Hospital/Clinic	NIL	Class of Driving Licence & Expiry Date	Class: 3 Date of Expiry: NIL
Date Treatment	NIL	Date Discharge	NIL
No. of Days granted Medical Leave	NIL	Degree of Injury	NIL

**Brief Details.**

On 17 March 2018 my mother namely Quah Lay Ting had borrowed my vehicle bearing the plate number of SLG 30J as she wanted to go shopping. At about 1040hrs, she had parked the vehicle at a parallel parking lot along Kandahar Street and went for shopping.

At about 1050hrs, when she got back to the vehicle she realized there was a yellow note on the front windscreen of the vehicle. As she read it, the note stated "taxi (blue) SHD 4868J, we witnessed this taxi hit the front right of your car and he drove off. Contact: Nafisah 97719207". My mother immediately made a check and realized that the vehicle front right side bumper and front right headlight had suffered slight damages. She then called me to inform the matter.

At about 1100hrs I called the witness namely Nafisah to enquire about the incident. She then told me she saw a blue taxi whom was trying to squeeze and park at a parallel lot in front of my vehicle. While reversing, the taxi had collided onto my vehicle which caused a loud impact. Upon knowing that he had collided onto the vehicle, he then left the said location. The witness also informed she had only remember the taxi vehicle number as SHD 4868J however she is unsure of the last alphabet of the taxi.



**SINGAPORE  
POLICE FORCE**



T/20180317/2048

Police Station Of Origin:  
Kolam Ayer NPP  
72 Geylang Bahru #01-3038 SINGAPORE  
330072  
Tel No: 1800-2969999

3 of 3

Report No. T/20180317/2048

CONTINUATION OF REPORT

**Sketch Plan**

Informant is not able to provide sketch plan

IMPORTANT: Please attach a copy of your vehicle's Insurance Certificate to this report. If you don't have the certificate with you now, please fax a copy to 65474885 stating the **report number** as reference.

Signature Of Officer Recording The Report:

A /

Sgt 1 MOHAMED FEROUZ S/O MOHAMED  
IQBAL

Signature Of Informant:

Signature Of Interpreter:

Not applicable

Date/Time:

17/03/2018 12:25

Officer In Charge Of Case:

TP / HRT /

SI TAN LEE HWANG DAWN

Contact No.: 65476215

Classification Of Case:

Authentication Stamp



Police Force

Taxi (Blue)  
SHD 4868 J

We witnessed this taxi  
hit the front right of your  
car and he drove off  
Contact: Nafisah 97719207

IDENTITY CARD NO. S8930121A



Name  
VICTOR KUAH CHUAN CHEE  
(KE QUANZHI)  
柯全志

Race  
CHINESE

Date of birth  
31-08-1989

Sex  
M

Country/Place of birth  
SINGAPORE



S8930121A

License Number: S8930121A

Holder  
VICTOR KUAH CHUAN CHEE  
(KE QUANZHI)

Birth Date: 31 Aug 1989

Issue Date: 11 Feb 2010



001830006J

5280714



NRIC No. S8930121A



Date of issue  
27-02-2014

BLK 808 THOMSON ROAD #18-19  
SINGAPORE 298190

NRIC No: S8930121A Date: 03/01/2018

YOU ARE LICENSED TO DRIVE VEHICLES IN THE FOLLOWING CLASS:

PASS DATE

Class 3 Motor Cars < 3000kg with < 7 passengers, exclusive of the driver; and other motor vehicles < 2500kg 11 Feb 2010



UP 425A

License No: S8930121A





**MSIG**

**\*MSIG Insurance (Singapore) Pte. Ltd.**  
4 Shenton Way, # 21-01, SGX Centre 2, Singapore 068807  
Tel +65 6827 7888, Fax +65 6827 7800  
Co. Reg. No. 200412212G GST Reg. No. 20-0412212G

## Certificate of Insurance

ROAD TRANSPORT ACT 1987 (MALAYSIA)  
THE MOTOR VEHICLES (THIRD-PARTY RISKS) RULES, 1959 (FEDERATION OF MALAYSIA)  
THE MOTOR VEHICLES (THIRD-PARTY RISKS AND COMPENSATION) ACT (CAP. 189 OF THE REVISED EDITION)  
(REPUBLIC OF SINGAPORE)  
THE MOTOR VEHICLES (THIRD-PARTY RISK AND COMPENSATION) RULES, 1996 EDITION (REPUBLIC OF SINGAPORE)  
OR ANY AMENDMENT, ACT OR ACTS PASSED IN SUBSTITUTION THEREOF.

Form M.X.1  
Individual Ownership

**VW DRIVEEASY**  
**Comprehensive**

**Certificate No.** A 28736267 AVW

**Excess :** SGD500

**Windscreen Excess :** SGD100

**1. Index Mark and Registration Number of Vehicle**

SLG30J

**2. Name of Policyholder**

Kuah Chuan Chee Victor

**3. Effective Date of the Commencement of Insurance for the purposes of the Act**

29/04/2017

**4. Date of Expiry of Insurance**

28/04/2018

**5. Persons or Classes of Persons entitled to drive\***

Kuah Chuan Chee Victor  
Geoffrey Kuah Chuan Aik  
Ng Ru Yin

Any other person provided he is driving on the Policyholder's order or with the Policyholder's permission.

\* Provided that the person driving is permitted in accordance with the licensing or other laws or laws or regulations to drive the Motor Vehicle or has been so permitted and is not disqualified by order of a Court of Law or by reason of any enactment or regulation in that behalf from driving the Motor Vehicle.

**6. Limitations as to use\***

Use only for social domestic and pleasure purposes and for the Policyholder's business.  
The Policy does not cover use for hire or reward racing pace-making reliability trial speed-testing the carriage of goods other than samples in connection with any trade or business or use for any purpose in connection with the Motor Trade.

\* Limitations rendered inoperative by Section 8 of the Motor Vehicles (Third-Party Risks and Compensation) Act (Chapter 189) and Section 95 of the Road Transport Act, 1987 (Malaysia), are not to be included under these headings.

**PLEASE NOTE ALL CLAIMS RELATED REPAIR MUST BE CARRIED OUT AT VOLKSWAGEN CENTRE SINGAPORE.**

This Certificate is not transferable to a new owner of the vehicle. If for any reason the Policy is terminated during its currency, the Certificate must be returned to the Insurer within 7 days of the termination or if the Certificate has been lost or destroyed, a Statutory Declaration to that effect must be made. Failure to comply with this obligation is an offence under the Motor Vehicles (Third-Party Risks and Compensation) Act (Cap. 189).

I/WE HEREBY CERTIFY that the Policy to which this Certificate relates is issued in accordance with the provisions of the Motor Vehicles (Third-Party Risks and Compensation) Act (Chapter 189) and Part IV of the Road Transport Act, 1987 (Malaysia) or any Amendment, Act or Acts passed in substitution thereof.

**MSIG Insurance (Singapore) Pte. Ltd.**  
Approved Insurers

for Chief Executive Officer



**LIST ITEMS**

<u>PAY</u>	<u>UNPAID</u>
2.07	26.96
738.40	599.44
955.40	39.23
	4418.70

**NETT ITEMS**

<u>PAY</u>	<u>UNPAID</u>
------------	---------------

**LABOUR**

<u>PAY</u>	<u>UNPAID</u>
1680.00	840.00
1600.00	800.00
360.00	
480.00	
280.00	
50.00	

0.00

0.00

1695.87

5084.33

4450.00

1640.00

6780.20

0.00

6090.00

1695.87

0.00

4450.00

5084.33

0.00

1640.00

0.00

0.00 (25% DISC )

0.00

1695.87 LIST ITEM (PAY)

4450.00 LABOUR (PAY)

---

6145.87

---

26.96

}

CHECK ITEM

0.00 (25% DISC )

0.00 LIST ITEM AFTER DISC (CHECK ITEM)

0.00 LABOUR (CHECK ITEM)

---

26.96

---

*List item (check item)*

TOTAL = 6172.83 (PAY ITEM + CHECK ITEM )

PDI TUAS

PDI TUAS

VICTOR KUAH CHUAN CHEE  
(KE QUANZHI)  
14 LENTOR GROVE  
Singapore, 789188  
Singapore

Phone No.  
Fax No.  
E-Mail

VAT Registration No. M20098505-2  
Tax No. 199101494Z

## Service Quote

Customer No. CV033574  
Quote No. SER/QUO/1800466  
QuoteDate 19/03/18  
Salesperson Delsie Ong  
Page 1

THIS IS NOT AN OFFICIAL TAX INVOICE

Make	Model Description	Mileage	Service Advisor
Volkswagen Passeng	JETTA TSI (DSG) SPORTLINE HIDS	43,943	Tang Shu Shi
License No.	VIN	Initial Registration	Sales Advisor
SLG30J	WVWZZZ16ZFM050769	29/04/16	Delsie Ong
Engine Code	Labor Type	Engine No.	Model Code
	M4	CAX F75034	1633G5

No.	Description	Qty.	UoM	Unit Price	Amount
P B&P MACP LABOUR	LABOUR	3	UNIT		1680/- 2,520.00
P B&P MACP PAINT	SPRAY PAINT	3	UNIT		1600/- 2,400.00
P B&P WHEEL ALIGNMENT	B&P WHEEL ALIGNMENT -NETT	1			360.00 ✓
P B&P DIAG	PROGRAMMING & CALIBRATION COMPULSORY TO DO AFTER AC	1	Time Un		480.00 ✓
P B&P MECH	ELECT WIRING & MECH COMPO	1	Time Un		280.00 ✓
P B&P MECH	Nett				
P B&P MECH	R&R RIM & BALANCE	1	Time Un	4450/-	50.00 ✓
	Nett				
	<b>Sum Labor</b>				<b>6,090.00</b>
P 839601361	TIRE VALVE	1	Pieces		2.07 ✓
P 5C6807184A	RHF BUMPER BRACKET	1	Pieces		26.96 ✓
P 5C6807217Q GRU	FRT BUMPER	1	Pieces		738.40 ✓
P 5C6821106A	RHF FENDER	1	Pieces		599.44 ✓
	Use Predecessor 5C6821106				
P 5C6821136	RHF FENDER BRACKET	1	Pieces		39.23 ✓
P 5C8941752B	RH HEADLIGHT	1	Pieces	1695.87	4,418.70 ✓
	Use Predecessor 5C8941752A				
P 5K0073147C 88Z	ALLOY WHEELS 17" SILEX	1	Pieces		955.40 ✓
	<b>Sum carried forward</b>				<b>12,870.20</b>

Payments to: - BBN: - Acc.-No.:

## PDI TUAS

PDI TUAS

VICTOR KUAH CHUAN CHEE  
(KE QUANZHI)  
14 LENTOR GROVE  
Singapore, 789188  
Singapore

Phone No.  
Fax No.  
E-Mail

VAT Registration No. M20098505-2  
Tax No. 199101494Z

## Service Quote

Customer No. CV033574  
Quote No. SER/QUO/1800466  
QuoteDate 19/03/18  
Salesperson Delsie Ong  
Page 2

THIS IS NOT AN OFFICIAL TAX INVOICE

Make	Model Description	Mileage	Service Advisor
Volkswagen Passeng	JETTA TSI (DSG) SPORTLINE HIDS	43,943	Tang Shu Shi
License No.	VIN	Initial Registration	Sales Advisor
SLG30J	WVWZZZ16ZFM050769	29/04/16	Delsie Ong
Engine Code	Labor Type	Engine No.	Model Code
	M4	CAX F75034	1633G5
Continued			12,870.20
Sum Item			6,780.20
Sum Labor			6,090.00
Sum Item			6,780.20
Total SGD			12,870.20
7% GST			12,870.20 900.92
Total SGD Incl. GST			13,771.11

## Explanations

P = Proportionately Charged

Payment Terms No Credit

Auto Consultants hence notify the Repairer of the following:

- To resurvey before after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer  
Signature:  
Date:

Payments to: - BBN: - Acc.-No.:

23/03/2018 @ 1200pm  
Not done  
7/Part 4 dep.  
Buyer  
2kk Auto  
Photo after repair  
Photo before paint

4 (145.8)

## Service Order Confirmation

SERVICE ORDER NO.: 18IP0790

CUSTOMER NO.: CV033574

CUSTOMER NAME: VICTOR KUAH CHUAN CHEE

TELEPHONE NO.:

ADDRESS: 14 LENTOR GROVE

Singapore

**VEH No.: SLG30J**

Order Date: 23/03/18

Reg Date: 29/04/16

KM: 48,578

VIN NO.: WVVZZZ16ZFM050769

ENGINE NO:

SA: Tang Shu Shi

MODEL: JETTA TSI (DSG) SPORTLINE HI MODEL NO.: 1833Q5

No.	DESCRIPTION	QTY	UOM	UNIT PRICE	DISC %	AMOUNT
<b>Labor</b>						
1	B&P MECH ELECT WIRING & MECH COMPONENT CHECK NETT	1	TU	280		280 ✓
2	B&P DIAG PROGRAMMING & CALIBRATION- NETT	1	TU	480		480 ✓
3	B&P MECH R&R RIM & BALANCE	1	TU	50		50 ✓
4	B&P MACP LABOUR LABOUR	2	UNIT	840		1,680 ✓
5	B&P MACP PAINT SPRAY PAINT	2	UNIT	800		1,600 ✓
6	B&P WHEEL ALIGNMENT BAP WHEEL ALIGNMENT -NETT	1		360		360 ✓
7	EXT00037 Tow SVC- Quality Recovery Services	1	UNIT	0		0
8	EXT00037 Tow SVC- Quality Recovery Services	1	UNIT	0		0
<b>Item</b>						
9	5C6807217Q GRU FRT BUMPER	1	PCS	738.40		738.40 ✓
10	5K0073147C 86Z ALLOY WHEELS 17" SILEX	1	PCS	955.40		955.40 ✓
11	839601361 TIRE VALVE	1	PCS	2.07		2.07 ✓

Remarks : M5 FIRST CAPITAL DIRECT

DOA: 17/03/2018

SURVEY BY: BRYAN (LKK)

TP VEHICLE: SHD4868X

## Service Order Confirmation

SERVICE ORDER NO: 18IP0790  
CUSTOMER NO.: CV033574  
CUSTOMER NAME: VICTOR KUAH CHUAN CHEE  
TELEPHONE NO.:  
ADDRESS: 14 LENTOR GROVE  
Singapore

**VEH No.: SLG30J**

Order Date: 23/03/18  
Reg Date: 29/04/18 KM: 48,578  
VIN NO.: WYVWZZ216ZFM050769 ENGINE NO:  
MODEL: JETTA TSI (DSG) SPORTLINE HI MODEL NO.: 1633G5

SA: Tang Shu Shi

<u>No.</u>	<u>DESCRIPTION</u>	<u>QTY</u>	<u>UOM</u>	<u>UNIT PRICE</u>	<u>DISC %</u>	<u>AMOUNT</u>
------------	--------------------	------------	------------	-------------------	---------------	---------------

TOTAL	6,145.87
GST AMOUNT	439.21
TOTAL AMOUNT	6,576.08

On Behalf Of "COMPANY"

Certified Goods/Service received:

Authorized Signature

Customer

NOTE: THIS IS NOT AN OFFICIAL RECEIPT



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
FIRST CAPITAL INSURANCE LTD		Ref : CS/FCI18005280/Dtd3q2	
36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877		Date : 16-04-2018	
		Code : FCI2	
<b>1. Policy Particulars :- THIRD PARTY CLAIM</b>			
Insured Veh.	SHD 4868X	Veh. Inspected	SLG 30J
Policy No.	D-18088936MFSH	Coverage (\$)	0.00
Claim No.	D18002274MFSH	Excess (\$)	0.00
Assign From	EILEEN LEE	Assign Date	20/03/2018
<b>2. Vehicle Particulars &amp; Condition</b>			
Make & Model	VOLKSWAGEN JETTA	c.c	1390
Engine No.	HIDDEN	Year of Reg.	2016
Chassis No.	WWWZZZ16ZFM050769	Colour	WHITE
Odometer	47882	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	GOOD		
<b>3. Conditions of Tyres</b>			
	Size	Make	Balance
R/H Front Tyre	225/45 R17	CONTINENTAL	6 mm
L/H Front Tyre	225/45 R17	CONTINENTAL	6 mm
R/H Rear Tyre	225/45 R17	CONTINENTAL	6 mm
L/H Rear Tyre	225/45 R17	CONTINENTAL	6 mm
<b>4. Description of Damages</b>			
THE VEHICLE SUSTAINED DAMAGES AT THE O/S FRONT PORTION. DAMAGES SEE DETAILS.			
<b>5. General Information</b>			
Accident Date	17/03/2018	Inspection Date	23/03/2018
Survey held at	VOLKSWAGEN CENTRE SINGAPORE 1 KAMPONG AMPAT OFF MACPHERSON ROAD SINGAPORE 368314		
<b>5a. Remarks</b>			
A)DAMAGES CONSISTENT TO ACCIDENT REPORT. B)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. C)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
<b>5b. Estimate Days of Repair</b>			
ESTIMATED NORMAL PERIOD FOR REPAIR:		4 Working Days	

**LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.: 1 of 1

**ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLG 30J**

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<b><u>REPLACEMENT OF PARTS</u></b>			
1	TIRE VALVE (SN)	NECESSARY	2.07	2.07
1	RHF BUMPER BRACKET (SN)	NOT NECESSARY	26.96	-
1	FRT BUMPER (SN)	CUT	738.40	738.40
1	RHF FENDER (SN)	TO REPAIR SEE LABOUR	599.44	-
1	RHF FENDER BRACKET (SN)	SERVICEABLE	39.23	-
1	RH HEADLIGHT (SN)	TO REPAIR SEE LABOUR	4,418.70	-
1	ALLOY WHEELS 17" SILEX (SN)	CUT	955.40	955.40
			6,780.20	1,695.87
	<b><u>LABOUR</u></b>			
	LABOUR INCLUSIVE OF THE REPAIR OF RHF FENDER AND RH HEADLIGHT.		2,520.00	1,680.00
	SPRAY PAINT.		2,400.00	1,600.00
	B&P WHEEL ALIGNMENT.		360.00	360.00
	PROGRAMMING & CALIBRATION COMPULSORY TO DO AFTER AC.		480.00	480.00
	ELECT WIRING & MECH COMPO.		280.00	280.00
	R&R RIM & BALANCE.		50.00	50.00
			6,090.00	4,450.00
	<b>GRAND TOTAL</b>		<b>12,870.20</b>	<b>6,145.87</b>
	<b>RECOMMENDED COST OF REPAIRS</b>			<b>6,145.87</b>

Report Ref No. CS/FCI18005280/Dtd3q2

**ANG BRYAN TANI**

Automotive Assessor / Investigator

**ADRIAN LING WAI PING**

B.Eng, AMSOE, AMIRTE, AMSAE-A, M. MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.