22/03/2002 REF: (3/6)	ATU 800 529U (TIrb nz Special Instruction:	
SUNVEYOR: Tauthon ASSIG	GNMENT (Office) Date/Time: 01032018 716am	2
To Inspect Vehicle No: XD 7877K at Workshop m/s Zenith English	Insured: 68611100	ţ.
Policy No: Sum Insured: Make of Veh:	Claim No:	
CHent's Record) CA / REV / REP. / REV 24 HRS Date/Time: 21131118 S54rd Person Co.	H543 Jln Bulat Mulich S'pur 155470 H.O.D. Endorsement: Ontacted: Azman Vehicle IN) OUT	20
Date/Time Action/Instruction () E	Estimate.	
7		9



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

			ationale Des Experts En Autor	mobile	
GF	EAT AMERICAN I	NSURANCE COMPANY	Ref : CS/GAI180052	294/T1rb	
#16	EMASEK AVENUE 3-01 CENTENNIAL IGAPORE 039190		Date: 21-03-2018 Code: GAI		
1.		Policy Particula	ars :- THIRD PARTY CLA	IM	
	Insured Veh.	GX 3173E	Veh. Inspected XD 7877K		
	Policy No.		Coverage (\$) 0.00		
	Claim No.		Excess (\$) 0.00		
	Assign From	RACHEL TAN	Assign Date 21/03/2018		
2.		Vehicle Pa	rticulars & Condition		
	Make & Model		c.c 0		
	Engine No.	HIDDEN	Year of Reg.		
	Chassis No.		Colour		
	Odometer	2	Steering		
	Brakes		Modification		
	General				
3.		Conc	ditions of Tyres		
		Size	Make	Balance	
	R/H Front Tyre		mm		
	L/H Front Tyre		mm		
	R/H Rear Tyre		mm		
	L/H Rear Tyre		mm		
1.		Descrip	otion of Damages		
5.	Engine No	Gene	ral Information		
	Accident Date	12/03/2018	Inspection Date	21/03/2018	
	Survey held at	ZENITH ENGINEERING PTE			
		NO. 34 JOO KOON CIRCLE SINGAPORE 629060			
ia.		Language Chief	Remarks		
	A)THE INSPECTION B)IN ACCORDANG	ON WAS CONDUCTED ON A"W CE TO YOUR INSTRUCTIONS,	/ITHOUT PREJUDICE" BAS WE HAVE NOT AUTHORIS	IS. ED REPAIRS.	

Catherine Chong (LKK Auto)

From:

Tan, Rachel <Rachel.Tan@sg.gaig.com>

Sent:

Wednesday, 21 March, 2018 9:16 AM

To:

mohamad.rani@sempcorp.com

Cc:

LKK Assignments

Subject:

RE: Accident Involving XD7877K and GX3173E along PIE towards Tuas near to

LP1825 on 12.03.18

Attachments:

img-320104918-0001.pdf; XD7877K_Damages Photos.pdf;

XD7877K_Quotation_Zenith.pdf; XD7877K_SAS.PDF; XD7877K_Vehicle Registration

Details.pdf; GX3173E_Insurance Enquiry.pdf

Without Prejudice

Dear Mr Azman

Thank you for taking my call. We are appointing LKK Auto Consultant to conduct survey of your vehicle. They will be in touch with you.

Dear LKK

Please accept assignment. Attached quotation for your reference.

Thank you.

Regards Rachel Tan

Executive, Motor Claims, Great American Insurance Company

Tel: 6804 7846

1137018 @ 1135cm
159470
1137018 @ 1135cm

From: Joanne Chew [mailto:joanne.chew@sembcorp.com]

Sent: Monday, March 19, 2018 11:00 PM To: ContactUs < ContactUs@GAIG.COM >

Cc: Mohamad Azman Bin Rani <mohamad.rani@sembcorp.com>

Subject: Accident Involving XD7877K and GX3173E along PIE towards Tuas near to LP1825 on 12.03.18

Importance: High

Dear Sirs

Attention: Motor Claims Department

We refer to the above matter.

We enclose our letter dated 20 March 2018 together with its enclosures for your attention.

Please contact our Fleet Management, Mr Azman at 91864590 to make the necessary arrangement to conduct a survey of our damaged vehicle within three (3) days from the date of the said letter.

Thank you.

Regards

Joanne

Joanne Chew

Senior Executive, Group Legal Legal & Compliance Sembcorp Environment Pte Ltd 30 Hill Street, #02-01 Singapore 179360

DID:67233018 FAX:6822 1882

This e-mail is confidential and may also be privileged. If you are not the intended recipient, please delete it and notify us immediately. You should not copy or use it for any purpose, nor disclose its contents to any other person. Thank you.

The content of this e-mail message and any attachments are confidential and may be legally privileged, intended solely for the addressee. If you are not the intended recipient, be advised that any use, dissemination, distribution, or copying of this e-mail is strictly prohibited. If you receive this message in error, please notify the sender immediately by reply email and destroy the message and its attachments.

Rachel Tan

Executive, Motor Claims, Great American Insurance Company

Tel: 6804 7846

From: Catherine Chong (LKK Auto) admin-d@lkkauto.com

Sent: Wednesday, March 21, 2018 11:42 AM To: Tan, Rachel < Rachel. Tan@sg.gaig.com >

Cc: 'LKK Assignments' <assignments@lkkauto.com>; 'SUR' <sur@lkkauto.com>

Subject: RE: Accident Involving XD7877K and GX3173E along PIE towards Tuas near to LP1825 on 12.03.18

Dear Rachel,

Thank you for the assignment.

Best Regards,

Catherine Chong | Admin

LKK Auto Consultants Pte Ltd

Phone: 6741-8434 | email: assignments@lkkauto.com | fax: 6256-4315 Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Tan, Rachel [mailto:Rachel.Tan@sg.gaig.com]

Sent: Wednesday, 21 March, 2018 9:16 AM

To: mohamad.rani@sempcorp.com

Cc: LKK Assignments < assignments@lkkauto.com>

Subject: RE: Accident Involving XD7877K and GX3173E along PIE towards Tuas near to LP1825 on 12.03.18

Without Prejudice

Dear Mr Azman

Thank you for taking my call. We are appointing LKK Auto Consultant to conduct survey of your vehicle. They will be in touch with you.

Dear LKK

Please accept assignment. Attached quotation for your reference.

Thank you.

Regards Rachel Tan

Executive, Motor Claims, Great American Insurance Company

Tel: 6804 7846

From: Joanne Chew [mailto:joanne.chew@sembcorp.com]

Sent: Monday, March 19, 2018 11:00 PM To: ContactUs < ContactUs@GAIG.COM >

Cc: Mohamad Azman Bin Rani <mohamad.rani@sembcorp.com>

Subject: Accident Involving XD7877K and GX3173E along PIE towards Tuas near to LP1825 on 12.03.18

Importance: High

Dear Sirs

Attention: Motor Claims Department

We refer to the above matter.

We enclose our letter dated 20 March 2018 together with its enclosures for your attention.

Please contact our Fleet Management, Mr Azman at 91864590 to make the necessary arrangement to conduct a survey of our damaged vehicle within three (3) days from the date of the said letter.

Thank you.

Regards Joanne

Joanne Chew

Senior Executive, Group Legal Legal & Compliance Sembcorp Environment Pte Ltd 30 Hill Street, #02-01 Singapore 179360 DID:67233018 FAX:6822 1882

This e-mail is confidential and may also be privileged. If you are not the intended recipient, please delete it and notify us immediately. You should not copy or use it for any purpose, nor disclose its contents to any other person. Thank you.

The content of this e-mail message and any attachments are confidential and may be legally privileged, intended solely for the addressee. If you are not the intended recipient, be advised that any use, dissemination, distribution, or copying of this e-mail is strictly prohibited. If you receive this message in error, please notify the sender immediately by reply email and destroy the message and its attachments.

The content of this e-mail message and any attachments are confidential and may be legally privileged, intended solely for the addressee. If you are not the intended recipient, be advised that any use, dissemination, distribution, or copying of this e-mail is strictly prohibited. If you receive this message in error, please notify the sender immediately by reply email and destroy the message and its attachments.

The content of this e-mail message and any attachments are confidential and may be legally privileged, intended solely for the addressee. If you are not the intended recipient, be advised that any use, dissemination, distribution, or copying of this e-mail is strictly prohibited. If you receive this message in error, please notify the sender immediately by reply email and destroy the message and its attachments.

Veron Chen (LKKAuto)

Zenith Engineering

From:

Tan, Rachel <Rachel.Tan@sg.gaig.com>

Sent:

Monday, 30 April 2018 8:59 AM

To:

Admin-D (LKKAuto); SUR

Cc:

assignments

Subject:

RE: RE: Accident Involving XD7877K and GX3173E along PIE towards Tuas near to

LP1825 on 12.03.18

HI All

Urgent.

I have not received survey report.

Sembcorp's legal office (Joanna Chew) wrote to our head office.

Regards

Rachel Tan

Executive, Motor Claims, Great American Insurance Company

Tel: 6804 7846

From: Catherine Chong (LKK Auto) <admin-d@lkkauto.com>

Sent: Monday, April 9, 2018 11:57 AM

To: Tan, Rachel <Rachel.Tan@sg.gaig.com>; 'SUR' <sur@lkkauto.com>

Cc: 'LKK Assignments' <assignments@lkkauto.com>

Subject: [External] RE: Accident Involving XD7877K and GX3173E along PIE towards Tuas near to LP1825 on 12.03.18

Dear Rachel,

Thank you for your email.

Dear Janice,

FYNA. Our ref: CS/GAI18005294/T1rb

Best Regards,

Catherine Chong | Admin

LKK Auto Consultants Pte Ltd

Phone: 6741-8434 | email: assignments@lkkauto.com | fax: 6256-4315 Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Tan, Rachel [mailto:Rachel.Tan@sg.gaig.com]

Sent: Monday, 9 April, 2018 11:46 AM

To: Catherine Chong (LKK Auto) admin-d@lkkauto.com/

Cc: 'LKK Assignments' <assignments@lkkauto.com>; 'SUR' <sur@lkkauto.com>

Subject: RE: Accident Involving XD7877K and GX3173E along PIE towards Tuas near to LP1825 on 12.03.18

Hi

Please provide SR, we received Sembcorp LOD on 20 March

Regards



Enquire Vehicle Registration Details

Owner Particulars

NRIC/Passport/Company Cert No.:

199507280G

Owner ID Type:

Company

Owner Name:

SEMBWASTE PTE LTD

Registered Address:

30 HILL STREET #05-04 SINGAPORE 179360

Mailing Address:

-

Birth Date:

Vehicle Particulars

Vehicle No.:

XD7877K

Previous Vehicle No.:

Effective Date of Ownership:

18 Oct 2013

18 Oct 2013

Original Regn Date:

Registration Date:

18 Oct 2013

Year of Manufacture:

2013

Vehicle Type:

Goods (Open) Garbage/Sanitary Wagon

PARF Eligibility Expiry Date: Minimum PARF Benefit: 0 No. of Transfers: 2010455457 IU Label No.: 2013101805000562H COE No .: 17 Oct 2023 COE Expiry Date: C - Goods Vehicle & Bus COE Category: C - Goods Vehicle & Bus COE Registration Category: -/\$69,217.00 Quota Premium (QP) / Prevailing Quota Premium: \$36,618.00 PQP Paid: QP (Regn Cat): No OPC Cash Rebate Eligibility: \$0.00 QP during COE Bidding Exercise: 5.00 % Additional Registration Fee Rate: \$6,160.00 Actual ARF Paid: 17 Oct 2033 Vehicle Lifespan Expiry Date: CO2 Emission:

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

- Please report <u>correctly</u> the details of the accident to speed up the claims process.
- This Form must be completed by the Policyholder and/or the Authorised Driver.
- 3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or witholding of material facts may allow insurance companies to repudiate policy ability.
- 4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.

Any false reporting may be referred to the Police for investigation.

- 6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
- 7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

	-			MENIT
ACC	IDEN	ISIA	U=1	

Date Of Report

12/03/2018 23:01

Date Of Accident

12/03/2018 16:00

Exact Location Of Accident

PIE(TUAS) AFTER JALAN BAHAR

Country/State of Loss

SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number

XD7877K

Insured/Policyholder

Name Of Registered Owner

SEMBWASTE PTE LTD

Co Reg No

199507280G

Email Address

NOEMAIL

Mobile Phone No

(LOCAL) +65-92398018

Alternative Phone No.

OFFICE-NOPHONE

Vehicle Particulars

Manufacturer

VOLVO

Model

YV2VH70D3DB665288

Exact Purpose for which vehicle was being used at WORK

time of accident

Are you claiming under your own insurance policy for repair to your vehicle?

NO

If No, Please state action to be taken

REPORTING ONLY

Vehicle Category

COMMERCIAL VEHICLE

Insurance Company

Name of Insurance Company

NTUC INCOME INSURANCE CO-OPERATIVE LTD

Type Of Coverage

COMPREHENSIVE

Fleet Policy

YES

Policy Number

5088412823-01

Cover Note Number

Driver

SOE TUN AUNG

Name of Driver Passport No/FIN

G5000556P

Date Of Birth

01/01/1980

Occupation

OUTDOOR

Date Of Driving Pass

09/06/2011

Driving Experience

6 YEARS AND 9 MONTHS

Gender

MALE

Mobile Number

(LOCAL) +65-92398018

Fax Number

Contact Number

EMail Address

NOEMAIL

BLK 117 JALAN BUKIT MERAH Address

#03-3755

NO

NO

3

NAME:

160117 Postcode

Was driver an employee of the Insured's Company YES

If No, Relationship of the Driver with the Insured

Vehicle Registration Number of Driver's Own

Vehicle

Insurance Company of Driver's Own Vehicle

General Information of the Accident

COLLISION - HEAD TO REAR Type Of Accident

CLEAR Weather Conditions WET Road Surface

Other Information

Was any foreign vehicle involved in this accident? NO

Number of vehicles involved in the accident

Was any body injured in the Accident? YES

Was any injured conveyed to hospital by ambulance?

YES Was any other material or property damaged?

I have been approached by unknown person(s) soliciting/offering accident claims assistance.

Number of Passengers (Including Driver)

: UNKNOWN Passenger 1 NAME:

GENDER: : MALE

: MALE GENDER:

Details of Police Action

Passenger 2

Was the accident reported to the police? YES

If Yes, Please state which Police Station

QUEENSTOWN N.P.C Police Station Name

ROAD: 3 QUEENSWAY #01-03, POSTCODE: 149073, COUNTRY: Police Station Address

: UNKNOWN

SINGAPORE

TEL NO: 1800-4719999 - FAX NO: Police Station Contact

NO Was notice of intended Prosecution given?

If Yes, against whom?

Circumstances of Accident

REFER TO POLICE REPORT AND SKETCH PLAN

Attachment(s)

YES Are accident photos available for attachment? Was there any video captured by Car Camera? NO NO Was there any audio recorded?

DETAILS OF OTHER VEHICLE PROPERTY 1

GX3173E Vehicle Registration Number

Vehicle Make/Model/Colour

Details Of Properties

COMMERCIAL VEHICLE Vehicle Category

Name of Driver

NRIC/Passport Number

Contact Number

Address

Postcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

DETAILS OF INJURED PERSON 1

Name

Approximate Age

Injuries Sustain

Injured person in which vehicle?

GX3173E

Were seat belts worn?

Was this injured conveyed to hospital by ambulance?

Address

Postcode

Sketch Plan

SKETCH PLAN

IMPORTANT NOTICE

- Present report correctly the actain of the accident to speed up the claims process.
- 1 The extratect to completed by the Palicyholder and/or the Authorised Driver
- intermediate producted must be as truthful and accurate as possible. Any widel increpresentation or authoriting of material tacts may allow insurance companies to repudiate policy liability.
- 4. The esserting is coptained of this force by osciraine companies a not an attribute of policy ichimy on the part at the restrance companies
- 5. Any false reporting may be referred to the Police for investigation.
- the report will be forwarded by the resizer, or the suA Records Management centre established by the General insurance Association of Superprise (sold) for an innoughout that expressed this report will for a fee be made available upon apply about by interested pettins.
- 7. By the longment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available afore said.
- 8 Consent under the Personal Data Protection Act (PDPA)

Condensand, acknowledge, agree and consent that

- (a) My scarer, my workship and the baneral insurance Association of Singapore ("GiA") may/are permitted to collect, use, disclose assigning accessing personal data/personal information set not in this [form] and any other personal information. provided by the or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal link implies to all recurse(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicles) involved in the accident shall be collectively referred to as the "insurers"), the insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purcose(s) 1
 - b) princesting, reading analysis dealing with my claims including the settlement of the claims and any necessary mestigations relating to the claims,
 - (iii) they begoing the accelerat analyst by claums
 - (ii) carrying out aud/or desiring with reviets factures or responding to any enqueries by me,
 - (w) administering my claims (including the mailing of correspondence, statements, involces, reports or notices to inc. which could involve disclosure of certain personal data about rise to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - [vi-complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes"
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal information may/can be disclosed by any of the insurers and/or GIA to their third party service providers or agents(inclusting their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators. Taw enforcement and government agencies as reasonably required for the purposes stated, or
 - (a) for complying with regainments under any regulations, laws or court orders

Policyholder's Signature

Date & Lines

Driver's Signature (if driver is not the policybolder) Date & Time 12 US 2015 2 (WITK)

Reporting Centre Personnel's Signature Name. JKHAM

NRIC/FIN NO 5857 4604

SKETCH PLAN

	1	i	A-007871K B-62-863173E
A	1	1	B-GZ-803173E
	1	X	
6	1 1	1	
			TOPE THAS PATER SEN

DE

Refer	to	Police	Rapid	T/20803(2/2139	

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature Date & Time

Driver's Signature

(If driver is not the policyholder)
Date & Time: 17 0 120(8) 200 HAS

Reporting Centre Personnel's Signature Name: | KIMAN NRIC/FIN No.: SSIRCIA |

Police Report



Police Station Of Chipes Committees N P C 3 Committees #01 03 SINGAPORE 149073 Tel No. 1800 47 (899)



Secret Mr. Tensues (2015)

REPORT OF A TRAFFIC ACCIDENT

Date: Time Report Made 12/03/2018 10:29

Valu Report No. F20180312 0123 Station Diery No. 54

informant's Particulars

Name of intomiant SOE TUNIAUNG

ii) Type / ii) No: FIN NO # 05000556P

Nationality MVANMAR

Sex Male 38

ADO

Date of Birth 01/01/1980

Rade Others Occupation Other heavy truck and lony divers

APT BLK 117 JALAN BUKIT MERAH #03-3765 HONG DAHRU ORCHID SINGAPORE 160117

Contact No. Home/Office

Person.

Type of informant

CHIMM Language. English

Driving Licence Information Class 3.4

Mobile 92398018

Institution / School Name

Date of Excey

General information of the Accident

Type of Accident. HELFY

Attended by Police

DIVIS Drive No

Date/Time of Accident 12/03/2018 15:00 Type of Location Straight Road

Location Mong Read 1 PAN ISLAND EXPRESSIVAY

PIE towards Tues, after Exit Jo Jin Bahar

Weather Cloudy Traffic Flow Road Surface West

Traffic Contro Not Controlled Road Speed Limit

Traffic Volume Heavy

Anyone conveyed by ambulance: Yes

Type of Collision

Between Moving Vehicles - Head To Rear

Details of Venicle involved Make Veticie No. 1 Type GX3173E LOTTY

X07877K Lotty

No of Pa Color Model Seriously 0 Damaged Slightly Damage

Details of Person Involved

Any Pedestnan Involved No. No of Pedestrians Injured NIL

Use of Pedestrian Crossing NA

Police Report



Poice Station Of Origin Queenitown N.P.C 3 Queenway #01-03 SINGAPORE 149073 Tel No. 1800-4719999

CONTINUATION OF REPORT

Proposit has Transactively the

G5000556P ID No. Direct SOF TUN AUNG Contact No. 92398018 Macro XD7877K (Lony) Related Venicle Class 3.4 Class of Date of Expry NIL Devoton ME Hospita/Clinic Licence & Expiry Date Date Discharge | NIL Degree of Injury | Sugnt Date Treatment - Nil. No of Days granted Medical Leave

On 12/03/2018 at about 1602hrs. I was traveling in vehicle XD7877K along PIE towards Tubs. It had just stopped raining and the road was very wet. After exit 36 Jaian Bahar, we felt that we were hit from the rear. We stopped the vehicle to check and discovered that another long GX3173E and hit our rear. The driver of the said tony was injured on the right arm and elbow and he was conveyed to the hospital by an anti-allatice.

S NGAPORE POLICE FORCE

Police Report

Character A. S. C. C. S. N. C. P. Sept. 149075.

Person to Tripostorique


CONTINUATION OF REPORT

Select Plan informatic since plan to provide exercit plan


number 1 AACT. Please around a copy of your vehicle's trisurance Certificate to this report. If you can't have the performance with you make please fax a copy to 55474650 strong the report number as returned.

Secretary of Colors Secretary Colors Secretary Secretary













ZENITH ENGINEERING PTE LTD

34 Joo Koon Circle, Singapore 629060

Tel: (65) 6861 1100

Fax: (65) 6862 1948

Email: info@ze.com.sg

Website: www.ze.com.sg

CO No: 197904024Z GST Reg No: M2-0037093-7

QUOTATION NO: QU18-L0267-R00

Customer :SembWaste Pte Ltd

4543 Jalan Bukit Merah

Singapore 159470

Attn

:Mr Mohamad Azman

Tel

:62723821

Fax: 62271443

Date

: 14/03/18

Validity

- 13/04/18

Account No

: SE04

Currency

: Singapore Dollar

Page

: Page 1 of 1

Description No.

Qty

UOM

Unit Price

Amount S\$

Replacement of new binlifter Assy for RCV XD7877K 1

,caused by accident .

10,400

11,600.00

11,600.00

Supply labour and material for the repair 2

> of RCV XD7877K as follows.removing of damaged binlifter Assy, forming & welding , fabrication of sub assembly , retrofitting new bin lifter onto the RCV and testing and painting of Binlifter assembly of affected area of repair.

TERMS & CONDITIONS

Paymet:Cash on Delivery

Validity: 30days from the date of this quotation

LKK Auto Consultants hence notify the Repairer of the following:

. To resurvey before/after spray painting To display damaged part(s) during resurvey

Parts prices are subject to confirmation

Third party survey is on a "Without Prejudice" basis

No illegal modification(s) is allowed

 Supplementary item(s) must be resurveyedent Amount is subject to final approval from Insur Add 7% GST

Acknowledged by Repairer Signature:

Date:

Taufilm 17495749 21/3/18 P 1445 * Resurvey new parts taufikh e likkauto.com

11,600.00

812.00

12,412.00

Ong Poh Kiat Head of Service Department 68611100

91079212.

Confirmed & Accepted By: SembWaste Pte Ltd

Name:

Title: Date:

Company Stamp:

Total Amount







LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
GREAT AMERICAN INSURANCE COMPANY	Ref :	CS/GAI18005294	/T1rbn2	
3 TEMASEK AVENUE #16-01 CENTENNIAL TOWER	Date:	03-05-2018		

16-0	MASEK AVENUE 01 CENTENNIAL T APORE 039190	OWER	Date: 03-05-2018 Code: GAI	
		D-U Ddide	ars :- THIRD PARTY CLAI	M
				XD 7877K
	Insured Veh.	GX 3173E	Veh. Inspected	0.00
	Policy No.	- FROM 2022	Coverage (\$)	0.00
	Claim No.	GX3173E	Excess (\$)	21/03/2018
	Assign From	RACHEL TAN	Assign Date	21/03/2010
2.			articulars & Condition	7110
	Make & Model	VOLVO FEE300	c.c	7146
	Engine No.	HIDDEN	Year of Reg.	2013
	Chassis No.	YV2VH70D3DB665288	Colour	WHITE
	Odometer	409602	Steering	IN ORDER
	Brakes	IN ORDER	Modification	NIL
	General	GOOD		
3.		Cor	ditions of Tyres	
	3	Size	Make	Balance
	R/H Front Tyre	295/80 R22.5	FIRENZA	8 mm
	L/H Front Tyre	295/80 R22.5	FIRENZA	8 mm
	R/H Rear Tyre	295/80 R22.5 (D)	FIRENZA	8/8 mm
	L/H Rear Tyre	295/80 R22.5 (D)	FIRENZA	8/8 mm
4.	and broken both	Desci	ription of Damages	
	THE VEHICLE SU	STAINED DAMAGES AT THE	REAR PORTION.	
	DAMAGES SEE D	FTAILS.		
5.	Driver Code of the		neral Information	
	Accident Date	12/03/2018	Inspection Date	21/03/2018
	Survey held at	4543 JALAN BUKIT MERAI	H SINGAPORE 159470	
	Repairer	ZENITH ENGINEERING PT	TE LTD	
5a.			Remarks	
-	A)THE INSPECTI	ON WAS CONDUCTED ON A	"WITHOUT PREJUDICE" BA	SIS. ISED REPAIRS.
EL.	B)IN ACCORDAN		nate Days of Repair	
5b.	TEOTIMATED NO.	RMAL PERIOD FOR REPAIR:		Davs



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. XD 7877K

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	LABOUR			
	REPLACEMENT OF NEW BINLIFTER ASSY FOR RCV XD 7877K, CAUSED BY ACCIDENT. SUPPLY LABOUR AND MATERIAL FO THE REPAIR OF RCV XD 7877K AS FOLLOWS, REMOVING OF DAMAGED BINLIFTER ASSY, FORMING & WELDING, FABRICATION OF SUB ASSEMBLY, RETROFITTING NEW BINLIFTER ONTO THE RCV AND TESTING AND PAINTING OF BINLIFTER ASSEMBLY OF AFFECTED AREA OF REPAIR.		11,600.00	10,400.00
	The representation of the Control of		11,600.00	10,400.00
	GRAND TOTAL		11,600.00	10,400.00

10,400.00	RECOMMENDED COST OF REPAIRS	118
	RECOMMENDED COST OF REPAIRS	IB

Report Ref No. CS/GAI18005294/T1rbn2

MOHAMAD TAUFIKH

M.MATAI, AMSAE-A

Automotive Assessor

ADRIAN LING WAI PING

B.Eng, AMSOE, AMIRTE, AMSAE-A, M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES: This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contact or tort, is accepted to any third party who may reply on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.