

22/03/2012

ASS. REC. BY:

REF:

CS/CT118005295/Urb72

Special Instruction:

Survivor:

Mawing

ASSIGNMENT (Office)

From (Person):

Jawyn Tay

of

CTI

Date/Time:

21/03/2018 1132am

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

GBC 8037 G

Insured:

GBC 7300Z

at Workshop m/s

Lee Sheng Auto

Tel:

67477333

of

Blk 1 Kaki Bukit Ave 6 # 01-60

Policy No:

DMCVSN 1528011702

Claim No:

SNM18001361C05

Sum Insured:

Excess:

Make of Veh:

D.O.A.

13032018

(Client's Record)

CA / REV / REP. / REV 24 HRS 'wp'

H.O.D. Endorsement:

Date/Time:

Person Contacted:

Vehicle IN/OUT

Date/Time	Action/Instruction (✓) Estimate
	GBC 8037 G - X
	GBC 7300Z - X

(08/11/13) wef

ASS. REC. BY: Marius

REF:

C71/

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No: 6B680376at Workshop m/s Teeshy

of _____

Insured: _____

Policy No. _____

Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

N/S	O/S

Bal. or Market Value: _____

IDAC Accident Rpt: _____ Consistent? : Yes or No

G/A / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: 5 days Res.: Yes or NoLum Sum: 20 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: 6B680376 r Regn: 10117

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or carMake: Toyota Dyna c.c. 2982Colour: white A/C: Insured / Std / NI / NASp. Reading: 22348 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: JT FAT 35400K 209116Gen. Cond: Good / Fair / Poor / BurntSteering: Good / Jammed / Leaked / Burnt orBrake: Good / Jammed / Leaked / Burnt orModi: Nil / S/Rim / STD A/Rim orTyre Size: F: 195 / 75 R15R: 155 R12

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

R/Bal. 6 mmL/Bal. 9 mmD.O.A. 13/3/18

Survey held at _____

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

Rt.

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

3/4/18 4/5 @ 2100 Confirmed with Greener lorry (Red 30HO-70, 59M) mslee

RECEIVED 04 APR 2018

Date/Time, File Pass to?

☐ : Preli. Report

1)

☐ : Final Report

Date/Time, File Return to?

2)

4/4 - typistReport Format: merimenLump Sum / I.B.I: (\$) 2100/2Days Of Repair: 5Resurvey No. of Trip: 1Add Fee: ☐ : Site Insp (\$ _____)☐ : Interview (\$ _____)☐ : Tech. Invs (\$ _____)☐ : Weekend (\$ _____)

Survey Fee:

Transportation:

S + RS \$ _____

Photos

Others

TOTAL

220




LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
CHINA TAIPING INSURANCE (S) PTE LTD		Ref : CS/CTI18005295/Urb		
3 ANSON ROAD #16-00 SPRINGLEAF TOWERS SINGAPORE 079909		Date : 21-03-2018		
		Code : CTI		
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	GBC 7300Z	Veh. Inspected	GBG 8037G	
Policy No.	DMCVSN1528011702	Coverage (\$)	0.00	
Claim No.	SNM18D01361C02	Excess (\$)	0.00	
Assign From	MERIMEN (JOWYN TAY)	Assign Date	21/03/2018	
2. Vehicle Particulars & Condition				
Make & Model	c.c		0	
Engine No.	HIDDEN	Year of Reg.		
Chassis No.	Colour			
Odometer	-	Steering		
Brakes	Modification			
General				
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre			mm	
L/H Front Tyre			mm	
R/H Rear Tyre			mm	
L/H Rear Tyre			mm	
4. Description of Damages				
5. General Information				
Accident Date	13/03/2018	Inspection Date	21/03/2018	
Survey held at	LEE SHENG AUTO PTE LTD 1 KAKI BUKIT AVE 6 #01-60 SINGAPORE 417883			
5a. Remarks				
A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	21 Mar 2018		21 Mar 2018 11:32 Assign				New Assignment Cancel Case

Main	Reference	Claim Details	Documents	Show All
------	-----------	---------------	-----------	----------

CLAIM SUBFOLDER DETAILS [Created by insurer]

Insured:	HAI SAI SEAFOOD PTE LTD, Co. Reg. No.: 197602076C		
Main Claimant:	AGAPE LOGISTICS PTE LTD, Co. Reg. No.: 200814279G		
Vehicle Reg. No.:	GBG8037G	Date of Loss:	13/03/2018 10:00 - :59
Claim Type:	TP / SNM18D01361C02	Policy/Cover Note No.:	DMCVSN1528011702
Vehicle Reg. No. (Insured):	GBC7300Z	Policy No. (Claimant):	
	Excess:	S\$0.00	
Repairer:	Lee Sheng Auto Pte Ltd (HQ) 1 Kaki Bukit Ave 6,, Autobay @Kaki Bukit #01-60/58, 417883 Kaki Bukit - Tel: 67477333		
Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Jowyn Tay - 6389 6174]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Final Rpt due 02/04/2018]		
Adj Asg. Remarks:	DEAR MARCUS, PLEASE ATTEND TO CONDUCT THIRD PARTY SURVEY, CHECK CONSISTENCY OF THE DAMAGES ON WITHOUT PREJUDICE BASIS.		

ASSOCIATED MAIL RECEIVED View All Compose Case Mail

There are no mail for this case.

☐ **ALL ASSOCIATED TASKS** View All Search Tasks Create New Task Complete

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

mrcus.

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	13/03/2018 17:39
Date Of Accident	13/03/2018 10:00
Exact Location Of Accident	STAR VISTA SHOPPING CENTRE LOADING/UNLOADING BAY
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	GBG8037G
Insured/Policyholder	
Name Of Registered Owner	AGAPE LOGISTICS PTE LTD
Co Reg No	200814279G
Email Address	NOEMAIL
Mobile Phone No	
Alternative Phone No	OFFICE-97405775

Vehicle Particulars

Manufacturer	TOYOTA
Model	DYNA 150 D-3.0 D (M)
Exact Purpose for which vehicle was being used at time of accident	
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	COMMERCIAL VEHICLE

Insurance Company

Name of Insurance Company	AXA INSURANCE PTE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	P2026573
Cover Note Number	

Driver

Name of Driver	JURAIMI BIN RAJAB
NRIC No	S8223419E
Date Of Birth	27/08/1982
Occupation	INDOOR
Date Of Driving Pass	05/01/2009
Driving Experience	9 YEARS AND 2 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-96140298
Fax Number	
Contact Number	
Email Address	NOEMAIL

Address	BLK 783 YISHUN RING ROAD #04-3522
Postcode	760783
Was driver an employee of the Insured's Company	YES
If No, Relationship of the Driver with the Insured	
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	COLLISION - HEAD TO REAR
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles involved in the accident	
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

PLEASE REFER TO SKETCH PLAN.

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	GBC7300Z
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	COMMERCIAL VEHICLE
Name of Driver	TAN TENG KWAN
NRIC/Passport Number	S1115935D
Contact Number	83832597
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

Sketch Plan Pg. 1

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.



Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:


13/3/18 @
5-20pm

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:



Sketch Plan Pg. 2

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

I was stationary due to a jam. As I pulled my hand brake and check the invoices, Vehicle B in front suddenly hit me at the front. Nobody was injured.

* Repair at other workshop.

DECLARATION

I/We declare the foregoing particulars are true in every respect.



Policyholder's Signature

Date & Time:

Company Chop (if applicable)

Driver's Signature

(If driver is not the policyholder)

Date & Time:

13/3/19
5:20pm

Shunma



Reporting Centre Personnel's Signature

Name:

NRIC/FIN No.:

Enquire PARF/COE Rebate for Registered Vehicle**Vehicle Owner Particulars**

Owner ID Type:	Company
Owner ID:	4279G

Vehicle Details

Vehicle No.:	GBG8037G
Vehicle to be Exported:	No
Intended De-registration Date:	21 Mar 2018
Vehicle Make:	TOYOTA
Vehicle Model:	DYNA 150 5MT
Primary Colour:	White
Manufacturing Year:	2017
Engine No.:	1KD2749526
Chassis No.:	JTFAT35Y00K209116
Maximum Power Output:	-
Open Market Value:	\$27,084.00
Original Registration Date:	30 Oct 2017
First Registration Date:	30 Oct 2017
Transfer Count:	1
Actual ARF Paid:	\$1,355.00

Intended PARF Rebate Details

PARF Eligibility:	No
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00

Intended COE Rebate Details

COE Expiry Date:	29 Oct 2027
COE Category:	C - Goods Vehicle & Bus
COE Period(Years):	10
PQP Paid:	\$35,803.00
COE Rebate Amount:	\$34,388.00
Total Rebate Amount:	\$34,388.00

The information contained herein is correct as at 21 Mar 2018

OK

LEE SHENG AUTO PTE LTD

Page 1 / 2

1, Kaki Bukit Ave 6, Autobay@KakiBukit

#01-60/58, Singapore 417883

Tel No. : 67477333 Fax No. : 67457138

E-Mail : leesheng@singnet.com.sg

Tax Reg. No. : 201000701R Buss. Reg. No. : 201000701R

Messrs. AGAPE LOGISTICS PTE LTD

Estimate : ES000617

Attention : Motor Claim Department

Contact : 97405775

Date : 16/03/2018
Vehicle Num. : GBG8037G
Make/Model : TOYOTA DYNA-2017
Chassis/Eng# : JTFAT35Y00K209116/1KD2749526
Accident Date : 16/03/2018
Claim No. :
Reference :
Policy No. :

*not Authorized
2/16/18
21/3/18
Take photo before repair.
Saley.*

S/N	Quantity	Particular	Unit Price	Amount S\$
LIST ITEMS :				
1.	1pc	FRONT PANEL		
2.	1PC	GRILLE		
3.	1PC	GRILLE EMBLEM		
4.	1PC	WIPER ARM LHS		
5.	1PC	WIPER ARM RHS		
6.	1PC	WIPER LINKAGE		
7.	1PC	WIPER MOTOR		
8.	2PC	WIPER NOZZLE		
9.	1PC	WIPER PANEL ASSY		
10.	1PC	FRONT BUMPER		
11.	1PC	NUMBER PLATE		
12.	1	DYNA EMBLEM		
13.	6	GRILLE EMBLEM CLOP		
List Total S\$:				
SPECIAL NETT ITEMS :				
1.	1	STICKER		
Special Nett Total S\$:				
LABOUR :				
	1	KNOCKING /JACKING WELDING	650.00	650.00
	1	SPRAY PAINTING	650.00	650.00

1/5 \$2100

(25%)

*1758.2
25%
1318.65*

<i>body on</i>	825.00	<i>==</i>
<i>one</i>	336.00	<i>==</i>
<i>nu</i>	57.20	<i>✓</i>
<i>11</i>	152.00	<i>x</i>
<i>11</i>	152.00	<i>x</i>
<i>11</i>	450.50	<i>x</i>
<i>11</i>	298.00	<i>x</i>
75.00 <i>11</i>	150.00	<i>x</i>
<i>11</i>	485.00	<i>✓</i>
<i>11</i>	659.00	<i>x</i>
<i>Sub</i>	20.00	<i>✓</i>
<i>nu</i>	35.00	<i>✓</i>
3.50 <i>11</i>	21.00	<i>x</i>
	3,640.70	
<i>nu</i>	150.00	<i>80</i>
	150.00	

CONTINUE / ...

LEE SHENG AUTO PTE LTD

Page 2 / 2

1, Kaki Bukit Ave 6, Autobay@KakiBukit

#01-60/58, Singapore 417883

Tel No. : 67477333 Fax No. : 67457138

E-Mail : leesheng@singnet.com.sg

Tax Reg. No. : 201000701R Buss. Reg. No. : 201000701R

Messrs. AGAPE LOGISTICS PTE LTD

Estimate : ES000617

Date : 16/03/2018

Vehicle Num. : GBG8037G

Make/Model : TOYOTA DYNA-2017

Chassis/Eng# : JTFAT35Y00K209116/1KD2749526

Accident Date : 16/03/2018

Claim No. :

Reference :

Policy No. :

Attention : Motor Claim Department

Contact : 97405775

S/N	Quantity	Particular	Unit Price	Amount S\$
		WIRING		30 50.00
		Labour Total S\$:		1,350.00

2128.65

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Total S\$: 5,140.70

=====

LEE SHENG AUTO PTE LTD

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/CTI18005295/URBN2

Date: 06/04/2018

REFERENCE

Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd.	Policy No:	DMCVSN1528011702
Claimant Vehicle No :	GBG8037G	Insured Vehicle No :	GBC7300Z
Date of Loss:	13/03/2018	Nature of Claim:	TP
		Claim No:	SNM18D01361C02

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	GBG8037G	Engine No:	1KD2749526
Make & Model:	TOYOTA DYNA 150, 3.0 D (M)	Chassis No:	JTFAT35Y00K209116
Reg. Date:	30/10/2017 (Man. Year: 2017)	Odometer:	22348 km
Colour:	White		
Engine Capacity:	2982 cc		
Market Value/New Car Price:	N/A		
Sum Insured (\$\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	195/75R15	Rear Tyre Size:	155R12 (D)
Front Left Side:	Bridgestone 6 mm	Rear Left Side:	Bridgestone 6/6 mm
Front Right Side:	Bridgestone 6 mm	Rear Right Side:	Bridgestone 6/6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS

	Repairer's	Adjuster's	Difference	Diff %
Parts	3,790.70	1,398.65	2,392.05	63.10
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,350.00	1,230.00	120.00	8.89
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (\$\$)	5,140.70	2,628.65	2,512.05	48.87
Approved Total (Overridden) (\$\$)		2,100.00		
(\$\$)	5,140.70	2,100.00	3,040.70	59.15
+ GST 7.00/7.00% (\$\$)	359.85	147.00	212.85	59.15
Nett Amount (\$\$)	5,500.55	2,247.00	3,253.55	59.15

INSPECTION

Date of Assignment: 21/03/2018

Date Inspected: 21/03/2018 Inspected At:

Lee Sheng Auto Pte Ltd (HQ)
1 Kaki Bukit Ave 6., Autobay @Kaki
Bukit #01-60/58
Singapore 417883

Estimated Period of Repair: 5.0 days

Adjuster: MARCUS CHUA

Manager: Janice Lee Si Hua

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	(Last Synchronised: 06 Apr 2018)	
Parts:	N/A	TOYOTA DYNA 150 3.0 D (M) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for GBG8037G)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT PANEL	Badly Dented	825.00 F	*825.00 FL
2	1		*GRILLE	Cracked	336.00 F	*336.00 FL
3	1		*GRILLE EMBLEM	Necessary	57.20 F	*57.20 FL
4	1		*WIPER ARM LHS	Not Necessary	152.00 F	*- FL
5	1		*WIPER ARM RHS	Not Necessary	152.00 F	*- FL
6	1		*WIPER LINKAGE	Not Necessary	450.50 F	*- FL
7	1		*WIPER MOTOR	Not Necessary	298.00 F	*- FL
8	2		*WIPER NOZZLE	Not Necessary	150.00 F	*- FL
9	1		*WIPER PANEL ASSY	Dented	485.00 F	*485.00 FL
10	1		*FRONT BUMPER	Repair	659.00 F	*- FL
11	1		*NUMBER PLATE	Bent	20.00 F	*20.00 FL
12	1		*DYNA EMBLEM	Necessary	35.00 F	*35.00 FL
13	6		*GRILLE EMBLEM CLIP	Not Necessary	21.00 F	*- FL
14	1		*STICKER	Necessary	150.00 FS	*80.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (S\$)	3,790.70	1,838.20
- List Item Discount on L Items 0.00/25.00% (S\$)	0.00	439.55
Total Parts (S\$)	3,790.70	1,398.65

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items**There are no new miscellaneous items selected.****Recommended Labour**

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	KNOCKING/JACKING WELDING	New	650.00	600.00
2	SPRAY PAINTING	New	650.00	600.00
3	WIRING	New	50.00	30.00
Gross Labour Cost (\$\$)			1,350.00	1,230.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >