

22/03/2001

ASS. REC. BY:

REF

C31/MSG18005321/Cd302

Special Instruction:

Surveyor:

ASSIGNMENT (Office)

From (Person): Eileen Goh of MSIG Date/Time: 22/3/18 @ 3.00pm

Estimated Cost: Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: SLG 5804K Insured: SLS 10804

at Workshop m/s JD Motorsports Tel: 9237 3644

of 25 Kaki Bkt Rd 4 # 06-38 synergy

Policy No: DMPCSN3059131601 Claim No: SNM18001422C02

Sum Insured: Excess:

Make of Veh: D.O.A. 17/03/2018  
(Client's Record)

CA / REV / REP. / REV 24 HRS lwp

H.O.D. Endorsement:

Date/Time: 10:01am @ 21/3/18 Person Contacted: Ronnie Vehicle IN / OUT

Date/Time	Action/Instruction
	( ) Estimate
	SLG 5804K - x
	SLS 10804 - x
	After repair: 26/3/2018

REF: MSIG

## ASSIGNMENT

COE Expired = 20/4/2018

From: Date: 23/3/18

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: SLG 5804K  
at Workshop m/s JD Motorsports  
of 25 Kaki Bkt Rd 4 #06-38

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its  
repair at the time of inspection.

Bal. or Market Value:

\$7.5K

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

days

Res.: Yes or No

Lum Sum:

%

3 Val: Yes or No

CA / REV / REP. / 24 HRS (up)

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No: SLG 5804 K Yr Regn: 21 Apr 2008

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Mit Lancer 1.6A

C.C. 1584

Colour: Grey

A/C Insured / Std / NI / NA

Sp. Reading 150627

T/Radio: Insured / Std / NI / NA

Eng/No:

C/No: JMYSTCS 3A BU 00664

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modl: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 195/60R15

R: ———

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or Falken.

Front

Rear

R/Bal. 5 mm

R/Bal. 5 mm

L/Bal. 5 mm

L/Bal. 5 mm

D.O.A. 17/3/2018

D.O.I. 11.10am 23/3/18

Survey held at

JD Motorsports

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

OS rear

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

- PRS. GIA Given.

Estimate repair range. \$1,500 - \$2,000

  
 23/3/2018

RECEIVED 17 APR 2018

Date/Time: File Pass to?

☐ : Preli. Report

1)

☐ : Final Report

Date/Time: File Return to?

2)

Days Of Repair: 1

Resurvey No. of Trip: 1

Survey Fee:

Transportation

1 S + RS \$

1 Photos

1 Charts

TOTAL

Report Format: PRS.

Lump Sum / I.B.I. (\$) :

Add Fee: ☐ Site Insp. (\$)☐ Interview (\$)☐ Tech. Insp. (\$)☐ Workshop (\$)

120

50

10

180

## ...CLAIM SUBFOLDER...(New Assignment)

### CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	19 Mar 2018		22 Mar 2018 10:21 <a href="#">Assign</a>				<b>New Assignment</b> <a href="#">Cancel Case</a>

Main

Reference

Claim Details

Documents

[Show All](#)

### CLAIM SUBFOLDER DETAILS

[Created by insurer]

Insured:	TAN LI CHOO, ID: S1699567C		
Main Claimant:	YEO TRADING SUPPLY, Co. Reg. No.: 47024200X		
Vehicle Reg. No.:	SLG5804K	Date of Loss:	17/03/2018 18:00 - :59
Claim Type:	TP / 552748	Policy/Cover Note No.:	29017356TMP (Third Party Only) Coverage: 08/09/2017 - 07/09/2018
Vehicle Reg. No. (Insured):	SLS1080U	Policy No. (Claimant):	
		Excess:	
Repairer:	Jd Motorsports Pte Ltd (HQ) 25 KAKI BUKIT ROAD 4, #06-38 SYNERGY@KB, 417800 Kaki Bukit - Tel:		
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Elaine Ngu Siau Mei - 6594 2540]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Imm.Advice due 23/03/2018]		
Driver/Custodian (Insured):	LIM SOHN HUI (), NRIC: S7539662G, Tel: +6591073464		

### ASSOCIATED MAIL RECEIVED

[View All](#)[Compose Case Mail](#)

There are no mail for this case.

### ALL ASSOCIATED TASKS

[View All](#)[Search Tasks](#)[Create New Task](#)[Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
----------	----------	------	------------	---------	---------	-------------	--------------	------------	-------

No results.

## Nivitha (LKK Auto)

---

**From:** Eileen Goh <eileen\_goh@sg.msig-asia.com>  
**Sent:** Tuesday, 20 March 2018 3:00 PM  
**To:** assignments@lkkauto.com  
**Cc:** Fievel Foo; Elaine Ngu  
**Subject:** NEW ASSISGNMENT : OI :SLS1080U M552748 / TP:SLG5804K

**Importance:** High

Dear ALL

Please take note that the assignment is assign to you by email as I don't have the third part gia report.

Once I have will update in merimen.

TP vehicle to be inspect at :

Venue : JD Motorsports Pte Ltd  
25 Kaki Bukit Road 4  
#06-38 Synergy@KB  
Singapore 417800  
Contact Person : Mr Ronnie : 9237 3644

*Have a great week ahead!*

Eileen Goh  
Admin Officer, Claims Services (Motor)  
Direct line +65 6594 2584 | Direct fax +65 6225 7402 | [eileen\\_goh@sg.msig-asia.com](mailto:eileen_goh@sg.msig-asia.com)



Insurer Claims  
Team of the Year  
2016

MSIG Insurance (Singapore) Pte Ltd 16 Raffles Quay, #24-01 Hong Leong Building, Singapore 048581 | T: +65 6220 9644 | F: +65 6225 6371 | Co. Reg. No. 200412212G | [msig.com.sg](http://msig.com.sg)



A Member of **MS&AD** INSURANCE GROUP

---

### CONFIDENTIALITY NOTICE

This e-mail (including any attachments) may contain information that is privileged or confidential. The sending of this e-mail to any person other than the intended recipient is not a waiver of the privilege or confidentiality that attaches to it. If you are not the intended recipient, please notify the sender immediately, delete the email and do not copy, distribute or disclose its contents.

D.O.A. 17/3/2018  
Bal = 1.1 mths

## Enquire PARF/COE Rebate for Registered Vehicle

<b>Vehicle Owner Particulars</b>	
Owner ID Type:	Business
Owner ID:	4200X
<b>Vehicle Details</b>	
Vehicle No.:	SLG5804K
Vehicle to be Exported:	No
Intended De-registration Date:	27 Mar 2018
Vehicle Make:	MITSUBISHI
Vehicle Model:	LANCER 1.6 A
Primary Colour:	Grey
Manufacturing Year:	2008
Engine No.:	4G18JP9124
Chassis No.:	JMYSTCS3A8U006664
Maximum Power Output:	79.0 kW (105 bhp)
Open Market Value:	\$13,101.00
Original Registration Date:	21 Apr 2008
First Registration Date:	21 Apr 2008
Transfer Count:	2
Actual ARF Paid:	\$13,101.00
<b>Intended PARF Rebate Details</b>	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	20 Apr 2018 /
PARF Rebate Amount:	\$6,550.00 //
<b>Intended COE Rebate Details</b>	
COE Expiry Date:	20 Apr 2018
COE Category:	A - Car (1600cc & below)
COE Period(Years):	10
QP Paid:	\$16,930.00
COE Rebate Amount:	\$112.00
<b>Total Rebate Amount:</b>	<b>\$6,662.00</b>

The information contained herein is correct as at 23 Mar 2018

OK

MSME18037766 / SME Motor Pte Ltd - Kaki Bukit  
 ENTRY DATE & TIME: 20/03/2018 12:44  
 SUBMITTED BY: Chia Pei Ying

Your NCD will be affected due to late reporting  
 Actual e-Filing Submission Date & Time: 20/03/2018 12:55

## SINGAPORE ACCIDENT STATEMENT

### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

### ACCIDENT STATEMENT

Date Of Report	20/03/2018 12:44
Date Of Accident	17/03/2018 19:10
Exact Location Of Accident	MALAYSIA CHECKPOINT BEFORE ENTERING WOODLANDS CHEC
Country/State of Loss	MALAYSIA/JOHOR DARUL TAKZIM

### DETAILS OF OWN VEHICLE

Vehicle Registration Number	SLG5804K
<b>Insured/Policyholder</b>	
Name Of Registered Owner	YEO TRADING SUPPLY
Co Reg No	47024200X
Email Address	NOEMAIL
Mobile Phone No	
Alternative Phone No	OFFICE-94244895
<b>Vehicle Particulars</b>	
Manufacturer	MITSUBISHI
Model	LANCER
Exact Purpose for which vehicle was being used at time of accident	
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR
<b>Insurance Company</b>	
Name of Insurance Company	NTUC INCOME INSURANCE CO-OPERATIVE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	5086869002
Cover Note Number	
<b>Driver</b>	
Name of Driver	ZUHAILI BIN MAZLI
NRIC No	S9231890G
Date Of Birth	12/09/1992
Occupation	OUTDOOR
Date Of Driving Pass	15/02/2012
Driving Experience	6 YEARS AND 1 MONTH
Gender	MALE
Mobile Number	(LOCAL) +65-97314099
Fax Number	
Contact Number	
E-Mail Address	NOEMAIL

Address BLK 354 CHOA CHU KANG CENTRAL #02-319  
 Postcode 680354  
 Was driver an employee of the Insured's Company YES  
 If No, Relationship of the Driver with the Insured  
 Vehicle Registration Number of Driver's Own Vehicle -  
 -  
 -  
 Insurance Company of Driver's Own Vehicle -  
 -  
 -

**General Information of the Accident**

Type Of Accident SIDE SWIPE  
 Weather Conditions CLEAR  
 Road Surface DRY

**Other Information**

Was any foreign vehicle involved in this accident? NO  
 Number of vehicles involved in the accident  
 Was any body injured in the Accident? NO  
 Was any injured conveyed to hospital by ambulance? NO  
 Was any other material or property damaged? YES  
 I have been approached by unknown person(s) soliciting/offering accident claims assistance. NO  
 Number of Passengers (Including Driver) 5  
 Passenger 1 NAME: : NOOR AZIZAH  
 GENDER: : FEMALE  
 Passenger 2 NAME: : ZULHILMI  
 GENDER: : MALE  
 Passenger 3 NAME: : HAMIDAH  
 GENDER: : FEMALE  
 Passenger 4 NAME: : NOR MAN  
 GENDER: : FEMALE

**Details of Police Action**

Was the accident reported to the police? YES  
 If Yes, Please state which Police Station  
 Police Station Name CLEMENTI NEIGHBOURHOOD POLICE CENTRE  
 Police Station Address ROAD: NO. 20 CLEMENTI AVENUE 5, POSTCODE: 129858, COUNTRY: SINGAPORE  
 Police Station Contact TEL NO: 1800-8729999 - FAX NO: 67748639  
 Was notice of intended Prosecution given? NO  
 If Yes, against whom?

**Circumstances of Accident**

REFER TO POLICE REPORT.

**Attachment(s)**

Are accident photos available for attachment? YES  
 Was there any video captured by Car Camera? NO  
 Was there any audio recorded? NO

**DETAILS OF OTHER VEHICLE PROPERTY 1**

Vehicle Registration Number SLS1080U

Vehicle Make/Model/Colour

Details Of Properties

Vehicle Category

Name of Driver

NRIC/Passport Number

Contact Number

Address

Postcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

VEHICLE B

PRIVATE CAR



## Sketch Plan Pg. 1

## SKETCH PLAN

## IMPORTANT NOTICE

1. Please report **correctly** the details of the accident to speed up the claims process.
2. This Form must be **completed by the Policyholder and/or the Authorised Driver**.
3. Information provided must be as **truthful and accurate as possible**. Any wilful misrepresentation or withholding of material facts may allow insurance companies to **repudiate policy liability**.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the Centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this (form) and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers, law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purposes:
  - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
  - (ii) investigating the accident and/or my claims;
  - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
  - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
  - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes").
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes;
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims;
- (e) the information so collected under (d) above may be shared / disclosed:
  - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated; or
  - (ii) for complying with requirements under any regulations, laws or court orders.

Policyholder's Signature  
Date & Time:


Driver's Signature  
(if driver is not the policyholder)  
Date & Time:

Reporting Centre Personnel's Signature  
Name  
NRIC/FIN No:

J.D. MOTORSPORTS

Sketch Plan #2 Pg. 1

SKETCH PLAN



Vehicle A - SLG 5804 K

Vehicle B - SLG 1080 U

DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

*Refer to police report*

You had been advised by workshop that in the event that you wish to claim against your own policy (OD claim), there is a **Fourteen (14) days clause** whereby the claim must be made within the stipulated timeframe from the day of occurrence.

Reporting Only
Claim OD
Claim TP
Claim OD / TP at other workshop

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature  
Date & Time:

Driver's Signature  
(If driver is not the policyholder)  
Date & Time:

Reporting Centre Personnel's Signature  
Name:  
NRIC/FIN No:

### ...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	19 Mar 2018		22 Mar 2018 10:21 <a href="#">Edit Adj Rpt</a>	<b>S\$0.00</b> <a href="#">Edit Estimates</a>	<b>S\$0.00</b> <a href="#">View Rpt</a>		<b>Pending for Survey Report</b> <a href="#">Cancel Case</a>

Main	Reference	Claim Details	Documents	Show All					
<b>CLAIM SUBFOLDER DETAILS</b> <span style="float: right;">[Created by insurer]</span>									
Insured: <b>TAN LI CHOO</b> , ID: S1699567C									
Main Claimant: <b>YEO TRADING SUPPLY</b> , Co. Reg. No.: 47024200X									
Vehicle Reg. No.: <b>SLG5804K</b>		Date of Loss: 17/03/2018 18:00 - :59 [118 Months and 24 Days From LTA Reg Date (Man Yr)]							
Claim Type: <b>TP / 552748</b>		Policy/Cover Note No.: 29017356TMP (Third Party Only) Coverage: 08/09/2017 - 07/09/2018							
Vehicle Reg. No. (Insured): <b>SLS1080U</b>		Policy No. (Claimant):							
		Excess:							
Repairer: <b>Jd Motorsports Pte Ltd (HQ)</b> 25 KAKI BUKIT ROAD 4, #06-38 SYNERGY@KB, 417800 Kaki Bukit - Tel:									
Handling Insurer: <b>MSIG Insurance (Singapore) Pte. Ltd. (HQ)</b> - Tel: +65 6827 7888 ... [Handled by <b>Elaine Ngu Siau Mei</b> - 6594 2540]									
Adjuster: <b>LKK Auto Consultants Pte Ltd (HQ)</b> - Tel: 6256-3561 ... [Handled by <b>ADRIAN LING</b> ] ... [Imm.Advice due 23/03/2018]									
Driver/Custodian (Insured): LIM SOHN HUI (), NRIC: S7539662G, Tel: +6591073464									
<b>ASSOCIATED MAIL RECEIVED</b> <span style="float: right;"><a href="#">View All</a> <a href="#">Compose Case Mail</a></span>									
There are no mail for this case.									
<b>ALL ASSOCIATED TASKS</b> <span style="float: right;"><a href="#">View All</a> <a href="#">Search Tasks</a> <a href="#">Create New Task</a> <a href="#">Complete</a></span>									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

## Claim Documents

\*SLG5804K (552748)

[SLS1080U]

TP









YEO TRADING SUPPLY

Mar 17 2018 6:00PM

[TAN LI CHOO]

Jd Motorsports Pte Ltd

<a href="#">Upload Documents</a> <a href="#">Upload Photos</a> <a href="#">Compose New Letter</a>		<b>View</b> <a href="#">View in Browser</a>	
<b>Assessment Reports</b>			
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)	1 per page <input checked="" type="checkbox"/>
1	22/03/18 10:19	<b>Accident Statement</b> From: SC - Reg. No: SLS1080U, Claimant: TAN LI CHOO	<div>Thumbnail</div> <div>Print</div> <div>Load HTM</div>
<b>Photos/Images</b>			
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	3 per page <input checked="" type="checkbox"/>
1	17/04/18 15:56	<b>General View</b>	<div>Thumbnail</div> <div>Print</div> <div>Load JPG</div>
2	17/04/18 15:56	<b>General View</b>	<div>Thumbnail</div> <div>Print</div> <div>Load JPG</div>
3	17/04/18 15:56	<b>General View</b>	<div>Thumbnail</div> <div>Print</div> <div>Load JPG</div>
4	17/04/18 15:56	<b>General View</b>	<div>Thumbnail</div> <div>Print</div> <div>Load JPG</div>
5	17/04/18 15:56	<b>General View</b>	<div>Thumbnail</div> <div>Print</div> <div>Load JPG</div>
6	17/04/18 15:56	<b>General View</b>	<div>Thumbnail</div> <div>Print</div> <div>Load JPG</div>
7	17/04/18 15:56	<b>General View</b>	<div>Thumbnail</div> <div>Print</div> <div>Load JPG</div>
8	17/04/18 15:56	<b>General View</b>	<div>Thumbnail</div> <div>Print</div> <div>Load JPG</div>
9	17/04/18 15:56	<b>General View</b>	<div>Thumbnail</div> <div>Print</div> <div>Load JPG</div>
10	17/04/18 15:56	<b>General View</b>	<div>Thumbnail</div> <div>Print</div> <div>Load JPG</div>
11	17/04/18 15:56	<b>General View</b>	<div>Thumbnail</div> <div>Print</div> <div>Load JPG</div>
12	17/04/18 15:56	<b>General View</b>	<div>Thumbnail</div> <div>Print</div> <div>Load JPG</div>
13	17/04/18 15:56	<b>General View</b>	<div>Thumbnail</div> <div>Print</div> <div>Load JPG</div>
14	17/04/18 15:56	<b>General View</b>	<div>Thumbnail</div> <div>Print</div> <div>Load JPG</div>
15	17/04/18 15:56	<b>General View</b>	<div>Thumbnail</div> <div>Print</div> <div>Load JPG</div>
16	17/04/18 15:56	<b>General View</b>	<div>Thumbnail</div> <div>Print</div> <div>Load JPG</div>
17	17/04/18 15:56	<b>General View</b>	<div>Thumbnail</div> <div>Print</div> <div>Load JPG</div>
18	17/04/18 15:56	<b>General View</b>	<div>Thumbnail</div> <div>Print</div> <div>Load JPG</div>
19	17/04/18 15:56	<b>General View</b>	<div>Thumbnail</div> <div>Print</div> <div>Load JPG</div>
20	17/04/18 15:56	<b>General View</b>	<div>Thumbnail</div> <div>Print</div> <div>Load JPG</div>
21	17/04/18 15:56	<b>General View</b>	<div>Thumbnail</div> <div>Print</div> <div>Load JPG</div>
22	17/04/18 15:56	<b>General View</b>	<div>Thumbnail</div> <div>Print</div> <div>Load JPG</div>
23	17/04/18 15:56	<b>General View</b>	<div>Thumbnail</div> <div>Print</div> <div>Load JPG</div>
24	17/04/18 15:56	<b>General View</b>	<div>Thumbnail</div> <div>Print</div> <div>Load JPG</div>
25	17/04/18 15:56	<b>General View</b>	<div>Thumbnail</div> <div>Print</div> <div>Load JPG</div>
26	17/04/18 15:56	<b>General View</b>	<div>Thumbnail</div> <div>Print</div> <div>Load JPG</div>
27	17/04/18 15:56	<b>General View</b>	<div>Thumbnail</div> <div>Print</div> <div>Load JPG</div>
28	17/04/18 15:56	<b>General View</b>	<div>Thumbnail</div> <div>Print</div> <div>Load JPG</div>
29	17/04/18 15:56	<b>General View</b>	<div>Thumbnail</div> <div>Print</div> <div>Load JPG</div>
30	17/04/18 15:56	<b>General View</b>	<div>Thumbnail</div> <div>Print</div> <div>Load JPG</div>
31	17/04/18 15:56	<b>General View</b>	<div>Thumbnail</div> <div>Print</div> <div>Load JPG</div>
32	17/04/18 15:56	<b>General View</b>	<div>Thumbnail</div> <div>Print</div> <div>Load JPG</div>
33	17/04/18 15:56	<b>General View</b>	<div>Thumbnail</div> <div>Print</div> <div>Load JPG</div>

Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
34	17/04/18 15:56	General View	 Load JPG	<input checked="" type="checkbox"/>
35	17/04/18 15:56	General View	 Load JPG	<input checked="" type="checkbox"/>
36	17/04/18 15:56	General View	 Load JPG	<input checked="" type="checkbox"/>
37	17/04/18 15:56	General View	 Load JPG	<input checked="" type="checkbox"/>
38	17/04/18 15:56	General View	 Load JPG	<input checked="" type="checkbox"/>
39	17/04/18 15:58	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
40	17/04/18 15:58	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
41	17/04/18 15:58	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
42	17/04/18 15:58	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
43	17/04/18 15:58	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
44	17/04/18 15:58	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
45	17/04/18 15:58	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
46	17/04/18 15:58	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
47	17/04/18 15:58	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
48	17/04/18 15:58	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
49	17/04/18 15:58	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
50	17/04/18 15:58	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
Documentation			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
1	22/03/18 10:19	EMAIL TO SUVRY BY EMAIL-SLG5804K.	 Load PDF	
2	22/03/18 10:20	TPD SLG5804K GIA REPORT	 Load PDF	

## Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
<b>Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)</b> <div style="border: 1px solid black; height: 40px; margin-top: 5px;"></div>			
<b>Show Remarks To:</b> <input type="checkbox"/> Handling Insurer <small>Note: Remarks are private unless you show it to other parties.</small>			

## LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS3/MSG18005321/CD3E2

Date: 19/04/2018

REFERENCE

Handling Insurer: MSIG Insurance (Singapore) Pte. Ltd.

Policy No: 29017356TMP

Claimant Vehicle No : SLG5804K

Insured Vehicle No : SLS1080U

Date of Loss: 17/03/2018

Nature of Claim: TP

Claim No: 552748

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SLG5804K

Make &amp; Model: MITSUBISHI LANCER, 1.6 (A)

Engine No: 4G18JP9124

Reg. Date: 21/04/2008 (Man. Year: 2008)

Chassis No: JMYSTCS3A8U006664

Colour: Grey

Odometer: 150627 km

Engine Capacity: 1584 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable):

Yes Footbrake (Serviceable):

Yes

Handbrake (Serviceable): Yes Engine Modification:

No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 195/60 R15

Rear Tyre Size: 195/60 R15

Front Left Side: Falken 5 mm

Rear Left Side: Falken 5 mm

Front Right Side: Falken 5 mm

Rear Right Side: Falken 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Nett Amount (S\$)</b>	<b>0.00</b>	<b>0.00</b>	<b>0.00</b>	

INSPECTION

Date of Assignment: 22/03/2018

Date Inspected: 23/03/2018 Inspected At:

Jd Motorsports Pte Ltd (HQ)  
25 KAKI BUKIT ROAD 4, #06-38  
SYNERGY@KB  
Singapore 417800

Estimated Period of Repair: 0.0 days

Adjuster: ADRIAN LING

Manager: Janice Lee Si Hua

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

- A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
- B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION.  
THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE.
- C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.

THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$1,500.00 - \$2,000.00

## REPAIR DETAILS

<b>Reference</b>		
<b>Part Source:</b>	MRM-SG	Version: 1.0 (Last Synchronised: 19 Apr 2018)
<b>Parts:</b>	143	MITSUBISHI LANCER 1.6 (A) (Catalogue:Merimen Singapore 1.0)
<b>Labour:</b>	Repairer's	(Price-denominated Standard List)
<b>Print Code:</b>	(Unsubmitted, no print-code for SLG5804K)	
<b>Validity:</b>	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
<b>Further Info:</b>	Items/values not in reference catalogue are prefixed with an asterisk *.	

## Recommended Parts

There are no new parts selected.

Report was unsubmitted during this print-out.



## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.

< END OF ESTIMATES >