

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

| | |
|----------------------------|------------------|
| Date Of Report | 15/03/2018 17:16 |
| Date Of Accident | 15/03/2018 16:10 |
| Exact Location Of Accident | TOA PAYOH RISE |
| Country/State of Loss | SINGAPORE |

DETAILS OF OWN VEHICLE

| | |
|-----------------------------|---------|
| Vehicle Registration Number | SKV521S |
|-----------------------------|---------|

Insured/Policyholder

| | |
|--------------------------|-------------------------|
| Name Of Registered Owner | NATALIE AGUS |
| Passport No/FIN | S9175283B |
| Email Address | GEOGEOF2006@HOTMAIL.COM |
| Mobile Phone No | (LOCAL) +65-97579071 |
| Alternative Phone No | Others-97579071 |

Vehicle Particulars

| | |
|--|-----------------------|
| Manufacturer | RENAULT |
| Model | CAPTUR FLAMME EDITION |
| Exact Purpose for which vehicle was being used at time of accident | |
| Are you claiming under your own insurance policy for repair to your vehicle? | NO |
| If No, Please state action to be taken | REPORTING ONLY |
| Vehicle Category | PRIVATE CAR |

Insurance Company

| | |
|---------------------------|--------------------------------------|
| Name of Insurance Company | AIG ASIA PACIFIC INSURANCE PTE. LTD. |
| Type Of Coverage | COMPREHENSIVE |
| Fleet Policy | NO |
| Policy Number | 2100477389-01 |
| Cover Note Number | |

Driver

| | |
|----------------------|-------------------------|
| Name of Driver | NATALIE AGUS |
| Passport No/FIN | S9175283B |
| Date Of Birth | 23/12/1991 |
| Occupation | INDOOR |
| Date Of Driving Pass | 17/08/2015 |
| Driving Experience | 2 YEARS AND 6 MONTHS |
| Gender | FEMALE |
| Mobile Number | (LOCAL) +65-97579071 |
| Fax Number | |
| Contact Number | |
| EMail Address | GEOGEOF2006@HOTMAIL.COM |

| | |
|---|---|
| Address | 700 LORONG 1 TOA PAYOH |
| Postcode | TRELLIS TOWERS #28-07 SINGAPORE 319773 |
| Was driver an employee of the Insured's Company | NO |
| If No, Relationship of the Driver with the Insured | OWNER |
| Vehicle Registration Number of Driver's Own Vehicle | - - - |
| Insurance Company of Driver's Own Vehicle | - - - |

General Information of the Accident

| | |
|--------------------|--------------------------|
| Type Of Accident | COLLISION - HEAD TO REAR |
| Weather Conditions | CLEAR |
| Road Surface | DRY |

Other Information

| | |
|---|-----|
| Was any foreign vehicle involved in this accident? | NO |
| Number of vehicles involved in the accident | |
| Was any body injured in the Accident? | NO |
| Was any injured conveyed to hospital by ambulance? | |
| Was any other material or property damaged? | YES |
| I have been approached by unknown person(s) soliciting/offering accident claims assistance. | NO |
| Number of Passengers (Including Driver) | 1 |

Details of Police Action

| | |
|---|----|
| Was the accident reported to the police? | NO |
| If Yes, Please state which Police Station | |
| Was notice of intended Prosecution given? | NO |
| If Yes, against whom? | |

Circumstances of Accident

Collision - Head to Rear (I hit a third party vehicle), #straightroad, Moving straight & Moving straight, Blue Car SKV521S, White Car SHD3060R "Traffic light was red. SKV521S stopped behind (with distance between them shown in video screenshot) SHD3060R, a blue taxi. SHD3060R was the first car at the traffic light. No collision yet. Both vehicles were stationary in red light. There was aluminium food container in the car of driver SKV521S, placed at the floor of the left front seat and it topples when the vehicle stops. The sound distracted driver of SKV521S. Driver of SKV521S looked on her left on reflex to see what happened, but forgot to engage on parking brake. SKV521S vehicle rolled forward slightly bumping the back of SHD3060R. The road may have some downslope hence the split second of it rolling forward before driver noticed caused the bump. Then, driver of SKV521S engaged parking brakes, turned on hazard lights, stepped out of vehicle. Driver of SHD3060R also stepped out of vehicle and took photos of his car. No visible damage on the front of SKV521S. Damage on SHD3060R seem to be very minor, which is slight imprinting of the car plates (the rectangular shape) on the back of SHD3060R. From the dashcam video, the imprinting of the car plates cant be seen at all. Driver of SHD3060R took info (IC and car number) of SKV521S. Driver of SKV521S was panicking (first time accident) and forgot to ask details of driver SHD3060R or take the picture of SHD3060R vehicle, but his face was captured on the video screenshot. The entire accident was on driver SKV521S dashboard video, attached in this report. Note that later on after moving her vehicle at the roadside, driver of SKV521S took photo of the front part of her car to show there's no visible damage. Driver of SHD3060R said his taxi company will make claim if any. "

Attachment(s)

| | |
|---|------------------------|
| Are accident photos available for attachment? | YES |
| Was there any video captured by Car Camera? | YES |
| Remarks/ Reasons: | NO VIDEO FILE PROVIDED |
| Was there any audio recorded? | NO |

DETAILS OF OTHER VEHICLE PROPERTY 1

| | |
|-----------------------------|----------|
| Vehicle Registration Number | SHD3060R |
| Vehicle Make/Model/Colour | |
| Details Of Properties | |
| Vehicle Category | TAXI |
| Name of Driver | |
| NRIC/Passport Number | |
| Contact Number | |
| Address | |

Postcode
Insurance Company Name
Nature Of Damage
No. Of Passenger (Including Driver)

Sketch Plan



Insd's Nric (Front)




Insd's Nric (Back)



Insd's Driving License (Front)



Insd's Driving License (Back)



YOU ARE LICENSED TO DRIVE VEHICLES IN THE FOLLOWING CLASS(S)

EFFECTIVE DATE

17 Aug 2015

Class 3A Motor cars without clutch pedals (Auto) \leq 3000kg
< 7 passengers, exclusive of the driver; and
other motor vehicles without clutch pedals \leq 2500kg



Licence No: S9175283

NP 428A

Accident Photo



Accident Photo



Accident Photo



Accident Photo

