

22/03/2002

ASS. REC. BY:

REF:

CS3/LPC160192514/MVB

Special Instructions:

Surveyor:

ASSIGNMENT (Office)

From (Person):

Gerard Poh

of

JPC

Date/Time: 11-10-2016 1013am

Estimated Cost:

Bill to:

OD/TP/WS/TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

ADV 9588

Insured:

SJH 846R

at Workshop m/s

Pang & Tan

Tel:

9731 8588

6255 5711

of

Blk 13 Sm Ming # 01-123

Michelle

Policy No:

Claim No:

16/16/16/VP03/019313

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A. 05-10-2016

CA / REV / REP. / REV 24 HRS WPI

H.O.D. Endorsement:

Date/Time:

11-10-2016 10:31am

Person Contacted:

Mr. Pang

Vehicle IN/OUT

Date/Time	Action/Instruction (X) Estimate.
	ADV 9588 - X
	SJH 846R - MIN / INC 0902118311/PI
30-12-16 11:15am	Mr. Pang arrange survey with owner.
200217 4:17pm	still pending appt for survey
25-04-17 4:20pm	owner still did not send in for repair
26-04-17 4:21pm	Email to Gerard Poh will temporary close this file

6/4/18 @ 240pm Michelle said vehicle already release.

6/4/18 Submit PRS report

RECEIVED 05 APR 2018

REF:

ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.



Bal. or Market Value:

IDAC Accident Rpt: Consistent? : Yes or No

GIA / PR Seen: Consistent? : Yes or No

Est. Repairs: days Res.: Yes or No

Lump Sum: % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date:

Person Contacted:

Veh No: ADV 9588 Yr Regn: / -

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: NISSAN C22 C.C. -

Colour: SILVER A/C: Insured / Std / NI / NA

Sp. Reading: 427458 T/Radio: Insured / Std / NI / NA

Eng/No:

C/No: VPC 22H00002

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 175/70/R13

R: ✓

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

APOLLO

Front

Rear

R/Bal. 8 mm

R/Bal. 8 mm

L/Bal. 8 mm

L/Bal. 8 mm

D.O.A.

D.O.I. 22/3/2018

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

NSBODY.

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

PRI (NO ESTIMATE upon survey)

Date/Time, File Pass to?



: Preli. Report

1)



: Final Report

Date/Time, File Return to?

2)

Days Of Repair:

Resurvey No. of Trip:

Survey Fee:

Transportation:

) \$ + RS. \$

) Photos

) Others

TOTAL

Report Format :

Lump Sum / I.B.I. (\$)

Add Fee:



: Site Insp (\$)



: Interview (\$)



: Tech. Insp (\$)



: Weekend (\$)



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

LONPAC INSURANCE BHD

Ref : CS3/LPC16019254/M1vb-1

300 BEACH ROAD

#17-04/07 THE CONCOURSESINGAPORE 199555

Date : 22-03-2018

Code : LPC2



1. Policy Particulars :- (THIRD PARTY CLAIM)

Insured Veh.	SJH 846R	Veh. Inspected	ADV 9588
Policy No.		Coverage (\$)	0.00
Claim No.	16/16/16/VP05/019313	Excess (\$)	0.00
Assign From	GERALD POH	Assign Date	22/03/2018

2. Vehicle Particulars & Condition

Make & Model	c.c	0
Engine No.	HIDDEN	Year of Reg.
Chassis No.		Colour
Odometer	-	Steering
Brakes		Modification
General		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm

4. Description of Damages

--

5. General Information

Accident Date	05/10/2016	Inspection Date	22/03/2018
Survey held at	160 SIN MING DRIVE #04-03		
Repairer	PANG & TAN VEHICLE SERVICE CENTRE		

5a. Remarks

A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.
--

Catherine Chong (LKK Auto)

From: Catherine Chong (LKK Auto) <admin-d@lkkauto.com>
Sent: Wednesday, 26 April, 2017 4:24 PM
To: 'GERALD POH WEE BIN'
Cc: 'MT_Claim_SG'; 'assignments@lkkauto.com'
Subject: RE: Yr ref: 16/16/16/VP05/019313 - Our ref: LCH.ry/SMPT-60749.16

Dear Mr Gerald,

Please be informed that we are unable to conduct the inspection after some attempts to inform the workshop to present the vehicle.

This case has been pending for a long time due to the unavailability of the owner, therefore we decided to temporarily close this case.

Kindly advise us if there is any arrangement made and will be glad to re-open the case accordingly.

Best Regards,

Catherine Chong | Admin

LKK Auto Consultants Pte Ltd

Phone: 6741-8434 | email: assignments@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Catherine Chong (LKK Auto) [mailto:admin-d@lkkauto.com]
Sent: Tuesday, 11 October, 2016 10:27 AM
To: 'GERALD POH WEE BIN' <geraldpoh@lonpac.com>
Cc: 'MT_Claim_SG' <mt_claim@lonpac.com>; assignments@lkkauto.com; sur@lkkauto.com
Subject: RE: Yr ref: 16/16/16/VP05/019313 - Our ref: LCH.ry/SMPT-60749.16

Dear Mr Gerald,

Thank you for the assignment.

Please be informed that vehicle currently not in the workshop, repairer will arrange.

Best Regards,

Catherine Chong | Admin

LKK Auto Consultants Pte Ltd

Phone: 6741-8434 | email: assignments@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

Catherine Chong (LKK Auto)

From: GERALD POH WEE BIN <geraldpoh@lonpac.com>
Sent: Tuesday, 11 October, 2016 10:13 AM
To: Catherine Chong (LKK Auto)
Cc: MT_Claim_SG
Subject: FW: Yr ref: 16/16/16/VP05/019313 - Our ref: LCH.ry/SMPT-60749.16
Attachments: SKMBT_C364e16101109560.pdf

Our Ref : 16/16/16/VP05/019313

Dear Catherine,

Please see attached and proceed accordingly.

Best Regards

Gerald Poh

Senior Claims Executive | Lonpac Insurance Bhd

100 Beach Road, #19-00 Shaw Tower, Singapore 189702

Tel: (65) 6250 7388 Ext.240 | Fax: (65) 6296 2706

From: Cheonghoh Law [mailto:mail@cheonghoh.sg]

Sent: Tuesday, 11 October, 2016 10:03 AM

To: GERALD POH WEE BIN

Cc: Pang & Tan Michelle

Subject: Yr ref: 16/16/16/VP05/019313 - Our ref: LCH.ry/SMPT-60749.16

Dear Gerald,

We enclose herewith our letter for your necessary action.

Thanks & regards,

Rayline

CHEONGHOH LAW CORPORATION

Blk 53 Chin Swee Road #03-05 Singapore 160053

T: 6337 8700 | F: 6337 3700 | E: mail@cheonghoh.sg

* With effect from 7 December 2015, our office is located at Blk 53 Chin Swee Road #03-05 Singapore 160053

**Cheonghoh
Law Corporation**

(Incorporated with limited liability) Blk 53 Chin Swee Road #03-05 . Singapore 160053
Co. Reg No.201108070G Tel: 63378700 Fax: 63373700 E-mail: mail@cheonghoh.sg

In reply, please quote our Reference Number

Our Ref: LCH.ry/SMPT-60749.16
Your Ref: 16/16/16/VP05/019313

11 October 2016

Lonpac Insurance Berhad
100 Beach Road #19-00
Shaw Tower
Singapore 189702
Attn: Gerald Poh

BY EMAIL ONLY
Fax No: 62962706

Dear Sirs

**ACCIDENT INVOLVING VEHICLES NO ADV 9588 AND SJH 846 R ON 5 OCTOBER 2016 AT/ALONG
LORONG 4 TOA PAYOH -**

We refer to the above matter and to your letter of even date.

Our client hereby nominate Mohamad Taufikh of your said letter to conduct the pre-repair survey of the damages to our client's vehicle arising out of the above mentioned accident.

Kindly contact Mr Pang at 97318588 from Pang & Tan Vehicle Service Centre, Blk 13 Sector B Sin Ming Industrial Estate #01-43 Singapore 575657 for the said necessary arrangement.

Thank you.

Yours faithfully

CHEONGHOH LAW CORPORATION
Lee Cheong Hoh
CHEONGHOH LAW CORPORATION

cc: client - via fax only (ADV 9588)



**SINGAPORE
POLICE FORCE**



T/20161006/2159

1 of 3

Police Station Of Origin:
Toa Payoh N.P.C
93 Toa Payoh Central #01-02 Toa Payoh
Community Building SINGAPORE 319194
Tel No: 1800-2519999

Report No. T/20161006/2159

REPORT OF A TRAFFIC ACCIDENT

Date/Time Report Made: 06/10/2016 18:12	Vide Report No.:	Station Diary No.: 143
--	------------------	---------------------------

Informant's Particulars			
Name of Informant: CHUIE ZHEN WEI		Address:	
ID Type / ID No.: FIN NO / G6968359U		Contact No.: Home/Office: Mobile: 83564801	
Nationality: MALAYSIAN		Email:	
Sex: Male	Age: 26	Date of Birth: 02/04/1990	Type of Informant: Driver
Race: Chinese		Language: English	Institution / School Name:
Occupation: Construction		Driving Licence Information: Class: Date of Expiry:	

General Information of the Accident				
Type of Accident:	Non-Injury Foreign Vehicle	Drink Drive: No	Date/Time of Accident: 05/10/2016 17:00	Type of Location:
Location: Along Road 1 LORONG 4 TOA PAYOH				
Blk 62 Lorong 4 Toa Payoh, loading and unloading bay				
Weather: Clear		Road Surface: Dry	Road Speed Limit:	
Traffic Flow:		Traffic Control:	Traffic Volume:	
Type of Collision: Between Moving Vehicles - Head To Side			Anyone conveyed by ambulance: No	

Details of Vehicle Involved						
Vehicle No.	Type	Make	Model	Color	Condition	No of
ADV9588	Car					1
SJH846R	Car					0

Details of Person Involved	
Any Pedestrian Involved: No	
No. of Pedestrians Injured: NIL	Use of Pedestrian Crossing: NA



**SINGAPORE
POLICE FORCE**



T/20161006/2159

3 of 3

Police Station Of Origin:

Toa Payoh N.P.C

93 Toa Payoh Central #01-02 Toa Payoh

Community Building SINGAPORE 319194

Tel No: 1800-2519999

Report No. T/20161006/2159

CONTINUATION OF REPORT

Sketch Plan

Informant is not able to provide sketch plan

IMPORTANT: Please attach a copy of your vehicle's Insurance Certificate to this report. If you don't have the certificate with you now, please fax a copy to 65474885 stating the report number as reference.

Signature Of Officer Recording The Report:
E /
Staff Sgt CHUA JUN JIE

Signature Of Informant:

Signature Of Interpreter:
Not applicable

Date/Time:
06/10/2016 18:12

Officer In Charge Of Case:
TP / AEIT /
Staff Sgt WONG SIEU LUI
Contact No.: 65476423

Classification Of Case:

Authentication Stamp
NP168

Signature:

Singapore Police Force

**LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

PRE-REPAIR INSPECTION REPORT

LONPAC INSURANCE BHD

Ref: CS3/LPC16019254/M1vbe2-1

300 BEACH ROAD

Date: 09-04-2018

#17-04/07 THE CONCOURSESINGAPORE 199555



Code: LPC2

1. Policy Particulars :- (THIRD PARTY CLAIM)

Insured Veh.	SJH 846R	Veh. Inspected	ADV 9588
Policy No.		Coverage (\$)	0.00
Claim No.	16/16/16/VP05/019313	Excess (\$)	0.00
Assign From	GERALD POH	Assign Date	11/10/2016


2. Vehicle Particulars & Condition

Make & Model	NISSAN C22	c.c	0
Engine No.	HIDDEN	Year of Reg.	
Chassis No.	VPC22A00002	Colour	SILVER
Odometer	427458 KM	Steering	IN ORDER
Brakes	IN ORDER	Modification	NIL
General	GOOD		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	175/70 R13	APOLLO	8 mm
L/H Front Tyre	175/70 R13	APOLLO	8 mm
R/H Rear Tyre	175/70 R13	APOLLO	8 mm
L/H Rear Tyre	175/70 R13	APOLLO	8 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE N/S BODY.	
--	---

5. General Information

Accident Date	05/10/2016	Inspect Date / Time	22/03/2018 (11:16 AM)
Survey held at	BLK 13 SIN MING #01-43		
Repairer	PANG & TAN VEHICLE SERVICE CENTRE		

5a. Remarks

A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.
--

Report Ref No. CS3/LPC16019254/M1vbe2-1

Inspected By

MA CHIN FOOK

Automotive Assessor

K.K.LAU CPT(RET)

BEng(Hons), B.Bus, MBA, PEng, PE, MInstAEA, MASME, MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.