





| PRE-REPAIR INSPECTION REPORT                 |  |                               |                         |   |
|--|--|-------------------------------|-------------------------|---|
| LONPAC INSURANCE BHD                         |  | Ref: CS3/LPC16019254/M1vbe2-1 |                         |   |
| 300 BEACH ROAD                               |  | Date: 09-04-2018              |                         |    |
| #17-04/07 THE CONCOURSESINGAPORE 199555      |  | Code: LPC2                    |                         |   |
| 1. Policy Particulars :- (THIRD PARTY CLAIM) |  |                               |                         |   |
| Insured Veh.                                 | SJH 846R   | Veh. Inspected                | ADV 9588                |   |
| Policy No.                                   |  | Coverage (\$)                 | 0.00                    |   |
| Claim No.                                    | 16/16/16/VP05/019313   | Excess (\$)                   | 0.00                    |   |
| Assign From                                  | GERALD POH   | Assign Date                   | 11/10/2016              |   |
| 2. Vehicle Particulars & Condition           |  |                               |                         |   |
| Make & Model                                 | NISSAN C22   | c.c                           | 0                       |   |
| Engine No.                                   | HIDDEN   | Year of Reg.                  |                         |   |
| Chassis No.                                  | VPC22A00002  | Colour                        | SILVER                  |   |
| Odometer                                     | 427458 KM  | Steering                      | IN ORDER                |   |
| Brakes                                       | IN ORDER   | Modification                  | NIL                     |   |
| General                                      | GOOD   |                               |                         |   |
| 3. Conditions of Tyres                       |  |                               |                         |   |
|  | Size   | Make                          | Balance                 |   |
| R/H Front Tyre                               | 175/70 R13   | APOLLO                        | 8 mm                    |   |
| L/H Front Tyre                               | 175/70 R13   | APOLLO                        | 8 mm                    |   |
| R/H Rear Tyre                                | 175/70 R13   | APOLLO                        | 8 mm                    |   |
| L/H Rear Tyre                                | 175/70 R13   | APOLLO                        | 8 mm                    |   |
| 4. Description of Damages                    |  |                               |                         |   |
|  | THE VEHICLE SUSTAINED DAMAGES AT THE N/S BODY.   |                               |                         |  |
| 5. General Information                       |  |                               |                         |   |
| Accident Date                                | 05/10/2016   | Inspect Date / Time           | 22/03/2018 ( 11:16 AM ) |   |
| Survey held at                               | BLK 13 SIN MING #01-43   |                               |                         |   |
| Repairer                                     | PANG & TAN VEHICLE SERVICE CENTRE  |                               |                         |   |
| 5a. Remarks                                  |  |                               |                         |   |
|  | A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.<br>B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION.<br>THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE.<br>C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS. |                               |                         |   |

Report Ref No. CS3/LPC16019254/M1vbe2-1

Inspected By

MA CHIN FOOK

Automotive Assessor

K.K.LAU CPT(RET)

BEng(Hons),B.Bus,MBA,PEng,PE, MInstAEA,MASME,MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.  
No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or  
relying on this Report, in whole or in part, does so at his or her own risk.